

# CARI 29-01 update

13<sup>th</sup> Rotorcraft Symposium  
Cologne, 10<sup>th</sup> December 2019

**Your safety is our mission.**

# Summary

- Origin and Scope of CARI 29-01
- Collected data
- EASA approach on the lesson learnt

# Origin and Scope of CARI 29-01



LN-OJF Accident 29<sup>th</sup> April 2016

Technical evidences on the accident are coming from:

- AIBN Accident Investigation Report
- AH activity in frame of Continued Airworthiness with EASA

# Origin and Scope of CARI 29-01




Fatigue fracture of 2<sup>nd</sup> stage planet gear outer race



Existing Chip Detectors performance not enough for the limited spalling of LN-OJF



Maintenance criteria following chip detection Particle criteria (e.g. total area accumulated) not adequate for the limited spalling of LN-OJF



Limited spalling release prior to failure (est. 28 mm<sup>2</sup>)



Development of micro pitting on the max stress contact line with the roller

**REPORT** SL 2018/04

**EASA Airworthiness Directive**  
 AD No.: 2017-0214  
 Issued: 27 July 2017

**REPORT ON THE AIR ACCIDENT NEAR TUI ØYGARDEN MUNICIPALITY, HORDALAND COUNTY, NORWAY 28 APRIL 2016 WITH AIR HELICOPTERS EC 225 LP, LN-OJF, OPERATED BY HELICOPTER SERVICE AS**

**EASA Airworthiness Directive**  
 AD No.: 2017-0214  
 Issued: 27 July 2017

**Design Approval Holder's Name:** AIRBUS HELICOPTERS  
**Type/Model designation(s):** AS 332 L2 and EC 225 LP helicopters

**Effective Date:** 01 August 2017  
**TCO Number(s):** EASA-002  
**Foreign AD:** Not applicable  
**Supervisor:** This AD supersedes EASA AD 2017-0111 dated 23 June 2017.

**ATA 09 – Time Limits / Maintenance Checks – Main Gearbox Particle Detector / Oil Filter / Oil Cooler – Inspection**  
**ATA 48 – Main Rotor Drive – Epicyclic Module – Replacement / Modification / Reduced Service Life Limit**

**Manufacturer(s):** Airbus Helicopters (Formerly Eurocopter, Eurocopter France, Aerospatiale)

**Applicability:** AS 332 L2 and EC 225 LP helicopters, all manufacturer serial numbers.

**Reason:** Following a fatal accident that occurred in Norway to an EC 225 LP helicopter, involving in-flight detachment of the main rotor hub from the Main Gearbox (MSG), EASA issued Emergency AD 2016-0205 and Emergency AD 2016-0208 to require some immediate inspections on an initial procedural basis.

After EASA AD 2016-0208 E was issued, a second preliminary report from the investigation board indicated metallurgical findings of fatigue and surface degradation in the outer race of a second stage planet gear of the MSG integral module. As this, it could not be determined whether that was a contributing factor to the accident, or a subsequent failure of another organ.

Contact pressure, surface hardening, inadequate inner vs. outer race contact pressure ratio and level of stress through the rim may increase the likelihood of subsurface cracking

Scrapping gears due to wear, corrosion, pits and spalling without in-depth analysis may prevent the identification of a significant subsurface damage

# Origin and Scope of CARI 29-01

|  |   |              |              |
|--|---|--------------|--------------|
|  | <b>CONTINUING AIRWORTHINESS<br/>REVIEW ITEM</b> | CARI:        | 29-01        |
|  |   | ISSUE:       | 1            |
|  |   | DATE:        | July 2, 2018 |
|  |   | PAGE No.:    | 1 of 3       |
|  |   | STATUS:      | OPEN         |
|  |   | NEXT ACTION: | TC Holders   |

**TITLE:** Fatigue cracking in MGB Critical Parts with Integral Bearing Races

**APPLICABILITY:** CS/JAR/FAR-29 Helicopter Types

**REQUIREMENT(S):** Part 21: 21.A.34, 3B  
CS29: 29.571, 917, 902, 1309, 1337

**PRIMARY PANEL(S):** Structures (Panel 3) and Transmissions (Panel 13)

**SECONDARY PANEL(S):** N/A

## IDENTIFICATION OF ISSUE

Service experience has shown that the previously accepted means of compliance with rotorcraft certification requirements have not adequately addressed risks associated with the following aspects of gearbox design:

- Evaluation of tolerance to rolling and sliding contact fatigue of component featuring integral bearing race;
- Review of bearing design parameters affecting bearing reliability;
- Effective performance of oil debris monitoring systems, i.e. chip detectors of 29.1337.

Investigation into the accident of LN-OJF revealed that the MGB failure initiated from cracking at a micro-pit on the integrated planet gear bearing outer race, which developed into a crack in the body of the affected planet gear ultimately leading to failure of this planet gear and jamming of the epicyclic module.

Only a limited area of spalling was present on the gear outer race surface and it did not trigger any advance warning of the impending gear failure. Prior to this accident spalling had been considered to be reliably detected by the oil debris monitoring systems before reaching any significant reduction in safety margins.

**EASA POSITION** (Issue 1, 02.07.2018)

## Objective

Due to the similarities between planet gear designs across many different helicopters and due to the fact that the causes for such catastrophic cracking with limited spalling have not, up to now, been isolated to specific features of the affected type, EASA considers that it is necessary to review related service experience and design data of other helicopter types.

CARI for Fatigue cracking in Critical Parts with Integral Bearing Races

→ Fatigue cracking in MGB Critical Parts with Integral Bearing Races

→ CS/JAR/FAR 29 helicopters

→ Accepted MoC have not adequately addressed risks associated to:

- Rolling/sliding fatigue on bearing races
- Bearing design parameters affecting reliability
- Performance of debris monitoring systems
- Continuous integrity verification of critical components

# Origin and Scope of CARI 29-01

|  |   |              |              |
|--|---|--------------|--------------|
|  | <b>CONTINUING AIRWORTHINESS<br/>REVIEW ITEM</b> | CARI:        | 29-01        |
|  |   | ISSUE:       | 1            |
|  |   | DATE:        | July 2, 2018 |
|  |   | PAGE No.:    | 1 of 3       |
|  |   | STATUS:      | OPEN         |
|  |   | NEXT ACTION: | TC Holders   |

**TITLE:** Fatigue cracking in MGB Critical Parts with Integral Bearing Races

**APPLICABILITY:** CSJAR/FAR-29 Helicopter Types

**REQUIREMENT(S):** Part 21: 21.A.34, 3B  
CS29: 29.571, 917, 902, 1309, 1337

**PRIMARY PANEL(S):** Structures (Panel 3) and Transmissions (Panel 13)

**SECONDARY PANEL(S):** N/A

## IDENTIFICATION OF ISSUE

Service experience has shown that the previously accepted means of compliance with rotorcraft certification requirements have not adequately addressed risks associated with the following aspects of gearbox design:

- Evaluation of tolerance to rolling and sliding contact fatigue of component featuring integral bearing race;
- Review of bearing design parameters affecting bearing reliability;
- Effective performance of oil debris monitoring systems, i.e. chip detectors of 29.1337.

Investigation into the accident of LN-OJF revealed that the MGB failure initiated from cracking at a micro-pit on the integrated planet gear bearing outer race, which developed into a crack in the body of the affected planet gear ultimately leading to failure of this planet gear and jamming of the epicyclic module.

Only a limited area of spalling was present on the gear outer race surface and it did not trigger any advance warning of the impending gear failure. Prior to this accident spalling had been considered to be reliably detected by the oil debris monitoring systems before reaching any significant reduction in safety margins.

**EASA POSITION** (Issue 1, 02.07.2018)

## Objective

Due to the similarities between planet gear designs across many different helicopters and due to the fact that the causes for such catastrophic cracking with limited spalling have not, up to now, been isolated to specific features of the affected type, EASA considers that it is necessary to review related service experience and design data of other helicopter types.

CARI for Fatigue cracking in Critical Parts with Integral Bearing Races

## Requested reporting:

### → Bearings

- Cases of through cracks
- Details on discards due to outer ring damages
- Design parameters of critical integral race bearings

### → Oil debris monitoring

- Failures detected by chip (performance index)
- Spalled area
- Methods for establishing the detection performance at design and any re-assessment due to in-service events
- ICA criteria for particles evaluation
- Overhaul criteria for rejection of integral race bearings (dents, pits, markings, ...)

# Collected Data

- EASA has collected data from all the involved European Manufacturers
- Following the Bilateral agreement provisions with TCCA and FAA, data have been collected from almost all the applicable Canadian and US Manufacturers
- Provided data are under analysis. No specific risk is emerging from the reported in-service experience

# EASA approach on the lesson learnt

- Design assessment of gearbox components should consider the effects of cracking of bearing integrated races
- Review of design parameters and analyses to evaluate the likelihood of spalling and cracking on bearing races
- Characterization of the bearing spalling and spalling detection, supported by the demonstration of an adequate chip detection effectiveness
- Justification of the ICA and O/H criteria for particle identification and inspection/removal criteria

[easa.europa.eu/connect](https://easa.europa.eu/connect)



**Your safety is our mission.**

An Agency of the European Union 