



HELICOPTERS

Corrosion of steel and stainless steel - fatigue limit effects Helicopter dynamic system components

N. Guillemot, J.M. Besson – rotor stress department

05/12/2017

AIRBUS

Table of contents

- 1. Corrosion incidents recently observed on the fleet**
- 2. Laboratory investigation of corrosion & tests**
- 3. Fatigue results**
 - ✓ Results on specimens
 - ✓ Results on full scale parts
- 4. Conclusions**

Table of contents

1. Corrosion incidents recently observed on the fleet

2. Laboratory investigation of corrosion & tests


3. Fatigue results

- ✓ Results on specimens
- ✓ Results on full scale parts


4. Conclusions

EC225 ditching: specific corrosion on 32CDV13 steel


- Vertical shaft of the Main Gear Box (MGB) → such corrosion inside the MGB is unusual
- Crack initiation on a 60µm depth corrosion pit
- One of the main root causes is **corrosion**



*Failure in the shaft radius
(close to the welding joint)*





3D measurement of failure areas



EC225 ditching: specific corrosion on 32CDV13 steel (2)

➤ Scenario details:





- During nominal functioning :
« **swimming pool effect** » (oil centrifugation) in the inner diameter.
- **Fretting powder** created by the wear of splines and due to centrifugation

Sticked fretting powder



EC225 ditching: specific corrosion on 32CDV13 steel (2)

➤ Scenario details:




Sticked fretting powder



- During nominal functioning :
« **swimming pool effect** » (oil centrifugation) in the inner diameter.
- **Fretting powder** created by the wear of splines and due to centrifugation
- Exchange with external air and **condensation** effect lead to humidity ingress inside the gearbox.
- Due to temperature gradient 100°C inside the MGB and 10°C outside in the main rotor shaft, an **humidity flow** is created. Then, a mixture of humidity and fretting powder could be trapped in the inner diameter.

EC225 ditching: specific corrosion on 32CDV13 steel (3)

- Internal component of the Main Gear Box (MGB)
Crack initiation on a 60µm depth corrosion pit
- Now, use of **welding modelling** in order to predict residual stress field → Fatigue behaviour



EC130: some mast/hub bolts failure from severe corrosion


➤ Context

- ✓ Customer operating in hot and wet conditions
- ✓ **Some bolts were broken (high strength steel) detected by maintenance routine**
- ✓ Fretting and severe corrosion marks
- ✓ Retex: Among 415 customers, 9% with light fretting or corrosion which remains much lower than these 2 incidents

*35NCD16 bolt
without cadmium*

➤ Background


- ✓ This assembly design exists since 1978 on more than 34 million of FH on Ecureuil fleet without any significant incident on this bolted assembly up to now




EC130 mast/hub bolts failure from severe corrosion

➤ Root cause:

- ✓ Assembly with presence of interface products not according to maintenance documentation.
 - 1st case: on the plane surface (complete loss of torque)
 - 2nd case: under screw head and in the threads
- Partial loss of tightening (> 30% according to torque tests)




- ✓ Local unsticking between mast & hub (outside & inside)




EC130 mast/hub bolts failure from severe corrosion

➤ Root cause:


- ✓ Local unsticking between mast & hub (outside & particularly inside)





- ✓ Humidity trapped at the interface hub/mast by centrifugal effect



- ✓ Corrosion **with confinement** at the plane interface




- ✓ Bolts failure






Contour Plot
Stress tensor(P1 (major), Max, CornerData)
Global System
Advanced Average
393.0
349.0
305.1
261.1
217.2
173.3
129.3
85.4
41.4
-2.5

Local Max = 393.0
Nodes 210029
Local Min = -2.5
Nodes 211344



AS332 MK2 blade pin: stainless steel

- One of the main root cause is corrosion
 - ✓ Such corrosion pit is unusual for such stainless steel (MARVAL X12)
 - ✓ Other aggravating factors have influenced crack initiation.



50µm depth corrosion pit




Table of contents

1. Corrosion incidents recently observed on the fleet
- 2. Laboratory investigation of corrosion & tests**
3. Fatigue results
 - ✓ Results on specimens
 - ✓ Results on full scale parts
4. Conclusions

Corrosion testing method for high strength steel

- Standard salt spray process is not adapted : no corrosion pits creation (generalized corrosion)
- Tests with electrolytic polishing: not representative in terms of « local roughness »






Pits generated with electrolytic polishing



Corrosion testing method for high strength steel (2)

➤ 3D roughness and morphology measurement



➤ A specific protocol has been developed in order to generate corrosion with appropriate roughness (accelerated test)


Corrosion testing method for stainless steels

- Standard salt spray process is not adapted : no corrosion creation
- Tests have been done with several methods: Retained method is based on successive acetic acid attacks

Corrosion on blade pin



Corrosion on specimen after acetic acid attacks





- Same corrosion morphologies between real parts and corroded specimen

Table of contents

1. Corrosion incidents recently observed on the fleet
2. Laboratory investigation of corrosion & tests
- 3. Fatigue results**
 - ✓ Results on specimens
 - ✓ Results on full scale parts
4. Conclusions

Fatigue results on specimens




*Effect of corrosion pits on fatigue limits
32CDV13 specimens (4 points bending)*



- Even with 20/30 µm depth, corrosion has an important impact on fatigue limit
- Asymptotic impact from 100µm depth

Fatigue results on full scale parts



Effect of corrosion pits on fatigue limits *Comparison between specimens and full scale components*



- Full scale component results and specimen results are consistent
- Full scale component behaviour lightly higher than specimen tests

Fatigue results on full scale parts

Effect of humidity & corrosion pits on fatigue limit



Fatigue test with humidity only
(without any aggressive products)
→ phenomenon called « active corrosion »

- In addition with corrosion pits, **HUMIDITY** generates an additional knockdown factor on fatigue limit
➔ Factor = 1,3 (less severe than fatigue corrosion)

Conclusions

➤ Airbus Helicopters fleet

- For the last 10 years, more critical corrosion cases have been discovered on dynamic components
 - Ageing of AH fleet (more than 93 millions of FH & 50 years)
 - More helicopters are flying today in severe climatic environments and usage conditions

➤ Design and stress issues: “safety first”

- A threat assessment is defined to check all possibilities of corrosion on external and internal parts taking into account surface integrity generated by manufacturing processes (welding, machining, ...)
- Inspection intervals for Damage Tolerance are computed thanks to knockdown factor applied on fatigue limit and not on cycles.
- The fleet feedbacks allow to develop new design rules for corrosion damage tolerance

➤ Prospects

- Influence of humidity (« active corrosion ») must be better understood
- Better knowledge of hydrogen embrittlement phenomenon (Environment Assisted Cracking & fatigue corrosion)
- Research activities are going on and growing



Thank you