

Commentator:	None					
Page No: 01						
<b>Comment:</b> No com Operation in APU Mo	de.	been received	on the	Special	condition	Engine
EASA Response	Noted					