



Alenia Aermacchi

A Finmeccanica Company


Sandwich Implementation - Test Activity

Presented by **Alfredo Lista**
Airframe - Structure Technology

Koln, 13-14 June 2013



AAEM "H/C PARTS" HISTORICAL BUSINESS




The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

ATR HISTORY

- ✓ ATR 42 was developed and certified on 1985 with primary structure made in full metal configuration with exception of the Rudder and Elevator made in non-metallic sandwich
- ✓ ATR 72 was developed and certified on 1989, the basic primary structure was in full metal configuration with exception of the external wing boxes made in C/Epoxy composite material
- ✓ In 1995 (New Airworthiness Requirement) passenger weight increase, Alenia launched a weight saving project to recover the original Aircraft Take-Off weight demonstrated during ATR 42 & 72 Certification.
- ✓ In 1996 a new Structural Configuration for ATR 42 and ATR 72 Co-cured Horizontal and Co-bonded Vertical Tails was certified consisting mainly in the material change from Aluminum Alloy to C/Epoxy configuration.

1st DELIVERY



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

ATR SERVICE HISTORY

✓ ATR 42 and 72 Rudder and Elevator in-service

- **1200 Rudder and Elevator Flying**
- **ATR 42 and ATR 72 totalized about 20 MLN fleet service hours**
- **The current Life of the Fleet Leader Aircraft is about 60.000 Flights (50.000 Flight Hours)**

✓ Summary of Rudder and Elevator service report:



- in-service experience of Rudder and Elevator are very good. There are no significant events inside database
- There are few SRAS (Structural Repair Approved Sheet) number concerning the different damage typology (12 about Elevator and 43 about Rudder).
- The main damage source are :
 - Lightning Strike
 - Counterbalance arm interference
 - Corrosion on metallic parts

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

REASONS FOR THE SUCCESS

➤ Good design

- No insert and blind rivets usage
- No bonding strap usage
- Right choice material (H/C Nomex)
- Minimum gauge skin thickness to minimize water ingress (3 plies fabric)
- Internal side with impermeable film (Tedlar)
- Right design solution



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.


REASONS FOR THE SUCCESS

➤ Aircraft Architecture

- high tail configuration leads in less probability of impact following tool drop on elevator

➤ Mission profile

- Both short and long range mission fly at cruise altitude, respectively of 15,000 and 25,000 feet, lower than the typical medium/long haul (around 40,000 feet). Sandwich structure benefit of lower ΔP .



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

SANDWICH USAGE AND ASSOCIATED RISK CLASSIFICATION

Following a classification based on “DT risk view” for HC primary structures.


- HC internal usage, i.e as Vstab ribs and Hstab Center-Box, is a low risk from DT point of view: The internal parts are protected from external threat.
- Rudder structure has an associated medium risk from DT point of view:
HC usage and associated risk classification vertical structures are less prone to on ground and tool drops during maintenance operation.
- Elevator structure has an associated high risk from DT point of view:
 - horizontal low mounted structure are more prone to on ground hail impact, to tool drops and run way debris
 - horizontal “high-Tail” configuration (ATR 42 ATR 72) has an associated medium risk from DT point of view: high tail structure are less prone to on ground and tool drops during maintenance operation

SANDWICH STRUCTURE HISTORICAL TECHNICAL CHALLENGE

- Hail, FOD and Lightning
- Composite face sheet fails as a result of an interaction among matrix cracks, fiber fracture and delamination.
- Sandwich structure may also exhibit core crushing and face sheet debonding. Damage may result from low-velocity impact such as tool drops or high energy events such as ballistic penetration
- An initial damage like a face sheet matrix cracking caused by hole, incorrect repair, puncture in the skin, severe hail damage could lead to water ingress into the H/C and/or cause disbond between face sheet and core
- In-service NDI

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.


UNDERSTANDING DAMAGE RESISTANCE



Test set up (only for reference)



Impact on external side (3 plies)



Impact on internal side (2 plies)



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

NDI C-SCAN MAP

Figure below shows the C-scan presentation of the results of the Automatic Through-Transmission inspection

Impact coding


XYZ – Z – NNN

X = impact location

YY = number of plies



Z = impactor diameter

NNN = impact energy




The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

MICROGRAPY INSPECTION RESULTS



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

UNDERSTANDING DAMAGE TOLERANCE UNDER ΔP




Vacuum chamber scheme

$E = 23 \text{ J}$; Dia impactor = 2"
(based on Impact Survey)





NDI C-Scan Map



The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

UNDERSTANDING DAMAGE TOLERANCE UNDER ΔP





- The vacuum chamber has been set to apply a differential pressure of 600 mbar (typical of medium/long haul, cruise altitude around 40000 feet).
- Test is currently running
- Up today has been completed 2000 cycles and no growth has been detected

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

UNDERSTANDING DAMAGE TOLERANCE UNDER THERMAL CYCLES


Vacuum prior to start cycling



H/C + 3 External Plies & 2 Internal Plies

Ply Drop Zone


L (in)	W (in)
20	15



service simulation thermal cycle (specimen temperature)

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

NDI IN QUALITY CONTROL




Typical configuration relevant for NDI

IN-SERVICE NDI

In-service NDI

for possible damages following impact or unexpected events



Typical configuration relevant for NDI

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

OVERALL SANDWICH REQUIREMENTS FOR EMPENNAGE

- *Impact Resistance is demonstrate by test for different geometry.*

Hail Impact, Lightning Strike and Impact survey performed on:
Elevator
Rudder
Center Box
Vstab Ribs

-
- *Ultimate strength is demonstrate based on test data for H/C laminates with BVID and MD (Cat.1).*

CAI and TAI tests at L1 (allowable).
Rudder Compression Panel (Fatigue & RS)
Elevator Compression Panel (Fatigue & RS)
Center Box Panel (Fatigue & RS)

-
- *Residual strength is demonstrated by test for H/C laminates with impact damage associated to the associated threat (Cat.2).*

Rudder Compression Panel (Fatigue & RS)
Elevator Compression Panel (Fatigue & RS)
Center Box Panel (Fatigue & RS)

-
- *Structural repair concepts and methodologies are developed and tested.*

Repair Sandwich static and fatigue

-
- *Moisture absorption characteristics are evaluated by test for pristine structure, repaired structure.*

Moisture Absorption evaluation

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

OVERALL SANDWICH REQUIREMENTS

- *HC methodologies validation and calibration.*

Ramp Analysis

Sandwich Panel in Compression

Sandwich Panel in Shear

Sandwich Panel (Configuration Rudder) in Compression

Sandwich Panel (Configuration Elevator) in Compression

-
- *Damage propagation under ground-air-ground cycling and flight spectra.*

Damage Propagation in face-sheet core disbond.

-
- *Effect of water freezing and thaw cycling to the skin delamination and damage propagation.*

Damage Propagation in face-sheet core disbond.

THE CONDITIONS NECESSARY FOR THE SUCCESSFUL USE OF HC BASED ON ALENIA EXPERIENCE

➤ Good design

- No insert and blind rivets usage
- No bonding strap usage
- Right choice material (H/C Nomex)
- Minimum gauge skin thickness to minimize water ingress (3 plies fabric)
- Internal side with impermeable film (Tedlar)
- Right design solution

➤ Aircraft Architecture

- high tail configuration leads in less probability of impact following tool drop on elevator

➤ Mission profile

- Both short and long range mission fly at cruise altitude, respectively of 15,000 and 25,000 feet, lower than the typical medium/long haul (around 40,000 feet). Sandwich structure benefit of lower ΔP .

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

TEST SUMMARY BY INVESTIGATED DAMAGE

MAIN SCOPE		Description	Investigated Damage/Defect			
			MD	Cat.1	Cat.2	Cat.3
DAMAGE RESISTANCE		Impact Survey on Elevator Sandwich Panel		X	X	
		Impact Survey on Rudder Sandwich Panel		X	X	
		Impact Survey on Center Box Sandwich Panel		X	X	
		Impact Survey on VStab Sandwich Ribs		X	X	
		Sandwich Panel lightning strike test			X	X
DAMAGE TOLERANCE	METHODOLOGIES VALIDATION/ CALIBRATION	Sandwich Panel in Compression (Static)		X		
		Sandwich Panel in Shear (Static)		X		
		Ramp Analysis of sandwich Panel		X		
		Rudder Compression Panel (Fatigue & RS)	X	X	X	
		Elevator Compression Panel (Fatigue & RS)	X	X	X	
		Center Box Sandwich Panel (Fatigue & RS)	X	X	X	
		Damage Propagation on Sandwich structure (Thermal Cycling)	X	X		
		Damage Propagation on Sandwich Structure (GAG ΔP)	X	X		
		Damage Propagation on Sandwich Structure (Flight Load Spectra)	X	X		
REPAIR		Moisture Absorption Evaluation		X	X	
		Sandwich Panels Repairs Validation			X	X

The contents of this document are the intellectual property of Alenia. Apart from those contractually-agreed user rights, any copying or communication of this document in any form is forbidden without the written authorization of Alenia.

This document and all information contained herein is the sole property of ALENIA AERMACCHI SPA. No intellectual property rights are granted by the delivery of this document or the disclosure of its content. This document shall not be reproduced or disclosed to a third party without the express written consent of ALENIA AERMACCHI SPA. This document and its content shall not be used for any purpose other than that for which it is supplied.

