



AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL – BRAZIL

BRAZILIAN AIRWORTHINESS DIRECTIVE

ERRATA

AD No.: 2006-09-04R1

Effective Date: 21 Feb. 2007

AD No. 2006-09-04R1 - EMBRAER - Amendment 39-1170.

This Errata is being issued to correct a printing error in the English translation of this Airworthiness Directive. The first paragraph of the APPLICABILITY section was printed as follows:

This Emergency Airworthiness Directive is applicable to all Embraer ERJ-190() aircraft models in operation with engine main fuel pump part number (P/N) 2043M12P03 or P/N 2043M12P04 installed.

and shall be read as follows:

This Airworthiness Directive is applicable to all Embraer ERJ-190() aircraft models in operation with engine main fuel pump part number (P/N) 2043M12P03 or P/N 2043M12P04 installed.

Please modify the original AD text and attach this Errata to it.

APPROVAL:

CLÁUDIO PASSOS SIMÃO
General Manager
GGCP

NOTE: Original in English language signed and available in the files of the Aeronautical Products Certification Branch (GGCP) of the National Civil Aviation Agency (ANAC).