



## EASA Certification Information

**No.:** 2022-30  
**Issued:** 21 December 2022

**Subject:** Decision to revoke multiple EASA ETSO-C30c, -C96A Authorizations granted to B/E Aerospace Inc. (5349 S. Emmer Drive, New Berlin, WI, 53151 – USA)

ETSOA No.	Description	P/N	Date of last issue	DDP ref.
EASA.21O.10017634 Rev. D (EASA.21O.296 Rev. D)	Position Light Assemblies 9000 and 9200	03-9000-XXXX 03-9200-XXXX	04/12/2005	032-03-9000-01 Rev. 10 033-03-9200-01 Rev. 10 or subsequent rev.
EASA.21O.10017650 Rev. D (EASA.21O.335 Rev. D)	9500 Light Assembly LED red	03-9500-4001	04/12/2015	034-03-9500-00 Rev. 4 or subsequent rev.
EASA.21O.10017875 Rev. B (EASA.21O.832 Rev. B)	9501 Anticollision Light LED Class II	03-9501-XXXX	04/12/2015	041-03-9501 Rev. – or subsequent rev.
EASA.21O.10026816 Rev. B (EASA.21O.1113 Rev. B)	9505 LED Anticollision Light Class I	03-9505-XXXX	04/12/2015	045-03-9505 Rev. 1 or subsequent rev.
EASA.21O.10028951 Rev. B	9302 Combined Rear ACL Position Light	03-9302-XXXX	04/12/2015	046-03-9302 Rev. – or subsequent rev.
EASA. 21O.10032081 Rev. A	9800 combined wing ACL position light	03-9800-3003 03-9800-3004	04/12/2015	054-03-9800 Rev. – or subsequent rev.
EASA.21O.10038115 Rev. B	3000-2 LED anticollision light	03-3000-0002	04/12/2015	061-03-3000 Rev. 02 or subsequent rev.
EASA.21O.10038116 Rev. A	3000-0 LED anticollision light	03-3000-(XXX)0	04/12/2015	060-03-3000 Rev. 01 or subsequent rev.
EASA.21O.10041553 Rev. A	9002 and 9202 LED position light	03-9000-5003 03-9000-5004 03-9002-XXXX 03-9200-4006 03-9202-XXXX	04/12/2015	058-03-9000 Rev. 01 059-03-9200 Rev. 01 or subsequent rev.
EASA.21O.10050166 Rev. A	Combined LED wingtip light	03-0001-XXXX (excluding 03-0001-0000) 04-5000-XXXX	04/12/2015	068-03-0001 Rev. 02 or subsequent rev.

**Holder of the Certificate:** B/E AEROSPACE, Inc.  
5349 South Emmer Drive  
New Berlin WI 53151  
U.S.A.

**Background:**

On the date mentioned in the table above, the European Union Aviation Safety Agency (EASA) issued the above mentioned ETSO Authorizations for the purpose of recognition of U.S. Federal Aviation Administration (FAA) TSO Authorizations.

On the 2<sup>nd</sup> of March 2016 the Agreement between the USA and the EU on cooperation in the regulation of civil aviation safety has been amended by incorporating text additions and changes to the relevant paragraphs concerning the reciprocal automatic acceptance of ETSO/TSO Articles and approvals.

On the 06<sup>th</sup> of December 2022, FAA notified EASA of a transfer of ownership and change of address of the subject TSOA from B/E Aerospace, Inc., located at 5349 S. Emmer Drive, New Berlin, WI, 53151 to Goodrich Corporation, 3445 S. 5th Street, Suite 180, Phoenix, AZ 85040.

As result of such transfer, the FAA TSOA Certificate have been re-issued.

According to the Bilateral Agreement US-EU and policies shared with FAA, in case of TSO transfer with re-issue of TSO letters in the name of the new holder, EASA will proceed by revoking the related ETSO Authorizations as the conditions for which were validated no longer exist.

In virtue of the mutual acceptance of TSO/ETSO the re-issued TSOs are considered equivalent to EASA emitted ETSOA. Equipment can be exported to EU with relevant FAA authorization release form. Since revocation of ETSOAs, ETSO Marking is non more required.

Equipment produced and marked before the 06th of December 2022 can remain in service under the existing conditions.

**Contact:** Any request, query or comment shall be sent to:

European Union Aviation Safety Agency  
European Technical Standard Orders Section  
Postfach 10 12 53  
D – 50452 Köln  
E-Mail: [etsoa@easa.europa.eu](mailto:etsoa@easa.europa.eu)