



EASA Certification Information

No.: 2017 - 13
Issued: 02 August 2017

Subject: Revocation of various ETSOA certificates due to the revocation of the EASA.AP274.

Authorisation No: EASA.210.748, EASA.210.749, EASA.210.1051, EASA.210.10055168, EASA.210.10052398 REV. A

ETSOA No.	Description	P/N	Date of last issue	DDP ref.
EASA.210.748	6.00-6 M1 TL Aircraft Tyre	81200101	20/03/2008	TPF-MIT 014-04
EASA.210.749	6.50-10 M1 TL Aircraft Tyre	81210101	20/03/2008	TPF-MIT 015-04
EASA.210.1051	5.00 5 M 1 TL Aircraft Tyre	81220101	06/08/2008	TPF - MIT 016 - 07 EN
EASA.210.10055168	550 x 225 Model 5 Tubeless. Aircraft Tyre	81621101	16/10/2015	DDP-15/02
EASA.210.10052398 REV. A	720 x 310 Model 5 Tubeless	81666101	28/04/2016	DDP-15/01

Issued by: EASA

Holder of the Certificate: MITAS a.s.
 Švehlova 1900
 106 25 Praha 10
 Czech Republic

Background: With the revocation of EASA.AP274 on 07/07/2017 the capability for design is no longer provided and as a consequence EASA has decided to revoke all ETSO authorizations granted to MITAS a.s.

In accordance with the applicable EASA administrative procedures¹, EASA decided to revoke the aforementioned authorisations. EASA has submitted the decision to revoke EASA.210.748, EASA.210.749, EASA.210.1051, EASA.210.10055168, EASA.210.10052398 REV. A on 01 August 2017.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency
 Parts & Appliances Section
 Postfach 10 12 53
 D – 50452 Köln
 E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<http://easa.europa.eu/certification/internal-working-procedures.php>)