



EASA Certification Information

No.: 2016 - 05
Issued: 26 April 2016

Subject: Revocation of various ETSOs of Ameri-King Corporation due to bankruptcy termination of their TSO authorizations

Authorisation No:

ETSOA No.	Description / Model	P/N	Date of last issue	DDP ref.
EASA.IM.210.1 102	AK-451-(AF)(AP)(S) Emergency Locator Transmitter with GPS position interface	AK-451-(AF) (AP) (S)	20/11/2008	451
EASA.IM.210.1 0033545	AK 451.017-1B ELT Whip Antenna and AK 451.017-4(S) ELT Portable Whip Antenna	AK451.017-1B, AK451.017-4(S)	27/01/2011	451.017

Issued by: EASA

Holder of the Certificate: Ameri-King Corporation
 17881 Sampson Lane
 92648 Huntington Beach, California
 USA

Background: FAA informed EASA that FAA has terminated the TSO authorization of Ameri-King Corporation due to their bankruptcy and no further articles can be manufactured using this authorization.

In accordance with the applicable EASA administrative procedures¹, EASA decided to revoke the aforementioned authorisations. EASA has submitted the decision to revoke on 25 April 2016.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency
 Parts & Appliances Section
 Postfach 10 12 53
 D – 50452 Köln
 E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<http://easa.europa.eu/certification/internal-working-procedures.php>)