



Annual Safety Review 2021

Appendix 1 - List of Fatal Accidents



Appendix 1 List of fatal accidents

Local Date State of Occurrence Aeroplane Headline Location 10/02/2011 Ireland Cork Apt EICK SWEARINGEN - SA227 - BC Impacted runway inverted. Loading crew caught between loader and baggage door. 11/11/2012 Italy Roma Fiumicino Airport AIRBUS - A320 Anti-icing system not activated by flight crew - Pressure sensor 80 km south-east of Gossi obstructed by ice crystals. Aircraft stalled and crashed. 24/07/2014 Mali DOUGLAS - DC9 - 80 - 83 UUWW (VKO): DASSAULT - FALCON 50 -Aircraft collided with a snowplough vehicle during take-off run. Aircraft Moskva/Vnukovo 20/10/2014 Russian Federation was destroyed by fire. EX First officer alone in the cockpit, initiated a rapid descent - Aircraft 24/03/2015 France Prads-Haute-Bléone AIRBUS - A320 - 200 - 211 impacted mountainous terrain. IRU malfunction - Crew spatial disorientation - Loss of control - Aircraft **BOMBARDIER - CL600** 08/01/2016 Sweden Oajevágge 2B19 crashed on a mountainous terrain.

Commercial air transport – airlines and air taxi – large aeroplanes

Non-commercial complex business aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
10/12/2012	Cyprus	Larnaca	CESSNA - 750 - NO SERIES EXISTS	A service vehicle struck the right wingtip, vehicle driver trapped.
29/04/2013	Congo, Democratic Republic of the	FZAA (FIH): Kinshasa/N'djili	DASSAULT - FALCON 900EX	Collision with an individual on ground.
12/01/2014	Germany	Near Trier-Föhren Airport	CESSNA - 501	Aircraft collision against power pole.
03/10/2015	United Kingdom	Near Chigwell	BEECH - 200 - B200	Aircraft crashed shortly after take-off.
04/01/2018	Finland	Kittilä airport, EFKT	GULFSTREAM - GULFSTREAM 150	Fatal injuries to captain due to door opening violently.

Specialised operations aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
28/05/2010	Czech Republic	LKTO	ZLIN - Z142	Aircraft crashed shortly after take-off.
29/05/2010	Spain	Aldeanueva de Barbarroya (To)	PIPER - PA25	Stall during flight.
19/06/2010	United Kingdom	Methley Bridge (West Yorkshire	EXTRA - EA300	Aircraft crashed while performing an aerobatic display
17/08/2010	Spain	Aerodr. Casarrubios del Monte	ZIVKO - EDGE 540	Collision with terrain during aerobatic manoeuvre.

04/00/2010	United Kingdom	Norse Dude Jale of M/jeht	MOONEY - M20, VANS -	National States Angles Realine Treation of reas
04/09/2010	United Kingdom	Near Ryde, Isle of Wight	RV4	Mid-air collision during Merlin Trophy air race.
05/09/2010	Germany	Lauf-Lillinghof	DE HAVILLAND - DH82 - A	Collision with airshow spectators during take-off roll.
19/09/2010	Germany	Warngau (Miesbach)	EXTRA - EA300, XTREMEAIR	Mid-air collision during airshow.
	_		CESSNA - F172 - M, Aveko	
02/10/2010	France	Les Moëres	VL3B	Mid-air collision.
12/10/2010	Spain	Navarra	ROBIN - DR400	Collision with terrain during cruise.
				Robin 400 180R while towing a glider in the take-off phase crashed.
11/01/2011	•	Airport LIRG	ROBIN - DR400 - 180R	The pilot of the airplane was killed.
02/06/2011	Netherlands	EHTE	CESSNA - F172	The aircraft crashed after pick-up of a banner.
18/06/2011	Poland	Plock - Wisla River	CHRISTEN - EAGLE II	Crash during aerobatics over river.
04/07/2011	France	AD Dijon-Darois (21)	SOCATA	Stalling of towing aircraft after glider release.
				Loss of control during approach and subsequent crash with post-
30/08/2011	Poland	Nowy Targ	PZL OKECIE	impact fire.
28/04/2012	Germany	Alkersleben	ZLIN - Z226	Aircraft touched the ground after a formation flight.
			PIPER - PA25 - 235,	
05/05/2012	France	AD Buno Bonnevaux (91)	SLINGSBY - T31	Mid-air collision between a glider and an aeroplane above runway.
				Collision with power cables on approach and subsequent crash and
17/06/2012	Romania	Banesti, Prahova	AEROSTAR	post-impact fire.
22/07/2012	France	AD Couhé Vérac (86)	OTHER	Loss of control and subsequent crash during air show.
				Aircraft impacted terrain during aerial work operations - aerial
07/09/2012	Italy	Di Fioranello street 163, Rome	CESSNA - 402	photography.
				Avions Robin DR400 - Loss of control during take-off as aircraft fell
				into the vortex generated by the preceding aircraft c flying – 4 POB – 3
09/09/2012	Germany	Backnang-Heiningen	ROBIN - DR400 - 180R	OB Fatalities – 1 OB Serious.
			DIAMOND - DA40,	Mid-air collision during photo flight - POB 2 on each aircraft - 2
22/10/2012	Netherlands	EHAA	GENERAL AVIA - F22	fatalities - 2 serious injuries - both aircraft destroyed.
09/03/2013	Czech Republic	600m N Srbce (Chrudim)	ZLIN - Z37 - A	Aircraft collided with trees in IMC.
		Madrid-Cuatro Vientos Airport	HISPANO AVIACION -	
05/05/2013	Spain	(LECU)	HA200 - D	Aircraft crashed during airshow.
		Egmond aan Zee, Noord-		
08/05/2013	Netherlands	Holland	CESSNA - 172 - P	Ditched in North Sea near Egmond .
01/06/2013	Sweden	Söderhamn Airport	SAAB - 91	Engine failure during airshow due to lose spark plugs.
29/06/2013	Germany	Eberswalde-Finow	ZLIN - Z526 - AFS	Aircraft crashed during aerobatics.
30/06/2013	Sweden	Near Veberöd, Sweden	GRUMMAN - GA7	Crash in a field after reported engine problems.
				Abrupt manoeuvre - left wing structural failure due to a significant
19/10/2013	Belgium	Gelbressee	PILATUS - PC6	overload - aircraft out of control crashed into a ploughed field.

		2 km from Jämijärvi airfield		During climb, right wing broke due to a fatigue failure - aircraft
20/04/2014	Finland	EFJM, Satakunta	Other	entered a spin, crashed, and caught fire - 11POB - 8OB Fatalities.
				Pitts S-2B Special - Aircraft crashed during aerobatic routine - 1POB -
08/05/2014	Latvia	EVLA - Liepaja	PITTS - S2 - B	1OB Fatal - aircraft destroyed.
				Crashed shortly after take-off whilst glider towing. Glider
06/06/2014	Czech Republic	near Krizanov airfield, LKKA	TECNAM - P92	disconnected and landed safely - 1POB - 1OB Fatal - aircraft destroyed
			LEARJET - 35 - A, Military	
23/06/2014	Germany	Near Olsberg-Elpe	aircraft	Collision of two A/C in flight, one military - 3POB - 2OB Fatally Injured
		Topolów district Mykanów,		Piper PA-31 Navajo - Engine problems during climb-out, loss of height
		Czestochowskastreet No 36;		and collision with ground. Aircraft destroyed by post-impact fire – 12
05/07/2014	Poland	near Czestochowa	PIPER - PA31P	POB – 11 OB Fatal -1 OB Serious.
19/07/2014	Czech Republic	1 NM S LKKM	ZLIN - Z526 - F	The aircraft entered an inverted spin and impacted the ground.
				Aircraft suddenly descended in nose down attitude. Collision with the
01/08/2014	France	Linthal (68)	Other	ground during aerial photography flight.
				Parachute opened upon parachutist leaving the aircraft, parachute
				struck the tail of the aircraft and damaged part of the stabilizer, loss of
13/09/2014	France	At FL110 AD Tarbes Laloubère	CESSNA - U206 - F	control of aircraft and subsequent crash.
				During an evasive manoeuvre a light aircraft hit the tug's towrope of
				another aircraft with the propeller. The aircraft crashed into a
				cornfield and burst into flames – 2 POB – 2 OB Fatalities - aircraft
14/09/2014	Germany	Münster-Telgte Airfield - EDLT	DALLACH - D4, Other	destroyed
				XtremeAir Xtreme 3000 - Aircraft crashed during aerobatics
21/09/2014	Italy	near Venezia Lido Airport	XTREMEAIR	performance – 1 POB – 1 OB Fatal - aircraft destroyed
		near aviosuperficie Mensanello,		Loss of control during aerobatic manoeuvres. Aircraft crashed and
28/09/2014	Italy	Siena	PITTS	caught fire
				During aerobatics session the aircraft entered into spin after a half
30/05/2015	France	Blois	STAMPE - SV4 - C	loop manoeuvre. Aircraft crashed.
31/05/2015	Adriatic Sea	Tortoreto, Alba Adriatica (TE)	VANS - RV8 - A, VANS - RV7	Collision of two aircraft in flight during an air show.
01/08/2015	Romania	next to Stancuta airfield	PZL MIELEC - AN2 - R	Aircraft crashed shortly after take-off.
01/08/2015	United Kingdom	near Oulton Park	OTHER - Military	Flight into terrain during airshow.
				Aircraft deviated to the right during the take-off- the right wing tip hit
03/08/2015	Spain	Viladamat airfield	Other	the ground. The aircraft crashed and caught fire.
				Mid-air collision while en-route. Both aircraft were performing
20/08/2015	Slovakia	Cervený Kamen	LET - L410 - UVP, LET - L410	parachute dropping operations.
		· ·	HAWKER - HUNTER - T7 -	
22/08/2015	United Kingdom	near EGKA - Shoreham Airport	Т7	Aircraft crashed on a road during an air show.
	-			-

			COMCO IKARUS - IKARUS	
22/22/22/2			C42 - B, COMCO IKARUS -	
	Switzerland	Dittingen LSPD	IKARUS C42 - B	Mid-air collision during airshow
30/08/2015	Austria	Airfield Friesach Hirt, Carinthia	PITTS - S2 - B	Loss of control during aerobatic show with aircraft.
27/09/2015	France	LFDW - Chauvigny	OTHER	Loss of control in circuit pattern - aircraft crashed.
14/03/2016	Kenya	Proche AD Kauro	OTHER	Aircraft crash.
20/05/2016	Germany	Rodigast	PZL OKECIE - PZL101	Loss of control and subsequent crash into forest.
04/06/2016	Czech Republic	LKNYMB	OTHER	Fall of ULAC - Loss of speed during turn and fall into a spin.
				Parachutists reserve parachute opened prematurely. Parachutist hit
11/06/2016	Italy	Cecina	PILATUS - PC6	the RH stabilizer - structural damage in flight and crash.
		after take-off from LPFC :		
19/06/2016	Portugal	Figueira dos Cavaleiros	PILATUS - PC6 - B2H4	In-flight fuselage breakup due to material fatigue.
			PIPER - PA28 - 140, CESSNA	Two aircraft collided with each other in the vicinity of LHGD. 4 POB, 4
18/09/2016	Hungary	Gödöllo Arboretum	- 182 - D	fatalities.
16/07/2017	France	Capo di Feno	ICP - SAVANNAH - VG	Roll controls problem, loss of control - aircraft crashed.
		Near the 55 kilometer point of		
		N-340 road (Vejer de la		Bird strike followed by crash during fumigation work in a rice field
15/08/2017	Spain	Frontera)	PIPER - PA36 - 375	(low altitude operation).
03/09/2017	Italy	Pontinia	CESSNA - 182 - P	Loss of control inflight - crash and fire.
16/09/2017	Slovakia	LZPE	ZLIN - Z37 - C	Loss of control and crash.
		3.5 nautical miles (NM) west of		
13/05/2018	Ireland	ClonbullogueVillage, Co. Offaly	CESSNA - 208 - B	Aircraft crash following steeply banked turn.
		Just outside EHSE:		
31/05/2018	Netherlands	Hoeven/Seppe	PIPER - PA25 - 235	Aircraft crashed in attempt to pick up commercial text banner.
		2000 m off the coast of Cala		
		Solleric, municipality of Pollença		
12/06/2018	Spain	- Mallorca	AIR TRACTOR - AT802	Aircraft crashed into the sea.
27/07/2018	France	Bouloc-en-Quercy	PILATUS - PC6 - B2H4	Wing strike with a skydiver (wingsuiter).
29/07/2018	Slovenia	AD Bovec	ROBIN - DR400 - 180R	Collision with the ground after towing, fire
08/08/2018	Mauritania	Diatar	AYRES - S2R - T - T34	Aircraft collision with the ground, fire.
11/08/2018	Czech Republic	LKSR	OTHER	Loss of control - spiral dive
			AEROSPOOL - WT9,	Loss of control of the tug ULM during take-off in glider tow, collision
19/08/2018	France	AD Colmar Houssen	CENTRAIR - 101 - A	with runway, fire. 1 POB, 1 fatality.
		about 3 miles south of OMDB		Aircraft crashed on a second approach - possible wake turbulence
16/05/2019	United Arab Emirates	(DXB) : Dubai	DIAMOND - DA62	from landing heavy aircraft on parallel runway.
15/06/2019	Poland	Wisla river, Plock	YAKOVLEV - YAK52	Not recovered spin and crash to the river.
14/07/2019	Sweden	ESNU (UME) : Umeå	GIPPSLAND - GA8 - TC320	The aircraft impacted terrain in a steep nose down after take-off.

			MORANE SAULNIER -	
27/08/2019	Belgium	Kortrijk airport (EBKT)	MS893	Crash during banner pick up.
11/09/2019	Germany	Gransee	CESSNA - 208	Crash into terrain.
			COMCO IKARUS - IKARUS	Tow airplane failure on take-off - glider forced landing; airplane crash.
11/09/2019	France	take-off from LFIX : Itxassou	C42, SCHLEICHER - ASK21	1 fatality.
13/08/2020	Germany	Hessisch Lichtenau	ROBIN - DR400 - RP	Loss of control.
20/09/2020	Italy	near LILR : Cremona/Migliaro	PILATUS - PC6 - B2H4	Collision between airplane and skydiver. Crash.
			COMCO IKARUS - IKARUS	
30/09/2020	France	Mont d'Artzamendi	C42 - C	Birdstrike and crash during evasive manoeuvre.

Non-commercially operated small aeroplanes

Local date	State/area of	Location name	Manufacturer/model	Headline
	occurrence			
		North See, 4.5 NM west from		Unintended flight in IMC, loss of control and crash to the sea. 1 POB, 1
04/01/2016	Netherlands	Schoorl	CIRRUS - SR20	fatality.
15/01/2016	Spain	0,4 km to Trebujena airfield	RANS - S12	Engine stopped just after take-off - aircraft lost control and crashed.
				Bird strike - left wing partial detachment - aircraft crashed and caught
16/01/2016	Spain	Serranía de Cuenca Natural Park	SOCATA - TB20	fire. 4 POB, 4 fatalities.
09/02/2016	Spain	near Beas de Segura	CESSNA - 172 - P	Aircraft asked a flight path deviation due to bad weather before crash.
21/02/2016	Spain	near Mutxamel airfield	TECNAM	Aircraft collided with a powerline on approach.
21/02/2016	France	near AD Vinon	JODEL	Loss of control during initial climb, aircraft crashed. 1 POB, 1 fatality.
25/02/2016	France	Saint-Héand	EXTRA - EA300 - 200	Collision with high level terrain in adverse weather conditions.
				Aircraft crashed in bad weather conditions. 1 POB, 1 fatal, 1 serious
28/02/2016	Hungary	5km SW from Agostyán, Tata	CESSNA - FA152	injury.
			COMCO IKARUS - IKARUS	Aircraft stall during the initial climb - aircraft struck powerlines,
20/03/2016	United Kingdom	Stoke airfield	C42 - FB100	crashed and caught fire.
20/03/2016	Ireland	EIAB - Abbeyshrule	OTHER	Aircraft crashed while executing rolls. 1 POB, 1 fatality.
25/03/2016	Hungary	near Valkó	TECNAM - P2002 - JF	Aircraft crashed due to loss of control.
30/03/2016	Spain	Perales de Tajuña	CESSNA - 172 - R	A bird strike, wing separation in flight and a crash. 3 POB, 3 fatalities.
				Aircraft crashed and caught fire. The aircraft impacted the ground
01/04/2016	France	Sondernach	ROBIN - HR100 - 210D	with a significant pitch down attitude. 1 POB, 1 fatality.
				Aircraft lost control and collided with terrain on a steep angle. 2 POB,
01/04/2016	Poland	Chmielewo	TECNAM - P2002	2 fatalities.
20/04/2016	Czech Republic	near LKST - Strakonice	CESSNA - 150	Aircraft lost control and crashed into a meadow. 1 POB, 1 fatality.
				Loss of control in flight - Aircraft crashed into a field. 2 POB, 2
30/04/2016	United Kingdom	Whitwell-on-the-Hill	SLINGSBY - T67 - MII	fatalities.

				Aircraft collision with the ground due to unknown reasons 1 DOP 1
05/05/2016	Germany	Grafenau-Lichteneck	MORANE SAULNIER - MS893 - E	Aircraft collision with the ground due to unknown reasons. 1 POB, 1 fatality.
03/03/2010	Germany	Glatenau-Lichteneck	1VI3033 - E	Aircraft spin and crash during flight around the aerodrome. 2 POB, 2
06/05/2016	Austria	near LOAN - Wr.Neustadt / Ost	RANS - S12	fatalities.
19/05/2016	Spain	Arbizu	ROBIN - DR400 - 180	Aircraft crashed due to birdstrike. 3 POB, 3 fatalities.
	•	Coëx	VANS - RV4	
01/06/2016	France	coex	COMCO IKARUS - IKARUS	Engine shut-down in flight and crash. 2 POB, 1 fatal, 1 serious injury.
09/06/2016	United Kingdom	Near Cushendun,	CONICO INAROS - INAROS C42 - FB80	Aircraft crashed into the sea for unknown reasons. 2 POB, 2 fatalities.
03/00/2010	Romania	Persani, BRASOV County	TECNAM	Aircraft crashed for unknown reasons.
		· · ·	OTHER	
03/07/2016	Germany	Mosbach	OTHER	Loss of Control during take-off. 1 POB, 1 fatality.
05/07/2016	Spain	LECU - Madrid / Cuatro Vientos	CIRRUS - SR22	Aircraft crash at the aerodrome during touch and go landing. 2 POB, 2 fatalities.
03/07/2010	Spain	LECO - Madrid / Cdatro Vientos	CIRRUS - SRZZ	After loss of engine power and unsuccessful forced landing due to late
08/07/2016	United Kingdom	1 nm north of Dinton, Wiltshire	YAKOVLEV - YAK52	decision aircraft crashed in field. 2 POB, 1 fatal, 1 serious injury.
08/07/2010	onited kingdom			Aircraft not able to maintain climb due to low speed during take-off
10/07/2016	Austria	LOWZ : Zell am see	PIPER - PA28 - 161	and stalls followed by crash. 4 POB, 1 fatal, 3 serious injuries.
15/07/2016	Spain	Los Garranchos airfield	RANS - S6	Engine shut down in flight - aircraft crashed.
15/07/2010	Spain		IANS - 50	Engine stut-down during initial climb - airplane crash while attempting
15/07/2016	France	nex to LFES - Guiscriff-Scaër	RANS - S6 - ES	return.
20/07/2016	France	near Lacave airfield	NICCOLLIER - HN700	Engine failure after take-off - microlight crash.
03/08/2016	France	LFCV - Villefranche de Rouergue	JODEL	Crash after unsuccessful landing. 1 POB, 1 fatality.
		English Channel, 1 mile from		Engine problem reported - most likely carburettor icing, aircraft
06/08/2016	United Kingdom	Winchelsea	PIPER - PA28 - 161	ditched and sank. 1 POB, 1 fatality.
12/08/2016	France	ALS Col de Bacchus	OTHER	Collision with the ground during take-off on a mountain airstrip.
				Unconsciousness during a training flight in aerobatics and crash. 1
15/08/2016	France	LFNE - Salon / Eyguieres	EXTRA - EA300 - 200	POB, 1 fatality.
16/08/2016	France	Guérande	OTHER	Collision with the ground due to incapacitation.
17/08/2016	France	LFHZ : Sallanches-Mont-Blanc	OTHER	Engine shutdown during climb, pilot lost control of the aircraft.
				Loss of control during the initial climb - aircraft crashed and caught
25/08/2016	France	Saint-Rémy de Maurienne	JODEL - D11	fire. 2 POB, 2 fatalities.
		·	EVEKTOR AEROTECHNIK -	
27/08/2016	Czech Republic	Dlouhá Loucka	EV97	Mid-air Collision of ultra light aircraft.
28/08/2016	France	Sarrouilles	OTHER	Microlight crash during night in IMC conditions.
01/09/2016	Slovenia	near Cezsoca	PIPER - PA28 - 161	Aircraft crashed due to unknown circumstances. 3 POB, 3 fatalities.
01/09/2016	Germany	Herlazhofen	ROBIN - DR400 - 140B	Aircraft crashed after engine failure. 3 POB, 3 fatalities.
03/09/2016	Germany	Dierdorf	OTHER	Aircraft crashed due to unknown circumstances. 1 POB, 1 fatality.
04/09/2016	Germany	Stettiner Haff	SOCATA - TB20	Aircraft crashed into the ocean. 3 POB, 3 fatalities.
01,00,2010	century			

04/09/2016	Poland	Wrocanka	VANS - RV6	Loss of control shortly after take-off. 2 POB, 2 fatalities.
				Aircraft collided with high voltage wires and crashed. 2 POB, 2
05/09/2016	Bulgaria	LBDB:DOLNA BANYA (AIRFIELD)	TECNAM - P92	fatalities.
		Close to Villanueva del Condado		On a long visual flight, the aircraft came down at a meadow close to
06/09/2016	Spain	village (León - Spain)	ROBIN - DR400 - 180	the village buildings. 2 POB, 2 fatalities.
08/09/2016	Germany	Northeim	OTHER	Crash into ground - no more information available.
11/09/2016	France	Pont Farcy	OTHER - Not mapped	Aircraft collided with terrain during low flying.
13/09/2016	Czech Republic	Chocen	OTHER	Loss of speed and aircraft stalled and fell into a forest. The pilot died.
		near Sankt Anton, Steißbachtal		
14/09/2016	Austria	(Vallugabahn)	AQUILA - AT01	Collision with cableway. 1 POB, 1 fatality.
				Two aircraft collided with each other in the vicinity of LHGD. 4 POB, 4
18/09/2016	Hungary	Gödöllo Arboretum	PIPER - PA28 - 140	fatalities.
			EVEKTOR AEROTECHNIK -	Aircraft spin and crash due to a wing collapse caused by an abrupt
18/09/2016	United Kingdom	Near Builth Wells	EV97	manoeuvre.
/ / / /	_			Loss of control at low altitude. Aircraft crashed and caught fire. 2 POB,
27/09/2016	France	Saint Ambroix	VANS - RV8	2 fatalities.
22 /4 2 /2 04 C	the the shift is a dama.		NORTH AMERICAN - P51 -	Aircraft crashed into a tree during aborted landing. 2 POB, 1 fatal, 1
02/10/2016	United Kingdom	near Topcroft Farm Airstrip	D	seriously injured.
04/10/2016	Claualtia			Probable hypoxia of the pilot and icing of the airframe. 1 POB, 1
04/10/2016	SIOVAKIA	near Jakubovany	LANCAIR - 360	fatality.
07/10/2016	Eranco	Varennes-lès-Mâcon	ZENAIR - CH600	Loss of control during an aerodrome circuit, collision with the ground, fire.
07/10/2010	Flance	Val el mes-res-rviacon		Skydiver's parachute was deployed while he was inside the aircraft
15/10/2016	Romania	Luncani, Cluj County	OTHER	and fell to the ground unconscious. 1 fatality.
16/10/2016	Greece	east of Kalabryta	CESSNA - 172 - P	Aircraft crashed into mountain. 2 POB, 2 fatalities.
17/10/2016		near EGSN - Bourn	CESSNA - F150 - M	Aircraft crashed after take-off. 2 POB, 1 fatal, 1 seriously injured.
17/10/2010	United Kingdom			Premature landing gear retraction and crash during take-off. 1 POB, 1
24/11/2016	Poland	EPZP - Zielona Góra	PIPER - PA31 - 350	fatality.
2 1/ 11/ 2010				Aircraft collision with mountain due to unintended flight into IMC. 2
25/11/2016	France	Jarsy	SOCATA - TB20	POB, 2 fatalities.
		54101		Mid-air collision powered ACFT and sailplane; the sailplane crashed,
04/12/2016	United Kingdom	over Lubenham	CESSNA - 150 - L	killing the pilot.
<u> </u>		in approach to LFSB (MLH) : Bâle		
07/12/2016	France	Mulhouse	PIPER - PA34 - 200T	Crash on a highway when trying to land - fire post impact.
19/12/2016	Germany	Garz	TECNAM - P2006T	Aircraft crashed into the forest for unknown reasons. 1 POB, 1 fatality.
	·	Near Aston Rowant Nature		Aircraft flying at low altitude in IMC condition, crashed into woodland.
15/01/2017	United Kingdom	Reserve	PIPER - PA30	1 POB, 1 fatality.

		near LEMT - Casarrubios Del		Aircraft crashed into a field in a high nose down attitude. 2 POB 2
15/01/2017	Spain	Monte	TECNAM - P2002	fatalities.
	- .	near LEAX - La Axarquia-Leoni		Loss of control of the aircraft by steep turn after take-off on runway
19/01/2017	Spain	Benabu	RANS - S6 - ES	30.
02/02/2017	Germany	Melle	DIAMOND - DA20 - A1	Aircraft collided with a wind turbine. 1 POB, 1 fatality.
20/02/2017	Guadeloupe	Petit Bourg	PIPER - PA28 - 161	Airplane crashed into a building while flying at low altitude.
			ALPI AVIATION -	
10/03/2017	France	near LFHL - Langogne / Lespéron	PIONEER200	Collision with the ground after take-off - A/C catch fire.
		Cloncoskoran, near Dungarvan Co.		
27/03/2017	Ireland	Waterford	RUTAN - LONGEZ	Aircraft crashed in a field due to engine failure. 1 POB, 1 fatality.
05/04/2017	Germany	Wedemark	OTHER - Not mapped	Collision with power line, fire, and crash.
				During a go-around manoeuvre, the aircraft collided with trees,
06/04/2017	France	AD Megève	OTHER	crashed and caught fire.
		during initial climb from LFQZ :		
08/04/2017	France	Dieuze-Guéblange	OTHER	Loss of control in flight, collision with the ground - post impact fire.
			EVEKTOR AEROTECHNIK -	Bounced landing, the student pilot lost the aircraft's control after
09/04/2017	France	AD Chelles Le Pin	SPORTSTAR RTC	initiating a go around. The aircraft crashed in a field. 1 POB, 1 fatality.
14/04/2017	Italy	Dovera (CR)	TECNAM - P92	Aircraft crashed on the ground during VFR flight. 2 POB, 2 fatalities.
				During take-off the A/C strikes the tops of the trees. The aircraft
15/04/2017	France	Saint Cybardeaux	OTHER - Not mapped	collides with the ground in a field and catches fire.
17/04/2017	Portugal	Cascais	PIPER - PA31T	Loss of control after failure of critical engine during take off.
29/04/2017	Spain	Canillas de Aceituno	SOCATA - TB20	Inadvertent flight into IMC. Aircraft collided with a mountain.
30/04/2017	France	Sainte-Maxime, col de Bougnon	OTHER	Microlight entered into a spin and crashed.
12/05/2017	France	AD Villefranche-de-Rouergue	OTHER	Aircraft rolled and crashed after take-off.
				Ultralight loss of control and crash due to opening of the canopy in
17/05/2017	France	Bettenheim	AEROSPOOL - WT9	flight.
				Aircraft in low stratus clouds, mist, and fog, lost from radar, wreckage
25/05/2017	United Kingdom	2 miles north of Skipness, Kintyre	PIPER - PA28R - 201	found in water.
				Aircraft partial loss of power as a result of fuel vapor disrupting fuel
				supply to engine during take-off followed by crash in adjacent field. 1
28/05/2017	United Kingdom	Apperknowle	EUROPA	POB, 1 fatality.
				Engine lost power after take-off and the aircraft crashed to the
03/06/2017	France	LFEZ : Nancy-Malzéville	OTHER - Not mapped	ground.
				Pilot loss control of the aircraft while performing an aerodrome
04/06/2017	France	LFEB : Dinan Trélivan	JODEL - D9	circuit. The aircraft crashed to the ground.
17/06/2017	France	Parisot	OTHER - Not mapped	The microlight hit the ground with a strong nose down attitude.

40/06/2017		Spanhoe Airfield,		
18/06/2017	United Kingdom	Northamptonshire	AUSTER	Aircraft stall and crash shortly after take-off.
20/00/2017	C-ach Danublia			Aircraft crashed shortly after take-off. 2 POB, 1 fatality, 1 serious
26/06/2017	Czech Republic	LKHD : Hodkovice	PIPER - L4 - J	injury.
05/07/2017			CZECH SPORT - PS28 - NO	
05/07/2017	Switzerland	near LSGN - Neuchatel	SERIES EXISTS	Pilot lost control after take-off during initial climb. 2 POB, 2 fatalities.
10/07/2017		Lievestuore (municipality of		Aircraft crashed into a forest during final approach in bad weather
19/07/2017	Finland	Laukaa)	PIPER - J3C - 65 - 65	condition.
21/07/2017	Poland	EPML	OTHER	Loss of control shortly after take-off - 2 POB - 2 fatal injuries.
	-		TL ULTRALIGHT - TL2000	Ultralight TL-2000 airplane Crashed close to RWY threshold resulting
26/07/2017	Greece	Terpsithea airfield - LARISSA	STING	to fatal injury of both occupants.
28/07/2017	Poland	EPLL	CESSNA - 152	Aircraft collided with trees during approach. 1 POB, 1 fatality.
01/08/2017	Norway	Oppland county	AQUILA - AT01	Aircraft crashed into mountain. 1 POB, 1 fatality.
				Forced landing on the beach due to engine failure. Aircraft collided
02/08/2017	Portugal	Praia de São João da Caparica	CESSNA - 152	with pedestrians. 2 POB 2 fatal injuries on ground.
04/08/2017	Switzerland	Diavolezza/GR	PIPER - PA28 - 181	Collision with high terrain. 3 POB, 3 fatally injured.
07/08/2017	France	P-F ULM Saint-Estèphe	PIPISTREL	Crash during a low passage right after take-off followed by fire.
				The aircraft crashed into the Lake Bodensee north of Konstanz. 2 POB
08/08/2017	Germany	Bodensee / Mainau	PIPER - PA46	2 fatalities.
				Loss of control with incorrect flap configuration followed by aircraft
19/08/2017	Spain	Coscojuela de Sobrarbe airfield	OTHER	stall and crash during approach.
19/08/2017	Romania	Valcica village, Iasi county	OTHER	Engine failure shortly after take-off. Aircraft loss height and crashed.
20/08/2017	Switzerland	Alp Tsanfleuron, Savièse VS	PIPER - PA28 - 161	Aircraft collided with terrain. 3 POB and 3 fatalities.
				Pilot lost the aircraft control while performing aerobatics manoeuvre
22/08/2017	Norway	near Holmestrand	PITTS - S2 - B	and crashed. 2 POB, 2 fatalities.
26/08/2017	United Kingdom	near EGHA : Compton Abbas	DE HAVILLAND - DH82 - A	Engine problems after take-off - crash on return to airfield.
	~ ~ ~		MORANE SAULNIER -	Collision with the ground due to unknown circumstances. 1 POB 1
27/08/2017	Germany	Moormeerland	MS883	fatality.
31/08/2017	Spain	Sant Pau D'Ordal	ICP - SAVANNAH	Crash in mountainous area in adverse weather conditions.
	.			Aircraft crashed on the ground during VFR approach in poor weather
09/09/2017	Italy	Salussola (BI)	PIPER - PA34	conditions. 1 POB 1 fatality.
10/09/2017	France	Luray	EVEKTOR AEROTECHNIK	The pilot lost control of his aircraft which collided with the ground.
11/09/2017	United Kingdom	Wolferton, Norfolk	PIPER - PA28RT - 201	Rough running engine followed by mayday call.
12/09/2017	France	Ghisonaccia	DIAMOND - DA42	Aircraft crashed due to unknown reasons. 4 POB 4 fatalities.
12,00,202				Aircraft crashes in high terrain - 2 POB - 2 fatally injured - Aircraft
12/09/2017	Switzerland	Braunwald/GL	MOONEY - M20K	destroyed.
19/09/2017	Norway	near ENHA - Hamar / Stafsberg	VANS - RV4	Loss of control on approach, spin and crash. 2 POB, 2 fatalities.
13/03/2017	Norway	near Eining Thanhar / Starsberg		

26/09/2017	Czech Republic	near Noviny pod Ralskem	CESSNA - 421 - B	ENG1 failure en-route, spin, ENG2 shut-down; Crash and fire.
28/09/2017	United Kingdom	Grove Farm, Wolvey	EUROPA - EUROPA	On landing, runway excursion through hedge.
28/09/2017	France	AD Saint-Jean-d'Angély	OTHER - Not mapped	Engine failure, loss of control, collision with the ground, fire.
05/10/2017	Portugal	Marim-Quelfes	KOLB - TWINSTAR - III	Aircraft stalled shortly after take-off and crashed.
05/10/2017	France	LFCL - Toulouse Lasbordes	COLOMBAN	Runway excursion - aircraft overturned.
07/10/2017	Italy	1,5 km from Padenghe sul Garda	TECNAM - P2002	Aircraft crashed on the ground during VFR flight.
08/10/2017	France	LFCN - Nogaro	OTHER - Not mapped	Loss of control on take-off, collision with ground and fire.
08/10/2017	Spain	Escorca, near Binissalem	OTHER	Aircraft collision with mountainous terrain in a narrow valley.
				Stall during a manoeuvre with high inclination and low height shortly
08/10/2017	France	AD Nogaro	FUNK	after takeoff, collision with the ground, fire.
				Malfunction of the pyrotechnic system of the cruise rescue parachute,
16/10/2017	Germany	Jüterbog	AVID - MARK IV	loss of control, collision with the ground.
				Mid-air collision between a Cessna and a Guimbal helicopter fatal
17/11/2017	United Kingdom	near Waddesdon	CESSNA - 152	injuries. 2 POB, 2 fatalities.
		<u>^</u>		Aircraft turn back during cruise in adverse weather conditions, loss of
07/12/2017	New Caledonia	vers AD Île des Pins	TECNAM	radio contact.
			BEST OFF - SKYRANGER	
09/12/2017	United Kingdom	AD Plaistow	NYNJA	Crash after take-off in student solo flight.
		·····	GULFSTREAM -	
04/01/2018	Finland	Kittilä airport, EFKT	GULFSTREAM 150	Fatal injuries to captain due to door opening violently.
00/01/2010		Near Bredon Hill, Overbury,		
08/01/2018	United Kingdom	Worcestershire	PIPER - PA28 - 161	Aircraft struck trees in poor weather.
19/01/2018	Spain	La Pobla de Benifassà(Castellón)	ZENITH - CH601 - XL - XL	Aircraft crashed while flying low. 2 POB, 2 fatalities.
22/01/2018	Cormonu	Dhilippohurg		Mid-air collision between a helicopter and small aircraft. 4 persons
23/01/2018	•	Philippsburg	EUROCOPTER - EC135 - P2	fatally injured.
29/01/2018	Spain	Villamartín aerodrome, Cadiz	BREEZER	Loss of control followed by crash - during training flight in approach.
21/01/2010	Halv	Decomposition (V/D) LIDN		Aircraft crashed in mountainous area during proficiency check - during
31/01/2018	Italy	Boscomantico (VR) - LIPN	CESSNA - F150 - L	circuit pattern downwind in approach.
11/02/2018	Norway	Near Svolvær airport Helle	PIPER - PA28 - 161	Crash into the sea shortly after take-off during night conditions whilst returning to departure airport for unknown reason.
11/02/2010	NUIWay	9,8 NM from EBZW outside the	PIPER - FAZO - 101	
		residential area of Bolderberg		
12/02/2018	Belgium	Heusden Zolder	BEECH - 33 - F33A	Aircraft collided with trees before coming to rest.
12,02,2020				Asymmetrical extension of the flaps in the final, loss of control and
24/02/2018	France	Trignac	DYN AERO - MCR01 - ULC	collision with the ground.
10/03/2018	Germany	Bensheim	ZENAIR - CH601	Airplane crashed due to unknow circumstances. 2 POB, 2 fatalities.
31/03/2018		Proche AD Saint Chamond	ROBIN - DR400 - 120	Runway overrun on take-off, collision with an obstacle.
51/05/2010	Tranec		NODIN DIATOS 120	Runway overran on take on, comsion with an obstacle.

05/04/2018	Niger	АД Тароа	OTHER	Accident for yet unknown reasons. 1 POB, 1 fatality.
				Aircraft crashed after a half roll followed by a half loop-down at low
08/04/2018	France	LFQL : Lens / Bénifontaine	YAKOVLEV - YAK18 - A	height.
		2NM SW Veselí nad Lužnicí near		Ultralight aircraft crashed and debris was scattered over large area. 2
09/04/2018	Czech Republic	Kundratice	OTHER - Not mapped	fatalities.
			CIRRUS - SR20 - NO SERIES	
15/04/2018	Germany	Schwäbisch Hall	EXISTS	Collision of two powered aircraft during approach. 2 fatalities.
19/04/2018	United Kingdom	Crumlin	CESSNA - 152	Aircraft crashed by unknown reasons and caught fire.
21/04/2018	Greece	13.26 km East of City of Nafpaktos	PIPER - PA28 - 140	Collision with cable during emergency landing.
23/04/2018	France	Channay-sur-Lathan ULM airfield	RANS - S6 - ES	Aircraft crash after upset on rejected lading.
				Aircraft stalled during initial climb. Aircraft destroyed and 1POB fatally
24/04/2018	Germany	Mittelfischach	OTHER	injured.
29/04/2018	Austria	next to LOWI - Innsbruck	RUTAN - VARIEZE	Aircraft crash after take-off. 2 fatalities.
01/05/2018	Poland	Skorupy pow. Otwocki	OTHER	Aircraft crash with unknown cause.
04/05/2018	Ireland	near Ballina	OTHER - Not mapped	Aircraft crashed after pilot became unconscious.
				Aircraft hit tree tops at the top of a ridge, collision with the ground,
08/05/2018	France	Marnaves	AQUILA - AT01	post-impact fire.
				Contamination of extruded polystyrene foam with fuel - wing fracture
				due to seepage / fuel leak followed by material separating from A/C
11/05/2018	France	AD Nancy-Essey	RUTAN - VARIEZE	followed by spin, crash, and post impact fire - during initial climb.
16/05/2018	Spain	LESU: La Seu d'Urgell Airport	PIPISTREL	Aircraft crash during go around manoeuvre.
		Low flying area Gouda, near		
22/05/2018	Netherlands	Stolwijk	CESSNA - F172 - N	Collision with trees followed by crash.
26/05/2018	Spain	Vicinity of Loja Aerodrome	AVID - AVID FLYER	Aircraft crash due to a loss of control during the initial climb.
			AEROSPOOL - WT9 - NO	
27/05/2018	Germany	Nürtingen	SERIES EXISTS	Aircraft crashed into a forested mountain. 1 fatality.
31/05/2018	Hungary	Pécs-Pogány Airport, SW 1.8 km	OTHER - Generic	Aircraft crashed after take-off and caught fire after the impact.
				The pilot lost control after a turn and the aircraft got into a spin.
01/06/2018	Germany	Bad Neuenahr/Ahrweiler	MURPHY - RENEGADE	Microlight caught fire after impact on ground.
			RIHN - DR107 - NO SERIES	
01/06/2018	Sweden	Opand airport	EXISTS	Aircraft crashed, possibly after aerobatic manoeuvres. 1 fatality.
				After a manoeuvre to over fly over a mountain the aircraft lost
02/06/2018	•	Malga Casarine - Trento	CESSNA - 152	altitude and crashed.
20/06/2018	Germany	Mosbach	JODEL - D9	Aircraft crashed shortly after take-off.
24/06/2018	France	Arvieu	BEST OFF - SKYRANGER	Collision with a power line followed by crash.
26/06/2018	France	AD Oloron Herrère	OTHER	Aircraft crashed for yet unknown reason.
04/07/2018	Austria	LOAV - Bad Vöslau	CESSNA - 172 - S	Aircraft stall on take-off and crash.

08/07/2018 Latvia Parish Davini BUCKER - BU133 - C Out and the function control, collision with the ground during approach. 09/07/2018 France Ladignac C42 - B Loss of control, collision with the ground during approach. 10/07/2018 Portugal runway 03 threshold CESSNA - 152 runway 03 threshold 10/07/2018 France after take-off from Les Mureaux TECNAM - P2002 - JF instruction flight. 11/07/2018 France Gilliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Gilliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power los during initial clumb, aircraft crashed. 23/07/2018 Sinte-Partouvet Vielvic CESSNA - F172 - N Trajectory deviation. Aircraft crashed after finishing towing a glider. 1 POB 1 29/07/2018 Solvenia Near Airport Bovec ROBIN - DR400 - 180 Engine power los during initial clumb, aircraft crashed after a power los during initial clumb, aircraft crashed. 29/07/2018 Solvenia Near Airport Bovec ROBIN - DR400 - 180 The towing crashed aft					Aircraft terrain collision during emergency landing due to low engine
CDMCO IKARUS - IKARUS 09/07/2018 France Ladignac C42 - B Loss of control, collision with the ground during approach. 10/07/2018 Fortugal runway 02 threshold CESSNA - 152 runway 21. 16/07/2018 France after take-off from Les Mureaux TECNAM - P2002 - JF Instruction flight. 17/07/2018 France Giuliano SOCATA - T820 Low pass over the see and crash. 23/07/2018 France Giuliano SOCATA - T820 Low pass over the see and crash. 23/07/2018 France Gollison with elevated terrain in mountainous area. ZE/07/2018 28/07/2018 France AD Charleville Mézières ROBIN - DRA00 - 180 Callision with elevated terrain in mountainous area. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DRA00 - 180 fatality, aircraft carshed after finishing towing a glider. 1 POB 1 29/07/2018 Slovenia Near Airport Bovec ROBIN - DRA00 - 180 fatality, aircraft crashed after finishing towing a glider. 1 POB 1 29/07/2018 Slovenia Near Airport Bovec ROBIN - DRA00 - 180 fatality, aircraft destroyed. 04/08/	08/07/2018	Latvia	Parish Davini	BUCKER - BU133 - C	
09/07/2018 France Ladignac C42 - B Loss of control, collision with the ground during approach. 10/07/2018 Portugal runway 03 threshold CESSNA - 152 runway 21. 10/07/2018 France after take-off from les Mureaux TECNAM - P2002 - JF Loss of engine power in initial climb, collision with the ground, in instruction flight. 17/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Giuliano RODEN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 Switzerland near Col Durand ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 Solvenia Near Fratavill Vechi alfield, LRSV STEEN - SKYBOLT Collision with a ground aller. 1 POB 1 29/07/2018 Solvenia Near Fratavill Vechi alfield, LRSV STEEN - SKYBOLT Collision with aground and radar contact, collision with the ground. 04/08/2018 Switzerland Renge Pass (LU) SOCATA - TB10 Crash in training fight - during approach. 11/08/2018 France Mazoires CESSNA - 172 - S Loss of radio and radar c	00/07/2010				
Farm Field to 1.2NM West of runway 03 threshold Aircraft crash for unknown reasons during the RH downwind to runway 21. 10/07/2018 France after take-off from Les Mureaux Loss of engine power in initial climb, collision with the ground, in instruction flight. 16/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Saint-Pardoux-et-Vielvic CESSNA - 1712 - N Trajectory deviation. Aircraft crashed. 23/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turnel left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 Engine power loss during training for air show. 04/08/2018 Switzerland Reng Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 Germany Münster BEECH - 58 Crash during raining flight - during approach. 11/08/2018 Germany Nanchausen OTHER - PAL8 - 150 Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018	09/07/2018	France	Ladignac		Loss of control, collision with the ground during approach.
10/07/2018 Portugal runway 03 threshold CESSNA - 152 runway 21. 16/07/2018 France after take-off from Les Mureaux TECNAM - P2002 - JF Loss of engine power in initial climb, collision with the ground, in instruction flight. 10/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Saint-Pardoux-et-Vielvic CESSNA - F172 - N Trajectory deviation. Aircraft crashed. 23/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 Sivenia Near Airport Bovec ROBIN - DR400 - 180 Engine power loos during initial climb, aircraft turned left and stalled. 79/07/2018 Sivenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft during training for air show. 04/08/2018 Romania Near Fratau?il Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 France Maories CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 05/08/2018 France Maories CESSNA - 172 - S Loss of radio and fater a poweri line collision. 1					
Loss of engine power in initial climb, collision with the ground, in instruction flight. 16/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Saint-Pardoux-et-Vielvic CESSNA - F172 - N Trajectory deviation. Aircraft crashed. 23/07/2018 Switzerland near Col Durand ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turned left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft cashed after finishing towing a glider. 1 POB 1 29/07/2018 Romania Near Fratau'il Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 Romania Near Fratau'il Vechi airfield, LRSV STEEN - SKYBOLT Collision with the ground. 05/08/2018 Germany Münster BECH - SK Lows of adiu and radar contact, collision with the ground. <td>10/07/2018</td> <td>Portugal</td> <td>runway 03 threshold</td> <td>CESSNA - 152</td> <td>-</td>	10/07/2018	Portugal	runway 03 threshold	CESSNA - 152	-
Mediterranean Sea, near San Mediterranean Sea, near San 17/07/2018 France Giuliano SOCATA - TB20 Low pass over the see and crash. 23/07/2018 France Saint-Pardoux-et-Vielvic CESSNA - F172 - N Trajectory deviation. Aircraft crashed. 27/07/2018 Switzerland near Col Durand ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 France AD Charleville Méxières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turned left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft during training for air show. 04/08/2018 Romania Near Fratacyli Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 Remany Mazoires CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 05/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed due to unknown reasons, fire and 2 fatalities. 15/08/2018 Germany Nanhausen OTHER Aircraft crashed in the vicinity of the airfield. Unknown reason.					Loss of engine power in initial climb, collision with the ground, in
17/07/2018FranceGiulianoSOCATA - TB20Low pass over the see and crash.23/07/2018FranceSaint-Pardoux-et-VielvicCESSNA - F172 - NTrajectory deviation. Aircraft crashed.27/07/2018Switzerlandnear Col DurandROBIN - DR400 - 180Collision with elevated terrain in mountainous area.28/07/2018FranceAD Charleville MézièresROBIN - DR400 - 180Engine power loss during initial climb, aircraft turned left and stalled.29/07/2018SloveniaNear Airport BovecROBIN - DR400 - 180Fraince durarist crashed after finishing towing a gilder. 1 POB 129/07/2018SilverainaNear Fratau?ii Vechi airfield, LRSVSTEEN - SKYBOLTCollision of two aircraft during training for air show.04/08/2018SwitzerlandRengg Pass (LU)SOCATA - TB10Crash during cruise phase.06/08/2018GermanyMünsterBEECH - 58Crash in training flight - during approach.11/08/2018GermanyEDXG : Melle-GronegauDYN AERO - MCR01Aircraft crashed after a power line collision.16/08/2018GermanyNanhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018FeranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.16/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceRueOTHERCrash during training fli	16/07/2018	France	after take-off from Les Mureaux	TECNAM - P2002 - JF	instruction flight.
23/07/2018 France Saint-Pardoux-et-Vielvic CESSNA - F172 - N Trajectory deviation. Aircraft crashed. 27/07/2018 Switzerland near Col Durand ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turned left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft destroyed. 04/08/2018 Romania Near Fratau?ii Vechi airfield, LSSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 France Mazoires CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 09/08/2018 Germany Münster BEECH - 58 Crash in training flight - during approach. 11/08/2018 Germany EDKG : Melle-Gronegau DYN AERO - MCRO1 Aircraft crashed direr a power line collision. 15/08/2018 Germany Nannhausen OTHER Aircraft crashed inter vicinity of the airfield. Unknown reason. 16/08/2018 France Rue OTHER Crash during training flight followed by post-impact fire. 11/08/2018 Franc			Mediterranean Sea, near San		
27/07/2018 Switzerland near Col Durand ROBIN - DR400 - 180 Collision with elevated terrain in mountainous area. 28/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turned left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft destroyed. 04/08/2018 Romania Near Fratau?ii Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 Switzerland Rengg Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 Germany Münster BEECH - 58 Crash in training flight - during approach. 11/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed after a power line collision. 16/08/2018 Trance Rue OTHER Aircraft crashed after a power line collision. 16/08/2018 France Rue OTHER Crash during training flight followed by post-impact fire. 21/08/2018 France LFJD : Corlier ROBIN - DR400 - 180 Aircraft crashed after a power line collision. 16/08/2018 France LFJD : Corlier ROBI				SOCATA - TB20	•
28/07/2018 France AD Charleville Mézières ROBIN - DR400 - 180 Engine power loss during initial climb, aircraft turned left and stalled. 29/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 fatality, aircraft crashed after finishing towing a glider. 1 POB 1 04/08/2018 Romania Near Fratau?ii Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 Switzerland Rengg Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 France Mazoires CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 09/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed due to unknown reasons, fire and 2 fatalities. 11/08/2018 Germany Nannhausen OTHER Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 France Rue OTHER Crash during training fight followed by post-impact fire. 21/08/2018 France LFJD : Corlier ROBIN - DR400 - 180 Aircraft crash during training fight followed by post-impact fire. 24/08/2018 Bulgaria LBWB CIRRUS	23/07/2018	France	Saint-Pardoux-et-Vielvic	CESSNA - F172 - N	Trajectory deviation. Aircraft crashed.
Z9/07/2018 Slovenia Near Airport Bovec ROBIN - DR400 - 180 The towing aircraft crashed after finishing towing a glider. 1 POB 1 29/07/2018 Slovenia Near Fratav?ii Vechi airfield, LSV STEEN - SKYBOLT Collision of two aircraft destroyed. 04/08/2018 Switzerland Rengg Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 France Mazoires CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 09/08/2018 Germany Münster BEECH - 58 Crash in training flight - during approach. 11/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed due to unknown reasons, fire and 2 fatalities. 15/08/2018 Italy Cimadolmo PIPE - PA18 - 150 Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 France Rue OTHER Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 France Rue OTHER Crash during training flight followed by post-impact fire. 21/08/2018 France Rue OTHER Crash during training ning ning inght followed by post-impact fire.	27/07/2018	Switzerland	near Col Durand	ROBIN - DR400 - 180	Collision with elevated terrain in mountainous area.
29/07/2018SloveniaNear Airport BovecROBIN - DR400 - 180fatality, aircraft destroyed.04/08/2018RomaniaNear Fratau?ii Vechi airfield, LRSVSTEEN - SKYBOLTCollision of two aircraft during training for air show.04/08/2018SwitzerlandRengg Pass (LU)SOCATA - TB10Crash during cruise phase.06/08/2018FranceMazoiresCESSNA - 172 - SLoss of radio and radar contact, collision with the ground.09/08/2018GermanyMünsterBEECH - 58Crash in training flight - during approach.11/08/2018GermanyEDXG : Melle-GronegauDYN AERO - MCR01Aircraft crashed after a power line collision.16/08/2018ItalyCimadolmoPIPER - PAIS - 150Aircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLBWBCIRRUS - SR22left.29/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Calek RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P22 - ETotal loss o	28/07/2018	France	AD Charleville Mézières	ROBIN - DR400 - 180	Engine power loss during initial climb, aircraft turned left and stalled.
04/08/2018 Romania Near Fratau?ii Vechi airfield, LRSV STEEN - SKYBOLT Collision of two aircraft during training for air show. 04/08/2018 Switzerland Rengg Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 France Mazoires CESNA - 172 - S Loss of radio and radar contact, collision with the ground. 09/08/2018 Germany Münster BEECH - 58 Crash in training flight - during approach. 11/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed due to unknown reasons, fire and 2 fatalities. 15/08/2018 Italy Cimadolmo PIPER - PA18 - 150 Aircraft crashed after a power line collision. 16/08/2018 Germany Nannhausen OTHER Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 France Rue OTHER Crash during training flight followed by post-impact fire. 21/08/2018 France Rue OTHER Crash during training flight followed by post-impact fire. 21/08/2018 France Bulgaria LBWB CIRUS - SR22 left. 29/08/2018 France Bourg-Saint-Maurice VANS - RV7 Aircraft crash in					
04/08/2018 Switzerland Rengg Pass (LU) SOCATA - TB10 Crash during cruise phase. 06/08/2018 France Mazoires CESSNA - 172 - S Loss of radio and radar contact, collision with the ground. 09/08/2018 Germany Münster BEECH - 58 Crash in training flight - during approach. 11/08/2018 Germany EDXG : Melle-Gronegau DYN AERO - MCR01 Aircraft crashed due to unknown reasons, fire and 2 fatalities. 15/08/2018 Italy Cimadolmo PIPER - PA18 - 150 Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 Germany Nannhausen OTHER Aircraft crashed in the vicinity of the airfield. Unknown reason. 16/08/2018 Poland Smerek TECNAM - P2002 Low flying; wheel hit a man. 21/08/2018 France Rue OTHER Crash during before the runway threshold, then tilting on the back. 80unced landing with increased angle of attack and bank angle to the Bourg-Saint-Maurice VANS - RV7 Aircraft crash into mountain in unfavourable weather conditions. 08/09/2018 Czech Republic LKTEPL OTHER Loss of control during approach. 11/09/2018 Italy Calatabiano (CT) TECNAM	29/07/2018	Slovenia		ROBIN - DR400 - 180	
06/08/2018FranceMazoiresCESSNA - 172 - SLoss of radio and radar contact, collision with the ground.09/08/2018GermanyMünsterBEECH - 58Crash in training flight - during approach.11/08/2018GermanyEDXG : Melle-GronegauDYN AERO - MCR01Aircraft crashed due to unknown reasons, fire and 2 fatalities.15/08/2018ItalyCimadolmoPIPE - PA18 - 150Aircraft crashed after a power line collision.16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018PolandSmerekTECNAM - P2002Low flying; wheel hit a man.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLBWBCIRRUS - SR22left.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off.26/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018FranceAillant-sur-TholonOTHERLoss of radar contact and collision with the ground.26/09/2018	04/08/2018	Romania	Near Fratau?ii Vechi airfield, LRSV	STEEN - SKYBOLT	Collision of two aircraft during training for air show.
09/08/2018GermanyMünsterBEECH - 58Crash in training flight - during approach.11/08/2018GermanyEDXG : Melle-GronegauDYN AERO - MCR01Aircraft crashed due to unknown reasons, fire and 2 fatalities.15/08/2018ItalyCimadolmoPIPER - PA18 - 150Aircraft crashed after a power line collision.16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLEJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back.21/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceAillant-sur-TholonOTHERCollision with the ground.25/09/2018FranceAillant-sur-TholonOTHERLoss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.16/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAikerslebenTEC	04/08/2018	Switzerland	Rengg Pass (LU)	SOCATA - TB10	Crash during cruise phase.
11/08/2018GermanyEDXG : Melle-GronegauDYN AERO - MCR01Aircraft crashed due to unknown reasons, fire and 2 fatalities.15/08/2018ItalyCimadolmoPIPER - PA18 - 150Aircraft crashed after a power line collision.16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceAillant-sur-TholonOTHERCollision with the ground.25/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.26/09/2018GermanyAlkerslebenTECNAM - P20 - EAircraft crash after engine problems.26/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkersle	06/08/2018	France	Mazoires	CESSNA - 172 - S	Loss of radio and radar contact, collision with the ground.
15/08/2018ItalyCimadolmoPIPER - PA18 - 150Aircraft crashed after a power line collision.16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018PolandSmerekTECNAM - P2002Low flying; wheel hit a man.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAilkerslebenTECNAM - P92 - ETotal loss of nadar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAilkerslebenTECN	09/08/2018	Germany	Münster	BEECH - 58	Crash in training flight - during approach.
16/08/2018GermanyNannhausenOTHERAircraft crashed in the vicinity of the airfield. Unknown reason.16/08/2018PolandSmerekTECNAM - P2002Low flying; wheel hit a man.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back. Bounced landing with increased angle of attack and bank angle to the24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.25/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAiffield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	11/08/2018	Germany	EDXG : Melle-Gronegau	DYN AERO - MCR01	Aircraft crashed due to unknown reasons, fire and 2 fatalities.
16/08/2018PolandSmerekTECNAM - P2002Low flying; wheel hit a man.21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	15/08/2018	Italy	Cimadolmo	PIPER - PA18 - 150	Aircraft crashed after a power line collision.
21/08/2018FranceRueOTHERCrash during training flight followed by post-impact fire.21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back. Bounced landing with increased angle of attack and bank angle to the left.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	16/08/2018	Germany	Nannhausen	OTHER	Aircraft crashed in the vicinity of the airfield. Unknown reason.
21/08/2018FranceLFJD : CorlierROBIN - DR400 - 180Aircraft landing before the runway threshold, then tilting on the back. Bounced landing with increased angle of attack and bank angle to the left.24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAlkerslebenTECNAM - P12 - EAircraft crash after engine problems.10/10/2018United KingdomAlkerslebenTECNAM - P12 - EAircraft crash after engine problems.	16/08/2018	Poland	Smerek	TECNAM - P2002	Low flying; wheel hit a man.
24/08/2018BulgariaLBWBCIRRUS - SR22Bounced landing with increased angle of attack and bank angle to the left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172Seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	21/08/2018	France	Rue	OTHER	Crash during training flight followed by post-impact fire.
24/08/2018BulgariaLBWBCIRRUS - SR22left.29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	21/08/2018	France	LFJD : Corlier	ROBIN - DR400 - 180	Aircraft landing before the runway threshold, then tilting on the back.
29/08/2018FranceBourg-Saint-MauriceVANS - RV7Aircraft crash into mountain in unfavourable weather conditions.08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.					Bounced landing with increased angle of attack and bank angle to the
08/09/2018Czech RepublicLKTEPLOTHERLoss of control during approach.11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	24/08/2018	Bulgaria	LBWB	CIRRUS - SR22	left.
11/09/2018ItalyCalatabiano (CT)TECNAM - P92 - ETotal loss of power after take-off. Impact with terrain.16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.26/09/2018United KingdomAirfield, East Yorkshire.CESSNA - 172Seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	29/08/2018	France	Bourg-Saint-Maurice	VANS - RV7	Aircraft crash into mountain in unfavourable weather conditions.
16/09/2018FranceSaint-SecondinROBIN - DR400 - 120Loss of radar contact and collision with the ground.25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.Approx. 1.5 miles NW of BeverleyThe aircraft was manoeuvring in the final approach area when it was10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	08/09/2018	Czech Republic	LKTEPL	OTHER	Loss of control during approach.
25/09/2018FranceAillant-sur-TholonOTHERCollision with the ground after take-off.26/09/2018GermanyAlkerslebenTECNAM - P92 - EAircraft crash after engine problems.26/09/2018Maprox. 1.5 miles NW of BeverleyThe aircraft was manoeuvring in the final approach area when it was10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	11/09/2018	Italy	Calatabiano (CT)	TECNAM - P92 - E	Total loss of power after take-off. Impact with terrain.
26/09/2018 Germany Alkersleben TECNAM - P92 - E Aircraft crash after engine problems. 26/09/2018 Approx. 1.5 miles NW of Beverley The aircraft was manoeuvring in the final approach area when it was 10/10/2018 United Kingdom Airfield, East Yorkshire. CESSNA - 172 seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	16/09/2018	France	Saint-Secondin	ROBIN - DR400 - 120	Loss of radar contact and collision with the ground.
Approx. 1.5 miles NW of BeverleyThe aircraft was manoeuvring in the final approach area when it was10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	25/09/2018	France	Aillant-sur-Tholon	OTHER	Collision with the ground after take-off.
Approx. 1.5 miles NW of BeverleyThe aircraft was manoeuvring in the final approach area when it was10/10/2018United KingdomAirfield, East Yorkshire.CESSNA - 172Seen to descend rapidly to the ground. 2 POB, both with fatal injuries.	26/09/2018	Germany	Alkersleben	TECNAM - P92 - E	Aircraft crash after engine problems.
			Approx. 1.5 miles NW of Beverley		The aircraft was manoeuvring in the final approach area when it was
13/10/2018 Netherlands near EHST - Stadskanaal PIPISTREL Aircraft loss of control, crash and fire.	10/10/2018	United Kingdom	Airfield, East Yorkshire.	CESSNA - 172	seen to descend rapidly to the ground. 2 POB, both with fatal injuries.
	13/10/2018	Netherlands	near EHST - Stadskanaal	PIPISTREL	Aircraft loss of control, crash and fire.

14/10/2018	Germany	EDER - Wasserkuppe	CESSNA - F172 - N	Runway overrun - aircraft collided with bystanders.
16/10/2018	Germany	near EDKB - Bonn / Hangelar	TECNAM - P2008 - JC	Engine failure - airplane crash.
		Océan Atlantique 60NM ouest		
23/10/2018	France	pointe du Raz	FLIGHT DESIGN - CTLS	Aircraft crashed
25/10/2018	New Caledonia	NWWE (ILP) : Ile Des Pins Moue	ZENAIR - CH601	Engine problem, stall, collision with the ground while test flight.
26/10/2018	France	Beaucaire	OTHER	Collision with the ground - post impact fire.
03/11/2018	Italy	Airfield "Caorle"	SIAI MARCHETTI - SF260 - D	Aircraft crashed after a VFR approach.
07/11/2018	Norway	Near Meraaker Airfield	VANS - RV6	Aircraft crashed due to unknown reasons.
13/11/2018	Spain	coordinates below	CESSNA - 150 - F	Lost control in flight. Aircraft destroyed.
17/11/2018	Germany	over Erkelenz / Kückhoven airfield	REMOS - G3	UL aircraft mid-air collision. 1 fatality and 1 seriously injured.
				Aircraft collided trees on final and crashed into the water (during non-
17/11/2018	France	Pleslin-Trigavou	SOCATA - TB20	precision approach without external visual reference).
			SCOTTISH AVIATION -	
30/11/2018	Hungary	Rábasömjén	BULLDOG	Aircraft collided with cable and crashed.
07/12/2018	Spain	Near LELL: Sabadell Airport	CESSNA - F177RG	Aircraft collided with a building and crashed during approach.
10/12/2018	France	Beaubery	CIRRUS - SR22	Communication lost while en route, collision with elevated terrain.
				Shortly after lift-off (approx. 100ft) aircraft fell and rolled; aircraft
15/12/2018	Netherlands	EHHV	OTHER	impacted with inverted attitude and was fully destroyed.
		approach to VTBT : Chon Buri /		
30/12/2018	Thailand	Bang Phra	FLIGHT DESIGN - CTLS - ELA	Aircraft crash on final approach. Suspected collision with powerlines.
09/01/2019	Spain	Mount Ernio	PIPER - PA28R - 201	Aircraft crash in mountains.
12/01/2019	Germany	Prädikow	PARTENAVIA - P68 - B	Crash into terrain due to unknown reasons.
		Approx. 1.650 m along from		
	_	Kavourotrypes Kryoneri beach of		
16/01/2019	Greece	Mesolongi sea area	MONNETT - SONERAI - 2	Aircraft uncontrollable ditched and sank on the beach.
46/04/2010	6	Sea area at Patraikos Bay - Greece,	MONNETT CONFRAME	
16/01/2019	Greece	1650m from Kryoneri Beach	MONNETT - SONERAI - 2	Ultralight airplane crashed at sea near Kryoneri at Patraikos Bay.
25 /01 /2010	ltal.	Dutor Clasion		Mid-air collision and crash between a helicopter and a Jodel. 6
25/01/2019	Italy	Rutor Glacier	AEROSPATIALE - AS350 - B3	fatalities.
03/02/2019	United Kingdom	near Belchamp Walter	LUTON - LA4 - A	Aircraft lost altitude, rolled and crashed after take-off.
06/02/2019	Spain	1 NM south-east of Quijorna (Madrid)	TECNAM - P2002 - JF	Mid-air collision - 2 fatal injuries.
21/02/2019	France	Port le Grand	OTHER - Not mapped	Ultralight collided with trees in unfavourable weather conditions.
		after take-off from LRTZ : Tuzla	DIAMOND - DA42	
21/02/2019	Romania		EVEKTOR AEROTECHNIK -	Loss of control during take-off followed by crash.
24/02/2019	Spain	LEIR : Aerodromo Air Marugan	EVENTOR AEROTECHNIK -	Loss of control during initial climb and crash.
24/02/2019	Sham	LEIN . ACIOUIUIIIU AII Matugali		

			CZECH SPORT -	
16/03/2019	Portugal	LPBG (BGC) : Bragança	SPORTCRUISER	RH wing failure/separation in flight - aircraft crash.
		Aviosuperficie Alfina (Castel		Aircraft collided with the ground while performing aerobatics
30/03/2019	Italy	Viscardo – Terni)	ZLIN - Z50 - LA	manoeuvres.
31/03/2019	Italy	Chantornè (Torgnon – Aosta)	ZLIN	Loss of control inflight (microlight).
20/04/2019	Bulgaria	Orizari	ZENAIR - CH601	LH wing separation in flight - aircraft crashed.
07/05/2019	France	Saint-Antonin-sur-Bayon	BEST OFF - SKYRANGER	Collision with a mountain due to flight control problems.
14/05/2019	Switzerland	near LSZF : Birrfeld	HB AIRCRAFT	Aircraft crash and fire shortly after take-off.
15/05/2019	Romania	Nehoiasu, Buzau county	TECNAM - P2008 - JC	Aircraft crashed under unknown circumstances.
19/05/2019	Germany	Wilhelmshaven, near	CIRRUS - SR20	Aircraft is missing, last seen over the North-Sea on radar.
25/05/2019	Germany	Elz	AEROPRO - EUROFOX	Microlight crashed in a forest due to unknown reasons. 1 fatality.
26/05/2019	Bulgaria	take-off from LBHT : Ihtiman	PIPISTREL	Aircraft entered spin after take-off.
30/05/2019	Switzerland	near LSGP : La Côte	JODEL - D140 - R	Aircraft crash shortly after take-off during a turn.
09/06/2019	Portugal	next to LPJF : Leiria	BRM AERO - BRISTELL NG5	Aircraft crash followed by post-impact fire after a low pass.
10/06/2019	Germany	EDBW : Werneuchen	OTHER - Not mapped	Microlight crash and fire shortly after take-off.
13/06/2019	Ireland	Belan, near Moone, Co. Kildare	BRM AERO - BRISTELL NG5	Loss of control causing vertical impact with terrain. 2 fatalities.
				Loss of turn control during initial climb followed by collision with
13/06/2019	France	Saillagouse (66)	CESSNA - 172RG	ground and post-impact fire.
21/06/2019	Netherlands	Oudemolen	PIPER - PA18 - 125	Mid-air collision whilst a formation fight.
22/06/2019	North Sea	11NM S of Mandal	PIPER - PA28 - 161	Engine suffered temporary failure - crashed into the ocean.
22/06/2019	Belgium	near EBBZ : Pont-À-Celles / Buzet	ZENAIR - CH601	Aircraft crash on approach. Parachute deployed.
27/06/2019	Switzerland	near of Col de Sonlomont	REMOS - GX	Plane crashed into a forested, steep hillside.
		Wetterstein, 2.5 NM N of 6105		
18/07/2019	Austria	Leutasch	CIRRUS - SR22	Aircraft crashed into a mountain for unknown reasons. 3 fatalities.
22/27/2010	0			During approach phase, the aircraft turned to the left and has a
20/07/2019	Germany	Bruchsal	JODEL - DR1050	collision with a building.
23/07/2019	France	Proche P-F ULM Calviac	OTHER EVEKTOR AEROTECHNIK -	Aircraft collided with the ground due to unknown reasons.
24/07/2019	France	Larche	EVERTOR AEROTECHNIK - EV97 - TEAMEUROSTAR UK	Navigation error in the mountains followed by loss of control during a U-turn.
24/07/2013			EVEKTOR AEROTECHNIK -	The aircraft made a steep left turn during an initial climb and probably
31/07/2019	Finland	EFTP (TMP) : Tampere-Pirkkala	EVERTOR ALKOTECHNIK -	entered into a spin - aircraft crashed.
			EVEKTOR AEROTECHNIK -	Crash into field under unknown circumstances. 1 POB, 1 fatality,
01/08/2019	Germany	Jesenwang	EV97	aircraft destroyed.
06/08/2019	Italy	Monte Carmo (Savona)	DIAMOND - DA20 - A1	Collision with high terrain. 2 POB, 2 fatalities, aircraft destroyed.
		after take-off from LFDJ : Pamiers		
15/08/2019	France	Les Pujols	OTHER	Loss of control after take-off. 1 POB, 1 fatality.

22/08/2019	Germany	Steinfeld	CESSNA - 150 - L	Crash into field due to unknown reasons.
22/08/2019	Germany	Schneizelreuth	CESSNA - FR172 - H	Collision with mountain due to unknown reasons.
24/08/2019	United Kingdom	Stonor (near Henley-on-Thames)	PITTS - S2 - A	Aircraft crashed into field due to unknown reasons.
				Aircraft crashed at the Simplon pass east of the hospice. Aircraft
25/08/2019	Switzerland	Simplon Pass, 6600 ft	PIPER - PA28RT - 201	destroyed by post impact fire.
25/08/2019	France	platform ULM La selle en Hermoy	OTHER	Loss of control in the final approach followed by crash.
			COMCO IKARUS - IKARUS	During a scenic flight, the ultralight had contact with trees and
31/08/2019	Germany	Tiefenbach/Hofen	С42 - В	crashed to the ground. 2 POB. 1 fatality 1 serious injury.
15/09/2019	Spain	Pedreguer	CIRRUS - SR22	Airplane collision with mountain in IMC.
		near LIME (BGY) : Bergamo / Orio		Undefined problems - aircraft return; Loss of control after aborted
21/09/2019	Italy	Al Serio	MOONEY - M20K	landing/go-around and crash.
21/09/2019	France	Putanges-le-lac	OTHER - Not mapped	Seaplane collision with a power line and crash.
				Airplane lost control and crashed in a forest. 2 POB, 2 fatalities,
26/09/2019	Czech Republic	near Petrovice	PIPER - PA22	aircraft destroyed.
28/09/2019	France	Longuesse	DYN AERO - MCR04S	Crash for unknown reason, possible engine failure.
06/10/2019	Ireland	Duncormick, Co. Wexford	ROLLASON - D62 - B	Possible inflight breakup. 2 fatalities.
07/10/2019	France	Jumeauville	OTHER - Not mapped	Ultralight crashed due to unknown reasons.
				Crash for yet unknown reason - while en route in night dual
10/10/2019	Spain	Bonastre	DIAMOND - DA40	instruction flight.
16/10/2019	Réunion	Plaine des Sables	CESSNA - 172 - S	Aircraft crashed after a technical malfunction.
		approach to LFPX : Chavenay		
22/10/2019	France	Villepreux	OTHER	Loss of control on final, collision with ground.
			ALPI AVIATION -	
30/10/2019	France	LFBJ : Saint-Junien	PIONEER200	Loss of control on approach, collision with the ground.
01/11/2019	Italy	near Monti della Tolfa airfield	CESSNA - FA150 - L	Aeroplane collision with powerline on final approach - crash and fire.
		River Labe between village Nucice		
16/11/2019	Czech Republic	and Nucnicky	OTHER	Collision with power lines .
08/12/2019	Lithuania	Noreikiškes	PIPER - PA30	Aeroplane crash after touch-and-go.
15/12/2019	United Kingdom	Northfield Farm, Spilsby	OTHER	Bystander reported engine problem before aircraft crashed.
21/12/2019	Austria	near LOWZ : Zell am See	CIRRUS - SR22 - T	Aircraft crashed during missed approach in IFR.
28/12/2019	France	LFAV : Valenciennes / Denain	OTHER - Generic	Loss of control after take-off and crash.
29/12/2019	Switzerland	Arosa/GR	ZLIN	Aircraft crashed in mountainous terrain.
		near NWWL (LIF) : Lifou		
04/01/2020	New Caledonia	Ouanaham / Iles Loyaute	MOONEY - M20J	Airplane crash after take-off.
07/01/2020	Switzerland	1.2 SW of Buttwil LSZU	CESSNA - F152	Aircraft crashed shortly after take-off.
16/01/2020	Germany	Strausberg	DALLACH - D4	The microlight crashed shortly after take-off.

24/04/2020	Nex			Deep landing combined with poor braking action on icy grass runway
21/01/2020	Norway	Gjølstad	DYN AERO - MCR01 - ULC	resulted in loss of control.
22/01/2020	Switzerland	Near Châtel-St-Denis	PIPER - PA28 - 181	Aircraft crashed into a forest.
11/02/2020	Italy	Airfield "Reno Air Club" (Bologna)	TECNAM - P2002 - JF	Aircraft crashed on the ground after take-off.
12/02/2020	Italy	Carlentini (Siracusa)	TECNAM - P2002 - JF	Loss of control inflight
16/02/2020	Dominica	Au large de la Dominique	PIPER - PA28 - 161	Missed aircraft over the ocean.
16/02/2020	France	Creissels	PIPER - PA28 - 161	Aircraft crashed and caught fire.
18/02/2020	France	Au large de Fécamp	ROBIN - DR400	Aircraft crashed into the sea due to unknown reasons.
				Engine failure, stall on approach, wire strike, crash and post impact
20/02/2020	Spain	Pamplona airport LEPP (PNA)	PIPER - PA60 - 602P	fire.
26/02/2020	France	Elne	PIPER - PA44 - 180	Aircraft crashed for unknown reasons.
17/03/2020	France	AD Vannes	OTHER	Engine shutdown in flight, loss of control, collision with the ground.
19/03/2020	Romania	near Siria Airfield, Arad county	OTHER - Not mapped	Crashed of ultralight aircraft under unknown circumstances.
			BRM AERO - BRISTELL NG5	
24/04/2020	Czech Republic	Svatoborice (Hodonín)	- NO SERIES EXISTS	Ultralight aircraft crashed shortly after take-off due to loss of control.
25/04/2020	Slovenia	Ajdovscina Aerodrome	OTHER - Not mapped	Mid-air collision of an aeroplane and a paraglider and crash of both.
09/05/2020	Lithuania	on approach EYVK : Kyviskes mil	PIPER - PA38 - 112	Loss of control and crash in a field.
11/05/2020	Lithuania	EYVK	PIPER - PA38 - 112	Aircraft crashed close to the aerodrome. Loss of control suspected.
		Sjön Öjjen: 62°13,336'N		
12/05/2020	Sweden	017°18,825'E	OTHER	Accident pilot injured and passenger found dead in the water.
22/05/2020	France	La Ferté-Bernard	OTHER - Not mapped	Crash of aircraft under unknown circumstances.
		proximity of airport Roma Urbe		
25/05/2020	Italy	(LIRU)	DIAMOND - DA20 - C1	Aircraft crashed after take-off and sunk into river.
27/05/2020	Germany	Blomberg	CESSNA - F150 - L	Aeroplane crashed into forest due to unknown reasons.
		Carcassonne Salvaza Aerodrome		
30/05/2020	France	LFMK (CCF)	PITTS - S2 - A	Crash of airplane shortly after take-off and fire post-impact.
		Aviosuperficie Arma di Nettuno		
31/05/2020	Italy	(RM)	TECNAM - P92 - E	Crash of aircraft after take-off.
02/06/2020	Sweden	Ekås	AAI	Accident - Small aeroplane - fatal injuries.
06/06/2020	Germany	Gießen	TL ULTRALIGHT	Loss of control after take-off - aircraft crashed.
17/06/2020	Germany	Reinsfield	PIPER - PA34 - 220T	Broke up in parts of aircraft en route and crashed.
19/06/2020	France	Mortemer	OTHER - Not mapped	Loss of control while cruising. Collision with the ground.
			GROB - G115 -	Runway Excursion during TGL - Collision with obstacle on runway strip
25/06/2020	Czech Republic	LKBE	UNDESIGNATED SERIES	- Damage to aircraft.
04/07/2020	France	Marcé	STAMPE - SV4	Loss of control in flight and crash.
12/07/2020	Germany	Rheinstetten	OTHER - Not mapped	Loss of control in flight due to unknown reasons.

		EPBY (BZG) :		
14/07/2020	Poland	Bydgoszcz/Szweredowo	TECNAM - P2006T	Loss of control during a low pass over runway - crash.
				Electric problem during maintenance check filght – fire and forced
23/07/2020	France	AD Basle-Mulhouse	PIPER - PA28RT - 201T	landing.
25/07/2020	Germany	Wesel-Lackhausen	OTHER - Not mapped	Crash of aircraft into a house and fire post-impact.
02/08/2020	Germany	Heringsdorf	PILATUS - P2	Aircraft stalled during initial climb and crashed.
02/08/2020	France	AD Arras Roclincourt	ISSOIRE - APM30	Loss of control in flight during the last turn, collision with the ground.
04/08/2020	United Kingdom	near Bradley's Lawn airfield	RANS - S6 - 116	Aircraft crashed and fire.
05/08/2020	Germany	Iserlohn / Rheinermark airfield	ZLIN	Aircraft crashed after take-off.
				Bounced landing - Attempted go-around - Loss of control - Aircraft
06/08/2020	France	P-F ULM Cruis Mas Des Grailles	FLIGHT DESIGN - CTSW	crashed and caught fire.
15/08/2020	Poland	near EPKI : KIKITY	BRM AERO - BRISTELL NG5	Aircraft crashed under yet unknown circumstances.
				Aircraft struck treetops - Loss of control - aircraft crashed and caught
15/08/2020	France	AD Saint-Martin de Londres	OTHER	fire.
16/08/2020	Germany	Porta Westfalica	OTHER	Crashed shortly after take-off and caught fire.
26/08/2020	Italy	nearby airfield "Sibari" (CS)	AVIAMILANO	Aircraft crashed shortly after take-off.
29/08/2020	Sweden	59°36,086'N 012°54,225'E	OTHER	ALRS - Accident - Small aeroplane.
			AVIONS FAIREY - TIPSY	
29/08/2020	Belgium	next to EBZH : Hasselt/Kiewit	NIPPER T66 - 2	Crash immediately after take-off.
30/08/2020	Denmark	EKFU : FUR	COMMANDER - 114 - B	Aircraft collided with trees during take-off.
		Bukovno c.p.150, cca 6km NW		Aircraft crashed, due to unknown reasons, into a garden and was
04/09/2020	Czech Republic	Mladá Boleslav	ZLIN - Z526 - AFS	destroyed.
12/09/2020	France	LFCH : Arcachon La Teste De Buch	ROBIN - DR400 - 120	Crash shortly after take-off and caught fire.
12/09/2020	France	Pas de la Coche	ROBIN - DR400 - 140B	Aircraft collided with elevated terrain and caught fire.
13/09/2020	Belgium	Chemin de Camusselle	RANS - S6 - ES	Loss of control inflight - aircraft crashed and caught fire.
16/09/2020	France	Arbent	OTHER	Collision with the ground on initial ascent, fire post-impact.
17/09/2020	Germany	Bienenfarm	DE HAVILLAND - DHC1 - 22	Aircraft lost control and crashed into a field.
10/10/2020	France	Loches	ROBIN - DR400 - 140	Mid-air collision, loss of control, collision with the ground, ULM fire.
11/10/2020	United Kingdom	Troutbeck Airfield	CESSNA - FRA150 - L	Crash after take-off for unknown reasons.
29/10/2020	Czech Republic	Olšany u Prostejova	OTHER - Not mapped	Aircraft crashed due to unknown reasons.
02/11/2020	France	AD Cannes	SOCATA - TB10	Aircraft crashed into the sea during a night flight.
21/11/2020	Germany	Gera	OTHER - Not mapped	Loss of control in flight while en route.
08/12/2020	Germany	Flammersfeld	CESSNA - T41	Descended and then crash landed in a field. Aircraft overturned.
23/12/2020	Germany	Büchenbach / Pegnitz	CESSNA - 172	Aircraft hit trees and crashed in a field.

Microlights

Local date	State/area of	Location name	Manufacturer/model	Headline
	occurrence			
18/01/2010	France	English Channel 20nm Le Touque	OTHER	Microlight crash at sea in bad visibility conditions.
				Collision in flight between a ULM and an aeroplane under solo
04/02/2010	France	Saint-Martin-de-Nigelles (28)	JABIRU - SK	instruction.
21/03/2010	Portugal	Feiteira, Castelo Branco	OTHER	Loss of control
28/03/2010	Hungary	Nagykanizsa	OTHER	Apollo Fox crashed after losing control during flight at low altitude.
			EVEKTOR AEROTECHNIK -	
11/04/2010	Germany	Spenge	EV97 - VLA	Loss of control in flight, 2 POB 2 fatalities.
16/04/2010	Austria	Eidenberg, OÖ	OTHER	Aircraft crashed as a result of a dive causing structural failure.
08/05/2010	Romania	CISNADIE	OTHER	Right wing collapsed during approach. 1 POB 1 fatality.
08/05/2010	France	Etang-Salé (974)	RANS - S6	Loss of control at low height during an engine failure exercise.
			COMCO IKARUS - IKARUS	
25/05/2010	Germany	Wertheim-Sachsenhausen	C42	Loss of control during climb.
05/06/2010	France	AD Castelnaudary (11)	OTHER	Collision with the ground after take-off.
05/06/2010	France	Le Mans (72)	OTHER	Loss of control during low flight, collision with the ground.
			AIR CREATION -	
26/06/2010	France	AD St Rambert-d'Albon (26)	ULTRAFLIGHT FUN	Stall on short final, collision with the ground.
			FLIGHT DESIGN - CT	
26/06/2010	Poland	Stara Wies	SUPRALIGHT	Aircraft crashed after stalling during low flying.
			COMCO IKARUS - IKARUS	
28/06/2010	Germany	Vettweiß-Soller	C42	Engine failure and loss of control in flight of a microlight.
29/06/2010	Greece	Aigio area	OTHER	Stall and crash after low pass.
			EVEKTOR AEROTECHNIK -	Aircraft found crashed in a lake. A gap in the forest exposed the
30/06/2010	Finland	Jämijärvi	EV97 - VLA	aircraft during search and rescue. 2 POB 2 fatalities.
02/07/2010	France	Errouville (54)	OTHER	Collision with ground due to unknown reasons.
			AIR CREATION -	
03/07/2010	France	AD Nîmes Courbessac (30)	ULTRAFLIGHT FUN	Collided with a tree on final, solo.
06/07/2010	Norway	Krogstadfjorden	RANS - S6	Microlight crashed resulting in 2 fatalities.
10/07/2010	Norway	Fagerhaug	RANS - S6	Microlight aircraft crashed, 2 POB, 2 fatalities.
16/07/2010	France	Feurs (42)	OTHER	Loss of control on take-off collision with the ground.
19/07/2010	France	Saint Jeab de Bournay (38)	AIR CREATION	Collision with a house.
23/07/2010	Poland	Radawiec	ZENAIR - CH601	Engine failure and stall. 2 POB, 2 fatalities.
				Loss of control during a 360° turn on final, collision with the ground,
02/08/2010	France	AD lle d'Yeu (85)	ZENAIR	fire.

00/00/2010	Freedor			Bend initiated during low altitude movements, collision with trees,
08/08/2010	France	Milhars (81)	OTHER	fire.
20/08/2010	France	AD Troyes (10)	OTHER	Collision with the ground after take-off.
21/08/2010	Poland	Lodz	OTHER	Ultralight entered a spin and crash.
29/08/2010	Portugal	Lagoa de Óbidos	OTHER	Loss of control during a left turn. 2 POB 2 fatalities.
13/09/2010	Spain	Collado de Sahún (Hu)	TECNAM	Aircraft crashed due to unknown reasons .
18/09/2010	New Caledonia	au large de Poingam	OTHER	Collision with water surface.
				Cessna F172 & Aveko VL3B - Mid-air Collision – 4 POB – 2 OB Fatalities
02/10/2010	France	Les Moëres	OTHER - Not mapped	– 2 OB Minor - F172 Substantial damage - Aveko destroyed.
02/10/2010	Latvia	Vecsaliena, Daugavpils novads	OTHER	Accident with the small aeroplane "Quantum 03S".
11/10/2010	Denmark	Herning Flyveplads (EKHG)	RANS - S12	Engine stopped just after take-off - aircraft lost control and crashed.
15/12/2010	Portugal	Praia da Aguda (Sintra)	TECNAM	Engine failed during take-off.
16/01/2011	Hungary	Eger	OTHER	Ultralight crashed after take-off.
27/02/2011	France	P-F ULM Perreux (89)	OTHER	Stall during the last turn, collision with the ground.
				Collision with terrain during a U-turn in a valley, fire during a
10/03/2011	France	Sault, Mont Ventoux (84)	OTHER	mountain flight.
				Loss of control in basic leg, fall of the passenger, collision with
28/03/2011	France	AD Berck-sur-Mer (80)	OTHER	vegetation.
31/03/2011	France	Lieu dit Haut Haunay (33)	OTHER	Collision with ground due to unknown reasons.
				Bounce during a take-off touchdown, collision with trees during the
06/04/2011	France	P-F ULM Torreilles (66)	OTHER	initial climb.
05/05/2011	Austria	Leogang, S	OTHER	Aircraft crashed on railway line. 2 POB 2 fatalities.
06/05/2011	France	Seyne les Alpes (04)	OTHER	Loss of control during initial climb, collision with the ground.
				Pilot died after the aircraft went off the runway side and hit an
14/05/2011	Spain	AERODROMO GUILLENA-SEVILLA	OTHER	embankment.
				Decrease in power during initial climb, U-turn, loss of control, collision
15/05/2011	France	AD St-Pierre-Pierrefonds (974)	OTHER	with ground, fire.
				Loss of control in flight resulted in a destroyed aircraft and death of
20/05/2011	Germany	Stralsund	OTHER	both occupants.
				Mid-air collision between a glider and LSA aircraft. 3 POB, 3 fatalities,
21/05/2011	Germany	Saarmund	REMOS - G3	both aircraft destroyed.
25/05/2011	France	Levet (18)	OTHER	Collision with a power line, fire.
29/05/2011	Germany	Tannheim	OTHER	Loss of control during approach, 1 POB 1 fatality.
				Loss of control during a practice flight. 2 POB, 1 fatality and 1 serious
30/05/2011	Germany	Barßel	OTHER	injury.
05/06/2011	Latvia	Airfield Cesis	OTHER	Ultralight aircraft Tucano Delta 3 YL-LVJ collision with ground.

	_			Collision with ground due to unknown reasons. Medical reasons
26/06/2011	France	Larressingle (32)	FLIGHT DESIGN - CTLS	suspected.
25/05/2014	2		751110	Loss of control during a practice flight. 2 POB, 1 fatality and 1 serious
26/06/2011	•	Wiefelstede	ZENAIR	injury.
28/06/2011	Czech Republic	Velešín	OTHER	Manoeuvring at low altitude, loss of control and subsequent crash.
				Engine failure after take-off, aircraft made a steep turn and lost
	Czech Republic	LKCM	SKYSTAR - KITFOX	control.
11/07/2011	•	Brno	OTHER	Aircraft crashed shortly after takeoff. 1 POB, 1 fatality.
16/07/2011	Czech Republic	Nová Pec	TECNAM - P92 - EA	Aircraft crashed during off-field landing. 1 POB, 1 serious injury.
			EVEKTOR AEROTECHNIK -	Aircraft entered spin at the top of climb and did not manage to
19/07/2011	Czech Republic	Osek, 2 km N LKRY	EV97 - VLA	recover. 2 POB, 2 fatalities.
		AERÓDROMO DE MARUGÁN		Aircraft impacted terrain during demonstration flight. Reason
28/07/2011		(SEGOVIA)	OTHER	unknown.
02/08/2011	Germany	Steinsfeld, nahe	OTHER	Loss of control in flight. Aircraft crashed causing 2 fatalities.
				Loss of control in flight during an aerobatic evolution in first flight,
17/08/2011	France	Lingreville (50)	OTHER	collision with the water surface.
				Engine stopped on initial climb, U-turn, loss of control, collision with
19/08/2011	France	P-F ULM Torreilles (66)	OTHER	the ground.
			EVEKTOR AEROTECHNIK -	Microlight lost control, started spinning and crashed. 2 POB, 2
21/08/2011	Poland	Lososina Dolna	EV97 - VLA	fatalities.
				Stall while turning, collision with an electric pylon and impact with
24/08/2011		AD Sarlat (24)	OTHER	trees.
28/08/2011	France	P-F ULM Perols sur Vezere (19)	OTHER	Collision with trees during take-off, fire.
28/08/2011	France	Nant Lieu dit Homs (12)	RANS - S6	Engine failure, stall, collision with the ground.
				Loss of control on final, collision with the ground, rollover onto the
01/09/2011	France	P-FULM Montpezat d'Agenais(47)	OTHER	back.
03/09/2011	Germany	Sinningen	OTHER	Aircraft stalled during climb and crashed into a lake.
14/09/2011	France	Doizieux (42)	ZENAIR	Collision with terrain in IMC conditions.
			EVEKTOR AEROTECHNIK -	Aircraft found overturned with no pilot on board. Pilot found dead
23/09/2011	France	Bondigoux (81)	EV97 - TEAMEUROSTAR UK	300 meters away.
01/10/2011	France	P-F ULM Maubec (82)	OTHER	Collision with the ground on the last turn or final.
				Microlight stalled and entered spin until hitting the ground. 2 POB, 2
01/10/2011	Poland	Glebinow	OTHER	fatalities.
15/10/2011	Latvia	Krimulda area	ZLIN	Aircraft collision with terrain.
22/10/2011		Korbach	OTHER	Loss of control during flight.
22/10/2011	•	P-F ULM Cappel (57)	RANS	Rotating propeller fatally injured a person on the ground.
,,	i i difice			

				At approximately 100ft during aerotow take-off, hang glider lost
			CYCLONE AIRSPORTS -	control & impacted the ground. One POB, fatal injuries. Extensive
28/10/2011	United Kingdom	Darley Moor (Derbyshire)	PEGASUS QUANTUM 15	damage.
				The pilot fell from the aircraft and died. The aircraft crashed 2 km
29/10/2011	France	Combovin (26)	OTHER	further on.
10/11/2011	France	Laragne-Monteglin (05)	OTHER	Loss of control in turn, collision with ground in solo instruction.
22/12/2011	Spain	Ambite (Madrid)	TECNAM	Aircraft crashed for unknown reasons.
			AIR CREATION -	
28/12/2011	France	AD privé Corbonod (01)	ULTRAFLIGHT FUN	Loss of control during take-off, collision with the ground.
			COMCO IKARUS - IKARUS	
14/01/2012	Netherlands	Mussel (Groningen)	C42	Loss of control after engine failure.
05/02/2012	Italy	San Donà di Piave - Venezia	OTHER	Aircraft lost wing while manoeuvring.
15/03/2012	Germany	Rockenhausen	OTHER	Loss of control during turning the aircraft.
23/03/2012	Austria	Bodensee	TECNAM - P92 - EA	Aircraft crashed into the Bodensee. 2 POB, 2 fatalities.
			TL ULTRALIGHT - TL2000	Ultralight stalled and crashed shortly after take-off while performing
03/04/2012	Portugal	Benavente, Portugal	STING	airfield circuit.
			COMCO IKARUS - IKARUS	Aircraft crashed onto frozen lake after losing control. 2 POB, 2
11/04/2012	Finland	Rääkkylä lake Pyhäselkä	C42	fatalities.
12/04/2012				After take-off at approx. 300ft the aircraft dropped and impacted the
12/04/2012	United Kingdom	Nr Clackmannan	MAINAIR - GEMINI FLASH	ground. One POB, fatal.
28/04/2012	Czech Republic	6km SSE LKTO	OTHER	Ultralight crashed after flying low and slow. 2 POB, 2 fatalities.
29/04/2012	Poland	Orla Gora	AVIASUD - MISTRAL	Airplane stalled and entered a spin until it crashed. 2 POB, 2 fatalities.
02/05/2012	Deland	Pila	ZENAIR - CH601	Aircraft suffered engine failure then stalled and crashed. 2 POB, 2 fatalities.
03/05/2012	Poland			
06/05/2012	Slovakia	Liskova	OTHER	Aircraft crash due to reasons unknown.
22/05/2012		ESKM	ZENAIR - CH601 - HD - HDS	Microlight suffered an engine failure and crashed into garden - Fatal.
24/05/2012	France	Digny (28)	OTHER	Collision with the ground in degraded weather conditions.
02/06/2012	Portugal	Azóia, Colares, Sintra	OTHER	Loss of control inflight and bad weather conditions.
05/06/2012	Curadan	Fuëlunde einstein	Fundauch	Microlight suffered an engine failure and crashed into a forest and
05/06/2012	Sweden	Frölunda airstrip	Eurocub	caught fire.
14/06/2012	France	Curienne (73)	OTHER	In-flight collision between a sailplane and an ultralight aircraft. 1 person on each aircraft. 1 fatality.
15/06/2012	France	P-F ULM Artigat (09)	OTHER	Loss of control, stall close to the ground.
			OTHER	Collision with the ground during a test flight, fire.
17/06/2012	France	P-F ULM Gellainville (28)	COMCO IKARUS - IKARUS	
24/06/2012	Romania	?iria	COMCO INAROS - INAROS C42 - B	Aircraft crash while turning over a city.
27/06/2012	Germany	Aalen-Heidenheim / Elchingen	OTHER	Loss of control during final approach.
27/00/2012	Germany	Aalen-Heidenneilli / Elchingen	UTTER	

20/20/20/2	_			Microlight suffered structural failure due to overload and crashed
29/06/2012	France	Pierre-Buffière (87)	JABIRU - UL	while flying in sub-optimal weather.
04/07/2012	Germany	Dingolfing	OTHER	Microlight crashed after take-off and caught fire. 1 POB, 1 fatality.
07/07/2012	•	Schönberg	REMOS - GX	Aircraft crashed in a cornfield during initial climb. 1 POB, 1 fatality.
07/07/2012	Romania	Chisineu-cris	OTHER	Motor hang glider stalled and spun to the ground. 1 POB, 1 fatality.
				Microlight loss of control in flight in a low altitude and steep left turn.
03/08/2012	•	Idar-Oberstein	OTHER	2 POB, 1 fatality, 1 serious injury.
10/08/2012		Frangy (74)	OTHER	Canopy retraction, loss of in-flight control, collision with the ground.
19/08/2012	France	Aspres-sur-Buëch (05)	OTHER	Exceeding the VNE, in-flight failure, collision with the ground.
				Right turn and descent after a low passage over the runway, collision
19/08/2012	France	P-F ULM Sainte-Hélène (33)	AVID - AVID FLYER	with the ground, fire.
				Witness saw the aircraft crash into a field. One POB, fatal injuries,
22/08/2012	United Kingdom	Laverstock	CFM - SHADOW	aircraft destroyed.
				Engine misfire, loss of control, spin, collision with ground, fire on
31/08/2012		Saint-Junien (87)	FLIGHT DESIGN - CTSW	impact.
17/09/2012	Germany	Niederschöna	OTHER	Loss of control, aircraft crashed. 2 fatalities.
			COMCO IKARUS - IKARUS	Snow removal was not performed before take-off. Aircraft crashed
22/09/2012		Lill-Blåbergsträsket	С42 - В	after take-off.
23/09/2012	Finland	Utsjoki	OTHER	Ultralight accident due to weight exceedance.
				Failure in flight, loss of control, collision with the sea surface under
07/10/2012		llet du Gosier (971)	ZENAIR - STOL CH701	investigation.
20/10/2012	Iceland	Reykjanes	RANS - S6 - ES	Microlight stalled during turn and crashed.
21/10/2012	Belgium	EBBZ,640 meters north of RWY	RANS - S6	Aircraft came down in corn field.
23/10/2012	France	St Sorlin-de-Vienne (38)	OTHER	Collision with a powerline during flight.
08/11/2012	France	Mardié (45)	OTHER	Wing broke during flight and crashed.
13/11/2012	Sweden	Arvika Westlanda flygplats	ZENAIR - STOL CH701	Microlight suffered structural failure and crashed.
			JABIRU - UL - NO SERIES	Aircraft crashed whilst manoeuvring in an area of low cloud and fog.
08/12/2012	United Kingdom	Aldham	EXISTS	One POB fatally injured. Aircraft destroyed.
				Door detached during circuit, leading to a loss of control. Aircraft hit
12/12/2012	France	Sauvian (34)	OTHER	the ground and a fire erupted. 1 POB Fatal.
		200m North of runway 15		
		threshold, Lameira Farm, Alter	EVEKTOR AEROTECHNIK -	During a low pass, the aircraft hit a small tree and a roof, crashed and
05/01/2013	Portugal	doChão	EV97	caught fire.
			EVEKTOR AEROTECHNIK -	
05/01/2013	Portugal	Herdade Lameira, Alter do Chão	EV97	Collision with tree during low flying.
			COMCO IKARUS - IKARUS	
17/02/2013	Germany	Rüdesheim-Aulhausen	C42	Microlight collided with trees and caught fire.

1/03/2013 Spain Monte[Toledo) OTHER POB, 1 fatal arithy. 27/03/2013 France AD Poully-Maconge (21) OTHER Monte[Toledo) 27/03/2013 France AD Poully-Maconge (21) OTHER Impact. 1 POB. 1 Fatal - ariter and testored. 08/04/2013 Germany Neustadt-Glewe CQMCO IKARUS - IKARUS Runway side excursion, aircraft destroyed. 13/04/2013 Poland Wola Bedkowska OTHER Microlight crashed due to unknown circumstances. 15/04/2013 France Vers AD Niort (79) OTHER Microlight crashed during flight - persons on board died. 03/05/2013 Finland Symä OTHER Ultralight crashed during flight - persons on board died. 03/05/2013 Finland Orivesi RANS - S6 Ultralight crashed during flight - persons on board died. 05/05/2013 Germany Bid Saulgau Airport FILEN Ultralight crashed during flight - persons on board died. 05/05/2013 France Arbois (39) OTHER Ultralight crashed during flight - persons on board died. 05/05/2013 France AD Saint-Fioretin (89) Ultralight crashed during flight or persons on board died. 05/05/2013 France AD Saint-Fioretin (89) OTHER Lessor (Control during initial climb, collision with ground, free. <t< th=""><th></th><th></th><th></th><th></th><th></th></t<>					
27/03/2013 France AD Pouilly-Maconge (21) OTHER Impact. 1 POB - 1 Fatal - aircraft destroyed. 08/04/2013 Germany Neustadt-Giewe C24 Rumway side excursion, aircraft collided with a hangar causing fatal aircraft destroyed. 13/04/2013 France Vers AD Nort (79) OTHER Microlight crashed due to unknown circumstances. 05/05/2013 Finland Sysmä OTHER Decrease of engine power in cruise, forced landing and the ULM tilts 05/05/2013 Finland Sysmä OTHER Ultralight crashed during fight - persons on board died. 05/05/2013 Germany Bad Saulgau Airport FUGHT DESIGN - CT2K Microlight salled shortly after take-off. 08/05/2013 Germany Birlingen AVASUD Microlight salled shortly after take-off. 08/05/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during climb. 04/08/2013 Spain near Milagro EVEVTOR AEROTECHNIK - EVYOR Caught fire. 04/08/2013 France Loss of Control during initial climb. Aircraft destroyed and 1 POB 10/08/2013 <td></td> <td></td> <td></td> <td></td> <td>- ·</td>					- ·
27/03/2013 France AD Pouilly-Maconge (21) OTHER impact. 1 POB - 1 Fatal – aircraft destroyed. 08/04/2013 Germany Neustadt-Giewe CA2 injuries to the student pliot. 13/04/2013 Poland Wola Bedkowska OTHER Microlight crashed due to unknown circumstances. 13/04/2013 France Vers AD Niort (79) OTHER Ofrward. 1 POB - 1 OE Fatal - aircraft destroyed. 03/05/2013 Finland Sysmå OTHER Ultralight crashed during flight - persons on board died. 05/05/2013 Germany Bad Saugau Airport FLIGHT DESIGN - CT2K Microlight stalled shortly after take-off. 08/05/2013 Finland Orivesi RANS - S6 Ultralight carshed during flight - persons on board died. 05/05/2013 France Arbois (39) OTHER Ultralight suffered structural failure and crashed. 06/07/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 03/08/2013 Germany Boll OTHER Loss of control during initial climb, collision with ground, fire. 04/08/2013 France Arbois (39) OTHER Loss of control during initini Climb, co	17/03/2013	Spain	Monte(Toledo)	OTHER	
COMCO IKARUS - IKARUS Rumway side excursion, aircraft collided with a hangar causing fatal injuries to the student pilot. 08/04/2013 Poland Wola Bedkowska OTHER Microlight crashed due to unknown circumstances. 15/04/2013 France Vers AD Niort (79) OTHER Decrease of engine power in cruise, forced landing and the ULM tilts 03/05/2013 Finland Sysmä OTHER Ultralight crashed during flight - persons on board died. 05/05/2013 Germany Bad Saulgau Airport FLIGHT DESIGN - CT2K Microlight suffered servertured on landing and snk - passenger died. 05/05/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 05/06/2013 France Arbois (39) OTHER Ultralight accident - Ground impact. 1 POB - 1 Fatal - aircraft 22/06/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight trashed during initial climb, Aircraft cashed and inginitial climb.		_			
08/04/2013GermanyNeustadt-GleweC42injuries to the student pilot.13/04/2013PolandWola BedkowskaOTHERMicrolight crashed due to unknown circumstances.15/04/2013FranceVers AD Niort (79)OTHERforward. 1 POB - 1 OB Fatal - aircraft destroyed.03/05/2013FinlandSysmäOTHERfinlengt crashed during flight - persons on board died.05/05/2013GermanyBad Saligau AirportFLIGHT DESIGN - CT2KMicrolight stalled shortly after take-off.08/05/2013FinlandOrivesiRANS - S6Ultralight acrient overtured on landing and sank - passenger died.05/06/2013GermanyBirtlingenAVIASUDMicrolight suffered structural failure and crashed.22/06/2013FranceArbois (39)OTHERdestroyed.06/07/2013FranceArbois (39)OTHERLoss of control during initial clinb, collision with ground, fire.14/07/2013United KingdomNear Stoke Golding AirfieldRANS - S6fatal injuries.03/08/2013GermanyBollOTHERMicrolight crashed during climb.04/08/2013Spainnear MilagroEVEKTOR AEROTECHNIK-Bird struck the canopy - pilot lost the controls - aircraft crashed and04/08/2013Spainnear MilagroOTHERAircraft stalled during initial climb. Aircraft cashed and 1 POB07/08/2013FranceLessay (50)OTHERAircraft stalled during initial climb. Aircraft cashed and 1 POB07/08/2013Spainnear MilagroTHERMicrolight in-filist stru	27/03/2013	France	AD Pouilly-Maconge (21)		
13/04/2013 Poland Wola Bedkowska OTHER Microlight crashed due to unknown circumstances. Decrease of engine power in cruise, forced landing and the ULM tilts Decrease of engine power in cruise, forced landing and the ULM tilts 03/05/2013 Finland Sysmå OTHER Ultralight crashed during flight - persons on board died. 03/05/2013 Finland Orivesi RANS - 56 Ultralight acreaft destroyed. 05/05/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 05/06/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 02/06/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 22/06/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - 56 fatal injuries. 03/08/2013 Spain near Milagro EVEKTOR AEROTECHNIK - Bird struck the canopy - pilot lost the controls - aircraft crashed and 14/07/2013 07/08/2013 France Lossay (50) OTHER Collision with an obstacle during initial climb. Aircraft destroyed and 1 POB fatal injured. 10/08/2013 France Holešov OTHER					
JS/04/2013 France Vers AD Niort (79) OTHER forward. 1 POB - 1 OB Fatal - aircraft destroyed. 03/05/2013 Finland Sysmä OTHER Ultralight crashed during fight - persons on board died. 05/05/2013 Germany Bad Saulgau Airport FLIGHT DESIGN - CT2K Microlight stalled shortly after take-off. 08/05/2013 Finland Orivesi RANS - S6 Ultralight aircraft overturned on landing and sank - passenger died. 05/06/2013 France Arbois (39) OTHER destroyed. 06/07/2013 France Arbois (39) OTHER destroyed. 06/07/2013 France Arbois (39) OTHER destroyed. 06/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 04/08/2013 Spain near Milagro CYHCR AEROTECHNIK - Bird struck the canopy - pilot lost the controls - aircraft crashed and curing initial climb. Aircraft destroyed and 1 POB 07/08/2013 France Holešov OTHER Collision with an obstacle during ti		•			· · · ·
15/04/2013FranceVers AD Niort (79)OTHERforward. 1 POB - 1 OB Fatal - aircraft destroyed.03/05/2013FinlandSysmåOTHERUltralight crashed during flight - persons on board died.05/05/2013FinlandOrivesiRANS - S6Ultralight arcraft overturned on landing and sank - passenger died.05/05/2013GermanyBitlingenAVIASUDMicrolight suffered structural failure and crashed.22/06/2013FranceArbois (39)OTHERdestroyed.06/07/2013FranceArbois (39)OTHERLoss of control during initial climb, collision with ground, fire.06/07/2013FranceArbois (39)OTHERLoss of control during initial climb, collision with ground, fire.14/07/2013United KingdomNear Stoke Golding AirfieldRANS - S6fatal injuries.03/08/2013GermanyBollOTHERMicrolight crashed during climb.04/08/2013Spainnear MilagroEVFCOR AEROTECHNIKBird struck the controls - aircraft crashed and04/08/2013Spainnear MilagroEVFCOR AEROTECHNIKEvertice acueght fire.07/08/2013FranceHolešovOTHERCollision with an obstacle during initial climb. Aircraft destroyed.10/08/2013Cech RepublicHolešovOTHERCollision with an obstacle during initial climb. Aircraft testenyed and 1 POB10/08/2013FranceMortlig (17)OTHERCollision with an obstacle during initial climb. Aircraft testenyed.20/08/2013FranceMontig (12)OTHERMicrolight	13/04/2013	Poland	Wola Bedkowska	OTHER	
03/05/2013 Finland Sysmå OTHER Ultralight crashed during flight - persons on board died. 05/05/2013 Germany Bad Saulgau Airport FLIGHT DESIGN - CT2K Microlight stalled shortly after take-off. 05/05/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 05/06/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 05/06/2013 France Arbois (39) OTHER Loss of control during initial climb, collision with ground, fire. 06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 04/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Spain near Milagro EVEKTOR AEROTECHNIK - EVEKTOR AEROTECHNIK -					
05/05/2013 Germany Bad Saulgau Airport FLIGHT DESIGN - CT2K Microlight stalled shortly after take-off. 08/05/2013 Finland Orivesi RANS - S6 Ultralight aircraft overturned on landing and sank - passenger died. 05/06/2013 Germany Birtlingen AVIASUD Microlight stalled shortly after take-off. 22/06/2013 France Arbois (39) OTHER destroyed. 06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Spain near Milagro EVEKTOR AEROTECHNIK - Bird Struck the canopy - pilot lost the controls - aircraft crashed and caught fire. 07/08/2013 France Lessay (50) OTHER Collision with an obstacle during initial climb. Aircraft destroyed and 1 POB 10/08/2013 Germany Gerbach, nahe SERES Microlight in-flight breakup. 2 POB, 2 fatalities. 26/08/2013 Germany Gerbach, nahe SERIES Microlight in-flight breakup. 2 POB, 2 fatalities.			Vers AD Niort (79)		· ·
08/05/2013 Finland Orivesi RANS - S6 Ultralight aircraft overturned on landing and sank - passenger died. 05/06/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 22/06/2013 France Arbois (39) OTHER Ultralight accident - Ground impact. 1 POB - 1 Fatal - aircraft destroyed. 06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 03/08/2013 France Lessay (50) OTHER Microlight in-digito instite controls - aircraft crashed and caught fire. 07/08/2013 France Lessay (50) OTHER Collision with an obstacle during take-off. 0/08/2013 Czech Republic Holešov OTHER fatally injured. 26/08/2013 Germany Gerbach, nahe SENES Microlight in-flight breakup. 2 POB, 2 fatalities. 0/08/2013		Finland	Sysmä		
05/06/2013 Germany Birtlingen AVIASUD Microlight suffered structural failure and crashed. 22/06/2013 France Arbois (39) OTHER destroyed. 06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 04/08/2013 Spain near Milagro EVEKTOR AEROTECHNIK - EVEKTOR AEROTECHNIK - EVETOR AEROTECHNI	05/05/2013	Germany	Bad Saulgau Airport	FLIGHT DESIGN - CT2K	Microlight stalled shortly after take-off.
22/06/2013 France Arbois (39) OTHER destroyed. 06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microfight crashed during climb. 04/08/2013 Spain near Milagro EV97 caught fire. 07/08/2013 France Lessay (50) OTHER Collision with an obstacle during take-off. 01/08/2013 Czech Republic Holešov OTHER fatally injured. 10/08/2013 Germany Gerbach, nahe SERIES Microlight in-flight breakup. 2 POB, 2 fatalities. 26/08/2013 France Montils (17) OTHER ground. 204/09/2013 31/08/2013 France Montils (17) OTHER Aircraft ureck was found in a field. Causes not known. 31/08/2013 France Montagne-Fayel (80) OTHER Aircraft ureck was found in a field. Causes not known. 31/08/2013 France Montagne-Fayel (80) OTHER Aircraft ureck was found in a fie	08/05/2013	Finland	Orivesi	RANS - S6	Ultralight aircraft overturned on landing and sank - passenger died.
22/06/2013FranceArbois (39)OTHERdestroyed.06/07/2013FranceAD Saint-Florentin (89)OTHERLoss of control during initial climb, collision with ground, fire. Aircraft appeared to enter a stall followed by a spin. Two POB, both fatal injuries.03/08/2013United KingdomNear Stoke Golding AirfieldRANS - S6fatal injuries.03/08/2013GermanyBollOTHERMicrolight crashed during climb.04/08/2013Spainnear MilagroEV97caught fire.07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off.01/08/2013Czech RepublicHolešovOTHERAircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.10/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontig (17)OTHERground.30/08/2013FranceMontig (17)OTHERground.31/08/2013FranceMontigne-Fayel (80)OTHERground.31/08/2013FranceMontigne-Fayel (80)OTHERground.31/08/2013FranceMontigne-Fayel (80)OTHERLoss of control during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsieresOTHERUltralight aircraft stalled	05/06/2013	Germany	Birtlingen	AVIASUD	Microlight suffered structural failure and crashed.
06/07/2013 France AD Saint-Florentin (89) OTHER Loss of control during initial climb, collision with ground, fire. 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 04/08/2013 Spain near Milagro EVEKTOR AEROTECHNIK - Bird struck the canopy - pilot lost the controls - aircraft crashed and caught fire. 07/08/2013 France Lessay (50) OTHER Collision with an obstacle during take-off. 10/08/2013 Czech Republic Holešov OTHER fatally injured. 26/08/2013 Germany Gerbach, nahe SERES Microlight in-flight breakup. 2 POB, 2 fatalities. 26/08/2013 France Montils (17) OTHER gound. 31/08/2013 France Montils (17) OTHER caught fire. 0/09/2013 France					Ultralight accident - Ground impact. 1 POB - 1 Fatal - aircraft
Aircraft appeared to enter a stall followed by a spin. Two POB, both 14/07/2013 United Kingdom Near Stoke Golding Airfield RANS - S6 fatal injuries. 03/08/2013 Germany Boll OTHER Microlight crashed during climb. 04/08/2013 Spain near Milagro EV97 caught fire. 07/08/2013 France Lessay (50) OTHER Collision with an obstacle during take-off. 01/08/2013 Czech Republic Holešov OTHER Collision with an obstacle during take-off. 01/08/2013 Czech Republic Holešov OTHER Collision with an obstacle during take-off. 01/08/2013 Germany Gerbach, nahe SERIES Microlight in-flight breakup. 2 POB, 2 fatalities. 00/08/2013 France Montils (17) OTHER Detachment of the canopy in flight, loss of control, collision with the ground. 01/08/2013 France Montagne-Fayel (80) OTHER Aircraft wreck was found in a field. Causes not known. 04/09/2013 France La Roche Soupeze (86) AVIASUD Engine failed during initial climb and aircraft stalled. 05/09/2013 Spain Marugán airfield TECNAM - P92 - EA before th	22/06/2013	France	Arbois (39)	OTHER	destroyed.
14/07/2013United KingdomNear Stoke Golding AirfieldRANS - S6fatal injuries.03/08/2013GermanyBollOTHERMicrolight crashed during climb.04/08/2013Spainnear MilagroEV97Bird struck the canopy - pilot lost the controls - aircraft crashed and caught fire.07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off.10/08/2013Czech RepublicHolešovOTHERfatally injured.10/08/2013Czech RepublicHolešovOTHERfatally injured.26/08/2013GermanyGerbach, naheSEIESMicrolight in-flight breakup. 2 POB, 2 fatalities.30/08/2013FranceMontils (17)OTHERAircraft wreck was found in a field. Causes not known.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled. Loss of control during the final approach - Aircraft crashed 132 m05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUItralight aircraft stalled while manoeuvring. UItralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	06/07/2013	France	AD Saint-Florentin (89)	OTHER	Loss of control during initial climb, collision with ground, fire.
03/08/2013GermanyBollOTHERMicrolight crashed during climb.04/08/2013Spainnear MilagroEV97Bird struck the canopy - pilot lost the controls - aircraft crashed and caught fire.07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off.10/08/2013Czech RepublicHolešovOTHERfatally injured.10/08/2013GermanyGerbach, naheEVEKTOR AEROTECHNIK - EV97 - UNDESIGNATEDMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontils (17)OTHERMicrolight in-flight breakup. 2 POB, 2 fatalities.30/08/2013FranceMontagne-Fayel (80)OTHERAircraft stralled during initial climb. aircraft stalled.30/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.					Aircraft appeared to enter a stall followed by a spin. Two POB, both
EVEKTOR AEROTECHNIK - 04/08/2013Bird struck the canopy - pilot lost the controls - aircraft crashed and caught fire.07/08/2013Spainnear MilagroEV97Bird struck the canopy - pilot lost the controls - aircraft crashed and caught fire.07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off. Aircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.10/08/2013Czech RepublicHolešovOTHERAircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontils (17)OTHER ground.Detachment of the canopy in flight, loss of control, collision with the ground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled. Loss of control during the final approach - Aircraft crashed 132 m before the runway threshold.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	14/07/2013	United Kingdom	Near Stoke Golding Airfield	RANS - S6	fatal injuries.
04/08/2013Spainnear MilagroEV97caught fire.07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off.10/08/2013Czech RepublicHolešovOTHERAircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.10/08/2013Czech RepublicHolešovOTHERFatally injured.26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontils (17)OTHERground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	03/08/2013	Germany	Boll	OTHER	Microlight crashed during climb.
07/08/2013FranceLessay (50)OTHERCollision with an obstacle during take-off.10/08/2013Czech RepublicHolešovOTHERAircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.10/08/2013Czech RepublicHolešovOTHERfatally injured.26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontils (17)OTHERground.30/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.				EVEKTOR AEROTECHNIK -	Bird struck the canopy - pilot lost the controls - aircraft crashed and
Aircraft stalled during initial climb. Aircraft destroyed and 1 POB fatally injured.10/08/2013Czech RepublicHolešovOTHERfatally injured.26/08/2013GermanyGerbach, naheEVEKTOR AEROTECHNIK - EV97 - UNDESIGNATEDEVEKTOR AEROTECHNIK - EV97 - UNDESIGNATED26/08/2013FranceMontils (17)DTHERDetachment of the canopy in flight, loss of control, collision with the ground.30/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.31/08/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.04/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.05/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDUltralight airclaft stalled while manoeuvring.	04/08/2013	Spain	near Milagro	EV97	caught fire.
10/08/2013Czech RepublicHolešovOTHERfatally injured.EVEKTOR AEROTECHNIK - EV97 - UNDESIGNATEDEVEKTOR AEROTECHNIK - EV97 - UNDESIGNATEDEVEKTOR AEROTECHNIK - EV97 - UNDESIGNATED26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.30/08/2013FranceMontils (17)OTHERDetachment of the canopy in flight, loss of control, collision with the ground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	07/08/2013	France	Lessay (50)	OTHER	Collision with an obstacle during take-off.
EVEKTOR AEROTECHNIK - EV97 - UNDESIGNATED26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.26/08/2013FranceMontils (17)OTHERDetachment of the canopy in flight, loss of control, collision with the ground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.					Aircraft stalled during initial climb. Aircraft destroyed and 1 POB
26/08/2013GermanyGerbach, naheEV97 - UNDESIGNATED26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities. Detachment of the canopy in flight, loss of control, collision with the ground.30/08/2013FranceMontils (17)OTHERDetachment of the canopy in flight. Causes not known.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring. Ultralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	10/08/2013	Czech Republic	Holešov	OTHER	fatally injured.
26/08/2013GermanyGerbach, naheSERIESMicrolight in-flight breakup. 2 POB, 2 fatalities.30/08/2013FranceMontils (17)OTHERDetachment of the canopy in flight, loss of control, collision with the ground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring. Ultralight airplane crashed due to carbon monoxide causing incapacitation of the pilot.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.				EVEKTOR AEROTECHNIK -	
30/08/2013FranceMontils (17)OTHERDetachment of the canopy in flight, loss of control, collision with the ground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.				EV97 - UNDESIGNATED	
30/08/2013FranceMontils (17)OTHERground.31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	26/08/2013	Germany	Gerbach, nahe	SERIES	
31/08/2013FranceMontagne-Fayel (80)OTHERAircraft wreck was found in a field. Causes not known.04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled.05/09/2013SpainMarugán airfieldTECNAM - P92 - EALoss of control during the final approach - Aircraft crashed 132 m05/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.07/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.					Detachment of the canopy in flight, loss of control, collision with the
04/09/2013FranceLa Roche Soupeze (86)AVIASUDEngine failed during initial climb and aircraft stalled. Loss of control during the final approach - Aircraft crashed 132 m05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring. Ultralight airplane crashed due to carbon monoxide causing08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	30/08/2013	France	Montils (17)		
05/09/2013SpainMarugán airfieldTECNAM - P92 - EALoss of control during the final approach - Aircraft crashed 132 m before the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring. Ultralight airplane crashed due to carbon monoxide causing incapacitation of the pilot.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	31/08/2013	France	Montagne-Fayel (80)	OTHER	Aircraft wreck was found in a field. Causes not known.
05/09/2013SpainMarugán airfieldTECNAM - P92 - EAbefore the runway threshold.07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.	04/09/2013	France	La Roche Soupeze (86)	AVIASUD	Engine failed during initial climb and aircraft stalled.
07/09/2013BelgiumIsièresOTHERUltralight aircraft stalled while manoeuvring.08/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDincapacitation of the pilot.					Loss of control during the final approach - Aircraft crashed 132 m
O8/09/2013HungaryHajdúszoboszlóCFM - SHADOW - BDUltralight airplane crashed due to carbon monoxide causing	05/09/2013	Spain	Marugán airfield	TECNAM - P92 - EA	before the runway threshold.
08/09/2013 Hungary Hajdúszoboszló CFM - SHADOW - BD incapacitation of the pilot.	07/09/2013	Belgium	Isières	OTHER	Ultralight aircraft stalled while manoeuvring.
					Ultralight airplane crashed due to carbon monoxide causing
08/09/2013 Finland Haapavesi RANS - S6 Ultralight aircraft crashed for unknown reasons, one person died.	08/09/2013	Hungary	Hajdúszoboszló	CFM - SHADOW - BD	incapacitation of the pilot.
	08/09/2013	Finland	Haapavesi	RANS - S6	Ultralight aircraft crashed for unknown reasons, one person died.

13/09/2013	Poland	Chojna	OTHER	Microlight stalled and crashed during initial climb.
17/09/2013	France	Piton Mazerin (974)	RANS - S7	Collision with the terrain in unfavourable weather conditions.
				Overweight flight - aircraft stalled during the last turn before the
21/09/2013	France	LFYK Marville	COLOMBAN - MC15	landing, crashed to the ground and caught fire.
				Pilot reported control problems, aircraft collided with trees and ended
22/09/2013	Germany	Stendal	OTHER	on a field. 2 POB, 2 fatalities.
01/10/2013	France	AD Le Castellet (83)	ZENAIR	Aircraft hit a tree while turning onto final. 2 POB, 2 fatalities.
05/10/2013	Spain	Salobralejo(Ávila)	OTHER	Ultralight flew low and crashed. 2 POB, 2 fatalities.
			CYCLONE AIRSPORTS -	Aircraft hit power lines on approach to land on a farm strip. One POB,
06/10/2013	United Kingdom	Stourton	PEGASUS XL - R	fatally injured.
13/10/2013	France	Les Fourgs (25)	AVIONS MIGNET - HM1000	Wreckage found in the forest, no witnesses.
			EVEKTOR AEROTECHNIK -	
17/10/2013	Germany	Koblenz-Winningen	EV97	Microlight stalled after take-off.
			EVEKTOR AEROTECHNIK -	
30/11/2013	Germany	Beesten	EV97	The microlight crashed on a flat field.
		Open water between Medas		
11/12/2013	Spain	Islands and Norfeu Cape(Girona)	TECNAM - P2002	Aircraft crashed into the ocean. 1 POB, 1 fatality.
02/02/2014	France	Kerozar	OTHER	Loss of control, collision with the ground and post-crash fire
14/02/2014	France	Cahors (46)	OTHER	Ultralight crashed due to unknown circumstances.
			CYCLONE AIRSPORTS -	Aircraft crashed after hitting trees. Aircraft destroyed. Two POB, one
18/04/2014	United Kingdom	Farway Common Airfield	PEGASUS QUIK	fatally injured, one seriously injured.
23/04/2014	Germany	Leutkirch-Unterzeil	OTHER	Microlight stalled during touch-and-go training.
30/04/2014	Portugal	Évora: LPEV	OTHER	Aircraft accident loss of control inflight.
02/05/2014	France	Ghisonaccia (2B)	OTHER	Ultralight crashed due to unknown circumstances.
			MAINAIR - GEMINI FLASH -	Student pilot lost control of microlight on take-off and crashed onto
15/05/2014	United Kingdom	EGCK : Caernarfon	IIA	the taxiway. One POB, fatally injured. Aircraft destroyed.
				Rans S6 - Hit a tree and crashed on the ground, during training – 2
17/05/2014	France	Bailleul-Sir-Berthout (62)	RANS - S6	POB – 2 OB fatal - aircraft destroyed.
				Aircraft crashed in a corn field – 2 POB – 2 OB fatalities - aircraft
28/05/2014	Hungary	Kisapostag	OTHER - Not mapped	destroyed.
28/05/2014	Hungary	near LHDV - Dunaújváros	OTHER	Aircraft entered spin and crashed due to unknown circumstances.
29/05/2014	France	Lalandelle (60)	RANS - S6	Ultralight crashed due to unknown circumstances.
				Engine stopped after take-off, pilot incapacitation, loss of control,
05/06/2014	France	AD Albertville (73)	AVID - AVID FLYER	collision with the ground, fire, during training.
				Aircraft stalled during steep turn right after take-off and crashed. 2
14/06/2014	Spain	LEGY:Garray airfield(Soria)	OTHER	POB, 2 fatalities.
25/06/2014	Latvia		OTHER	Aircraft collision with terrain.

		500m N Kondrac, 6km S Trhové		
26/06/2014	Czech Republic	Sviny	AEROSPOOL - WT9	Ultralight crashed due to unknown circumstances.
				Engine problem during approach, aircraft probably stalled and
02/08/2014	Finland	Haukilahti, Espoo	OTHER - Not mapped	crashed on the water -1POB - 1OB fatal – aircraft destroyed.
			COMCO IKARUS - IKARUS	
08/08/2014	Germany	Kulmbach	C42	Microlight spin during go-around.
15/08/2014	Czech Republic	Near Trebovice, Ústí nad Orlicí	OTHER	Aircraft crashed into a village. 2 POB, 2 fatalities. Cause unknown.
23/08/2014	Czech Republic	Fryšták u Zlína	OTHER	Aircraft collided with a power line, fire and crash.
		Copalnic - Manastur, jud		
23/08/2014	Romania	Maramures	COMCO IKARUS	Aircraft Crashed due to elevator failure.
25/08/2014	France	Saint-Paul d'Espis (82)	OTHER	Aircraft unstable after take-off then collided with the ground.
				Aircraft collided with the ground after 20 minutes of flight, cause
28/08/2014	France	Lapalisse (03)	EVEKTOR AEROTECHNIK	unknown.
07/09/2014	France	Fontenailles (65)	OTHER	Aircraft stalled during a steep left turn after take-off.
				Comco Ikarus C42C - ultralight aircraft caught fire in flight and crashed
			COMCO IKARUS - IKARUS	to the ground 300 m near the runway - 2 POB - 2 OB Fatalities -
11/09/2014	•	Schweighofen	C42	aircraft destroyed.
11/09/2014	Germany	Nausis	OTHER	The microlight had an inflight fracture of the right wing and crashed.
				The aircraft crashed during approach phase after collision with the
14/09/2014	•	Münster-Teltge	DALLACH - D4	rope of another aircraft.
17/09/2014	France	AD Saint-Quentin (02)	AVIASUD	Loss of control inflight and crash with the ground.
I				Mid-air collision. One aircraft crashed into field with the one POB
22/00/2014	Linite of King of one	Townsford		fatally injured. Other aircraft declared MAYDAY but landed on
23/09/2014	United Kingdom	near St Neots, Tempsford	DENNEY - KITFOX - II	aerodrome.
11/11/2014	Paland	Mysliborz	ZENAIR - CH601	Airplane stalled while performing a low pass when it crashed and caught fire.
16/11/2014		Ferrière-La-Grande	ZENAIR - CH601 ZENAIR - CH601	Wing rupture in-flight while performing aerobatics, Aircraft crashed.
10/11/2014		Femere-La-Granue		ICP Savannah - Aircraft lost altitude probably due to a technical
				malfunction and crashed into a restaurant - 2POB - 1OB Fatal - 1OB
26/11/2014	Italy	Cirò Marina, Calabria	ICP - SAVANNAH	Serious - aircraft destroyed.
03/01/2015	•	Campo de Voo de Valdonas, Tomar	TECNAM - P92	Loss of control during hammerhead manoeuvre followed by crash.
00,01,2012		Campo de Voo de Valdonas, ronal Campo de Voo de Alqueidão		
06/02/2015	Portugal	Azambuja	OTHER	Loss of control during initial climb. Aircraft crashed and caught fire.
22/02/2015		Ventosilla	BREEZER	The aircraft encountered terrain inadvertently. Aircraft destroyed.
			EIPPER - QUICKSILVER -	
14/03/2015	Spain	Llucmajor	GT500	Rejected landing - go around - aircraft crashed.
	- 1			

20/02/2015	D á sua ta sa	T D		Loss of the right wing upper surface covering fabric - Loss of control -
30/03/2015	Reunion	Tan Rouge	RANS - S6 - ES	Aircraft crashed.
07/04/2015			FLY BUY ULTRALIGHTS -	Aircraft crashed shortly after take-off. One POB fatally injured. Aircraft
07/04/2015	United Kingdom	EGAD : Newtownards	IKARUS C42	destroyed.
46/04/2015	F	N A		Pilot loss control shortly after take-off and the aircraft collided with
16/04/2015	France	Marguerittes	OTHER	the airport perimeter fence.
20/04/2015	F	Color Managert de Casas	ALPI AVIATION -	Alter of the state of design of the ball
30/04/2015		Saint-Vincent-de-Cosse	PIONEER200	Aircraft crashed during first flight.
22/05/2015	France	Les Hauts-de-Chée	OTHER - Not mapped	Aircraft crash after long, multisector flight.
				Loss of visual references, deployment of emergency parachute in
2.1/25/2015	_			flight, landed on a hangar roof, slid down from the roof and caught
24/05/2015		Ault	LEPAGE - PELICAN	fire.
20/06/2015		Petit-Palais-et-Cornemps	MICRO AVIATION	Loss of control, collision with power lines, crash and fire.
22/06/2015	France	LFFX - Tournus-Cuisery	TECNAM	Loss of control on final, collision with terrain, post-crash fire.
14/07/2015	Norway	Stafsberg	AEROSPOOL - WT9	Fatal crash of microlight aircraft northwest of Hamar aerodrome.
17/07/2015	France	Moulin Papon	AEROPRAKT - A22	Aircraft crashed into a lake.
17/07/2015	Poland	Nowogrod	OTHER	Microlight crash due to unknown reasons.
				Engine failure during initial climb - pilot initiated a turn back. Aircraft
18/07/2015	France	LFHS : Bourg Ceyzériat	OTHER	stalled, crashed and caught fire.
				Loss of control while performing turns on horizontal flight. Aircraft
24/07/2015	France	Laneuveville-en-Saulnois	OTHER	crashed.
25/07/2015	Ireland	Garranbaun, Co. Waterford	BEDE - BD5 - G	Forced landing, due engine fire and control difficulties.
			AIR CREATION -	
26/07/2015	Portugal	Praia de Mira	ULTRAFLIGHT FUN	Engine failure at very low level.
			EVEKTOR AEROTECHNIK -	Accidental opening of the canopy during the take-off - Aircraft return
31/07/2015	France	AD Berck	EV97 - TEAMEUROSTAR UK	at low height - Loss of control - collision with terrain.
				Pilot of an ultralight aircraft misjudged the distance and collided with
01/08/2015	Croatia	Daruvar	OTHER	a hill.
05/08/2015	Germany	Oedheim	SCHEIBE	Loss of control inflight and crash.
21/08/2015	Czech Republic	Lipno	OTHER	Ultralight aircraft crashed during low flying.
			COMCO IKARUS - IKARUS	· · · · · · · · · · · · · · · · · · ·
09/09/2015	Germany	Iserlohn	C42	Aircraft, during a test flight stalled and crashed into a field.
13/09/2015	Germany	Ohrsleben	OTHER	Collision with power cable.
				Ultralight aircraft flew through the Austrian Alps, encountered strong
17/09/2015	Austria	Grießenkar, Flachau	OTHER	winds and crashed.
				Loss of control due to unknown reasons resulting in a violent collision
20/09/2015	Portugal	Valdonas Airfield	OTHER	with the terrain.
	-			

24/00/2015	F	F (1)	EVEKTOR AEROTECHNIK -	Canopy opened during the initial climb - pilot lost the control - aircraft
24/09/2015	France	Fréjus	EV97 - TEAMEUROSTAR UK	crashed and caught fire.
25/00/2015	France	LECE - Decurse Challenges		Engine power decrease during initial climb, aircraft return, collision
25/09/2015	France	LFGF : Beaune Challanges	OTHER	with the ground.
				Engine fire in-flight, pilot returned and tried to perform a forced
10/10/2015	Dalaiuna	near EBAV:HANNUT/AVERNAS-LE-		landing in a field close to the airport. Aircraft crashed and the
18/10/2015	Belgium	BAUDUIN	OTHER	wreckage burned totally.
25/10/2015	Spain	Rwy 27 extension, Mollerussa airfield	TECNAM - P92 - E	Loss of control during take-off manoeuvre being above MTOW, A/C crashed and caught fire.
25/10/2015	Spain	almeiu	TECINAIVI - P92 - E	Ultralight stalled and crashed shortly after take-off while performing
08/11/2015	France	Ménerval	OTHER	airfield circuit.
14/11/2015		Erstein	OTHER	
	France			Aircraft stalled at low height and crashed.
24/12/2015	•	Wetzlar	AEROSPOOL - WT9	Microlight hit trees and crashed on a field.
25/12/2015	France	AD Sainte-Foy-la-Grande	OTHER	Loss of control during the approach. Aircraft crashed and burned.
15/01/2016	Spain	0,4 km to Trebujena airfield	RANS - S12	Engine stopped just after take-off - aircraft lost control and crashed.
13/02/2016	Germany	Hildesheiim - Söhlde	OTHER	Microlight loss of control.
21/02/2016	Spain	near Mutxamel airfield	TECNAM	Aircraft collided with a powerline on approach.
			COMCO IKARUS - IKARUS	Aircraft stall during the initial climb - Aircraft struck powerlines,
20/03/2016	United Kingdom	Stoke airfield	C42 - FB100	crashed and caught fire.
08/05/2016	Germany	Teising	OTHER	Microlight crashed after loss of control.
				On approach to land the A/C was observed to stall - the A/C struck the
				ground in a nearby field of the airfield - both occupants were fatally
30/05/2016	United Kingdom	Near Shifnal Airfield, Shropshire	OTHER	injured.
02/07/2016	Romania	Persani, BRASOV County	TECNAM	Aircraft crashed by unknown reasons.
15/07/2016	Spain	Los Garranchos airfield	RANS - S6	Engine shut down in flight - aircraft crashed.
				Engine stut-down during initial climb - airplane crash while attempting
15/07/2016	France	nex to LFES - Guiscriff-Scaër	RANS - S6 - ES	return.
20/07/2016	France	near Lacave airfield	NICCOLLIER - HN700	Engine failure after take-off - microlight crash.
12/08/2016	France	ALS Col de Bacchus	OTHER	Collision with the ground during take-off on a mountain airstrip.
13/08/2016	Germany	Hasselfelde	OTHER	Crash during climb.
16/08/2016	France	Guérande	OTHER	Collision with the ground.
17/08/2016		LFHZ : Sallanches-Mont-Blanc	OTHER	Engine shutdown during climb, pilot lost control of the aircraft.
			EVEKTOR AEROTECHNIK -	
27/08/2016	Czech Republic	Dlouhá Loucka	EV97	Mid-air collision of two ultralight aircraft.
28/08/2016	•	Sarrouilles	OTHER	Microlight crash during night in IMC conditions.
08/09/2016		Northeim	OTHER	Crash into ground due to unknown reasons.
00,00,2022	oernan,		0 men	

10/09/2016	Germany	Großrückerswalde	FLIGHT DESIGN - CT SUPRALIGHT	Two aircraft, a glider and an ultralight collided close to the threshold. Pilot of the ultralight died.
11/09/2016	France	Pont Farcy	OTHER - Not mapped	Aircraft collided with terrain during low flying.
13/09/2016	Czech Republic	Chocen	OTHER	Aircraft lost speed after take-off and crashed into a forest.
18/09/2016	United Kingdom	Near Builth Wells	EVEKTOR AEROTECHNIK - EV97	Aircraft spin and crash due to a wing collapse caused by an abrupt manoeuvre.
07/10/2016	France	Varennes-lès-Mâcon	ZENAIR - CH600	Loss of control during an aerodrome circuit, collision with the ground, fire.
		near LEAX - La Axarquia-Leoni		
19/01/2017	Spain	Benabu	RANS - S6 - ES	Aircraft crashed for unknown reasons.
29/01/2017	Italy	Caschina Breda - Castelverde	OTHER	Aircraft crashed for unknown reasons.
08/02/2017	Spain	Villaverde aerodrome	TECNAM - P2002	Aircraft crash due to loss of control after stalling during the take off. Engine was not producing power during impact.
10/03/2017	France	near LFHL - Langogne / Lespéron	ALPI AVIATION - PIONEER200	Collision with the ground after take-off - Aircraft caught fire.
05/04/2017	Germany	Wedemark	OTHER - Not mapped	Aircraft collided with a power line, fire and crash.
06/04/2017	France	AD Megève	OTHER	During a go-around manoeuvre, the aircraft collided with trees, crashed and caught fire.
08/04/2017	France	during initial climb from LFQZ : Dieuze-Guéblange	OTHER	Loss of control in flight, collision with the ground - post impact fire.
08/04/2017	France	AD Briare	OTHER - Not mapped	Collision with trees and the ground during an aerodrome circuit.
15/04/2017	France	Saint Cybardeaux	OTHER - Not mapped	During take-off the aircraft struck the tops of the trees. The aircraft collided with the ground in a field and caught fire.
30/04/2017	France	Sainte-Maxime, col de Bougnon	OTHER	Microlight entered into a spin and crashed.
12/05/2017	France	AD Villefranche-de-Rouergue	OTHER	An aircraft crashed into the ground during manoeuvring in the vicinity of the airfield.
17/05/2017	France	Bettenheim	AEROSPOOL - WT9	Ultralight loss of control and crash due to opening of the canopy in flight.
20/05/2017	Spain	vincinity of Flight Field ULM de Gurb	EIPPER - QUICKSILVER - GT500	Aircraft veered to the left, lost altitude and crashed during initial climb.
03/06/2017	France	LFEZ : Nancy-Malzéville	OTHER - Not mapped	Engine lost power after take-off and the aircraft crashed to the ground.
04/06/2017	France	LFEB : Dinan Trélivan	JODEL - D9	Pilot loss control of the aircraft while performing an aerodrome circuit. The aircraft crashed to the ground.
17/06/2017	France	Parisot	OTHER - Not mapped	The microlight hit the ground with a strong nose down attitude.
20/06/2017	United Kingdom	Luffenhall	KOLB	Aircraft impacted ground. One POB fatally injured.
21/07/2017	Germany	Nordsee	OTHER	Microlight disappeared; radar contact ended by the Baltic coast.

20/07/2017	Crease		TL ULTRALIGHT - TL2000	Ultralight TL-2000 airplane Crashed close to RWY threshold resulting
26/07/2017	Greece	Terpsithea airfield - LARISSA	STING	to fatal injury of both occupants.
07/08/2017	France	P-F ULM Saint-Estèphe	PIPISTREL	Crash during a low passage right after take off followed by fire.
19/08/2017	Romania	Valcica village, Iasi county	OTHER	Engine failure shortly after take-off. Aircraft loss height and crashed.
	. .			Loss of control with incorrect flap configuration followed by A/C stall
19/08/2017	Spain	Coscojuela de Sobrarbe airfield	OTHER	and crash - during approach.
31/08/2017	Spain	Sant Pau D'Ordal	ICP - SAVANNAH	Crash in mountainous area in adverse weather conditions.
10/09/2017	France	Luray	EVEKTOR AEROTECHNIK	Ultralight airplane lost control and crashed. 1 POB, 1 fatality.
		mountainous area 6,5 nm NW of		Private Airplane declared missing and found disintegrated in a
22/09/2017	Greece	Kommotini city	FLIGHT DESIGN - CT2K	mountainous area. Both occupants fatally Injured.
28/09/2017	France	AD Saint-Jean-d'Angély	OTHER - Not mapped	Engine failure, loss of control, collision with the ground, fire.
05/10/2017	Portugal	Marim-Quelfes	KOLB - TWINSTAR - III	Aircraft stalled shortly after take-off and crashed.
05/10/2017	France	LFCL - Toulouse Lasbordes	COLOMBAN	RWY excursion - aircraft overturned.
07/10/2017	Italy	1,5 km from Padenghe sul Garda	TECNAM - P2002	Aircraft crashed on the ground during VFR flight.
08/10/2017	Spain	Escorca, near Binissalem	OTHER	Aircraft collision with mountainous terrain in a narrow valley.
				Stall during a manoeuvre with high inclination and low height shortly
08/10/2017	France	AD Nogaro	FUNK	after take-off, collision with the ground, fire.
				Collision with trees in mountainous area in unintended IMC
13/10/2017	Germany	Grebenhain, Vogelsberg	AEROSPOOL - WT9	encounter.
				Malfunction of the pyrotechnic system of the cruise rescue parachute,
16/10/2017	Germany	Jüterbog	AVID - MARK IV	loss of control, collision with the ground.
21/10/2017	Romania	Vantu de Jos, Alba county	OTHER	Aircraft crash after take-off due to unknown reasons.
				Aircraft turn back during cruise in adverse weather conditions, loss of
07/12/2017	New Caledonia	vers AD Île des Pins	TECNAM	radio contact.
			BEST OFF - SKYRANGER	
09/12/2017	United Kingdom	AD Plaistow	NYNJA	Crash after take-off in student solo flight.
				Aircraft stalled, lost control and crashed. 2 POB, 1 fatality, 1 serious
19/01/2018	Spain	La Pobla de Benifassà(Castellón)	ZENITH - CH601 - XL - XL	injury.
/	_			Asymmetrical extension of the flaps in the final, loss of control and
24/02/2018	France	Trignac	DYN AERO - MCR01 - ULC	collision with the ground.
05 /00 /0010	<u> </u>		FLIGHT DESIGN - CT2K - NO	
05/03/2018	Germany	Karlstadt	SERIES EXISTS	Aircraft stalled and lost control during climb phase. 1 POB, 1 fatality.
05/04/2018	Niger	AD Tapoa	OTHER	Aircraft found crashed for yet unknown reasons.
00/01/2015		2NM SW Veselí nad Lužnicí near		
09/04/2018	Czech Republic	Kundratice	OTHER - Not mapped	Aircraft lost control and crashed into the ground. 2 POB, 2 fatalities.
23/04/2018	France	Channay-sur-Lathan ULM airfield	RANS - S6 - ES	Ultralight aircraft crashed after loss of control during rejected lading.

24/04/2018	Company	N ditta liingh ook		Aircraft stalled during initial climb. Aircraft destroyed and 1 POB
24/04/2018	Germany	Mittelfischach	OTHER	fatally injured.
01/05/2018		Skorupy pow. Otwocki	OTHER	Aeroplane crashed, cause unknown.
04/05/2018		near Ballina	OTHER - Not mapped	Aircraft crashed after pilot became unconscious.
16/05/2018	•	LESU: La Seu d'Urgell Airport	PIPISTREL	Aircraft crash during go around manoeuvre.
26/05/2018	Spain	Vicinity of Loja Aerodrome	AVID - AVID FLYER	Aircraft crash due to a loss of control during the initial climb.
			AEROSPOOL - WT9 - NO	Aircraft lost control and crashed into a mountain side while
27/05/2018	•	Nürtingen	SERIES EXISTS	descending. 1 POB, 1 fatality.
31/05/2018	Poland	Bobrowniki gm. Nieborów	OTHER - Not mapped	Ultralight aircraft crashed due to unknown reasons. 2 POB 2 fatalities.
				The pilot lost control after a turn and the aircraft got into a spin.
01/06/2018	Germany	Bad Neuenahr/Ahrweiler	MURPHY - RENEGADE	Microlight caught fire after impact on ground.
24/06/2018	France	Arvieu	BEST OFF - SKYRANGER	Collision with a power line followed by crash.
26/06/2018	France	AD Oloron Herrère	OTHER	Ultralight aircraft crashed for yet unknown reason.
			COMCO IKARUS - IKARUS	
09/07/2018	France	Ladignac	С42 - В	Loss of control, collision with the ground during approach.
				Aircraft crashed and caught fire for reasons unknown. 1 POB, 1
11/08/2018	Germany	EDXG : Melle-Gronegau	DYN AERO - MCR01	fatality.
16/08/2018	Germany	Nannhausen	OTHER	Aircraft crashed for unknown reasons. 1 POB, 1 fatality.
21/08/2018	France	Rue	OTHER	Crash during training flight followed by post-impact fire.
08/09/2018	Czech Republic	LKTEPL	OTHER	Loss of control during approach and crash.
				Aircraft lost all power after take-off and crashed into terrain. 1 POB, 1
11/09/2018	Italy	Calatabiano (CT)	TECNAM - P92 - E	fatality.
				Ultralight aircraft entered spin, crashed and was found completely
18/09/2018	Lithuania	EYSI	RANS - S6	burnt.
				Aircraft crashed with the ground shortly after take-off. 1 POB, 1
25/09/2018	France	Aillant-sur-Tholon	OTHER	fatality.
				Aircraft lost control, stalled and span during approach, crashed and
13/10/2018	Netherlands	near EHST - Stadskanaal	PIPISTREL	caught fire. 1 POB, 1 fatality.
		Océan Atlantique 60NM ouest		
23/10/2018	France	pointe du Raz	FLIGHT DESIGN - CTLS	An aircraft crashed into the ocean.
25/10/2018	New Caledonia	NWWE (ILP) : Ile Des Pins Moue	ZENAIR - CH601	Engine problem, stall, collision with the ground while test flight.
26/10/2018	France	Beaucaire	OTHER	Collision with the ground - post impact fire.
				Two Ultralight aircraft had a mid-air collision. 2 POB, 1 fatality, 1
17/11/2018	Germany	over Erkelenz / Kückhoven airfield	REMOS - G3	serious injury.
04/01/2019	Italy	Sommacampagna	EVEKTOR AEROTECHNIK	Ultralight aircraft crashed into terrain. 1 POB, 1 fatality.
		Sea area at Patraikos Bay - Greece,		
16/01/2019	Greece	1650m from Kryoneri Beach	MONNETT - SONERAI - 2	Ultralight airplane crashed at sea near Kryoneri at Patraikos Bay.

02/02/2010		Dela la constanta la constanta de la constanta		Aircraft stalled shortly after take-off and crashed. Possible engine
03/02/2019	United Kingdom	near Belchamp Walter	LUTON - LA4 - A	failure or flight control problem. 1 POB, 1 fatality.
		1 NMA south a set of Outlines	AIR CREATION -	Million will be and simple to a board 2 DOD 2 fatalities 4 minut
00/02/2010	C !	1 NM south-east of Quijorna	ULTRAFLIGHT FUN - 18S	Mid-air collision, one aircraft crashed. 3 POB, 2 fatalities, 1 minor
06/02/2019	•	(Madrid)	GTBIS	injury.
21/02/2019	France	Port le Grand	OTHER - Not mapped	Ultralight collided with trees in unfavourable weather conditions.
			EVEKTOR AEROTECHNIK -	
24/02/2019	Spain	LEIR : Aerodromo Air Marugan	EV97	Loss of control during initial climb and crashed.
10/00/00/0			CZECH SPORT -	
16/03/2019		LPBG (BGC) : Bragança	SPORTCRUISER	RH wing failure/separation in flight - Aircraft crashed.
31/03/2019	Italy	Chantornè (Torgnon – Aosta)	ZLIN	Loss of control during a fly-by, aircraft entered a spin and crashed.
				Pilot reported flight control problems and collided with a mountain. 1
07/05/2019		Saint-Antonin-sur-Bayon	BEST OFF - SKYRANGER	POB, 1 fatality.
25/05/2019	Germany	Elz	AEROPRO - EUROFOX	Microlight crashed in a forest.
26/05/2019	Bulgaria	take-off from LBHT : Ihtiman	PIPISTREL - Virus SW 100	Aircraft entered spin shortly after take-off. 2 POB, 2 fatalities.
			LONG - MIDGET MUSTANG	Accident of a historic aircraft due to an abrupt manoeuvre followed by
31/05/2019	Poland	Napoleon pow. Klobucki	- NO SERIES EXISTS	a stall and crash.
09/06/2019	Portugal	next to LPJF : Leiria	BRM AERO - BRISTELL NG5	Aircraft crashed followed by post-impact fire after a low pass.
10/06/2019	Germany	EDBW : Werneuchen	OTHER - Not mapped	Microlight crash and fire shortly after take-off.
			AIR CREATION -	
15/06/2019	Italy	URGNANO, VIA MULINO DEI PRATI	ULTRAFLIGHT FUN	A small aircraft crashed into a hillside. 1 POB 1 fatality.
				Aircraft crashed on approach. Emergency parachute was deployed
22/06/2019	Belgium	near EBBZ : Pont-À-Celles / Buzet	ZENAIR - CH601	while flying low. 2 POB, 2 fatalities.
27/06/2019	Switzerland	near of Col de Sonlomont	REMOS - GX	Plane crashed into a forested, steep hillside.
				Aircraft found crashed on the ground in the vicinity of the airfield. 1
23/07/2019	France	Proche P-F ULM Calviac	OTHER	POB, 1 fatality.
			EVEKTOR AEROTECHNIK -	Navigation error in the mountains followed by loss of control during a
24/07/2019	France	Larche	EV97 - TEAMEUROSTAR UK	U-turn.
			EVEKTOR AEROTECHNIK -	
31/07/2019	Finland	EFTP	EV97	Ultralight EV-97 stalled and crashed after take-off, one fatality.
		San Juan del Puerto Port (Huelva –		
23/08/2019	Spain	Spain)	OTHER	A wing of an ultralight aircraft was detached in flight.
		Carretera vieja de Costix, 400m		
25/08/2019	Spain	away from Inca hospital	AEROPRAKT - A22 - L	Mid-air collision between helicopter and ultralight.
25/08/2019	France	platform ULM La selle en Hermoy	OTHER	Loss of control in the final approach followed by crash.
			COMCO IKARUS - IKARUS	During a scenic flight, the ultralight had contact with trees and
31/08/2019	Germany	Tiefenbach/Hofen	С42 - В	crashed to the ground. 2 POB. 1 fatality 1 serious injury.
		·		.

21/09/2019	France	Putanges-le-lac	OTHER - Not mapped	Seaplane collision with a power line and crash.
27/09/2019	Lithuania	Stetiskes, near Panevezys	UNKNOWN	Fatal accident with ultralight Skystar.
07/10/2019	France	Jumeauville	OTHER - Not mapped	Ultralight crashed due to unknown circumstances.
		approach to LFPX : Chavenay		
22/10/2019	France	Villepreux	OTHER	Loss of control on final, collision with ground.
			ALPI AVIATION -	
30/10/2019	France	LFBJ : Saint-Junien	PIONEER200	Loss of control on approach, collision with the ground.
		River Labe between village Nucice		
16/11/2019	Czech Republic	and Nucnicky	OTHER	Collision with Power Lines - Ultralight aircraft crashed.
28/12/2019	France	LFAV : Valenciennes / Denain	OTHER - Generic	Loss of control after take-off and crash.
29/12/2019	Switzerland	Arosa/GR	ZLIN	Aircraft crashed in mountainous terrain.
				Deep landing combined with poor braking action on iced grass runway
21/01/2020	Norway	Gjølstad	DYN AERO - MCR01 - ULC	resulted in loss of control.
11/02/2020	Italy	Airfield "Reno Air Club" (Bologna)	TECNAM - P2002 - JF	Aircraft crashed on the ground after take-off.
19/03/2020	Romania	near Siria Airfield, Arad county	OTHER - Not mapped	Crashed of ultralight aircraft under unknown circumstances.
			BRM AERO - BRISTELL NG5	Aircraft stalled and crashed during turn after take-off. 2 POB, 2
24/04/2020	Czech Republic	Svatoborice (Hodonín)	- NO SERIES EXISTS	fatalities.
25/04/2020	Slovenia	NEAR LJAJ	OTHER	A collision between a plane and a paraglider.
25/04/2020	Slovenia	Ajdovscina Aerodrome	OTHER - Not mapped	Mid-air collision of an Aeroplane and a Paraglider and Crash of both.
22/05/2020	France	La Ferté-Bernard	OTHER - Not mapped	Crash of aircraft under unknown circumstances.
I		Aviosuperficie Arma di Nettuno		
31/05/2020	Italy	(RM)	TECNAM - P92 - E	Crash of aircraft shortly after take-off. 2 POB, 2 fatalities.
06/06/2020	Germany	Gießen	TL ULTRALIGHT	Loss of control after take-off - Aircraft crashed.
19/06/2020	France	Mortemer	OTHER - Not mapped	Loss of control while cruising. Collision with the ground.
10/07/2020	Norway	Meråker	ICP - SAVANNAH - VG	Collision with tree during final approach resulted in fatal accident.
			AEROPRO - EUROFOX - NO	Runway excursion ended in a crash during a go-around. Aircraft
12/07/2020	Germany	Senheld	SERIES EXISTS	caught fire. 1 POB, 1 fatality.
12/07/2020	Germany	Rheinstetten	OTHER - Not mapped	Loss of control caused aircraft to crash. 2 POB, 2 fatalities.
25/07/2020	Germany	Wesel-Lackhausen	OTHER - Not mapped	Crash of aircraft into a house and fire post-impact.
				Aircraft was seen crashing into the ground and catching fire. 1 POB, 1
04/08/2020	United Kingdom	near Bradley's Lawn airfield	RANS - S6 - 116	fatality.
				The aircraft stalled shortly after take-off. 2 POB, 1 fatality and 1
05/08/2020	Germany	Iserlohn / Rheinermark airfield	ZLIN	serious injury.
				Bounced landing - attempted go-around - loss of control - aircraft
06/08/2020	France	P-F ULM Cruis Mas Des Grailles	FLIGHT DESIGN - CTSW	crashed and caught fire.
15/08/2020	Poland	near EPKI : KIKITY	BRM AERO - BRISTELL NG5	Aircraft crashed under yet unknown circumstances.

				Aircraft struck tree tops - loss of control - aircraft crash and caught
15/08/2020	France	AD Saint-Martin de Londres	OTHER	fire.
16/08/2020	Germany	Porta Westfalica	OTHER	Crashed shortly after take-off and caught fire.
29/10/2020	Czech Republic	Olšany u Prostejova	OTHER - Not mapped	Pilot reported engine problems, rapid descent. 1 POB, 1 fatality.
21/11/2020	Germany	Gera	Flying Machines FM25	Loss of control due to unknown reasons 1 POB, 1 fatality.

Aeroplanes registered outside the EASA Member States

Local date	State/area of occurrence	Location name	Manufacturer/model	Headline
15/01/2010	United Kingdom	Oxford	PIPER - PA31	Incapacitation of pilot.
29/05/2010	Spain	Menorca	BEECH - 55	Aircraft crashed after loss of control during a steep turn.
08/12/2010	Italy	Grottarossa Trambus Depot	PIPER - PA32R - 301T	Air crash after take-off at Grottarossa TRAMBUS Depot.
24/04/2011	France	AD Fontenay-Tresigny (77)	YAKOVLEV - YAK52	Loss of control when flying at low height, collision with the ground.
				Aircraft crashed into reservoir. Two POB, both with fatal injuries.
28/04/2011	United Kingdom	Maldon Reservoir (Essex)	YAKOVLEV - YAK52	Substantial aircraft damage.
				Aircraft stalled and crashed in a field due to incorrectly performed
02/08/2011	Netherlands	Near Lelystad Airport (EHLE)	YAKOVLEV - YAK52	circuit procedure.
				Aircraft stalled during a go-around manoeuvre, crashed and caught
09/11/2011	France	Décines-Charpieu	SOCATA - TBM700 - A	fire.
			CIRRUS - SR22 - NO SERIES	
14/11/2011	Germany	Gleisweiler	EXISTS	Cirrus SR22 collided with terrain in fog.
			CESSNA - 750 - NO SERIES	
01/03/2012	Germany	Egelsbach, nahe	EXISTS	Controlled flight into terrain.
21/04/2012	Spain	Albalat de la Ribera	OTHER	Aircraft crashed after take-off due to unknown reasons.
13/07/2012	France	Castellet Airport	GULFSTREAM - GIV	Runway excursion, ground spoilers not deployed delaying the thrust reversers to react. 3 POB, 3 fatalities.
		I		Loss of control in IMC condition - collision with the ground - aircraft
05/01/2013	France	Saint-Geoirs (38)	PIPER - PA34 - 220T	caught fire after the impact.
09/02/2013	Belgium	EBCI	CESSNA - 210	Aircraft crash due to icing and loss of control.
04/03/2013	France	Annemasse Airport	RAYTHEON - 390	Hawker Raytheon Premier 390 - Collision with a House on Take Off.
01/05/2013	Austria	westlich Baumkirchen/Tirol	BEDE - BD5	Aircraft crashed after experiencing technical failures.
				During climb the pilot became incapacitated and loss the control of
27/05/2013	Germany	Wolfsbehringen	PIPER - PA39	the aircraft.
29/05/2013	France	Gap (05)	PIPER - PA28R	Engine fire while cruising, smoke in the cabin, emergency landing, collision with vegetation and then the ground.

		near LFLC (CFE) : Clermont-Ferrand		
08/08/2013	France	Auvergne	SOCATA - TBM700 - N	Aircraft lost control and crashed during approach for landing.
00/00/2013	Trance	Auvergne		Cessna 421 with PT6 engines - loss of control on take-off, A/C crashed
24/09/2013	France	Lyon-Bron Airport, France	CESSNA - 421	and caught fire.
19/11/2013	France	Mouffy (89), FRANCE	SOCATA - TBM700 - B	Aircraft lost control and crashed during descent. 6 POB, 6 fatalities.
				-
12/01/2014	Germany	Near Trier-Föhren Airport	CESSNA - 501	Aircraft collision against power pole due to a VFR flight in IMC.
04/04/2014	Halu	Casarola mountain Collagna	PIPER - PA30	Controlled flight into mountain clana
04/04/2014	Italy	(Reggio Emilia)	PIPER - PASU	Controlled flight into mountain slope. After water landing, A/C flipped in hard wing and high sea condition -
		Laka Vättorn noar Vicingsö		Water rudder left in the down position - 1POB - 1OB Fatal -
14/06/2014	Swadan	Lake Vättern near Visingsö, Jönköping county	CESSNA - TU206 - G	Substantial damage.
14/00/2014	SWeuen		CESSINA - 10200 - G	Jodel D-185 - A/C crashed killing the pilot - 1POB - 1OB Fatal - A/C
25/06/2014	Latvia		JODEL	Destroyed.
23/00/2014	Ldivid	Jelgava	JODEL	Collision with a mountain in cruise - 3POB - 3OB Fatalities - A/C
12/07/2014	France	Urtaca (2B)	PIPER - PA28R - 201T	Destroyed.
12/07/2017	Flance			Loss of control in flight and impact with the ground - 5POB - 2OB
06/08/2014	Franco	Saint-Jean-les-2-Jumeaux (77)	SOCATA - TBM700 - B	Fatalities - 30B Serious - A/C Destroyed.
00/00/2014		Same Jean ies-2-Junicaux (77)		Unspecified ultralight - A/C crashed on a tree covered area - 2POB -
09/08/2014	Italy	Varsi (Parma)		10B Fatal - 10B Serious - A/C Destroyed.
03/00/2011	ιταιγ			Ultralight Kitfox - Aircraft loss heigh during take-off, crashed into a
27/09/2014	Italy	Salgareda, Treviso Airport	DENNEY - KITFOX	vineyard and caught fire - 1POB - 1OB Fatal - A/C Destroyed.
277037201.	icary			ICP Savannah - Aircraft lost altitude probably due to a technical
				malfunction and crashed into a restaurant - 2POB - 10B Fatal - 10B
26/11/2014	Italy	Cirò Marina, Calabria	ICP - SAVANNAH	Serious - A/C Destroyed.
30/01/2015	Switzerland	Bernex	PIPER - PA46 - 350P	Loss of control in flight - Aircraft crashed.
24/05/2015	Ireland	Blackstairs Mt., Co. Carlow	CESSNA - T182 - T	Impact with mountainous terrain.
27/03/2013		Diackstairs with co. carlow		Following TCAS RA to avoid a microlight the aircraft landed long and
31/07/2015	United Kingdom	Blackbushe Airport	EMBRAER - EMB505	then exited the runway.
51/07/2015	Officer Kingdom			Pilot lost the control of the aircraft in IMC condition. Aircraft crashed
14/11/2015	United Kingdom	Buttles Farm, Churchinford	PIPER - PA46 - 350P	in a field.
14/07/2016	Slovenia	7 Km north of AJdovscina	PIPER - PA32R - 301T	Aircraft crash in a wooded field after a "Mayday" call.
14/07/2010	51070110		YAKOVLEV - YAK11 - NO	
25/08/2016	Germany	Speyer	SERIES EXISTS	Loss of control in a turn after take-off.
25/00/2010	Germany	- эреусі	SERIES EXISTS	Aircraft crash during landing due to reported pitch control problems.
06/09/2017	United Kingdom	Caernarfon Airport	PIPER - PA31	1 POB, 1 fatality.
00,00,201.	Officer Kingdoff	mountainous area 6,5 nm NW of		Private Airplane (CT-2K) declared missing and found disintegrated in a
22/09/2017	Greece	Kommotini city	FLIGHT DESIGN - CT2K	mountainous area. Both occupants fatally Injured.
22/03/201/	Greece	Kommotini eity		mountainous area. Both occupants latany injurca.

-				
21/10/2017	Romania	Vantu de Jos, Alba county	OTHER	Aircraft crash after take-off due to unknown reasons.
17/02/2018	France	Saint-Laurent-La-Roche	BEECH - 55 - 95B55	Loss of radio and radar contact while cruising, collision with terrain.
24/03/2018	Switzerland	Arosa/GR	MAULE - M7 - 235	Collision with a bridge after take-off in Arosa.
				Ultralight aircraft entered spin, crashed and was found completely
18/09/2018	Lithuania	EYSI	RANS - S6	burnt.
			LONG - MIDGET MUSTANG	
31/05/2019	Poland	Napoleon pow. Klobucki	- NO SERIES EXISTS	Aircraft crashed due to unknown reasons shortly after take-off.
21/07/2019	United Kingdom	Near Hythe	DE HAVILLAND - DH82 - A	Aircraft rolled into a steeply banked turn crashing on a crop field.
		250 m southeast of the mountain		
		hut "Tschuggenhütte" near the		The aircraft crashed from low altitude above ground and in a rotary
29/11/2019	Switzerland	village of Arosa (GR)	ZLIN	motion into rough terrain.
				Pilot lost control of the aircraft after an engine failure 2 POB, 2
23/02/2020	France	Beaulieu, Puy-de-Dôme	RYAN - ST3KR	fatalities.
				Aircraft crashed most likely due to fuel starvation while performing go
19/09/2020	Germany	Moosburg	RAVEN	around.
20/09/2020	Germany	Kulmbach	PITTS - S1 - S	Loss of control and crash during aerobatics.
		on app to LFQM : Besançon-La-		Crash on approach. Fire post-impact. Likely loss of control during
28/09/2020	France	Vèze	CIRRUS - SR22	approach.

Commercial air transport helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
27/01/2010	Norway	Horten	ROBINSON R44	Helicopter crashed into water
28/10/2010	Antarctica	A 53 NM de Dumont d'Urville	AEROSPATIALE AS350	Helicopter crashed whilst conducting aerial work
04/07/2011	Norway	Dalamot	AEROSPATIALE AS350	Helicopter crashed in turn
11/07/2011	Myanmar	Yetagon oil rig, Andaman Sea	SIKORSKY S76	Pilot performed a ditching due to engine power loss during tak-off
09/11/2011	Italy	Italy	AEROSPATIALE AS365	Helicopter collided with wind turbine
11/11/2011	Italy	Macerata	AGUSTA A109	Helicopter crashed
08/04/2012	Niger	Niger	AEROSPATIALE AS350	Helicopter crashed in the desert
23/08/2013	United Kingdom	near Sumburgh Airport	AEROSPATIALE AS332	Helicopter crashed in the sea during approach to land
14/01/2014	Norway	Near Solihogda, Norway	EUROCOPTER EC135	Medical helicopter struck power lines and crashed
		Under Kláštorná roklina gorge -		Helicopter crashed on a river bank after strike with power cables
17/07/2015	Slovakia	Hornád canyon	AGUSTA A109	during en route HEMS mission
31/07/2015	Italy	Pizzo Zocca di val Masino (Sondrio)	AEROSPATIALE AS350	Controlled flight into a mountain peak obscured by clouds
29/04/2016	Norway	near Turøy	EUROCOPTER EC225	Helicopter crashed during an offshore mission
02/06/2016	Moldova	Haragis	EUROCOPTER EC135	Helicopter crashed in a wood

07/09/2016	Slovakia	Strelníky	BELL 429	Controlled flight into terrain during a HEMS flight in mountainous area
08/09/2016	Austria	Carinthia, ca. 2346 m	ROBINSON R66	Helicopter crashed in a mountainous area
24/01/2017	Italy	Monte Cefalone, Lucoli (AQ)	AGUSTA AW139	Helicopter crashed into a mountain slope during HEMS flight
23/01/2018	Germany	Philippsburg	EUROCOPTER EC135	Mid air collision
15/12/2018	Portugal	1NM South of Valongo	AGUSTA A109	Collision with radio tower in bad weather conditions
25/01/2019	Italy	Rutor Glacier	AEROSPATIALE AS350	Mid-air collision between helicopter and small aeroplane
				HEMS helicopter near miss with a paraglider, loss of control and crash
11/05/2019	France	Le Conquet	EUROCOPTER EC135	of paraglider
		Sea area between Galatas and		
20/08/2019	Greece	Poros island	AGUSTA A109	Helicopter crashed in sea after collision with power lines
		Carretera vieja de Costix, 400m		
25/08/2019	Spain	away from Inca hospital	BELL 206	Mid-air collision between helicopter and ultralight aeroplane
31/08/2019	Norway	near Alta	AEROSPATIALE AS350	Helicopter crashed in mountainous area
				Skier remained hooked with helicopter's utility basket on take-off and
07/01/2020	Italy	Maravidi Mountain	AEROSPATIALE AS350	fell to the ground

Specialised operations helicopters

-	-			
Local Date	State of Occurrence	Location	Aeroplane	Headline
27/06/2010	Netherlands	Maasvlakte, Rotterdam	EUROCOPTER EC130	Loss of control during hover
23/07/2010	Austria	Gahbuhel	BELL 204	Tail rotor collision with tree during sling load operation
31/07/2010	France	Bormes-les-Mimosas (83)	AEROSPATIALE AS350	Vibrations during landing, hard landing
04/08/2010	French Guyana	2 Nm S-E Croisée d'Apatou	AEROSPATIALE AS350	Collision with vegetation during sling load operation
08/08/2010	Belarus	Minsk-Barawaja	HUGHES 369	Helicopter crashed during low level aerobatic flight manoeuvres
17/08/2010	Algeria	Benbakhta, wilaya de Boumerdes	AEROSPATIALE AS350	Helicopter loss of control and subsequent crash
08/03/2011	United Kingdom	Honister Slate Mine, Seatoller	AEROSPATIALE SA341	Aircraft missing later found crashed in valley
26/04/2011	Italy	1.3 NM S-SE of Sulmona (AQ)	ROBINSON R22	Controlled flight into terrain during aerial work
07/06/2011	Spain	Quincoces de Yuso	BELL 407	Helicopter crashed in mountainous area and post-impact fire
15/06/2011	Andorra	Pleta de Juclar (Canillo)	AEROSPATIALE AS350	Helicopter crashed during sling load operation
25/06/2011	Italy	Cison di Valmarino (TV)	SCHWEIZER 269C	Helicopter impacted cables during aerial work
05/08/2011	Italy	Cogolo di Pejo (Trento)	AEROSPATIALE AS350	Collision with obstacles during aerial work
14/09/2011	France	Vallorcine (74)	AEROSPATIALE AS350	Collision with cable car cable and post-impact fire
18/10/2011	Belgium	10km from Liege	EUROCOPTER EC120	Helicopter crashed during aerial work
11/01/2012	Norway	Mosjøen SE of	ROBINSON R44	Helicopter crashed into ground during reindeer herding
14/03/2012	Gabon	near Iguela	BELL 212	Collision with obstacles during sling load operation
06/04/2012	Belgium	Huy	ROBINSON R22	Collision with cable in hover

29/06/2012	Germany	Lieser, nahe	HUGHES 369	Collision with powerline
09/09/2012	Germany	Roßfelder Glider Airfield	EUROCOPTER EC120	Loss of control during an airshow
 				Helicopter crashed due to loss of control caused by a previous rotor
29/06/2013	Switzerland	Switzerland	AEROSPATIALE AS350	strike
L				Helicopter crashed in a mountainous area and caught fire in unknown
01/07/2013	Switzerland	Switzerland	AEROSPATIALE AS350	circumstances
12/11/2013	France	Saint-Chaffrey	AEROSPATIALE AS350	Helicopter crashed after hitting a cable of a chairlift
18/12/2013	Portugal	near Monchique	EUROCOPTER EC120	Helicopter collision with power lines and crash.
				Helicopter crashed in a mountainous snow-covered area during aerial
14/07/2015	Switzerland	Guggigletscher, Lauterbrunnen	AEROSPATIALE AS350	work mission
l -				Helicopter turned back due to bad weather conditions and crashed
31/12/2015	Réunion	Rempart du Maïdo	AEROSPATIALE AS350	shortly afterwards
19/05/2016	Bulgaria	Gylovtsa village, Nesebar	ΚΑΜΟΥ ΚΑ26	Collision with power lines
l -				helicopter overturned onto its side and rolled over during landing in a
13/05/2017	Switzerland	Petersgrat	AEROSPATIALE AS350	mountainous area
26/09/2017	Sweden	Högheden	HUGHES 369	Helicopter accident during power line inspection flight
11/06/2018	Switzerland	near Attinghausen	AEROSPATIALE AS350	Helicopter crashed
13/06/2018	United Kingdom	Loch Scadavay, North Uist	AEROSPATIALE AS350	Helicopter crashed in a lake sling load operation
07/01/2019	France	near Castres	AEROSPATIALE AS350	Helicopter crashed during sling load operation
				Helicopter crashed for unknown reasons while performing a
06/07/2020	Spain	near LESU : Seo de urgel	AEROSPATIALE AS350	powerline survey mission
19/05/2016 13/05/2017 26/09/2017 11/06/2018 13/06/2018 07/01/2019	Bulgaria Switzerland Sweden Switzerland United Kingdom France	Gylovtsa village, Nesebar Petersgrat Högheden near Attinghausen Loch Scadavay, North Uist near Castres	KAMOV KA26 AEROSPATIALE AS350 HUGHES 369 AEROSPATIALE AS350 AEROSPATIALE AS350 AEROSPATIALE AS350	shortly afterwardsCollision with power lineshelicopter overturned onto its side and rolled over during landing mountainous areaHelicopter accident during power line inspection flightHelicopter crashedHelicopter crashed in a lake sling load operationHelicopter crashed during sling load operationHelicopter crashed for unknown reasons while performing a

Non-commercially operated helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
21/02/2010	France	Le Tampon (974)	AEROSPATIALE SA318	Loss of control during landing and collision with terrain
23/05/2010	Germany	Mönchgrün - Saale	HILLER FH1100	Engine failure and loss of control during flight
31/05/2010	France	Col des Boeufs (974)	ROBINSON R22	Collision with terrain after take-off
25/07/2010	France	Coullons (45)	SCHWEIZER 269C	Collision with trees
12/08/2010	Italy	Milazzo (ME)	ROBINSON R44	Helicopter crashed just after take-off.
09/12/2010	France	Tourrettes-sur-Loup (06)	ROBINSON R22	Collision with terrain in mountainous area
18/02/2011	Italy	Canne della Battaglia	ROBINSON R44	helicopter crashed during en route
09/07/2011	France	Luzoir (02)	ROBINSON R44	Loss of control at low altitude in bad weather conditions
24/07/2011	United Kingdom	Furze Farm, Marhamchurch, Bude	ROBINSON R44	Helicopter crashed
19/09/2011	Spain	Municipality of La Peza (Granada)	BELL AB412	Helicopter crashed on a wooded area and caught fire
12/11/2011	Spain	Prox Andratx (Palma Mallorca)	HUGHES 369	Helicopter loss of control and collision with terrain

06/01/2012	United Kingdom	Ely	ROBINSON R22	Helicopter nosedived and crashed into a field
				Collision with trees during low level flight in instrumental flight
09/06/2012	Germany	Teisendorf	ROBINSON R44	conditions
				Rotor mast tailgating during cruise and rupture in-flight followed by a
03/09/2012		Valouse	ROBINSON R44	crash
10/01/2013	Germany	Wolpertshausen	ROBINSON R44	Collision with power line in bad weather conditions
01/03/2013	France	France	AEROSPATIALE SA316	Helicopter crashed into a frozen lake
29/07/2013	Romania	lake near Taureni	EUROCOPTER EC130	Controlled flight into a lake
13/09/2013	Poland	Wygonin	ROBINSON R44	Collision with Terrain
12/10/2013	Poland	Wolica Kozia	ENSTROM 280	Helicopter crashed following engine failure
19/11/2013	Germany	Neuhausen ob Eck	ROBINSON R44	Helicopter crashed into a forest in foggy weather conditions
20/12/2013	France	Lugon and Ile du Carney (33)	ROBINSON R44	collision with water during flight at a low height
		Baltic Sea, about 3 NM north of		
28/02/2014	Germany	Prerow	MBB BK117	Helicopter fell in the water during training exercise in the see
13/03/2014	United Kingdom	Near Gillingham Hall	AGUSTA BELL AB139	Aircraft crashed shortly after take-off in degraded visual references
05/04/2014	Austria	Am Kogl, Kirchham	ENSTROM 280	Helicopter crashed in a wooded area whilst en route to airfield
		On EBCF airfield 10m off Runway		Engine power incorrect management during final leg followed by loss
13/06/2014	Belgium	30 (RH)	SCHWEIZER 269C	of control and crash
				Helicopter crashed on a mountainous terrain due to an unexpected
08/08/2014	Italy	Chanton Desout	SUD AVIATION SA318	weather deterioration
		In Samsoe Belt between Røsnæs		
05/09/2014	Denmark	and Samso	ROBINSON R44	Helicopter crashed under unknown circumstances into the sea
02/10/2014	France	France	EUROCOPTER EC130	Controlled flight into terrain in IMC conditions
04/12/2014	Portugal	near LPSO - Ponte de Sor	SCHWEIZER 269C	Helicopter crashed on a training flight
29/03/2015	Czech Republic	Filipova Hut	ROBINSON R44	Helicopter crashed
06/06/2015	Isle of Man	Near Creg-ny-Baa	BELL 206	Helicopter crashed on mountain side
16/07/2016	Spain	Valmayor Reservoir (Valdemorillo)	ROBINSON R22	Helicopter hooked with a high voltage wire and crash into a reservoir
16/08/2016	Czech Republic	near LKPS - Plasy	ROBINSON R44	The helicopter crashed during autorotation training
05/09/2016	France	Origny le Sec	ROBINSON R22	Helicopter crashed
		Monte RhoArcisate/Bisuschio		
19/11/2016	Italy	(Varese)	AGUSTA A109	Helicopter crashed
15/03/2017	France	Figeac	BELL 206	Helicopter crashed whilst flying at low altitude during a night flight
29/03/2017	United Kingdom	Rhinog Fawr Mountain	AEROSPATIALE AS355	Helicopter struck a mountain
		Scinias of Marathonas area		Helicopter crashed during low flying due to collision with electrical
23/06/2017	Greece	wetland	MD HELICOPTER 369	power lines
08/10/2017	Latvia	Near Gramzda	ROBINSON R44	Helicopter impacted a powerline and crashed

17/11/2017	United Kingdom	near Waddesdon	GUIMBAL CABRI	Mid-air collision between helicopter and small aeroplane
30/05/2018	United Kingdom	Nr Aldborough	BELL 206	Helicopter impacted terrain
07/07/2018	Slovakia	Boundary of Village Kanaš	ROBINSON R44	Helicopter hit a power line during take-off and crashed
11/07/2018	Poland	Domecko near Opole	ROBINSON R44	Helicopter crashed for unknown reasons
05/09/2018	Czech Republic	Domažlická 1059, Plzen - Skvrnany	ROBINSON R44	Loss of control during manoeuvring at low altitude
27/10/2018	United Kingdom	Leicester	AGUSTA AW169	Helicopter tail rotor control loss and crash
17/02/2019	Norway	North of Roeldal alpine center	ROBINSON R44	Helicopter crashed in mountainous terrain
22/03/2019	Czech Republic	Near Blažkov village	ENSTROM 480	Helicopter loss of control in flight
03/05/2019	Italy	Pegognaga (Mantova)	ROBINSON R22	Loss of control in flight and impact with the ground
25/10/2020	Italy	In the proximity of Cervinia	ROBINSON R44	Loss of control shortly after take off and collided with the ground
				Helicopter crashed in mountainous area during training flight for
08/12/2020	France	French Alps, Bonvillard (73) Savoie	EUROCOPTER EC135	winching by night conditions

Helicopters registered outside the EASA Member States

Local Date	State of Occurrence	Location	Aeroplane	Headline
23/10/2010	United Kingdom	Shanlive, Mourne Mountains	AGUSTA A109	Helicopter crashed
07/12/2010	France	Piène-Haute (06)	AEROSPATIALE AS350	Collision with terrain in mountainous area in foggy conditions
26/04/2012	Romania	near Ostrov	KAMOV KA32	Helicopter crashed
				Helicopter crashed shortly after taking off and destroyed by post
05/09/2014	Belgium	Roeselare, West Flanders	ROBINSON R44	impact fire
10/05/2017	Italy	Fundres (BZ)	ENSTROM 480	In flight separation of main rotor blade and main rotor hub
		Approximately 6NM S/SW Gorgona		
22/07/2019	Italy	Island	ROBINSON R66	Helicopter crashed into the sea

Annex I helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
14/11/2010	Czech Republic	lake Naklo,10 km N Olomouc	HELISPORT CH7 KOMPRESS	Fall of ultralight helicopter
29/04/2011	France	Saint-Gervasy (30)	DYNALI H2S	Loss of power leading to loss of control and collision with terrain
18/02/2012	Germany	Lahr	CHR SAFARI	Tail rotor blade separation during take off
12/03/2012	Martinique	Le Lorrain	BELL 47	Collision with power lines and consequent post-impact fire
14/05/2012	Czech Republic	Sindlovy Dvory	CHR SAFARI	Fall of helicopter
21/04/2013	Slovakia	385 metrov od prahu VPP TK 31	DYNALI H2S	Helicopter crashed
14/09/2013	France	Gignac (34)	FAMA K209MF	Detachment of rotor in flight, terrain collision, fire
03/12/2013	Czech Republic	6 km W LKBO - Štepánov	HELISPORT CH7 RANABOT	Fall of helicopter

-				
12/02/2015	Czech Republic	Bohušovice nad Ohrí	ROTORWAY TALON A600	Fall of helicopter
15/06/2015	France	AD Longuyon Vilette	MOSQUITO XE	Loss of control during hovering, terrain collision and fire
17/07/2016	United Kingdom	EGBR - Breighton	AEROSPATIALE SE313	Loss of control with ground impact during quick stop / flare
10/05/2017	Austria	Gramaialm	BELL 47G	Helicopter crashed after collision with cable and caught fire
		Between Millas and Corbère-les-		
13/03/2018	France	Cabanes	CHR SAFARI	Crash followed by post-impact fire
05/04/2018	France	AD Libourne	BELL 47G	Ground collision with fire during instruction flight
05/04/2018	France	Crestet	ROTORWAY EXEC	Loss of control in flight, collision with the ground, fire
				Inadvertent opening of a door, impact of the rotor with the door, loss
19/06/2018	France	AD Châtellerault	HELISPORT CH7 RANABOT	of control, collision with the ground, fire
13/07/2018	France	Saint Raphaël	HELISPORT CH7 RANABOT	Helicopter collided with tree and caught fire
				Loss of control in flight followed by tail boom separation during
13/07/2018	Italy	Musile di Piave (VE)	YO-YO 222 3RD SERIES	approach
	Saint Pierre and			
05/11/2018	Miquelon	Saint Pierre et Miquelon	ROTORWAY EXEC	Collision with the ground shortly after take-off
		Barysiai, Joniskiu district, Siauliai		
22/03/2019	Lithuania	county	ULTRASPORT 555	Helicopter crashed
15/07/2019	France	PF ULM Grand Couronné	HELISPORT CH7 RANABOT	Terrain collision
		Approx. 3 km southeast of Herisau		Helicopter crashed into a meadow during an auto-rotation,
24/08/2019	Switzerland	(AR)	ROTORWAY EXEC	overturned and caught fire
24/09/2019	France	AD Montélimar-Ancone	LH 212 DELTA	Ground collision during manoeuvring
30/11/2019	France	Gréoux-les-Bains	HELISPORT CH7 RANABOT	Helicopter crashed
30/06/2020	Poland	Strzegom	PHOENIX UH22	Helicopter crashed after losing control inflight
10/07/2020	Italy	Nazzano (Rome)	R22 like	Helicopter clipped powerlines and fell into a river

Balloons

	State of			
Local Date	Occurrence	Location	Aeroplane	Headline
01/01/2011	United Kingdom	Midsomer Norton	CAMERON - O120	Balloon deflated during flight and fell to the ground.
				Flight initiated in spite of poor weather forecast. High speed landing
22/04/2011	Belgium	Oudenburg	KUBICEK - BB37 - N	caused the basket to flip 180 degrees.
25/06/2011	Switzerland	Fisibach/AG	WORNER	Loss of control of a balloon and hard landing.
13/05/2012	France	Charly-sur-Marne (02)	SCHROEDER	
				Hard landing, one passenger was ejected and hit by the basket - 34
19/08/2012	France	Feings(41)	CAMERON	POB - 1 OB Fatal - No damage.

				Hot air balloon crash in storm - 32POB - 6OB Fatalities - 12OB Serious -
23/08/2012	Slovenia	Ljubljana marshes	LINDSTRAND - LBL600C	14OB Minor - A/C destroyed.
06/08/2013	Switzerland	Haut-Intyamon/FR	CAMERON - Z105	Collision of balloon with powerline.
		· · · · · · · · · · · · · · · · · · ·	SCHROEDER - FIRE	
			BALLOONS G - NO SERIES	Balloon flying in convective atmosphere generating wind variations
05/10/2014	France	Cazes Mondenard (82)	EXISTS	with decision to precautionary landing.
				Balloon basket impacted a metal fence on final approach, basket
12/07/2015	Spain	Vilanova del Cami	ULTRAMAGIC - S160	overturned, some occupants ejected included pilot - pilot died.
			SCHROEDER - FIRE	
08/10/2015	Italy	Montescaglioso (MT)	BALLOONS G	Balloon forced landing after hitting power line.
				Fall of a person that gripped on the outside of the basket during take-
05/01/2016	France	Aurel	ULTRAMAGIC - M120	off.
			SCHROEDER - FIRE	
02/06/2019	France	Pons	BALLOONS G	Balloon bounced landing - pilot ejected and hit by basket.
08/03/2020	Spain	Sports Center Palomares del Río	ULTRAMAGIC - H77	Pilot is thrown during the touchdown of the balloon.
16/08/2020	Germany	St. Goar	KUBICEK - BB51 - Z	Balloon hard landing resulting in 1 fatal injury and 4 serious injuries.
05/09/2020	Hungary	Vál	BALLOON ALOFT - AX8	Fire in balloon basket during landing procedure.

Sailplanes

Date	State/area of occurrence	Location name	Manufacturer/model	Headline
06/04/2010	France	Aspres-sur-Buech (05)	SCHEMPP HIRTH - VENTUS 2CM	Loss of control in flight. Aircraft crashed on a mountainous area.
19/04/2010	France	Pont-sur-Yonne (89)	CENTRAIR - 101	Sailplane collided with ground, possible incapacitation of the pilot. 1 POB, 1 fatality, aircraft destroyed.
18/05/2010	France	AD La Motte du Caire (83)	SPORTINE AVIACIJA - LAK17 - AT	Loss of control during winch take-off, 1 POB, 1 fatality, aircraft destroyed.
22/05/2010	France	Les Ressuintes (28)	SCHLEICHER - ASW28	Collision with the ground when landing in the field during a competition. 1 POB, 1 fatality, aircraft destroyed.
24/05/2010	Germany	Flugplatz Elz	SCHEIBE - SF34	Loss of control on return after winch cable disconnect.
29/05/2010	Germany	Villingendorf	SCHEMPP HIRTH - DISCUS BT	Collision with ground wave during off-field-landing.
09/06/2010	Austria	Kalwang, ST	PZL BIELSKO - SZD59 - NO SERIES EXISTS	Sailplane crashed into a field during a cross country flight. Circumstances unknown. 1 POB, 1 fatality, aircraft destroyed.
12/06/2010	Austria	Near LOKG	LET - L13	Sailplane crashed due to RH wing spar collapse.

12/06/2010	Belgium	EBWE Weelde	PIK - PIK20D	Sailplane crashed during winch launch. Elevator controls were disconnected. 1 POB, 1 fatality, aircraft destroyed.
13/06/2010	Germany	Neidlingen	DIAMOND - HK36	Controlled flight into terrain, 2 POB, 2 fatalities, aircraft destroyed.
23/06/2010	Switzerland	Provence/VD	GLASER DIRKS - DG300	Sailplane collides with trees.
26/06/2010	Germany	Pfronstetten-Tigerfeld	OTHER	Loss of control during off-field-landing.
04/07/2010	Austria	Steyrling, Kremsmauer, Oberösterreich	SCHLEICHER - K8 - B	Sailplane collision with obstacle and rock wall during search of lift - sailplane destroyed.
07/07/2010	Spain	Castejón de Sos	SCHLEICHER - ASW27 - 18E	Pilot Lost the control during slope soaring flight.
08/07/2010	Slovakia	Near Turcianske Teplice	SPORTINE AVIACIJA - LAK19 - T	Sailplane entered spin and crashed on approach. 1 POB, 1 fatality, aircraft destroyed.
11/07/2010	Austria	Stanzach, T	GLASER DIRKS - DG300	Sailplane crashed into an elevated terrain. 1 POB, 1 fatality, aircraft destroyed.
15/07/2010	Germany	Pillig	GLASFLUGEL - 304	Airframe failure during thermal lift.
01/08/2010	France	Monistrol d'Allier (43)	CENTRAIR - 201	Structural failure during flight causing the sailplane to crash. 2 POB, 2 fatalities, aircraft destroyed.
07/08/2010	Switzerland	Münster/VS	SCHEMPP HIRTH - DISCUS CS	Mid air collision between a sailplane and a paraglider.
08/08/2010	United Kingdom	Bicester Airfield, Oxfordshire	PZL BIELSKO - SZD24 - C	Wings separated during winch launch.
13/08/2010	Belgium	Saint Hubert Airfield	OTHER	Sailplane accident during solo student flight. One POB fatal.
04/09/2010	Czech Republic	LKSN	LET - L23	Sailplane entered spin when turning on final. 2 POB, 1 fatality, 1 serious injury, aircraft destroyed.
27/09/2010	France	Sommet du Ruth (04)	ROLLADEN SCHNEIDER - LS8	Loss of control in flight due to strong down wash from a mountain ridge, collision with the ground. 1 POB, 1 fatality, aircraft destroyed.
09/10/2010	Poland	Bezmiechowa	PZL BIELSKO - SZD9 - 1E	Sailplane crashed to the hangar while landing.
24/12/2010	Australia	Corowa, near	SCHLEICHER - ASW22	Sailplane impacted a powerline and crashed. 1 POB, 1 fatality, aircraft destroyed.
13/04/2011	France	Clamensane (04)	ROLLADEN SCHNEIDER - LS8 - B	Loss of control in flight due to rough wind conditions, collision with terrain. 1 POB, 1 fatality, aircraft destroyed.
22/04/2011	Switzerland	Mollis LSMF	GLASER DIRKS - DG800	Loss of control during winch launching.
18/05/2011	France	Le Sappey (38)	SCHLEICHER - ASH25	Loss of control while turning, collision with terrain, instructional flight. 2 POB, 2 fatalities, aircraft destroyed.
21/05/2011	Germany	Saarmund	GROB - G102 - ASTIR CS	Mid-air collision between a sailplane and LSA aircraft. 3 POB, 3 fatalities, both aircraft destroyed.
02/06/2011	Germany	Hornberg	OTHER	Sailplane loss of control in flight.
11/06/2011	Germany	Mönchsheide	SCHLEICHER - ASH26 - E	Collision with trees.
12/06/2011	Finland	Hattula	SCHLEICHER - ASW27 - 18E	Sailplane mid-air collision.

15/06/2011	Slovenia	Ptuj	SCHEIBE - BERGFALKE IV	Sailplane stalled and crashed while performing a winch launch. 2 POB, 1 fatality, 1 seriously injured, aircraft destroyed.
17/06/2011	Germany	Laucha	SCHLEICHER - KA6	Loss of control during approach. 1 POB, 1 fatality, aircraft substantially damaged.
26/06/2011	Germany	Hütten-Hotzenwald	SCHEMPP HIRTH - VENTUS 2C	Loss of control during winch launch take-off. 1 POB, 1 fatality, aircraft destroyed.
28/06/2011	Austria	Scharnstein, nahe	GLASER DIRKS - DG100 - G	Collision with trees.
30/06/2011	France	Savournon (05), col de Faye	SCHLEICHER - ASH25E	Collision with a tree at the bottom of a valley in bad weather. 2 POB, 2 fatalities, aircraft substantially damaged.
07/07/2011	Austria	next to LOKF - Feldkirchen / Ossiachersee	PZL BIELSKO - MDM1	Sailplane crash after low pass.
10/07/2011	Germany	Scheuen	SCHEMPP HIRTH - DUO DISCUS	Aircraft lost control and crashed into a field during low flying. 1 POB, 1 fatality, aircraft destroyed.
10/07/2011	Germany	Near Jena-Schöngleina	PZL BIELSKO - SZD30	Inflight breakup (Luftzerleger).
11/07/2011	Poland	Nowy Targ	PZL BIELSKO - SZD50 - 3	Sailplane spin and crash.
31/07/2011	Germany	Haigerloch	SCHEMPP HIRTH - VENTUS CM	Loss of control in low altitude.
01/08/2011	Switzerland	Gsteig/BE	GLASFLUGEL - KESTREL	Sailplane crashed at 1600m in the alps.
03/08/2011	Germany	Wasserkuppe	SCHLEICHER - ASK23	Runway excursion during take-off.
13/08/2011	France	Saint-Firmin (05)	OTHER	Loss of control while turning during a mountain flight, collision with terrain. 1 POB, 1 fatality, aircraft destroyed.
16/08/2011	Poland	Laka Wielka	PZL BIELSKO - SZD36	Sailplane mid-air collision and crash.
21/08/2011	Italy	Ortona dei Marsi	OTHER	Sailplane crash.
26/08/2011	Italy	Anterselva Valley (BZ)	GROB - G103 - TWIN ASTIR	Sailplane crashed near the top of the mountain.
28/08/2011	Austria	Zell am See	DIAMOND - HK36 - R	Collision between two aircraft.
02/10/2011	Spain	Sayerri Peak, in Borau	SCHEMPP HIRTH - DUO DISCUS	Sailplane bird strike caused an elevator failure.
05/10/2011	France	Saint-Geniez (04)	ROLLADEN SCHNEIDER - LS8	Stall during a spiral near a ridge, collision with the terrain. 1 POB, 1 fatality, aircraft destroyed.
15/10/2011	Germany	Blocksdorf	SCHEMPP HIRTH - MINI NIMBUS	Sailplane loss of control during final approach.
25/10/2011	Austria	Uttendorf, Zell/See, Salzburg	SCHLEICHER - ASH26 - E	Turbulence encounter at low height, pilot loss the control, the aircraft struck tree and crashed.
28/10/2011	United Kingdom	Darley Moor (Derbyshire)	OTHER	At approximately 100ft during aerotow take-off, a hang glider being towed lost control & impacted the ground. One POB, fatal injuries. Extensive damage. The ultralight landed safely.

31/10/2011	Spain	Pla de Beret (Lleida)	OTHER	Sailplane entered spin and crashed. 1 POB, 1 fatality, aircraft destroyed.
25/03/2012	Portugal	Águeda, Portugal	GLASER DIRKS - DG800	Powered sailplane entered spin and crashed. 1 POB, 1 fatality, aircraft substantially damaged.
10/04/2012	Switzerland	Innerthal	GLASER DIRKS - DG800	Sailplane crashed into a mountain. Cause unknown. 1 POB, 1 fatality, aircraft destroyed.
15/04/2012	Germany	Laufenselden	GLASER DIRKS - DG500 - TRAINER	Sailplane collision with trees after failed rope connection.
17/04/2012	Poland	Olsztyn-Dajtki	SPORTINE AVIACIJA - LAK17 - A	Sailplane stalled during turn to final approach after a failed winch launch. 1 POB, 1 fatality, aircraft destroyed.
30/04/2012	United Kingdom	Dunstable	SCHLEICHER - ASW24	ASW 24 sailplane crashed in a field.
30/04/2012	Germany	Unterwössen	ROLLADEN SCHNEIDER - LS6	Collision with trees during landing.
03/05/2012	France	Claix, France	ROLLADEN SCHNEIDER - LS7	Sailplane crashed into a mountain side. 1 POB, 1 fatality, aircraft destroyed.
05/05/2012	France	AD Buno Bonnevaux (91)	PIPER - PA25 - 235	Mid-air collision between a sailplane and an aeroplane above runway.
19/05/2012	Switzerland	unbekannt	ROLLADEN SCHNEIDER - LS1	Missing sailplane - found crashed 2 weeks later.
19/05/2012	Switzerland	Maienfeld, Switzerland	SCHLEICHER - ASW28	Sailplane crashed in the mountains.
26/05/2012	Switzerland	Hütten/ZH	OTHER	Powered sailplane stalled and crashed. 1 POB, 1 fatality, aircraft destroyed.
28/05/2012	Germany	Ludwigshafen-Dannstadt	SCHEMPP HIRTH - DISCUS BT	Loss of control in flight.
14/06/2012	France	Curienne (73)	CENTRAIR - 101	In-flight collision between a glider and an ULM. 1 person on each aircraft. 1 fatality.
18/06/2012	France	La Piarre, France	GLASER DIRKS - DG400	Sailplane loss of control in flight.
18/06/2012	France	La Piarre	GLASER DIRKS - DG400	Powered sailplane was found crashed. 1 POB, 1 fatality, aircraft destroyed.
30/06/2012	Italy	Cicogna	SPORTINE AVIACIJA - LAK19	Sailplane crashed in mountains.
22/07/2012	Poland	Krosno	PZL BIELSKO - SZD50 - 3	Sailplane entered spin while performing a steep turn ending by crashing to the ground. 2 POB, 1 fatality, 1 serious injury, aircraft destroyed.
23/07/2012	Germany	Pfronten, nahe	SCHLEICHER - ASH25	Sailplane crashed in the mountains.
26/07/2012	Switzerland	Romont/FR	OTHER	Powered sailplane crashed on a field.
27/07/2012	Switzerland	Glarus Nord/GL	OTHER	Sailplane collided with a mountain.
30/07/2012	France	Barles (04), lieu dit le Forest, altitude 1 170 m	PZL BIELSKO - SZD48	Sailplane impacted the ground in mountainous area .

bund. rst solo. able was released. if-field landing final. upted winch launch. vinch launch. he mountain.
able was released. f-field landing final. upted winch launch. vinch launch. he mountain.
f-field landing final. Ipted winch launch. vinch launch. he mountain.
ipted winch launch. vinch launch. he mountain.
vinch launch. he mountain.
he mountain.
with troop
with trees.
during final approach, ground impact, estroyed.
phase winch launching.
act - 1 POB - 1 OB Fatal
nching.
aunch.
e take off.
close to the ground. 1 POB, 1 fatality,
descent, during competition.
ght in mountainous terrain.
aunch.
trol on flight at low altitude. Aircraft OB - 1OB Serious - A/C Destroyed.
g approach.
ountain flight.
winching.
horizontal stabilizer separation.
high terrain.

28/10/2013	Poland	Bezmiechowa Gorna	PZL BIELSKO - SZD30	Sailplane hit a tree and crashed while flying a circuit pattern after take-off. 1 POB, 1 fatality, aircraft destroyed.
17/11/2013	Poland	EPST	OTHER	Sailplane disintegration and crash while take-off.
03/04/2014	Austria	Hohe Wand	SCHLEICHER - ASH26 - E	Sailplane crashed into the terrain.
30/04/2014	France	LFMF - Fayence	SCHLEICHER - ASW20	Cartwheel - sailplane overturn while take-off.
28/05/2014	Italy	Alzate Brianza Airfield - LILB	OTHER - Not mapped	Alisport Silent 2 Electro - A/C crashed into a wooded area at the end of the runway during the approach - 1POB - 1OB Fatal - A/C Destroyed.
01/06/2014	Poland	Pila	PZL BIELSKO - SZD41	Sailplane mid-air collision and crash.
06/06/2014	Czech Republic	LKKA 1km RAD 320 RWY 32	TECNAM - P92	Fall of ULL during a Glider Towing.
13/06/2014	Germany	Oppingen Airfield	GLASER DIRKS - DG1000	Sailplane crashed - 2POB - 2OB Fatal - A/C Destroyed.
18/06/2014	United Kingdom	North Hill Airfield, Sheldon	SCHLEICHER - ASW20L	Airbrake and landing gear lever mis-selected - Aircraft stalled during the approach and crashed.
10/07/2014	France	Eourres	SCHEMPP HIRTH - VENTUS 2CM	Loss of control during an altitude flight - right wing broke-off - aircraft crashed.
11/07/2014	Finland	Piikajärvi airfield (EFPI), Finland	PZL BIELSKO - SZD51 - 1	Sailplane crashed on the runway during towing - 1POB - 1OB Fatal - A/C Destroyed.
12/07/2014	Germany	Nieder-Werbe	ROLLADEN SCHNEIDER - LS4 - A	Sailplane crashed in mountainous area.
26/07/2014	Germany	Glider airfield Sultmer Berg, Northeim	ROLLADEN SCHNEIDER - LS4 - A	Sailplane stalled during winch launch.
26/07/2014	France	AD Puimoisson (04)	GROB - G103C - TWIN III SL - TWIN III SL	Loss of control on approach, aircraft crashed.
10/08/2014	Italy	localita Tassigano, Capannori, Lucca	GROB - G103C - TWIN ASTIR - TWIN III ACRO	Shortly after take-off, the left wing broke due to overload in the execution of an abrupt recovery from an aerobatic manoeuvre. The A/C fell to the ground - 2POB - 2OB Fatalities - A/C Destroyed.
12/08/2014	Italy	Acceglio (Cuneo)	GLASER DIRKS - DG200 - 17	Collision with terrain during a mountain flight - 1POB - 1OB Fatal - A/C destroyed.
27/08/2014	France	Saint-André-d'Embrun (05)	SCHLEICHER - ASK13	Collision with terrain during a competition.
20/09/2014	Greece	LGMG	GLASFLUGEL - MOSQUITO	Perhaps while unconscious a sailplane pilot approaching LGMG crashed inside the airport while other aircraft take-off was in progress.
30/11/2014	Namibia	Blumfelde	BINDER	The sailplane crashed after the left wing broke-up in flight - 2POB - 2OB Fatalities - A/C Destroyed.
23/12/2014	Germany	Böslingen	OTHER	TMG crashed shortly after take-off.
06/04/2015	Sweden	10 km SSE Nikkaluokta	GROB - G103C - TWIN III SL - TWIN III SL	Loss of control during wave flight (in cloud), sailplane disintegration in flight. Pilot bailed out; the student was killed.

			Wing hit the ground during take-off - the glider swerved and
Germany	Oschatz	SCHEIBE - LSPATZ 55	overturned.
France	La Piarre	GLASER DIRKS - DG800	Breakage of airbrakes control during a mountain flight, autorotation, collision with terrain.
Germany	Bad Münder, Bakede	SCHEMPP HIRTH - NIMBUS 3	Glider stalled and crashed into a forested area.
Austria	Near Airfield Hohenems, Vorarlberg	GLASER DIRKS - DG300	Mid-air collision. One of the two aircraft crashed into the mountain rocks and caught fire. The other aircraft returned to the airfield and landed safely.
Germany	Bartholomä	SCHEMPP HIRTH - JANUS	Glider crashed into the ground during a winch launch. 2 POB, 1 fatality, 1 serious injury, aircraft destroyed.
Italy	East of Mount Paganella, at about 2 mm away from Comune di Terlago (TN)	SCHEMPP HIRTH - VENTUS 2CM	Sailplane crashed on a mountain slope. 1 POB, 1 fatality, aircraft destroyed.
Hungary	LHEM	OTHER	Two sailplanes collided during approach. One Sailplane broke and crashed. 2 POB - 2 fatalities. The other glider managed to land.
United Kingdom	Aston Down Airfield	SCHLEICHER - K8 - B	A Sailplane crashed into roof of building - Suicide.
Switzerland	Klosters-Serneus/GR	ROLLADEN SCHNEIDER - LS8 - 18	Sailplane accident in Klosters-Serneus/GR. 1 POB, 1 fatality, aircraft destroyed.
Austria	Seitenstetten, NÖ	PILATUS - B4 - PC11	The sailplane hit the ground after an aerobatic manoeuvre. 1 POB, 1 fatality, aircraft destroyed.
France	Eygliers	PIPISTREL	Loss of control in flight, the sailplane collided with the ground.
France	Saint-André	SCHEMPP HIRTH - VENTUS C	Collision with the mountain side. The sailplane wreckage has been found at 2700m of altitude.
Croatia	Donji Lapac., area Kruge		Sailplane found crashed - POB 1, 1 fatal injury.
Germany	Füssen	ROLLADEN SCHNEIDER - LS8	The sailplane lost control and crashed in a forested area. 1 POB, 1 fatality, aircraft destroyed.
Romania	MUCHIA CHEII, Masivul Postavarul	OTHER	Aircraft crashed in a mountainous area. Wreckage found several months after the accident 1 POB, 1 fatality, aircraft destroyed.
Poland	ATZ EPPL	PZL BIELSKO - SZD50 - 2	Sailplane collided with a winch cable and crashed. 2 POB, 2 fatalities, aircraft destroyed.
France	Embrun	ROLLADEN SCHNEIDER - LS1	Sailplane collided with trees and crashed to the mountain. 1 POB, 1 fatality, aircraft destroyed.
Italy	Col FERRET	SCHEMPP HIRTH - ARCUS M	Powered sailplane crashed against a mountain slope. 2 POB, 2 fatalities, aircraft destroyed.
Germany	Purkshof	GLASER DIRKS - DG100	Sailplane disconnected the rope during towing and crashed on the runway. 1 POB, 1 fatality, aircraft destroyed.
	Germany Austria Germany taly lungary Jnited Kingdom Gwitzerland Grance Grance Granta Germany Romania Poland Grance taly	GermanyBad Münder, BakedeAustriaNear Airfield Hohenems, VorarlbergGermanyBartholomäEast of Mount Paganella, at about 2 mm away from Comune di Terlago (TN)AungaryLHEMJnited KingdomAston Down AirfieldWitzerlandKlosters-Serneus/GRAustriaSeitenstetten, NÖGroatiaDonji Lapac., area KrugeGermanyFüssenAustriaMUCHIA CHEII, Masivul PostavarulPolandATZ EPPLFanceEmbrunCol FERRET	SermanyBad Münder, BakedeSCHEMPP HIRTH - NIMBUS 3AustriaNear Airfield Hohenems, VorarlbergGLASER DIRKS - DG300SermanyBartholomäSCHEMPP HIRTH - JANUSSermanyBartholomäSCHEMPP HIRTH - VENTUS 2CMtalyEast of Mount Paganella, at about 2 mm away from Comune di Terlago (TN)SCHEMPP HIRTH - VENTUS 2CMHungaryLHEMOTHERJnited KingdomAston Down AirfieldSCHELICHER - K8 - B ROLLADEN SCHNEIDER - LS8 - 18AustriaSeitenstetten, NÖPILATUS - B4 - PC11FranceEygliersPIPISTREL SCHEMPP HIRTH - VENTUS cGroatiaDonji Lapac., area KrugeSCHEMPP HIRTH - VENTUS cSomaniaMUCHIA CHEII, Masivul PostavarulOTHERPolandATZ EPPLPZL BIELSKO - SZD50 - 2FranceEmbrunROLLADEN SCHNEIDER - LS1talyCol FERRETSCHEMPP HIRTH - ARCUS M

23/08/2015	Spain	near LEZL (SVQ): Sevilla	PIPISTREL	Pilot incapacitation in flight - Passenger took the controls - Aircraft crashed and caught fire. 2 POB, 1 fatality, 1 serious injury.
24/09/2015	Norway	Hatten mountain, Lesja municipality	SCHLEICHER - ASW24	Sailplane crash - pilot jumped out too close to the ground. 1 POB, 1 fatality, substantial damage.
26/09/2015	Denmark	5 km øst for EKRS : Ringsted	SCHLEICHER - ASW24	From level flight the aircraft suddenly pitched nose down and hit the ground in a steep nose down attitude. The pilot died and the sailplane was destroyed.
03/10/2015	Poland	Miedzybrodzie Zywieckie	PZL BIELSKO - SZD48 - 3	Sailplane entered spin after a long flight and crashed. 1 POB, 1 fatality, aircraft destroyed.
13/12/2015	Germany	Koblenz-Winningen	OTHER	Powered sailplane collided with a communication tower during a flight in fog. 2 POB, 2 fatalities, substantial damage.
24/12/2015	Namibia	Stryfontein Farm	SCHEMPP HIRTH - VENTUS CM	Powered sailplane crashed; no details available. 1 POB, 1 fatality, substantial damage.
03/01/2016	Germany	Near Kamp Lintfort Airfield (EDLC)	DIAMOND - HK36 - R	Aircraft crashed during a go-around - 1 POB 1 fatality.
26/03/2016	France	Seillans	OTHER - Generic	Pilot incapacitated due to a medical condition, Collision with trees and terrain.
03/04/2016	Austria	Kötschach Mauthen	GLASER DIRKS - DG400	Sailplane crashed into a mountain - 1 POB, 1 fatality.
03/04/2016	Austria	3,3 kmNorth from LOGL - Lanzen- Turnau	SPORTINE AVIACIJA - LAK19	Sailplane entered spin and crashed into terrain. 1 POB - 1 fatality.
16/04/2016	Poland	EPST	PZL BIELSKO - SZD9	Sailplane crashed into the ground after winch cable was released. 1 POB 1 fatality.
20/04/2016	Slovakia	Lysá Polana	SCHLEICHER - ASW27 - 18E	Competition flight - loss of height below safe altitude - abrupt manoeuvre - The aircraft stalled and crashed with a nose down attitude. 1 POB 1 fatality.
03/05/2016	Germany	Bautzen	PIK - PIK20E - NO SERIES EXISTS	Crash on approach during glider competition. 1 POB, 1 fatality, substantial damage.
04/05/2016	Slovenia	Near Airport LJSG	GLASER DIRKS - DG800	Sailplane accident. Suspected pilot incapacitation. 1 POB 1 fatality.
21/05/2016	Switzerland	Montricher LSTR	GLASER DIRKS - DG400	Sailplane collides with trees and crashes. 1 POB 1 fatality.
29/05/2016	Germany	Rhede/Emsland	LET - L23	Sailplane crashed into a field under unknown circumstances. 2 POB 1 fatality.
19/06/2016	Germany	Bramsche	SCHEMPP HIRTH	Loss of control during approach causing the aircraft to enter spin. 1 POB 1 fatality.
22/06/2016	France	Authon	SCHEMPP HIRTH	Loss of control followed by collision with terrain - during training flight en route. 2 POB, 1 fatality, 1 serious injury.
06/07/2016	Switzerland	Lenk/BE	GLASER DIRKS - DG800	Sailplane collides with elevated terrain. 1 POB 1 fatality.

09/08/2016	Germany	Lüsse	SCHLEICHER - ASW27	Sailplane fell to the ground during winch launch take-off. 1 POB 1 fatality.
27/08/2016	France	Sauto	SPORTINE AVIACIJA - LAK17 - A	Collision with a cable/wire followed by crash. 1 POB 1 fatality.
10/09/2016	Germany	Großrückerswalde	SCHLEICHER - ASK21	Two aircraft -glider and an ultralight collided close to the threshold. Pilot of the ultralight died.
14/09/2016	Switzerland	L'Isle	BINDER - EB29 - D	Sailplane lost control entered a vertical dive and crashed.
04/12/2016	United Kingdom	over Lubenham	CESSNA - 150 - L	Mid-air collision powered ACFT and glider; Glider crashed killing the pilot.
04/12/2016	United Kingdom	Brentor	SCHLEICHER - ASW24	Sailplane winch launch failed. Pilot was not able to land safely due to downdraft. 1 POB 1 fatality.
19/03/2017	France	Le Vernet	GLASER DIRKS - DG1000 - M	Collision with trees and ground. 2 POB 1 fatality 1 serious injury.
29/03/2017	France	LFLE - Chambéry / Challes-les-Eaux	SPORTINE AVIACIJA - LAK17 - A	Sailplane crash during winch launch take-off. 1 POB 1 fatality.
08/04/2017	Germany	Eschbach	SCHLEICHER - ASW24 - E	Sailplane Crashed into Industrial Area. 1 POB 1 fatality.
08/04/2017	United Kingdom	Currock Hill airfield	PZL BIELSKO - SZD55 - 1	Sailplane elevator not connected - glider crashed on aerotow. 1 POB 1 fatality.
12/04/2017	France	Valdeblore	SCHLEICHER - ASW22	Sailplane lost control - rolled onto its side and crashed into the ground. 1 POB 1 fatality.
03/05/2017	Poland	EPJL	PZL BIELSKO - SZD30	Sailplane made a steep climb then rolled and crashed during a winch launch. 1 POB 1 fatality.
06/05/2017	Germany	Mannheim	SPORTINE AVIACIJA - LAK17	Sailplane spin shortly after release from winch-launch followed by crash. 1 POB, 1 fatality, aircraft destroyed.
14/05/2017	France	near LFDH - Auch Gers	SCHEMPP HIRTH - CIRRUS	Loss of control at low height during a low turn speed and near the terrain. 1 POB, 1 fatality, aircraft destroyed.
20/05/2017	Hungary	Nyíregyháza	PZL BIELSKO - SZD30	Sailplane crash for unknown reasons. 1 POB, 1 fatality, aircraft destroyed.
10/06/2017	Italy	Riva Valdobbia (VC)	GLASFLUGEL - MOSQUITO	Sailplane collided with terrain below mountain tip. 1 POB, 1 fatality, aircraft destroyed.
11/06/2017	Italy	Novi Ligure	OTHER	Sailplane lost wing during aerotow and crashed in city centre. 1 POB, 1 fatality, aircraft destroyed.
15/06/2017	Austria	near Karlhöhe	GLASER DIRKS - DG600	Sailplane lost control and crashed in a mountainous area. 1 POB, 1 fatality, aircraft destroyed.
16/06/2017	Hungary	LHTL	SCHEIBE - SF25 - C	Motorized sailplane lost control and crashed during emergency training exercise. 2 POB, 2 fatalities, aircraft destroyed.

ilplane hit ground during winch launch causing it to fatality.
· · · · · /
rol while searching for lift and fell to the ground. 1
to a field due to unknown circumstances. 2 POB 2
due to loss of control. 1 POB. 1 fatal injury.
flight followed by glider collision with elevated atality, aircraft destroyed.
d the ground during winch launch take-off. 1 POB, 1 estroyed.
nd crashed on a field. Loss of control suspected. 1
l onto a steep pasture and was destroyed upon atality.
below a mountain ridge. 2 POB. 1 fatality and 1
(crash) – spin after the safety latch of the winch winch launching.
uring winch launching. 1 POB 1 fatality.
at ca 2500 meter altitude in mountainous area. . POB 1 fatality.
rol and crashed into a forest after a winch launch atality, 1 serious injury.
spin in flight followed by crash. 1 POB, 1 fatality.
e crashed shortly after take-off, 1 POB, 1 fatality,
in mountainous area for yet unknown reason. 1
while a field landing exercise. 2 POB, 2 fatalities.
during winch launch take-off, 1 POB, 1 fatality,
while turning on final, 2 POB, 1 fatality, 1 serious troyed.
rol and collided with terrain. 1 POB, 1 fatality,

19/07/2018	Germany	Oberammergau	ROLLADEN SCHNEIDER - LS7	Sailplane crashed into mountain after flying close to it and entering turbulence. 1 POB, 1 fatality, aircraft destroyed.
02/08/2018	France	Thones	ROLLADEN SCHNEIDER - LS4	Collision with elevated terrain due to medical incapacitation. 1 POB, 1 fatality, aircraft destroyed.
08/08/2018	Poland	M. Klików	OTHER	Sailplane accident - missing thermal lift and colliding with trees. 1 POB, 1 fatality, aircraft destroyed.
11/08/2018	Germany	Braunschweig - Waggum	SCHLEICHER - KA6 - CR	Blocked aileron - glider spin and crash. 1 POB, 1 fatality, aircraft destroyed.
12/08/2018	France	Orcières	SCHLEICHER - ASH25M	Sailplane collided with the ground Circumstances unknown. 1 POB, 1 fatality, aircraft destroyed.
19/08/2018	France	AD Colmar Houssen	AEROSPOOL - WT9	Loss of control of the tug ULM during take-off in glider tow, collision with runway, fire. 1 POB, 1 fatality.
26/08/2018	France	Frontenas	SCHLEICHER - ASW17	Loss of control in flight, collision with the ground. 1 POB, 1 fatality.
11/09/2018	Switzerland	Bedretto/TI	IAR BRASOV - IS28M2 - GR	Sailplane crashes in mountainous area due to unknown reasons. 1 POB, 1 fatality.
29/09/2018	Czech Republic	Lenešice near Louny	SCHEMPP HIRTH - STANDARD CIRRUS - NO SERIES EXISTS	Sailplane lost control and span to the ground. 1 POB, 1 fatality, aircraft destroyed.
30/09/2018	Germany	EDLE (ESS): Essen/Mulheim	SCHLEICHER - ASK18	Sailplane crashed on approach for unknown reasons. 1 POB, 1 fatality, aircraft destroyed.
05/10/2018	Germany	on approach to EDFK : BAD KISSINGEN	DIAMOND - HK36 - R	Sailplane crashed on approach due to unknown reasons. 1 POB, 1 fatality, aircraft destroyed.
08/12/2018	Spain	LEFM : Fuentemilanos (Segovia)	GROB - G103A - TWIN ASTIR - TWIN II ACRO	Aircraft on final approach collided with another aircraft standing on ground. One person on the ground was fatally injured.
17/03/2019	Italy	Montecchio-Podere S.Apollonia airfield	ROLLADEN SCHNEIDER - LS1 - D	Sailplane crashed during winch-launch. 1 POB, 1 fatality, aircraft destroyed.
24/03/2019	Germany	EDST : Hahnweide	SPORTINE AVIACIJA - LAK17 - B FES	Aircraft stalled and crashed during a winch launch. 1 POB, 1 fatality, aircraft destroyed.
24/03/2019	Spain	LEIG : Igualada-Odena (Barcelona)	GLASER DIRKS - DG800 - B	Engine failure during the initial climb. Powered sailplane stalled and crashed. 1 POB, 1 fatality, aircraft destroyed.
13/04/2019	France	Avize	ROLLADEN SCHNEIDER - LS8 - 18	Sailplane loss of control and crash.
22/04/2019	Germany	Leck	ROLLADEN SCHNEIDER - LS7 - WL	Unexpected rope release during winch launch. Glider entered spin and crashed. 1 POB 1 Fatality. Aircraft destroyed.
03/05/2019	Norway	Grinder	SCHLEICHER - ASH31 - MI	Sailplane lost control during a soaring competition. 1 POB, 1 fatality, aircraft destroyed.

04/05/2019	United Kingdom	Near Blaenau Ffestiniog	ROLLADEN SCHNEIDER - LS7	Sailplane lost control due to a medical incapacitation of the pilot. 1 POB, 1 fatality, aircraft destroyed.
08/05/2019	Czech Republic	Roundabout near Hranice n. M.	SCHEMPP HIRTH - CIRRUS	Sailplane crashed due to loss of control. 1 POB, 1 fatality, aircraft destroyed.
02/06/2019	Germany	EDBY : Schmoldow	PZL BIELSKO - SZD36 - A	Sailplane lost control and crashed. 1 POB, 1 fatality, aircraft destroyed.
08/06/2019	Poland	EPNT	PZL BIELSKO - SZD50	Sailplane accident - collision with motorcycle. 1 POB, 1 fatality, substantial damage.
15/06/2019	Poland	Szczury	PZL BIELSKO - SZD48 - 1	Sailplane crash during attempted off-airfield landing. 1 POB, 1 fatality, aircraft destroyed.
16/06/2019	Germany	Hahnweide	SCHEMPP HIRTH	Sailplane crashed into terrain due to unknown reasons. 1 POB, 1 fatality, aircraft destroyed.
23/06/2019	Switzerland	Sex Noir mountain	SCHLEICHER - ASG32	Sailplane crashed into mountains. 1 POB, 1 fatality, aircraft destroyed.
02/07/2019	Germany	Lüsse	SCHLEICHER - ASW20L	Sailplane lost control crashed into a field. Possible medical incapacitation. 1 POB, 1 fatality, aircraft destroyed.
11/07/2019	Czech Republic	LKDK	GROB - SPEED ASTIR IIB - NO SERIES EXISTS	Loss of control during landing - fall of glider.
16/07/2019	France	Valernes	GLASER DIRKS - DG1000 - T	Aircraft crashed in mountainous terrain. 2 POB, 2 fatalities, aircraft destroyed.
28/07/2019	Denmark	EKTO : Tølløse	SCHEMPP HIRTH - DISCUS B	Broken winch cable; sailplane spin on final approach. 1 POB, 1 fatality, aircraft destroyed.
30/07/2019	Germany	between Rickenbach and Altenschwand, Baden- Württemberg	GLASFLUGEL - HORNET	A sailplane crashed onto a local road during thermal flight instruction.
11/08/2019	Czech Republic	LKHB : Havlíckuv Brod	SCHLEICHER - ASW19 - B	Loss of control during take-off tow of sailplane. 1 POB, 1 fatality.
13/08/2019	Czech Republic	SW part of Trutnov	ORLICAN	Mid-air collision of sailplanes. 1 fatality and aircraft destroyed.
25/08/2019	France	Romilly sur Seine	OTHER	Loss of control after take-off - aircraft crashed.
31/08/2019	Spain	LEMX : La Mancha	GROB - SPEED ASTIR II	Sailplane crash during take-off. 1 POB, 1 fatality, aircraft destroyed.
01/09/2019	Austria	Priel, Wolfsberg	PZL BIELSKO - MDM1	Elevator problems in aerobatic flight - PIC bailed-out, PAX too late. 2 POB, 1 fatality, 1 serious injury.
11/09/2019	France	take-off from LFIX : Itxassou	COMCO IKARUS - IKARUS C42	Tow airplane failure on take-off - sailplane forced landing, airplane crash. 1 fatality.
13/09/2019	France	Saint Pons	SCHLEICHER - ASH26 - E	Sailplane lost control during soaring and crashed in mountainous area. 1 POB, 1 fatality, aircraft destroyed.
19/09/2019	Germany	near Boberg airfield	SCHEMPP HIRTH - DISCUS 2CT	Sailplane crashed due to unknown reasons. 1 POB, 1 fatality, aircraft destroyed.

				Callebra distance and a filtebra device depose de pope defension de service
12/10/2019	Czech Republic	Vrbno pod Pradedem	PZL BIELSKO - SZD42 - 2	Sailplane disintegration in flight and crash. 1 POB, 1 fatality, aircraft destroyed.
15/10/2019	France	Pic Saint Loup	ROLLADEN SCHNEIDER - LS7	Collision with terrain in flight on a slope. 1 POB, 1 fatality.
26/10/2019	Spain	Meranges	SCHEMPP HIRTH - VENTUS C	Sailplane crashed into a mountainous area while searching for thermals. 1 POB, 1 fatality, damage unknown.
03/11/2019	Czech Republic	Ludvikov	SCHLEICHER - ASW19 - B	Sailplane disintegration in flight and crash. 1 POB, 1 fatality, aircraft destroyed.
27/05/2020	Austria	A-6370 Kitzbühel	SCHEMPP HIRTH - DISCUS 2CT	Crash of a sailplane in steep terrain.
30/05/2020	Germany	Günzburg	SCHEIBE - ZUGVOGEL - III - IIIA	Sailplane impacted to the ground after interrupted A/C towing.
01/06/2020	Germany	Fulda-Johannisau	SCHLEICHER - ASW28	Sailplane with auxiliary power stalled and hit the Ground. After the impact the A/C caught fire.
11/07/2020	Germany	Dülmen	ROLLADEN SCHNEIDER - LS4 - B	Airborne collision between two aircrafts.
12/07/2020	Netherlands	EHGR (GLZ) : Gilze-Rijen	GLASER DIRKS - LS8 - 18	Loss of control after cable release - crash.
19/07/2020	France	Saint-Doulchard	GROB - G103 - TWIN ASTIR - TWIN II	Loss of control inflight and crash.
07/08/2020	Germany	EDNW : WEISSENHORN	ROLLADEN SCHNEIDER - LS4	Airborne collision between sailplane and a powered sailplane.
08/08/2020	Belgium	EBTN : Goetsenhoven	SCHEMPP HIRTH - NIMBUS 4DM	Loss of control on approach - Aircraft crashed.
15/08/2020	Italy	Rima San Giuseppe (Vercelli)	GLASER DIRKS - DG800 - B	Sailplane crashed into a mountainside. 1 POB, 1 fatality, aircraft destroyed.
19/08/2020	France	Saint André les Alpes	SCHEMPP HIRTH - VENTUS 2C	Aircraft collided with high terrain.
26/08/2020	United Kingdom	In a field on St. Edwards Junior School, Cheltenham	SCHLEICHER - ASH25E	Aircraft crashed under yet unknown circumstances.
31/08/2020	France	LFID : Condom Valence-Sur-Baïse	OTHER	Crash on initial climb.
12/09/2020	Switzerland	Col du Mollendruz	CENTRAIR - 101 - A	Crash after tow rope release.
11/10/2020	Spain	LEAX : La Axarquia-Leoni Benabu (Malaga)	SCHEIBE - SF25 - B	Incapacitation of pilot in-flight.

Aerodromes and ground handling

	State of			
Local Date	Occurrence	Location	Aeroplane	Headline
25/07/2010	Spain	Aeródromo Casarrubios del Mont	OTHER	Gyroplane collided with a person during taxi.
			PIPER - PA25 - 235,	Mid-air collision between a sailplane and an aeroplane above the
05/05/2012	France	AD Buno Bonnevaux (91)	SLINGSBY - T31	runway.
11/11/2012	Italy	Roma Fiumicino Airport	AIRBUS - A320	Loading crew caught between loader and baggage door.
10/12/2012	Cyprus	Larnaca	CESSNA - 750	A service vehicle struck the right wingtip, vehicle driver trapped.
		2 km from Jämijärvi airfield EFJM,		During climb, right wing broke due to a fatigue failure - aircraft entered
20/04/2014	Finland	Satakunta	OTHER	a spin, crashed, and caught fire.
24/12/2015	Spain	Ronda	SOCATA - TB9	Aircraft crashed and consumed by post-crash fire, incorrect fuel used.
		Lievestuore (municipality of		Aircraft crashed into a forest during final approach in bad weather
19/07/2017	Finland	Laukaa)	PIPER - J3C - 65 - 65	condition.

ATM/ANS

Local Date	State of Occurrence	Location	Aeroplane	Headline
02/08/2012				Aircraft experienced an unstable approach and crashed in heavy fog
	Spain	Approach to Santiago Airport (LEST)	CESSNA-500	condition. Both crew were killed, and the aircraft destroyed.
30/09/2012				Aircraft crashed in wooded terrain in IMC weather conditions. Aircraft
				was not airworthy and was overloaded with 8 passengers on board. The
				accident resulted in 6 fatalities and 2 passengers sustaining serious
	Austria	Ellbögen, Innsbruck district, Tirol	CESSNA - 414	injuries. Aircraft was destroyed.
17/07/2015	Slovakia	Under Kláštorná roklina gorge –	AGUSTA - A109 - K2	Rescue helicopter crashed into a riverbank after colliding into power
		Hornád canyon - Slovenský Raj		cables during an emergency medical services mission. All 4 crew
				members and passengers were killed in the crash.
31/07/2015	Italy	Pizzo Zocca di val Masino (Sondrio)	AEROSPATIALE - AS350 -	Helicopter crashed into mountain peak obscured by clouds during a VFR
			B3	aerial working flight. All 3 crew members were killed in the crash.
24/01/2017	Italy	Monte Cefalone, Lucoli (AQ)	AGUSTA - AW139	Helicopter performing HEMS flight to Campo Felice ski area impacted
				the South-West side of the Cefalone Mountain. The 6 persons on board
				were fatally injured and the helicopter completely destroyed.
23/01/2018	Germany	Philippsburg	EUROCOPTER - EC135 -	A helicopter and an airplane collided mid-air near Philipsburg. The 4
			P2, PIPER - PA28RT - 201T	occupants onboard the 2 aircraft were fatally injured.

15/12/2018	Portugal	1NM South of Valongo	AGUSTA - A109 - S	Helicopter conducting emergency medical service collided with radio tower in poor weather conditions. All 4 crew members and passengers on board were killed.
25/01/2019	Italy	Rutor Glacier	AEROSPATIALE - AS350 - B3, JODEL - D140 - E	A helicopter and an airplane collided near the Rutor glacier. The pilot and 4 out of the 5 passengers on board of the helicopter and 2 out of the 3 pilots on board of the airplane died.





Catalogue number

TO-AA-21-001-EN-N

ISBN

978-92-9210-224-1

ISSN

2314-9272

DOI 10.2822/071257

Postal address

Postfach 101253 50452 Cologne

Visiting address

European Union Aviation Safety Agenc Konrad-Adenauer-Ufer 3, D-50668 Köln, Germany
 Tel.
 +49 221 89990-000

 Fax
 +49 221 89990-999

 Mail
 info@easa.europa.eu

 Web
 www.easa.europa.eu