


CO ALARM CHECKLIST



- TURN CABIN HEAT FULLY OFF
- OPEN CABIN FRESH AIR VENTS
- **DO NOT** OPEN PILOT STORM WINDOW- THIS WILL REDUCE CABIN PRESSURE AND MIGHT MAKE THINGS WORSE
- LEAN FUEL MIXTURE AGGRESSIVELY AS POSSIBLE – LEAN OF PEAK OPERATIONS
- IF AVAILABLE: USE SUPPLEMENTAL OXYGEN
- MONITOR CO DETECTOR FOR DROPPING PPM LEVELS
- IF CO CONCENTRATION IS ABOVE 50-70 PPM, AND/OR YOU RECOGNISE SYMPTOMS LIKE HEADACHE, NAUSEA, DOUBLE VISION, ETC. INFORM ATC/FIS AND DO NOT HESITATE TO DECLARE AN EMERGENCY
- LAND PROMPTLY, AS SOON AS PRACTICABLE
- SEEK MEDICAL ATTENTION AFTER LANDING
- HAVE AIRCRAFT INSPECTED PRIOR TO FURTHER FLIGHTS