

EASA Certification Information

No.: 2015 - 12

Issued: 22 December 2015

Subject: Revocation of various ETSOAs and Luftfahrt-Bundesamt (LBA) approvals upon request to

surrender by AmSafe Bridport, Ltd. t/a AmSafe Bridport as legal successor of Hoffmann

Air Cargo Equipment GmbH

Authorisation No: EASA.210.281, EASA.210.299, EASA.210.336

LBA.O.11.401/24 JTSO, LBA.O.11.401/68 JTSO, LBA.O.11.401/69 JTSO, LBA.O.11.401/70 JTSO, LBA.O.11.401/71 JTSO, LBA.O.11.401/78 JTSO (grandfathered under Article 6 of

Regulation (EU) 748/2012)

ETSOA No./LBA No.	Description / Model	P/N	Date of last issue	DDP ref.
EASA.210.281	Air Cargo Net, Type HTRO 7	HTRO 7 ()	01/07/2005	HTRO 7
EASA.210.299	Air Cargo Net, Type HTRO 9	HTRO 9 ()	01/07/2005	HTRO 9
EASA.210.336	Air Cargo Net, Type HTRO 8	HTRO 8 ()	09/09/2005	HTRO 8
LBA.O.11.401/24 JTSO	Air Cargo Net, Type HTRO 1	HTRO 1 ()	16/05/2000	HTRO 1
LBA.O.11.401/68 JTSO	Air Cargo Net, Type HTRO 2	HTRO 2 ()	19/05/2000	HTRO 2
LBA.O.11.401/69 JTSO	Cargo Pallet Net Type: HTRO 3 ()	HTRO 3 ()	26/06/2000	HTRO 3
LBA.O.11.401/70 JTSO	Cargo Pallet Net Type: HTRO 4 ()	HTRO 4 ()	02/08/2000	HTRO 4
LBA.O.11.401/71 JTSO	Cargo Pallet Net Type: HTRO 5 ()	HTRO 5 ()	02/08/2000	HTRO 5
LBA.O.11.401/78 JTSO	Air Cargo Net, Type HTRO 6	HTRO 6 ()	12/09/2000	HTRO 6

Issued by: EASA.210.281, EASA.210.299, EASA.210.336- by EASA

 ${\tt LBA.O.11.401/24\ JTSO,\ LBA.O.11.401/68\ JTSO,\ LBA.O.11.401/69\ JTSO,\ LBA.O.11.401/70}$

JTSO, LBA.O.11.401/71 JTSO, LBA.O.11.401/78 JTSO – by LBA

Holder of the Certificate: AmSafe Bridport, Ltd. t/a AmSafe Bridport

The Court, West Street DT6 3QU Bridport, Dorset

United Kingdom

as legal successor of

Hoffmann Air Cargo Equipment GmbH

Background:

The request by AmSafe Bridport, Ltd. t/a AmSafe Bridport of 13 August 2015 to surrender its authorisations EASA.210.281, EASA.210.299, EASA.210.336, LBA.O.11.401/24 JTSO, LBA.O.11.401/68 JTSO, LBA.O.11.401/69 JTSO, LBA.O.11.401/70 JTSO, LBA.O.11.401/71 JTSO, LBA.O.11.401/78 JTSO has been accepted by EASA.

AmSafe Bridport, Ltd. t/a AmSafe Bridport as legal successor of Hoffmann Air Cargo Equipment GmbH informed the Agency that none of the Hoffmann Pallet Net designs as listed in the table above have been manufactured, supplied or released since acquisition in May 2010.

In accordance with the applicable EASA administrative procedures¹, EASA decided to accept the surrender of the aforementioned authorisations. EASA has submitted the decision to revoke EASA.210.281, EASA.210.299, EASA.210.336, LBA.O.11.401/24 JTSO, LBA.O.11.401/68 JTSO, LBA.O.11.401/69 JTSO, LBA.O.11.401/70 JTSO, LBA.O.11.401/71 JTSO, LBA.O.11.401/78 JTSO to the authorisation holder on 21 December 2015.

Contact:

Any request, query or comment should be sent to:

European Aviation Safety Agency Parts & Appliances Section Postfach 10 12 53 D – 50452 Köln

E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (http://easa.europa.eu/certification/internal-working-procedures.php)