

SAFETY REVIEW

APPENDIX 1 - LIST OF FATAL ACCIDENTS



2022

Appendix 1 List of fatal accidents

Commercial air transport – airlines and air taxi – large aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
			SWEARINGEN - SA227 -	
10/02/2011	Ireland	Cork Apt EICK	ВС	Impacted runway inverted.
11/11/2012	Italy	Roma Fiumicino Airport	AIRBUS - A320	Loading crew caught between loader and baggage door.
				Anti-icing system not activated by flight crew - Pressure sensor
24/07/2014	Mali	80 km south-east of Gossi	DOUGLAS - DC9 - 80 - 83	obstructed by ice crystals. Aircraft stalled and crashed.
		UUWW (VKO):	DASSAULT - FALCON 50 -	Aircraft collided with a snowplough vehicle during take-off run.
20/10/2014	Russian Federation	Moskva/Vnukovo	EX	Aircraft was destroyed by fire.
				First officer alone in the cockpit, initiated a rapid descent - Aircraft
24/03/2015	France	Prads-Haute-Bléone	AIRBUS - A320 - 200 - 211	impacted mountainous terrain.
			BOMBARDIER - CL600	IRU malfunction - Crew spatial disorientation - Loss of control -
08/01/2016	Sweden	Oajevágge	2B19	Aircraft crashed on a mountainous terrain.

Non-commercial complex business aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
			CESSNA - 750 - NO SERIES	
10/12/2012	Cyprus	Larnaca	EXISTS	A service vehicle struck the right wingtip, vehicle driver trapped.
	Congo, Democratic		DASSAULT - FALCON	
29/04/2013	Republic of the	FZAA (FIH): Kinshasa/N'djili	900EX	Collision with an individual on ground.
12/01/2014	Germany	Near Trier-Föhren Airport	CESSNA - 501	Aircraft collision against power pole.
			GULFSTREAM -	
04/01/2018	Finland	Kittilä airport, EFKT	GULFSTREAM 150	Fatal injuries to captain due to door opening violently.

Specialised operations aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Robin 400 180R while towing a glider in the take-off phase crashed.
11/01/2011	Italy	Airport LIRG	ROBIN - DR400 - 180R	The pilot of the airplane was killed.
02/06/2011	Netherlands	EHTE	CESSNA - F172	The aircraft crashed after pick-up of a banner.
18/06/2011	Poland	Plock - Wisla River	CHRISTEN - EAGLE II	Crash during aerobatics over river.
04/07/2011	France	AD Dijon-Darois (21)	SOCATA	Stalling of towing aircraft after glider release.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Loss of control during approach and subsequent crash with post-
30/08/2011	Poland	Nowy Targ	PZL OKECIE	impact fire.
28/04/2012	Germany	Alkersleben	ZLIN - Z226	Aircraft touched the ground after a formation flight.
			PIPER - PA25 - 235,	
05/05/2012	France	AD Buno Bonnevaux (91)	SLINGSBY - T31	Mid-air collision between a glider and an aeroplane above runway.
				Collision with power cables on approach and subsequent crash and
17/06/2012	Romania	Banesti, Prahova	AEROSTAR	post-impact fire.
22/07/2012	France	AD Couhé Vérac (86)	OTHER	Loss of control and subsequent crash during air show.
				Aircraft impacted terrain during aerial work operations - aerial
07/09/2012	Italy	Di Fioranello street 163, Rome	CESSNA - 402	photography.
				Avions Robin DR400 - Loss of control during take-off as aircraft fell
				into the vortex generated by the preceding aircraft flying - 4 persons
09/09/2012	Germany	Backnang-Heiningen	ROBIN - DR400 - 180R	on board, 3 fatalities, 1 serious injury.
			DIAMOND - DA40,	Mid-air collision during photo flight - 2 persons on board on each
22/10/2012	Netherlands	EHAA	GENERAL AVIA - F22	aircraft, 2 fatalities, 2 serious injuries - both aircraft destroyed.
09/03/2013	Czech Republic	600m N Srbce (Chrudim)	ZLIN - Z37 - A	Aircraft collided with trees in IMC.
		Madrid-Cuatro Vientos Airport	HISPANO AVIACION -	
05/05/2013	Spain	(LECU)	HA200 - D	Aircraft crashed during airshow.
		Egmond aan Zee, Noord-		
08/05/2013	Netherlands	Holland	CESSNA - 172 - P	Ditched in North Sea near Egmond.
01/06/2013	Sweden	Söderhamn Airport	SAAB - 91	Engine failure during airshow due to lose spark plugs.
29/06/2013	Germany	Eberswalde-Finow	ZLIN - Z526 - AFS	Aircraft crashed during aerobatics.
30/06/2013	Sweden	Near Veberöd, Sweden	GRUMMAN - GA7	Crash in a field after reported engine problems.
				Abrupt manoeuvre - left wing structural failure due to a significant
19/10/2013	Belgium	Gelbressee	PILATUS - PC6	overload - aircraft out of control crashed into a ploughed field.
				During climb, right wing broke due to a fatigue failure - aircraft
		2 km from Jämijärvi airfield		entered a spin, crashed, and caught fire - 11 persons on board, 8
20/04/2014	Finland	EFJM, Satakunta	Other	fatalities.
				Pitts S-2B Special - Aircraft crashed during aerobatic routine - 1 person
08/05/2014	Latvia	EVLA - Liepaja	PITTS - S2 - B	on board, 1 fatality - aircraft destroyed.
				Crashed shortly after take-off whilst glider towing. Glider
				disconnected and landed safely - 1 person on board, 1 fatality on
06/06/2014	Czech Republic	near Krizanov airfield, LKKA	TECNAM - P92	board - aircraft destroyed
			LEARJET - 35 - A, Military	Collision of two aircraft in flight, one military - 3 persons on board, 2
23/06/2014	Germany	Near Olsberg-Elpe	aircraft	fatally injured on board

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Topolów district Mykanów,		Piper PA-31 Navajo - Engine problems during climb-out, loss of height
		Czestochowskastreet No 36;		and collision with ground. Aircraft destroyed by post-impact fire – 12
05/07/2014	Poland	near Czestochowa	PIPER - PA31P	persons on board – 11 fatalities on board, 1 serious injury.
19/07/2014	Czech Republic	1 NM S LKKM	ZLIN - Z526 - F	The aircraft entered an inverted spin and impacted the ground.
				Aircraft suddenly descended in nose down attitude. Collision with the
01/08/2014	France	Linthal (68)	Other	ground during aerial photography flight.
				Parachute opened upon parachutist leaving the aircraft, parachute
				struck the tail of the aircraft and damaged part of the stabilizer, loss of
13/09/2014	France	At FL110 AD Tarbes Laloubère	CESSNA - U206 - F	control of aircraft and subsequent crash.
				During an evasive manoeuvre a light aircraft hit the tug's towrope of
				another aircraft with the propeller. The aircraft crashed into a
1.1/20/2011			5	cornfield and burst into flames – 2 persons on board, 2 fatalities -
14/09/2014	Germany	Münster-Telgte Airfield - EDLT	DALLACH - D4, Other	aircraft destroyed
21/00/2014	land.	naan Vanasia Lida Aimaant	VTDENACAID	XtremeAir Xtreme 3000 - Aircraft crashed during aerobatics
21/09/2014	Italy	near Venezia Lido Airport	XTREMEAIR	performance – 1 person on board, 1 fatality - aircraft destroyed
28/09/2014	Italy	near aviosuperficie Mensanello, Siena	PITTS	Loss of control during aerobatic manoeuvres. Aircraft crashed and caught fire
26/09/2014	italy	Sieria	P1113	During aerobatics session the aircraft went into spin after a half loop
30/05/2015	France	Blois	STAMPE - SV4 - C	manoeuvre. Aircraft crashed.
30/03/2013	Trance	Biol3	VANS - RV8 - A, VANS -	manocavic. All craft crashed.
31/05/2015	Adriatic Sea	Tortoreto, Alba Adriatica (TE)	RV7	Collision of two aircraft in flight during an air show.
01/08/2015	Romania	next to Stancuta airfield	PZL MIELEC - AN2 - R	Aircraft crashed shortly after take-off.
				Aircraft deviated to the right during the take-off- the right-wing tip hit
03/08/2015	Spain	Viladamat airfield	Other	the ground. The aircraft crashed and caught fire.
			LET - L410 - UVP, LET -	Mid-air collision while en-route. Both aircraft were performing
20/08/2015	Slovakia	Cervený Kamen	L410	parachute dropping operations.
			COMCO IKARUS - IKARUS	
			C42 - B, COMCO IKARUS -	
23/08/2015	Switzerland	Dittingen LSPD	IKARUS C42 - B	Mid-air collision during air show.
30/08/2015	Austria	Airfield Friesach Hirt, Carinthia	PITTS - S2 - B	Loss of control during aerobatic show with aircraft.
27/09/2015	France	LFDW - Chauvigny	OTHER	Loss of control in circuit pattern - aircraft crashed.
14/03/2016	Kenya	Proche AD Kauro	OTHER	Aircraft crash.
20/05/2016	Germany	Rodigast	PZL OKECIE - PZL101	Loss of control and subsequent crash into forest.
04/06/2016	Czech Republic	LKNYMB	OTHER	Fall of ULAC - Loss of speed during turn and fall into a spin.
				Parachutists reserve parachute opened prematurely. Parachutist hit
11/06/2016	Italy	Cecina	PILATUS - PC6	the RH stabilizer - structural damage in flight and crash.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		after take-off from LPFC:		
19/06/2016	Portugal	Figueira dos Cavaleiros	PILATUS - PC6 - B2H4	In-flight fuselage breakup due to material fatigue.
			PIPER - PA28 - 140,	Two aircraft collided with each other in the vicinity of LHGD. 4 persons
18/09/2016	Hungary	Gödöllo Arboretum	CESSNA - 182 - D	on board, 4 fatalities.
16/07/2017	France	Capo di Feno	ICP - SAVANNAH - VG	Roll controls problem, loss of control - aircraft crashed.
		Near the 55 kilometer point of		
		N-340 road (Vejer de la		Bird strike followed by crash during fumigation work in a rice field
15/08/2017	Spain	Frontera)	PIPER - PA36 - 375	(low altitude operation).
03/09/2017	Italy	Pontinia	CESSNA - 182 - P	Loss of control inflight - crash and fire.
16/09/2017	Slovakia	LZPE	ZLIN - Z37 - C	Loss of control and crash.
		3.5 nautical miles (NM) west of		
13/05/2018	Ireland	ClonbullogueVillage, Co. Offaly	CESSNA - 208 - B	Aircraft crash following steeply banked turn.
		Just outside EHSE:		
31/05/2018	Netherlands	Hoeven/Seppe	PIPER - PA25 - 235	Aircraft crashed in attempt to pick up commercial text banner.
		2000 m off the coast of Cala		
		Solleric, municipality of Pollença		
12/06/2018	Spain	- Mallorca	AIR TRACTOR - AT802	Aircraft crashed into the sea.
27/07/2018	France	Bouloc-en-Quercy	PILATUS - PC6 - B2H4	Wing strike with a skydiver (wingsuiter).
29/07/2018	Slovenia	AD Bovec	ROBIN - DR400 - 180R	Collision with the ground after towing, fire
08/08/2018	Mauritania	Diatar	AYRES - S2R - T - T34	Aircraft collision with the ground, fire.
			AEROSPOOL - WT9,	Loss of control of the tug ULM during take-off in glider tow, collision
19/08/2018	France	AD Colmar Houssen	CENTRAIR - 101 - A	with runway, fire. 1 person on board, 1 fatality.
15/06/2019	Poland	Wisla river, Plock	YAKOVLEV - YAK52	Not recovered spin and crash to the river.
14/07/2019	Sweden	ESNU (UME): Umeå	GIPPSLAND - GA8 - TC320	The aircraft impacted terrain in a steep nose down after take-off.
			MORANE SAULNIER -	
27/08/2019	Belgium	Kortrijk airport (EBKT)	MS893	Crash during banner pick up.
11/09/2019	Germany	Gransee	CESSNA - 208	Crash into terrain.
			COMCO IKARUS - IKARUS	Tow airplane failure on take-off - glider forced landing, airplane crash.
11/09/2019	France	take-off from LFIX: Itxassou	C42, SCHLEICHER - ASK21	1 fatality.
13/08/2020	Germany	Hessisch Lichtenau	ROBIN - DR400 - RP	Loss of control.
20/09/2020	Italy	near LILR: Cremona/Migliaro	PILATUS - PC6 - B2H4	Collision between airplane and skydiver. Crash.
			COMCO IKARUS - IKARUS	
30/09/2020	France	Mont d'Artzamendi	C42 - C	Birdstrike and crash during evasive manoeuvre.
				Aircraft crashed into terrain during a locust spraying mission and
11/02/2021	Ethiopia	Goba	AYRES - S2R600 - T - T34	caught fire.
26/07/2021		Nordeneney	CESSNA - 208	Aircraft crashed into the water during approach.

Local Dat	e State of Occurrence	e Location	Aeroplane	Headline
			AEROSPOOL - WT9,	
13/10/20	21 France	Bordes-de-Rivière	GLASER DIRKS - DG600M	Glider crashed into terrain after disconnection from the tug microlight

Non-commercially operated small aeroplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
		near LEMT - Casarrubios Del		Aircraft crashed into a field in a high nose down attitude. 2 persons on
15/01/2017	Spain	Monte	TECNAM - P2002	board, 2 fatalities.
		near LEAX - La Axarquia-Leoni		Loss of control of the aircraft by steep turn after take-off on runway
19/01/2017	Spain	Benabu	RANS - S6 - ES	30.
02/02/2017	Germany	Melle	DIAMOND - DA20 - A1	Aircraft collided with a wind turbine. 1 person on board, 1 fatality.
20/02/2017	Guadeloupe	Petit Bourg	PIPER - PA28 - 161	Airplane crashed into a building while flying at low altitude.
		near LFHL - Langogne /	ALPI AVIATION -	
10/03/2017	France	Lespéron	PIONEER200	Collision with the ground after take-off - Aircraft catch fire.
		Cloncoskoran, near Dungarvan		Aircraft crashed in a field due to engine failure. 1 person on board, 1
27/03/2017	Ireland	Co. Waterford	RUTAN - LONGEZ	fatality.
05/04/2017	Germany	Wedemark	OTHER - Not mapped	Collision with power line, fire, and crash.
				During a go-around manoeuvre, the aircraft collided with trees,
06/04/2017	France	AD Megève	OTHER	crashed and caught fire.
		during initial climb from LFQZ:		
08/04/2017	France	Dieuze-Guéblange	OTHER	Loss of control in flight, collision with the ground - post impact fire.
				Bounced landing, the student pilot lost the aircraft's control after
			EVEKTOR AEROTECHNIK -	initiating a go around. The aircraft crashed in a field. 1 person on
09/04/2017	France	AD Chelles Le Pin	SPORTSTAR RTC	board, 1 fatality.
				Aircraft crashed on the ground during VFR flight. 2 persons on board,
14/04/2017	Italy	Dovera (CR)	TECNAM - P92	2 fatalities.
				During take-off the aircraft strikes the tops of the trees. The aircraft
15/04/2017	France	Saint Cybardeaux	OTHER - Not mapped	collides with the ground in a field and catches fire.
17/04/2017	Portugal	Cascais	PIPER - PA31T	Loss of control after failure of critical engine during take-off.
29/04/2017	Spain	Canillas de Aceituno	SOCATA - TB20	Inadvertent flight into IMC. Aircraft collided with a mountain.
30/04/2017	France	Sainte-Maxime, col de Bougnon	OTHER	Microlight went into a spin and crashed.
12/05/2017	France	AD Villefranche-de-Rouergue	OTHER	Aircraft rolled and crashed after take-off.
				Ultralight loss of control and crash due to opening of the canopy in
17/05/2017	France	Bettenheim	AEROSPOOL - WT9	flight.
				Aircraft partial loss of power as a result of fuel vapor disrupting fuel
				supply to engine during take-off followed by crash in adjacent field. 1
28/05/2017	United Kingdom	Apperknowle	EUROPA	person on board, 1 fatality.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Engine lost power after take-off and the aircraft crashed to the
03/06/2017	France	LFEZ: Nancy-Malzéville	OTHER - Not mapped	ground.
				Pilot loss control of the aircraft while performing an aerodrome
04/06/2017	France	LFEB: Dinan Trélivan	JODEL - D9	circuit. The aircraft crashed to the ground.
17/06/2017	France	Parisot	OTHER - Not mapped	The microlight hit the ground with a strong nose down attitude.
				Aircraft crashed shortly after take-off. 2 persons on board, 1 fatality, 1
26/06/2017	Czech Republic	LKHD: Hodkovice	PIPER - L4 - J	serious injury.
			CZECH SPORT - PS28 - NO	Pilot lost control after take-off during initial climb. 2 persons on
05/07/2017	Switzerland	near LSGN - Neuchatel	SERIES EXISTS	board, 2 fatalities.
		Lievestuore (municipality of		Aircraft crashed into a forest during final approach in bad weather
19/07/2017	Finland	Laukaa)	PIPER - J3C - 65 - 65	condition.
				Loss of control shortly after take-off - 2 persons on board, 2 fatal
21/07/2017	Poland	EPML	OTHER	injuries.
			TL ULTRALIGHT - TL2000	Ultralight TL-2000 airplane Crashed close to RWY threshold resulting
26/07/2017	Greece	Terpsithea airfield - LARISSA	STING	to fatal injury of both occupants.
				Aircraft collided with trees during approach. 1 person on board, 1
28/07/2017	Poland	EPLL	CESSNA - 152	fatality.
01/08/2017	Norway	Oppland county	AQUILA - AT01	Aircraft crashed into mountain. 1 person on board, 1 fatality.
				Forced landing on the beach due to engine failure. Aircraft collided
02/08/2017	Portugal	Praia de São João da Caparica	CESSNA - 152	with pedestrians. 2 persons on board, 2 fatal injuries on ground.
04/08/2017	Switzerland	Diavolezza/GR	PIPER - PA28 - 181	Collision with high terrain. 3 persons on board, 3 fatally injured.
07/08/2017	France	P-F ULM Saint-Estèphe	PIPISTREL	Crash during a low passage right after take-off followed by fire.
				The aircraft crashed into the Lake Bodensee north of Konstanz. 2
08/08/2017	Germany	Bodensee / Mainau	PIPER - PA46	persons on board 2 fatalities.
				Loss of control with incorrect flap configuration followed by aircraft
19/08/2017	Spain	Coscojuela de Sobrarbe airfield	OTHER	stall and crash during approach.
19/08/2017	Romania	Tătăruși commune, Lași county	OTHER	Engine failure shortly after take-off. Aircraft loss height and crashed.
20/08/2017	Switzerland	Alp Tsanfleuron, Savièse VS	PIPER - PA28 - 161	Aircraft collided with terrain. 3 persons on board, 3 fatalities.
				Pilot lost the aircraft control while performing aerobatics manoeuvre
22/08/2017	Norway	near Holmestrand	PITTS - S2 - B	and crashed. 2 persons on board, 2 fatalities.
	_		MORANE SAULNIER -	Collision with the ground due to unknown circumstances. 1 person on
27/08/2017	Germany	Moormeerland	MS883	board, 1 fatality.
31/08/2017	Spain	Sant Pau D'Ordal	ICP - SAVANNAH	Crash in mountainous area in adverse weather conditions.
00/00/55:5		0 1 (0)	DIDED DAG(Aircraft crashed on the ground during VFR approach in poor weather
09/09/2017	Italy -	Salussola (BI)	PIPER - PA34	conditions. 1 person on board, 1 fatality.
10/09/2017	France	Luray	EVEKTOR AEROTECHNIK	The pilot lost control of his aircraft which collided with the ground.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Aircraft crashed due to unknown reasons. 4 persons on board, 4
12/09/2017	France	Ghisonaccia	DIAMOND - DA42	fatalities.
				Aircraft crashes in high terrain - 2 persons on board, 2 fatally injured -
12/09/2017	Switzerland	Braunwald/GL	MOONEY - M20K	Aircraft destroyed.
				Loss of control on approach, spin and crash. 2 persons on board, 2
19/09/2017	Norway	near ENHA - Hamar / Stafsberg	VANS - RV4	fatalities.
26/09/2017	Czech Republic	near Noviny pod Ralskem	CESSNA - 421 - B	ENG1 failure en-route, spin, ENG2 shutdown; Crash and fire.
28/09/2017	United Kingdom	Grove Farm, Wolvey	EUROPA - EUROPA	On landing, runway excursion through hedge.
28/09/2017	France	AD Saint-Jean-d'Angély	OTHER - Not mapped	Engine failure, loss of control, collision with the ground, fire.
05/10/2017	Portugal	Marim-Quelfes	KOLB - TWINSTAR - III	Aircraft stalled shortly after take-off and crashed.
05/10/2017	France	LFCL - Toulouse Lasbordes	COLOMBAN	Runway excursion - aircraft overturned.
		1,5 km from Padenghe sul		
07/10/2017	Italy	Garda	TECNAM - P2002	Aircraft crashed on the ground during VFR flight.
08/10/2017	France	LFCN - Nogaro	OTHER - Not mapped	Loss of control on take-off, collision with ground and fire.
08/10/2017	Spain	Escorca, near Binissalem	OTHER	Aircraft collision with mountainous terrain in a narrow valley.
				Stall during a manoeuvre with high inclination and low height shortly
08/10/2017	France	AD Nogaro	FUNK	after take-off, collision with the ground, fire.
				Malfunction of the pyrotechnic system of the cruise rescue parachute,
16/10/2017	Germany	Jüterbog	AVID - MARK IV	loss of control, collision with the ground.
		•		Aircraft turn back during cruise in adverse weather conditions, loss of
07/12/2017	New Caledonia	Near AD Île des Pins	TECNAM	radio contact.
			GULFSTREAM -	
04/01/2018	Finland	Kittilä airport, EFKT	GULFSTREAM 150	Fatal injuries to captain due to door opening violently.
		Near Bredon Hill, Overbury,		
08/01/2018	United Kingdom	Worcestershire	PIPER - PA28 - 161	Aircraft struck trees in poor weather.
19/01/2018	Spain	La Pobla de Benifassà(Castellón)	ZENITH - CH601 - XL - XL	Aircraft crashed while flying low. 2 persons on board, 2 fatalities.
		-1 ···	EUROCOPTER - EC135 -	Mid-air collision between a helicopter and small aircraft. 4 persons
23/01/2018	Germany	Philippsburg	P2	fatally injured.
29/01/2018	Spain	Villamartín aerodrome, Cadiz	BREEZER	Loss of control followed by crash - during training flight in approach.
24/04/2215			050014 5450 :	Aircraft crashed in mountainous area during proficiency check - during
31/01/2018	Italy	Boscomantico (VR) - LIPN	CESSNA - F150 - L	circuit pattern downwind in approach.
44/02/2042	NI	No. of Contract of Hall	DIDED DA20 464	Crash into the sea shortly after take-off during night conditions whilst
11/02/2018	Norway	Near Svolvær airport Helle	PIPER - PA28 - 161	returning to departure airport for unknown reason.
		9,8 NM from EBZW outside the		
12/02/2010	Dolaium	residential area of Bolderberg	DEECH 22 F224	Aircraft callided with troop before consists to rest
12/02/2018	Belgium	Heusden Zolder	BEECH - 33 - F33A	Aircraft collided with trees before coming to rest.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Asymmetrical extension of the flaps in the final, loss of control and
24/02/2018	France	Trignac	DYN AERO - MCR01 - ULC	collision with the ground.
				Airplane crashed due to unknow circumstances. 2 persons on board, 2
10/03/2018	Germany	Bensheim	ZENAIR - CH601	fatalities.
31/03/2018	France	Proche AD Saint Chamond	ROBIN - DR400 - 120	Runway overrun on take-off, collision with an obstacle.
05/04/2018	Niger	AD Tapoa	OTHER	Accident for yet unknown reasons. 1 person on board, 1 fatality.
				Aircraft crashed after a half roll followed by a half loop-down at low
08/04/2018	France	LFQL: Lens / Bénifontaine	YAKOVLEV - YAK18 - A	height.
		2NM SW Veselí nad Lužnicí near		Ultralight aircraft crashed and debris was scattered over large area. 2
09/04/2018	Czech Republic	Kundratice	OTHER - Not mapped	fatalities.
			CIRRUS - SR20 - NO	
15/04/2018	Germany	Schwäbisch Hall	SERIES EXISTS	Collision of two powered aircraft during approach. 2 fatalities.
19/04/2018	United Kingdom	Crumlin	CESSNA - 152	Aircraft crashed by unknown reasons and caught fire.
		13.26 km East of City of		
21/04/2018	Greece	Nafpaktos	PIPER - PA28 - 140	Collision with cable during emergency landing.
		Channay-sur-Lathan ULM		
23/04/2018	France	airfield	RANS - S6 - ES	Aircraft crash after upset on rejected lading.
				Aircraft stalled during initial climb. Aircraft destroyed and 1 person on
24/04/2018	Germany	Mittelfischach	OTHER	board fatally injured.
29/04/2018	Austria	next to LOWI - Innsbruck	RUTAN - VARIEZE	Aircraft crash after take-off. 2 fatalities.
01/05/2018	Poland	Skorupy pow. Otwocki	OTHER	Aircraft crash with unknown cause.
04/05/2018	Ireland	near Ballina	OTHER - Not mapped	Aircraft crashed after pilot became unconscious.
				Aircraft hit treetops at the top of a ridge, collision with the ground,
08/05/2018	France	Marnaves	AQUILA - AT01	post-impact fire.
				Contamination of extruded polystyrene foam with fuel - wing fracture
				due to seepage / fuel leak followed by material separating from
	_			aircraft followed by spin, crash, and post impact fire - during initial
11/05/2018	France	AD Nancy-Essey	RUTAN - VARIEZE	climb.
16/05/2018	Spain	LESU: La Seu d'Urgell Airport	PIPISTREL	Aircraft crash during go around manoeuvre.
22/05/2012	A 1	Low flying area Gouda, near	0500NA 5470 N	
22/05/2018	Netherlands	Stolwijk	CESSNA - F172 - N	Collision with trees followed by crash.
26/05/2018	Spain	Vicinity of Loja Aerodrome	AVID - AVID FLYER	Aircraft crash due to a loss of control during the initial climb.
27/05/2010	Commons	NUMBER	AEROSPOOL - WT9 - NO	Aircraft arealised into a forested assumbting 4 fotality.
27/05/2018	Germany	Nürtingen	SERIES EXISTS	Aircraft crashed into a forested mountain. 1 fatality.
31/05/2018	Hungary	Pécs-Pogány Airport, SW 1.8 km	OTHER - Generic	Aircraft crashed after take-off and caught fire after the impact.
04 /06 /2040	C	Dad Navasaka/Akawailas	MUDDLIV DENECADE	The pilot lost control after a turn and the aircraft got into a spin.
01/06/2018	Germany	Bad Neuenahr/Ahrweiler	MURPHY - RENEGADE	Microlight caught fire after impact on ground.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			RIHN - DR107 - NO SERIES	
01/06/2018	Sweden	Opand airport	EXISTS	Aircraft crashed, possibly after aerobatic manoeuvres. 1 fatality.
				After a manoeuvre to over fly over a mountain the aircraft lost
02/06/2018	Italy	Malga Casarine - Trento	CESSNA - 152	altitude and crashed.
20/06/2018	Germany	Mosbach	JODEL - D9	Aircraft crashed shortly after take-off.
24/06/2018	France	Arvieu	BEST OFF - SKYRANGER	Collision with a power line followed by crash.
26/06/2018	France	AD Oloron Herrère	OTHER	Aircraft crashed for yet unknown reason.
04/07/2018	Austria	LOAV - Bad Vöslau	CESSNA - 172 - S	Aircraft stall on take-off and crash.
				Aircraft terrain collision during emergency landing due to low engine
08/07/2018	Latvia	Parish Davini	BUCKER - BU133 - C	oil pressure.
			COMCO IKARUS - IKARUS	
09/07/2018	France	Ladignac	C42 - B	Loss of control, collision with the ground during approach.
		Farm field to 1.2NM West of		Aircraft crash for unknown reasons during the RH downwind to
10/07/2018	Portugal	runway 03 threshold	CESSNA - 152	runway 21.
				Loss of engine power in initial climb, collision with the ground, in
16/07/2018	France	after take-off from Les Mureaux	TECNAM - P2002 - JF	instruction flight.
		Mediterranean Sea, near San		
17/07/2018	France	Giuliano	SOCATA - TB20	Low pass over the see and crash.
23/07/2018	France	Saint-Pardoux-et-Vielvic	CESSNA - F172 - N	Trajectory deviation. Aircraft crashed.
27/07/2018	Switzerland	near Col Durand	ROBIN - DR400 - 180	Collision with elevated terrain in mountainous area.
28/07/2018	France	AD Charleville Mézières	ROBIN - DR400 - 180	Engine power loss during initial climb, aircraft turned left and stalled.
				The towing aircraft crashed after finishing towing a glider. 1 person on
29/07/2018	Slovenia	Near Airport Bovec	ROBIN - DR400 - 180	board 1 fatality, aircraft destroyed.
		Near Frătăuții Vechi airfield,		
04/08/2018	Romania	LRSV	STEEN - SKYBOLT	Collision of two aircraft during training for air show.
04/08/2018	Switzerland	Rengg Pass (LU)	SOCATA - TB10	Crash during cruise phase.
06/08/2018	France	Mazoires	CESSNA - 172 - S	Loss of radio and radar contact, collision with the ground.
09/08/2018	Germany	Münster	BEECH - 58	Crash in training flight - during approach.
11/08/2018	Germany	EDXG: Melle-Gronegau	DYN AERO - MCR01	Aircraft crashed due to unknown reasons, fire and 2 fatalities.
15/08/2018	Italy	Cimadolmo	PIPER - PA18 - 150	Aircraft crashed after a power line collision.
16/08/2018	Germany	Nannhausen	OTHER	Aircraft crashed in the vicinity of the airfield. Unknown reason.
16/08/2018	Poland	Smerek	TECNAM - P2002	Low flying. Wheel hit a man.
21/08/2018	France	Rue	OTHER	Crash during training flight followed by post-impact fire.
21/08/2018	France	LFJD: Corlier	ROBIN - DR400 - 180	Aircraft landing before the runway threshold, then tilting on the back.
				Bounced landing with increased angle of attack and bank angle to the
24/08/2018	Bulgaria	LBWB	CIRRUS - SR22	left.

Local Date	State of Occurrence	Location	Aeroplane	Headline
29/08/2018	France	Bourg-Saint-Maurice	VANS - RV7	Aircraft crash into mountain in unfavourable weather conditions.
08/09/2018	Czech Republic	LKTEPL	OTHER	Loss of control during approach.
11/09/2018	Italy	Calatabiano (CT)	TECNAM - P92 - E	Total loss of power after take-off. Impact with terrain.
16/09/2018	France	Saint-Secondin	ROBIN - DR400 - 120	Loss of radar contact and collision with the ground.
25/09/2018	France	Aillant-sur-Tholon	OTHER	Collision with the ground after take-off.
26/09/2018	Germany	Alkersleben	TECNAM - P92 - E	Aircraft crash after engine problems.
13/10/2018	Netherlands	near EHST - Stadskanaal	PIPISTREL	Aircraft loss of control, crash and fire.
14/10/2018	Germany	EDER - Wasserkuppe	CESSNA - F172 - N	Runway overrun - aircraft collided with bystanders.
16/10/2018	Germany	near EDKB - Bonn / Hangelar	TECNAM - P2008 - JC	Engine failure - airplane crash.
		Océan Atlantique 60NM ouest		
23/10/2018	France	pointe du Raz	FLIGHT DESIGN - CTLS	Aircraft crashed
25/10/2018	New Caledonia	NWWE (ILP) : Ile Des Pins Moue	ZENAIR - CH601	Engine problem, stall, collision with the ground while test flight.
26/10/2018	France	Beaucaire	OTHER	Collision with the ground - post impact fire.
			SIAI MARCHETTI - SF260 -	
03/11/2018	Italy	Airfield "Caorle"	D	Aircraft crashed after a VFR approach.
07/11/2018	Norway	Near Meraaker Airfield	VANS - RV6	Aircraft crashed due to unknown reasons.
13/11/2018	Spain	coordinates below	CESSNA - 150 - F	Lost control in flight. Aircraft destroyed.
		over Erkelenz / Kückhoven		
17/11/2018	Germany	airfield	REMOS - G3	UL aircraft mid-air collision. 1 fatality and 1 seriously injured.
				Aircraft collided trees on final and crashed into the water (during non-
17/11/2018	France	Pleslin-Trigavou	SOCATA - TB20	precision approach without external visual reference).
			SCOTTISH AVIATION -	
30/11/2018	Hungary	Rábasömjén	BULLDOG	Aircraft collided with cable and crashed.
07/12/2018	Spain	Near LELL: Sabadell Airport	CESSNA - F177RG	Aircraft collided with a building and crashed during approach.
10/12/2018	France	Beaubery	CIRRUS - SR22	Communication lost while en-route, collision with elevated terrain.
				Shortly after lift-off (approx. 100ft) aircraft fell and rolled; aircraft
15/12/2018	Netherlands	EHHV	OTHER	impacted with inverted attitude and was fully destroyed.
		approach to VTBT: Chon Buri /	FLIGHT DESIGN - CTLS -	
30/12/2018	Thailand	Bang Phra	ELA	Aircraft crash on final approach. Suspected collision with powerlines.
09/01/2019	Spain	Mount Ernio	PIPER - PA28R - 201	Aircraft crash in mountains.
12/01/2019	Germany	Prädikow	PARTENAVIA - P68 - B	Crash into terrain due to unknown reasons.
		Approx. 1.650 m along from		
		Kavourotrypes Kryoneri beach		
16/01/2019	Greece	of Mesolongi sea area	MONNETT - SONERAI - 2	Aircraft uncontrollable ditched and sank on the beach.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Sea area at Patraikos Bay -		
		Greece, 1650m from Kryoneri		
16/01/2019	Greece	Beach	MONNETT - SONERAI - 2	Ultralight airplane crashed at sea near Kryoneri at Patraikos Bay.
			AEROSPATIALE - AS350 -	Mid-air collision and crash between a helicopter and a Jodel. 6
25/01/2019	Italy	Rutor Glacier	В3	fatalities.
		1 NM south-east of Quijorna		
06/02/2019	Spain	(Madrid)	TECNAM - P2002 - JF	Mid-air collision - 2 fatal injuries.
21/02/2019	France	Port le Grand	OTHER - Not mapped	Ultralight collided with trees in unfavourable weather conditions.
21/02/2019	Romania	after take-off from LRTZ: Tuzla	DIAMOND - DA42	Loss of control during take-off followed by crash.
			EVEKTOR AEROTECHNIK -	
24/02/2019	Spain	LEIR: Aerodromo Air Marugan	EV97	Loss of control during initial climb and crash.
			CZECH SPORT -	
16/03/2019	Portugal	LPBG (BGC): Bragança	SPORTCRUISER	RH wing failure/separation in flight - aircraft crash.
		Aviosuperficie Alfina (Castel		Aircraft collided with the ground while performing aerobatics
30/03/2019	Italy	Viscardo – Terni)	ZLIN - Z50 - LA	manoeuvres.
31/03/2019	Italy	Chantornè (Torgnon – Aosta)	ZLIN	Loss of control inflight (microlight).
20/04/2019	Bulgaria	Orizari	ZENAIR - CH601	LH wing separation in flight - aircraft crashed.
07/05/2019	France	Saint-Antonin-sur-Bayon	BEST OFF - SKYRANGER	Collision with a mountain due to flight control problems.
14/05/2019	Switzerland	near LSZF: Birrfeld	HB AIRCRAFT	Aircraft crash and fire shortly after take-off.
15/05/2019	Romania	Nehoiasu, Buzau county	TECNAM - P2008 - JC	Aircraft crashed under unknown circumstances.
19/05/2019	Germany	Wilhelmshaven, near	CIRRUS - SR20	Aircraft is missing, last seen over the North-Sea on radar.
25/05/2019	Germany	Elz	AEROPRO - EUROFOX	Microlight crashed in a forest due to unknown reasons. 1 fatality.
26/05/2019	Bulgaria	take-off from LBHT: Ihtiman	PIPISTREL	Aircraft entered spin after take-off.
30/05/2019	Switzerland	near LSGP: La Côte	JODEL - D140 - R	Aircraft crash shortly after take-off during a turn.
			BRM AERO - BRISTELL	
09/06/2019	Portugal	next to LPJF: Leiria	NG5	Aircraft crash followed by post-impact fire after a low pass.
10/06/2019	Germany	EDBW: Werneuchen	OTHER - Not mapped	Microlight crash and fire shortly after take-off.
			BRM AERO - BRISTELL	
13/06/2019	Ireland	Belan, near Moone, Co. Kildare	NG5	Loss of control causing vertical impact with terrain. 2 fatalities.
				Loss of turn control during initial climb followed by collision with
13/06/2019	France	Saillagouse (66)	CESSNA - 172RG	ground and post-impact fire.
21/06/2019	Netherlands	Oudemolen	PIPER - PA18 - 125	Mid-air collision whilst a formation fight.
22/06/2019	North Sea	11NM S of Mandal	PIPER - PA28 - 161	Engine suffered temporary failure - crashed into the ocean.
		near EBBZ: Pont-À-Celles /		
22/06/2019	Belgium	Buzet	ZENAIR - CH601	Aircraft crash on approach. Parachute deployed.
27/06/2019	Switzerland	near of Col de Sonlomont	REMOS - GX	Plane crashed into a forested, steep hillside.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Wetterstein, 2.5 NM N of 6105		
18/07/2019	Austria	Leutasch	CIRRUS - SR22	Aircraft crashed into a mountain for unknown reasons. 3 fatalities.
				During approach phase, the aircraft turned to the left and has a
20/07/2019	Germany	Bruchsal	JODEL - DR1050	collision with a building.
23/07/2019	France	Proche P-F ULM Calviac	OTHER	Aircraft collided with the ground due to unknown reasons.
			EVEKTOR AEROTECHNIK -	
			EV97 - TEAMEUROSTAR	Navigation error in the mountains followed by loss of control during a
24/07/2019	France	Larche	UK	U-turn.
			EVEKTOR AEROTECHNIK -	The aircraft made a steep left turn during an initial climb and probably
31/07/2019	Finland	EFTP (TMP): Tampere-Pirkkala	EV97	went into a spin - aircraft crashed.
			EVEKTOR AEROTECHNIK -	Crash into field under unknown circumstances. 1 person on board, 1
01/08/2019	Germany	Jesenwang	EV97	fatality, aircraft destroyed.
				Collision with high terrain. 2 persons on board, 2 fatalities, aircraft
06/08/2019	Italy	Monte Carmo (Savona)	DIAMOND - DA20 - A1	destroyed.
		after take-off from LFDJ:		
15/08/2019	France	Pamiers Les Pujols	OTHER	Loss of control after take-off. 1 person on board, 1 fatality.
22/08/2019	Germany	Steinfeld	CESSNA - 150 - L	Crash into field due to unknown reasons.
22/08/2019	Germany	Schneizelreuth	CESSNA - FR172 - H	Collision with mountain due to unknown reasons.
				Aircraft crashed at the Simplon pass east of the hospice. Aircraft
25/08/2019	Switzerland	Simplon Pass, 6600 ft	PIPER - PA28RT - 201	destroyed by post impact fire.
		platform ULM La selle en		
25/08/2019	France	Hermoy	OTHER	Loss of control in the final approach followed by crash.
			COMCO IKARUS - IKARUS	During a scenic flight, the ultralight had contact with trees and
31/08/2019	Germany	Tiefenbach/Hofen	C42 - B	crashed to the ground. 2 persons on board, 1 fatality, 1 serious injury.
15/09/2019	Spain	Pedreguer	CIRRUS - SR22	Airplane collision with mountain in IMC.
		near LIME (BGY): Bergamo /		Undefined problems - aircraft return; Loss of control after aborted
21/09/2019	Italy	Orio Al Serio	MOONEY - M20K	landing/go-around and crash.
21/09/2019	France	Putanges-le-lac	OTHER - Not mapped	Seaplane collision with a power line and crash.
				Airplane lost control and crashed in a forest. 2 persons on board, 2
26/09/2019	Czech Republic	near Petrovice	PIPER - PA22	fatalities, aircraft destroyed.
28/09/2019	France	Longuesse	DYN AERO - MCR04S	Crash for unknown reason, possible engine failure.
06/10/2019	Ireland	Duncormick, Co. Wexford	ROLLASON - D62 - B	Possible inflight breakup. 2 fatalities.
07/10/2019	France	Jumeauville	OTHER - Not mapped	Ultralight crashed due to unknown reasons.
				Crash for yet unknown reason - while en-route in night dual
10/10/2019	Spain	Bonastre	DIAMOND - DA40	instruction flight.
16/10/2019	Réunion	Plaine des Sables	CESSNA - 172 - S	Aircraft crashed after a technical malfunction.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		approach to LFPX: Chavenay		
22/10/2019	France	Villepreux	OTHER	Loss of control on final, collision with ground.
			ALPI AVIATION -	
30/10/2019	France	LFBJ: Saint-Junien	PIONEER200	Loss of control on approach, collision with the ground.
01/11/2019	Italy	near Monti della Tolfa airfield	CESSNA - FA150 - L	Aeroplane collision with powerline on final approach - crash and fire.
		River Labe between village		
16/11/2019	Czech Republic	Nucice and Nucnicky	OTHER	Collision with power lines.
08/12/2019	Lithuania	Noreikiškes	PIPER - PA30	Aeroplane crash after touch-and-go.
21/12/2019	Austria	near LOWZ: Zell am See	CIRRUS - SR22 - T	Aircraft crashed during missed approach in IFR.
28/12/2019	France	LFAV: Valenciennes / Denain	OTHER - Generic	Loss of control after take-off and crash.
29/12/2019	Switzerland	Arosa/GR	ZLIN	Aircraft crashed in mountainous terrain.
		near NWWL (LIF): Lifou		
04/01/2020	New Caledonia	Ouanaham / Iles Loyaute	MOONEY - M20J	Airplane crash after take-off.
07/01/2020	Switzerland	1.2 SW of Buttwil LSZU	CESSNA - F152	Aircraft crashed shortly after take-off.
16/01/2020	Germany	Strausberg	DALLACH - D4	The microlight crashed shortly after take-off.
				Deep landing combined with poor braking action on icy grass runway
21/01/2020	Norway	Gjølstad	DYN AERO - MCR01 - ULC	resulted in loss of control.
22/01/2020	Switzerland	Near Châtel-St-Denis	PIPER - PA28 - 181	Aircraft crashed into a forest.
		Airfield "Reno Air Club"		
11/02/2020	Italy	(Bologna)	TECNAM - P2002 - JF	Aircraft crashed on the ground after take-off.
12/02/2020	Italy	Carlentini (Siracusa)	TECNAM - P2002 - JF	Loss of control inflight
16/02/2020	Dominica	Au large de la Dominique	PIPER - PA28 - 161	Missed aircraft over the ocean.
16/02/2020	France	Creissels	PIPER - PA28 - 161	Aircraft crashed and caught fire.
18/02/2020	France	Au large de Fécamp	ROBIN - DR400	Aircraft crashed into the sea due to unknown reasons.
				Engine failure, stall on approach, wire strike, crash, and post impact
20/02/2020	Spain	Pamplona airport LEPP (PNA)	PIPER - PA60 - 602P	fire.
26/02/2020	France	Elne	PIPER - PA44 - 180	Aircraft crashed for unknown reasons.
17/03/2020	France	AD Vannes	OTHER	Engine shutdown in flight, loss of control, collision with the ground.
19/03/2020	Romania	near Siria Airfield, Arad county	OTHER - Not mapped	Crashed of ultralight aircraft under unknown circumstances.
			BRM AERO - BRISTELL	
24/04/2020	Czech Republic	Svatoborice (Hodonín)	NG5 - NO SERIES EXISTS	Ultralight aircraft crashed shortly after take-off due to loss of control.
25/04/2020	Slovenia	Ajdovscina Aerodrome	OTHER - Not mapped	Mid-air collision of an aeroplane and a paraglider and crash of both.
09/05/2020	Lithuania	on approach EYVK: Kyviskes mil	PIPER - PA38 - 112	Loss of control and crash in a field.
11/05/2020	Lithuania	EYVK	PIPER - PA38 - 112	Aircraft crashed close to the aerodrome. Loss of control suspected.
		Sjön Öjjen: 62°13,336'N		
12/05/2020	Sweden	017°18,825'E	OTHER	Accident pilot injured and passenger found dead in the water.

Local Date	State of Occurrence	Location	Aeroplane	Headline
22/05/2020	France	La Ferté-Bernard	OTHER - Not mapped	Crash of aircraft under unknown circumstances.
		proximity of airport Roma Urbe		
25/05/2020	Italy	(LIRU)	DIAMOND - DA20 - C1	Aircraft crashed after take-off and sunk into river.
27/05/2020	Germany	Blomberg	CESSNA - F150 - L	Aeroplane crashed into forest due to unknown reasons.
		Carcassonne Salvaza		
30/05/2020	France	Aerodrome LFMK (CCF)	PITTS - S2 - A	Crash of airplane shortly after take-off and fire post-impact.
		Aviosuperficie Arma di Nettuno		
31/05/2020	Italy	(RM)	TECNAM - P92 - E	Crash of aircraft after take-off.
02/06/2020	Sweden	Ekås	AAI	Accident - Small aeroplane - fatal injuries.
06/06/2020	Germany	Gießen	TL ULTRALIGHT	Loss of control after take-off - aircraft crashed.
17/06/2020	Germany	Reinsfield	PIPER - PA34 - 220T	Broke up in parts of aircraft en-route and crashed.
19/06/2020	France	Mortemer	OTHER - Not mapped	Loss of control while cruising. Collision with the ground.
			GROB - G115 -	Runway Excursion during TGL - Collision with obstacle on runway strip
25/06/2020	Czech Republic	LKBE	UNDESIGNATED SERIES	- Damage to aircraft.
04/07/2020	France	Marcé	STAMPE - SV4	Loss of control in flight and crash.
12/07/2020	Germany	Rheinstetten	OTHER - Not mapped	Loss of control in flight due to unknown reasons.
14/07/2020	Poland	EPBY): Bydgoszcz/Szweredowo	TECNAM - P2006T	Loss of control during a low pass over runway - crash.
				Electric problem during maintenance check flight – fire and forced
23/07/2020	France	AD Basle-Mulhouse	PIPER - PA28RT - 201T	landing.
25/07/2020	Germany	Wesel-Lackhausen	OTHER - Not mapped	Crash of aircraft into a house and fire post-impact.
02/08/2020	Germany	Heringsdorf	PILATUS - P2	Aircraft stalled during initial climb and crashed.
02/08/2020	France	AD Arras Roclincourt	ISSOIRE - APM30	Loss of control in flight during the last turn, collision with the ground.
04/08/2020	United Kingdom	near Bradley's Lawn airfield	RANS - S6 - 116	Aircraft crashed and fire.
05/08/2020	Germany	Iserlohn / Rheinermark airfield	ZLIN	Aircraft crashed after take-off.
				Bounced landing - Attempted go-around - Loss of control - Aircraft
06/08/2020	France	P-F ULM Cruis Mas Des Grailles	FLIGHT DESIGN - CTSW	crashed and caught fire.
			BRM AERO - BRISTELL	
15/08/2020	Poland	near EPKI: KIKITY	NG5	Aircraft crashed under yet unknown circumstances.
				Aircraft struck treetops - Loss of control - aircraft crashed and caught
15/08/2020	France	AD Saint-Martin de Londres	OTHER	fire.
16/08/2020	Germany	Porta Westfalica	OTHER	Crashed shortly after take-off and caught fire.
26/08/2020	Italy	nearby airfield "Sibari" (CS)	AVIAMILANO	Aircraft crashed shortly after take-off.
29/08/2020	Sweden	59°36,086'N 012°54,225'E	OTHER	ALRS - Accident - Small aeroplane.
			AVIONS FAIREY - TIPSY	
29/08/2020	Belgium	next to EBZH: Hasselt/Kiewit	NIPPER T66 - 2	Crash immediately after take-off.
30/08/2020	Denmark	EKFU: FUR	COMMANDER - 114 - B	Aircraft collided with trees during take-off.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Bukovno c.p.150, cca 6km NW		Aircraft crashed, due to unknown reasons, into a garden and was
04/09/2020	Czech Republic	Mladá Boleslav	ZLIN - Z526 - AFS	destroyed.
		LFCH: Arcachon La Teste De		
12/09/2020	France	Buch	ROBIN - DR400 - 120	Crash shortly after take-off and caught fire.
12/09/2020	France	Pas de la Coche	ROBIN - DR400 - 140B	Aircraft collided with elevated terrain and caught fire.
13/09/2020	Belgium	Chemin de Camusselle	RANS - S6 - ES	Loss of control inflight - aircraft crashed and caught fire.
16/09/2020	France	Arbent	OTHER	Collision with the ground on initial ascent, fire post-impact.
			DE HAVILLAND - DHC1 -	
17/09/2020	Germany	Bienenfarm	22	Aircraft lost control and crashed into a field.
10/10/2020	France	Loches	ROBIN - DR400 - 140	Mid-air collision, loss of control, collision with the ground, ULM fire.
29/10/2020	Czech Republic	Olšany u Prostejova	OTHER - Not mapped	Aircraft crashed due to unknown reasons.
02/11/2020	France	AD Cannes	SOCATA - TB10	Aircraft crashed into the sea during a night flight.
21/11/2020	Germany	Gera	OTHER - Not mapped	Loss of control in flight while en-route.
08/12/2020	Germany	Flammersfeld	CESSNA - T41	Descended and then crash landed in a field. Aircraft overturned.
23/12/2020	Germany	Büchenbach / Pegnitz	CESSNA - 172	Aircraft hit trees and crashed in a field.
		Mitsikeli Mountain, approx. 3,6		
		nm NE fromloannina Airport		Diamond DV20 airplane in solo training flight crashed on mountain
31/01/2021	Greece	(LGIO)	DIAMOND - DV20	while in poor visibility conditions.
05/02/2021	Germany	Sefferweich	OTHER	Loss of Control during VFR-Flight in IMC.
				During manoeuvring at altitude of 500 AGL, the aircraft came into a
13/02/2021	Netherlands	Nearby the town of Kornhorn	AEROSPOOL - WT9	steep dive from which it did not recover.
				Engine failure during initial climb, low runway circuit, steep turn, and
21/02/2021	France	Saint Florentin, Chaîne, France	OTHER	collision with ground during landing.
				Loss of control during an aerobatic manoeuvre, collision with the
28/03/2021	France	AD Villeneuve-sur-lot	MUDRY - CAP10	ground.
	_		EVEKTOR AEROTECHNIK -	
30/03/2021	Germany	Jandelsbrunn	EV97	Crash into Ground LOC-I: Loss of control - inflight.
				Loss of control occurred while cruising. The aircraft crashed into a
18/04/2021	Germany	Schepsdorf	OTHER	wooded area with a large descent angle and high energy.
10/01/0001	_			Collision with a bird, loss of control and collision with the ground,
18/04/2021	France	Saint-Pathus	ROBIN - DR400	under investigation.
22/24/2224		5001	OTUES.	During the initial climb, the ultralight aircraft got into an uncontrolled
22/04/2021	Germany	EDQK	OTHER	attitude and crashed into the ground.
23/04/2021	France	Grayan-et-l'Hôpital	AAI	Loss of control, smoke in cabin, possibly from Lithium battery.
08/05/2021	Switzerland	Oberramsern/SO	LANCAIR - LEGACY 2000	Aircraft crashed from low altitude.
09/05/2021	Poland	EPZP	TECNAM	Aircraft crash during take-off.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Loss of control in flight. The aircraft crashed to the ground near the
14/05/2021	Italy	Ravenna Airport (LIDR)	PILATUS - PC6	Ravenna airport. The aircraft caught fire on impact.
				The airplane was in cruise flight, slightly above FL100. The pilot
				initiated a right turn and descended. Shortly after, the plane crashed
23/05/2021	Germany	Straßenreuth, nahe	DIAMOND - DA20	on a field.
				During the final approach there was a change of direction in the flight
				path and contact with a tree. The left wing was severed, and the
26/05/2021	Germany	Grefrath	DIAMOND - DA20	aircraft crashed into a meadow.
12/06/2021	Switzerland	West of Piz Nair/GR	ROBIN - DR400	Collision between a glider and a single engine aircraft.
				The aircraft collided with vegetation and the ground. It was then
18/06/2021	France	Commune of Thoiry, Ain	FLIGHT DESIGN - CTLS	consumed by a post-crash fire.
20/06/2021	Czech Republic	Jickovice, Paseky district	NORTH AMERICAN - T28	During a formation flight one of the aircraft diverted and crashed.
		Village of Charia approx. 14 Km		Ultralight airplane with 2 persons on board crashed and destroyed by
21/06/2021	Greece	NE of the city of Pyrgos	OTHER - Not mapped	fire resulting in fatal injury of both occupants.
23/06/2021	Germany	Gefell, Thüringen	DIAMOND - DV20	Aircraft crashed - no information available of the causes.
				Light Type Aircraft Aquila A-210 crashed shortly after take-off and was
08/07/2021	Germany	EDXN Nordholz/Spieka	AQUILA - AT01	consumed by post impacted fire with 2 persons on board.
				Shortly after take-off the aircraft suddenly descended and crashed
				into ground. Fatal injuries with the persons onboard and the aircraft
08/07/2021	Sweden	ESOE - On the airport area	DE HAVILLAND - DHC2	was destroyed.
				During climb out after take-off in instrument flight conditions the
				control of the aircraft was lost. The aircraft impacted in a steep angle
17/07/2021	Germany	Steinenbronn	PIPER - PA28RT	at high speed in a wooded area.
18/07/2021	Germany	Renneritz	PZL OKECIE - PZL104	Aircraft crashed after loss of control following steep turn.
18/07/2021	Switzerland	Gotthard region/UR	MOONEY - M20J	The aircraft collided with high terrain and was destroyed.
				The aircraft entered a spiral trajectory, descending sharply, and hit
20/07/2021	Switzerland	Subingen/SO	BUCKER - BU131	grassland.
20/07/2021	Italy	Contrada Coccaro, Fasano (BR)	PIPER - PA28	Aircraft at low altitude, hit a power line and crashed to the ground.
29/07/2021	Czech Republic	Jablonná	OTHER - Not mapped	Aircraft entered into a spin after take-off.
				Difficulties experienced during initial climb, U-turn, loss of control,
30/07/2021	France	AD Vesoul - Frotey	OTHER	collision with ground. Instructional flight.
05/08/2021	France	Col du Glandon	ROBIN - DR400	Collision with trees then the ground, fire, during a flight in a valley.
06/08/2021	France	AD Courchevel	PIPER - PA46	Collision with the ground before the runway threshold, fire.
				After take-off the aircraft lost engine power and collided with the
08/08/2021	Latvia	EVCA	OTHER	terrain.
		Hang am Kuchelberg im Ettaler		Terrain collision during cross country flight in an engine powered
11/08/2021	Germany	Forst, Bayern	GLASER DIRKS - DG808	glider.

Local Date	State of Occurrence	Location	Aeroplane	Headline
21/08/2021	France	Courcelles	OTHER	Collision with a power line and then the ground during low flight.
				Smoke on board after touchdown, short circuit, loss of control,
23/08/2021	France	AD Lille Marcq-en-Baroeul	PIPER - L18	collision with the ground, fire.
				Aircraft suffered oil leak, student pilot diched into the sea, landing on
24/08/2021	France	Biscarosse - Plage	PIPER - J3C	a beach, instructional flight.
		Mokrý Háj next to golf course ca		The plane in an ascending left turn at an altitude of 2500 ft entered
27/08/2021	Slovakia	3km SE Skalica	EVEKTOR AEROTECHNIK	left spin, and after hitting the ground, the crew died.
27/08/2021	Czech Republic	LKMO	ZLIN - Z526	Aircraft crashed for yet unknown reason.
30/08/2021	Spain	Niebla	RANS - S12	Aircraft crashed for yet unknown reason.
				Wreckage of the aircraft found in a field 7.5 km from the airport,
04/09/2021	France	Woignarue	OTHER	causes not known.
06/09/2021	Germany	Wilnsdorf-Niederdielfen	OTHER	Crash into forest ca 10 minutes after take-off.
				The pilot announced a diversion to Dijon - Darois. The aircraft collided
10/09/2021	France	AD Dijon Darois	ROBIN - DR400	with the ground in a field near runway 02.
12/09/2021	France	Autouillet (78)	OTHER	Loss of control, collision with the ground, fire.
		East EBZH 33M after threshold		The aircraft made a sharp descending turn to the left. The aircraft
22/09/2021	Belgium	27	BRUGGER - MB2	descended rapidly and steep and impacted the ground.
27/09/2021	Finland	EFHV	VANS	Aircraft crashed due to unknown reasons.
		Ekfännsberget between Dala-		The aircraft collided with treetops and crashed. Wings broke off and
29/09/2021	Sweden	Järna and Leksand	CESSNA - F172	fire started. Pilot died.
30/09/2021	France	AD Saint Rambert d'Albon	TECNAM - P92	Decrease in engine power during initial climb, right turn and stall.
03/10/2021	Italy	Milano	PILATUS - PC12	Aircraft crashed during initial climb.
				Steep climb of the glider during towing, release then collision of the
13/10/2021	France	Bordes	GLASER DIRKS - DG600M	glider with the ground.
		LFGF Challanges Airport,		During the initial climb, the pilot lost control of his aircraft which
16/10/2021	France	Beaune	OTHER - Not mapped	collided with the ground. There was a post impact fire.
				Loss of power in the engine, causing the aircraft to crash into a farm
05/11/2021	Spain	LEAX Airport Axarquia	OTHER - Not mapped	located to the west of the aerodrome.
				Collision with high terrain. Wrong turn made ending with a collision
11/11/2021	Austria	6845 Hohenems	CESSNA - P210	with a mountain.
		Mountainous area "Profitis		
4	_	Ilias" approx. 40 Km east of		Ultralight experimental airplane crashed on mountainous terrain -
15/11/2021	Greece	Larissa city	OTHER	Fatal Injury.
				Collision with a pylon shortly after take-off and collision with the
18/11/2021	France	Proche AD Meaux	OTHER	ground.
23/11/2021	Norway	Tvedalen	DIAMOND - DA42	Aircraft crashed into terrain. All three on board received fatal injuries.

Microlights

Local Date	State of Occurrence	Location	Aeroplane	Headline
16/01/2011	Hungary	Eger	OTHER	Ultralight crashed after take-off.
27/02/2011	France	P-F ULM Perreux (89)	OTHER	Stall during the last turn, collision with the ground.
				Collision with terrain during a U-turn in a valley, fire during a
10/03/2011	France	Sault, Mont Ventoux (84)	OTHER	mountain flight.
				Loss of control in basic leg, fall of the passenger, collision with
28/03/2011	France	AD Berck-sur-Mer (80)	OTHER	vegetation.
31/03/2011	France	Lieu dit Haut Haunay (33)	OTHER	Collision with ground due to unknown reasons.
				Bounce during a take-off touchdown, collision with trees during the
06/04/2011	France	P-F ULM Torreilles (66)	OTHER	initial climb.
05/05/2011	Austria	Leogang, S	OTHER	Aircraft crashed on railway line. 2 persons on board, 2 fatalities.
06/05/2011	France	Seyne les Alpes (04)	OTHER	Loss of control during initial climb, collision with the ground.
		AERODROMO GUILLENA-		Pilot died after the aircraft went off the runway side and hit an
14/05/2011	Spain	SEVILLA	OTHER	embankment.
				Decrease in power during initial climb, U-turn, loss of control, collision
15/05/2011	France	AD St-Pierre-Pierrefonds (974)	OTHER	with ground, fire.
				Loss of control in flight resulted in a destroyed aircraft and death of
20/05/2011	Germany	Stralsund	OTHER	both occupants.
				Mid-air collision between a glider and LSA aircraft. 3 persons on
21/05/2011	Germany	Saarmund	REMOS - G3	board, 3 fatalities, both aircraft destroyed.
25/05/2011	France	Levet (18)	OTHER	Collision with a power line, fire.
29/05/2011	Germany	Tannheim	OTHER	Loss of control during approach, 1 person on board, 1 fatality.
				Loss of control during a practice flight. 2 persons on board, 1 fatality
30/05/2011	Germany	Barßel	OTHER	and 1 serious injury.
05/06/2011	Latvia	Airfield Cesis	OTHER	Ultralight aircraft Tucano Delta 3 YL-LVJ collision with ground.
				Collision with ground due to unknown reasons. Medical reasons
26/06/2011	France	Larressingle (32)	FLIGHT DESIGN - CTLS	suspected.
				Loss of control during a practice flight. 2 persons on board, 1 fatality
26/06/2011	Germany	Wiefelstede	ZENAIR	and 1 serious injury.
28/06/2011	Czech Republic	Velešín	OTHER	Manoeuvring at low altitude, loss of control and subsequent crash.
				Engine failure after take-off, aircraft made a steep turn and lost
11/07/2011	Czech Republic	LKCM	SKYSTAR - KITFOX	control.
11/07/2011	Czech Republic	Brno	OTHER	Aircraft crashed shortly after take-off. 1 person on board, 1 fatality.
				Aircraft crashed during off-field landing. 1 person on board, 1 serious
16/07/2011	Czech Republic	Nová Pec	TECNAM - P92 - EA	injury.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			EVEKTOR AEROTECHNIK -	Aircraft entered spin at the top of climb and did not manage to
19/07/2011	Czech Republic	Osek, 2 km N LKRY	EV97 - VLA	recover. 2 persons on board, 2 fatalities.
		AERÓDROMO DE MARUGÁN		Aircraft impacted terrain during demonstration flight. Reason
28/07/2011	Spain	(SEGOVIA)	OTHER	unknown.
02/08/2011	Germany	Steinsfeld, nahe	OTHER	Loss of control in flight. Aircraft crashed causing 2 fatalities.
				Loss of control in flight during an aerobatic evolution in first flight,
17/08/2011	France	Lingreville (50)	OTHER	collision with the water surface.
				Engine stopped on initial climb, U-turn, loss of control, collision with
19/08/2011	France	P-F ULM Torreilles (66)	OTHER	the ground.
			EVEKTOR AEROTECHNIK -	Microlight lost control, started spinning and crashed. 2 persons on
21/08/2011	Poland	Lososina Dolna	EV97 - VLA	board, 2 fatalities.
				Stall while turning, collision with an electric pylon and impact with
24/08/2011	France	AD Sarlat (24)	OTHER	trees.
28/08/2011	France	P-F ULM Perols sur Vezere (19)	OTHER	Collision with trees during take-off, fire.
28/08/2011	France	Nant Lieu dit Homs (12)	RANS - S6	Engine failure, stall, collision with the ground.
		P-FULM Montpezat		Loss of control on final, collision with the ground, rollover onto the
01/09/2011	France	d'Agenais(47)	OTHER	back.
03/09/2011	Germany	Sinningen	OTHER	Aircraft stalled during climb and crashed into a lake.
14/09/2011	France	Doizieux (42)	ZENAIR	Collision with terrain in IMC conditions.
			EVEKTOR AEROTECHNIK -	
			EV97 - TEAMEUROSTAR	Aircraft found overturned with no pilot on board. Pilot found dead
23/09/2011	France	Bondigoux (81)	UK	300 meters away.
01/10/2011	France	P-F ULM Maubec (82)	OTHER	Collision with the ground on the last turn or final.
				Microlight stalled and entered spin until hitting the ground. 2 persons
01/10/2011	Poland	Glebinow	OTHER	on board, 2 fatalities.
15/10/2011	Latvia	Krimulda area	ZLIN	Aircraft collision with terrain.
22/10/2011	Germany	Korbach	OTHER	Loss of control during flight.
22/10/2011	France	P-F ULM Cappel (57)	RANS	Rotating propeller fatally injured a person on the ground.
				The pilot fell from the aircraft and died. The aircraft crashed 2 km
29/10/2011	France	Combovin (26)	OTHER	further on.
10/11/2011	France	Laragne-Monteglin (05)	OTHER	Loss of control in turn, collision with ground in solo instruction.
22/12/2011	Spain	Ambite (Madrid)	TECNAM	Aircraft crashed for unknown reasons.
			AIR CREATION -	
28/12/2011	France	AD privé Corbonod (01)	ULTRAFLIGHT FUN	Loss of control during take-off, collision with the ground.
			COMCO IKARUS - IKARUS	
14/01/2012	Netherlands	Mussel (Groningen)	C42	Loss of control after engine failure.
05/02/2012	Italy	San Donà di Piave - Venezia	OTHER	Aircraft lost wing while manoeuvring.

Local Date	State of Occurrence	Location	Aeroplane	Headline
15/03/2012	Germany	Rockenhausen	OTHER	Loss of control during turning the aircraft.
23/03/2012	Austria	Bodensee	TECNAM - P92 - EA	Aircraft crashed into the Bodensee. 2 persons on board, 2 fatalities.
			TL ULTRALIGHT - TL2000	Ultralight stalled and crashed shortly after take-off while performing
03/04/2012	Portugal	Benavente, Portugal	STING	airfield circuit.
			COMCO IKARUS - IKARUS	Aircraft crashed onto frozen lake after losing control. 2 persons on
11/04/2012	Finland	Rääkkylä lake Pyhäselkä	C42	board, 2 fatalities.
				Ultralight crashed after flying low and slow. 2 persons on board, 2
28/04/2012	Czech Republic	6km SSE LKTO	OTHER	fatalities.
				Airplane stalled and entered a spin until it crashed. 2 persons on
29/04/2012	Poland	Orla Gora	AVIASUD - MISTRAL	board, 2 fatalities.
				Aircraft suffered engine failure then stalled and crashed. 2 persons on
03/05/2012	Poland	Pila	ZENAIR - CH601	board, 2 fatalities.
06/05/2012	Slovakia	Liskova	OTHER	Aircraft crash due to reasons unknown.
			ZENAIR - CH601 - HD -	
22/05/2012	Sweden	ESKM	HDS	Microlight suffered an engine failure and crashed into garden - Fatal.
24/05/2012	France	Digny (28)	OTHER	Collision with the ground in degraded weather conditions.
02/06/2012	Portugal	Azóia, Colares, Sintra	OTHER	Loss of control inflight and bad weather conditions.
				Microlight suffered an engine failure and crashed into a forest and
05/06/2012	Sweden	Frölunda airstrip	Eurocub	caught fire.
				In-flight collision between a sailplane and an ultralight aircraft. 1
14/06/2012	France	Curienne (73)	OTHER	person on each aircraft. 1 fatality.
15/06/2012	France	P-F ULM Artigat (09)	OTHER	Loss of control, stall close to the ground.
17/06/2012	France	P-F ULM Gellainville (28)	OTHER	Collision with the ground during a test flight, fire.
			COMCO IKARUS - IKARUS	
24/06/2012	Romania	Siria, Arad	C42 - B	Aircraft crash while turning over a city.
27/06/2012	Germany	Aalen-Heidenheim / Elchingen	OTHER	Loss of control during final approach.
	_			Microlight suffered structural failure due to overload and crashed
29/06/2012	France	Pierre-Buffière (87)	JABIRU - UL	while flying in sub-optimal weather.
				Microlight crashed after take-off and caught fire. 1 person on board, 1
04/07/2012	Germany	Dingolfing	OTHER	fatality.
07/07/2065		6.11	DENAGE GV	Aircraft crashed in a cornfield during initial climb. 1 person on board,
07/07/2012	Germany	Schönberg	REMOS - GX	1 fatality.
07/07/2215			OTHER	Motor hang glider stalled and spun to the ground. 1 person on board,
07/07/2012	Romania	Chisineu-cris	OTHER	1 fatality.
00/00/00/0			OTHER	Microlight loss of control in flight in a low altitude and steep left turn.
03/08/2012	Germany	Idar-Oberstein	OTHER	2 persons on board, 1 fatality, 1 serious injury.
10/08/2012	France	Frangy (74)	OTHER	Canopy retraction, loss of in-flight control, collision with the ground.

Local Date	State of Occurrence	Location	Aeroplane	Headline
19/08/2012	France	Aspres-sur-Buëch (05)	OTHER	Exceeding the VNE, in-flight failure, collision with the ground.
				Right turn and descent after a low passage over the runway, collision
19/08/2012	France	P-F ULM Sainte-Hélène (33)	AVID - AVID FLYER	with the ground, fire.
				Engine misfire, loss of control, spin, collision with ground, fire on
31/08/2012	France	Saint-Junien (87)	FLIGHT DESIGN - CTSW	impact.
17/09/2012	Germany	Niederschöna	OTHER	Loss of control, aircraft crashed. 2 fatalities.
			COMCO IKARUS - IKARUS	Snow removal was not performed before take-off. Aircraft crashed
22/09/2012	Sweden	Lill-Blåbergsträsket	C42 - B	after take-off.
23/09/2012	Finland	Utsjoki	OTHER	Ultralight accident due to weight exceedance.
				Failure in flight, loss of control, collision with the sea surface under
07/10/2012	France	llet du Gosier (971)	ZENAIR - STOL CH701	investigation.
20/10/2012	Iceland	Reykjanes	RANS - S6 - ES	Microlight stalled during turn and crashed.
21/10/2012	Belgium	EBBZ,640 meters north of RWY	RANS - S6	Aircraft came down in corn field.
23/10/2012	France	St Sorlin-de-Vienne (38)	OTHER	Collision with a powerline during flight.
08/11/2012	France	Mardié (45)	OTHER	Wing broke during flight and crashed.
13/11/2012	Sweden	Arvika Westlanda flygplats	ZENAIR - STOL CH701	Microlight suffered structural failure and crashed.
				Door detached during circuit, leading to a loss of control. Aircraft hit
12/12/2012	France	Sauvian (34)	OTHER	the ground and a fire erupted. 1 person on board. Fatal.
		200m North of runway 15		
		threshold, Lameira Farm, Alter	EVEKTOR AEROTECHNIK -	During a low pass, the aircraft hit a small tree and a roof, crashed and
05/01/2013	Portugal	doChão	EV97	caught fire.
			EVEKTOR AEROTECHNIK -	
05/01/2013	Portugal	Herdade Lameira, Alter do Chão	EV97	Collision with tree during low flying.
			COMCO IKARUS - IKARUS	
17/02/2013	Germany	Rüdesheim-Aulhausen	C42	Microlight collided with trees and caught fire.
08/03/2013	Germany	Leidringen	OTHER	After losing the cockpit canopy the gyrocopter crashed.
		LEMT:Casarrubios del		Pilot lost control of the aircraft during a steep turn and crashed. 1
17/03/2013	Spain	Monte(Toledo)	OTHER	person on board, 1 fatality.
				Apollo Fox ULM - Loss of control during final approach and ground
27/03/2013	France	AD Pouilly-Maconge (21)	OTHER	impact. 1 person on board, 1 fatality – aircraft destroyed.
			COMCO IKARUS - IKARUS	Runway side excursion, aircraft collided with a hangar causing fatal
08/04/2013	Germany	Neustadt-Glewe	C42	injuries to the student pilot.
13/04/2013	Poland	Wola Bedkowska	OTHER	Microlight crashed due to unknown circumstances.
				Decrease of engine power in cruise, forced landing and the ULM tilts
15/04/2013	France	Vers AD Niort (79)	OTHER	forward. 1 person on board, 1 fatality - aircraft destroyed.
03/05/2013	Finland	Sysmä	OTHER	Ultralight crashed during flight - persons on board died.
05/05/2013	Germany	Bad Saulgau Airport	FLIGHT DESIGN - CT2K	Microlight stalled shortly after take-off.

Local Date	State of Occurrence	Location	Aeroplane	Headline
08/05/2013	Finland	Orivesi	RANS - S6	Ultralight aircraft overturned on landing and sank - passenger died.
05/06/2013	Germany	Birtlingen	AVIASUD	Microlight suffered structural failure and crashed.
				Ultralight accident - Ground impact. 1 person on board, 1 fatality -
22/06/2013	France	Arbois (39)	OTHER	aircraft destroyed.
06/07/2013	France	AD Saint-Florentin (89)	OTHER	Loss of control during initial climb, collision with ground, fire.
03/08/2013	Germany	Boll	OTHER	Microlight crashed during climb.
			EVEKTOR AEROTECHNIK -	Bird struck the canopy - pilot lost the controls - aircraft crashed and
04/08/2013	Spain	near Milagro	EV97	caught fire.
07/08/2013	France	Lessay (50)	OTHER	Collision with an obstacle during take-off.
				Aircraft stalled during initial climb. Aircraft destroyed and 1 person on
10/08/2013	Czech Republic	Holešov	OTHER	board fatally injured.
			EVEKTOR AEROTECHNIK -	
			EV97 - UNDESIGNATED	
26/08/2013	Germany	Gerbach, nahe	SERIES	Microlight in-flight breakup. 2 persons on board, 2 fatalities.
				Detachment of the canopy in flight, loss of control, collision with the
30/08/2013	France	Montils (17)	OTHER	ground.
31/08/2013	France	Montagne-Fayel (80)	OTHER	Aircraft wreck was found in a field. Causes not known.
04/09/2013	France	La Roche Soupeze (86)	AVIASUD	Engine failed during initial climb and aircraft stalled.
				Loss of control during the final approach - Aircraft crashed 132 m
05/09/2013	Spain	Marugán airfield	TECNAM - P92 - EA	before the runway threshold.
07/09/2013	Belgium	Isières	OTHER	Ultralight aircraft stalled while manoeuvring.
				Ultralight airplane crashed due to carbon monoxide causing
08/09/2013	Hungary	Hajdúszoboszló	CFM - SHADOW - BD	incapacitation of the pilot.
08/09/2013	Finland	Haapavesi	RANS - S6	Ultralight aircraft crashed for unknown reasons, one person died.
13/09/2013	Poland	Chojna	OTHER	Microlight stalled and crashed during initial climb.
17/09/2013	France	Piton Mazerin (974)	RANS - S7	Collision with the terrain in unfavourable weather conditions.
				Overweight flight - aircraft stalled during the last turn before the
21/09/2013	France	LFYK Marville	COLOMBAN - MC15	landing, crashed to the ground and caught fire.
	_			Pilot reported control problems, aircraft collided with trees and ended
22/09/2013	Germany	Stendal	OTHER	on a field. 2 persons on board, 2 fatalities.
0.4 / 4.0 / 0.0 4.0	_	15 (22)		Aircraft hit a tree while turning onto final. 2 persons on board, 2
01/10/2013	France	AD Le Castellet (83)	ZENAIR	fatalities.
05/10/2013	Spain	Salobralejo (Ávila)	OTHER	Ultralight flew low and crashed. 2 persons on board, 2 fatalities.
42/40/2045	F	15(25)	AVIONS MIGNET -	Marchael Conditions Construction 19
13/10/2013	France	Les Fourgs (25)	HM1000	Wreckage found in the forest, no witnesses.
47/40/2012		Walder Mean	EVEKTOR AEROTECHNIK -	Maria de la lata de lla de francia la confi
17/10/2013	Germany	Koblenz-Winningen	EV97	Microlight stalled after take-off.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			EVEKTOR AEROTECHNIK -	
30/11/2013	Germany	Beesten	EV97	The microlight crashed on a flat field.
		Open water between Medas		
		Islands and Norfeu Cape		
11/12/2013	Spain	(Girona)	TECNAM - P2002	Aircraft crashed into the ocean. 1 person on board, 1 fatality.
02/02/2014	France	Kerozar	OTHER	Loss of control, collision with the ground and post-crash fire
14/02/2014	France	Cahors (46)	OTHER	Ultralight crashed due to unknown circumstances.
23/04/2014	Germany	Leutkirch-Unterzeil	OTHER	Microlight stalled during touch-and-go training.
30/04/2014	Portugal	Évora: LPEV	OTHER	Aircraft accident loss of control inflight.
02/05/2014	France	Ghisonaccia (2B)	OTHER	Ultralight crashed due to unknown circumstances.
				Rans S6 - Hit a tree and crashed on the ground, during training – 2
17/05/2014	France	Bailleul-Sir-Berthout (62)	RANS - S6	persons on board, 2 fatalities - aircraft destroyed.
				Aircraft crashed in a corn field – 2 persons on board, 2 fatalities -
28/05/2014	Hungary	Kisapostag	OTHER - Not mapped	aircraft destroyed.
28/05/2014	Hungary	near LHDV - Dunaújváros	OTHER	Aircraft entered spin and crashed due to unknown circumstances.
29/05/2014	France	Lalandelle (60)	RANS - S6	Ultralight crashed due to unknown circumstances.
				Engine stopped after take-off, pilot incapacitation, loss of control,
05/06/2014	France	AD Albertville (73)	AVID - AVID FLYER	collision with the ground, fire, during training.
				Aircraft stalled during steep turn right after take-off and crashed. 2
14/06/2014	Spain	LEGY:Garray airfield(Soria)	OTHER	persons on board, 2 fatalities.
25/06/2014	Latvia		OTHER	Aircraft collision with terrain.
		500m N Kondrac, 6km S Trhové		
26/06/2014	Czech Republic	Sviny	AEROSPOOL - WT9	Ultralight crashed due to unknown circumstances.
				Engine problem during approach, aircraft probably stalled and
02/00/2014	Circle and	Havdilahai Fanas	OTUED Net many	crashed on the water - 1 person on board, 1 fatality – aircraft
02/08/2014	Finland	Haukilahti, Espoo	OTHER - Not mapped	destroyed.
00/00/2014	Cormony	Kulmbaah	COMCO IKARUS - IKARUS	Microlight onin during go around
08/08/2014	Germany	Kulmbach	C42	Microlight spin during go-around.
15/08/2014	Czech Republic	Near Trebovice, Ústí nad Orlicí	OTHER	Aircraft crashed into a village. 2 persons on board, 2 fatalities. Cause unknown.
23/08/2014	Czech Republic	Fryšták u Zlína	OTHER	Aircraft collided with a power line, fire and crash.
23/08/2014	Czecii Kepublic	Copalnic - Manastur, jud	OTHER	Aircraft conided with a power line, fire and crash.
23/08/2014	Romania	Maramures	COMCO IKARUS	Aircraft Crashed due to elevator failure.
25/08/2014	France	Saint-Paul d'Espis (82)	OTHER	Aircraft crashed due to elevator raildre. Aircraft unstable after take-off then collided with the ground.
23,00,2014	Tranice	Jame 1 dai a Espis (02)	OTTIEN	Aircraft collided with the ground after 20 minutes of flight, cause
28/08/2014	France	Lapalisse (03)	EVEKTOR AEROTECHNIK	unknown.
07/09/2014	France	Fontenailles (65)	OTHER	Aircraft stalled during a steep left turn after take-off.
37/03/2014	. rance	· strendines (os)	O I I I E II	or are stailed during a steep left tall latter take on.

Comco Ikarus C42C - ultralight aircraft caught fire in flight and crashed to the ground 300 m near the runway - 2 persons on board - 2 fatallities - aircraft destroyed. 11/09/2014 Germany Nausis OTHER The microlight had an inflight fracture of the right wing and crashed. 14/09/2014 Germany Münster-Teltge DALLACH - D4 rope of another aircraft. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. 23/09/2014 United Kingdom near St Neots, Tempsford DENNEY - KITFOX - II on board fatally injured. Other aircraft declared MAYDAY but landed on near dark on the caught fire. 11/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. 28/00/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 29/00/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft cashed and caught fire. 40/00/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. 29/00/2015 Portugal Azambuja Llucmajor GT500 Rejected landing - go around - aircraft crashed. 20/00/2015 Reúnion Tan Rouge RANS - S6 - ES Aliraraft crashed. 20/00/2015 Portugal Tan Rouge PANS - S6 - ES Aliraraft crashed. 20/00/2015 Portugal Portugal Llucmajor PANS - S6 - ES Aliraraft crashed. 20/00/2015 Portugal Portugal Pans - Aircraft crashed. 20/00/2015 Portugal Po	Local Date	State of Occurrence	Location	Aeroplane	Headline
11/09/2014 Germany Schweighofen C42 fatalities - aircraft destroyed. 11/09/2014 Germany Nausis OTHER The microlight had an inflight fracture of the right wing and crashed. 14/09/2014 Germany Münster-Teltge DALLACH - D4 rope of another aircraft. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on bear of the company of the					Comco Ikarus C42C - ultralight aircraft caught fire in flight and crashed
11/09/2014 Germany Nausis OTHER The microlight had an inflight fracture of the right wing and crashed. The aircraft crashed during approach phase after collision with the rope of another aircraft. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control linflight and crash with the ground. Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on aerodrome. Airplane stalled while performing a low pass when it crashed and 11/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed and 11/11/2014 Prance Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed malfunction and crashed into a restaurant - 2 persons on board, 1 (CP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, Tecnando Voo de Voo d				COMCO IKARUS - IKARUS	to the ground 300 m near the runway - 2 persons on board - 2
The aircraft crashed during approach phase after collision with the rope of another aircraft. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on aerodrome. Airplane stalled while performing a low pass when it crashed and caught fire. 16/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. 1CP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. 26/11/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - EIPPER - QUICKSILVER - Loss of the right-wing upper surface covering fabric - Loss of control shortly after take-off and the aircraft collided with	11/09/2014	Germany	Schweighofen	C42	fatalities - aircraft destroyed.
14/09/2014 Germany Münster-Teltge DALLACH - D4 rope of another aircraft. 17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on board fatally injured. Other aircraft declared MAYDAY but landed on board fatally injured. Other aircraft declared MAYDAY but landed on a erodrome. Airplane stalled while performing a low pass when it crashed and caught fire.	11/09/2014	Germany	Nausis	OTHER	The microlight had an inflight fracture of the right wing and crashed.
17/09/2014 France AD Saint-Quentin (02) AVIASUD Loss of control inflight and crash with the ground. Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on aerodrome. Airplane stalled while performing a low pass when it crashed and caught fire. 16/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. CP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, TeCNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed.					The aircraft crashed during approach phase after collision with the
Mid-air collision. One aircraft crashed into field with the one person on board fatally injured. Other aircraft declared MAYDAY but landed on aerodrome. Airplane stalled while performing a low pass when it crashed and caught fire. 16/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, O3/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - EIPPER - QUICKSILVER - GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	14/09/2014	Germany	Münster-Teltge	DALLACH - D4	•
on board fatally injured. Other aircraft declared MAYDAY but landed on aerodrome. Airplane stalled while performing a low pass when it crashed and caught fire. 11/11/2014 Poland Mysliborz ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, TeCNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Spain Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	17/09/2014	France	AD Saint-Quentin (02)	AVIASUD	<u> </u>
23/09/2014 United Kingdom near St Neots, Tempsford DENNEY - KITFOX - II on aerodrome. Airplane stalled while performing a low pass when it crashed and 11/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, 03/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with					•
Airplane stalled while performing a low pass when it crashed and caught fire. 16/11/2014 Poland Mysliborz ZENAIR - CH601 Caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, 03/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with					
11/11/2014 Poland Mysliborz ZENAIR - CH601 caught fire. 16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, O3/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	23/09/2014	United Kingdom	near St Neots, Tempsford	DENNEY - KITFOX - II	
16/11/2014 France Ferrière-La-Grande ZENAIR - CH601 Wing rupture in-flight while performing aerobatics, Aircraft crashed. ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, O3/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with					
ICP Savannah - Aircraft lost altitude probably due to a technical malfunction and crashed into a restaurant - 2 persons on board, 1 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, O3/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with			•		-
malfunction and crashed into a restaurant - 2 persons on board, 1 26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - EIPPER - QUICKSILVER - GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	16/11/2014	France	Ferrière-La-Grande	ZENAIR - CH601	• , • • • • •
26/11/2014 Italy Cirò Marina, Calabria ICP - SAVANNAH fatality, 1 serious injury - aircraft destroyed. Campo de Voo de Valdonas, Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with					•
Campo de Voo de Valdonas, 03/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with					•
O3/01/2015 Portugal Tomar TECNAM - P92 Loss of control during hammerhead manoeuvre followed by crash. Campo de Voo de Alqueidão O6/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	26/11/2014	Italy	<u> </u>	ICP - SAVANNAH	fatality, 1 serious injury - aircraft destroyed.
Campo de Voo de Alqueidão 06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	00/01/0015	5	•		
06/02/2015 Portugal Azambuja OTHER Loss of control during initial climb. Aircraft crashed and caught fire. 22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	03/01/2015	Portugal		TECNAM - P92	Loss of control during hammerhead manoeuvre followed by crash.
22/02/2015 Spain Ventosilla BREEZER The aircraft encountered terrain inadvertently. Aircraft destroyed. EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	05/02/2015	5		OTUEN	
EIPPER - QUICKSILVER - 14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with			· · · · · · · · · · · · · · · · · · ·		
14/03/2015 Spain Llucmajor GT500 Rejected landing - go around - aircraft crashed. Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	22/02/2015	Spain	ventosilia		The aircraft encountered terrain inadvertently. Aircraft destroyed.
Loss of the right-wing upper surface covering fabric - Loss of control - 30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	14/02/2015	Cnain	Llucmaiar		Dejected landing as around aircraft arashed
30/03/2015 Réunion Tan Rouge RANS - S6 - ES Aircraft crashed. Pilot loss control shortly after take-off and the aircraft collided with	14/03/2015	Spain	Liucmajor	G1500	
Pilot loss control shortly after take-off and the aircraft collided with	20/02/2015	Páunian	Tan Pougo	DANS SE ES	
	30/03/2013	Redillon	raii Nouge	KAN3 - 30 - L3	
16/04/2015 France Marguerittes OTHER the airport perimeter fence.	16/04/2015	France	Marguerittes	OTHER	•
ALPI AVIATION -	10/04/2013	Trance	Walgachttes		the unport perimeter reflect
30/04/2015 France Saint-Vincent-de-Cosse PIONEER200 Aircraft crashed during first flight.	30/04/2015	France	Saint-Vincent-de-Cosse		Aircraft crashed during first flight
22/05/2015 France Les Hauts-de-Chée OTHER - Not mapped Aircraft crash after long, multisector flight.					<u> </u>
Loss of visual references, deployment of emergency parachute in	22,03,2023	110100	les made de emec	отпен постарреа	
flight, landed on a hangar roof, slid down from the roof and caught					. , ,
24/05/2015 France Ault LEPAGE - PELICAN fire.	24/05/2015	France	Ault	LEPAGE - PELICAN	
20/06/2015 France Petit-Palais-et-Cornemps MICRO AVIATION Loss of control, collision with power lines, crash and fire.					
22/06/2015 France LFFX - Tournus-Cuisery TECNAM Loss of control on final, collision with terrain, post-crash fire.			·		
14/07/2015 Norway Stafsberg AEROSPOOL - WT9 Fatal crash of microlight aircraft northwest of Hamar aerodrome.			•		
17/07/2015 France Moulin Papon AEROPRAKT - A22 Aircraft crashed into a lake.		•			· ·

Local Date	State of Occurrence	Location	Aeroplane	Headline
17/07/2015	Poland	Nowogrod	OTHER	Microlight crash due to unknown reasons.
				Engine failure during initial climb - pilot initiated a turn back. Aircraft
18/07/2015	France	LFHS: Bourg Ceyzériat	OTHER	stalled, crashed and caught fire.
				Loss of control while performing turns on horizontal flight. Aircraft
24/07/2015	France	Laneuveville-en-Saulnois	OTHER	crashed.
25/07/2015	Ireland	Garranbaun, Co. Waterford	BEDE - BD5 - G	Forced landing, due engine fire and control difficulties.
			AIR CREATION -	
26/07/2015	Portugal	Praia de Mira	ULTRAFLIGHT FUN	Engine failure at very low level.
			EVEKTOR AEROTECHNIK -	
			EV97 - TEAMEUROSTAR	Accidental opening of the canopy during the take-off - Aircraft return
31/07/2015	France	AD Berck	UK	at low height - Loss of control - collision with terrain.
				Pilot of an ultralight aircraft misjudged the distance and collided with
01/08/2015	Croatia	Daruvar	OTHER	a hill.
05/08/2015	Germany	Oedheim	SCHEIBE	Loss of control inflight and crash.
21/08/2015	Czech Republic	Lipno	OTHER	Ultralight aircraft crashed during low flying.
			COMCO IKARUS - IKARUS	
09/09/2015	Germany	Iserlohn	C42	Aircraft, during a test flight stalled and crashed into a field.
13/09/2015	Germany	Ohrsleben	OTHER	Collision with power cable.
				Ultralight aircraft flew through the Austrian Alps, encountered strong
17/09/2015	Austria	Grießenkar, Flachau	OTHER	winds and crashed.
				Loss of control due to unknown reasons resulting in a violent collision
20/09/2015	Portugal	Valdonas Airfield	OTHER	with the terrain.
			EVEKTOR AEROTECHNIK -	
			EV97 - TEAMEUROSTAR	Canopy opened during the initial climb - pilot lost the control - aircraft
24/09/2015	France	Fréjus	UK	crashed and caught fire.
				Engine power decrease during initial climb, aircraft return, collision
25/09/2015	France	LFGF: Beaune Challanges	OTHER	with the ground.
				Engine fire in-flight, pilot returned and tried to perform a forced
40/40/2045	D 1 :	near EBAV:HANNUT/AVERNAS-	OT!!ED	landing in a field close to the airport. Aircraft crashed and the
18/10/2015	Belgium	LE-BAUDUIN	OTHER	wreckage burned totally.
25/40/2045	Caria	Rwy 27 extension, Mollerussa	TECNIANA DOS E	Loss of control during take-off manoeuvre being above MTOW,
25/10/2015	Spain	airfield	TECNAM - P92 - E	aircraft crashed and caught fire.
00/11/2015	Гиомоо	National	OTHER	Ultralight stalled and crashed shortly after take-off while performing
08/11/2015	France	Ménerval	OTHER	airfield circuit.
14/11/2015	France	Erstein	OTHER	Aircraft stalled at low height and crashed.
24/12/2015	Germany	Wetzlar	AEROSPOOL - WT9	Microlight hit trees and crashed on a field.
25/12/2015	France	AD Sainte-Foy-la-Grande	OTHER	Loss of control during the approach. Aircraft crashed and burned.

Local Date	State of Occurrence	Location	Aeroplane	Headline
15/01/2016	Spain	0,4 km to Trebujena airfield	RANS - S12	Engine stopped just after take-off - aircraft lost control and crashed.
13/02/2016	Germany	Hildesheiim - Söhlde	OTHER	Microlight loss of control.
21/02/2016	Spain	near Mutxamel airfield	TECNAM	Aircraft collided with a powerline on approach.
08/05/2016	Germany	Teising	OTHER	Microlight crashed after loss of control.
02/07/2016	Romania	Persani, BRASOV County	TECNAM	Aircraft crashed by unknown reasons.
15/07/2016	Spain	Los Garranchos airfield	RANS - S6	Engine shut down in flight - aircraft crashed.
				Engine stut-down during initial climb - airplane crash while attempting
15/07/2016	France	nex to LFES - Guiscriff-Scaër	RANS - S6 - ES	return.
20/07/2016	France	near Lacave airfield	NICCOLLIER - HN700	Engine failure after take-off - microlight crash.
12/08/2016	France	ALS Col de Bacchus	OTHER	Collision with the ground during take-off on a mountain airstrip.
13/08/2016	Germany	Hasselfelde	OTHER	Crash during climb.
16/08/2016	France	Guérande	OTHER	Collision with the ground.
17/08/2016	France	LFHZ: Sallanches-Mont-Blanc	OTHER	Engine shutdown during climb, pilot lost control of the aircraft.
			EVEKTOR AEROTECHNIK -	
27/08/2016	Czech Republic	Dlouhá Loucka	EV97	Mid-air collision of two ultralight aircraft.
28/08/2016	France	Sarrouilles	OTHER	Microlight crash during night in IMC conditions.
08/09/2016	Germany	Northeim	OTHER	Crash into ground due to unknown reasons.
			FLIGHT DESIGN - CT	Two aircraft, a glider and an ultralight collided close to the threshold.
10/09/2016	Germany	Großrückerswalde	SUPRALIGHT	Pilot of the ultralight died.
11/09/2016	France	Pont Farcy	OTHER - Not mapped	Aircraft collided with terrain during low flying.
13/09/2016	Czech Republic	Chocen	OTHER	Aircraft lost speed after take-off and crashed into a forest.
				Loss of control during an aerodrome circuit, collision with the ground,
07/10/2016	France	Varennes-lès-Mâcon	ZENAIR - CH600	fire.
		near LEAX - La Axarquia-Leoni		
19/01/2017	Spain	Benabu	RANS - S6 - ES	Aircraft crashed for unknown reasons.
29/01/2017	Italy	Caschina Breda - Castelverde	OTHER	Aircraft crashed for unknown reasons.
				Aircraft crash due to loss of control after stalling during the take off.
08/02/2017	Spain	Villaverde aerodrome	TECNAM - P2002	Engine was not producing power during impact.
		near LFHL - Langogne /	ALPI AVIATION -	
10/03/2017	France	Lespéron	PIONEER200	Collision with the ground after take-off - Aircraft caught fire.
05/04/2017	Germany	Wedemark	OTHER - Not mapped	Aircraft collided with a power line, fire and crash.
00/04/22:5	_		071170	During a go-around manoeuvre, the aircraft collided with trees,
06/04/2017	France	AD Megève	OTHER	crashed and caught fire.
00/04/2215	_	during initial climb from LFQZ:	OTHER	
08/04/2017	France	Dieuze-Guéblange	OTHER	Loss of control in flight, collision with the ground - post impact fire.
08/04/2017	France	AD Briare	OTHER - Not mapped	Collision with trees and the ground during an aerodrome circuit.

Table	Local Date	State of Occurrence	Location	Aeroplane	Headline
30/04/2017 France Sainte-Maxime, col de Bougnon OTHER Microlight entered into a spin and crashed.					During take-off the aircraft struck the tops of the trees. The aircraft
AD Villefranche-de-Rouergue OTHER of the africal trashed into the ground during manoeuvring in the vicinity of the afficial of	15/04/2017	France	Saint Cybardeaux	OTHER - Not mapped	collided with the ground in a field and caught fire.
12/05/2017 France Bettenheim AEROSPOOL - WT9 flight. 17/05/2017 France Gurcin Gurcin France Bettenheim AEROSPOOL - WT9 flight. 20/05/2017 Spain Gurcin Gurcin France LFEZ: Nancy-Malzéville OTHER - Not mapped Pilot loss control of the aircraft while performing an aerodrome circuit. The aircraft crashed to the ground. 20/05/2017 France LFEZ: Nancy-Malzéville OTHER - Not mapped Pilot loss control of the aircraft while performing an aerodrome circuit. The aircraft crashed to the ground. 21/07/2017 France Parisot OTHER - Not mapped The microlight his the ground with a strong nose down attitude. 22/09/2017 France Parisot OTHER - Not mapped The microlight his the ground with a strong nose down attitude. 26/07/2017 Germany Nordsee OTHER Not mapped The microlight his the ground with a strong nose down attitude. 26/07/2017 France Persithea airfield - LARISSA STING OTHER DISTRICT Crash during a low passage right after take-off lowed by fire. 26/07/2017 Greece Terpsithea airfield - LARISSA STING OTHER DISTRICT Crash during a low passage right after take-off followed by fire. 29/08/2017 Romania Tätärusi commune, Laşi county OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER Stall and crash - during approach. 21/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. 22/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control with incorrect flap configuration followed by aircraft call fatality. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control on bord, 1 fatality. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control on bord, 1 fatality. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 23/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with th	30/04/2017	France	Sainte-Maxime, col de Bougnon	OTHER	Microlight entered into a spin and crashed.
17/05/2017 France Bettenheim AEROSPOOL - WT9 flight 20/05/2017 Spain Gurb Gurb 20/05/2017 Spain Gurb 20/05/2017 France LFEZ: Nancy-Malzéville OTHER - Not mapped ground. 20/06/2017 France LFEE: Dinan Trélivan JODEL - D9 Gricuit. The aircraft cashed to the ground. 21/06/2017 France Parisot OTHER - Not mapped Gricuit. The aircraft crashed to the ground. 21/06/2017 France Parisot OTHER - Not mapped The microlight hit the ground with a strong nose down attitude. 21/07/2017 Germany Nordsee OTHER - Not mapped The microlight hit the ground with a strong nose down attitude. 21/07/2017 Greece Terpsithea airfield - LARISSA STING Ultralight T1-2000 airplane Crashed close to RWY threshold resulting to fatal injury of both occupants. 26/07/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 21/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. 21/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. 22/09/2017 France Luray EVEKTOR AEROTECHNIK Crash in mountainous area in adverse weather conditions. 22/09/2017 France AD Saint-Jean-d'Angély OTHER Not mapped Crashed claired in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER Not mapped Grade declared missing and found disintegrated in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER Not mapped Grade declared missing and found disintegrated in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER Not mapped Grade falled Aller and the aircraft crashed on the ground, fire. 23/09/2017 France AD Saint-Jean-d'Angély OTHER Not mapped Grade faller faller. Aller and the aircraft crashed on the ground during VFR flight. 24/09/2017 Spain Escorca, near Binissalem OTHER Aller Aller and the since with high inclination and low height shortly after take-off, collision with the ground, fire. 25/10/2017 Spain Esc					,
17/05/2017 France Bettenheim AEROSPOOL - WT9 flight 20/05/2017 Spain Gurb GT900 GT900 Climb. 20/05/2017 Spain Gurb GT900 GT900 Climb. 20/05/2017 France LFEZ: Nancy-Malzéville OTHER - Not mapped ground. 20/05/2017 France LFEB: Dinan Trélivan JODEL - D9 circuit. The aircraft crashed to the ground. 21/07/2017 France AFROSPOOL - WT9 GT900 Circuit. The aircraft crashed to the ground. 21/07/2017 Germany Nordsee OTHER - Not mapped The microlight hit the ground with a strong nose down attitude. 21/07/2017 Germany Nordsee OTHER Microlight disappeared; radar contact ended by the Baltic coast. 26/07/2017 Grecce Terpsithea airfield - LARISSA STING OTHER Microlight disappeared; radar contact ended by the Baltic coast. 26/07/2017 Grecce Terpsithea airfield - LARISSA STING OTHER Microlight occupants. 26/07/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. 19/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. 21/09/2017 France Luray EVEKTOR AEROTECHNIK Falality. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with	12/05/2017	France	AD Villefranche-de-Rouergue	OTHER	
Vincinity of Flight Field ULM de Gurb Gurb Gurb Gurb Gurb Gurb Gurb Gurb					, , ,
20/05/2017 Spain Gurb GTS00 Climb. Engine lost power after take-off and the aircraft crashed to the ground.	17/05/2017	France			-
Engine lost power after take-off and the aircraft crashed to the ground. France			•		- I am a second and
O3/06/2017 France LFEZ: Nancy-Malzéville OTHER - Not mapped ground. Pilot loss control of the aircraft while performing an aerodrome O4/06/2017 France LFEB: Dinan Trélivan JODEL - D9 Circuit. The aircraft crashed to the ground.	20/05/2017	Spain	Gurb	GT500	
04/06/2017 France LFEB: Dinan Trélivan JODEL - D9 circuit. The aircraft while performing an aerodrome circuit. The aircraft crashed to the ground. 17/06/2017 France Parisot OTHER - Not mapped The microlight hit the ground with a strong nose down attitude. 21/07/2017 Germany Nordsee OTHER Microlight disappeared; radar contact ended by the Baltic coast. TL ULTRALIGHT - TL2000 Ultralight TL-2000 airplane Crashed close to RWY threshold resulting to fatal injury of both occupants. 07/08/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Romania Tätäruşi commune, Laşi county OTHER Engine failure shortly after take-off followed by fire. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control and crashed. 1 person on board, 1 fatality. mountainous area 6,5 nm NW mountainous area 6,5 nm NW 22/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. ### Private Airplane declared missing and found disintegrated in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul Garda Garda Marim-Quelfes COLOMBAN RWY excursion - aircraft overturned. 7/10/2017 Italy Garda Eccorca, near Binissalem OTHER Aircraft Collision with the ground during VFR flight. 8/10/2017 France AD Nogaro FUNK after Alex-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC					•
04/06/2017 France LFEB: Dinan Trélivan JODEL - D9 circuit. The aircraft crashed to the ground. 17/06/2017 France Parisot OTHER - Not mapped The microlight hit the ground with a strong nose down attitude. 21/07/2017 Germany Nordsee OTHER Microlight disappeared; radar contact ended by the Baltic coast. 26/07/2017 Greece Terpsithea airfield - LARISSA STING to fatal injury of both occupants. 07/08/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Romania Tätäruşi commune, Laşi county OTHER Engine failure shortly after take-off followed by fire. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER Engine failure shortly after take-off Aircraft loss height and crashed. 19/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d	03/06/2017	France	LFEZ: Nancy-Malzéville	OTHER - Not mapped	<u> </u>
17/06/2017 France					, g
21/07/2017 Germany Nordsee OTHER Microlight disappeared; radar contact ended by the Baltic coast. TL ULTRALIGHT - TL2000 OT/08/2017 Greece Terpsithea airfield - LARISSA STING to fatal injury of both occupants. OT/08/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Romania Tătăruși commune, Lași county OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control and crashed. 1 person on board, 1 fatality. Private Airplane declared missing and found disintegrated in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 Spain Escorca, near Binissalem OTHER Aircraft crashed on the ground during VFR flight. 08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. OTHER Aircraft collision with mountainous area in a narrow valley. Self-OTA - Spain Escorca, near Binissalem OTHER Aircraft stale during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. OTHER Aircraft collision with trees in mountainous terrain in a narrow valley.					<u>-</u>
26/07/2017 Greece Terpsithea airfield - LARISSA STING to fatal injury of both occupants. 07/08/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Romania Tătăruşi commune, Laşi county OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control with incorrect flap configuration followed by aircraft stall and crash - during approach. 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. mountainous area 6,5 nm NW Private Airplane declared missing and found disintegrated in a mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LECL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC					<u> </u>
26/07/2017 Greece Terpsithea airfield - LARISSA STING to fatal injury of both occupants. 07/08/2017 France P-F ULM Saint-Estèphe PIPISTREL Crash during a low passage right after take-off followed by fire. 19/08/2017 Romania Tătăruşi commune, Laşi county OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. 19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control and crashed. 1 person on board, 1 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. mountainous area 6,5 nm NW Private Airplane declared missing and found disintegrated in a 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. OTHER - NOTHING AIRCRAFT - Aircraft crashed on the ground during VFR flight. OS/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. OTHER - NOTHING AIRCRAFT - Aircraft crashed on the ground during VFR flight. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	21/07/2017	Germany	Nordsee		
O7/08/2017 France					
19/08/2017 Romania Tătăruşi commune, Laşi county OTHER Engine failure shortly after take-off. Aircraft loss height and crashed. Loss of control with incorrect flap configuration followed by aircraft stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. mountainous area 6,5 nm NW Private Airplane declared missing and found disintegrated in a 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER AD Nogaro FUNK after take-off, collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC			·		· · · ·
Loss of control with incorrect flap configuration followed by aircraft stall and crash - during approach. 31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control and crashed. 1 person on board, 1 fatality. Private Airplane declared missing and found disintegrated in a mountainous area 6,5 nm NW of Kommotini city pure. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC			•		· · · · · · · · · · · · · · · · · · ·
19/08/2017 Spain Coscojuela de Sobrarbe airfield OTHER stall and crash - during approach. Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. Ultralight airplane lost control and crashed. 1 person on board, 1 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. Private Airplane declared missing and found disintegrated in a 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	19/08/2017	Romania	Tătăruși commune, Lași county	OTHER	· · · · · · · · · · · · · · · · · · ·
31/08/2017 Spain Sant Pau D'Ordal ICP - SAVANNAH Crash in mountainous area in adverse weather conditions. 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. 10/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 22/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC					
Ultralight airplane lost control and crashed. 1 person on board, 1 10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. mountainous area 6,5 nm NW 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with trees in mountainous area in unintended IMC		<u> </u>			<u> </u>
10/09/2017 France Luray EVEKTOR AEROTECHNIK fatality. mountainous area 6,5 nm NW 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with trees in mountainous area in unintended IMC	31/08/2017	Spain	Sant Pau D'Ordal	ICP - SAVANNAH	
mountainous area 6,5 nm NW 22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with trees in mountainous area in unintended IMC					Ultralight airplane lost control and crashed. 1 person on board, 1
22/09/2017 Greece of Kommotini city FLIGHT DESIGN - CT2K mountainous area. Both occupants fatally injured. 28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	10/09/2017	France	· · · · · · · · · · · · · · · · · · ·	EVEKTOR AEROTECHNIK	•
28/09/2017 France AD Saint-Jean-d'Angély OTHER - Not mapped Engine failure, loss of control, collision with the ground, fire. 05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with trees in mountainous area in unintended IMC			•		
05/10/2017 Portugal Marim-Quelfes KOLB - TWINSTAR - III Aircraft stalled shortly after take-off and crashed. 05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with trees in mountainous area in unintended IMC		Greece	of Kommotini city	FLIGHT DESIGN - CT2K	· · ·
05/10/2017 France LFCL - Toulouse Lasbordes COLOMBAN RWY excursion - aircraft overturned. 1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	28/09/2017	France	AD Saint-Jean-d'Angély	OTHER - Not mapped	-
1,5 km from Padenghe sul 07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	05/10/2017	Portugal	Marim-Quelfes	KOLB - TWINSTAR - III	·
07/10/2017 Italy Garda TECNAM - P2002 Aircraft crashed on the ground during VFR flight. 08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	05/10/2017	France	LFCL - Toulouse Lasbordes	COLOMBAN	RWY excursion - aircraft overturned.
08/10/2017 Spain Escorca, near Binissalem OTHER Aircraft collision with mountainous terrain in a narrow valley. Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC			1,5 km from Padenghe sul		
Stall during a manoeuvre with high inclination and low height shortly after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	07/10/2017	Italy	Garda	TECNAM - P2002	
08/10/2017 France AD Nogaro FUNK after take-off, collision with the ground, fire. Collision with trees in mountainous area in unintended IMC	08/10/2017	Spain	Escorca, near Binissalem	OTHER	•
Collision with trees in mountainous area in unintended IMC					Stall during a manoeuvre with high inclination and low height shortly
	08/10/2017	France	AD Nogaro	FUNK	after take-off, collision with the ground, fire.
13/10/2017 Germany Grebenhain, Vogelsberg AEROSPOOL - WT9 encounter.					Collision with trees in mountainous area in unintended IMC
	13/10/2017	Germany	Grebenhain, Vogelsberg	AEROSPOOL - WT9	encounter.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Malfunction of the pyrotechnic system of the cruise rescue parachute,
16/10/2017	Germany	Jüterbog	AVID - MARK IV	loss of control, collision with the ground.
21/10/2017	Romania	Vantu de Jos, Alba county	OTHER	Aircraft crash after take-off due to unknown reasons.
				Aircraft turn back during cruise in adverse weather conditions, loss of
07/12/2017	New Caledonia	Near AD Île des Pins	TECNAM	radio contact.
				Aircraft stalled, lost control, and crashed. 2 persons on board, 1
19/01/2018	Spain	La Pobla de Benifassà(Castellón)	ZENITH - CH601 - XL - XL	fatality, 1 serious injury.
				Asymmetrical extension of the flaps in the final, loss of control and
24/02/2018	France	Trignac	DYN AERO - MCR01 - ULC	collision with the ground.
			FLIGHT DESIGN - CT2K -	Aircraft stalled and lost control during climb phase. 1 person on
05/03/2018	Germany	Karlstadt	NO SERIES EXISTS	board, 1 fatality.
05/04/2018	Niger	AD Tapoa	OTHER	Aircraft found crashed for yet unknown reasons.
		2NM SW Veselí nad Lužnicí near		Aircraft lost control and crashed into the ground. 2 persons on board,
09/04/2018	Czech Republic	Kundratice	OTHER - Not mapped	2 fatalities.
		Channay-sur-Lathan ULM		
23/04/2018	France	airfield	RANS - S6 - ES	Ultralight aircraft crashed after loss of control during rejected lading.
				Aircraft stalled during initial climb. Aircraft destroyed and 1 person on
24/04/2018	Germany	Mittelfischach	OTHER	board fatally injured.
01/05/2018	Poland	Skorupy pow. Otwocki	OTHER	Aeroplane crashed, cause unknown.
04/05/2018	Ireland	near Ballina	OTHER - Not mapped	Aircraft crashed after pilot became unconscious.
16/05/2018	Spain	LESU: La Seu d'Urgell Airport	PIPISTREL	Aircraft crash during go around manoeuvre.
26/05/2018	Spain	Vicinity of Loja Aerodrome	AVID - AVID FLYER	Aircraft crash due to a loss of control during the initial climb.
			AEROSPOOL - WT9 - NO	Aircraft lost control and crashed into a mountain side while
27/05/2018	Germany	Nürtingen	SERIES EXISTS	descending. 1 person on board, 1 fatality.
				Ultralight aircraft crashed due to unknown reasons. 2 persons on
31/05/2018	Poland	Bobrowniki gm. Nieborów	OTHER - Not mapped	board, 2 fatalities.
		<u>.</u>		The pilot lost control after a turn and the aircraft got into a spin.
01/06/2018	Germany	Bad Neuenahr/Ahrweiler	MURPHY - RENEGADE	Microlight caught fire after impact on ground.
24/06/2018	France	Arvieu	BEST OFF - SKYRANGER	Collision with a power line followed by crash.
26/06/2018	France	AD Oloron Herrère	OTHER	Ultralight aircraft crashed for yet unknown reason.
			COMCO IKARUS - IKARUS	
09/07/2018	France	Ladignac	C42 - B	Loss of control, collision with the ground during approach.
	_			Aircraft crashed and caught fire for reasons unknown. 1 person on
11/08/2018	Germany	EDXG: Melle-Gronegau	DYN AERO - MCR01	board, 1 fatality.
16/08/2018	Germany	Nannhausen	OTHER	Aircraft crashed for unknown reasons. 1 person on board, 1 fatality.
21/08/2018	France	Rue	OTHER	Crash during training flight followed by post-impact fire.
08/09/2018	Czech Republic	LKTEPL	OTHER	Loss of control during approach and crash.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Aircraft lost all power after take-off and crashed into terrain. 1 person
11/09/2018	Italy	Calatabiano (CT)	TECNAM - P92 - E	on board, 1 fatality.
				Ultralight aircraft entered spin, crashed, and was found completely
18/09/2018	Lithuania	EYSI	RANS - S6	burnt.
				Aircraft crashed with the ground shortly after take-off. 1 person on
25/09/2018	France	Aillant-sur-Tholon	OTHER	board, 1 fatality.
				Aircraft lost control, stalled and span during approach, crashed and
13/10/2018	Netherlands	near EHST - Stadskanaal	PIPISTREL	caught fire. 1 person on board, 1 fatality.
		Océan Atlantique 60NM ouest		
23/10/2018	France	pointe du Raz	FLIGHT DESIGN - CTLS	An aircraft crashed into the ocean.
25/10/2018	New Caledonia	NWWE (ILP): Ile Des Pins Moue	ZENAIR - CH601	Engine problem, stall, collision with the ground while test flight.
26/10/2018	France	Beaucaire	OTHER	Collision with the ground - post impact fire.
		over Erkelenz / Kückhoven		Two Ultralight aircraft had a mid-air collision. 2 persons on board, 1
17/11/2018	Germany	airfield	REMOS - G3	fatality, 1 serious injury.
04/01/2019	Italy	Sommacampagna	EVEKTOR AEROTECHNIK	Ultralight aircraft crashed into terrain. 1 person on board, 1 fatality.
		Sea area at Patraikos Bay -		
		Greece, 1650m from Kryoneri		
16/01/2019	Greece	Beach	MONNETT - SONERAI - 2	Ultralight airplane crashed at sea near Kryoneri at Patraikos Bay.
		_	AIR CREATION -	
		1 NM south-east of Quijorna	ULTRAFLIGHT FUN - 18S	Mid-air collision, one aircraft crashed. 3 persons on board, 2 fatalities,
06/02/2019	Spain	(Madrid)	GTBIS	1 minor injury.
21/02/2019	France	Port le Grand	OTHER - Not mapped	Ultralight collided with trees in unfavourable weather conditions.
/ /			EVEKTOR AEROTECHNIK -	
24/02/2019	Spain	LEIR: Aerodromo Air Marugan	EV97	Loss of control during initial climb and crashed.
15/22/2212	-	1000 (000)	CZECH SPORT -	
16/03/2019	Portugal	LPBG (BGC) : Bragança	SPORTCRUISER	RH wing failure/separation in flight - Aircraft crashed.
31/03/2019	Italy	Chantornè (Torgnon – Aosta)	ZLIN	Loss of control during a fly-by, aircraft entered a spin and crashed.
/ /	_			Pilot reported flight control problems and collided with a mountain. 1
07/05/2019	France	Saint-Antonin-sur-Bayon	BEST OFF - SKYRANGER	person on board, 1 fatality.
25/05/2019	Germany	Elz	AEROPRO - EUROFOX	Microlight crashed in a forest.
25/27/2242	5			Aircraft entered spin shortly after take-off. 2 persons on board, 2
26/05/2019	Bulgaria	take-off from LBHT: Ihtiman	PIPISTREL - Virus SW 100	fatalities.
			LONG - MIDGET	A settle of a first action of all and a second or all a second or all and a second or all a second or
24 /05 /2040	Dalamal	Manalaga nassa 121-1-12	MUSTANG - NO SERIES	Accident of a historic aircraft due to an abrupt manoeuvre followed by
31/05/2019	Poland	Napoleon pow. Klobucki	EXISTS PRICEELL	a stall and crash.
00/06/2010	Dantonal	and to IDIE Laivie	BRM AERO - BRISTELL	A insurefy consolved fellowed by weak insurest five afternal a
09/06/2019	Portugal	next to LPJF: Leiria	NG5	Aircraft crashed followed by post-impact fire after a low pass.

Local Date	State of Occurrence	Location	Aeroplane	Headline
10/06/2019	Germany	EDBW: Werneuchen	OTHER - Not mapped	Microlight crash and fire shortly after take-off.
		URGNANO, VIA MULINO DEI	AIR CREATION -	
15/06/2019	Italy	PRATI	ULTRAFLIGHT FUN	A small aircraft crashed into a hillside. 1 person on board, 1 fatality.
		near EBBZ : Pont-À-Celles /		Aircraft crashed on approach. Emergency parachute was deployed
22/06/2019	Belgium	Buzet	ZENAIR - CH601	while flying low. 2 persons on board, 2 fatalities.
27/06/2019	Switzerland	near of Col de Sonlomont	REMOS - GX	Plane crashed into a forested, steep hillside.
				Aircraft found crashed on the ground in the vicinity of the airfield. 1
23/07/2019	France	Proche P-F ULM Calviac	OTHER	person on board, 1 fatality.
			EVEKTOR AEROTECHNIK -	
			EV97 - TEAMEUROSTAR	Navigation error in the mountains followed by loss of control during a
24/07/2019	France	Larche	UK	U-turn.
			EVEKTOR AEROTECHNIK -	
31/07/2019	Finland	EFTP	EV97	Ultralight EV-97 stalled and crashed after take-off, one fatality.
		San Juan del Puerto Port		
23/08/2019	Spain	(Huelva – Spain)	OTHER	A wing of an ultralight aircraft was detached in flight.
		Carretera vieja de Costix, 400m		
25/08/2019	Spain	away from Inca hospital	AEROPRAKT - A22 - L	Mid-air collision between helicopter and ultralight.
		platform ULM La selle en		
25/08/2019	France	Hermoy	OTHER	Loss of control in the final approach followed by crash.
			COMCO IKARUS - IKARUS	During a scenic flight, the ultralight had contact with trees and
31/08/2019	Germany	Tiefenbach/Hofen	C42 - B	crashed to the ground. 2 persons on board, 1 fatality, 1 serious injury.
21/09/2019	France	Putanges-le-lac	OTHER - Not mapped	Seaplane collision with a power line and crash.
27/09/2019	Lithuania	Stetiskes, near Panevezys	UNKNOWN	Fatal accident with ultralight Skystar.
07/10/2019	France	Jumeauville	OTHER - Not mapped	Ultralight crashed due to unknown circumstances.
		approach to LFPX: Chavenay		
22/10/2019	France	Villepreux	OTHER	Loss of control on final, collision with ground.
			ALPI AVIATION -	
30/10/2019	France	LFBJ: Saint-Junien	PIONEER200	Loss of control on approach, collision with the ground.
		River Labe between village		
16/11/2019	Czech Republic	Nucice and Nucnicky	OTHER	Collision with Power Lines - Ultralight aircraft crashed.
28/12/2019	France	LFAV: Valenciennes / Denain	OTHER - Generic	Loss of control after take-off and crash.
29/12/2019	Switzerland	Arosa/GR	ZLIN	Aircraft crashed in mountainous terrain.
				Deep landing combined with poor braking action on iced grass runway
21/01/2020	Norway	Gjølstad	DYN AERO - MCR01 - ULC	resulted in loss of control.
		Airfield "Reno Air Club"		
11/02/2020	Italy	(Bologna)	TECNAM - P2002 - JF	Aircraft crashed on the ground after take-off.
19/03/2020	Romania	near Siria Airfield, Arad county	OTHER - Not mapped	Crashed of ultralight aircraft under unknown circumstances.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			BRM AERO - BRISTELL	Aircraft stalled and crashed during turn after take-off. 2 persons on
24/04/2020	Czech Republic	Svatoborice (Hodonín)	NG5 - NO SERIES EXISTS	board, 2 fatalities.
25/04/2020	Slovenia	NEAR LJAJ	OTHER	A collision between a plane and a paraglider.
25/04/2020	Slovenia	Ajdovscina Aerodrome	OTHER - Not mapped	Mid-air collision of an Aeroplane and a Paraglider and Crash of both.
22/05/2020	France	La Ferté-Bernard	OTHER - Not mapped	Crash of aircraft under unknown circumstances.
		Aviosuperficie Arma di Nettuno		
31/05/2020	Italy	(RM)	TECNAM - P92 - E	Crash of aircraft shortly after take-off. 2 persons on board, 2 fatalities.
06/06/2020	Germany	Gießen	TL ULTRALIGHT	Loss of control after take-off - Aircraft crashed.
19/06/2020	France	Mortemer	OTHER - Not mapped	Loss of control while cruising. Collision with the ground.
10/07/2020	Norway	Meråker	ICP - SAVANNAH - VG	Collision with tree during final approach resulted in fatal accident.
			AEROPRO - EUROFOX -	Runway excursion ended in a crash during a go-around. Aircraft
12/07/2020	Germany	Senheld	NO SERIES EXISTS	caught fire. 1 person on board, 1 fatality.
				Loss of control caused aircraft to crash. 2 persons on board, 2
12/07/2020	Germany	Rheinstetten	OTHER - Not mapped	fatalities.
25/07/2020	Germany	Wesel-Lackhausen	OTHER - Not mapped	Crash of aircraft into a house and fire post-impact.
				The aircraft stalled shortly after take-off. 2 persons on board, 1 fatality
05/08/2020	Germany	Iserlohn / Rheinermark airfield	ZLIN	and 1 serious injury.
				Bounced landing - attempted go-around - loss of control - aircraft
06/08/2020	France	P-F ULM Cruis Mas Des Grailles	FLIGHT DESIGN - CTSW	crashed and caught fire.
			BRM AERO - BRISTELL	
15/08/2020	Poland	near EPKI: KIKITY	NG5	Aircraft crashed under yet unknown circumstances.
15/08/2020	France	AD Saint-Martin de Londres	OTHER	Aircraft struck treetops - loss of control - aircraft crash and caught fire.
16/08/2020	Germany	Porta Westfalica	OTHER	Crashed shortly after take-off and caught fire.
				Pilot reported engine problems, rapid descent. 1 person on board, 1
29/10/2020	Czech Republic	Olšany u Prostejova	OTHER - Not mapped	fatality.
21/11/2020	Germany	Gera	Flying Machines FM25	Loss of control due to unknown reasons 1 person on board, 1 fatality.
13/02/2021	Netherlands	Kornhorn	AEROSPOOL - WT9	Loss of control during manoeuvring.
		Buccella (comune di Vigevano		
14/02/2021	Italy	provincia di Pavia)	OTHER	Ground impact after suspected wing separation.
21/02/2021	France	LFGP Saint-Florentin Chéu	OTHER	Engine failure on initial climb, collision with ground on landing.
			EVEKTOR AEROTECHNIK -	
30/03/2021	Germany	Jandelsbrunn	EV97	Crash into ground
22/04/2021	Germany	Kulmbach	OTHER	Crash into ground
23/04/2021	France	Grayan-et-l'hôpital	AAI - JCC Aviation J300	Collision with the ground.
	_	Village of Charia approx. 14 Km		
21/06/2021	Greece	NE of the city of Pyrgos	OTHER - Not mapped	Aircraft crashed and destroyed by fire.

Local Date	State of Occurrence	Location	Aeroplane	Headline
29/07/2021	Czech Republic	Jablonná Horní Hbity	OTHER - Not mapped	Aircraft crashed shortly after take-off.
				Problem in initial climb, turnaround, loss of control, collision with
30/07/2021	France	LFQW: Vesoul Frotey	OTHER	ground.
21/08/2021	France	Courcelles	OTHER	Collision with a power line.
30/08/2021	Spain	Niebla	RANS - S12	An ULM crashed into terrain with nose down attitude.
04/09/2021	France	Woignarue	OTHER	Collision with the ground.
12/09/2021	France	Autouillet (78)	OTHER	Loss of control, collision with the ground.
30/09/2021	France	LFLR: Saint-Rambert-D'Albon	TECNAM - P92	Microlight turn right and stall in the turn.
10/10/2021	Réunion	Saint-Paul de la Réunion	RANS - S6	The ultralight collided with the terrain.
			AEROSPOOL - WT9,	
13/10/2021	France	Bordes-de-Rivière	GLASER DIRKS - DG600M	Glider crashed into terrain after disconnection from the tug microlight
16/10/2021	France	LFGF: Beaune Challanges	OTHER	Loss of control on initial climb, collision with ground.
		Near LEAX : La Axarquía		
05/11/2021	Spain	aerodrome	BUCKER - BU131	Aircraft crashed due to engine failure.
		Mountainous area 'Profitis Ilias'		
		approx. 40 Km east of Larissa		
15/11/2021	Greece	city	OTHER	Ultralight experimental airplane crashed into mountainous terrain.
				Collision with a pylon shortly after take-off and collision with the
18/11/2021	France	Nera LFPE: Meaux Esbly	OTHER	ground.
20/12/2021	Italy	Bastiglia (Modena)	TECNAM - P92	Collision with building.

Aeroplanes registered outside the EASA Member States

Local Date	State of Occurrence	Location	Aeroplane	Headline
24/04/2011	France	AD Fontenay-Tresigny (77)	YAKOVLEV - YAK52	Loss of control when flying at low height, collision with the ground.
				Aircraft crashed into reservoir. Two persons on board, both with fatal
28/04/2011	United Kingdom	Maldon Reservoir (Essex)	YAKOVLEV - YAK52	injuries. Substantial aircraft damage.
				Aircraft stalled and crashed in a field due to incorrectly performed
02/08/2011	Netherlands	Near Lelystad Airport (EHLE)	YAKOVLEV - YAK52	circuit procedure.
				Aircraft stalled during a go-around manoeuvre, crashed and caught
09/11/2011	France	Décines-Charpieu	SOCATA - TBM700 - A	fire.
			CIRRUS - SR22 - NO	
14/11/2011	Germany	Gleisweiler	SERIES EXISTS	Cirrus SR22 collided with terrain in fog.
			CESSNA - 750 - NO SERIES	
01/03/2012	Germany	Egelsbach, nahe	EXISTS	Controlled flight into terrain.
21/04/2012	Spain	Albalat de la Ribera	OTHER	Aircraft crashed after take-off due to unknown reasons.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Runway excursion, ground spoilers not deployed delaying the thrust
13/07/2012	France	Castellet Airport	GULFSTREAM - GIV	reversers to react. 3 persons on board, 3 fatalities.
				Loss of control in IMC condition - collision with the ground - aircraft
05/01/2013	France	Saint-Geoirs (38)	PIPER - PA34 - 220T	caught fire after the impact.
09/02/2013	Belgium	EBCI	CESSNA - 210	Aircraft crash due to icing and loss of control.
04/03/2013	France	Annemasse Airport	RAYTHEON - 390	Hawker Raytheon Premier 390 - Collision with a house on take-off.
01/05/2013	Austria	westlich Baumkirchen/Tirol	BEDE - BD5	Aircraft crashed after experiencing technical failures.
				During climb the pilot became incapacitated and loss the control of
27/05/2013	Germany	Wolfsbehringen	PIPER - PA39	the aircraft.
				Engine fire while cruising, smoke in the cabin, emergency landing,
29/05/2013	France	Gap (05)	PIPER - PA28R	collision with vegetation and then the ground.
		near LFLC (CFE): Clermont-		
08/08/2013	France	Ferrand Auvergne	SOCATA - TBM700 - N	Aircraft lost control and crashed during approach for landing.
				Cessna 421 with PT6 engines - loss of control on take-off, aircraft
24/09/2013	France	Lyon-Bron Airport, France	CESSNA - 421	crashed and caught fire.
				Aircraft lost control and crashed during descent. 6 persons on board, 6
19/11/2013	France	Mouffy (89), FRANCE	SOCATA - TBM700 - B	fatalities.
12/01/2014	Germany	Near Trier-Föhren Airport	CESSNA - 501	Aircraft collision against power pole due to a VFR flight in IMC.
		Casarola mountain Collagna		
04/04/2014	Italy	(Reggio Emilia)	PIPER - PA30	Controlled flight into mountain slope.
				After water landing, aircraft flipped in hard wing and high sea
		Lake Vättern near Visingsö,		condition - Water rudder left in the down position - 1person on board
14/06/2014	Sweden	Jönköping county	CESSNA - TU206 - G	- 10B Fatal - Substantial damage.
				Jodel D-185 - aircraft crashed killing the pilot - 1 person on board, 1
25/06/2014	Latvia	Jelgava	JODEL	fatality - aircraft destroyed.
				Collision with a mountain in cruise - 3 persons on board, 3 fatalities -
12/07/2014	France	Urtaca (2B)	PIPER - PA28R - 201T	aircraft destroyed.
				Loss of control in flight and impact with the ground - 5 persons on
06/08/2014	France	Saint-Jean-les-2-Jumeaux (77)	SOCATA - TBM700 - B	board, 2 fatalities, 3 serious injuries - aircraft destroyed.
				Unspecified ultralight - aircraft crashed on a tree covered area - 2
09/08/2014	Italy	Varsi (Parma)		persons on board, 1 fatality, 1 serious injury - aircraft destroyed.
				Ultralight Kitfox - Aircraft loss heigh during take-off, crashed into a
27/00/224			DENINEY WITTON	vineyard and caught fire - 1 person on board, 1 fatality - aircraft
27/09/2014	Italy	Salgareda, Treviso Airport	DENNEY - KITFOX	destroyed.
				ICP Savannah - Aircraft lost altitude probably due to a technical
26/44/204	trad	CO Marian Color	ICD CANAANSAA	malfunction and crashed into a restaurant - 2 persons on board, 1
26/11/2014	Italy	Cirò Marina, Calabria	ICP - SAVANNAH	fatality, 1 serious injury - aircraft destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
30/01/2015	Switzerland	Bernex	PIPER - PA46 - 350P	Loss of control in flight - Aircraft crashed.
24/05/2015	Ireland	Blackstairs Mt., Co. Carlow	CESSNA - T182 - T	Impact with mountainous terrain.
				Following TCAS RA to avoid a microlight the aircraft landed long and
31/07/2015	United Kingdom	Blackbushe Airport	EMBRAER - EMB505	then exited the runway.
				Pilot lost the control of the aircraft in IMC condition. Aircraft crashed
14/11/2015	United Kingdom	Buttles Farm, Churchinford	PIPER - PA46 - 350P	in a field.
14/07/2016	Slovenia	7 Km north of AJdovscina	PIPER - PA32R - 301T	Aircraft crash in a wooded field after a "Mayday" call.
			YAKOVLEV - YAK11 - NO	
25/08/2016	Germany	Speyer	SERIES EXISTS	Loss of control in a turn after take-off.
				Aircraft crash during landing due to reported pitch control problems.
06/09/2017	United Kingdom	Caernarfon Airport	PIPER - PA31	1 person on board, 1 fatality.
		mountainous area 6,5 nm NW		Private Airplane (CT-2K) declared missing and found disintegrated in a
22/09/2017	Greece	of Kommotini city	FLIGHT DESIGN - CT2K	mountainous area. Both occupants fatally Injured.
21/10/2017	Romania	Vantu de Jos, Alba county	OTHER	Aircraft crash after take-off due to unknown reasons.
17/02/2018	France	Saint-Laurent-La-Roche	BEECH - 55 - 95B55	Loss of radio and radar contact while cruising, collision with terrain.
24/03/2018	Switzerland	Arosa/GR	MAULE - M7 - 235	Collision with a bridge after take-off in Arosa.
				Ultralight aircraft entered spin, crashed, and was found completely
18/09/2018	Lithuania	EYSI	RANS - S6	burnt.
			LONG - MIDGET	
			MUSTANG - NO SERIES	
31/05/2019	Poland	Napoleon pow. Klobucki	EXISTS	Aircraft crashed due to unknown reasons shortly after take-off.
21/07/2019	United Kingdom	Near Hythe	DE HAVILLAND - DH82 - A	Aircraft rolled into a steeply banked turn crashing on a crop field.
		250 m southeast of the		
		mountain hut 'Tschuggenhütte'		The aircraft crashed from low altitude above ground and in a rotary
29/11/2019	Switzerland	near the village of Arosa (GR)	ZLIN	motion into rough terrain.
				Pilot lost control of the aircraft after an engine failure - 2 persons on
23/02/2020	France	Beaulieu, Puy-de-Dôme	RYAN - ST3KR	board, 2 fatalities.
				Aircraft crashed most likely due to fuel starvation while performing go
19/09/2020	Germany	Moosburg	RAVEN	around.
20/09/2020	Germany	Kulmbach	PITTS - S1 - S	Loss of control and crash during aerobatics.
		on app to LFQM: Besançon-La-		Crash on approach. Fire post-impact. Likely loss of control during
28/09/2020	France	Vèze	CIRRUS - SR22	approach.
				Collision with high terrain. Wrong turn made ending with a collision
11/11/2021	Austria	6845 Hohenems	CESSNA - P210	with a mountain.

Commercial air transport helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
04/07/2011	Norway	Dalamot	AEROSPATIALE AS350	Helicopter crashed in turn.
11/07/2011	Myanmar	Yetagon oil rig, Andaman Sea	SIKORSKY S76	Pilot performed a ditching due to engine power loss during take-off.
09/11/2011	Italy	Italy	AEROSPATIALE AS365	Helicopter collided with wind turbine.
11/11/2011	Italy	Macerata	AGUSTA A109	Helicopter crashed.
08/04/2012	Niger	Niger	AEROSPATIALE AS350	Helicopter crashed in the desert.
14/01/2014	Norway	Near Solihogda, Norway	EUROCOPTER EC135	Medical helicopter struck power lines and crashed.
		Under Kláštorná roklina gorge -		Helicopter crashed on a riverbank after strike with power cables
17/07/2015	Slovakia	Hornád canyon	AGUSTA A109	during en-route HEMS mission.
		Pizzo Zocca di val Masino		
31/07/2015	Italy	(Sondrio)	AEROSPATIALE AS350	Controlled flight into a mountain peak obscured by clouds.
29/04/2016	Norway	near Turøy	EUROCOPTER EC225	Helicopter crashed during an offshore mission.
02/06/2016	Moldova	Haragis	EUROCOPTER EC135	Helicopter crashed in wood.
				Controlled flight into terrain during a HEMS flight in mountainous
07/09/2016	Slovakia	Strelníky	BELL 429	area.
08/09/2016	Austria	Carinthia, ca. 2346 m	ROBINSON R66	Helicopter crashed in a mountainous area.
24/01/2017	Italy	Monte Cefalone, Lucoli (AQ)	AGUSTA AW139	Helicopter crashed into a mountain slope during HEMS flight.
23/01/2018	Germany	Philippsburg	EUROCOPTER EC135	Mid-air collision.
15/12/2018	Portugal	1NM South of Valongo	AGUSTA A109	Collision with radio tower in bad weather conditions.
25/01/2019	Italy	Rutor Glacier	AEROSPATIALE AS350	Mid-air collision between helicopter and small aeroplane.
				HEMS helicopter near miss with a paraglider, loss of control and crash
11/05/2019	France	Le Conquet	EUROCOPTER EC135	of paraglider.
		Sea area between Galatas and		
20/08/2019	Greece	Poros island	AGUSTA A109	Helicopter crashed in sea after collision with power lines.
		Carretera vieja de Costix, 400m		
25/08/2019	Spain	away from Inca hospital	BELL 206	Mid-air collision between helicopter and ultralight aeroplane.
31/08/2019	Norway	near Alta	AEROSPATIALE AS350	Helicopter crashed in mountainous area.
				Skier remained hooked with helicopter's utility basket on take-off and
07/01/2020	Italy	Maravidi Mountain	AEROSPATIALE AS350	fell to the ground.

Specialised operations helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
08/03/2011	United Kingdom	Honister Slate Mine, Seatoller	AEROSPATIALE SA341	Aircraft missing later found crashed in valley.
26/04/2011	Italy	1.3 NM S-SE of Sulmona (AQ)	ROBINSON R22	Controlled flight into terrain during aerial work.
07/06/2011	Spain	Quincoces de Yuso	BELL 407	Helicopter crashed in mountainous area and post-impact fire.

Local Date	State of Occurrence	Location	Aeroplane	Headline
15/06/2011	Andorra	Pleta de Juclar (Canillo)	AEROSPATIALE AS350	Helicopter crashed during sling load operation.
25/06/2011	Italy	Cison di Valmarino (TV)	SCHWEIZER 269C	Helicopter impacted cables during aerial work.
05/08/2011	Italy	Cogolo di Pejo (Trento)	AEROSPATIALE AS350	Collision with obstacles during aerial work.
14/09/2011	France	Vallorcine (74)	AEROSPATIALE AS350	Collision with cable car cable and post-impact fire.
18/10/2011	Belgium	10km from Liege	EUROCOPTER EC120	Helicopter crashed during aerial work.
11/01/2012	Norway	Mosjøen SE of	ROBINSON R44	Helicopter crashed into ground during reindeer herding.
14/03/2012	Gabon	near Iguela	BELL 212	Collision with obstacles during sling load operation.
06/04/2012	Belgium	Huy	ROBINSON R22	Collision with cable in hover.
29/06/2012	Germany	Lieser, nahe	HUGHES 369	Collision with powerline.
09/09/2012	Germany	Roßfelder Glider Airfield	EUROCOPTER EC120	Loss of control during an air show.
				Helicopter crashed due to loss of control caused by a previous rotor
29/06/2013	Switzerland	Switzerland	AEROSPATIALE AS350	strike.
				Helicopter crashed in a mountainous area and caught fire in unknown
01/07/2013	Switzerland	Switzerland	AEROSPATIALE AS350	circumstances.
12/11/2013	France	Saint-Chaffrey	AEROSPATIALE AS350	Helicopter crashed after hitting a cable of a chairlift.
18/12/2013	Portugal	near Monchique	EUROCOPTER EC120	Helicopter collision with power lines and crash.
				Helicopter crashed in a mountainous snow-covered area during aerial
14/07/2015	Switzerland	Guggigletscher, Lauterbrunnen	AEROSPATIALE AS350	work mission.
				Helicopter turned back due to bad weather conditions and crashed
31/12/2015	Réunion	Rempart du Maïdo	AEROSPATIALE AS350	shortly afterwards.
19/05/2016	Bulgaria	Gylovtsa village, Nesebar	KAMOV KA26	Collision with power lines.
				Helicopter overturned onto its side and rolled over during landing in a
13/05/2017	Switzerland	Petersgrat	AEROSPATIALE AS350	mountainous area.
26/09/2017	Sweden	Högheden	HUGHES 369	Helicopter accident during power line inspection flight.
11/06/2018	Switzerland	near Attinghausen	AEROSPATIALE AS350	Helicopter crashed.
07/01/2019	France	near Castres	AEROSPATIALE AS350	Helicopter crashed during sling load operation.
				Helicopter crashed for unknown reasons while performing a
06/07/2020	Spain	near LESU: Seo de urgel	AEROSPATIALE AS350	powerline survey mission.
				Person on ground was stuck in the external load lifting device, lifted
16/11/2021	Sweden	20 km north of Sundsvall	AEROSPATIALE AS350	into the air and then fell to the ground.

Non-commercially operated helicopters

Local Date	State of Occurrence	Location	Aeroplane	Headline
18/02/2011	Italy	Canne della Battaglia	ROBINSON R44	helicopter crashed during en-route.
09/07/2011	France	Luzoir (02)	ROBINSON R44	Loss of control at low altitude in bad weather conditions.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Municipality of La Peza		
19/09/2011	Spain	(Granada)	BELL AB412	Helicopter crashed on a wooded area and caught fire.
				Collision with trees during low level flight in instrumental flight
09/06/2012	Germany	Teisendorf	ROBINSON R44	conditions.
				Rotor mast tailgating during cruise and rupture in-flight followed by a
03/09/2012	France	Valouse	ROBINSON R44	crash.
10/01/2013	Germany	Wolpertshausen	ROBINSON R44	Collision with power line in bad weather conditions.
01/03/2013	France	France	AEROSPATIALE SA316	Helicopter crashed into a frozen lake.
29/07/2013	Romania	lake near Taureni	EUROCOPTER EC130	Controlled flight into a lake.
13/09/2013	Poland	Wygonin	ROBINSON R44	Collision with Terrain.
12/10/2013	Poland	Wolica Kozia	ENSTROM 280	Helicopter crashed following engine failure.
19/11/2013	Germany	Neuhausen ob Eck	ROBINSON R44	Helicopter crashed into a forest in foggy weather conditions.
20/12/2013	France	Lugon and Ile du Carney (33)	ROBINSON R44	Collision with water during flight at a low height.
		Baltic Sea, about 3 NM north of		
28/02/2014	Germany	Prerow	MBB BK117	Helicopter fell in the water during training exercise in the see.
05/04/2014	Austria	Am Kogl, Kirchham	ENSTROM 280	Helicopter crashed in a wooded area whilst en-route to airfield.
		On EBCF airfield 10m off		Engine power incorrect management during final leg followed by loss
13/06/2014	Belgium	Runway 30 (RH)	SCHWEIZER 269C	of control and crash.
27/07/2014	Italy	Lago del Salto	AEROSPATIALE AS350	Helicopter collision with wakeboard installation and subsequent crash
				Helicopter crashed on a mountainous terrain due to an unexpected
08/08/2014	Italy	Chanton Desout	SUD AVIATION SA318	weather deterioration.
		In Samsoe Belt between Røsnæs		
05/09/2014	Denmark	and Samso	ROBINSON R44	Helicopter crashed under unknown circumstances into the sea.
02/10/2014	France	France	EUROCOPTER EC130	Controlled flight into terrain in IMC conditions.
04/12/2014	Portugal	near LPSO - Ponte de Sor	SCHWEIZER 269C	Helicopter crashed on a training flight.
29/03/2015	Czech Republic	Filipova Hut	ROBINSON R44	Helicopter crashed.
		Valmayor Reservoir		
16/07/2016	Spain	(Valdemorillo)	ROBINSON R22	Helicopter hooked with a high voltage wire and crash into a reservoir.
16/08/2016	Czech Republic	near LKPS - Plasy	ROBINSON R44	The helicopter crashed during autorotation training.
05/09/2016	France	Origny le Sec	ROBINSON R22	Helicopter crashed.
		Monte RhoArcisate/Bisuschio		
19/11/2016	Italy	(Varese)	AGUSTA A109	Helicopter crashed.
15/03/2017	France	Figeac	BELL 206	Helicopter crashed whilst flying at low altitude during a night flight.
		Scinias of Marathonas area		Helicopter crashed during low flying due to collision with electrical
23/06/2017	Greece	wetland	MD HELICOPTER 369	power lines.
08/10/2017	Latvia	Near Gramzda	ROBINSON R44	Helicopter impacted a powerline and crashed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
02/05/2018	French Guyana	Cacao	BELL AB 2016	Helicopter crashed into a forest.
07/07/2018	Slovakia	Boundary of Village Kanaš	ROBINSON R44	Helicopter hit a power line during take-off and crashed.
11/07/2018	Poland	Domecko near Opole	ROBINSON R44	Helicopter crashed for unknown reasons.
		Domažlická 1059, Plzen -		
05/09/2018	Czech Republic	Skvrnany	ROBINSON R44	Loss of control during manoeuvring at low altitude.
17/02/2019	Norway	North of Roeldal alpine center	ROBINSON R44	Helicopter crashed in mountainous terrain.
22/03/2019	Czech Republic	Near Blažkov village	ENSTROM 480	Helicopter loss of control in flight.
03/05/2019	Italy	Pegognaga (Mantova)	ROBINSON R22	Loss of control in flight and impact with the ground.
01/12/2019	Italy	not reported	MBB BK117	Helicopter crashed yet in undetermined circumstances.
25/10/2020	Italy	In the proximity of Cervinia	ROBINSON R44	Loss of control shortly after take-off and collided with the ground.
		French Alps, Bonvillard (73)		Helicopter crashed in mountainous area during training flight for
08/12/2020	France	Savoie	EUROCOPTER EC135	winching by night conditions.
08/12/2020	Germany	Speyer	GUIMBAL CABRI	Helicopter loss of control in flight.
09/02/2021	France	Planay	BELL 206	Collision with the ground in mountainous area.
22/02/2021	Poland	Pszczyna	BELL 429	Helicopter crashed in a forest during night conditions.
07/03/2021	France	Touques helipad	AEROSPATIALE AS350	Helicopter impacted trees while taking off from a private airfield.
		Leksand 12 km southwest of		
17/03/2021	Sweden	city	ROBINSON R44	Helicopter collision with tree.
17/06/2021	Norway	Eldanger	ROBINSON R44	Helicopter possible collision with power lines.
17/10/2021	Germany	Buchen-Stürzenhardt	ROBINSON R44	Helicopter crashed.

Helicopters registered outside the EASA Member States

Local Date	State of Occurrence	Location	Aeroplane	Headline
21/11/2011	Spain	Port d'Andratx (Palma Mallorca)	HUGHES 369	Helicopter loss of control and collision with terrain.
26/04/2012	Romania	near Ostrov	KAMOV KA32	Helicopter crashed.
				Helicopter crashed shortly after taking off and destroyed by post
05/09/2014	Belgium	Roeselare, West Flanders	ROBINSON R44	impact fire.
10/05/2017	Italy	Fundres (BZ)	ENSTROM 480	In flight separation of main rotor blade and main rotor hub.
		Approximately 6NM S/SW		
22/07/2019	Italy	Gorgona Island	ROBINSON R66	Helicopter crashed into the sea.

Annex I helicopters (list of fatal accidents not updated for 2021)

Local Date	State of Occurrence	Location	Aeroplane	Headline
29/04/2011	France	Saint-Gervasy (30)	DYNALI H2S	Loss of power leading to loss of control and collision with terrain.

Local Date	State of Occurrence	Location	Aeroplane	Headline
18/02/2012	Germany	Lahr	CHR SAFARI	Tail rotor blade separation during take-off.
12/03/2012	Martinique	Le Lorrain	BELL 47	Collision with power lines and consequent post-impact fire.
14/05/2012	Czech Republic	Sindlovy Dvory	CHR SAFARI	Fall of helicopter.
21/04/2013	Slovakia	385 metrov od prahu VPP TK 31	DYNALI H2S	Helicopter crashed.
14/09/2013	France	Gignac (34)	FAMA K209MF	Detachment of rotor in flight, terrain collision, fire.
03/12/2013	Czech Republic	6 km W LKBO - Štepánov	HELISPORT CH7 RANABOT	Fall of helicopter.
12/02/2015	Czech Republic	Bohušovice nad Ohrí	ROTORWAY TALON A600	Fall of helicopter.
15/06/2015	France	AD Longuyon Vilette	MOSQUITO XE	Loss of control during hovering, terrain collision and fire.
17/07/2016	United Kingdom	EGBR - Breighton	AEROSPATIALE SE313	Loss of control with ground impact during quick stop/ flare.
10/05/2017	Austria	Gramaialm	BELL 47G	Helicopter crashed after collision with cable and caught fire.
		Between Millas and Corbère-		
13/03/2018	France	les-Cabanes	CHR SAFARI	Crash followed by post-impact fire.
05/04/2018	France	AD Libourne	BELL 47G	Ground collision with fire during instruction flight.
05/04/2018	France	Crestet	ROTORWAY EXEC	Loss of control in flight, collision with the ground, fire.
				Inadvertent opening of a door, impact of the rotor with the door, loss
19/06/2018	France	AD Châtellerault	HELISPORT CH7 RANABOT	of control, collision with the ground, fire.
13/07/2018	France	Saint Raphaël	HELISPORT CH7 RANABOT	Helicopter collided with tree and caught fire.
				Loss of control in flight followed by tail boom separation during
13/07/2018	Italy	Musile di Piave (VE)	YO-YO 222 3RD SERIES	approach.
	Saint Pierre and			
05/11/2018	Miquelon	Saint Pierre et Miquelon	ROTORWAY EXEC	Collision with the ground shortly after take-off.
		Barysiai, Joniskiu district,		
22/03/2019	Lithuania	Siauliai county	ULTRASPORT 555	Helicopter crashed.
15/07/2019	France	PF ULM Grand Couronné	HELISPORT CH7 RANABOT	Terrain collision.
		Approx. 3 km southeast of		Helicopter crashed into a meadow during an autorotation, overturned
24/08/2019	Switzerland	Herisau (AR)	ROTORWAY EXEC	and caught fire.
24/09/2019	France	AD Montélimar-Ancone	LH 212 DELTA	Ground collision during manoeuvring.
30/11/2019	France	Gréoux-les-Bains	HELISPORT CH7 RANABOT	Helicopter crashed.
30/06/2020	Poland	Strzegom	PHOENIX UH22	Helicopter crashed after losing control inflight.
10/07/2020	Italy	Nazzano (Rome)	R22 like	Helicopter clipped powerlines and fell into a river.

Balloons

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Flight initiated in spite of poor weather forecast. High speed landing
22/04/2011	Belgium	Oudenburg	KUBICEK - BB37 - N	caused the basket to flip 180 degrees.

Local Date	State of Occurrence	Location	Aeroplane	Headline
25/06/2011	Switzerland	Fisibach/AG	WORNER	Loss of control of a balloon and hard landing.
13/05/2012	France	Charly-sur-Marne (02)	SCHROEDER	Collision with a powerline, fire.
				Hard landing, one passenger was ejected and hit by the basket - 34
19/08/2012	France	Feings(41)	CAMERON	persons on board, 1 fatality - No damage.
				Hot air balloon crash in storm - 32 persons on board, 6 fatalities, 12
23/08/2012	Slovenia	Ljubljana marshes	LINDSTRAND - LBL600C	serious injuries, 14 minor injuries - aircraft destroyed.
06/08/2013	Switzerland	Haut-Intyamon/FR	CAMERON - Z105	Collision of balloon with powerline.
			SCHROEDER - FIRE	
			BALLOONS G - NO SERIES	Balloon flying in convective atmosphere generating wind variations
05/10/2014	France	Cazes Mondenard (82)	EXISTS	with decision to precautionary landing.
				Balloon basket impacted a metal fence on final approach, basket
12/07/2015	Spain	Vilanova del Cami	ULTRAMAGIC - S160	overturned, some occupants ejected included pilot - pilot died.
			SCHROEDER - FIRE	
08/10/2015	Italy	Montescaglioso (MT)	BALLOONS G	Balloon forced landing after hitting power line.
				Fall of a person that gripped on the outside of the basket during take-
05/01/2016	France	Aurel	ULTRAMAGIC - M120	off.
			SCHROEDER - FIRE	
02/06/2019	France	Pons	BALLOONS G	Balloon bounced landing - pilot ejected and hit by basket.
08/03/2020	Spain	Sports Center Palomares del Río	ULTRAMAGIC - H77	Pilot is thrown during the touchdown of the balloon.
16/08/2020	Germany	St. Goar	KUBICEK - BB51 - Z	Balloon hard landing resulting in 1 fatal injury and 4 serious injuries.
05/09/2020	Hungary	Vál	BALLOON ALOFT - AX8	Fire in balloon basket during landing procedure.
22/05/2021	Ukraine	Kulchiivtsi village	OTHER	Hard Landing caused one fatality and five serious injuries
16/08/2021	Italy	Buonconvento	ULTRAMAGIC - M160	Pilot fell on the ground from a balloon.

Sailplanes

Local Date	State of Occurrence	Location	Aeroplane	Headline
			ROLLADEN SCHNEIDER -	Loss of control in flight due to rough wind conditions, collision with
13/04/2011	France	Clamensane (04)	LS8 - B	terrain. 1 person on board, 1 fatality, aircraft destroyed.
22/04/2011	Switzerland	Mollis LSMF	GLASER DIRKS - DG800	Loss of control during winch launching.
				Loss of control while turning, collision with terrain, instructional flight.
18/05/2011	France	Le Sappey (38)	SCHLEICHER - ASH25	2 persons on board, 2 fatalities, aircraft destroyed.
				Mid-air collision between a sailplane and LSA aircraft. 3 persons on
21/05/2011	Germany	Saarmund	GROB - G102 - ASTIR CS	board, 3 fatalities, both aircraft destroyed.
02/06/2011	Germany	Hornberg	OTHER	Sailplane loss of control in flight.
11/06/2011	Germany	Mönchsheide	SCHLEICHER - ASH26 - E	Collision with trees.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			SCHLEICHER - ASW27 -	
12/06/2011	Finland	Hattula	18E	Sailplane mid-air collision.
				Sailplane stalled and crashed while performing a winch launch. 2
15/06/2011	Slovenia	Ptuj	SCHEIBE - BERGFALKE IV	persons on board, 1 fatality, 1 seriously injured, aircraft destroyed.
				Loss of control during approach. 1 person on board, 1 fatality, aircraft
17/06/2011	Germany	Laucha	SCHLEICHER - KA6	substantially damaged.
			SCHEMPP HIRTH -	Loss of control during winch launch take-off. 1 person on board, 1
26/06/2011	Germany	Hütten-Hotzenwald	VENTUS 2C	fatality, aircraft destroyed.
			GLASER DIRKS - DG100 -	
28/06/2011	Austria	Scharnstein, nahe	G	Collision with trees.
				Collision with a tree at the bottom of a valley in bad weather. 2
30/06/2011	France	Savournon (05), col de Faye	SCHLEICHER - ASH25E	persons on board, 2 fatalities, aircraft substantially damaged.
		next to LOKF - Feldkirchen /		
07/07/2011	Austria	Ossiachersee	PZL BIELSKO - MDM1	Sailplane crash after low pass.
			SCHEMPP HIRTH - DUO	Aircraft lost control and crashed into a field during low flying. 1 person
10/07/2011	Germany	Scheuen	DISCUS	on board, 1 fatality, aircraft destroyed.
10/07/2011	Germany	Near Jena-Schöngleina	PZL BIELSKO - SZD30	Inflight breakup (Luftzerleger).
11/07/2011	Poland	Nowy Targ	PZL BIELSKO - SZD50 - 3	Sailplane spin and crash.
			SCHEMPP HIRTH -	
31/07/2011	Germany	Haigerloch	VENTUS CM	Loss of control in low altitude.
01/08/2011	Switzerland	Gsteig/BE	GLASFLUGEL - KESTREL	Sailplane crashed at 1600m in the alps.
03/08/2011	Germany	Wasserkuppe	SCHLEICHER - ASK23	Runway excursion during take-off.
				Loss of control while turning during a mountain flight, collision with
13/08/2011	France	Saint-Firmin (05)	OTHER	terrain. 1 person on board, 1 fatality, aircraft destroyed.
16/08/2011	Poland	Laka Wielka	PZL BIELSKO - SZD36	Sailplane mid-air collision and crash.
21/08/2011	Italy	Ortona dei Marsi	OTHER	Sailplane crash.
			GROB - G103 - TWIN	
26/08/2011	Italy	Anterselva Valley (BZ)	ASTIR	Sailplane crashed near the top of the mountain.
28/08/2011	Austria	Zell am See	DIAMOND - HK36 - R	Collision between two aircraft.
			SCHEMPP HIRTH - DUO	
02/10/2011	Spain	Sayerri Peak, in Borau	DISCUS	Sailplane bird strike caused an elevator failure.
			ROLLADEN SCHNEIDER -	Stall during a spiral near a ridge, collision with the terrain. 1 person on
05/10/2011	France	Saint-Geniez (04)	LS8	board, 1 fatality, aircraft destroyed.
			SCHEMPP HIRTH - MINI	
15/10/2011	Germany	Blocksdorf	NIMBUS	Sailplane loss of control during final approach.
				Turbulence encounter at low height, pilot loss the control, the aircraft
25/10/2011	Austria	Uttendorf, Zell/See, Salzburg	SCHLEICHER - ASH26 - E	struck tree and crashed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Sailplane entered spin and crashed. 1 person on board, 1 fatality,
31/10/2011	Spain	Pla de Beret (Lleida)	OTHER	aircraft destroyed.
				Powered sailplane entered spin and crashed. 1 person on board, 1
25/03/2012	Portugal	Águeda, Portugal	GLASER DIRKS - DG800	fatality, aircraft substantially damaged.
				Sailplane crashed into a mountain. Cause unknown. 1 person on
10/04/2012	Switzerland	Innerthal	GLASER DIRKS - DG800	board, 1 fatality, aircraft destroyed.
			GLASER DIRKS - DG500 -	
15/04/2012	Germany	Laufenselden	TRAINER	Sailplane collision with trees after failed rope connection.
			SPORTINE AVIACIJA -	Sailplane stalled during turn to final approach after a failed winch
17/04/2012	Poland	Olsztyn-Dajtki	LAK17 - A	launch. 1 person on board, 1 fatality, aircraft destroyed.
			ROLLADEN SCHNEIDER -	
30/04/2012	Germany	Unterwössen	LS6	Collision with trees during landing.
			ROLLADEN SCHNEIDER -	Sailplane crashed into a mountain side. 1 person on board, 1 fatality,
03/05/2012	France	Claix, France	LS7	aircraft destroyed.
05/05/2012	France	AD Buno Bonnevaux (91)	PIPER - PA25 - 235	Mid-air collision between a sailplane and an aeroplane above runway.
			ROLLADEN SCHNEIDER -	
19/05/2012	Switzerland	unbekannt	LS1	Missing sailplane - found crashed 2 weeks later.
19/05/2012	Switzerland	Maienfeld, Switzerland	SCHLEICHER - ASW28	Sailplane crashed in the mountains.
				Powered sailplane stalled and crashed. 1 person on board, 1 fatality,
26/05/2012	Switzerland	Hütten/ZH	OTHER	aircraft destroyed.
			SCHEMPP HIRTH - DISCUS	
28/05/2012	Germany	Ludwigshafen-Dannstadt	BT	Loss of control in flight.
				In-flight collision between a glider and an ULM. 1 person on each
14/06/2012	France	Curienne (73)	CENTRAIR - 101	aircraft. 1 fatality.
18/06/2012	France	La Piarre, France	GLASER DIRKS - DG400	Sailplane loss of control in flight.
			SPORTINE AVIACIJA -	
30/06/2012	Italy	Cicogna	LAK19	Sailplane crashed in mountains.
				Sailplane entered spin while performing a steep turn ending by
				crashing to the ground. 2 persons on board, 1 fatality, 1 serious injury,
22/07/2012	Poland	Krosno	PZL BIELSKO - SZD50 - 3	aircraft destroyed.
23/07/2012	Germany	Pfronten, nahe	SCHLEICHER - ASH25	Sailplane crashed in the mountains.
26/07/2012	Switzerland	Romont/FR	OTHER	Powered sailplane crashed on a field.
27/07/2012	Switzerland	Glarus Nord/GL	OTHER	Sailplane collided with a mountain.
		Barles (04), lieu-dit Le Forest,		
30/07/2012	France	altitude 1 170 m	PZL BIELSKO - SZD48	Sailplane impacted the ground in mountainous area.
04/08/2012	Germany	Quakenbrück	SCHLEICHER - ASK13	Sailplane crashed into houses, first solo.
04/08/2012	France	Mont-Dauphin, FRANCE	SCHEMPP HIRTH - CIRRUS	Sailplane crashes after towing cable was released.

Local Date	State of Occurrence	Location	Aeroplane	Headline
05/08/2012	Germany	Adenau	GLASFLUGEL - H301	Loss of control in flight during off-field landing final.
15/08/2012	Germany	Ottenberg bei Nürnberg	SCHEMPP HIRTH - CIRRUS	Sailplane spiral dive after interrupted winch launch.
08/09/2012	France	Aussois, FRANCE	LANGE - E1	Crash against a rocky mountain.
			SCHEMPP HIRTH -	
15/09/2012	Italy	Albavilla, ITALLY	VENTUS2A	Sailplane crash near the top of the mountain.
13/10/2012	France	Pierrevert (04)	SCHLEICHER - ASW19	Loss of control in flight, collision with trees.
				Scheibe SF25C - Loss of control during final approach, ground impact,
20/02/2013	France	AD Coulommiers (77)	SCHEIBE - SF25 - C	fire. 1 person on board, 1 fatality - aircraft destroyed.
			SPORTINE AVIACIJA -	
04/05/2013	Germany	Bohmte	LAK19	Sailplane crashed in initial climb phase winch launching.
05/05/2013	France	Llupia (66)	OTHER	Powered sailplane - ground impact - 1 person on board, 1 fatality.
21/05/2013	Germany	Beilngries	GLASFLUGEL - MOSQUITO	Loss of control during winch launching.
05/06/2013	Netherlands	Malden	GLASER DIRKS - DG808	Sailplane crashed during winch launch.
07/06/2013	France	LFFC - Mantes-Chérence	SCHLEICHER - ASW20	Cartwheel - glider overturn while take off.
			SCHEMPP HIRTH -	Sailplane crashed while flying to close to the ground. 1 person on
08/06/2013	Croatia	Aerodrom Buševec	STANDARD CIRRUS - 75	board, 1 fatality, aircraft destroyed.
			SCHEMPP HIRTH -	
16/06/2013	France	Saint-Geniez (04)	VENTUS 2C	Collision with terrain in a spiral descent, during competition.
25/06/2013	France	Curbans (04), France	GLASER DIRKS - DG800	Collision with terrain during a flight in mountainous terrain.
01/07/2013	Germany	Klippeneck, GERMANY	GLASER DIRKS - DG600M	Sailplane crashed during winch launch.
				Schleicher ASW24E - Loss of control on flight at low altitude. Aircraft
		Dobratsch sud Area "Roten		crashed into a wooded area - 1person on board, 1 serious injury -
12/07/2013	Austria	Wand"	SCHLEICHER - ASW24 - E	aircraft destroyed.
24/07/2013	France	Montaigu (85)	CENTRAIR - 101	Collision with a power line during approach.
01/08/2013	France	Col de Vars (05), FRANCE	SCHLEICHER - ASK13	Collision with terrain during a mountain flight.
			ROLLADEN SCHNEIDER -	
01/08/2013	France	AD Angers Marcé (49), FRANCE	LS8	Collision with the ground during winching.
15/08/2013	Poland	Bezmiechowa Gorna	PZL SWIDNIK - PW6 - U	Sailplane crash during take-off - horizontal stabilizer separation.
			SCHEMPP HIRTH - ARCUS	
18/08/2013	France	Barcelonette, nahe	E	Sailplane crashed in Mountains.
04/09/2013	Switzerland	Laax/ GR	OTHER	Powered sailplane collides with high terrain.
			ROLLADEN SCHNEIDER -	
18/09/2013	France	Gréoux-les-Bains (04)	LS3	Sailplane collided with the ground.
				Sailplane hit a tree and crashed while flying a circuit pattern after
28/10/2013	Poland	Bezmiechowa Gorna	PZL BIELSKO - SZD30	take-off. 1 person on board, 1 fatality, aircraft destroyed.
17/11/2013	Poland	EPST	OTHER	Sailplane disintegration and crash while take-off.

Local Date	State of Occurrence	Location	Aeroplane	Headline
03/04/2014	Austria	Hohe Wand	SCHLEICHER - ASH26 - E	Sailplane crashed into the terrain.
30/04/2014	France	LFMF - Fayence	SCHLEICHER - ASW20	Cartwheel - sailplane overturn while take-off.
				Alisport Silent 2 Electro - aircraft crashed into a wooded area at the
				end of the runway during the approach - 1 person on board, 1 fatality
28/05/2014	Italy	Alzate Brianza Airfield - LILB	OTHER - Not mapped	- aircraft destroyed.
01/06/2014	Poland	Pila	PZL BIELSKO - SZD41	Sailplane mid-air collision and crash.
06/06/2014	Czech Republic	LKKA 1km RAD 320 RWY 32	TECNAM - P92	Fall of ULL during a Glider Towing.
				Sailplane crashed - 2 persons on board, 2 fatalities - aircraft
13/06/2014	Germany	Oppingen Airfield	GLASER DIRKS - DG1000	destroyed.
			SCHEMPP HIRTH -	Loss of control during an altitude flight - right wing broke-off - aircraft
10/07/2014	France	Eourres	VENTUS 2CM	crashed.
				Sailplane crashed on the runway during towing - 1 person on board, 1
11/07/2014	Finland	Piikajärvi airfield (EFPI), Finland	PZL BIELSKO - SZD51 - 1	fatality - aircraft destroyed.
			ROLLADEN SCHNEIDER -	
12/07/2014	Germany	Nieder-Werbe	LS4 - A	Sailplane crashed in mountainous area.
		Glider airfield Sultmer Berg,	ROLLADEN SCHNEIDER -	
26/07/2014	Germany	Northeim	LS4 - A	Sailplane stalled during winch launch.
			GROB - G103C - TWIN III	
26/07/2014	France	AD Puimoisson (04)	SL - TWIN III SL	Loss of control on approach, aircraft crashed.
				Shortly after take-off, the left wing broke due to overload in the
				execution of an abrupt recovery from an aerobatic manoeuvre. The
10/00/001		localita Tassigano, Capannori,	GROB - G103C - TWIN	aircraft fell to the ground - 2 persons on board, 2 fatalities - aircraft
10/08/2014	Italy	Lucca	ASTIR - TWIN III ACRO	destroyed.
10/00/001			GLASER DIRKS - DG200 -	Collision with terrain during a mountain flight - 1 person on board, 1
12/08/2014	Italy	Acceglio (Cuneo)	17	fatality - aircraft destroyed.
27/08/2014	France	Saint-André-d'Embrun (05)	SCHLEICHER - ASK13	Collision with terrain during a competition.
				Perhaps while unconscious a sailplane pilot approaching LGMG
20/09/2014	Crooss	LGMG	CLASSILICSI MOSOLUTO	crashed inside the airport while other aircraft take-off was in
20/09/2014	Greece	LGIVIG	GLASFLUGEL - MOSQUITO	progress.
30/11/2014	Namibia	Blumfelde	BINDER	The sailplane crashed after the left wing broke-up in flight - 2 persons on board, 2 fatalities - aircraft destroyed.
23/12/2014			OTHER	TMG crashed shortly after take-off.
23/12/2014	Germany	Böslingen	GROB - G103C - TWIN III	Loss of control during wave flight (in cloud), sailplane disintegration in
06/04/2015	Sweden	10 km SSE Nikkaluokta	SL - TWIN III SL	flight. Pilot bailed out; the student was killed.
00/04/2013	JWEUEII	TO KIII SSE IVIKKAIUUKIA	JL - I WIIN III JL	Wing hit the ground during take-off - the glider swerved and
12/04/2015	Germany	Oschatz	SCHEIBE - LSPATZ 55	overturned.
12/04/2013	Germany	Oscilatz	JUILLIDE - LOPATE JO	overturned.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Breakage of airbrakes control during a mountain flight, autorotation,
29/04/2015	France	La Piarre	GLASER DIRKS - DG800	collision with terrain.
			SCHEMPP HIRTH -	
02/05/2015	Germany	Bad Münder, Bakede	NIMBUS 3	Glider stalled and crashed into a forested area.
				Mid-air collision. One of the two aircraft crashed into the mountain
		Near Airfield Hohenems,		rocks and caught fire. The other aircraft returned to the airfield and
18/05/2015	Austria	Vorarlberg	GLASER DIRKS - DG300	landed safely.
20/05/2045	C	Double Love Y	CCUENADO LUDTU. IANUIC	Glider crashed into the ground during a winch launch. 2 persons on
28/05/2015	Germany	Bartholomä	SCHEMPP HIRTH - JANUS	board, 1 fatality, 1 serious injury, aircraft destroyed.
		East of Mount Paganella, at	SCHEMPP HIRTH -	Cailalana ayaahad ay a yaayyatain alana 1 yayaay ay baayd 1 fatality
05/06/2015	Italy	about 2 mm away from Comune di Terlago (TN)	VENTUS 2CM	Sailplane crashed on a mountain slope. 1 person on board, 1 fatality, aircraft destroyed.
03/06/2013	italy	di Terrago (TN)	VEINTUS ZCIVI	Two sailplanes collided during approach. One Sailplane broke and
				crashed. 2 persons on board, 2 fatalities. The other glider managed to
07/06/2015	Hungary	LHEM	OTHER	land.
0770072013	Transary	2112111	ROLLADEN SCHNEIDER -	Sailplane accident in Klosters-Serneus/GR. 1 person on board, 1
01/07/2015	Switzerland	Klosters-Serneus/GR	LS8 - 18	fatality, aircraft destroyed.
		,		The sailplane hit the ground after an aerobatic manoeuvre. 1 person
03/07/2015	Austria	Seitenstetten, NÖ	PILATUS - B4 - PC11	on board, 1 fatality, aircraft destroyed.
13/07/2015	France	Eygliers	PIPISTREL	Loss of control in flight, the sailplane collided with the ground.
			SCHEMPP HIRTH -	Collision with the mountain side. The sailplane wreckage has been
02/08/2015	France	Saint-André	VENTUS C	found at 2700m of altitude.
03/08/2015	Croatia	Donji Lapac., area Kruge		Sailplane found crashed - 1 person on board, 1 fatal injury.
			ROLLADEN SCHNEIDER -	The sailplane lost control and crashed in a forested area. 1 person on
06/08/2015	Germany	Füssen	LS8	board, 1 fatality, aircraft destroyed.
				Aircraft crashed in a mountainous area. Wreckage found several
		MUCHIA CHEII, Masivul		months after the accident - 1 person on board, 1 fatality, aircraft
06/08/2015	Romania	Postavarul	OTHER	destroyed.
44 /00 /004 5		A.T.7. EDD!	D71 D151 51/0 - 67D 50 - 0	Sailplane collided with a winch cable and crashed. 2 persons on board,
11/08/2015	Poland	ATZ EPPL	PZL BIELSKO - SZD50 - 2	2 fatalities, aircraft destroyed.
11/00/2015	Franco	Embrun	ROLLADEN SCHNEIDER -	Sailplane collided with trees and crashed to the mountain. 1 person
11/08/2015	France	Embrun	LS1 SCHEMPP HIRTH - ARCUS	on board, 1 fatality, aircraft destroyed. Powered sailplane crashed against a mountain slope. 2 persons on
12/08/2015	Italy	Col FERRET	M	board, 2 fatalities, aircraft destroyed.
12/00/2013	icaly	COLFERNET	IVI	Sailplane disconnected the rope during towing and crashed on the
20/08/2015	Germany	Purkshof	GLASER DIRKS - DG100	runway. 1 person on board, 1 fatality, aircraft destroyed.
20/00/2013	Germany	I UI KSIIUI	GLASEK DIKKS - DOTOO	runway. I person on board, I ratanty, and art destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Pilot incapacitation in flight - Passenger took the controls - Aircraft
				crashed and caught fire. 2 persons on board, 1 fatality, 1 serious
23/08/2015	Spain	near LEZL (SVQ): Sevilla	PIPISTREL	injury.
		Hatten mountain, Lesja		Sailplane crash - pilot jumped out too close to the ground. 1 person on
24/09/2015	Norway	municipality	SCHLEICHER - ASW24	board, 1 fatality, substantial damage.
				From level flight the aircraft suddenly pitched nose down and hit the
				ground in a steep nose down attitude. The pilot died and the sailplane
26/09/2015	Denmark	5 km øst for EKRS: Ringsted	SCHLEICHER - ASW24	was destroyed.
				Sailplane entered spin after a long flight and crashed. 1 person on
03/10/2015	Poland	Miedzybrodzie Zywieckie	PZL BIELSKO - SZD48 - 3	board, 1 fatality, aircraft destroyed.
				Powered sailplane collided with a communication tower during a
13/12/2015	Germany	Koblenz-Winningen	OTHER	flight in fog. 2 persons on board, 2 fatalities, substantial damage.
			SCHEMPP HIRTH -	Powered sailplane crashed, no details available. 1 person on board, 1
24/12/2015	Namibia	Stryfontein Farm	VENTUS CM	fatality, substantial damage.
02/04/2046	•	Near Kamp Lintfort Airfield	DIAMOND LIKOS D	. 6 1 1 1 1 1 1 1 1 1
03/01/2016	Germany	(EDLC)	DIAMOND - HK36 - R	Aircraft crashed during a go-around - 1 person on board, 1 fatality.
25/22/2245	_	6 :11	OTUED O	Pilot incapacitated due to a medical condition, Collision with trees and
26/03/2016	France	Seillans	OTHER - Generic	terrain.
03/04/2016	Austria	Kötschach Mauthen	GLASER DIRKS - DG400	Sailplane crashed into a mountain - 1 person on board, 1 fatality.
02/04/2046	A	3,3 kmNorth from LOGL -	SPORTINE AVIACIJA -	Sailplane entered spin and crashed into terrain. 1 person on board - 1
03/04/2016	Austria	Lanzen-Turnau	LAK19	fatality.
45/04/2045	D. L. J	FDCT	DZI DIELCKO CZDO	Sailplane crashed into the ground after winch cable was released. 1
16/04/2016	Poland	EPST	PZL BIELSKO - SZD9	person on board, 1 fatality.
			COLUEICHED ACM27	Competition flight - loss of height below safe altitude - abrupt
20/04/2016	Clavalda	Lucé Dalana	SCHLEICHER - ASW27 -	manoeuvre - The aircraft stalled and crashed with a nose down
20/04/2016	Slovakia	Lysá Polana	18E	attitude. 1 person on board, 1 fatality.
03/05/2016	Cormany	Bautzen	PIK - PIK20E - NO SERIES EXISTS	Crash on approach during glider competition. 1 person on board, 1 fatality, substantial damage.
05/05/2016	Germany	Bautzen	EXISTS	,·
04/05/2016	Slovenia	Near Airport LJSG	GLASER DIRKS - DG800	Sailplane accident. Suspected pilot incapacitation. 1 person on board, 1 fatality.
21/05/2016	Switzerland	Montricher LSTR	GLASER DIRKS - DG400	Sailplane collides with trees and crashes. 1 person on board, 1 fatality.
21/03/2010	Switzerianu	WORLD LAIN	GLASEN DINKS - DG400	Sailplane crashed into a field under unknown circumstances. 2
29/05/2016	Germany	Rhede/Emsland	LET - L23	persons on board, 1 fatality.
23/03/2010	Germany	Mieue/ Lilisianu	LLI - LZJ	Loss of control during approach causing the aircraft to enter spin. 1
19/06/2016	Germany	Bramsche	SCHEMPP HIRTH	person on board, 1 fatality.
13/00/2010	Germany	DIGITISCHE	JCHLIVII I IIIIVIII	Loss of control followed by collision with terrain - during training flight
22/06/2016	France	Authon	SCHEMPP HIRTH	en-route. 2 persons on board, 1 fatality, 1 serious injury.
22/00/2010	Trance	Autiloii	JOHEIVITT HIIVITI	en route. 2 persons on board, I fatality, I serious injury.

Local Date	State of Occurrence	Location	Aeroplane	Headline
06/07/2016	Switzerland	Lenk/BE	GLASER DIRKS - DG800	Sailplane collides with elevated terrain. 1 person on board, 1 fatality.
				Sailplane fell to the ground during winch launch take-off. 1 person on
09/08/2016	Germany	Lüsse	SCHLEICHER - ASW27	board, 1 fatality.
			SPORTINE AVIACIJA -	Collision with a cable/wire followed by crash. 1 person on board, 1
27/08/2016	France	Sauto	LAK17 - A	fatality.
				Two aircraft -glider and an ultralight collided close to the threshold.
10/09/2016	Germany	Großrückerswalde	SCHLEICHER - ASK21	Pilot of the ultralight died.
14/09/2016	Switzerland	L'Isle	BINDER - EB29 - D	Sailplane lost control entered a vertical dive and crashed.
			GLASER DIRKS - DG1000 -	Collision with trees and ground. 2 persons on board, 1 fatality, 1
19/03/2017	France	Le Vernet	M	serious injury.
		LFLE - Chambéry / Challes-les-	SPORTINE AVIACIJA -	Sailplane crash during winch launch take-off. 1 person on board, 1
29/03/2017	France	Eaux	LAK17 - A	fatality.
08/04/2017	Germany	Eschbach	SCHLEICHER - ASW24 - E	Sailplane Crashed into Industrial Area. 1 person on board, 1 fatality.
				Sailplane lost control - rolled onto its side and crashed into the
12/04/2017	France	Valdeblore	SCHLEICHER - ASW22	ground. 1 person on board, 1 fatality.
				Sailplane made a steep climb then rolled and crashed during a winch
03/05/2017	Poland	EPJL	PZL BIELSKO - SZD30	launch. 1 person on board, 1 fatality.
			SPORTINE AVIACIJA -	Sailplane spin shortly after release from winch-launch followed by
06/05/2017	Germany	Mannheim	LAK17	crash. 1 person on board, 1 fatality, aircraft destroyed.
				Loss of control at low height during a low turn speed and near the
14/05/2017	France	near LFDH - Auch Gers	SCHEMPP HIRTH - CIRRUS	terrain. 1 person on board, 1 fatality, aircraft destroyed.
				Sailplane crash for unknown reasons. 1 person on board, 1 fatality,
20/05/2017	Hungary	Nyíregyháza	PZL BIELSKO - SZD30	aircraft destroyed.
				Sailplane collided with terrain below mountain tip. 1 person on board,
10/06/2017	Italy	Riva Valdobbia (VC)	GLASFLUGEL - MOSQUITO	1 fatality, aircraft destroyed.
				Sailplane lost wing during aerotow and crashed in city centre. 1
11/06/2017	Italy	Novi Ligure	OTHER	person on board, 1 fatality, aircraft destroyed.
				Sailplane lost control and crashed in a mountainous area. 1 person on
15/06/2017	Austria	near Karlhöhe	GLASER DIRKS - DG600	board, 1 fatality, aircraft destroyed.
				Motorized sailplane lost control and crashed during emergency
16/06/2017	Hungary	LHTL	SCHEIBE - SF25 - C	training exercise. 2 persons on board, 2 fatalities, aircraft destroyed.
				Wing tip of the sailplane hit ground during winch launch causing it to
18/06/2017	Germany	Purkshof	GROB - G102 - ASTIR CS	overturn. 1 person on board, 1 fatality.
0.1/0.0/5.5.=			GROB - G103 - TWIN	Sailplane lost control while searching for lift and fell to the ground. 1
24/06/2017	Germany	Bartholomä-Amalienhof	ASTIR	person on board, 1 fatality.
10/07/55:-		5 1(SCHLEICHER - ASW27 -	Sailplane crashed due to loss of control. 1 person on board, 1 fatal
13/07/2017	Hungary	Pirtó	18E	injury.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Sailplane impacted the ground during winch launch take-off. 1 person
17/07/2017	France	LFOV (LVA): Laval Entrammes	CENTRAIR - 101 - A	on board, 1 fatality, aircraft destroyed.
				Sailplane was found crashed on a field. Loss of control suspected. 1
04/08/2017	Germany	Rädicke	SCHLEICHER - ASW24 - E	person on board, 1 fatality.
				The glider crashed onto a steep pasture and was destroyed upon
13/08/2017	Switzerland	Villavolar	GLASER DIRKS - DG800B	impact. 1 person on board, 1 fatality.
			GROB - G103 - TWIN	Sailplane crashed below a mountain ridge. 2 persons on board, 1
27/08/2017	Croatia	Sinj - Kamešnica	ASTIR	fatality, 1 seriously injured.
		EPBC Warszawa Babice / ATZ		Sailplane accident (crash) – spin after the safety latch of the winch
30/08/2017	Poland	EPBC	PZL BIELSKO - SZD50 - 3	cable broke while winch launching.
			ROLLADEN SCHNEIDER -	
10/09/2017	Germany	Hockenheim	LS8	Sailplane stalled during winch launching. 1 person on board, 1 fatality.
			ROLLADEN SCHNEIDER -	Sailplane crashed at ca 2 500 meters of altitude in mountainous area.
14/10/2017	Switzerland	Davos/GR	LS8 - 18	Cause unknown. 1 person on board, 1 fatality.
				Sailplane lost control and crashed into a forest after a winch launch
02/04/2018	Germany	Metzingen	SCHLEICHER - ASK13	failure. 2 persons on board, 1 fatality, 1 serious injury.
				Sailplane entered spin in flight followed by crash. 1 person on board, 1
17/04/2018	France	AD Florac-Sainte Enimie	CENTRAIR - SNC34C	fatality.
				Powered sailplane crashed shortly after take-off, 1 person on board, 1
27/05/2018	Germany	Reichenbuch	GLASER DIRKS - DG800	fatality, aircraft destroyed.
				Sailplane crashed in mountainous area for yet unknown reason. 1
10/06/2018	Italy	Località le Piaie - Belluno	ISF - MISTRAL - C	person on board, 1 fatal injury.
				Sailplane crashed during winch launch take-off, 1 person on board, 1
23/06/2018	Austria	LOSM: Mauterndorf Airfield	PILATUS - B4 - PC11AF	fatality, aircraft destroyed.
				Sailplane crashed while turning on final, 2 persons on board, 1 fatality,
03/07/2018	Poland	Lupiny	PZL BIELSKO - SZD9	1 serious injury, aircraft destroyed.
			SCHEMPP HIRTH - DISCUS	Sailplane lost control and collided with terrain. 1 person on board, 1
08/07/2018	Switzerland	Mettligrat (VS)	2C	fatality, aircraft destroyed.
			ROLLADEN SCHNEIDER -	Sailplane crashed into mountain after flying close to it and entering
19/07/2018	Germany	Oberammergau	LS7	turbulence. 1 person on board, 1 fatality, aircraft destroyed.
			ROLLADEN SCHNEIDER -	Collision with elevated terrain due to medical incapacitation. 1 person
02/08/2018	France	Thones	LS4	on board, 1 fatality, aircraft destroyed.
				Sailplane accident - missing thermal lift and colliding with trees. 1
08/08/2018	Poland	M. Klików	OTHER	person on board, 1 fatality, aircraft destroyed.
				Blocked aileron - glider spin and crash. 1 person on board, 1 fatality,
11/08/2018	Germany	Braunschweig - Waggum	SCHLEICHER - KA6 - CR	aircraft destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Sailplane collided with the ground Circumstances unknown. 1 person
12/08/2018	France	Orcières	SCHLEICHER - ASH25M	on board, 1 fatality, aircraft destroyed.
				Loss of control of the tug ULM during take-off in glider tow, collision
19/08/2018	France	AD Colmar Houssen	AEROSPOOL - WT9	with runway, fire. 1 person on board, 1 fatality.
				Loss of control in flight, collision with the ground. 1 person on board,
26/08/2018	France	Frontenas	SCHLEICHER - ASW17	1 fatality.
			IAR BRASOV - IS28M2 -	Sailplane crashes in mountainous area due to unknown reasons. 1
11/09/2018	Switzerland	Bedretto/TI	GR	person on board, 1 fatality.
			SCHEMPP HIRTH -	
			STANDARD CIRRUS - NO	Sailplane lost control and span to the ground. 1 person on board, 1
29/09/2018	Czech Republic	Lenešice near Louny	SERIES EXISTS	fatality, aircraft destroyed.
				Sailplane crashed on approach for unknown reasons. 1 person on
30/09/2018	Germany	EDLE (ESS): Essen/Mulheim	SCHLEICHER - ASK18	board, 1 fatality, aircraft destroyed.
		on approach to EDFK: BAD		Sailplane crashed on approach due to unknown reasons. 1 person on
05/10/2018	Germany	KISSINGEN	DIAMOND - HK36 - R	board, 1 fatality, aircraft destroyed.
			GROB - G103A - TWIN	Aircraft on final approach collided with another aircraft standing on
08/12/2018	Spain	LEFM: Fuentemilanos (Segovia)	ASTIR - TWIN II ACRO	ground. One person on the ground was fatally injured.
		Montecchio-Podere S.Apollonia	ROLLADEN SCHNEIDER -	Sailplane crashed during winch-launch. 1 person on board, 1 fatality,
17/03/2019	Italy	airfield	LS1 - D	aircraft destroyed.
			SPORTINE AVIACIJA -	Aircraft stalled and crashed during a winch launch. 1 person on board,
24/03/2019	Germany	EDST: Hahnweide	LAK17 - B FES	1 fatality, aircraft destroyed.
		LEIG: Igualada-Odena		Engine failure during the initial climb. Powered sailplane stalled and
24/03/2019	Spain	(Barcelona)	GLASER DIRKS - DG800 - B	crashed. 1 person on board, 1 fatality, aircraft destroyed.
			ROLLADEN SCHNEIDER -	
13/04/2019	France	Avize	LS8 - 18	Sailplane loss of control and crash.
			ROLLADEN SCHNEIDER -	Unexpected rope release during winch launch. Glider entered spin
22/04/2019	Germany	Leck	LS7 - WL	and crashed. 1 person on board 1 Fatality. Aircraft destroyed.
				Sailplane lost control during a soaring competition. 1 person on board,
03/05/2019	Norway	Grinder	SCHLEICHER - ASH31 - MI	1 fatality, aircraft destroyed.
				Sailplane crashed due to loss of control. 1 person on board, 1 fatality,
08/05/2019	Czech Republic	Roundabout near Hranice n. M.	SCHEMPP HIRTH - CIRRUS	aircraft destroyed.
				Sailplane lost control and crashed. 1 person on board, 1 fatality,
02/06/2019	Germany	EDBY: Schmoldow	PZL BIELSKO - SZD36 - A	aircraft destroyed.
				Sailplane accident - collision with motorcycle. 1 person on board, 1
08/06/2019	Poland	EPNT	PZL BIELSKO - SZD50	fatality, substantial damage.
				Sailplane crash during attempted off-airfield landing. 1 person on
15/06/2019	Poland	Szczury	PZL BIELSKO - SZD48 - 1	board, 1 fatality, aircraft destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
				Sailplane crashed into terrain due to unknown reasons. 1 person on
16/06/2019	Germany	Hahnweide	SCHEMPP HIRTH	board, 1 fatality, aircraft destroyed.
				Sailplane crashed into mountains. 1 person on board, 1 fatality,
23/06/2019	Switzerland	Sex Noir mountain	SCHLEICHER - ASG32	aircraft destroyed.
				Sailplane lost control crashed into a field. Possible medical
02/07/2019	Germany	Lüsse	SCHLEICHER - ASW20L	incapacitation. 1 person on board, 1 fatality, aircraft destroyed.
			GROB - SPEED ASTIR IIB -	
11/07/2019	Czech Republic	LKDK	NO SERIES EXISTS	Loss of control during landing - fall of glider.
			GLASER DIRKS - DG1000 -	Aircraft crashed in mountainous terrain. 2 persons on board, 2
16/07/2019	France	Valernes	Т	fatalities, aircraft destroyed.
			SCHEMPP HIRTH - DISCUS	Broken winch cable; sailplane spin on final approach. 1 person on
28/07/2019	Denmark	EKTO: Tølløse	В	board, 1 fatality, aircraft destroyed.
		between Rickenbach and		
		Altenschwand, Baden-		
30/07/2019	Germany	Württemberg	GLASFLUGEL - HORNET	A sailplane crashed onto a local road during thermal flight instruction.
				Loss of control during take-off tow of sailplane. 1 person on board, 1
11/08/2019	Czech Republic	LKHB: Havlíckuv Brod	SCHLEICHER - ASW19 - B	fatality.
13/08/2019	Czech Republic	SW part of Trutnov	ORLICAN	Mid-air collision of sailplanes. 1 fatality and aircraft destroyed.
25/08/2019	France	Romilly sur Seine	OTHER	Loss of control after take-off - aircraft crashed.
				Sailplane crash during take-off. 1 person on board, 1 fatality, aircraft
31/08/2019	Spain	LEMX: La Mancha	GROB - SPEED ASTIR II	destroyed.
				Elevator problems in aerobatic flight - PIC bailed-out, PAX too late. 2
01/09/2019	Austria	Priel, Wolfsberg	PZL BIELSKO - MDM1	persons on board, 1 fatality, 1 serious injury.
			COMCO IKARUS - IKARUS	Tow airplane failure on take-off - sailplane forced landing, airplane
11/09/2019	France	take-off from LFIX: Itxassou	C42	crash. 1 fatality.
	_			Sailplane lost control during soaring and crashed in mountainous area.
13/09/2019	France	Saint Pons	SCHLEICHER - ASH26 - E	1 person on board, 1 fatality, aircraft destroyed.
			SCHEMPP HIRTH - DISCUS	Sailplane crashed due to unknown reasons. 1 person on board, 1
19/09/2019	Germany	near Boberg airfield	2CT	fatality, aircraft destroyed.
				Sailplane disintegration in flight and crash. 1 person on board, 1
12/10/2019	Czech Republic	Vrbno pod Pradedem	PZL BIELSKO - SZD42 - 2	fatality, aircraft destroyed.
45/40/55:5	_		ROLLADEN SCHNEIDER -	
15/10/2019	France	Pic Saint Loup	LS7	Collision with terrain in flight on a slope. 1 person on board, 1 fatality.
0.0/4.0/5.5.5			SCHEMPP HIRTH -	Sailplane crashed into a mountainous area while searching for
26/10/2019	Spain	Meranges	VENTUS C	thermals. 1 person on board, 1 fatality, damage unknown.
00/44/0045	0 10 11			Sailplane disintegration in flight and crash. 1 person on board, 1
03/11/2019	Czech Republic	Ludvikov	SCHLEICHER - ASW19 - B	fatality, aircraft destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			SCHEMPP HIRTH - DISCUS	
27/05/2020	Austria	A-6370 Kitzbühel	2CT	Crash of a sailplane in steep terrain.
			SCHEIBE - ZUGVOGEL - III	
30/05/2020	Germany	Günzburg	- IIIA	Sailplane impacted to the ground after interrupted aircraft towing.
				Sailplane with auxiliary power stalled and hit the Ground. After the
01/06/2020	Germany	Fulda-Johannisau	SCHLEICHER - ASW28	impact the aircraft caught fire.
			ROLLADEN SCHNEIDER -	
11/07/2020	Germany	Dülmen	LS4 - B	Airborne collision between two aircrafts.
12/07/2020	Netherlands	EHGR (GLZ) : Gilze-Rijen	GLASER DIRKS - LS8 - 18	Loss of control after cable release - crash.
			GROB - G103 - TWIN	
19/07/2020	France	Saint-Doulchard	ASTIR - TWIN II	Loss of control inflight and crash.
			ROLLADEN SCHNEIDER -	
07/08/2020	Germany	EDNW: WEISSENHORN	LS4	Airborne collision between sailplane and a powered sailplane.
			SCHEMPP HIRTH -	
08/08/2020	Belgium	EBTN: Goetsenhoven	NIMBUS 4DM	Loss of control on approach - Aircraft crashed.
				Sailplane crashed into a mountainside. 1 person on board, 1 fatality,
15/08/2020	Italy	Rima San Giuseppe (Vercelli)	GLASER DIRKS - DG800 - B	aircraft destroyed.
	_		SCHEMPP HIRTH -	
19/08/2020	France	Saint André les Alpes	VENTUS 2C	Aircraft collided with high terrain.
	_	LFID: Condom Valence-Sur-		
31/08/2020	France	Baïse	OTHER	Crash on initial climb.
12/09/2020	Switzerland	Col du Mollendruz	CENTRAIR - 101 - A	Crash after tow rope release.
		LEAX : La Axarquia-Leoni		
11/10/2020	Spain	Benabu (Malaga)	SCHEIBE - SF25 - B	Incapacitation of pilot in-flight.
07/00/0004				Glider lost control while winch take-off. Cable prematurely released. 2
07/03/2021	Spain	LETI: Tiétar Aerodrome	SCHLEICHER - ASK13	persons on board, 2 fatalities.
00/05/2024	C	Harris Bard Martin Land	ROLLADEN SCHNEIDER -	
08/05/2021	Germany	Horn Bad Meinberg	LS4	Glider crashed. 1 person on board, 1 fatality.
16/05/2021	Germany	Dingel	SCHLEICHER - ASW24	Loss of control resulted in a crash. 1 person on board, 1 fatality.
20/05/2024	D	THO	CDOD C103	Turn into tailwind at low altitude and at a low airspeed led to an
29/05/2021	Denmark	approach to ETKO	GROB - G102	unrecoverable spin.
12/06/2021	Curitanalas d	Divio	COLUEICHED ACMAZ	Probable mid-air collision between a sailplane and a Robin DR400, 5
12/06/2021	Switzerland	Bivio	SCHLEICHER - ASW27	persons on board, 5 fatalities.
23/06/2021	Germany	Eschwege	GROB - G103	Crash on runway. 2 persons on board, 2 fatalities.
22/07/2024	Consider and a second	Conthou	ALICDODT CUENTS	Glider with electric motor crashed into a steep slope during cross
22/07/2021	Switzerland	Conthey	ALISPORT - SILENT 2	country flying. 1 person on board, 1 fatality.

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Approach to LFTM: Serres, La	SPORTINE AVIACIJA -	
02/08/2021	France	Bâtie-Montsaléon	LAK17	Loss of control on approach, collision with ground.
08/08/2021	Italy	Val di Fua, Cartore, Rieti	LANGE -	Loss of control in flight then impact with the terrain.
			SCHEMPP HIRTH - DISCUS	
25/08/2021	Germany	Oerlinghausen	2A	Mid-air collision of two gliders resulting in 1 fatality.
				Glider crashed while winch due to loss of lateral balance. 1 person on
10/10/2021	Poland	EPWK: Włocławek-Kruszyn	PZL BIELSKO - SZD30	board, 1 fatality.
13/10/2021	France	Bordes-de-Rivière	GLASER DIRKS - DG600M	Glider crashed into terrain after disconnection from the tug microlight

Aerodromes and ground handling

Local Date	State of Occurrence	Location	Aeroplane	Headline
			PIPER - PA25 - 235,	Mid-air collision between a sailplane and an aeroplane above the
05/05/2012	France	AD Buno Bonnevaux (91)	SLINGSBY - T31	runway.
11/11/2012	Italy	Roma Fiumicino Airport	AIRBUS - A320	Loading crew caught between loader and baggage door.
10/12/2012	Cyprus	Larnaca	CESSNA - 750	A service vehicle struck the right wingtip, vehicle driver trapped.
26/02/2020	France	Elne	PIPER - PA44	Aircraft crashed due to unknown circumstances.

ATM/ ANS

Local Date	State of Occurrence	Location	Aeroplane	Headline
		Approach to Santiago Airport		Aircraft experienced an unstable approach and crashed in heavy fog
02/08/2012	Spain	(LEST)	CESSNA-500	condition. Both crews were killed, and the aircraft destroyed.
				Aircraft crashed in wooded terrain in IMC weather conditions. Aircraft
				was not airworthy and was overloaded with 8 passengers on board.
				The accident resulted in 6 fatalities and 2 passengers sustaining
30/09/2012	Austria	Ellbögen, Innsbruck district, Tirol	CESSNA - 414	serious injuries. Aircraft was destroyed.
				Rescue helicopter crashed into a riverbank after colliding into power
		Under Kláštorná roklina gorge –		cables during an emergency medical services mission. All 4 crew
17/07/2015	Slovakia	Hornád canyon - Slovenský Raj	AGUSTA - A109 - K2	members and passengers were killed in the crash.
		Pizzo Zocca di val Masino	AEROSPATIALE - AS350 -	Helicopter crashed into mountain peak obscured by clouds during a
31/07/2015	Italy	(Sondrio)	B3	VFR aerial working flight. All 3 crew members were killed in the crash.
				Helicopter performing HEMS flight to Campo Felice ski area impacted
				the South-West side of the Cefalone Mountain. The 6 persons on
24/01/2017	Italy	Monte Cefalone, Lucoli (AQ)	AGUSTA - AW139	board were fatally injured and the helicopter completely destroyed.

Local Date	State of Occurrence	Location	Aeroplane	Headline
			EUROCOPTER - EC135 -	
			P2, PIPER - PA28RT -	A helicopter and an airplane collided mid-air near Philipsburg. The 4
23/01/2018	Germany	Philippsburg	201T	occupants onboard the 2 aircraft were fatally injured.
				Helicopter conducting emergency medical service collided with radio
				tower in poor weather conditions. All 4 crew members and
15/12/2018	Portugal	1NM South of Valongo	AGUSTA - A109 - S	passengers on board were killed.
				A helicopter and an airplane collided near the Rutor glacier. The pilot
			AEROSPATIALE - AS350 -	and 4 out of the 5 passengers on board of the helicopter and 2 out of
25/01/2019	Italy	Rutor Glacier	B3, JODEL - D140 - E	the 3 pilots on board of the airplane died.
		Gletscherspitze above Blatten /		
25/07/2020	Switzerland	VS	CESSNA 172	Aircraft collided with elevated terrain.



EUROPEAN UNION AVIATION SAFETY AGENCY SAFETY INTELLIGENCE DEPARTMENT

Catalogue number

TO-AA-22-001-EN-N

ISBN

978-92-9210-279-1

ISSN

2314-9272

DOI

10.2822/056444

Postal address

Postfach 10 12 53 50452 Cologne Germany : Visiting address

European Union Aviation Safety Agency Konrad-Adenauer-Ufer 3, D-50668 Köln, Germany **Tel.** +49 221 89990 - 000

Mail safetypromotion@easa.europa.euWeb www.easa.europa.eu