

EASA Certification Information

No.: 2022-26

Issued: 27 September 2022

Subject: Decision to surrender of Transicoil LLC the following ETSO Authorization:

ETSOA No.	Model/Description	P/Ns	Date of ETSOA last issue	DDP Ref.
EASA.IM.210.10040673	MCDU	DNM-100-261-(XX)	18/07/2012	DDP No 30-078,
	Multifunctional			REV.—or
	Control & Display			Subsequent
	Unit			Revisions

Holder of the Certificate: ADS/TRANSICOIL

9, Iron Bridge Drive, Collegeville PA 19426

USA

Background: On the dates mentioned in the table above EASA issued the specified authorisations to

ADS/TRANSICOIL.

On the 26^{th} of July 2022, the FAA NY ACO informed EASA that the TSO Authorization dated the 21^{st} of March 2012 of TRANSICOIL LLC has been surrendered. As consequence, the related EASA validated authorization mention in the table above is being surrendered as the conditions for which it was validated no longer exist.

In accordance with Article 19 (1) (d) of Regulation (EU) No 2018/1139, EASA surrenders the above listed authorization as of the 26^{th} of July 2022.

Upon that date, the authorisation listed above has become ineffective pursuant to Article 21A.619(a)(4) of the Annex (Part 21) to Commission Regulation (EU) No 748/2012.

Contact: Any request, query or comment shall be sent to:

European Union Aviation Safety Agency European Technical Standard Orders Section

Postfach 10 12 53 50452 Köln - Germany

E-Mail: etsoa@easa.europa.eu