



## EASA Certification Information

**No.:** 2022-28  
**Issued:** 06 October 2022

**Subject:** Decision to surrender various ETSO Authorisations

ETSOA No.	Description	P/N	Date of last issue	DDP ref.
EASA.21O.10048819	DF1575 LH&RH Oven	P/N 4315750-00-6000, 4315757 - 00-0000	11/04/2014	431 57-DDP-3-01, ISSUE 2 or Subsequent Revisions
EASA.21O.10048931	Galley Insert, Convection Oven, DF1 500 Atlas LH&RH	4315000-00-0000, 4315001-00-0000	25/04/2014	437 50-DDP-3-01, ISSUE 1 or Subsequent Revisions
EASA.21O.10048932	Galley Insert, Convection Oven, DEI 500 ARINC LH&RH	431 5000-90-0000, 4315001-90-0000	25/04/2014	431 50-DDP-3-02, ISSUE 1 or Subsequent Revisions
EASA.21O.10051359	DS3500 Steam oven (ARINC)	4323500-(XX)-(XX)00, 4323501-(XX)-(XX)00	22/10/2020	43235-DDP-3-01, ISSUE 1, or Subsequent Revisions
EASA.21O.10051370	DF3500 Convection oven (ARINC)	4313500-(XX)-(XX)00, 4313501-(XX)-(XX)00	22/10/2020	43235-DDP-3-01, ISSUE 1, or Subsequent Revisions
EASA.21O.10051630	DF3500 Convection oven (ATLAS)	4313510-(XX)-(XX)00, 4313511-(XX)-(XX)00	22/10/2020	43235-DDP-3-02, ISSUE 1, or Subsequent Revisions
EASA.21O.10051631	DS3500 Steam oven (ATLAS)	4323510-(XX)-(XXX), 4323511-(XX)-(XXX)	22/10/2020	43235-DDP-3-02, ISSUE 1, or Subsequent Revisions
EASA.21O.10057649	DF3700 BUNWARMER	4313700-00-660, 4313700-01-6600, 4313700-02-6600, 4313700-03-6600	04/04/2016	43137-DP-04, ISSUE 1 or Subsequent Revisions

**Holders of the Certificate:**      **Koninklijke Fabriek Inventum B.V. (DBA B/E Aerospace)**  
Galvanibaan 5  
3439 MG Nieuwegein  
The Netherlands

**Background:**

On the dates mentioned in the table above, EASA issued ETSOA No. EASA.21O.10048819, EASA.21O.10048931, EASA.21O.10048932, EASA.21O.10051359, EASA.21O.10051370, EASA.21O.10051630, EASA.21O.10051631, EASA.21O.10057649 to Koninklijke Fabriek Inventum B.V. (DBA B/E Aerospace).

The Agency has been informed by B/E Aerospace on 16 July 2021 about the surrender of the AP-DOA Approval of Koninklijke Fabriek Inventum B.V., trading under B/E Aerospace. EASA.AP381 was cancelled by EASA on the 26 August 2021.

Consequently, in conjunction with the surrender of the Alternative Procedures to DOA AP381, the ETSO authorisations listed above have become ineffective on 26 August 2021 in accordance with the Fees & Charges Regulation (Commission Implementing Regulation (EU) 2019/2153 of 16 December 2019).

**Contact:**                              Any request, query or comment shall be sent to:

European Union Aviation Safety Agency  
European Technical Standard Orders Section  
Postfach 10 12 53  
50452 Köln  
E-Mail: [etsoa@easa.europa.eu](mailto:etsoa@easa.europa.eu)