Centurion 3.0 series engines

Issue: 05 Date: 22 August 2025



# TYPE-CERTIFICATE DATA SHEET

No. E.104

for

Centurion 3.0 series engines

# **Type Certificate Holder**

Continental Aerospace Technologies GmbH
Platanenstr. 14
D-09356 Sankt Egidien
Germany

For Models: Centurion 3.0



Intentionally left blank



Issue: 05

## **TABLE OF CONTENTS**

I. General	. 4
1. Type/ Model	
2. Type Certificate Holder	. 4
3. Manufacturer	. 4
4. Date of Application	. 4
5. EASA Type Certification Date	. 4
II. Certification Basis	. 4
1. Reference Date for determining the applicable airworthiness requirements:	. 4
2. EASA Certification Basis	. 5
2.1. Airworthiness Standards	. 5
2.2. Special Conditions (SC)	. 5
2.3. Equivalent Safety Findings	. 5
2.4. Deviations	. 5
2.5. Environmental Protection	. 5
III. Technical Characteristics	. 5
1. Type Design Definition	. 5
2. Description	. 5
3. Equipment	. 5
4. Dimensions	. 6
5. Dry Weight	. 6
6. Ratings	. 6
7. Control System	
8. Fluids (Fuel, Oil, Coolant, Additives)	
9. Aircraft Accessory Drives	. 6
IV. Operating Limitations	. 7
1. Temperature Limits	
2. Speed Limits	
3. Pressure Limits	
4. Operating Altitude	
5. Time Limited Dispatch (TLD)	
V. Operating and Service Instructions	
VI. Notes	
SECTION: ADMINISTRATIVE	
I. Acronyms and Abbreviations	
II. Type Certificate Holder Record	
III. Change Record	10

Date: 22 August 2025

TCDS No.: E.104 Issue: 05

I. General

## 1. Type/ Model

Centurion 3.0 / Centurion 3.0

## 2. Type Certificate Holder

Continental Aerospace Technologies GmbH Platanenstr. 14 D-09356 Sankt Egidien Germany

DOA EASA.21J.010

#### 3. Manufacturer

Continental Aerospace Technologies GmbH

POA DE.21G.0269

Previous Manufacturer: Technify Motors GmbH (before 01 August 2019)

# 4. Date of Application

Centurion 3.0		
19 December 2013		

## 5. EASA Type Certification Date

Centurion 3.0		
20 June 2017		

## **II. Certification Basis**

## 1. Reference Date for determining the applicable airworthiness requirements:

20 June 2014



TE.CERT.00052-001 © European Union Aviation Safety Agency, 2025. All rights reserved. ISO9001 Certified. Page 4 of 10 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Issue: 05 22 August 2025

#### 2. EASA Certification Basis

#### 2.1. Airworthiness Standards

CS-E, Amendment 3, dated 23 December 2010

## 2.2. Special Conditions (SC)

Addition to CS-E 210 Failure Analysis, Addition to CS-E 240(d) Engine Flame Out during Flight

## 2.3. Equivalent Safety Findings

CS-E 70, 100, 110 – Type design
CS-E 130(h) – Fireproofness of engine attachment points
CS-E 440(b)(3) Endurance Test – Schedule for Engine Incorporating a Turbocharger

#### 2.4. Deviations

None

#### 2.5. Environmental Protection

None (not required for piston engines)

# **III. Technical Characteristics**

## 1. Type Design Definition

TDD-06-01, Issue 1 dated 10 October 2016 or later approved issue/revision

## 2. Description

The Centurion 3.0 engine is a V6-cylinder, four stroke Diesel piston engine with a displacement of 2987 cm<sup>3</sup>, equipped with common rail high pressure direct injection, turbocharger, gearbox with reduction ratio of 1:1.66 and an Electronic Engine Control Unit (EECU).

## 3. Equipment

See Installation Manual



Issue: 05 22 August 2025

#### 4. Dimensions

Model	Centurion 3.0		
Overall Length	980 mm		
Overall Height	700 mm		
Width	790 mm		

## 5. Dry Weight

Model	Centurion 3.0		
Weight	265 kg		

## 6. Ratings

Rating		Centurion 3.0		
	Take-off (5 min)	221 kW (300 HP) at 3900 engine rpm		
Power	Max. Continuous	(2340 prop rpm) 200 kW (272 HP) at 3830 engine rpm (2300 prop rpm)		

Note: The performance values specified above correspond to minimum values defined under the conditions of ICAO or ARDC standard atmosphere.

# 7. Control System

The engine is equipped with an Electronic Engine Control Unit (EECU). Software verified to level C according to RTCA Document DO-178B.

FADEC P/N 06-7610-E000202 or later approved standard

Software: D6-v1.00 or later approved standard

Software Mapping: Refer to Service Bulletin TM TAE 000-0007 for approved software P/N.

## 8. Fluids (Fuel, Oil, Coolant, Additives)

See Operation & Maintenance Manual for approved fluids (see also Note 4).

## 9. Aircraft Accessory Drives

	Rotation	Speed (rpm)	Max. Torque	Type of Drive
Accessory Drive	CCW	3900	13 Nm	AND 20000 modified

CCW = Counter-Clock-Wise

Speed is indicated for a reference engine speed of 3880 rpm.

Accessory drive direction of rotation is as viewed facing the drive.



TE.CERT.00052-001 © European Union Aviation Safety Agency, 2025. All rights reserved. ISO9001 Certified. Page 6 of 10 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Issue: 05 22 August 2025

## **IV. Operating Limitations**

## 1. Temperature Limits

	Temperature in °C / °F	Comments
Minimum opening up Oil Temperature	50 °C / 122 °F	
Max. Oil Temperature:	125 °C / 257 °F	
Minimum Ambient Temperature for Starting	+5 °C / 41 °F	With 32 ≤ Cetane N° < 38
Willimum Ambient Temperature for Starting	-25 °C / -13 °F	With Cetane N°≥38
Minimum Fuel Temperature during operation	-25 °C / -13 °F	
Minimum opening up Cooling Fluid Temperature	60 °C / 140 °F	
Max. Cooling Fluid Temperature	105 °C / 221 °F	
Max. Gearbox Temperature	110 °C / 230 °F	
Max. Exhaust Gas Temperature	850 °C / 1562 °F	

## 2. Speed Limits

Maximum Engine Over-speed (Crankshaft Speed)	4200 rpm (2520 prop rpm)
Take-off speed	3900 rpm (2340 prop rpm)
Max. continuous speed	3830 rpm (2300 prop rpm)

## 3. Pressure Limits

Minimum Fuel Pressure (at inlet of feed pump)	-300 mbar (4.4 psig)
Maximum Fuel Pressure (at inlet of feed pump)	1000 mbar (14.5 psig)
Minimum Oil Pressure at Idle Conditions	2 bar (29 psig)
Oil Pressure (normal operation)	2.3 7.0 bar (33.4 101.5 psig)
Maximum Oil Pressure	7.5 bar (108.8 psig)

# 4. Operating Altitude

Maximum altitude	7620 m (25000 ft)

## 5. Time Limited Dispatch (TLD)

The engine is not approved for Time Limited Dispatch. All engine systems and equipment must be functional prior to aircraft take-off. Any detected engine system or equipment failure must be corrected before next flight. For special instructions, see OM-06-01.



TE.CERT.00052-001 © European Union Aviation Safety Agency, 2025. All rights reserved. ISO9001 Certified. Page 7 of 10 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Issue: 05

22 August 2025

## **V. Operating and Service Instructions**

Manuals	Centurion 3.0	
Installation Manual	IM-06-01	
Operation Manual	OM-06-01	

Instructions for Continued	Centurion 3.0	
Airworthiness (ICA)		
Maintenance Manual	OM-06-01	
Overhaul Manual	OHM-06-01	

Service Bulletins as issued.

#### VI. Notes

- 1. The EASA approved Airworthiness Limitations Section of the Instructions for Continued Airworthiness is published in the applicable "Operation & Maintenance Manual" document, chapter 06-OM-05-01 "Airworthiness Limitations". This ALS section is empty because no life limit is necessary for these models.
- 2. Suffixes in parentheses may be added to the engine model number to define installation specific configuration changes. The software of the electronic engine control for each application has a specific software mapping. See Service Bulletin TM TAE 000-0007 for the installation versions and software mappings. Also refer to Installation Manual for appropriate installation.
- **3.** The Centurion 3.0 series engines are approved for the installation in Part 23 normal and utility category airplanes.
- 4. The Centurion 3.0 series engines are approved for operation with jet fuels (see Operation Manual OM-06-01). The engine has been tested for fuels up to a maximum ignition delay time of 6,78 ms resp. a minimum derived cetane number of 32 (determined according EN 15195/ASTM D6890).
- **5.** The Centurion 3.0 engine, including the FADEC, is approved for use with the propeller MTV-12-D models. This approval does not include the approval of the propellers and their control systems.
- **6.** This engine design features an integrated propeller control in the FADEC. The software in the FADEC has been developed in accordance with DO-178B at level C. The approval of the engine and its FADEC does not include approval of the propeller control system.
- 7. The recommended Time Between Overhaul (TBO) is published in SB TMG 300-0001.
- **8.** The engine control system has been tested according to DO-160G for lightning protection and magnetic interference. The demonstrated levels are declared in the Installation Manual.
- **9.** The EECU must not be installed in a dedicated fire zone. The installation conditions are defined in the Installation Manual.



TE.CERT.00052-001 © European Union Aviation Safety Agency, 2025. All rights reserved. ISO9001 Certified. Page 8 of 10 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Centurion 3.0 series engines

TCDS No.: E.104 Issue: 05 22 August 2025

Installation Assumptions: See Installation Manual. 10.

11. Containment has been demonstrated for max. turbocharger speed of 192500 rpm.

12. Sales name of the model Centurion 3.0: CD-300



TE.CERT.00052-001 © European Union Aviation Safety Agency, 2025. All rights reserved. ISO9001 Certified. Page 9 of 10 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Issue: 05 22 August 2025

## **SECTION: ADMINISTRATIVE**

## I. Acronyms and Abbreviations

n/a

## **II. Type Certificate Holder Record**

Continental Aerospace Technologies GmbH Platanenstr. 14 D-09356 Sankt Egidien Germany

**DOA EASA.21J.010** 

Previous TC Holder:

before 01 August 2019: Technify Motors GmbH Platanenstr. 14 D-09356 Sankt Egidien Germany

# III. Change Record

Issue	Date	Changes	TC issue
Issue 01	20 June 2017	Initial Issue	Initial Issue,
			20 June 2017
Issue 02	02 December 2019	Name Change of TC Holder / Manufacturer	02 December 2019
Issue 03	07 May 2020	Change of Operating Limitations (Major	
		Change Approval 10073167)	
Issue 04	27 October 2020	Editorial change regarding the Maximum	
		Continuous Power Rating	
Issue 05	22 August 2025	Overhaul Manual added (Major Change	
		Approval 10087860), editorial corrections	

-END-

