



TYPE-CERTIFICATE DATA SHEET FOR NOISE

No. EASA.IM.A.120

for

Boeing 737

Type Certificate Holder:

The Boeing Company

1901 Oakesdale Ave SW

Renton, WA 98057-2623

USA

For models:	737-100	737-600	737-8
	737-200	737-700	737-8200
	737-200 (ADV)	737-800	737-9
	737-300	737-900	
	737-400	737-900ER	
	737-500		



CONTENTS

For 737-100, 737-200, 737-200 (ADV), 737-300,
737-400 and 737-500 models see TCDSN EASA.IM.A.120 Volume 1

For 737-600 models see TCDSN EASA.IM.A.120 Volume 2

For 737-700 models see TCDSN EASA.IM.A.120 Volume 3

For 737-800 models see TCDSN EASA.IM.A.120 Volume 4

For 737-900 and 737-900ER models see TCDSN EASA.IM.A.120 Volume 5

For 737-8, 737-9 and 737-8200 models see TCDSN EASA.IM.A.120 Volume 6



Change Record

Issue	Date	Changes
Issue 1	16 April 2008	Initial Issue
Issue 2	06 March 2009	Revised
Issue 3	16 February 2010	Added records A13631 - 14008, A14184, A14186, A14187, A14198, A14199, A14201-A14203, A14414 and A14215; Revised other records
Issue 4	13 October 2010	Records A10450-A10461 : Engine designation revised ; Records A837, A838, A10595, A10596, A10598, A10601, A10602, A10604 : Flyover noise level revised ; Record A13631 : changed record number to A15035 ; Records A14414, A15211 and A15209 added
Issue 5	19 January 2011	Added records A15455, A15560-A15565, A15573-A15590
Issue 6	29 June 2011	Revised
Issue 7	24 October 2011	Revised
Issue 8	05 March 2012	Revised
Issue 9	11 July 2012	Revised
Issue 10	09 April 2013	Revised
Issue 11	12 December 2013	TCDSN EASA.IM.A.120 published as 5 volumes: Volume 1, issue 1, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 1, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 1, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 1, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 1, EASA.IM.A.120.5 for the 737-900 & 737-900ER
Issue 12	10 March 2015	TCDSN EASA.IM.A.120 published as 5 volumes: Volume 1, issue 2, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 1, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 1, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 1, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 1, EASA.IM.A.120.5 for the 737-900 & 737-900ER
Issue 13	29 September 2015	TCDSN EASA.IM.A.120 published as 5 volumes: Volume 1, issue 3, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 1, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 3, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 3, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 2, EASA.IM.A.120.5 for the 737-900 & 737-900ER
Issue 14	05 April 2016	TCDSN EASA.IM.A.120 published as 5 volumes: Volume 1, issue 4, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 4, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 4, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 3, EASA.IM.A.120.5 for the 737-900 & 737-900ER
Issue 15	24 November 2016	TCDSN EASA.IM.A.120 published as 5 volumes: Volume 1, issue 5, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 5, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 5, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 3, EASA.IM.A.120.5 for the 737-900 & 737-900ER



Issue	Date	Changes
Issue 16	28 February 2017	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 5, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 5, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 5, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 3, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 1, EASA.IM.A.120 for the 737 “Max” series
Issue 17	27 June 2017	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 5, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 5, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 6, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 3, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 1, EASA.IM.A.120 for the 737 “Max” series
Issue 18	12 January 2018	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 6, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 6, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 7, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 3, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 1, EASA.IM.A.120 for the 737 “Max” series
Issue 19	15 June 2018	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 7, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 7, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 8, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 1, EASA.IM.A.120 for the 737 “Max” series
Issue 20	17 October 2018	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 7, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 7, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 8, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 2, EASA.IM.A.120 for the 737 “Max” series
Issue 21	24 October 2018	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 7, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 7, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 8, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 3, EASA.IM.A.120 for the 737 “Max” series
Issue 22	15 November 2018	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 7, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 8, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 9, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 3, EASA.IM.A.120 for the 737 “Max” series



Issue	Date	Changes
Issue 23	12 April 2019	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 8, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 9, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 10, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 4, EASA.IM.A.120 for the 737 “Max” series
Issue 24	07 August 2019	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 9, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 10, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 11, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 4, EASA.IM.A.120 for the 737 “Max” series
Issue 25	07 September 2020	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 9, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 11, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 12, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 4, EASA.IM.A.120 for the 737 “Max” series
Issue 26	06 April 2021	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 9, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 11, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 13, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 5, EASA.IM.A.120 for the 737 “Max” series
Issue 27	25 October 2021	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 10, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 12, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 14, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 6, EASA.IM.A.120 for the 737 “Max” series
Issue 28	25 March 2022	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 11, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 13, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 15, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 7, EASA.IM.A.120 for the 737 “Max” series
Issue 29	31 August 2022	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 12, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 14, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 16, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 7, EASA.IM.A.120 for the 737 “Max” series



Issue	Date	Changes
Issue 30	13 October 2022	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 12, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 14, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 16, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 8, EASA.IM.A.120 for the 737 "Max" series
Issue 31	30 November 2022	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 12, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 14, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 17, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 8, EASA.IM.A.120.6 for the 737 "Max" series
Issue 32	10 January 2023	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 12, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 14, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 17, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 9, EASA.IM.A.120.6 for the 737 "Max" series
Issue 33	27 February 2023	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 13, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 14, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 18, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 9, EASA.IM.A.120.6 for the 737 "Max" series
Issue 34	30 May 2023	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 13, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 15, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 19, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 9, EASA.IM.A.120.6 for the 737 "Max" series
Issue 35	06 September 2023	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 14, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 15, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 20, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 10, EASA.IM.A.120.6 for the 737 "Max" series
Issue 36	08 December 2023	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 14, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 15, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 21, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 11, EASA.IM.A.120.6 for the 737 "Max" series



Issue	Date	Changes
Issue 37	04 March 2024	TCDSN EASA.IM.A.120 published as 6 volumes: Volume 1, issue 15, EASA.IM.A.120.1 for the 737-100, 737-200, 737-200 (ADV), 737-300, 737-400 & 737-500; Volume 2, issue 2, EASA.IM.A.120.2 for the 737-600; Volume 3, issue 15, EASA.IM.A.120.3 for the 737-700; Volume 4, issue 22, EASA.IM.A.120.4 for the 737-800; and Volume 5, issue 4, EASA.IM.A.120.5 for the 737-900 & 737-900ER Volume 6, issue 11, EASA.IM.A.120.6 for the 737 “Max” series

-END-