

**Subject: Airspace of Egypt Sinai Peninsula****Status:**

Active

**Issued date:**

24/05/2019

**Valid until:**

29/11/2019

**Revision:**

This CZIB is revised to extend the validity period of CZIB-2017-09R2, and to amend reference publications.

**Referenced publication(s):**

- United Kingdom AIP ENR 1.1 issued 31 Jan. 2019 (see Appendix 1).
- United States Federal Aviation Administration KICZ A0010/19 issued 30 March 2019 (see Appendix 2).
- Ireland NOTAM B00471/19 issued 01 May 2019 (see Appendix 3).

**Affected Airspace:**

Egypt airspace, Cairo Flight Information Region (FIR HECC), Sinai Peninsula.

**Applicability:**

Applies to operators

**Description:**

The Agency draws the attention of the aviation community to the above referenced information, copies of which are attached to this CZIB. This CZIB is issued on the basis of information available to EU Member States and EU institutions. Due to the hazardous situation, it is assessed that the risk of operation and overflight below FL250 is HIGH.

---

This is information only. Recommendations are not mandatory.



**Recommendation(s):**

Operators should take this information and any other relevant information into account in their own risk assessments, alongside any available guidance or directions from their national authority as appropriate. Latest operational information on 'Closures and warnings' issued by means of ICAO State Letters, NOTAMs, AICs/AIPs, EASA CZIB may be found in the [Network Manager NOP Portal](#) [2] (password protected version).

**Affected Countries:**

**Egypt**

## Appendix 1

Source: United Kingdom [AIP ENR 1.1](#)  
[United Kingdom Aeronautical Information Service](#)

Hazardous Situation in Egypt

Potential risk to aviation overflying Egyptian airspace in Northern Sinai

Governate within the area bounded by 311400N 0322200E - 294000N 0324000E - 293000N 0345400E - 312000N 0341200E - 311400N 0322200E (Cairo FIR, Sinai Peninsula) at less than 25,000 ft above ground level (agl) from dedicated anti-aviation weaponry.

Operators are strongly advised to avoid operating at less than 25,000 ft agl in this airspace.

Contact UK Department for Transport +44 (0)207-944 4426 or +44 (0)207-944 5999 out of hours.

## Appendix 2

Source: United States Federal Aviation Administration [NOTAM KICZ A0010/19](#)

A0010/19 (Issued for KICZ)

SECURITY..UNITED STATES OF AMERICA ADVISORY FOR EGYPT SINAI PENINSULA.

THOSE PERSONS DESCRIBED IN PARAGRAPH A BELOW SHOULD AVOID FLYING INTO, OUT OF, WITHIN OR OVER THE SINAI PENINSULA IN THE CAIRO FLIGHT INFORMATION REGION (FIR) (HECC) AT ALTITUDES BELOW FL260 WITHIN THE FOLLOWING LATERAL LIMITS:

311855N 0321900E TO 294443N 0322815E TO 281650N 0331928E TO 272900N 0341900E

---

This is information only. Recommendations are not mandatory.



An agency of the European Union

TE.CAP.0124-002 © European Aviation Safety Agency. All rights reserved. ISO9001 Certified.  
 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

TO 292920N 0345500E THEN ALONG THE EGYPT/ISRAEL BORDER TO 311800N 0341300E TO 311855N 0321900E.

A. APPLICABILITY. THIS NOTAM APPLIES TO: ALL U.S. AIR CARRIERS AND COMMERCIAL OPERATORS; ALL PERSONS EXERCISING THE PRIVILEGES OF AN AIRMAN CERTIFICATE ISSUED BY THE FAA, EXCEPT SUCH PERSONS OPERATING U.S.-REGISTERED AIRCRAFT FOR A FOREIGN AIR CARRIER; AND ALL OPERATORS OF AIRCRAFT REGISTERED IN THE UNITED STATES, EXCEPT WHERE THE OPERATOR OF SUCH AIRCRAFT IS A FOREIGN AIR CARRIER.

B. PLANNING. THOSE PERSONS DESCRIBED IN PARAGRAPH A PLANNING TO FLY INTO, OUT OF, WITHIN, OR OVER THE ABOVE-NAMED AREA MUST REVIEW CURRENT SECURITY/THREAT INFORMATION AND NOTAMS; COMPLY WITH ALL APPLICABLE FAA REGULATIONS, OPERATIONS SPECIFICATIONS, MANAGEMENT SPECIFICATIONS, AND LETTERS OF AUTHORIZATION, INCLUDING UPDATING B450; AND PROVIDE AT LEAST 72 HOURS ADVANCE NOTICE OF PLANNED FLIGHTS TO THE FAA AT AEO-CITWATCH@FAA.GOV WITH SPECIFIC FLIGHT DETAILS TO THE MAXIMUM EXTENT POSSIBLE.

C. OPERATIONS. EXERCISE EXTREME CAUTION DURING FLIGHT OPERATIONS DUE TO THE RISK FROM POTENTIAL EXTREMIST/MILITANT ATTACKS INVOLVING ANTI-AIRCRAFT WEAPONS, INCLUDING MAN-PORTABLE AIR DEFENSE SYSTEMS (MANPADS), ANTI-TANK MISSILES, SMALL-ARMS FIRE, AND INDIRECT FIRE FROM MORTARS AND ROCKETS TARGETING AIRCRAFT AND SINAI AIRPORTS. THOSE PERSONS DESCRIBED IN PARAGRAPH A MUST REPORT SAFETY AND/OR SECURITY INCIDENTS TO THE FAA AT +1 202-267-3333 OR 1 202-267-3203.

THE JUSTIFICATION FOR THIS ADVISORY WILL BE RE-EVALUATED BY 30 MARCH 2020.

ADDITIONAL INFORMATION IS PROVIDED AT:

[HTTPS://WWW.FAA.GOV/AIR\\_TRAFFIC/PUBLICATIONS/US\\_RESTRICTIONS/](https://www.faa.gov/air_traffic/publications/us_restrictions/).

SFC - FL259, 30 MAR 10:28 2019 UNTIL 30 MAR 23:59 2020 ESTIMATED. CREATED: 30 MAR 10:33 2019

## Appendix 3

---

This is information only. Recommendations are not mandatory.



An agency of the European Union

TE.CAP.0124-002 © European Aviation Safety Agency. All rights reserved. ISO9001 Certified.  
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Source: Ireland [NOTAM B0471/19](#)

FLIGHT IN EGYPT AIRSPACE, CAIRO FLIGHT INFORMATION REGION (FIR HECC), SINAI PENINSULA.

THE IRISH AVIATION AUTHORITY HAS BEEN DIRECTED BY THE MINISTER FOR TRANSPORT, TOURISM AND SPORT UNDER SECTION 7 (1) (B) OF THE IRISH AVIATION ACT 1993, TO ISSUE A DIRECTION TO IRISH AOC CARRIERS THAT IRISH AOC AIRCRAFT SHOULD NOT FLY BELOW 26000FT IN EGYPT AIRSPACE, CAIRO FLIGHT INFORMATION REGION (FIR HECC), SINAI PENINSULA. THE IRISH AVIATION AUTHORITY, IN PURSUANCE OF ARTICLES 4,7 AND 25 OF THE IRISH AVIATION AUTHORITY (OPERATIONS) ORDER (S.I. NO.61 OF 2006), (HEREINAFTER REFERRED TO AS THE ORDER), HEREBY DIRECTS THAT ALL IRISH AOC AIRCRAFT SHOULD NOT FLY BELOW 26000FT IN EGYPT'S AIRSPACE CAIRO FLIGHT INFORMATION REGION (FIR HECC), SINAI PENINSULA.

01 MAY 15:55 2019 UNTIL 01 AUG 17:00 2019 ESTIMATED. CREATED: 01 MAY 15:58 2019

---

This is information only. Recommendations are not mandatory.



An agency of the European Union

TE.CAP.0124-002 © European Aviation Safety Agency. All rights reserved. ISO9001 Certified.  
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.