



EASA Certification Information

No.: 2017 - 01
Issued: 08 March 2017

Subject: Revocation of DGAC France Authorisation No. F.O.011 upon refusal of PRONAL to pay the fees (ref. EC No. 593/2007, Annex, Table 6) for this authorization.

Authorisation No: F.O.011 (grandfathered under Article 6 of Regulation (EU) 748/2012)

Issue date: 17.10.2000

Issued by: DGAC France

Holder of the Certificate: PRONAL
Z.I ROUBAIX-EST, Rue du Trieu du Quesnoy
59115 Leers
France

Model: Wall of bladders for flexible fuel tank

Part Number: RAHE(XXXXX)-(X)

Background: PRONAL refused with a letter from 14 March 2015 to pay the required annual fees and in accordance with the applicable EASA administrative procedures¹, EASA decided to revoke the DGAC France Authorisation No. F.O.011.

EASA has submitted the decision to revoke F.O.011 to the authorisation holder on 08 March 2017.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency
Parts & Appliances Section
Postfach 10 12 53
D – 50452 Köln
E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<http://easa.europa.eu/certification/internal-working-procedures.php>)