



# T67 Service Bulletins

No	Title	Issue	Date	Classification	Applicability									Notes	Info	CAA/EASA A.D. No.	Approval	
					T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A					
001	Aileron Control Circuit Inspection	1	11/05/1982	Compulsory	T67A												003-01-93	CAA
002	Exhaust Heat Exchanger Asbestos Seal Inspection	1	21/06/1982	Compulsory	T67A												004-01-93	CAA
002	Exhaust Heat Exchanger - Asbestos Carb Heat	2	06/07/1982	Compulsory	T67A												004-01-93	CAA
003	Bendix Magneto Impulse Couplings	1	13/10/1982	Compulsory	T67A												N/A	SAL
004	Inspection of Control Column	1	10/02/1983	Recommended	T67A												N/A	SAL
005	Inspection of Mainplane Walkways	1	10/02/1983	Recommended	T67A												N/A	SAL
006	Rudder Turnbuckles	1	01/11/1983	Recommended	T67A												N/A	SAL
007	Oil Level Limitations for Aerobatic Flight	1	06/01/1984	Compulsory	T67A												005-01-93	CAA
007	Oil Level Limitations for Aerobatic Flight	2	03/05/1984	Compulsory	T67A												005-01-93	CAA
008	Inspection of Rudder/Toe Brake Assembly for Security of Hexagon Socket Cap Screws	1	08/06/1984	Recommended		T67B			T67M								N/A	SAL
008	Inspection of Rudder/Toe Brake Assembly for Security of Hexagon Socket Cap Screws	2	20/11/1985	Mandatory		T67B	T67C		T67M	T67M200		T67M-MkII					013-11-85	CAA
009	NOT ISSUED																	
010	Inspection of Tailplane Attachment Bolts - T67 Aircraft	1	29/08/1985	Mandatory		T67B			T67M								006-01-93	CAA
010	Inspection of Tailplane Attachment Bolts - T67 Aircraft	2	08/04/1988	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII					006-01-93	CAA
011	NOT ISSUED																	
012	Inspection for Battery Acid Leakage and/or Damage T67M	1	03/04/1986	Mandatory					T67M					Pre-Mod 117 or Pre-Mod 114B			011-05-87	CAA
013	Main Undercarriage Top Mounting Block	1	05/01/1987	Mandatory		T67B			T67M	T67M200		T67M-MkII		T67M200 Post Mod M198A			003-05-87	CAA
014	Bearings in Control Column Aileron Tie Rod	1	05/01/1987	Mandatory	T67A	T67B			T67M	T67M200		T67M-MkII					004-05-87	CAA
014	Bearings in Control Column Aileron Tie Rod	2	19/02/1987	Mandatory	T67A	T67B			T67M	T67M200		T67M-MkII					004-05-87	CAA
014	Bearings in Control Column Aileron Tie Rod	3	14/03/1988	Mandatory	T67A	T67B			T67M	T67M200		T67M-MkII					004-05-87	CAA
015	Rudder Pedal to Sidewall and Rudder Cable Clearances	1	05/01/1987	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Works Numbers 2000-2020 and 2023-2034 Only			005-05-87	CAA
016	NOT ISSUED																	
017	T67A Aft Tailplane Location Brackets	1	27/11/1986	Mandatory	T67A									Work Numbers 1988-1997			012-05-87	CAA
018	Inspection of Flap Centre Drive Brackets	1	16/01/1987	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII					007-01-93	CAA
019	Deletion of Mod M067 shoulder Strap Extensions from T67A Aircraft	1	24/04/1987	Mandatory	T67A									Post Mod M067			013-07-87	CAA
020	Service Life - T67 GRP Aircraft	1	15/12/1987	Mandatory		T67B	T67C		T67M	T67M200		T67M-MkII					008-01-93	CAA
021	Special Inspection to Engine Mounting Frames T67 GRP 160 HP and 200 HP aircraft. pre Mod M278A and Mod M278B respectively	1	15/12/1987	Maintenance			T67C		T67M	T67M200		T67M-MkII		2014, 1999-2000, 2002-2004, 2009-2010, 2017-2018, 2021-2022, 2043-2044, 2047, 2027, 2030-2034, 2038-2042				SAL
022	Checks on Fuel Flow: Aerobatic Flight	1	28/04/1988	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		T67C Post Mod M156			AD not Issued	CAA
022	Checks on Fuel Flow: Aerobatic Flight	2	16/01/1989	Optional	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		T67C Post Mod M156				SAL
022	Checks on Fuel Flow: Aerobatic Flight	3	11/04/1994	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		T67C Post Mod M156			004-04-94	CAA
023	T67M200 Propeller Daily Inspection	1	20/06/1988	Mandatory						T67M200				All T67M200 fitted with Hoffmann HO-V123K-V/180R			LBA(AD)-LTA88-20	CAA
023	T67M200 Propeller Daily Inspection	2	26/05/2004							T67M200				All T67M200 fitted with Hoffmann HO-V123K-V/180R			LBA(AD)-LTA88-20	CAA
024	T67M200 Propeller Fitting	1	04/07/1988	Mandatory						T67M200				T67M200 prior to Construction No. 2058			009-01-93	CAA
025	Flight in Thunderstorm and Lightning Activity	1	04/07/1988	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		All T67 with Mod 272B or M177B Fitted			010-01-93	CAA
025	Flight in Thunderstorm and Lightning Activity	2	08/11/1989	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		All T67 with Mod 272B or M177B Fitted			010-01-93	CAA
026	T.B.O. - Propeller R.P.M. Governors	1	29/08/1988	Recommended					T67M	T67M200		T67M-MkII						SAL
027	Hoffmann Propeller - T.B.O	1	30/09/1988	Recommended					T67M			T67M-MkII						SAL
028	Special Inspection - A125D/66 Stiffnuts	1	17/11/1988	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		T67 Construction Nos.2045-2051,2052-2061, 2063			011-01-93	CAA
029	Recall of Aeroquip 601 Type Hose	1	22/03/1989	Mandatory			T67C			T67M200		T67M-MkII					024-03-89	CAA
030	Aileron Flettner Strips	1	23/05/1989	Optional					T67M	T67M200		T67M-MkII		Except Works Nos.2043,2062,2066 and subsequent				SAL
031	Special Inspection - Safety Harness (Negative 'G' Strap)	1	07/06/1989	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260		T67M260-T3A	Part A:Works Nos 2000,2002-2004, 2008-2011,2013-2018, 2020-2033,2035-063,2066-2069,2075,2078 -Part B:2064,2065,2070-074,2076,2077,2079 and subsequent			012-01-93	CAA
032	King Radio KCS 55A Slaved Gyrocompass System - Erroneous Readings	1	17/07/1989	Mandatory						T67M200		T67M-MkII					013-01-93	CAA
032	King Radio KCS 55A Slaved Gyrocompass System - Erroneous Readings	2	06/11/1989	Mandatory						T67M200		T67M-MkII					013-01-93	CAA
033	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	1*		Mandatory			T67C	T67C3	T67M	T67M200				Except Works No.1999, T67M200 Pre Mod M412			014-01-93	CAA
033	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	2	28/08/1989	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Except Works No.1999, T67M200 Pre Mod M412			014-01-93	CAA
033	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	3	09/11/1992	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Except Works No.1999, T67M200 Pre Mod M412			014-01-93	CAA
033	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	4	18/07/1995	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Except Works No.1999, T67M200 Pre Mod M412			014-01-93	CAA
034	Rudder Upper and Lower Hinge Support Angles - Inspection	1	06/11/1989	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII					015-01-93	CAA
035	Wing Rear Spar	1	25/06/1990	Maintenance	T67A													SAL
035	Wing Rear Spar Inspection T67A aircraft.	2	10/01/1997	Essential	T67A													SAL
036	Inspection of Nose Undercarriage Sliding Leg Weld	1	08/06/1990	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Pre Mod M468			018-06-90	CAA
037	Inspection of Main Undercarriage Torque Link Bolts	1	10/07/1991	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII					016-01-93	CAA
038	Extension of Fuel Vent Pipes (Wing Tank Aircraft Only)	1	06/04/1992	Optional	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Works Nos.2017, 2018, 2021-2022, 2027,2031-2033, 2038-2052, 2054-2061,2066-2069,2075 -2076, 2078				SAL
039	Inspection of Wing Rear Spar Top Surface to Fuselage Fairing Clearance	1	06/04/1992	Optional	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Except Works Nos.2074,2077, 2081,2083 2087 2099-2101				SAL
040	Special Inspection of Throttle Cable - T67C Aircraft	1	18/03/1992	Mandatory			T67C	T67C3									017-01-93	CAA
040	Special Inspection of Throttle Cable - T67C Aircraft	2	09/11/1992	Mandatory			T67C	T67C3						Pre Mod 480			017-01-93	CAA
041	Special Inspection of Throttle Cable - T67 GRP Aircraft Except T67C	1	09/11/1992	Mandatory		T67B			T67M	T67M200		T67M-MkII					018-01-93	CAA
041	Special Inspection of Throttle Cable - T67B Aircraft	2	30/01/9'5	Mandatory		T67B											018-01-93	CAA
042	Inspection to Aileron Support Rib Outboard (Rib 8)	1	08/01/1993	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		T67M260 Mod M490A only			002-01-93	CAA
043	Engine Settings to Alleviate Engine Stop in Spin	1	02/03/1993	Advisory			T67C	T67C3									015-03-93	CAA
043	Engine Settings to Alleviate Engine Stop in Spin	2	05/03/1993	Mandatory			T67C	T67C3									015-03-93	CAA
044	Check on Clearance between Forward U/C Leg and Engine Mounting Frame	1	10/03/1994	Mandatory			T67C	T67C3				T67M-MkII		Post Mod M468			004-03-94	CAA
045	T67A Centre Console Inspection	1	29/03/1994	Recommended	T67A				T67M					T67M Works No 1999				SAL
046	Split Canopy Locating Lug Re-Profile	1	29/03/1994	Recommended	T67A		T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129				SAL
046	Split Canopy Locating Lug Re-Profile	2	18/04/1994	Recommended	T67A		T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129				SAL
047	Static System Blockage	1	18/08/1994	Advisory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A					SAL
048	Windscreen De-Misting Duct Routing Check	1	01/03/1994	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Pre Mod M515			011-03-94	CAA
049	Rudder Mechanism to Fuel Pipe Clearance Check	1	12/08/1994	Advisory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M156				SAL

050	Inspection of Port Throttle Limit Stop Bolts	1	29/03/1994	Advisory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII					SAL
051	Inspection of Rudder Cable to Link Plate Socket Head Cap Screw	1	29/03/1994	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M95		015-03-94	CAA
052	Elevator Horn Water Ingress	1	27/05/1994	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			010-05-94	CAA
052	Elevator Horn Water Ingress	2	27/06/1994	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			010-05-94	CAA
052	Elevator Horn Water Ingress	3	06/03/1996	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			010-05-94	CAA
053	Inspection of Air Injector Box Auxiliary Intake Door Spring Attachment	1	15/02/1994	Essential									T67M260-T3A				SAL
054	Inspection of Wing Fuel Tank Drain Valves	1	26/05/1994	Mandatory								T67M-MkII	T67M260-T3A	T67M-MkII - 2116 to 2122, T67M260-T3A - 2109, 2110, 2123 to 2130		011-05-94	CAA
055	Special Inspection of Throttle Cable - T67 GRP Aircraft Except T67C	1	14/04/1994	Mandatory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M480	Supersedes and replaces SB 40 & SB 41	005-04-94	CAA
055	Special Inspection of Throttle Cable - T67 GRP Aircraft	2	22/04/1994	Mandatory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M480	Supersedes and replaces SB 40 & SB 41	005-04-94	CAA
055	Special Inspection of Throttle Cable - T67 160/200 HP aircraft	3	01/12/1994	Mandatory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M480	Supersedes and replaces SB 40 & SB 41	005-04-94	CAA
055	Special Inspection of Throttle Cable - T67 160/200 HP aircraft	4	24/01/1995	Mandatory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M480		005-04-94	CAA
056	Inspection of Air Intake Box By-Pass Flap Hinge	1	12/09/1994	Highly Recommended					T67M	T67M200		T67M-MkII					SAL
056	Inspection of Air Intake Box By-Pass Flap Hinge	2	17/07/1994	Highly Recommended					T67M	T67M200		T67M-MkII		Pre Mod M595			SAL
057	Inspection of Rear Canopy Slide Rail Assembly	1	01/12/1994	Highly Recommended					T67C		T67M200		T67M-MkII	T67M260-T3A			SAL
058	Fairey Undercarriage Inspection	1	20/06/1994	Recommended				T67C	T67C3				T67M-MkII	T67M260-T3A	Post Mod 468		SAL
059	<b>NOT ISSUED</b>																
060	Isolation of Low Fuel Sensor Units	1	09/09/1994	Mandatory									T67M260-T3A			009-09-94	CAA
061	Fuel System Maintenance	1	02/11/1994	Highly Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M156			SAL
062	Flap Lever Proof Test	1	29/11/1994	Mandatory									T67M260-T3A			005-11-94	CAA
063	Inspection of Fuel System Joints	1	25/11/1994	Recommended									T67M260-T3A				SAL
064	Inspection of Elevator Bearing Plate	1	25/11/1994	Mandatory									T67M260-T3A			006-11-94	CAA
065	Nose Landing Gear Inspection and Modification	1	01/12/1994	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	All T67 Post Mod M468		001-12-94	CAA
066	<b>NOT ISSUED</b>																
067	Inspection of Landing/Taxi Light Supply Cable Routing	1	02/02/1995	Recommended	T67A	T67B	T67C		T67M			T67M-MkII		Not Including Works No.1999			SAL
068	Canopy Latch Correct Operation Inspection	1	31/03/1995	Highly Recommended				T67C	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129 (Split Canopy)			SAL
068	Canopy Latch Correct Operation Inspection	2	26/11/1995	Highly Recommended				T67C	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129 (Split Canopy)			SAL
068	Canopy Latch Correct Operation Inspection	3	20/06/1996	Highly Recommended				T67C	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129 (Split Canopy)			SAL
068	Canopy Latch Correct Operation Inspection	4	27/09/1997	Highly Recommended				T67C	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129/M129B (Split Canopy)			SAL
068	Canopy Latch Correct Operation Inspection	5	17/07/1998	Highly Recommended				T67C	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129/M129B (Split Canopy)			SAL
069	Inspection of Electric Trim Switch Holder	1	02/02/1995	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M443			SAL
070	Inspection of Manifold/Pressure Gauge to Pipe Connections	1	27/03/1995	Mandatory					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			012-03-95	CAA
071	Inspection of Rudder Pedal Layshaft Mounting Brackets	1	02/02/1995	Highly Recommended									T67M260-T3A				SAL
071	Inspection of Rudder Pedal Layshaft Mounting Brackets	2	12/08/1996	Highly Recommended							T67M260		T67M260-T3A	T67M260 Pre Mod M720			SAL
072	Inspection of Thermostatic Bypass Valves	1	03/02/1995	Mandatory									T67M260-T3A				SAL
072	Inspection of Thermostatic Bypass Valves	2	09/02/1995	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL
073	Inspection of Left, Right and Tail Navigation Light Lens Gaskets	1	08/03/1995	Highly Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL
074	Inspection of Routing of Upper Spark Plug Leads	1	08/03/1995	Highly Recommended							T67M260		T67M260-T3A				SAL
074	Inspection of Routing of Upper Spark Plug Leads	2	31/03/1995	Highly Recommended							T67M260		T67M260-T3A				SAL
075	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	1	08/03/1995	Highly Recommended							T67M260		T67M260-T3A				SAL
075	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	2	06/04/1995	Highly Recommended							T67M260		T67M260-T3A				SAL
075	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	3	02/06/1995	Highly Recommended							T67M260		T67M260-T3A				SAL
075	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	4	02/10/2002	Highly Recommended							T67M260		T67M260-T3A	T67M260 Works Nos 2072, 2234 to 2260 & T67M260-T3A Works Nos. 2109, 2110, 2123 to 2133			SAL
076	Inspection of Wiring Looms in Centre Console and at Wing Main Spar	1	09/03/1995	Recommended									T67M260-T3A				SAL
077	Inspection of Oil Cooler Duct to Engine Mounting Frame Clearance	1	08/03/1995	Recommended									T67M260-T3A	Pre Mod M628			SAL
078	Inspection of Rudder Cables and their Fairlead Pulleys	1	27/03/1995	Recommended				T67C			T67M260	T67M-MkII	T67M260-T3A	Post Mods M419 & M456			SAL
078	Inspection of Rudder Cables and their Fairlead Pulleys	2	30/06/1995	Recommended				T67C			T67M260	T67M-MkII	T67M260-T3A	Post Mods M419 & M456			SAL
078	Inspection of Rudder Cables and their Fairlead Pulleys	3	20/06/1996	Recommended				T67C			T67M260	T67M-MkII	T67M260-T3A	Post Mods M419 & M456 & Pre Mod M670			SAL
079	Inspection of Control Column to Seat Clearance and Seat Attachment Integrity	1	31/03/1995	Mandatory				T67C			T67M260	T67M-MkII	T67M260-T3A	Post Mod M445		008-04-95	CAA
079	Inspection of Control Column to Seat Clearance and Seat Attachment Integrity	2	04/04/1996	Mandatory				T67C	T67M		T67M260	T67M-MkII	T67M260-T3A	T67M Works No.2004 Post Mod M401A, T67C, T67M-MkII (Post Mod M445)		008-04-95	CAA
080	Inspection of Trim Cable Protective Sleeves	1*	05/07/1996	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A		<b>NO COPY AT MARSHALL ADG</b>		SAL
080	Inspection of Trim Cable Protective Sleeves	2	15/01/1997	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL
081	Inspection and Replacement of Aluminium Hinge Injector Air Intake Duct Auxiliary Intake Door	1	05/07/1996	Highly Recommended									T67M260-T3A				SAL
082	Inspection of Wing Walkway Areas	1*	18/07/1995	Mandatory		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII			<b>NO COPY AT MARSHALL ADG</b>	009-07-95	CAA
082	Inspection of Wing Walkway Areas	2	20/01/2000	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260 Works Nos 2234 & 2235 only		009-07-95	CAA
082	Inspection of Wing Walkway Areas	3	01/07/2006	Airworthiness Directive		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A prior to works number 2265. Not applicable Post Mod M827C repaired aircraft.		009-07-95	CAA
082	Inspection of Wing Walkway Areas	4	15/12/2006	Airworthiness Directive		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A prior to works number 2265. Not applicable Post Mod M827C repaired aircraft.		009-07-95	CAA
083	Inspection for Foul Between No.2 Rudder Pedal Pad Pivot and Nosewheel Steering Rod Arm	1	16/02/1996	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Not Works No.1999		006-02-96	CAA
083	Inspection for Foul Between No.2 Rudder Pedal Pad Pivot and Nosewheel Steering Rod Arm	2	06/03/1996	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Not Works No.1999		006-02-96	CAA
084	Inspection of Rib 2 Lower Flange Bond to Wing Skin	1	27/07/1995	Mandatory							T67M260		T67M260-T3A			010-07-95	CAA
084	Inspection of Rib 2 Lower Flange Bond to Wing Skin	2	09/03/1999	Mandatory									T67M260-T3A	T67M260-T3A Serial/Works Nos.2153/92-0657, 2154/92-0658, 2171/93-0567, 2109/92-0625, 2132/92-0636, 2137/92-0641, 2138/92-0642.		010-07-95	CAA
085	Inspection for Axle Burrs and Revised Mainwheel Torque Instructions	1	27/07/1995	Recommended		T67B	T67C	T67C3		T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M200 - All Post Mod M468 - Fairey Hydraulics Undercarriage			SAL
085	Inspection for Axle Burrs and Revised Mainwheel Torque Instructions	2	10/07/1997	Recommended		T67B	T67C	T67C3		T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M200 - All Post Mod M468 - Fairey Hydraulics Undercarriage			SAL
086	Inspection of Fuselage Drain Holes	1	05/07/1996	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL
087	Reduced Structural Temperature Limitation from 55°C to 50°C and Prohibited Flight Temperature Limitation from 65°C to 55°C	1	31/08/1995	Mandatory							T67M260		T67M260-T3A			002-09-95	CAA
087	Reduced Structural Temperature Limitation from 55°C to 50°C and Prohibited Flight Temperature Limitation from 65°C to 55°C	2	20/09/1995	Mandatory							T67M260		T67M260-T3A			002-09-95	CAA
088	Rudder Pedal to Mixture Lever Potential Foul	1	29/08/1996	Mandatory							T67M260		T67M260-T3A	Pre Mod M687 standard		007-08-95	CAA
088	Rudder Pedal to Mixture Lever Potential Foul	2	02/10/1996	Mandatory							T67M260		T67M260-T3A	Pre Mod M687 standard		007-08-95	CAA
089	Additional Aileron Trim Tab Requirement	1	01/02/1996	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL
090	Installation of an Air Intake Flow Divider to Eliminate Vibration & Noise in the Air Conditioning Condenser	1	16/02/1996	Recommended							T67M260		T67M260-T3A	T67M260 & T67M260-T3A with air con installed (Post Mod M501A)			SAL
091	Inspection of Torque Link Mounting Lugs SAB Nose Wheel Leg	1	18/04/1996	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		All Pre Mod M468, ie SAB undercarriage aircraft			SAL
092	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, plus Vent Pipe Inlet Re-Orientation	1	01/02/1996	Highly Recommended									T67M260-T3A	Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233			SAL

092	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, plus Vent Pipe Inlet Re-Orientation	2	18/02/2005	Highly Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233 Actions 1, 2.1 & 3 -T67C wing tank (Post Mod M156) only, T67M-MkII, T67M200 & T67M260 action 2.2			SAL	
092	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, plus Vent Pipe Inlet Re-Orientation	3	04/09/2007	Highly Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233 Actions 1, 2.1 & 3 -T67C wing tank (Post Mod M156) only, T67M-MkII, T67M200 & T67M260 action 2.2			SACL	
093	Inspection and Identification of Alternator Capacitor	1	05/07/1996	Highly Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
094	Inspection of Elevator Pushrod to Control Column Assembly Pivot Bolt to Seat Clearance	1	05/07/1996	Mandatory									T67M260-T3A	Pre Mod M695		007-07-96	CAA	
095	Inspection of Throttle Cable Mounting Bracket	1	18/04/1996	Recommended					T67M			T67M-MkII					SAL	
096	Inspection and Replacement of Trim Wheel Thrust Washers	1	01/10/1996	Recommended			T67C				T67M260		T67M260-T3A	T67C Post Mod M443			SAL	
097	Inspection of Engine Wiring for Chafing	1	18/04/1996	Highly Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
098	Inspection and Rectification of Air Conditioning Compressor Alignment	1	29/02/1996	Recommended									T67M260-T3A	Work Nos 2109, 2110, 2123 to 2158			SAL	
098	Inspection and Rectification of Air Conditioning Compressor Alignment	2	04/04/1996	Recommended									T67M260-T3A	Work Nos 2109, 2110, 2123 to 2148			SAL	
099	Inspection and Rectification of Rudder Pedal Sliders	1	05/07/1996	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M -Not Works No.1999			SAL	
099	Inspection and Rectification of Rudder Pedal Sliders	2	12/05/1999	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M -Not Works No.1999			SAL	
099	Inspection and Rectification of Rudder Pedal Sliders	3	24/06/1997	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M -Not Works No.1999			SAL	
099	Inspection and Rectification of Rudder Pedal Sliders	4	27/09/1997	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M -Not Works No.1999			SAL	
100	Water Ingress into Cockpit from ECS Frame 2 Bay	1	06/03/1996	Highly Recommended									T67M260-T3A	Post Mod M501A			SAL	
100	Water Ingress into Cockpit from ECS Frame 2 Bay	2	18/04/1996	Highly Recommended									T67M260-T3A	T67M260-T3A Post Mod M501A,Pre Mod 680B			SAL	
101	Inspection and Replacement of Flap Torque Tube Bearing at Rib 2	1	18/04/1996	Recommended		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		T67M-MkII -Pre Mod M519			SAL	
102	Inspection of and Wiring of Roll Pin on Fuel Selector Torque Tube	1	29/02/1996	Mandatory							T67M260		T67M260-T3A			007-02-96	CAA	
103	Inspection of Outboard Elevator Hinge Pivot Bush	1	24/06/1998	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
104	Inspection of Bonding Braid from Flap Torque Tube Pivot to Aft Seat Mounting Tube Lower Bolt	1	11/09/998	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A Pre Mod M721			SAL	
105	Inspection of Control Surfaces for Rubbing Marks	1	10/01/1997	Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
106	Inspection of Brake Cylinder for Correct Stroke	1	30/04/1996	Mandatory							T67M260		T67M260-T3A			005-04-96	CAA	
107	Inspection of Pilots Mixture Lever	1	13/02/1998	Highly Recommended							T67M260		T67M260-T3A				SAL	
108	Maintenance of Oil crossover Valve for Correct Operation	1	19/12/1996	Recommended					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
109	Inspection of Brake Caliper Bolts	1	29/08/1996	Recommended									T67M260-T3A				SAL	
110	Inspection and Re-Routing of Air Conditioning Wiring	1	11/09/1998	Recommended							T67M260		T67M260-T3A	Post Mod M501			SAL	
111	Fuel Servo Idle Mixture Setting	1	16/09/1996	Highly Recommended							T67M260		T67M260-T3A	All T67 a/c equipped with Lycoming RSA-5-AB1 fuel injection systems			SAL	
112	Colour Scheme Approval	1	27/08/1996	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
113	Inspection of SAB Nose Leg Scissor Pivot	1	10/01/1997	Essential		T67B	T67C		T67M	T67M200		T67M-MkII		Pre Mod M468			SAL	
114	Inspection of King KT76A Transponders	1	23/09/1996	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	All T67 Series A/C fitted with KT76A ATC Transponders			SAL	
115	Inspection of Left Hand Pilots Throttle Pushrod	1	02/10/1996	Highly Recommended							T67M260		T67M260-T3A				SAL	
116	Lycoming SB No.527B Recall of Piston Pin - Part No. LW-14077	1	14/01/1997	Essential			T67C	T67C3		T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
117	Inspection of Elevator Electric Trim Motor Wire Routing	1	27/09/1997	Highly Recommended			T67C				T67M260		T67M260-T3A	T67C Post Mod M443 (Electric Trim), T67M260 Except Works No 2072			SAL	
118	Inspection of Fuel Servo Throttle and Mixture Lever Extensions for Movement and Wear	1	09/04/1999	Highly Recommended							T67M260		T67M260-T3A				SAL	
119	Lycoming S.B. No.525A Inspection of High Pressure Fuel Pump P/N LW-15473	1	06/11/1996	Mandatory					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			FAA Priority Letter - AD96-23-03	SAL	
120	Inspection of Rudder Bar Support Brackets	1*	10/01/1997	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Works No.1999 not applicable		NO COPY AT MARSHALL ADG	012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	2	31/01/1997	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Works No.1999 not applicable			012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	3	12/05/1997	Mandatory		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Works No.1999 not applicable			012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	4	22/01/2009	Airworthiness Directive		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Works No.1999 not applicable			EASA AD 2009-0013	CAA/EASA
121	Inspection of SAB Type Nose Undercarriage Leg	1	17/03/1997	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M425 & Pre Mod M468 a/c ie SAB Type Undercarriaged			010-03-097	CAA
122	Dry Air Pump Coupling Service Life Limitation	1	27/04/1997	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
123	Lycoming Service Bulletin/Instruction/Letter Listings	1	24/06/1997	Essential							T67M260		T67M260-T3A				SAL	
124	Not Used																	
125	Inspection of Wiring Looms at Rear of Instrument Panel for Chafing	1	27/09/1997	Essential	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
125	Inspection of Wiring Looms at Rear of Instrument Panel for Chafing	2	02/10/2002	Essential	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
126	Inspection of Port Rudder Bar for Chafing	1	27/09/1997	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
126	Inspection of Port Rudder Bar for Chafing	2	13/03/1998	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	1	17/07/1997	Mandatory	T67A	T67B			T67M								005-07-97	CAA
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	2	19/12/2003	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				005-07-97	CAA
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	3	10/07/2004	Airworthiness Directive	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				G-2004-0013/EASA AD 2004-6425	EASA
128	Inspection of Placard Reading "This Aircraft is Certified VFR IFR Day or Night"	1	16/04/1997	Essential									T67M260-T3A				SAL	
129	Hoffmann SB 61-11-03 E9 Inspection for Wear and Leakage on Spacer	1	12/05/1997	Recommended						T67M200	T67M260						SAL	
129	Hoffmann SB 61-11-03 E9A Inspection for Wear and Leakage on Spacer	2	17/09/1997	Recommended						T67M200	T67M260						SAL	
130	Inspection of Rudder Pedals for Adjustment Restriction	1	12/07/1997	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Excluding Works No.1999			SAL	
130	Inspection of Rudder Pedals for Adjustment Restriction	2	12/03/1999	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M - Excluding Works No.1999			SAL	
131	Inspection for Centre Console Fixing Screw Fouling Electric Trim System	1	27/09/1997	Highly Recommended							T67M260		T67M260-T3A	T67M260 - Not Works No.2072, T67C - Post Mod M443 (Electric Trim)			SAL	
131	Inspection for Centre Console Fixing Screw Fouling Electric Trim System	2	20/05/1998	Highly Recommended			T67C				T67M260		T67M260-T3A	T67M260 - Not Works No.2072, T67C - Post Mod M443 (Electric Trim)			SAL	
132	Inspection for Water in Bump Stop	1	12/09/1997	Mandatory						T67M200	T67M260			T67M200 - Post Mod M675			002-09-97	CAA
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	1	27/09/1997	Essential	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	2	13/03/1998	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	3	01/07/2006	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260 - Post Mod M950 Electric Flapped aircraft			SAL	
134	Woodward Service Bulletin Listing	1	27/08/1997	Essential							T67M260						SAL	
135	Hoffmann Service Bulletin/Letter Listing	1	27/08/1997	Essential							T67M260						SAL	
136	Fairey Hydraulic Service Bulletin Listing	1	27/08/1997	Essential							T67M260						SAL	
137	Bendix King Service Bulletin Listing	1	27/08/1997	Essential							T67M260						SAL	
138	Inspection of ECS Frame 2 Bay for Corrosion	1	12/09/1997	Essential							T67M260		T67M260-T3A	T67M260-T3A Post Mod M501A			SAL	
139	Inspection of Steering Arm on Fairey Hydraulics Nose Leg	1	12/09/1997	Mandatory			T67C				T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M468, T67M-MkII Post Mod M468 & M791			003-09-97	CAA
139	Inspection of Steering Arm on Fairey Hydraulics Nose Leg	2	20/10/2000	Mandatory			T67C				T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M468, T67M-MkII Post Mod M468 & M791			003-09-97	CAA
140	Lycoming SB No.505A Inspection of Crankshaft ID for Corrosion	Cancelled																
141	Recommended Stiffnut Maintenance Procedures and Clarification of Existing Maintenance Manual Screw/Bolt Torque Values	1	25/02/2000	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
142	Inspection for Correct Elevator Trim Tab Indication	1	27/08/1997	Recommended														



143	Fairey Hydraulics Main Undercarriage Backlash Check	2	09/03/1999	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Post Mod M468			SAL	
144	Trim Tab Drive Pin Check	1	12/02/1998	Essential							T67M260		T67M260-T3A				SAL	
145	Inspection and Replacement of Centring Roller Retaining Rivet with Pin	1	17/07/1998	Highly Recommended			T67C				T67M260	T67M-MkII	T67M260-T3A	Post Mod M468 & M791			SAL	
146	Not Used																	
147	SAB Undercarriage Nosewheel Steering Adaptor Inspection	1	24/09/1998	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M468			SAL	
148	Not Used																	
149	Not Used																	
150	Inspection of Elevator Lever Pivot Stiffnut at Frame 7	1	09/12/1997	Mandatory	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			002-12-97	CAA	
151	Inspection of Canopy Slide Lock Spring Dimensions	1	25/06/1998	Highly Recommended						T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M283			SAL	
152	Airborne ILS (Localiser) VOR and VHF Communications - Improved FM Broadcast Interference Immunity Standards/Placarding	1	12/02/1998	Essential	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M-MkII T67M200 T67M260 and T67M260-T3A operating within Europe, Africa, Russia or the Middle East.			SAL	
152	Airborne ILS (Localiser) VOR and VHF Communications - Improved FM Broadcast Interference Immunity Standards/Placarding	2	01/08/2002	Essential	T67A	T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M-MkII T67M200 T67M260 and T67M260-T3A operating within Europe, Africa, Russia or the Middle East.			SAL	
153	SAB Undercarriage Nosewheel Fork Inspection	1	24/09/1998	Recommended		T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M468, M791, Post Mod M136A			SAL	
153	SAB Undercarriage Nosewheel Fork Inspection	2	30/04/2003	Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M468, M791, Post Mod M136A			SAL	
154	Inspection for Clearance Between SAB Undercarriage Noseleg Steering Pushrod and Engine Mounting Frame	1	21/08/1998	Highly Recommended	T67A	T67B	T67C	T67C3	T67M	T67M200		T67M-MkII		Pre Mod M468 and M791			SAL	
155	Inspection for Foul Between Canopy Slide Rail Pivot Bolt and Fuselage Splash Shields	1	21/08/1998	Highly Recommended			T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129			SAL	
156	Inspection for Engine/Propeller Control Foul with Forward Console	1	21/08/1998	Recommended							T67M260		T67M260-T3A				SAL	
157	Five Year Fuel Tank Inspection	1	25/06/1998	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Pre & Post Mod M945			SAL	
157	Five Year Fuel Tank Inspection	2	04/02/2000	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Pre & Post Mod M945			SAL	
157	Five Year Fuel Tank Inspection	3	19/03/2001	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Pre & Post Mod M945			SAL	
157	Five Year Fuel Tank Inspection	4	15/04/2005	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Pre & Post Mod M945			SAL	
157	Five Year Fuel Tank Inspection	5	26/01/2007	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Pre & Post Mod M945			SAL	
157	Five Year Fuel Tank Inspection	6	27/06/2012			T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Pre & Post Mod M945			MA	
157	Five Year Fuel Tank Inspection	7	01/12/2015			T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII		Pre & Post Mod M945			MA	
158	Inspection of Rudder for Ceconite Fabric Debonding	1	25/06/1998	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
159	Inspection of Stainless Steel Brake Pipes for Correct Bonding	1	20/01/2000	Highly Recommended		T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-, T67M260-T3A plus Post Mod M585			SAL	
160	Inspection of Lower Undercarriage Mounting Blocks for Water Ingress	1	13/04/1999	Essential		T67B	T67C		T67M	T67M200		T67M-MkII					SAL	
161	Fuel Tank Vent Pipe Check	1	29/10/1999	Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M156			SAL	
161	Fuel Tank Vent Pipe Check	2	23/03/2001	Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M156			SAL	
162	Inspection of Pitot Tube Inlet Pipe	1	27/08/1999	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
162	Inspection of Pitot Tube Inlet Pipe and Lightning Conductor for Cracking	2	23/03/2001	Essential		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
163	Inspection of Fuel Valve Torque Shaft Universals	1	11/10/1999	Highly Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M156, T67M260-T3A Pre Mod M830			SAL	
163	Inspection of Fuel Valve Torque Shaft Universals	2	26/02/2008	Highly Recommended			T67C			T67M200	T67M260	T67M-MkII	T67M260-T3A	T67C Post Mod M156, T67M260-T3A Pre Mod M830, T67M260 Pre Mod M945. Not applicable to works numbers 2267 thru to 2284			SACL	
164	Hoffmann Service Letter 61-12-04 SL E4B Introduction of Leading Edge Erosion Film	1	08/12/1999	Recommended					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
165	Inspection for Water in Leading Edge of Rudder Plus Addition of Drain Hole	1	20/01/2000	Essential		T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
165	Inspection for Water in Leading Edge of Rudder Plus Addition of Drain Hole	2	28/03/2001	Mandatory		T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			005-03-2001	CAA	
166	Hoffmann 61-10-03 SB E1W Listing TBO of Hoffmann Variable Pitch Propellers	1	08/12/1999	Recommended					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
166	Hoffmann 61-10-03 SB E1W Listing TBO of Hoffmann Variable Pitch Propellers	2	06/06/2003	Recommended					T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
167	Inspection of External Aileron and Flap Drive Pushrod for Cracking	1	01/08/2000	Essential	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
168	Inspection of Cockpit Floor Beneath Port Rudder Bar Support Bracket	1	19/09/2000	Recommended		T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
169	Inspection of Engine Air Intake Duct Mesh and Alternate Air Door	1	27/07/2000	Essential					T67M			T67M-MkII					SAL	
169	Inspection of Engine Air Intake Duct Mesh and Alternate Air Door	2	18/02/2005	Essential					T67M			T67M-MkII	T67M260-T3A	Part A - Post Mod M595: Pre & Post Mod M760 T67M, T67M-MkII. Part B - Pre Mod M818, M830 & Post Mod M696 T67M260 & T3A - N/A to Works No 2261, 2266 & Subsequent			SAL	
170	Inspection of Control Column Aileron Stop Bolt, Mounting Plate and Rivnut	1	28/03/2001	Highly Recommended	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
171	Inspection of Main Undercarriage Top Mounting Collars	1	28/03/2001	Highly Recommended						T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M-MkII Post Mod M835, T67M200 Post Mod M914			SAL	
172	Inspection of Flap Drive Torque Tube	1	28/03/2001	Highly Recommended	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				SAL	
172	Inspection of Flap Drive Torque Tube	2	22/08/2002	Highly Recommended	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260 Pre Mod M950			SAL	
172	Inspection of Flap Drive Torque Tube	3	23/12/2003	Highly Recommended	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260 Pre Mod M950			SAL	
173	Canopy Latch Assembly Covers	1	15/05/2001	Highly Recommended			T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Post Mod M129			SAL	
174	Hoffmann 61-11-03 E13 Propeller Pitch Change Mechanism Screw Modification	1	27/06/2001	Essential						T67M200	T67M260		T67M260-T3A				SAL	
175	Inspection of Control Column Housing Brazing	1	11/07/2002	Mandatory	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			005-07-2002	CAA	
176	Inspection for Fitment of Correct Stiffnut on Nosewheel Axle	1	09/07/2002	Essential			T67C				T67M260	T67M-MkII	T67M260-T3A	Post Mod M468, M791			SAL	
177	Inspection of Starter and Ground Power Socket Solenoids for Cracking - Frame 5 Avionics Panel Mounted	1	02/10/2002	Essential						T67M200	T67M260			Post Mod M860 (2261 to 2264, 2266 & 2267)			SAL	
178	Lycoming SB No. 554 Crankshaft Gear Retaining Bolt Replacement	1	27/11/2002	Mandatory							T67M260		T67M260-T3A				SAL	
178	Lycoming SB No. 554 Crankshaft Gear Retaining Bolt Replacement	2	23/12/2003	Highly Recommended							T67M260		T67M260-T3A				SAL	
179	Inspection of Tailplane Attachment Brackets	1	10/12/2002	Mandatory	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A All const nos except 2266 and subsequent		001-12-2002	CAA	
179	Inspection of Tailplane Attachment Brackets	2	11/04/2003	Mandatory	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	T67M260-T3A All const nos except 2266 and subsequent		001-12-2002	CAA	
179	Inspection of Tailplane Attachment Brackets	3	20/01/2005	Airworthiness Directive	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				G-2005-0004/EASA AD 2005-564	CAA
179	Inspection of Tailplane Attachment Brackets	4	15/03/2007	Airworthiness Directive	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A				G-2005-0004/EASA AD 2005-564/ EASA AD.2012-0169	CAA
180	Inspection of Alternator/Starter Wiring Loom P-Clipping at Engine	1	30/04/2003	Mandatory	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A			005-04-2003	CAA	
181	Airborne Service Letters	1	12/08/2003	Highly Recommended	T67A	T67B	T67C		T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A					SAL
182	Not Used																	
183	Inspection of Tailplane Aluminium Fittings for Exfoliation Corrosion	1	06/10/2005	Airworthiness Directive	T67A												G-2005-0032/EASA AD 2005-6366	CAA
184	Inspection and Wire locking of Fwd Quadrant Engine Control Spindle CV Tension Pin	1	31/07/2006	Highly Recommended						T67M200	T67M260		T67M260-T3A	Post Mod M915			SACL	
185	Inspection for and Prevention of Water into NACA Air Intake	1	05/09/2007	Highly Recommended						T67M200	T67M260		T67M260-T3A	Post Mod M915, M566			SACL	
186	Inspection of Rudder Navigation Light Wiring for Chaffing	1	05/09/2007	Highly Recommended						T67M200	T67M260			Post Mod M915, Pre Mod M950			SACL	
186	Inspection of Rudder Navigation Light Wiring for Chaffing	2	28/05/2008	Highly Recommended		T67B	T67C	T67C3	T67M	T67M200	T67M260	T67M-MkII	T67M260-T3A	Pre Mod M915, M1025A & M1025B. Not applicable Post Mod M950 Works No.2266 to 2281			SACL	
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	1	09/03/2007	Airworthiness Directive						T67M200	T67M260			T67M200 -Works Nos. 2264 and 2265 only		EASA AD 2007-0132	CAA	
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	2	10/05/2007	Airworthiness Directive						T67M200	T67M260		T67M260-T3A	T67M200 -Works Nos. 2264 and 2265 only		EASA AD 2007-0132	CAA	

187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	3	16/10/2007	Airworthiness Directive						T67M200	T67M260		T67M260-T3A	T67M200 -Works Nos. 2264 and 2265 only	EASA AD 2007-0132	CAA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	4	22/01/2009	Airworthiness Directive						T67M200	T67M260		T67M260-T3A	T67M200 -Works Nos. 2264 and 2265 only	EASA AD 2009-0013	CAA/EASA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	5	14/10/2009	Airworthiness Directive						T67M200	T67M260		T67M260-T3A	T67M200 -Works Nos. 2264 and 2265 only	EASA AD 2009-0218	CAA/EASA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket and for Ground Towing Damage. Also includes General Rudder Pedal Clearances	6	20/12/2012	Airworthiness Directive						T67M200	T67M260		T67M260-T3A	T67M200 -Works Nos. 2264 and 2265 only	EASA AD 2009-0218	CAA/EASA
188	Inspection for Rudder Pedal Clearances between Rudder Pedals and the Aircraft Structure and Components	1	09/03/2007	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M200 Excluding Works No. 2264 and 2265	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	2	10/05/2007	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M Excluding Works No. 1999, T67M200 Excluding Works No. 2264 and 2265	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	3	16/10/2007	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M Excluding Works No. 1999, T67M200 Excluding Works No. 2264 and 2265	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	4	22/01/2009	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M Excluding Works No. 1999, T67M200 Excluding Works No. 2264 and 2265	EASA AD 2009-0013	CAA/EASA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	5	10/10/2009	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M Excluding Works No. 1999, T67M200 Excluding Works No. 2264 and 2265	EASA AD 2009-0218	CAA/EASA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components also Inspection for Ground Towing Damage	6	20/12/2012	Airworthiness Directive	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII		T67M Excluding Works No. 1999, T67M200 Excluding Works No. 2264 and 2265	EASA AD 2009-0218	CAA/EASA
189	Inspection of Tailplane Attachment Bolt Thread Diameter	1	19/08/2008	Highly Recommended	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII	T67M260-T3A	with Slingsby Bolt Batches G208350 and/or G208351 Installed		SACL
190	Inspection of SAB Nose Undercarriage Torque Links for Cracks	1	05/10/2012		T67A	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII	T67A - Pre Mod M468 & M791 Aircraft only		MA
191	Inspection of Integrity of Frame 6 and 7 Joint Bonding	1	03/10/2002			T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII			MA
192	Inspection for Integrity Bonding of the Jacking Point	1	02/10/2002		T67A	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII			MA
193	Inspection of Slingsby T67 Firefly Aircraft for Fitting of Undercut Bolts	1	01/04/2013		T67A	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII			MA
194	Inspection of SAB T9S Main Undercarriage Legs for Cracks in Wing Mounting Portion	1	03/12/2011	Airworthiness Directive	T67A	T67B	T67C	T67C3	T67M		T67M200		T67M-MkII	T67A Post Mod M136B & T67M200 all Pre Mod M468	2011-0240	CAA/EASA
195	Introduction of Slingsby T67M260 Firefly Aircraft Air Conditioning Compressor Mounting Bracket for Cracks	1	05/10/2012								T67M260			Post Mod 501 Works No. 2234, 2235, 2266, 2268-2274, 2276, 2277, 2279-2284		MA
196	Inspection of Slingsby T67 Firefly Propeller Spinner Support Disc for Rubber Condition	1	10/10/2012						T67M	T67M200	T67M260	T67M-MkII				MA
196	Inspection of Slingsby T67 Firefly Propeller Spinner Support Disc for Rubber Condition	2	01/01/2013						T67M	T67M200	T67M260	T67M-MkII				MA
197	Introduction of Modification Kit T67A-05-1992 (MA1992)	1	01/12/2014			T67B	T67C		T67M	T67M200	T67M260	T67M-MkII		Excluding T67M Construction No.1999		
198	Inspection of Post Mod M501 T67M260 Firefly Rudder Pedal Cables for Fouling and Air Conditioning Hoses for Damage	1	01/09/2013								T67M260			Post Mod M501		MA
199	Promulgation of Lycoming SB No. 530B and Supplement No. 1 - Application of Protective Coating on Crankshaft	Cancelled														
200	Brake Master Cylinder Pivot Pin Examination	Initial	01/03/2015	Essential	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII				MA
200	Brake Master Cylinder Pivot Pin Examination	1	01/04/2015	Essential	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII				MA
200	Brake Master Cylinder Pivot Pin Examination	2	01/12/2015	Essential	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII				MA
200	Brake Master Cylinder Pivot Pin Examination	3	01/03/2017	Essential	T67B	T67C	T67C3	T67M		T67M200	T67M260	T67M-MkII				MA
201	Modification Bulletin M644A - Introduction of Improved Wheel Brake System - Production	Initial	20/01/2016								T67M260			Refer to Modification Bulletin M644A		MA
202	Modification MA2458 - Additional Securing of Nose Landing Gear Axle Bolt	Initial	16/07/2017		T67B	T67C	T67C3	T67M		T67M200		T67M-MkII				