



List of ETSO Authorisations

This report provides the list of ETSO Authorisation issued by EASA. It is updated on a monthly basis and is sorted by the name of the approval holder/manufacturer.

The columns of the report contain the following information:

1. Approval Number
2. Date of last Issue of the ETSOA
3. Description/Name of the Equipment
4. Partnumber(s) covered by the ETSOA
5. ETSO Standard(s)
6. DDP reference

For records added within the last month (31 days prior to the last update) the columns for **Approval Number, Date of last Issue and Description** are displayed in inverted color, to ease the identification of updates in the list.

Last update: 01/12/2015

| Approval Holder | Approval Number | Date of last Issue | Description |
|------------------------------|-------------------------------|---------------------------|--|
| ADVANCED COMPOSITE STRUCT | EASA.IM.210.052, REV. B | 11/11/2015 | AKE-3XX // Air Cargo Unit Load Device |
| | EASA.IM.210.1155, REV. A | 11/11/2015 | AKE-4SC // Air Cargo Unit Load Device |
| | EASA.IM.210.156, REV. B | 11/11/2015 | AKE-1 // Air Cargo Unit Load Device |
| | EASA.IM.210.207, REV. B | 11/11/2015 | AKE-2XX // Air Cargo Unit Load Device |
| Approval Holder | Approval Number | Date of last Issue | Description |
| AMSAFE, Inc. | EASA.IM.210.10055619 | 23/11/2015 | Inflatable Restraint System Assembly |
| Approval Holder | Approval Number | Date of last Issue | Description |
| B/E AEROSPACE, Inc. | EASA.IM.210.10042055, REV. B | 10/11/2015 | TYPE A / BE16.2-()-() // Forward Facing Seats |
| | EASA.IM.210.10049868, REV. D | 02/11/2015 | Model No. BE14.1-()-() Diamond Forward Facing Seats |
| | EASA.IM.210.10055639 | 25/11/2015 | One Place Side Facing Divan |
| | ETSOA.IM.210.10054287, REV. A | 02/11/2015 | TYPE A / BE17.2-()-() // Side Facing Seats |
| Approval Holder | Approval Number | Date of last Issue | Description |
| ESTERLINE BELGIUM | ETSOA.210.10055459 | 13/11/2015 | DU-885AF |
| Approval Holder | Approval Number | Date of last Issue | Description |
| GARMIN INTERNATIONAL, Inc. | EASA.IM.210.10055357 | 04/11/2015 | GTX 330 / GTX 330D // Mode S Transponder with Extended |
| | EASA.IM.210.10055433 | 09/11/2015 | GTX 33 / GTX 33D // Mode S Transponder with Extended |
| Approval Holder | Approval Number | Date of last Issue | Description |
| KID-SYSTEME GmbH | EASA.210.10055498 | 13/11/2015 | On Board Control Equipment Worldwide (OBCE-WW) |
| Approval Holder | Approval Number | Date of last Issue | Description |
| RECARO AIRCRAFT SEATING Gm | EASA.210.10054881, REV. A | 06/11/2015 | 3530A // Economy Class Passenger Seat Assembly, Forw |
| Approval Holder | Approval Number | Date of last Issue | Description |
| ROCKWELL COLLINS, Inc. | EASA.IM.210.10040261, REV. A | 10/11/2015 | TSS-4100 and TSSA-4100 Traffic Surveillance Processing |
| Approval Holder | Approval Number | Date of last Issue | Description |
| VIKING LIFE-SAVING EQUIPMENT | EASA.210.10055419 | 06/11/2015 | PS5040 VIKING HELICOPTER TRANSPORTATION SUIT |
| Approval Holder | Approval Number | Date of last Issue | Description |
| ZODIAC AIRCATERING EQUIPMEN | EASA.210.10055404 | 06/11/2015 | BG08I SERIES // Container |
| | EASA.210.10055405 | 06/11/2015 | TK615-SERIES TROLLEY // Hybrite Trolley Full Size |
| | EASA.210.10055461 | 11/11/2015 | TL614-SERIES TROLLEY // Hybrite Trolley Half Size |
| Approval Holder | Approval Number | Date of last Issue | Description |
| ZODIAC SEATS US L.L.C. | EASA.IM.210.10034772, REV.G | 23/11/2015 | MODEL 5751 // T/C Passenger Seat |

2 EXCEL DESIGN LIMITED - 72 FIELDING ROAD W4 1DB LONDON UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|---------------|------------------|-----------------|
| EASA.210.10048348 | 05/03/2014 | F20/23XLM Extra Low Maintenance Ni-Cd Battery | 4575126-() | C173 | JN381-ADC13 (4) |

AAR MANUFACTURING Inc. - 1100 N. WOOD DALE ROAD 60191 WOOD DALE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--------------------------|------------------|------------------|
| EASA.IM.210.800 | 17/10/2007 | AKE Structural/ Lower Deck Cargo Container | 3DC-A27-8K-507 | C90c | 1000 |
| EASA.IM.210.859 | 14/11/2007 | AAA Main Deck Container DCT51892 | DCT51892-3 DCT51892-5 | C90c | AAA/DDP/1001 |
| CAA.N-O.00002 | 05/08/2003 | AKE | DCT50032-() | | TIR-DDP-DCT50032 |
| CAA.N-O.00003 | 05/08/2003 | ABY | A-AB146-N28 | | TEL/DDP/052 |
| CAA.N-O.00004 | 15/08/2003 | AEP | A-AE1-N() | | TEL/DDP/054 |
| CAA.N-O.00005 | 05/08/2003 | ALP | A-A11P-N5 | | ACE/DDP/077 |
| CAA.N-O.00006 | 05/08/2003 | AKH | DCT50251-535 | | TIR-DDP-DCT50251 |

AB AIRCONTAINER A.C. - P.O. BOX 320 611 27 NYKOPING SWEDEN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--------------|---------------------|------------------|-----------------|
| EASA.210.661 | 16/09/2008 | ATC-RKN-1000 | ATC-A-1-000-002-() | C90c | ATC-A-1-950-075 |

ACK TECHNOLOGIES Inc. - 440 WEST JULIAN STREET 95110 SAN JOSE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|------------------------------------|----------------------------|-------------------------|---------------|
| EASA.IM.210.10028407 | 05/01/2010 | E-04 Emergency Locator Transmitter | E-04() E-04.0 E-04.8 | 2C91a 2C126 C142a | ACK E-04 |

ACR ELECTRONICS, Inc. - 5757 RAVENSWOOD ROAD 33312-6645 FORT LAUDERDALE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|---|---------------------|--------------------------|
| EASA.IM.210.146, REV. B | 16/05/2012 | C406-N and C406-NHM Emergency Locator Transmitter | 453-5060 453-5061 | 2C126 | 6459 |
| EASA.IM.210.147, REV. B | 16/05/2012 | G406-4 Emergency Locator Transmitter | 453-5012-() | 2C126 | 6460 |
| EASA.IM.210.416, REV. B | 16/05/2012 | ME406 Emergency Locator Transmitter | 453-6603 | 2C126 | 6461 |
| EASA.IM.210.608, REV. B | 16/05/2012 | ME406HM Emergency Locator Transmitter | 453-6604-(X) | 2C126 | 6462 |
| EASA.IM.210.743, REV. B | 21/05/2012 | ME406P Emergency Locator Transmitter | 453-6611 | 2C126 | 6463 |
| EASA.IM.210.839, REV. B | 16/05/2012 | SLB406 Emergency Locator Transmitter Type S | 453-6700 | 2C126 | 6097 |
| EASA.IM.210.10039654 | 21/05/2012 | Emergency Locator Transmitter B406-4() | 453-5004() REV () 453-650() REV () ANTENNAE 110-3()-() REV () | JTSO-2C126 Other | 6455 |
| EASA.IM.210.10039656 | 21/05/2012 | Emergency Locator Transmitter C406-1() | 453-5002() REV () 453-5003() REV () ANTENNAE 110-3()-() REV () ELT/NAV INTERFACE 453-650() REV () | JTSO-2C126 Other | 6457 |
| EASA.IM.210.10040703 | 20/07/2012 | Emergency Locator Transmitter C406-2() | 453-5000-() REV () 453-5001-() REV () ANTENNAE P/N 110-3()-() REV () | JTSO-2C126 | 6450 |
| EASA.IM.210.10050368 | 03/09/2014 | ELT-1000 | A3-06-2749 | C126a C142a | Y1-13-0138 REVISION B |

ACRO AIRCRAFT SEATING Ltd. - OLD BRIGHTON ROAD RH11 0PR CRAWLEY UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------------|---|------------------|---------------|
| EASA.210.936 | 17/01/2008 | Clark - Forward Facing Passenger Seat | 11-XX-207 11-XX-208 11-XX-209 11-XX-210 11-XX-212 11-XX-301 11-XX-302 11-XX-303 11-XX-304 11-XX-305 11-XX-306 11-XX-307 11-XX-308 11-XX-311 11-XX-312 11-XX-313 11-XX-314 11-XX-315 11-XX-316 11-XX-327 11-XX-328 | C39b | ACR-DDP-001 |

ACRO AIRCRAFT SEATING Ltd. - OLD BRIGHTON ROAD RH11 0PR CRAWLEY UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------------|--------------------|--|--|------------------|---------------|
| EASA.21O.1032 | 11/05/2009 | Clark - Forward Facing Passenger Seat | 13-XX-201 | C127a | ACR-020-DDP |
| | | | 13-XX-202 | | |
| | | | 13-XX-203 | | |
| | | | 13-XX-204 | | |
| | | | 13-XX-205 | | |
| | | | 13-XX-206 | | |
| | | | 13-XX-301 | | |
| | | | 13-XX-302 | | |
| | | | 13-XX-303 | | |
| | | | 13-XX-304 | | |
| | | | 13-XX-305 | | |
| | | | 13-XX-306 | | |
| | | | 13-XX-307 | | |
| | | | 13-XX-308 | | |
| | | | 13-XX-311 | | |
| | | | 13-XX-312 | | |
| | | | 13-XX-313 | | |
| | | | 13-XX-314 | | |
| | | | 13-XX-315 | | |
| | | | 13-XX-316 | | |
| | | | 13-XX-317 | | |
| | | | 13-XX-321 | | |
| | | | 13-XX-322 | | |
| | | | 13-XX-323 | | |
| | | | 13-XX-324 | | |
| | | | 13-XX-325 | | |
| | | | 13-XX-326 | | |
| | | | 13-XX-329 | | |
| | | | 13-XX-330 | | |
| | | | 14-XX-201 | | |
| | | | 14-XX-202 | | |
| | | | 14-XX-203 | | |
| 14-XX-204 | | | | | |
| 14-XX-205 | | | | | |
| 14-XX-206 | | | | | |
| 14-XX-301 | | | | | |
| 14-XX-302 | | | | | |
| 14-XX-303 | | | | | |
| 14-XX-304 | | | | | |
| 14-XX-305 | | | | | |
| 14-XX-306 | | | | | |
| 14-XX-307 | | | | | |
| 14-XX-308 | | | | | |
| 14-XX-315 | | | | | |
| 14-XX-316 | | | | | |
| 14-XX-321 | | | | | |
| 14-XX-322 | | | | | |
| 14-XX-327 | | | | | |
| 14-XX-328 | | | | | |
| EASA.21O.10032530, REV. A | 27/04/2015 | SUPERLIGHT R // Passenger Seat | 21-(XX)-(Y)-2(XX) 21-(XX)-(Y)-3(XX) 22-(XX)-(Y)-2(XX) 22-(XX)-(Y)-3(XX) | C39b | ACR-039-DDP |
| EASA.21O.10037147, REV. D | 10/09/2015 | SUPERLIGHT R // Passenger Seat – Economy | 31-(XX)-(YY)-2(XX) 31-(XX)-(YY)-3(XX) 32-(XX)-(YY)-2(XX) 32-(XX)-(YY)-3(XX) 33-(XX)-(YY)-2(XX) 33-(XX)-(YY)-3(XX) | C127a | ACR-053-DDP |
| EASA.21O.10050003, REV. A | 27/04/2015 | SERIES 4 // Passenger Seat | 41-(0)-(0)-1(0) 41-(0)-(0)-2(0) 42-(0)-(0)-1(0) 42-(0)-(0)-2(0) 43-(0)-(0)-1(0) 43-(0)-(0)-2(0) | C127a | ACR-119-DDP |
| ETSOA.21O.10054228, REV. A | 13/08/2015 | Series 5 Seat // Passenger Seat Economy | 5X-XX-XX-1X1 5X-XX-XX-1X3 5X-XX-XX-1X5 5X-XX-XX-1X7 5X-XX-XX-2X2 5X-XX-XX-2X4 5X-XX-XX-2X6 5X-XX-XX-2X8 5X-XX-XX-3X8 | C39c | ACR-197-CP |

ACSS, AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS, L.L.C. - 19810 NORTH 7TH AVENUE 85027 PHOENIX USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|-------------------|---|------------------|---------------|
| EASA.IM.21O.1221 | 26/06/2014 | T°CAS Release 8.1 | TT-950: 9000000-10408 TT-951: 9000000-55408 TT-952: 9000000-20408 | C119b | 8003940-002 |

| ACSS, AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS, L.L.C. - 19810 NORTH 7TH AVENUE 85027 PHOENIX USA | | | | | |
|--|--------------------|--|--|----------------------------------|-----------------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.341, REV. A | 18/04/2007 | XS-950 Mode S Datalink Transponder | 7517800-11006 7517800-11009 7517800-56006 7517800-56009 | 2C112a | 8003667-001 |
| EASA.IM.210.566, REV. C | 25/11/2011 | TCAS 3000 | 9003000-10001 9003000-10002 9003000-10003 9003000-10004 9003000-55001 9003000-55002 9003000-55003 9003000-55004 9003000-65001 9003000-65002 9003000-65003 9003000-65004 | C119b | 8006225-004 |
| EASA.IM.210.10018357 | 19/06/2012 | RCZ-852 | 7510700-951, 7510700-960 | 2C112a | 8002599-001 |
| EASA.IM.210.10038111 | 19/01/2012 | TCAS 3000 | 9003000-10005 9003000-55005 9003000-65005 | C119c | 8006225-005 |
| EASA.IM.210.10048230 | 24/02/2014 | TCAS II | 4066010-913 | JTSO-C119B Other | 8008322-002 |
| EASA.IM.210.10034316, REV. A | 13/01/2012 | TCAS II Computer / TCAS 2000 Model | 7517900-10010 7517900-10020 7517900-55010 7517900-55020 7517900-56106 7517900-56120 7517900-71010 7517900-71020 | C119c | 8006610-005 REV.-/ 8006610-008 |
| EASA.IM.210.10034317, REV. A | 30/04/2013 | TCAS II Computer / TCAS II Model | 4066010-911, 4066010-914 | C119c | 8008322-001 |
| EASA.IM.210.10036067, REV. B | 05/10/2012 | Surveillance Processor Computer | 9003500-10905 9003500-12907 9003500-55805 9003500-55905 9003500-58907 9003500-65905 9003500-68907 WITH ASD SOFTW. 9200002-001XX | C119c | 8007829-002 |
| EASA.IM.210.10049649, REV. A | 23/07/2015 | T ² CAS TT-952 | 9000000-20310 APM: 9000001-10001 ASDB: 9200000-(XXXXX) TT952: 9000000-20309 | C117a C119c C129a C151b | 8003940-004 |
| EASA.IM.210.10052537, REV. A | 10/03/2015 | NXT-600 Release 1.3 or higher NXT-800 Release 1.3 or higher | 9006000-55000 WITH SOFTWARE 9006000-56000 WITH SOFTWARE 9008000-10000 WITH SOFTWARE 9008000-55000 WITH SOFTWARE MOD C OR HIGHER | C112d C166b | 8008855-001 |
| EASA.IM.210.1156, REV. A | 22/10/2012 | XS-950 Mode S Datalink Transponder | 7517800-10005, 7517800-10007 7517800-10009, 7517800-10100 7517800-10300, 7517800-10310 7517800-55005, 7517800-55007 7517800-55009, 7517800-55310 | 2C112a | 8000391-001 |
| EASA.IM.210.1171, REV. A | 31/08/2012 | RT-950/951 | 7517900-10012, 7517900-55012 7517900-56108, 7517900-71012 7517900-(XX)003 7517900-(XX)004 7517900-(XX)006 7517900-(XX)007 7517900-(XX)101 7517900-(XX)102 7517900-(XX)104 7517900-(XX)105 | JTSO-C119B Other | 8006610-006 |

ACSS, AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS, L.L.C. - 19810 NORTH 7TH AVENUE 85027 PHOENIX USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------------|--------------------|---------------------------------|---------------|------------------|---------------|
| EASA.IM.210.1179, REV. C | 29/11/2011 | Surveillance Processor Computer | 9003500-10001 | C119b | 8007829-002 |
| | | | 9003500-10002 | | |
| | | | 9003500-10003 | | |
| | | | 9003500-10004 | | |
| | | | 9003500-10005 | | |
| | | | 9003500-10802 | | |
| | | | 9003500-10803 | | |
| | | | 9003500-10900 | | |
| | | | 9003500-10901 | | |
| | | | 9003500-10902 | | |
| | | | 9003500-10903 | | |
| | | | 9003500-10904 | | |
| | | | 9003500-10908 | | |
| | | | 9003500-12906 | | |
| | | | 9003500-55001 | | |
| | | | 9003500-55002 | | |
| | | | 9003500-55003 | | |
| | | | 9003500-55004 | | |
| | | | 9003500-55005 | | |
| | | | 9003500-55901 | | |
| | | | 9003500-55902 | | |
| | | | 9003500-55904 | | |
| | | | 9003500-55908 | | |
| | | | 9003500-57901 | | |
| | | | 9003500-58906 | | |
| | | | 9003500-65001 | | |
| | | | 9003500-65002 | | |
| | | | 9003500-65003 | | |
| | | | 9003500-65004 | | |
| | | | 9003500-65005 | | |
| | | | 9003500-65901 | | |
| | | | 9003500-65902 | | |
| | | | 9003500-65904 | | |
| 9003500-65908 | | | | | |
| 9003500-68906 | | | | | |
| WITH ASD SOFTW. 9200002-001XX | | | | | |

| | | | | | |
|-------------------------------|------------|-----------------------------------|--|-------------------------|-------------|
| ETSOA.IM.210.10054174, REV. A | 15/09/2015 | T2CAS TT-950 & TT-951 Release 9.x | | C117a C119c C151b | 8003940-009 |
|-------------------------------|------------|-----------------------------------|--|-------------------------|-------------|

| | | | | | |
|-------------------------|------------|---------------------------|---|--|-------------|
| LBA.N-O.10.930/060 JTSO | 21/05/2002 | XS-950 Mode S Transponder | 7517800-10004 7517800-10004, -55004 7517800-55004 | | 8002034-001 |
|-------------------------|------------|---------------------------|---|--|-------------|

| | | | | | |
|------------------------|------------|---------------------------|--------------------------------|--|--|
| LBA.N-O.10.930/56 JTSO | 09/07/1999 | XS-950 Mode S Transponder | 7517800-10001 7517800-55001 | | |
|------------------------|------------|---------------------------|--------------------------------|--|--|

| | | | | | |
|------------------------|------------|------------|---|--|-------------|
| LBA.N-O.10.940/06 JTSO | 03/07/2003 | RT-950/951 | 7517900-10002 7517900-55002 7517900-71002 | | 8001780-001 |
|------------------------|------------|------------|---|--|-------------|

| | | | | | |
|------------------------|------------|----------------------|-------------|--|-----------|
| LBA.N-O.10.940/08 JTSO | 19/12/2000 | RT-910 TCAS Computer | 4066010-910 | | 5140-0897 |
|------------------------|------------|----------------------|-------------|--|-----------|

ADS/TRANSICOIL - 9 IRON BRIDGE DRIVE 19426 COLLEGEVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|------------------|------------------|---------------|
| EASA.IM.210.10040673 | 18/07/2012 | MCDU Multifunction Control & Display Unit DNM-100-261 | DNM-100-261-(XX) | C113 | 30-078 |

ADVANCED COMPOSITE STRUCTURES, LLC - 1026 LEGRAND BOULEVARD 29492 CHARLESTON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------------|--------------------|---------------------------------------|-----------------------|------------------|---------------|
| EASA.IM.210.052, REV. B | 11/11/2015 | AKE-3XX // Air Cargo Unit Load Device | 10126(XXX) | C90c | PD-10152 |
| EASA.IM.210.156, REV. B | 11/11/2015 | AKE-1 // Air Cargo Unit Load Device | 10011(XXX) | C90c | PD-10098 |
| EASA.IM.210.207, REV. B | 11/11/2015 | AKE-2XX // Air Cargo Unit Load Device | 10155(XXX) | C90c | PD-10221 |
| EASA.IM.210.10048542 | 20/03/2014 | PAG-01 / Air Cargo Unit Load Device | PAG-01-600() () () | C90d | PD-11022 |
| EASA.IM.210.10048543 | 20/03/2014 | ALF-01 / Air Cargo Unit Load Device | ALF-01-600() () () | C90d | PD-11020 |
| EASA.IM.210.10048544 | 20/03/2014 | PMC-01 / Air Cargo Unit Load Device | PMC-01-600() () () | C90d | PD-11021 |
| EASA.IM.210.1155, REV. A | 11/11/2015 | AKE-4SC // Air Cargo Unit Load Device | 12500-001-() | C90c | PD-10591 |

AEROANTENNA TECHNOLOGY, Inc. - 20732 LASSEN STREET 91311 CHATSWORTH USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------------|--------------------|---|---|------------------|---------------|
| EASA.IM.210.918 | 07/07/2008 | AT2300-126 Dual Channel XM / GPS Antenna | AT2300-126() | C144 | DDP2300-126 |
| EASA.IM.210.1083 | 05/11/2008 | AT113 Dual Port VOR Antenna | AT113-() | 2C36f 2C40c | DDP113 |
| EASA.IM.210.1084 | 04/11/2008 | AT130 L-Band Blade Antenna (DME) | AT130-6() | 2C66b | 130 |
| EASA.IM.210.10034032 | 01/03/2011 | AT575-343 GPS Antenna | AT575-343() | C190 | 575343 |
| EASA.IM.210.1004, REV. A | 20/11/2008 | AT575 GPS Antenna | AT575-126() AT575-143() AT575-332G() AT575-93G() | C144 | 575 |

AERODATA AG - HERMANN-BLENK-STRASSE 34-36 38108 BRAUNSCHWEIG GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|------------------------------------|--------------------------------|------------------|---------------|
| EASA.210.10039830 | 29/05/2012 | AeroPhone+ IRIDIUM | AD-STUI-0100 | 2C514 | REP-HW-1801 |
| EASA.210.10047043 | 13/11/2013 | AeroPhone + IRIDIUM / Dual Channel | AD-STUI-020(X), AD-WLAN-010(X) | 2C514 | REP-HW-1801 |

| AERODATA AG - HERMANN-BLENK-STRASSE 34-36 38108 BRAUNSCHWEIG GERMANY | | | | | |
|--|--------------------|---|---|-------------------|-------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| AERODYNE RESEARCH L.L.C. - 1407 FLIGHTLINE BOULEVARD, UNIT 14 32724 DELAND USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.158, REV. A | 26/06/2008 | Smart 99,110,120,135,150,160,175,190,220,250 Reserve Canopy, | 125 SINGLE HARNESS PARA ASSEMB P1482-00 SMART 99 CANOPY P1482-10 SMART 110 CANOPY P1482-20 SMART 120 CANOPY P1482-30 SMART 135 CANOPY P1482-40 SMART 150 CANOPY P1482-50 SMART 160 CANOPY P1482-60 SMART 175 CANOPY P1482-70 SMART 190 CANOPY P1482-80 SMART 220 CANOPY P1483-00 SMART 250 CANOPY P1606-20 HARNESS-HIP RING P1606-30 HARNESS-FULLY ART. P1607-00 STOWAGE CONTAINER P1608-00 DEPLOYMENT DEVICE P1609-00 PILOT CHUTE P1610-00 RIPCORDER-METAL HANDLE P1611-00 RIPCORDER-SOFT HANDLE P1612-00 ACTUATION DEVICE-RSL | C23d | 06-2008-1, 06-2008-2 |
| AERO NET - 22 RUE DE LA GARE 22110 PLOUGUERNEVEL FRANCE | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.424 | 15/11/2005 | Cargo Net NAS3610: 2M2N/2A1N, IATA: NME | MA3240 (XX) (XX) | C90c | 32400000 |
| EASA.210.522 | 14/06/2006 | Cargo Splice Net 2R1N, 96"x196"x118" | MA3321 (XX)-(XX) | C90c | 33210000 |
| EASA.210.523 | 14/06/2006 | Cargo Splice Net 2G1N, 96"x238.5"x118" | MA3141-(XX)-(XX) | C90c | 31410000 |
| EASA.210.570 | 19/12/2006 | NAS3610 : 2R1N; IATA CODE : NRA, Cargo Net | MA4321 (XX)(XX) | C90c | 43210000 |
| EASA.210.571 | 19/12/2006 | NAS3610 : 2M2N/2A1N; IATA: NME, Splice Net | LU3240-(XX)-(XX) | C90c | LU32400000 |
| EASA.210.781 | 29/09/2008 | 1B6N-9G cargo restraint net | MA 5036 (XX) (XX) | C90c | 50360000 |
| EASA.210.10055025 | 06/10/2015 | CARGO RESTRAINT STRAP / Tie Down Strap 5000 Lb | TDS445 (XXXXX) (XXX) (XXXX) | C172 | 44500000 |
| F.O.027 | 06/09/2000 | Type 2GIN Cargo Net | MA5141-(XX)-(XX) | | 51410000 |
| F.O.030 | 18/01/2001 | Cargo Net IATA Code NME | MA4240-(XX)-(XX) | | 42400000 |
| F.O.043 | 13/03/2001 | Cargo Net (NRA/2R1N) | MA5321-(XX)-(XX) | | |
| F.O.049 | 11/06/2001 | Cargo Net type NAS 3610 2E2N | MA5102-(XX)-(XX) | | |
| F.O.058 | 07/02/2002 | Cargo Net | MA4141-(XX)-(XX) | | 41410000 |
| F.O.059 | 07/02/2002 | Cargo Net | MA4223-(XX)-(XX) | | 42230000 |
| F.O.123 | 14/08/2003 | Cargo Net | MA4203-(XX)-(XX) | | 42030000 |
| AERO SEATING TECHNOLOGIES LLC - 5795 MARTIN RD 91706 IRWINDALE USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| ETSOA.IM.210.10054127 | 20/07/2015 | 70711 // Single LH Side Facing Divan, Single RH Side Facing D | 70711-11-(XXX)-(YY) 70711-12-(XXX)-(YY) | C39c | AST-908-DDP |
| ETSOA.IM.210.10054128 | 20/07/2015 | 71040 // Single LH - FWD Facing Seat / Single RH - FWD Facin | 71040-11-(YYY)-(XX) 71040-12-(YYY)-(XX) 71040-13-(YYY)-(XX) 71040-14-(YYY)-(XX) | C127a | AST-907-DDP |
| ETSOA.IM.210.10054140 | 21/07/2015 | 70701 // Single FWD / AFT Facing Seats | 70701-11-(XXX)-(YY) 70701-12-(XXX)-(YY) | C127a | AST-905-DDP |
| ETSOA.IM.210.10054141 | 21/07/2015 | 70702 // Double FWD / AFT Facing Seats | 70702-11-(XXX)-(YY) 70702-12-(XXX)-(YY) | C127a | AST-906-DDP |
| AER-TECHNOLOGY S.A.S. - ROUTE DEPARTEMENTALE 9 95380 VILLERON FRANCE | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10044085 | 22/03/2013 | VTC Vacuum Trash Compactor | AERTCG00000A-(XXX)-(XXX)- -(XXX)-(XX) | C184 | 430_AERTCG00000 A |
| AIRBUS DEFENCE AND SPACE GmbH - WILLY-MESSERSCHMITT-STRASSE 1 85521 OTTOBRUNN GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.1308 | 25/10/2010 | LTR 400 | LTR 400-A: 83138297 LTR 400X-A: 83139434 STR 2000: 83076198 | 2C112b C119c | 30198571 |
| EASA.210.10051463, REV. A | 08/12/2014 | LTR 400-C Transponder | LTR 400-C P/N: 83224123 LTR MOUNTING PANEL P/N: 83139383 | C112d C166B A1 | 30491708 |
| AIR CARGO CONTAINERS LLC - 21620 N 19TH AVE, STE A-10 85027-2796 PHOENIX USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10050204, REV. A | 02/12/2014 | AMJ/ACCA01A | ACCA01A1 ACCA01A2 ACCA01A3 | C90d | ACCA01A AMJ 01 |
| AIR CRUISERS COMPANY - 1747 STATE ROUTE 34 07727-3935 WALL TOWNSHIP USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10047235 | 27/11/2013 | AC-1 / AC-1000 Life Preserver | 66601(-) | C13f | EDN-4138 |

| AIR CRUISERS COMPANY - 1747 STATE ROUTE 34 07727-3935 WALL TOWNSHIP USA | | | | | |
|--|--------------------|---|---|------------------|----------------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10049157 | 15/05/2014 | A350 XWB Door 1/2/4 DUAL LANE EVACUATION SYSTEM / Inflatable | 67951-() 67952-() 67954-() | C69c | 67951.01 67952.01 67954.01 |
| EASA.IM.210.10049319 | 28/05/2014 | A350 XWB Door 1 & 3 Single Lane, Door 3 Dual Lane Evacuation | 67953-() 67961-() 67963-() | C69c | 67961.01, 67963.01, 67963.01 |
| EASA.IM.210.10055026 | 06/10/2015 | AC-2000 Life Preserver | 63600-() | C13f | EDN-4401 |
| AIRLINE CONTAINER LEASING, LLC - 436 SACO LOWELL ROAD 29640 EASLEY USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10030308 | 10/06/2010 | Air Cargo Net | 1519-4500(-) | C90c | DDP ETSO-C90C |
| EASA.IM.210.10046587 | 01/10/2013 | Cargo Restraint Strap Assemblies | 1519-172-()(-) | C172 | 1519-172-SERIES |
| AIRPLUS MAINTENANCE GmbH - FLUGHAFEN 28 88046 FRIEDRICHSHAFEN GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10038036 | 13/01/2012 | KRT-2 VHF Communication Transceiver | 100-(XXXX)-(XXX) 110-(XXXX)-(XXX) | 2C169A | DE-0502-320000 |
| ETSOA.210.10055186 | 20/10/2015 | KTX2 Mode S Transponder | FPGA 0.4.09 P/N 210-0000 WITH SW 0.2.10 | C112d | DE-3001-100000 |
| LBA.O.10.986/2 JTSO | 21/03/2000 | MT-Ultra Professional | MTUP/00-3.60() | | MTUP / 99-02 |
| AIR PRECISION T/A COBHAM AVIONICS - 5 AVENUE DENIS PAPIN, BP 36 92353 LES PLESSIS ROBINSON CEDEX FRANCE | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.1204 | 28/01/2009 | ELT96-STD | 13(XX)-82 ELT90A2560013() ELT90A2560500() ELT96()DGL ELT96()RCP ELT96-()STD | 2C91a 2C126 | PP-DEVA-04-02 |
| F.O.044 | 04/04/2001 | Triple Frequency ELT | ELT96 | | |
| F.O.045 | 04/04/2001 | Bi Frequency ELT | ELT90 | | |
| F.O.046 | 30/05/2001 | Triple Frequency ELT | ELT97 | | |
| F.O.047 | 30/05/2001 | Bi Frequency ELT | ELT91 | | |
| AIS-INTERNATIONAL B.V. - OUDE KERKSTRAAT 55 4878 AK ETTEN-LEUR NETHERLANDS | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.1077, REV. A | 02/02/2012 | Galley Cart Tigris 1 and Tigris 2 | TIGRIS1-801-XXX TIGRIS2-801-XXX TIGRIS2-803-XXX | C175 | AISI-12-01 |
| AMERI-KING CORPORATION - 17881 SAMPSON LANE 92648 HUNTINGTON BEACH USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.1102 | 20/11/2008 | AK-451-(AF)(AP)(S) Emergency Locator Transmitter with GPS po | AK-451-(AF) (AP) (S) | 2C91a 2C126 | 451 |
| EASA.IM.210.10033545 | 27/01/2011 | AK 451.017-1B ELT Whip Antenna and AK 451.017-4(S) ELT Porta | AK451.017-1B AK451.017-4(S) | 2C91a 2C126 | 451.017 |
| AMETEK, Inc. - 1100 CASSATT ROAD 19312-1177 BERWYN USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10038382 | 10/02/2012 | Engine Interface Unit (EIU) | 10900B()JM() | C43c | 10900DDP |
| AMSAFE BRIDPORT LIMITED - WEST STREET DT6 3QU BRIDPORT UNITED KINGDOM | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.029 | 19/05/2004 | 3G Cargo Restraint Net Mod. AC10-01172 () or use with 108"x | AC10-01172() | C90c | PD113 |
| EASA.210.031 | 19/05/2004 | 3G Cargo Restraint Net Mod. AC10-02117 () for use with 125"x | AC10-02117() | C90c | PD 130 |
| EASA.210.035 | 26/05/2004 | 3G Cargo Restraint Net Mod. QZ10-02828 () for use with 125" | QZ10-02828() | C90c | PD 262 |
| EASA.210.180 | 22/10/2004 | 3G Cargo Restraint Net Mod. QZ10-02929 () for use with 108"x | QZ10-02929() | C90c | PD-266 |
| EASA.210.181 | 22/10/2004 | 3G cargo Restraint Net Mod. QZ10-03131 () for use with 61.5" | QZ10-03131() | C90c | PD-268 |
| EASA.210.182 | 22/10/2004 | 3G Cargo Restraint Net Mod. QZ10-03333 () for use with 238.5 | QZ10-03333() | C90c | PD-264 |
| EASA.210.183 | 22/10/2004 | 3G Cargo Restraint Net Mod. QZ10-02727 for use with 125"x88" | QZ10-02727() | C90c | PD-270 |
| EASA.210.185 | 22/10/2004 | 3G Cargo Restraint Net Mod. QZ10-03232 () for use with 53"x8 | QZ10-03232() | C90c | PD-267 |
| EASA.210.186 | 22/10/2004 | 3G Cargo Restraint Net Mod. QZ10-03434 () for use with 196"x | QZ10-03434() | C90c | PD-269 |
| EASA.210.346 | 22/09/2005 | Cargo Pallet Net 125x88/96" | AC10-01545() | C90c | PD 275 |
| EASA.210.460 | 23/01/2006 | Cargo Restraint Net 125x96" | AC20-02712(XX) | C90c | PD 279 |
| EASA.210.508 | 19/05/2006 | QZ10-03535 Cargo Net, Quickzip 125X88/96" | QZ10-03535(XX) | C90c | PD286 |
| EASA.210.602 | 12/12/2006 | MN10-02717 - Net-Cargo | MN10-02717() | C90c | PD 295 |
| EASA.210.625 | 18/01/2007 | MN30-02783 | MN30-02783() | C90c | PD 296 |
| EASA.210.653 | 28/03/2007 | NET - CARGO MN30-02785 MODULAR 60.4" X 61.5" | MN30-02785() | C90c | PD 298 |
| EASA.210.654 | 27/03/2007 | NET - CARGO MN30-02786, MODULAR 60.4" X 125" | MN30-02786() | C90c | PD 300 |

| AMSAFE BRIDPORT LIMITED - WEST STREET DT6 3QU BRIDPORT UNITED KINGDOM | | | | | |
|--|--------------------|--|----------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.655 | 27/03/2007 | NET - CARGO MN30-02787 MODULAR 96"X238.5" | MN30-02787() | C90c | PD 301 |
| EASA.210.656 | 27/03/2007 | NET - CARGO MN30-02788 MODULAR 55" X 96" | MN30-02788() | C90c | PD 302 |
| EASA.210.805 | 31/08/2007 | MN20-02821 Net - Cargo, Modular 88/96"X125" | MN20-02821() | C90c | PD 309 |
| EASA.210.806 | 31/08/2007 | MN20-02822 Net - Cargo, Modular 60.4"X61.5" | MN20-02822() | C90c | PD 311 |
| EASA.210.807 | 31/08/2007 | MN20-02823 Net - Cargo, Modular 60.4"X125" | MN20-02823() | C90c | PD 312 |
| EASA.210.808 | 31/08/2007 | MN20-02824 Net - Cargo, Modular 96"X238.5" | MN20-02824() | C90c | PD 313 |
| EASA.210.827 | 01/10/2007 | MN10-02812 NET - CARGO, MODULAR 88/96"X125" | MN10-02812() | C90c | PD 316 |
| EASA.210.979 | 18/04/2008 | MN10-02813 NET - CARGO, CLAMSHELL 88/96"X125" | MN10-02813() | C90c | PD 320 |
| EASA.210.030, REV. A | 08/08/2006 | 3G Cargo Restraint Net for use with 96"x 60.4" or 61.5" and | AC20-01123() | C90c | PD122 |
| EASA.210.1027 | 07/05/2008 | MN40-02829 NET - PALLET, MODULAR 88/96"X125" | MN40-02829() | C90c | PD 336 |
| EASA.210.1123 | 03/11/2008 | MN50-02849 NET-PALLET, MODULAR 88/96"X125" | MN50-02849() | C90c | PD 344 |
| EASA.210.1178 | 12/05/2009 | CS10-02862 Active ULD Container | CS10-02862() | C90c | PD 274 |
| EASA.210.1236 | 29/04/2009 | MN50-02869 NET - PALLET, MODULAR 88/96" X 125" | MN50-02869() | C90c | PD 355 |
| EASA.210.184, REV. A | 08/08/2006 | 3G Cargo Restraint Net for use with 96"x61.5" or 60.4" and 9 | QZ20-03030() | C90c | PD-265 |
| EASA.210.10031652 | 02/09/2010 | NET-Pallet, Modular 88/96"X125" | QZ35-03636 () | C90c | PD 379 |
| EASA.210.10035892 | 26/07/2011 | MN50-02871 Net - Pallet, Modular 60.4"X61.5" | MN50-02871() | C90c | PD 406 |
| EASA.210.10035924 | 27/07/2011 | MN50-02879 Net - Pallet, Modular 60.4"X125" | MN50-02879() | C90c | PD 405 |
| EASA.210.10036355 | 02/09/2011 | MN55-03007 Net - Pallet, FR Restraint 88/96"X125" | MN55-03007() | C90c | PD 402 |
| EASA.210.10042277 | 20/11/2012 | CARGO TIE DOWN STRAP ASSEMBLY (5000lbf) | TS40-02996() | C172 | PD 407 |
| EASA.210.10045554 | 04/07/2013 | MN55-03073 NET - PALLET 108x88 | MN55-03073() | C90d | PD426 |
| EASA.210.10045607 | 05/07/2013 | MN55-03065 Net - Pallet 88/96X125 | MN55-03065() | C90d | PD425 |
| EASA.210.10047109 | 19/11/2013 | MN50-03066 Net - Pallet, Modular, Restraint Master 88/96x125 | MN50-03066(XX) | C90d | PD 424 |
| EASA.210.10047211 | 25/11/2013 | MN50-03067 Net - Pallet, Modular, Restraint Master 88/96x125 | MN50-03067(XX) | C90d | PD 428 |
| EASA.210.10051004 | 30/10/2014 | TS20-04443 Cargo Tie Down Strap Assembly (2000 lbf) | TS20-04443() | C172 | PD 449 |

| AMSAFE, Inc. - 1043 NORTH 47TH AVENUE 85043 PHOENIX USA | | | | | |
|--|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10031731 | 08/09/2010 | Seat Belt Airbag Assembly | 7115-1-()-() | C22g | E511373 |
| EASA.IM.210.10031752 | 09/09/2010 | Seat Belt Airbag Assembly | 7121-1-()-() | C22g | E511377 |
| EASA.IM.210.10041627 | 05/10/2012 | Seat Belt Assembly | 2220-1-()-() 2220-2-()-() 2220-5-()-() | C22g | E512440 |
| EASA.IM.210.10045660 | 10/07/2013 | Restraint System | 4115-1-()-() | C114 | DDP4115 |
| EASA.IM.210.10047696 | 13/01/2014 | 2074 / Lap Belt assy / Extension assy / Extension assy | 2074-1-()-() 2074-2-()-() 2074-5-()-() | C22g | DDP2074 |
| EASA.IM.210.10051296 | 20/11/2014 | 2231 Lap belt assy / extension assy | 2231-1-()-() 2231-2-()-() 2231-5-()-() | C22g | DDP2231 |
| EASA.IM.210.10052735 | 24/03/2015 | 4287 // Restraint System Assembly | 4287-()-() | C114 | DDP4287 |
| EASA.IM.210.10054425 | 17/08/2015 | 7266 // Inflatable Lap Belt Assembly | 7266-1-() | C22g | E513867 |
| EASA.IM.210.10055619 | 23/11/2015 | Inflatable Restraint System Assembly | 7216-1-() | C114 | 7216 |
| ETSOA.IM.210.10054125 | 20/07/2015 | 7235 // Lap Belt Assembly | 7235-1-(), 7235-2-() | C22g | 513704 |
| ETSOA.IM.210.10054126 | 20/07/2015 | 7232 // Lap Belt Assembly | 7232-1-() 7232-2-() | C22g | 513759 |

| ANJOU AERONAUTIQUE S.R.L. - STR. LIVEZII 98, ETAJ P 550042 SIBIU ROMANIA | | | | | |
|---|--------------------|--|--|-------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10041247 | 31/08/2012 | Torso Restraint System Type 349, Models 34914, 34915, and 34 | 34914(XX), 34915(XX) 34918(XX) | TSO-C114 Other | 349DC-001 |
| DGAC QAC 120 | 18/02/2015 | Seatbelt type 349 | 34911(XX) 34912(XX) 34913(XX) | C22g | NO. 2 |
| EASA.210.10036843, REV. A | 19/10/2011 | Torso restraint system | 35811(XXX)-(XX)-(XXX) 35812(XXX)-(XX)-(XXX) 35813(XXX)-(XX)-(XXX) 35814(XXX)-(XX)-(XXX) 35815(XXX)-(XX)-(XXX) 35816(XXX)-(XX)-(XXX) 35817(XXX)-(XX)-(XXX) 35818(XXX)-(XX)-(XXX) | C114 | DDP358DC-001 |
| EASA.210.10048944, REV. A | 18/02/2015 | 35311, 35313 Seatbelt | 35311(XXX)-(XX)-(XXX) 35312(XXX)-(XX)-(XXX) 35313(XXX)-(XX)-(XXX) | C22g | NO. 2 |

| ANJOU AERONAUTIQUE S.R.L. - STR. LIVEZII 98, ETAJ P 550042 SIBIU ROMANIA | | | | | |
|---|--------------------|--|--|---|-------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| ETSOA.21O.10052604 | 17/03/2015 | 35911, 35912 Seatbelt, 35913 Seatbelt Extension | 35911 (XXX)-(XX)-(XXX) 35912 (XXX)-(XX)-(XXX) 35913 (XXX)-(XX)-(XXX) | C22g | 359DC-001 |
| AOA APPARATEBAU GAUTING GmbH - AMMERSEESTRASSE 45-49 82131 GAUTING GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| LBA.O.40.230/5 JTSO | 13/07/1999 | Smoke Detector | SD9470-() | | SD9470 |
| ARCHANGEL SYSTEMS Inc. - 1635 PUMPHREY AVE 36832 AUBURN USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.21O.10051561 | 10/12/2014 | AHR150A / AHR300A Air Data Attitude Heading Reference System | AHR150A-1-XX (ISU) AHR150A-2 / 2A (MSU) AHR300A-1-XX (ISU) | C4c C5e C6e C88a C106 A1 | DDP-AHR150A |
| ASPEN AVIONICS, Inc. - 5001 INDIAN SCHOOL ROAD NE 87110 ALBUQUERQUE USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.21O.1132 | 16/01/2009 | Electronic Flight Display EFD1000 | A-05-110-00 PFD WITH A-05-111-00 RSM A-05-112-00 ACU WITH A-05-113-00 CONFIG. MODULE A-05-114-00 CONFIG. MODULE A-05-118-00 CONFIG. MODULE A-08-130-00 INSTALLATION KIT A-08-131-00 INSTALLATION KIT A-08-132-00 INSTALLATION KIT SW A-02-148-1.(X) MAP SW A-02-158-1.(X) IOP SW A-02-178-1.(X) ACU | C2d C3d C4c C6d C8d C10b C106 C113 | A-01-318-00 |
| EASA.IM.21O.10034556 | 12/04/2011 | Electronic Flight Display EFD1000/500 System with Software V | 413-00002-() 903-00001-() 903-00002-() 903-00003-() 903-00007-() 903-00008-() 903-00011-() 910-00001-()WITH SW2.X OR B2.X 910-00003-() 910-00004-() WITH SW1.X 910-00005-() 910-00007-() 910-00013-() WITH SW.X | C2d C3d C4c C6d C8d C10b C106 C113 | 040-00002-002 |
| AUTOFLUG GmbH - INDUSTRIESTRASSE 10 25462 RELINGEN GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| LBA APPROVAL 40.320/9 | 02/01/1989 | Aufblasbare Ein-Mann-Rettungsinsel FRS-1, FRS-3 | AFG072229-02 | TSO-C70A Other | |
| AVEO ENGINEERING GROUP S.R.O. - OBORY C.P. 98 263 01 DOBRIS CZECH REPUBLIC | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.10053449 | 28/05/2015 | POSISTROBE CP LED position light white with strobe function | AVE-POSW-54G | C30c C96a | AVE-POSW-54G-DDP |
| EASA.21O.10053491 | 01/06/2015 | RedBaron Combo HISL | AVE-RBCRW-001 | C96a | AVE-RBCRW-001-DDP |
| EASA.21O.10053935 | 06/07/2015 | Ultra Galactica Red, Green and White Position lights with st | AVE-WPSTG-54G AVE-WPSTR-54G | C30c C96a | AVE-WPST-54G-DDP |
| EASA.21O.10053936 | 06/07/2015 | Ultra Galactica (Embedded) Red and Green Position lights wit | AVE-WPSG-64G AVE-WPSR-64G | C30c C96a | AVE-WPS-64G-DDP |
| EASA.21O.10055069 | 09/10/2015 | RedBaron XP Galactica | AVE-RBXP-001 AVE-RBXPW-001 | C96a | AVE-RBXP-001-DDP |
| EASA.21O.10055070 | 09/10/2015 | NEBULON | AVE-WPG-51G-402 AVE-WPR-51G-401 | C30c | AVE-WP-51G-DDP |
| EASA.21O.10055229 | 23/10/2015 | SmartStrobe | AVE-IS30ANCASAS-02G | C96a | AVE-IS30ANCASAS-02G-DDP |
| ETSOA.21O.10055101 | 13/10/2015 | PEGATRON | P/N AVE-POSW-74G-401 | C30c | AVE-POSW-74-DDP |
| AVIDYNE CORPORATION - 55 OLD BEDFORD ROAD 01773 LINCOLN USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |

AVIDYNE CORPORATION - 55 OLD BEDFORD ROAD 01773 LINCOLN USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|---------------|
| EASA.21O.131 | 05/07/2004 | Entegra PFD | 530-00138-000 VERSION () 700-00006-002-() | C2d C3d C4c C6d C8d C10b C44b C45a C47 C49b C52b C106 C113 | AVPFD-283 |
| EASA.IM.21O.446 | 03/01/2006 | EX500 | 530-00163-() 700-00007-() | 2C63c C110a C113 C118 C147 | AVMFD-369 |
| EASA.IM.21O.447 | 16/01/2006 | Multifunction Display EX5000 MFD | 530-00180-(XXX) REV (XX) 700-00004-(XXX) REV (XX) | C43c C44b C45a C47 C49b C55 C110a C113 C147 | AVMFD-378 |
| EASA.IM.21O.448 | 16/01/2006 | Primary Flight Display EXP5000 PFD | 530-00177-(XXX) REV (XX) 700-00006-(XXX) REV (XX) | C2d C3d C4c C6d C8d C10b C43c C44b C45a C47 C49b C52b C55 C88a C106 C113 | AVPFD-365 |
| EASA.IM.21O.449 | 16/01/2006 | Multifunction Display EX5000 MFD | 530-00180-(XXX) REV (XX) 700-00030-(XXX) REV (XX) | C43c C44b C45a C47 C49b C55 2C63c C110a C113 C147 | AVMFD-379 |
| EASA.IM.21O.684 | 27/09/2007 | EXP5000 Primary Flight Display with Software 530-00183-() | 700-00006-() WITH SOFTWARE 5 | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c C43c C44b C45a C46a C47 C49b C52b C55 C88a C106 C113 | AVPFD-418 |

AVIDYNE CORPORATION - 55 OLD BEDFORD ROAD 01773 LINCOLN USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|--|---------------|
| EASA.IM.210.843 | 03/04/2008 | EX5000 Multifunction Display | 700-00004-() WITH SOFTWARE 53 | C43c C44b C45a C47 C49b C55 C110a C113 C147 | AVMFD-448 |
| EASA.IM.210.844 | 03/04/2008 | EX5000 Multifunction Display | 700-00030-() WITH SOFTWARE 5 | C43c C44b C45a C47 C49b C55 2C63c C110a C113 C147 | AVMFD-449 |
| EASA.IM.210.851 | 21/01/2008 | TWX670 Tactical Weather Detection System | CONNECTOR KIT 800-00035-000-(MOUNT TRAY 700-00034-000-() PROCESSOR UNIT 700-00033-000-(| C110a | AVTWX-011 |
| EASA.210.129, REV. A | 15/09/2004 | Entegra Magnetometer/OAT Sensor | 700-00011-000-() | C6d | AVAHR-011 |
| EASA.210.130, REV. A | 15/09/2004 | Multifunction Display EX5000 MFD | 530-00137-000 VERSION () 700-00004-006-() | C43c C44b C45a C47 C49b C55 C110a C113 C147 | AVMFD-225 |
| EASA.210.234, REV. A | 21/02/2005 | Multi-Hazard-Display MHD Type 71-4100, 71-4200, 71-4300 | 70-4100-() 70-4200-() 70-4300-() 87-3188.() | C113 C118 C147 | NUMBER 1 |
| EASA.IM.210.10034484 | 07/04/2011 | EX600 Multifunction Display | 700-00167-() 700-00168-() WITH SW 530-00201-() | 2C63c C110a C113 C118 C147 C165 | AVMFD-518 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------------|--|------------------|---------------|
| EASA.210.027 | 19/05/2004 | Passenger Seat | 11T()+4N()()() | C39b | 02-26 |
| EASA.210.028 | 19/05/2004 | Passenger Seat | 12P()Z2H()()() | C39b | 04-02 |
| EASA.210.043 | 19/05/2004 | Passenger Seat | 12R()Z10()()() 12R()Z51()()() 12R()Z52()()() 12R()Z98()()() | C39b | 04-10 |
| EASA.210.044 | 26/05/2004 | Passenger Seat | 15Z()Z12()()() 15Z()Z98()()() | C39b | 04-11 |
| EASA.210.066 | 16/06/2004 | Passenger Seats | 16GA1Z5001KK 16GA1Z5101KK 16GA2Z5001KK | C127a | 03-45 |
| EASA.210.072 | 16/06/2004 | Passenger Seat | 16K()Z11()()() | C39b | 03-42 |
| EASA.210.073 | 16/06/2004 | Passenger Seat | 16J()Z15()()() | C39b | 03-41 |
| EASA.210.074 | 16/06/2004 | Passenger Seat | 11X()10()()() | C39b | 03-33 |
| EASA.210.075 | 16/06/2004 | Flotation Cushion | 12477-01()JL9 | C72c | 03-31 |
| EASA.210.076 | 16/06/2004 | Passenger Seat | 16M()Z10()()() | C39b | 03-37 |
| EASA.210.077 | 16/06/2004 | Passenger Seat | 16L()Z10()()() | C39b | 03-36 |
| EASA.210.078 | 16/06/2004 | Passenger Seats | 16H()Z10()()() 16H()Z11()()() | C39b | 03-38 |
| EASA.210.079 | 16/06/2004 | Passenger Seats | 16FA1Z1001KK 16FA1Z1002KK 16FA1Z1101KK 16FA1Z1102KK 16FA3Z1001KK 16FA3Z1002KK | C127a | 03-46 |
| EASA.210.083 | 16/06/2004 | Passenger Seats | 16H()Z01()()() 16H()Z12()()() | C39b | 03-49 |
| EASA.210.084 | 16/06/2004 | Flotation Cushion | 12470-01()JRK | C72c | 03-17 |
| EASA.210.085 | 16/06/2004 | Flotation Cushion | 12471-01()JRL | C72c | 03-16 |
| EASA.210.086 | 16/06/2004 | Passenger Seats | 12K()Z10()()() 12K()Z52()()() | C39b | 03-48 |
| EASA.210.137 | 12/07/2004 | Passenger Seat | 16N()Z10()()() 16N()Z59()()() | C39b | 04-22 |
| EASA.210.142 | 27/07/2004 | Passenger Seat | 12K()Z11()()() | C39b | 04-21 |
| EASA.210.175 | 18/10/2004 | Flotation Cushion | 12483-01()UP | C72c | 03-53 |
| EASA.210.176 | 18/10/2004 | Flotation Cushion | 12480-01()UN | C72c | 03-54 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|------------------|---------------|
| EASA.210.177 | 18/10/2004 | Flotation Cushion | 12482-01() UM | C72c | 03-55 |
| EASA.210.188 | 22/10/2004 | Triple Passenger Seat | 16GC1Z5001KK 16GC1Z5101KK 16GC2Z5001KK | C127a | 04-30 |
| EASA.210.189 | 22/10/2004 | Double Passenger Seat | 16FC1Z1001KK 16FC1Z1002KK 16FC1Z1101KK 16FC1Z1102KK 16FC3Z1001KK 16FC3Z1002KK | C127a | 04-31 |
| EASA.210.227 | 05/01/2005 | Passenger Seat | 11TA1Z8401WV 11TA1Z8501WV 11TA1Z8601WV 11TA1Z8705WV 11TA2Z8402WV 11TA2Z8404WV 11TA2Z8502WV 11TA2Z8602WV 11TA2Z8706WV 11TA3Z8403WV 11TN1Z8422WV 11TN3Z8421WV | C127a | 04-43 |
| EASA.210.228 | 05/01/2005 | Passenger Seat | 11WN1Z7A22WV 11WN1Z7A24WV 11WN3Z7A21WV 11WN4Z7A23WV | C127a | 04-44 |
| EASA.210.267 | 11/04/2005 | Passenger Seat 17A | 17A() Z01 17AZ10() () () | C39b | 05-02 |
| EASA.210.282 | 01/06/2005 | Passenger Seats | 16N() Z01() () () 16N() Z12() () () | C39b | DDP 05-07 |
| EASA.210.283 | 30/05/2005 | Flotation Cushion | 12500-01() JL9 | C72c | DDP 05-01 |
| EASA.210.486 | 22/03/2006 | Diamond First Class Seat 17E | 17E() Z01() () () | C39b | 06-02 |
| EASA.210.487 | 22/03/2006 | Diamond First Class Seat 17F | 17F() Z10() () () | C39b | 06-03 |
| EASA.210.520 | 12/06/2006 | Pegasus Economy Class Seat | 11T() Z84() () () 11T() Z85() () () 11T() Z86() () () 11T() Z87() () () 11W() Z7A() () () | C127a | 06-09 |
| EASA.210.521 | 12/06/2006 | Pegasus | 13F() Z10() () () 13F() Z51() () () 13F() Z52() () () 13F() Z53() () () | C39b | 06-04 |
| EASA.210.547 | 14/08/2006 | Phoenix Seat | 13C() Z51() () () 13C() Z52() () () 13C() Z53() () () | C127a | 06/17 |
| EASA.210.574 | 26/10/2006 | Perseus Business Class Seat | 17K() Z50() () () | C127a | 06-36 |
| EASA.210.575 | 26/10/2006 | Perseus Business Class Seat | 17M() Z10() () () | C127a | 06-14 |
| EASA.210.677 | 23/03/2007 | Shuttle 393 | 133() -15() () () | C39b | 06-39 |
| EASA.210.678 | 23/03/2007 | Venus First Class Seats 17N | 17N() Z01() () () 17N() Z02() () () | C127a | 06-34 |
| EASA.210.679 | 23/03/2007 | Centaurus 18A | 18A() Z95() () () | C39b | 06-37 |
| EASA.210.686 | 20/04/2007 | Centaurus 13K Economy Class Seat | 13K() Z52() () () | C127a | 07/07 |
| EASA.210.745 | 04/02/2009 | Flotation Bottom Cushion | 12568-01() JHR | C72c | 06-18 |
| EASA.210.767 | 23/05/2008 | Perseus First Class Seat | 17P() Z10() () () | C127a | 07-15 |
| EASA.210.801 | 19/10/2007 | Centaurus Convertible Economy Class Seat | 13L() Z58() () () 13L() Z89() () () | C39b | 07-21 |
| EASA.210.837 | 10/02/2009 | Centaurus Economy Class Seat | 13E() Z13() () () 13E() Z58() () () 13E() Z59() () () 13H() Z58() () () | C127a | 07-41 |
| EASA.210.838 | 12/02/2009 | Centaurus Convertible Economy Class Seat | 13L() Z58() () () | C127a | 07-42 |
| EASA.210.864 | 12/01/2009 | Bottom Cushion | 12618-01() JWJ | C72c | 07-44 |
| EASA.210.896 | 14/01/2009 | Centaurus 18A | 18A() Z11() () () 18A() Z12() () () 18A() Z51() () () 18A() Z52() () () 18A() Z53() () () 18A() Z55() () () 18A() Z56() () () 18A() Z58() () () 18A() Z90() () () 18A() Z91() () () | C127a | 07-45 |
| EASA.210.938 | 31/03/2008 | Centaurus Economy Class Seat | 13R() Z10() () () 13R() Z50() () () 13T() Z10() () () 13T() Z50() () () 13W() Z10() () () 13W() Z50() () () | C39b | 07-46 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.939 | 27/10/2008 | B/C Andromeda Forward Facing Business Class Seat | 161()Z18()()() 161()Z19()()() 161()Z20()()() | C39b | 98-47 |
| EASA.210.001, REV. A | 05/05/2011 | Passenger Seat Futura | 12M()Z2H()()() 12Y()Z2H()()() | C39b | 03-12 |
| EASA.210.1012 | 21/11/2008 | Centaurus Economy Class Seat 18K | 18K()Z10()()() 18K()Z11()()() 18K()Z51()()() 18K()Z56()()() 18K()Z59()()() 18K()Z90()()() 18K()Z91()()() | C127a | 08-05 |
| EASA.210.1127 | 11/03/2009 | DIAMOND First Class Seat | 17R()Z01()()() 17T()Z10()()() | C39b | 08-18 |
| EASA.210.114, REV. A | 06/01/2005 | Passenger Seat | 10()() 16C()() | C39b | 02-25 |
| EASA.210.115, REV. A | 06/01/2005 | Passenger Seat | 11()()() 16A()() | C39b | 02-24 |
| EASA.210.1244 | 24/09/2009 | Seat model "Futura" | 12X()Z2H()()() | C39b | 09-07 |
| EASA.210.576, REV. A | 21/05/2008 | Perseus First Class Seat | 17L()Z10()()() 17L()Z11()()() | C127a | 06-15 |
| EASA.210.665, REV. A | 26/07/2012 | Perseus Business Class Seat | 17K()Z13()()() 17K()Z17()()() | C127a | 07-05 |
| EASA.210.676, REV. B | 18/05/2011 | Centaurus Economy Class Seat 13E | 13E()Z12()()() 13E()Z14()()() 13E()Z15()()() 13E()Z16()()() 13E()Z17()()() 13E()Z18()()() 13E()Z20()()() 13E()Z52()()() 13E()Z53()()() 13E()Z54()()() 13E()Z55()()() 13E()Z56()()() 13E()Z57()()() 13E()Z60()()() 13E()Z63()()() 13E()Z91()()() | C127a | 06-32 |
| EASA.210.722, REV. B | 18/05/2011 | Centaurus Economy Class Seat 13H | 13H()Z12()()() 13H()Z14()()() 13H()Z15()()() 13H()Z16()()() 13H()Z17()()() 13H()Z18()()() 13H()Z51()()() 13H()Z52()()() 13H()Z60()()() 13H()Z62()()() 13H()Z91()()() | C127a | 06-33 |
| EASA.210.725, REV. B | 08/12/2011 | Perseus 17K Business Class Seat | 17K()Z11()()() 17K()Z12()()() 17K()Z14()()() 17K()Z15()()() 17K()Z16()()() | C39b | 07-12 |
| EASA.210.758, REV. B | 15/03/2012 | Andromeda Business Class Seat | 162()Z10()000 162()Z11()000 162()Z14()000 162()Z15()000 | C39b | 07-17 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-----------------------------------|--|-------------------|---------------|
| EASA.210.802, REV. B | 26/04/2012 | Centaurus Economy Class Seat | 13E()Z11()()() | C39b | 07-22 |
| | | | 13E()Z13()()() | | |
| | | | 13E()Z23()()() | | |
| | | | 13E()Z24()()() | | |
| | | | 13E()Z25()()() | | |
| | | | 13E()Z26()()() | | |
| | | | 13E()Z27()()() | | |
| | | | 13E()Z28()()() | | |
| | | | 13E()Z29()()() | | |
| | | | 13E()Z55()()() | | |
| | | | 13E()Z58()()() | | |
| | | | 13E()Z59()()() | | |
| | | | 13E()Z64()()() | | |
| | | | 13E()Z65()()() | | |
| | | | 13E()Z66()()() | | |
| | | | 13E()Z67()()() | | |
| | | | 13E()Z68()()() | | |
| | | | 13E()Z69()()() | | |
| | | | 13E()Z70()()() | | |
| | | | 13E()Z71()()() | | |
| | | | 13H()Z11()()() | | |
| | | | 13H()Z20()()() | | |
| | | | 13H()Z21()()() | | |
| | | | 13H()Z22()()() | | |
| | | | 13H()Z23()()() | | |
| | | | 13H()Z24()()() | | |
| | | | 13H()Z53()()() | | |
| | | | 13H()Z54()()() | | |
| | | | 13H()Z55()()() | | |
| | | | 13H()Z58()()() | | |
| | | | 13H()Z59()()() | | |
| | | | 13H()Z63()()() | | |
| | | | 13H()Z67()()() | | |
| EASA.210.846, REV. A | 12/08/2010 | Andromeda Business Class Seat | 162()Z10()()() 162()Z12()()() 162()Z13()()() | C127a | 07-17 |
| EASA.210.10029663 | 09/04/2010 | Shuttle 396 Double Passenger Seat | 188()30()()() | TSO-C39B Other | 10-09 |
| EASA.210.10030204 | 02/06/2010 | Shuttle 393 Crew Rest Seating | 12W()Z10()()() | C39b | 09-09 |
| EASA.210.10030205 | 02/06/2010 | Shuttle 393 Crew Rest Seating | 12T()Z10()()() | C39b | 09-08 |
| EASA.210.10031068 | 26/07/2010 | Andromeda Passenger Seat | 19E()Z10()()() | C127a | DDP 10-02 |
| EASA.210.10031959 | 27/09/2010 | Bottom cushion | 12725-01()JWJ | C72c | 10-08 |
| EASA.210.10035983 | 03/08/2011 | Business Class Seat Biz | 19L()Z10()()() 19L()Z11()()() | C127a | 10-13 |
| EASA.210.10037584 | 08/12/2011 | Ultralight Economy Class Seat | 14L()Z10()()() | C127a | 10-22 |
| EASA.210.10037690 | 15/12/2011 | Centaurus Economy Class Seat | 13N()Z67()()() | C39c | 11-05 |
| EASA.210.10038244 | 31/01/2012 | Seat Shuttle 393 | 184()6A()()() | C39c | 11-43 |
| EASA.210.10038616 | 02/03/2012 | Seat Ultralight C | 14L()Z11()()() 14L()Z12()()() 14L()Z50()()() 14L()Z51()()() | C127a | 11-45 |
| EASA.210.10038687 | 08/03/2012 | Seat Bottom Cushion | 12796-01()()() | C72c | 11-44 |
| EASA.210.10038688 | 08/03/2012 | Seat Bottom Cushion | 12778-01()()() | C72c | 11-39 |
| EASA.210.10038689 | 08/03/2012 | Seat Bottom Cushion | 12779-01()()() | C72c | 11-40 |
| EASA.210.10038690 | 08/03/2012 | Seat Bottom Cushion | 12780-01()()() | C72c | 11-41 |
| EASA.210.10038691 | 08/03/2012 | Seat Bottom Cushion | 12781-01()()() | C72c | 11-42 |
| EASA.210.10038795 | 15/03/2012 | Seat Shuttle 393 | 184()5C()()() 184()5E()()() 184()5F()()() | C39c | 12-02 |
| EASA.210.10038796 | 15/03/2012 | Passenger Seat Futura | 12K()Z10()()() 12K()Z52()()() 12K()Z54()()() | C39c | 12-01 |
| EASA.210.10039328 | 26/04/2012 | Centaurus Economy Class Seat | 13X()Z50()()() | C39c | 12-04 |
| EASA.210.10039628 | 29/05/2012 | Shuttle 399 Seat | 133()29()()() 133()42()()() 133()43()()() 133()5E()()() 133()63()()() 133()6A()()() 133()70()()() 133()71()()() 133()72()()() 133()76()()() | C39c | 12-08 |
| EASA.210.10041890 | 22/10/2012 | Centaurus Economy Class Seat | 13E()Z30()()() 13E()Z55()()() 13E()Z56()()() 13H()Z25()()() 13H()Z55()()() | C39c | 12-10 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|-----------------------------|--|------------------|---------------|
| EASA.21O.10043190 | 10/01/2013 | Seat Centaurus STD and IAT | 13Y())Z12()))) 13Y())Z13()))) 13Y())Z50()))) 13Z())Z10()))) 14Y())Z12()))) 14Y())Z13()))) 14Y())Z50()))) 14Z())Z10()))) | C39c | 12-13 |
| EASA.21O.10043827 | 27/02/2013 | Zeus Business Class Seat | 19M())Z10()))) 19M())Z11()))) | C127a | 12-11 |
| EASA.21O.10044184 | 25/03/2013 | Perseus Business Class Seat | 17K())Z20()))) 17Y())Z01()))) | C39c | 12-09 |
| EASA.21O.10044185 | 25/03/2013 | Perseus B/C Seat | 17X())Z19()))) | C39c | 12-12 |
| EASA.21O.10046319 | 09/09/2013 | Columbus Economy Class Seat | 14J())Z10()))) 14J())Z50()))) 14J())Z89()))) | C127a | 13-03 |
| EASA.21O.10046383 | 13/09/2013 | Seat Centaurus STD and IAT | 13Y())Z14()))) 13Y())Z15()))) 13Y())Z16()))) 13Y())Z51()))) 14Y())Z14()))) 14Y())Z15()))) 14Y())Z16()))) 14Y())Z51()))) | C127a | 13-10 |
| EASA.21O.10047727 | 16/01/2014 | Colombus Economy Class Seat | 14K())Z20()))) 14K())Z54()))) 14K())Z56()))) 14K())Z57()))) 14K())Z58()))) 14K())Z60()))) | C39c | 13-13 |
| EASA.21O.10047765 | 20/01/2014 | Zeus Business Class Seat | 19M())Z10()))) | C39c | 13-07 |
| EASA.21O.10044944, REV. A | 26/09/2013 | Centaurus Seat | 14H())Z10()))) 14H())Z11()))) 14H())Z12()))) 14H())Z13()))) 14H())Z15()))) 14H())Z16()))) 14H())Z17()))) 14H())Z18()))) 14H())Z19()))) 14H())Z50()))) 14H())Z51()))) 14H())Z89()))) 14J())Z89()))) 14N())Z10()))) 14N())Z54()))) 14N())Z55()))) | C39c | 13-02 |
| ENAC.O.004 | 01/02/2001 | Flotation cushions | 12417-01())L8 | | 00-21 |
| ENAC.O.005 | 01/02/2001 | Flotation cushions | 12436-01())L1 | | 00-20 |
| ENAC.O.006 | 12/01/2001 | Passenger seats | 15N())-53()))) | | 00-32 |
| ENAC.O.007 | 12/01/2001 | Passenger seats | 15M())-12()))) , 15M())-13 | | 00-23 |
| ENAC.O.008 | 12/01/2001 | Passenger seats | 11P())-76()))) , 11P())-72 | | 00-30 |
| ENAC.O.009 | 12/01/2001 | Passenger seats | 11R())-72()))) 11RZ9-8998()) | | 00-28 |
| ENAC.O.010 | 12/01/2001 | Passenger seats | 15H())-40()))) , 15H())-49 | | 00-07 |
| ENAC.O.011 | 23/02/2001 | Passenger seats | 184())-4E()))) , 184())-6P | | 00-26 |
| ENAC.O.012 | 16/05/2001 | Passenger seats | 159())-05()))) , 159())-15 | | 01-12 |
| ENAC.O.013 | 21/05/2001 | Passenger seats | 153())-15()))) | | 01-03 |
| ENAC.O.014 | 23/05/2001 | Passenger seats | 12A())-10()))) | | 00-25 |
| ENAC.O.015 | 04/06/2001 | Passenger seats | 15L())-12()))) , 15L())-22 | | 00-24 |
| ENAC.O.017 | 18/06/2001 | Passenger seats | 184())-7C()))) , 184())-7F | | 01-04 |
| ENAC.O.018 | 26/07/2001 | Passenger seats | 161())-15()))) | | 01-21 |
| ENAC.O.019 | 06/08/2001 | Passenger Seats | 15R())-53()))) | | 01-22 |
| ENAC.O.020 | 06/08/2001 | Passenger seats | 15P())-12()))) 15P())-13()))) 15P())-49()))) | | 01-20 |
| ENAC.O.021 | 11/10/2001 | Pasenger seats | 160())-10()))) 160())-12()))) 160())-51()))) 160())-52()))) | | 01-25 |
| ENAC.O.023 | 17/01/2002 | Passenger seats | 11T())-32()))) | | 01-33 |
| ENAC.O.024 | 13/02/2002 | Passenger seats | 165())-1E()))) 165())-1H()))) 165())-1L()))) 165())-1M()))) 165())-6E()))) 165())-6G()))) | | 01-26 |
| ENAC.O.025 | 18/02/2002 | Passenger seats | 12E())-01()))) 12E())-10()))) | | 01-27 |
| ENAC.O.026 | 18/02/2002 | Passenger seats | 12F())-01()))) 12F())-10()))) | | 01-32 |

AVIOINTERIORS S.p.A. - VIA NUOVA MARINA 5 80133 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-----------------|--|------------------|---------------|
| ENAC.O.027 | 30/04/2002 | Passenger seats | 16Y()0-10()0000 16Y()0-50()0000 | | 02-02 |
| ENAC.O.028 | 30/04/2002 | Passenger seats | 16Z()0-11()0000 | | 02-03 |
| ENAC.O.029 | 10/05/2002 | Seat cushion | 12303-01()0NW | | 02-07 |
| ENAC.O.032 | 14/01/2003 | Passenger seats | 165()0-3Q()0000 165()0-61()0000 | | 02-28 |
| ENAC.O.033 | 11/02/2002 | Passenger seats | 161()0+16()0000 | | 02-27 |
| ENAC.O.034 | 22/05/2003 | Passenger seats | 150()0-4A()0000 150()0-4C()0000 150()0-4E()0000 | | 03-01 |
| ENAC.O.035 | 18/07/2003 | Passenger seats | 16E()0Z12()0000 | | 03-08 |
| ENAC.O.036 | 18/07/2003 | Passenger seats | 16XE1Z1310QQ 16XE2Z1203QQ 16XE2Z1204QQ 16XE2Z1310QQ 16XE3Z1203QQ 16XE3Z1204QQ 16XE3Z1310QQ | | 03-34 |
| ENAC.O.037 | 18/07/2003 | Passenger seats | 16WE1Z1403QQ 16WE1Z1404QQ | | 03-35 |
| ENAC.O.038 | 03/09/2003 | Passenger seats | 15Z()0Z10()0000 | | 03-07 |
| ENAC.O.039 | 24/09/2003 | Passenger seats | 12L()0Z5C()0000 12L()0Z5E()0000 12L()0Z5F()0000 | | 03-05 |
| ENAC.O.040 | 26/09/2003 | Passenger seats | 12K()0Z50()0000 12K()0Z51()0000 12K()0Z53()0000 | | 03-06 |
| ENAC.O.041 | 26/09/2003 | Passenger seats | 12HA1-3006XE 12HA1-3007XE 12HA1-6402XE 12HA1-6403XE 12HA1-6502XE 12HA1-6503XE 12HA2-3008XE 12HA2-3009XE 12HA2-6404XE 12HA2-6405XE 12HA2-6504XE 12HA2-6505XE 12HA3-6701XE 12HA3-6801XE 12HA4-6711XE 12HB1-3006XE 12HB1-3007XE 12HB1-6402XE 12HB1-6403XE 12HB1-6502XE 12HB1-6503XE 12HB2-3008XE 12HB2-3009XE 12HB2-6504XE 12HB2-6505XE 12HB3-6701XE 12HB3-6801XE 12HB4-6711XE 12HB5-6402XE 12HB5-6403XE 12HB6-6404XE 12HB6-6405XE 12HB7-6701XE 12HB8-6711XE | | 02-20 |
| ENAC.O.042 | 26/09/2003 | Passenger seats | 186V1-6462XE 186V1-6463XE 186V2-6768XE 186W1-6462XE 186W1-6463XE 186W2-6768XE 186W3-6462XE 186W3-6463XE 186W4-6768XE | | 02-29 |
| ENAC.O.043 | 26/09/2003 | Passenger seats | 12JA1-6602XE 12JA1-6603XE 12JB1-6602XE 12JB1-6603XE | | 02-21 |

AVIONIK STRAUBING ENTWICKLUNGS GmbH - FLUGPLATZSTRASSE 5 94348 ATTING GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------|----------------------------------|------------------|------------------|
| EASA.210.1231 | 03/08/2009 | Altitude Preselect System APS4A | AS01-ALTPRE(-) AS02-ALTPIB(-) | C9c C52b | APS 1005 APS 001 |

AVIONIK STRAUBING ENTWICKLUNGS GmbH - FLUGPLATZSTRASSE 5 94348 ATTING GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|-----------------|
| EASA.210.356, REV. B | 08/04/2009 | Fuel Quantity Indication System, FQIS Series 300 | AS02-FQC(-)(-) AS02-FQH(-)(-) AS02-FQL(-)(-) AS02-FQS(-)(-) | C55 | AS94-FQISDDP-05 |

AVOX SYSTEMS Inc. - 225 ERIE STREET 14086 LANCASTER USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---------------|------------------|---------------|
| EASA.IM.210.10030373 | 11/06/2010 | 289-301(-) Series Oxygen Mask Assembly | 289-301(-) | C64a | 76 |

AVTECHTYEE, Inc. - 6500 MERRILL CREEK PARKWAY 98203 EVERETT USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------|--------------------|-----------------------------------|---------------|------------------|---------------|
| LBA.N-O.10.952/71 JTSO | 13/12/2000 | Display Switching Unit DSU 6001-1 | 6001-1[] | | |

AXITUDE S.R.L. - VIA VINCENZO ARANGIO RUIZ 83 80122 NAPOLI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--------------|---------------------|------------------|---------------|
| EASA.210.931 | 14/01/2008 | AHRS AX1-[] | AHRS1000RS1-01.(XX) | C4c C6d | 07.001.AX1 |

BARCO N.V. - PRESIDENT KENNEDY PARK 35 8500 KORTRIJK BELGIUM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|------------------|--------------------------------|
| EASA.210.463 | 30/01/2006 | MFD-6.8/1-PL02 Primary Flight Display | V9550060A(-)(-) | C113 | P-0308-SDRL-MFD-6.8/1-PL02-2.4 |
| EASA.210.627 | 16/09/2009 | DU-885 Flight Display | K9321061A(XX)(XX) | C113 | P0616-SDRL-DU-885-056 |
| EASA.210.810 | 16/08/2007 | KDU-1080 | K9321022A(YY)(XX) | C113 | P0526-SDRL-KDU-1080-131 |
| EASA.210.1000 | 29/02/2008 | KDU-1500 | K9321023A(XX)(XX) | C113 | P0527-SDRL-KDU-1500-137 |
| EASA.210.1087 | 12/01/2010 | CDMS 3100 Control Display Management System | K9321051A(XXX)(XX) | C113 | P0705-DDP-CDMS-3100 |
| EASA.210.628, REV. A | 24/11/2009 | DU-875 | K9321060A(YY)(XX) | C113 | P0615-SDRL-DU-875-056 |
| EASA.210.10028455 | 13/01/2010 | CDMS-3000 Control Display and Management System | AND K9321050A010-(XX) EXCLUDING K9321050A000-(XX) K9321050A(XXX)(XX) | C113 | P0705-DDP-CDMS-3000-002 |
| EASA.210.10046760 | 18/10/2013 | CHDD-268 10" Cockpit Head Down Display | K9321038A(XXX)(XX) | C113 | P0580-DDP-CHDD-268 |
| EASA.210.10048240 | 24/02/2014 | MFD-2068-01 | K9321100A(XXX)(XX) | C113 | P1201-DDP-MFD-2068-01 |
| EASA.210.10051317 | 21/11/2014 | Display Unit DU-1200 | K9323030A(XXX)(XX) | C113 | P1203-DDP-DU-1200 |
| EASA.210.1162, REV. A | 09/11/2009 | CDMS-3000 / Control Display and Management System Display Un | K9321050A000-(XX) K9321050A010-(XX) | C113 | P0705-DDP-CDMS-3000-001 |

B/E AEROSPACE FISCHER GMBH - MUELLER-ARMACK-STRASSE 4 84034 LANDSHUT GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---|-------------------|---------------|
| EASA.210.152 | 18/08/2004 | Attendant Seat Type: 15/14 | 0302(-)(-) | C127a | D0302-010 |
| EASA.210.201 | 24/11/2004 | F + E Executive Seat Type: 14/16 | 0306-000(-) | C127a | D0306-010 |
| EASA.210.202 | 24/11/2004 | F + E Executive Seat Type: 356/406 | 0307(-)(-) | C127a | D0307-010 |
| EASA.210.213 | 15/12/2004 | F + E Executive Seat Type 14/22 | 0303(-)(-) | C127a | D0303-010 |
| EASA.210.298 | 01/07/2005 | F + E Executive Seat, Type 14/22-s | 0304-000(-) | C127a | D0304-010 |
| EASA.210.303 | 04/07/2005 | F+E Passenger Seat Type 330/588 | 0315-0(-) | C39b | D0315-010 |
| EASA.210.304 | 04/07/2005 | F+E Passenger Seat Type 330/352 | 0314-0(-) | C39b | D0314-010 |
| EASA.210.596 | 28/11/2006 | F+E Seat 330/315 H140 | 0516(-)(-) | C127a | D0516-010 |
| EASA.210.601 | 05/12/2006 | 180/260 H140 Helicopter Seat | 0520(-)(-) | C127a | D0520-010 |
| EASA.210.633 | 21/05/2007 | Troop Seat 1410C | 0702(-)(-) | C127a | D0702-010 |
| EASA.210.811 | 04/08/2008 | Passenger Seat 350/280 | 0623-0(-)(-) | C127a | D0623-010 |
| EASA.210.812 | 11/09/2007 | Passenger Seat 250/406-3 | 0706(-)(-) | C39b | D0706-010 |
| EASA.210.852 | 14/03/2008 | Executive Seat 13/17 Armored | 0630(-)(-) | C127a | D0630-010 |
| EASA.210.1264 | 01/03/2011 | Common Seat 170/260 H160 | 0718(-)(-)(-) | C127a | D0718-010 |
| EASA.210.10030370 | 11/06/2010 | Crew Seat 279/363 H178 | 0820(-)(-) | C127a | D0820-010 |
| EASA.210.10032678 | 23/11/2010 | Crew Seat 387/310 H127 | 0909(-)(-)(-) | C127a | D0909-010 |
| EASA.210.10033803 | 10/02/2011 | Passenger Seat 185/410 | 9507(-)(-) | TSO-C127 Other | D9507-010 |
| EASA.210.10037248 | 14/11/2011 | Passenger Seat 12/13-T | 0914(-)(-)(-) | C127a | D0914-010 |
| EASA.210.10037280 | 16/11/2011 | Passenger Seat 12/13 | 0931(-)(-)(-) | C127a | D0931-010 |
| EASA.210.10037590 | 08/12/2011 | Common Seat 145 | 0923(-)(-)(-) | C127a | D0923-009 |
| EASA.210.10042168 | 13/11/2012 | Attendant Seat NG | 1021(-)A(-) 1021(-)B(-) 1021(-)C(-) | C127a | D1021-010 |
| EASA.210.10045165 | 04/06/2013 | Foldable Seat 1214 | 0804(-)(-)(-) | C39c | D0804-010 |
| EASA.210.10047393 | 09/12/2013 | Crew Seat 315/330 H140 | 1111(-)(-)(-) | C127a | D1111-010 |
| EASA.210.10048959 | 28/04/2014 | Passenger Seat 350/406 | 1305(-)(-)(-) | C127a | D1305-010 |
| EASA.210.10050424 | 09/09/2014 | F+E SEAT 364/140 NG // Passenger Seat for Rotorcrafts | 1404(-)(-)(-) | C39c | D1404-010 |
| EASA.210.10050954 | 28/10/2014 | F+E SEAT 364/140 NG // Passenger Seat for Rotorcrafts | 1404-A(-)(-) | C127a | D1404-010 |
| EASA.210.10052345 | 19/02/2015 | PILOT SEAT 330/355 H203 / Crew Seat for Transport Aircraft | 1114(-)(-)(-)(-) | C127a | D1114-010 |
| EASA.210.10053021 | 20/04/2015 | Executive Seat // Seat Model 356/406 NG Passenger Seat for H | 0802(-)(-)(-)(-) | C127a | D0802-010 |
| EASA.210.10054609 | 01/09/2015 | VIP SEAT 290/406 - Passenger Seat for Helicopters | 1317(-)(-)(-)(-) | C127a | D1317-010 |

B/E AEROSPACE FISCHER GMBH - MUELLER-ARMACK-STRASSE 4 84034 LANDSHUT GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|------------------|------------------|---------------|
| EASA.210.10043979, REV. B | 26/03/2013 | F+E Seat 364/140 | 0904-()-()-() | C127a | D0904-010 |
| ETSOA.210.10054933 | 01/10/2015 | Passenger Seat 120/335/6 // Passenger Seat for Helicopters | P/N 1403-A-()-() | C127a | D1403-010 |
| LBA.O.11.112/01 JTSO | 26/04/2002 | Pilot Seat Type: 225/355 H165 | 9916-0-() | | D9916-010 |
| LBA.O.11.112/2 JTSO | 10/09/2003 | F+E Seat 230/260 H110 SU | 0310-()-() | | D0310-010 |
| LBA.O.30.131/117 JTSO | 28/03/2001 | Pilot Seat Type: 120/335 | 9911-()-() | | D9911-010 |

B/E AEROSPACE, Inc. - 1400 CORPORATE CENTER WAY 33414 WELLINGTON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|--|---|------------------|----------------|
| EASA.210.092 | 16/06/2004 | 980-()-() Aircraft Passenger Seat | 1003815-XXX 1003817-XXX | C39b | 03-023 |
| EASA.210.159 | 16/09/2004 | CV3.6-()-(); CV3.7-()-(); CV3.8-2()- Forward Facing Pa | 115297-03 115297-05 115298-03 115298-05 115298-07 115301-04 115301-06 115302-04 115302-06 115309-02 | C39b | 04-020 |
| EASA.210.273 | 02/05/2005 | BE1.0 Series Seats - Aircraft Passenger Seat | BE1.0-()-() | C39b | 05-12 |
| EASA.IM.210.720 | 26/04/2007 | Spectrum 2, Tourist Class Seat | 986-()-() | C127a | 07-012 |
| EASA.210.037, REV. A | 10/06/2014 | Model No. 980-()-() Forward Facing Passenger Seats | 1004247-()-() 1004248-()-() 1006367-()-() | C127a | 04-003 |
| EASA.210.278, REV. A | 18/06/2010 | 986-()-() Spectrum Convertible Series Seat | 986-()-() | C39b | 05-007 ISSUE 2 |
| EASA.IM.210.1232 | 15/06/2009 | 3A()JF()207() Double Seats | 3A()JF()207()() | C127a | 53506 |
| EASA.IM.210.573, REV. C | 06/12/2011 | BE8.()-() MiniPod Premium Class Seat | 1005830-XXX 1005831-XXX 1005834-XXX 1014301-XXX | C127a | 06-032 |
| EASA.IM.210.10027760 | 29/10/2009 | 3AAF0254() Forward Facing single seat | 3AAF0254() | C127a | 53541 DDP |
| EASA.IM.210.10035755 | 18/07/2011 | B/E Spectrum Seats | 3A()JF()221()() 3A()JF()321()() 3A()JF()421()() | C127a | 54060 |
| EASA.IM.210.10036014 | 05/08/2011 | Forward/Aft Facing Double Seat | 3A()JF()237()() | C127a | 54026 |
| EASA.IM.210.10038617 | 02/03/2012 | 2523.541() Divan | 2523.541() | C39c | 54216DDP |
| EASA.IM.210.10038801 | 15/03/2012 | 2523.500() Side-facing Divan | 2523.500() | C39c | 51367DDP |
| EASA.IM.210.10039251 | 20/04/2012 | 3D()JF()103() One Place Divan | 3D()JF()103()() | C39c | 53840DDP |
| EASA.IM.210.10040790 | 26/07/2012 | 3A()JF()232() Double Seat | 3A()JF()232() | C127a | 54164A |
| EASA.IM.210.10041574 | 04/10/2012 | 3AAF0252() Single Seat, Forward Facing and 3AAF0253() Double | 3AAF0252(), 3AAF0253() | C127a | 53686 DDP |
| EASA.IM.210.10042054 | 06/11/2012 | BE16.2-()-() Seats | 1016261-(), 1016262-() | C39c | 12-036 |
| EASA.IM.210.10042514 | 06/12/2012 | 3A()JF()311() Triple Seat | 3A()JF()311()() | C39c | 54059DDP |
| EASA.IM.210.10044023 | 13/03/2013 | 3A()JF()227() Forward/Aft Facing Double Seat | 3A()JF()227()() | C39c | 54384 |
| EASA.IM.210.10045143 | 03/06/2013 | BE14.1-()-() Seat | 1009407-() | C39c | 13-006 |
| EASA.IM.210.10045428 | 25/06/2013 | 3A()JF()213() DOUBLE SEAT | 3A()JF()213()() | C127a | 54194DDP |
| EASA.IM.210.10045768 | 17/07/2013 | Forwarding Facing Single and Double Seat | 3AAF0255()(), 3AAF0256()() | C127a | 53980DDP |
| EASA.IM.210.10045902 | 29/07/2013 | 2523.523.01-() and 2523.588.01-() 3-Place Tracking Divan | 2523.523.01-03 2523.588.01-03 | C39c | 54350DDP |
| EASA.IM.210.10047258 | 28/11/2013 | BE16.5-()-() Seats | 1013432-() | C127a | 13-029 |
| EASA.IM.210.10047347 | 04/12/2013 | 3-Place Side Facing Divan | 2523.586.01-() | C39c | 54335DDP |
| EASA.IM.210.10047349 | 04/12/2013 | 3D()JF()104() One Place Forward Facing Divan Assembly3 | 3D()JF()104()() 3D()JF()105()() | C127a | 53855DDP |
| EASA.IM.210.10047434 | 11/12/2013 | Seat Model No. BE17.1-()-() | 1016301-() | C39c | 13-023 |
| EASA.IM.210.10049018 | 02/05/2014 | Model Number 3A()JF()106() Forward Facing Single Seat - | 3A()JF()106()() | C127a | 53491DDP |
| EASA.IM.210.10050415 | 08/09/2014 | Seat Model 3A()JF()1176() // Forwarding Facing Single Se | 3AJF1176501 3AJF1176503 3AJF1176505 3AJF1176507 | C127a | 54344DDP |
| EASA.IM.210.10050686 | 01/10/2014 | Forward Facing Double Seat | 3A()JF()206()() | C127a | 54426 |
| EASA.IM.210.10051904 | 14/01/2015 | 3A()F()205() // Forward facing Double Seat Assembly | 3A()F()205()() | C127a | 54341 |
| EASA.IM.210.10052178 | 06/02/2015 | BE7.2-()-() // Forward Facing Seats | 1011001-001 1011001-002 1011001-003 1011001-004 1011001-005 1011001-006 1011001-101 1011001-102 1011002-003 1011002-007 1011002-101 | C127a | 08-032 |
| EASA.IM.210.10054661 | 03/09/2015 | One Place Forward Facing Divan, One Place Aft Facing Divan | 3D()JF()114()(), 3D()JF() | C39c | 54682DDP |

| B/E AEROSPACE, Inc. - 1400 CORPORATE CENTER WAY 33414 WELLINGTON USA | | | | | |
|--|--------------------|--|---|------------------|------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10055138 | 15/10/2015 | 3A(JF()179()) // Forward Facing Single Seat | 3A(JF()179()) | C127a | 54663DDP |
| EASA.IM.210.10055139 | 15/10/2015 | 3D(F()109()), 3D(F()110()) // One Place Forward Facing D | 3D(F()109()) 3D(F()110()) | C127a | 53548DDP |
| EASA.IM.210.10055639 | 25/11/2015 | One Place Side Facing Divan | 3D(JF()108()) | C39c | 54680 |
| CAA.N-O.00001 | 08/04/2003 | 980-DS125()-() | 1003280-XXX | | 03-007 |
| EASA.IM.210.10031576, REV. A | 16/07/2014 | Seat Model No. BE 15.0-()-() V-Concept Diamon | 1012121-005EJ04 1012121-006EJ04 1012121-009EJ04 1012121-021EJ04 1012121-022EJ04 1012121-023EJ04 1019801-001EJ08 1019801-002EJ08 1019801-003EJ08 1019801-004EJ08 1019801-005EJ08 1019801-006EJ08 1019801-007EJ08 1019801-103EJ08 1019801-104EJ08 1019801-105EJ08 1019801-106EJ08 1019801-111EJ08 1019801-205EJ08 1019801-206EJ08 1019801-211EJ08 1019801-213EJ08 1019801-214EJ08 1019801-215EJ08 1019801-216EJ08 1019801-217EJ08 1019801-218EJ08 | C39b | 10-015 |
| EASA.IM.210.10034318, REV. D | 18/02/2015 | TYPE A / BE16.0-()-() Pinnacle Forward Facing Seat | 1012660-() 1012661-() 1018140-() 1024361-() 1024365-() 1025261-() 1025262-() 1025263-() 1025264-() 1028589-() 1042882-() 1042885-() | C127a | 13-020 |
| EASA.IM.210.10038144, REV. B | 13/04/2012 | Type A / BE7.3-()-() and BE7.4-()-() Forward Facing Seat | 1010382-(XXXXXXXX) | C127a | 12-015, 12-014 |
| EASA.IM.210.10038156, REV. B | 10/07/2013 | BE15.0-()-() Seats | 1012101-(), 1016401-() 1017401-() | C127a | 11-017, 13-003, 12-042 |
| EASA.IM.210.10042053, REV. A | 06/03/2015 | Forward / Rearward Facing Passenger Seat BE8.1-()-() | 1013040-(), 1013041-() 1014387-(), 1014388-() | C127a | 12-025 |
| EASA.IM.210.10042055, REV. B | 10/11/2015 | TYPE A / BE16.2-()-() // Forward Facing Seats | 1015620-(), 1015621-() 1015622-(), 1015793-() 1015794-(), 1015795-() | C127a | 12-037 + 12-029 |
| EASA.IM.210.10042516, REV. A | 31/10/2014 | 3A(JF()104()) Single Seat | 3A(JF()104()) | C39c | 53246DDP |
| EASA.IM.210.10048812, REV.A | 13/02/2015 | BA3.15-()-() / Forward Facing Seats | 1029841-() () () () () 1029842-() () () () () 1029843-() () () () () 87944() () () () () 87945() () () () () 87946() () () () () | C127a | 04-001 |
| EASA.IM.210.10049017, REV. A | 22/10/2014 | 3A(JF()217()) // Fwd/Aft Facing Double Seat | 3A(JF()217()) | C39c | 54624DDP |
| EASA.IM.210.10049868, REV. D | 02/11/2015 | Model No. BE14.1-()-() Diamond Forward Facing Seats | 1018001-() 1021821-() 1030990-() 1048001-() 1048001-001MJ02 1048001-002MJ02 1048001-003MJ02 1048001-101MJ02 1048001-102MJ02 1048001-103MJ02 1048001-201MJ02 1048001-202MJ02 1048001-203MJ02 1051718-() | C127a | 14-015 |
| EASA.IM.210.1233, REV. A | 31/10/2014 | 3A(JF()107()) // Fwd/aft Facing Single Seat | 3A(JF()107()) | C127a | 54609 |
| ETSOA.IM.210.10054287, REV. A | 02/11/2015 | TYPE A / BE17.2-()-() // Side Facing Seats | 1031301-() | C39c | 15-012 |

B/E AEROSPACE, Inc. - 1400 CORPORATE CENTER WAY 33414 WELLINGTON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|--------------------------------------|---|--------------------|---------------|
| LBA.N-O.30.131/112 JTSO | 27/04/2000 | Convertible Seat Type: CV1.1-()-() | 87282-001 87282-011 87282-013 87282-107 | JTSO-C39B Other | 99-001 |
| LBA.N-O.30.131/113 JTSO | 27/04/2000 | Convertible Seat Type: CV1.2-3-() | 87283-002 87283-006 87283-016 87283-018 87283-108 | JTSO-C39B Other | 99-008 |

B/E AEROSPACE SYSTEMS GmbH - REVALSTRASSE 1 23560 LUEBECK GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|-----------------------------|--------------------|---|
| EASA.21O.10033740 | 08/02/2011 | Crewmember Protective Breathing Equipment OXYCREW. | E28180-10 E28180-XX-YYYY | JTSO-C116 Other | E28180-10-C116 REV. 3 E28180-XX- YYYYP1 REV. 0 |
| EASA.21O.10046318 | 09/09/2013 | Oxygen Mask Assembly | E75000-(XX)-(YYYY) | C64a | E75000-XX-YYYY DP1 |
| LBA 40.110/27 NTS | 24/07/2001 | Generic Gaseous Passenger Oxygen System PNR E62800-00-Series | E62800-00-() | | E62800-00 DP1 |

B/E AEROSPACE (UK) Ltd. - GROVEBURY ROAD LU7 4TB LEIGHTON BUZZARD UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|--|------------------|------------------|
| EASA.21O.014 | 26/05/2004 | BA4.0-()-() Aircraft Passenger Seat | 87269604 87269605 87269704 87269705 | C39b | 868 |
| EASA.21O.155 | 01/09/2004 | 640002() Series - Passenger Seats | 640002() | C39b | 640/2 |
| EASA.21O.300 | 04/07/2005 | Passenger Seat Model AA2 () Skyluxe II | AA100(XXX) | C127 Other | AA2 |
| EASA.21O.1161 | 16/09/2009 | 980F-()-() Seat - Passenger Forward Facing | 1010859-101JB01 1010859-102JB01 1010860-101JB01 1010860-102JB01 | C127a | 980F-()-() |
| EASA.21O.1292 | 04/02/2010 | CAS1 - () - () Cabin Attendant Seat | CAS1 - () - () | C127a | CAS1 - () - () |
| EASA.21O.10035610 | 04/07/2011 | Seat Model BA3.4-()-(), Innovator 2 | 87449031AW02 87449032AW02 87449033AW02 87449034AW02 87449036AW02 87449037AW02 87449038AW02 87449039AW02 87449041AW02 87449043AW02 87449048AW02 87449050AW02 87449121AW02 87449122AW02 87449123AW02 87449124AW02 87449125AW02 87449126AW02 87449127AW02 87449128AW02 87450103AW02 87450104AW02 | C127a | BA3.4-()-() |
| EASA.21O.10046374 | 13/09/2013 | Passenger Seat Model AA2 () Skyluxe II | AA100(XXX) | C127 | 878 |

BECKER AVIONICS GmbH - BADEN AIRPARK, BUILDING B 108 77836 RHEINMUENSTER GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|--|------------------|---------------|
| EASA.21O.056 | 16/06/2004 | Transponder ATC5401 | ATC5401-1R-() | C74d | 62 |
| EASA.21O.322 | 12/08/2005 | Mode S Transponder System, BXP6400 | AM6400-1-() BXP6401-1-() BXP6401-2-() BXP6402-1R-() BXP6402-2R-() CU6401-1-() | 2C112a | 70 |
| EASA.21O.443 | 22/12/2005 | Digital Voice Communication System DVCS6100 | ACU6100-1-() ACU6100-2-() REU6100-2-() REU6100-3-() | C50c | 75 |
| EASA.21O.658 | 28/02/2007 | BE6400-01 Altitude Blind Encoder | BE6400-01-() | C88a | NO. 76 |
| EASA.21O.717 | 21/09/2007 | Mode S Transponder BXP6403-1 | BXP6403-1-() BXP6403-2-() MK6403-1 RFA6403-1 | 2C112b | 70 |

BECKER AVIONICS GmbH - BADEN AIRPARK, BUILDING B 108 77836 RHEINMUENSTER GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|---|---------------|
| EASA.210.738 | 16/05/2007 | NAV3300 | CU3300-()-01, CU3300-()-02 DC3300-() IN3300-()-01, IN3300-()-02 NR3300-()-01, NR3300-()-02 NR3301-()-01, NR3301-()-02 RM3300-() | TSO C34D TSO C35D TSO C36D TSO C40B Other | NO. 20 |
| EASA.210.1163 | 12/07/2010 | MKR3300-1 Marker Receiver | MKR3300-1-() | 2C35d | 81 |
| EASA.210.10031765 | 10/09/2010 | ACU6101 Control Unit | ACU6101-1-() ACU6101-2-() | C50c | 75 |
| EASA.210.10038538 | 24/02/2012 | AR4201 VHF Transceiver | AR4201-() CM4201-() | JTSO 2C37D JTSO 2C38D *) Other | 31 |
| EASA.210.10054849 | 23/09/2015 | AR6203-(XXX) VHF-Transceiver | AR6203-(XXX) | 2C169A Other | 86 |
| EASA.210.1249, REV. A | 22/05/2015 | AR6201 VHF-Transceiver, RCU6201 VHF-Transceiver Remote Contr | AR6201-() RCU6201-() RT6201-() | 2C37e 2C38e | 82 |
| LBA.O.10.530/001JTSO | 13/06/2003 | RMU-5000 Radio Management Unit | RMU5000-1-1100, RMU5000-1-2110 | | 59 |
| LBA.O.10.530/002JTSO | 13/06/2003 | RMU-5000 Radio Management Unit | RMU5000-2-1110, RMU5000-2-2110 | | 59 |
| LBA.O.10.550/1 JTSO | 27/11/2000 | DP4100 | DP4100-(XXX) | | |
| LBA.O.10.911/87 JTSO | 08/02/2000 | AR 4201 | AR 4201 | | 31 |
| LBA.O.10.911/96 JTSO | 08/02/2000 | AR 3209 | AR3209-(XX)-(XXX) | | 36 |
| LBA.O.10.911/99 JTSO | 08/02/2000 | RT 3209 and CU 5209 | CU5209-(X)-(XXX) RT3209-(XX) | | 42 |
| LBA.O.10.921/53 JTSO | 08/02/2000 | ADF 3500 System | AC 3503-(X) AC 3504-(X) AD 3502-(X)-(XX) AN 3500 CU 3502-(X)-(XX) CU 5502-(X)-(XXX) ID 3502-(X)-(XX) RA 3502-(XX) VR 3001-(X) | | 32 |
| LBA.O.10.922/89 JTSO | 29/07/1999 | VOR/ILS/MKR System NAV 900 | CU 900-()-XX NR 900-()-XX | | 40 |
| LBA.O.10.922/94 JTSO | 08/02/2000 | VOR/ILS Systems NAV 5300 | CU 5301-(X)-(XXX) NR 3320-(XX)-(XXX) NR 3330-(XX)-(XXX) RN 3320-(XX) RN 3330-(XX) | | Release |
| LBA.O.10.930/062 JTSO | 20/03/2002 | Transponder ATC 4401 | ATC 4401-1-175 ATC 4401-1-250 ATC 4401-2-175 ATC 4401-2-250 | | 57 |
| LBA.O.10.930/49 JTSO | 08/02/2000 | Transponder ATC 3401 | ATC 3401-(XXX) | | 33 |
| LBA.O.10.930/54 JTSO | 08/02/2000 | Transponder ATC 2000-(3)-R(XX) | ATC 3401-1-R CU 3400-1-(XX) CU 5401-1-(XXX) PC 2000-(X) | | 41 |

BECKER AVIONICS, Inc. - 10376 USA TODAY WAY 33025 MIRAMAR USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|------------------|---------------|
| EASA.IM.210.10045685 | 12/07/2013 | Digital Voice Communication System DVCS6100 | ACU6100-1-(), ACU6100-2-() CSW6100 REU6100-1-(), REU6100-2-() | C139 | 75 |

BERINGER AERO S.A.S. - AEROPOLE 05130 TALLARD FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|---|------------------|----------------|
| EASA.210.10042170 | 13/11/2012 | Nose wheel 8.90-12.5" | RA-008(-) | C26c | DDP-ETSO-003 |
| EASA.210.10054392 | 11/08/2015 | 18X5.5 // EA-008.1N(-) // EA-008.2N(-) // RF-010(-) | EA-008.1N(-) BRAKE EA-008.2N(-) BRAKE RF-010(-)18X5.5 WHEEL | C26c | DDP-ETSO-004 |
| EASA.210.10040509, REV. A | 09/07/2013 | 5.00-5 Wheel and Brake Assembly | EA-002.2N(-) BRAKE ASSEMBLY RF-005(-) MAIN WHEEL | C26c | DDP-ETSO-002.2 |
| EASA.210.10040511, REV. A | 09/07/2013 | 5.00-5 Wheel and Brake Assembly | BRAKE ASSEMBLY EA-002N(-) MAIN WHEEL RF-005(-) | C26c | DDP-ETSO-002.1 |
| EASA.210.10043365, REV. A | 29/05/2013 | Main wheel with Brake 6.00-6" Tubeless | BRAKE EA-003N(-) WHEEL RF-006(-) | C26c | DDP-ETSO-001.1 |
| EASA.210.10043366, REV. A | 29/05/2013 | Main wheel with Brake 6.00-6" Tubeless | BRAKE EA-003.3N(-) WHEEL: RF-006(-) | C26c | DDP-ETSO-001.2 |
| EASA.210.10043367, REV. A | 29/05/2013 | Main wheel with Brake 6.00-6" Tubeless | BRAKE: EA-003.4N(-) WHEEL: RF-006(-) | C26c | DDP-ETSO_001.3 |
| EASA.210.1145, REV. A | 29/05/2013 | Nose Wheel 6.00-6" tubeless | RA-005(-) | C26c | DDP-ETSO-001 |
| EASA.210.1146, REV. A | 09/07/2013 | 5.00-5 Nose Wheel | RA-002(-) NOSE WHEEL | C26c | ETSO-002 |

BIRDY - BÂTIMENT 3418 MODULE C 6 RUE DES PO 93290 TREMBLAY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
| F.O.124 | 10/09/2003 | Cargo Net | 2M2N-01-00 | | PR 09/2M2N 0 |

BOSE CORPORATION - THE MOUNTAIN 01701-9168 FRAMINGHAM USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

BOSE CORPORATION - THE MOUNTAIN 01701-9168 FRAMINGHAM USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|--|------------------|---------------|
| EASA.IM.210.10046405, REV. A | 21/04/2015 | BOSE A20 AVIATION HEADSET // Communication Headset | 324843-() 327070-() (EQUIPMENT PART NUMBER) (SHIPSET PART NUMBER) | C139 | CE346333 |

BRICE MANUFACTURING COMPANY, Inc. - 623 RADAR ROAD 27410 GREENSBORO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|--|------------------|---------------|
| EASA.210.057 | 16/06/2004 | Seat Model B1010 | 70615-401-() 70615-402-() 70616-451-() 70616-452-() 70617-451-() 70617-452-() 70618-451-() 70618-452-() 70618-453-() 70618-454-() 70618-455-() 70618-456-() 70618-463-() 70618-464-() 70619-451-() 70619-452-() 70619-455-() 70619-456-() 70620-451-() 70620-452-() 70621-451-() 70621-452-() | C39b | B1010-012 |
| EASA.210.110 | 28/06/2004 | Seating Systems, Type A, Forward Facing Model:B1000 | 70636-451-() 70636-452-() 70636-454-() | C127a | B100-014 |
| EASA.210.111 | 28/06/2004 | Seating Systems, Type A, Forward Facing Model:B2054 | 70640-401-001 70640-402-001 70640-403-001 70640-404-001 | C127a | B2054-015 |
| LBA.N-O.30.131/115 JTSO | 05/01/2000 | Economy passenger seat Model B 1000 | 70545-4XX-() 70546-4XX-() 70547-4XX-() 70548-4XX-() | | B1000-001 |

BRIDGESTONE CORPORATION - KYOBASHI 1-CHOME, CHUO-KU 10-1 1048340 TOKYO JAPAN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|--|---------------|------------------|---------------|
| EASA.IM.210.337 | 09/09/2005 | Aircraft Tyre for A340-500/-600 MLG/CLG and A380 MLG 1400x53 | APR06912 | C62d | EAQT 04-01 |
| EASA.IM.210.338 | 09/09/2005 | Aircraft Tyre for A340-500/-600 NLG 45x18.0R17 36PR | APR06800 | C62d | EAQT 04-02 |
| EASA.IM.210.339 | 09/09/2005 | Aircraft Tyre for A380 NLG 1270x455R22 32PR | APR07011 | C62d | EAQT 04-03 |
| EASA.IM.210.469 | 01/03/2006 | APS06030 - H44.5x16.5-21 30PR 48400LBS 235MPH | APS06030 | C62d | EAQT05-01 |
| EASA.IM.210.470 | 01/03/2006 | APS06017 - H44.5x16.5-21 28PR 44700LBS 235MPH | APS06017 | C62d | EAQT05-02 |
| EASA.IM.210.471 | 01/03/2006 | APR05102 - 27x7.75R15 12PR 9650LBS 235MPH | APR05102 | C62d | EAQT05-03 |
| EASA.IM.210.534 | 11/07/2006 | APR07642 - 50x20.0R22 34PR 61525LBS 235MPH | APR07642 | C62d | EAQT06-01 |
| EASA.IM.210.535 | 11/07/2006 | APR06700 - 40x16.0R16 26PR 31475LBS 235MPH | APR06700 | C62d | EAQT06-02 |
| EASA.IM.210.771 | 21/08/2007 | 1400X530R23 40PR 74950LBS 245 MPH Aircraft Tyre | APR06920 | C62d | EAQT 07-02 |
| EASA.IM.210.772 | 21/08/2007 | 45 X 18.0R17 36PR 50300LBS 245 MPH Aircraft Tyre | APR06820 | C62d | EAQT 07-01 |
| EASA.IM.210.828 | 14/11/2007 | 52X21.0R22 36PR 66500LBS 235 MPH Aircraft Tire | APR07740 | C62d | EAQT 07-03 |
| EASA.IM.210.900 | 07/01/2008 | H44.5x16.5-21 28PR 44700LBS 235 MPH Tire | APS06020 | C62d | EAQT 07-04 |
| EASA.IM.210.901 | 07/01/2008 | H44.5x16.5R21 30PR 48400LBS 235MPH Tire | APR04130 | C62d | EAQT 07-05 |
| EASA.IM.210.1144 | 12/12/2008 | 52 X 21.0R22 36PR 66500LBS 245MPH Tire | APR07745 | C62d | EAQT 08-01 |
| EASA.IM.210.1175 | 14/01/2009 | 52x21.0R22 36PR 66500LBS 245 MPH Tire for use on 777-200LR/3 | APR07705 | C62d | EAQT 08-02 |
| EASA.IM.210.1246 | 13/05/2009 | 50x20.0R22 26PR 45200LBS 235MPH Tire | APR07630 | C62d | EAQT 09-01 |
| EASA.IM.210.1285 | 30/09/2009 | Main Landing Gear Tyre 54x21.0R23 38PR 71200LBS 235MPH | APR07840 | C62d | EAQT 09-02 |
| EASA.IM.210.611, REV. A | 12/07/2011 | 1400x530R23 42PR 79300LBS 235MPH Aircraft Tyre | APR06913 | C62d | 11-03 |
| EASA.IM.210.612, REV. A | 23/09/2009 | APR07650 - 50x20.0R22 34PR 61525LBS 235MPH Aircraft Tyre | APR07650 | C62d | EAQT 06-04 |
| EASA.IM.210.10034830 | 05/05/2011 | 50x20.0R22 34PR 61525LBS 235MPH Aircraft Tyre | APR07660 | C62d | EAQT 11-01 |
| EASA.IM.210.10037160 | 07/11/2011 | 21x7.25R10 12PR 6400LBS 225MPH Tyre | APR01790 | C62d | EAQT 11-05 |

BRIDGESTONE CORPORATION - KYOBASHI 1-CHOME, CHUO-KU 10-1 1048340 TOKYO JAPAN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|---------------|------------------|----------------|
| EASA.IM.21O.10037162 | 07/11/2011 | H38x12.0R19 20PR 25275LBS 225MPH Tyre | APR04790 | C62d | EAQT 11-04 |
| EASA.IM.21O.10037796 | 22/12/2011 | 1400X530R23 40PR 74950LBS 235MPH Tyre | APR06930 | C62d | EAQT 11-07 |
| EASA.IM.21O.10039127 | 11/04/2012 | 1400X530R23 42PR 79300LBS 235MPH Tyre | APR06931 | C62d | EAQT 12-01 |
| EASA.IM.21O.10040416 | 02/07/2012 | 54X21.0R23 38PR 71200LBS 235MPH Tyre | APR07850 | C62d | EAQT 12-02 |
| EASA.IM.21O.10045581 | 19/05/2014 | 30X8.8R15 16PR // 30X8.8R15 16PR 14340LBS 225MPH | APR05145() | C62d | CAQT NO. 03-01 |
| EASA.IM.21O.10046153 | 22/08/2013 | H38 x 13.0R18 20PR 25075LBS 225MPH Tyre | APR04220 | C62e | EAQT 13-02 |
| EASA.IM.21O.10046154 REV. A | 07/08/2015 | Aircraft Tires // APR01220() | APR01220() | C62e | EAQT 13 |
| EASA.IM.21O.10049613 | 24/06/2014 | H41X16.0R20 22PR 32825LBS 225MPH | APR04270() | C62e | EAQT NO. 14-02 |
| EASA.IM.21O.10049614 | 24/06/2014 | H44.5X16.5R21 30PR 48400LBS 235MPH | APR04450() | C62e | EAQT NO. 14-01 |
| EASA.IM.21O.10054194 | 24/07/2015 | 50X20.0R22 34PR 61525LBS 245MPH | APR07675() | C62e | EAQT 15-01 |
| EASA.IM.21O.10033516, REV. B | 28/05/2014 | 52x21.0R22 36PR 66500LBS 235MPH Tyre | APR07750() | C62d | EAQT 10-01 |
| EASA.IM.21O.10034827, REV. A | 02/04/2015 | APR06505 // 1050X39R16 28PR 34200LBS 245MPH | APR06505 () | C62d | EAQT 11-02 |

BRUEGGEMANN GmbH & Co.KG - AM KALKHECK 2 58313 HERDECKE GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-----------------|------------------|---------------|
| EASA.21O.468 | 01/03/2006 | PGS9 Dual Harness Reserve Parachute Assembly | PGS9() () () | C23d | 101-904390 |
| EASA.21O.480 | 09/03/2006 | PGS7 Single Harness Reserve Parachute Assembly | PGS7() () () | C23d | 101-904370 |

CALEDONIAN AIRBORNE SYSTEMS LTD - 17 HANOVER SQUARE W1S 1HU LONDON UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|-----------------|------------------|---------------|
| EASA.21O.259 | 21/03/2005 | ADELTA Beacon System, Model CAS-CPT-900 | 070-0900-000() | 2C91a 2C126 | CAS/DDP/011 |

CHELTON ANTENNAS - 7 CHEMIN VAUBESNARD 91410 DOURDAN FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|-----------------------|-------------------------|-------------------|
| EASA.21O.112 | 16/06/2004 | Three Frequency ELT Antenna | 1327-8(X) | 2C91a 2C126 | 1327-8(X)-002-E |
| EASA.21O.648 | 15/05/2009 | DOUBLE MLS OMNIDIRECTIONAL CAPTURE ANTENNA | 1071-8(X)-(XX) | 2C104a | 1071-84-018 |
| EASA.21O.649 | 22/06/2009 | Passive MLS directional landing antenna | 3602-84-(XX) | 2C104a | 3602-84-019 |
| EASA.21O.657 | 28/02/2007 | Marker / C Band Antenna | 4905-8(X)-(XX) | 2C35d | DDP-4905-89-035 |
| EASA.21O.763 | 01/03/2010 | ATC/DME ANTENNA | 2439-89-XX | 2C66b C74d | DDP-2439-89-028 |
| EASA.21O.764 | 20/11/2009 | GLIDE ANTENNA | 6202-89-(XX) | 2C34f | DDP-6202-89-029 C |
| EASA.21O.769 | 24/11/2009 | LOC/DGPS ANTENNA | 6207-88-(XX) | 2C36f | DDP-6207-88-032 E |
| EASA.21O.865 | 04/03/2010 | VHF/COM ANTENNA | 2438-89-(XX) | 2C37e 2C38e | DDP-2438-89-034 |
| EASA.21O.1041 | 25/05/2010 | VHF ANTENNA | 2441-88-XX | 2C37e 2C38e | DDP-2441-88-051 |
| EASA.21O.10028104 | 01/12/2009 | LOC/DGPS Antenna | 6209-88-(XX) | 2C36f | 6209-88-044 |
| EASA.21O.10028263 | 14/12/2009 | Glide Antenna | 6208-88-(XX) | 2C34f | 6208-88-045 |
| EASA.21O.10031615 | 31/08/2010 | VOR ANTENNA | 3198-88-XX | 2C40c | 3198-88-046 |
| EASA.21O.10044971 | 23/05/2013 | ATC/DME Antenna 2442-88 | 2442-88-(XX) | 2C66b C74d | DDP-2442-88-052 |
| EASA.21O.10048083 | 11/02/2014 | ELT antenna | 2632-82 2632-82-XX | C126a | DDP-2632-82-065 |
| EASA.21O.10053810 | 24/06/2015 | VOR/LOC & GLIDE airborne antenna system P/N 6243-89-XX compo | | 2C34f 2C36f 2C40c | DDP-6243-89-074 |
| EASA.21O.10054799 | 17/09/2015 | VHF Low Profile Antenna | 2448-88-XX | 2C169A Other | DDP-2448-88-076 |
| F.O.015 | 04/07/2000 | Three frequency ELT antenna | 2624-8(X) | | 224/B |
| F.O.016 | 06/07/2000 | MARKER Antenna | 3107-8(X) | | 0937 |
| F.O.017 | 06/07/2000 | ACT/DME Antenna | 2406-8(X) | | |
| F.O.018 | 06/07/2000 | ACT/DME Antenna | 2407-8(X) | | 927 |
| F.O.019 | 06/07/2000 | VHF/COM Antenna | 2409-8(X) | | 927 |
| F.O.041 | 06/03/2001 | VHF Antenna 118-137Mhz | 2820-8(X) | | 2820 |

CHELTON AVIONICS, Inc. - 6400 WILKINSON DRIVE 86301 PRESCOTT USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|---|--|----------------------------------|---------------|
| EASA.IM.21O.693 | 02/07/2007 | CDM-451, FliteLine DME | 400-041181-() | 2C66b | 740-041181 |
| EASA.IM.21O.695 | 16/08/2007 | CVN-251, FliteLine NAV VHF Receiver | 400-048500-() | 2C34f 2C35d 2C36f 2C40c | 740-048500 |
| EASA.IM.21O.704 | 16/08/2007 | CVC-151, FliteLine COM VHF Transceiver | 400-048100-() | 2C37e 2C38e | 740-048100 |
| EASA.IM.21O.711 | 16/08/2007 | FliteLine Control Display | 400-047() | C113 | 740-047056 |
| EASA.IM.21O.10035057 | 23/05/2011 | PIA01 Passenger Intercom Amplifier | PIA01-(XXX) | C139 | 740-057000 |
| EASA.IM.21O.10027191, REV. A | 24/02/2011 | DACS Digital Audio Communication System | ACP5(Y-XXX) AMU50-(XXX) RM01-(XXX) | C139 | DACS/618-0 |

CHELTON FLIGHT SYSTEMS - ONE S-TEC WAY 76067 MINERAL WELLS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------------|--------------------|--|--|--|---------------|
| EASA.IM.210.753, REV. A | 15/07/2013 | Analog Interface Unit AIU-1 | 453-7000 | 2C34f 2C35d 2C36f 2C40c 2C41d C52b 2C87 C146 | CFS-2 |
| EASA.IM.210.1028, REV. A | 28/05/2013 | Integrated Display Unit (IDU) for Electronic Flight Instrume | 401-045500-0101 WITH SW P/N 320-145239-(060)(X) | C2d C4c C6d C8d C10b 2C34f 2C35d 2C36f 2C40c 2C41d C52b 2C87 C110a C113 C118 C119b C146 C147 C151b | 740-045080 |

CHELTON LIMITED - BROOK ROAD BH21 2BJ WIMBORNE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---------------------------------|----------------------------|------------------|---------------|
| EASA.210.509, REV. A | 26/08/2008 | 19-2020K Supersonic TAS Antenna | 19-2020()K() | C147 | 1138-(K)-1/A |
| EASA.210.510, REV. A | 26/08/2008 | 19-2021 Supersonic TAS Antenna | 19-2021()K() | C147 | 1474-19-1/A |
| EASA.210.10036171 | 17/08/2011 | 7-1351 Logic Converter Unit | 7-1351 | 2C37e 2C38e | 1614-7-1 |
| EASA.210.10036172 | 17/08/2011 | 12-5002 Tunable Antenna | 12-5002(XXXX) | 2C37e 2C38e | 1608-12-1 |
| WR00743 (CAA-UK) | 21/07/1997 | 16-21 VHF-Blade Antenna | 16-21B MOD1 16-21B MOD2 | 2C37e 2C38e | 255-(16-21)-1 |

CIMSA INGENIERIA DE SISTEMAS, S.A. - PASEO DE LA CASTELLANA 115 28046 MADRID SPAIN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|----------------|------------------|---------------|
| EASA.210.355 | 21/10/2005 | Personnel Reserve Parachute/RC | 317523-()-XXX | C23d | |
| EASA.210.685 | 03/04/2007 | 4060XX series single harness dual container | 4060XX()-T | C23d | DDP4060XX |

C.N.S. SYSTEMS AB - NYGATAN 25 582 19 LINKOEPING SWEDEN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|-------------------------|---|------------------|---------------|
| LFV: MSU NO.2/03 | 12/06/2003 | 4000/GA VDL Transponder | 4000-09-10 4000-10-10 W. SW -4000-10-3.() 4080-10-10 | | |

CONTOUR PREMIUM AIRCRAFT SEATING - LLANTARNAM PARK INDUSTRIAL ESTATE NP44 3HQ CWMBRAN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|------------------------------|--------------------|------------------|---------------|
| EASA.210.10032482 | 10/11/2010 | Platinum F22X15 Series Seats | F22(X)15-010-(XXX) | C127a | R635 |

CSAFE L.L.C. - 2985 SPRINGBORO ROAD WEST 45439 DAYTON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---------------------------|---------------|------------------|---------------|
| EASA.IM.210.10036406 | 07/09/2011 | CS10-02800 Active ULD RKN | CS10-02800() | C90c | DDP0001 |

DAYTON-GRANGER Inc. - 3299 SW 9TH AVENUE 33315 FORT LAUDERDALE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------------|---------------|------------------|---------------|
| EASA.IM.210.820 | 04/04/2008 | 3 Frequency ELT Antenna ELT10-835-() | ELT10-835-() | 2C91a 2C126 | 10-835-DDP |
| EASA.IM.210.822 | 04/04/2008 | 3 Frequency ELT Antenna ELT10-773-() | ELT10-773-() | 2C91a 2C126 | 10-773-DDP |

DME CORPORATION - 12889 INGENUITY DRIVE 32826 ORLANDO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------|--------------------|-------------|--------------------------------------|------------------|---------------|
| LBA.N-O.10.915/026JTSO | 22/09/2003 | SRB-406 | P3-03-0041-(XX)1 P3-03-0041-(XX)2 | | Y3-04-0002 |

DOKASCH GmbH ALUMINIUMVERARBEITUNG AIR CARGO EQUIPMENT + REPAIR - INDUSTRIEGEBIET FEINCHESWIESE 3 56424 STAUDT GERM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|------------------------------|---------------|------------------|----------------|
| EASA.210.132 | 05/07/2004 | Cargo Pallet Type:DO-08 | 1580-() | C90c | EBL-2004/04-01 |
| EASA.210.149 | 18/08/2004 | Cargo Container Type: RKN | BUD 010 () | C90c | EBL-2004-05-01 |
| EASA.210.455 | 11/05/2006 | Air Cargo Container Type AMD | BUD 008 () | C90c | GB-2005-06-01 |
| EASA.210.494 | 11/05/2006 | RAP Cargo Container | BUD090() | C90c | GB-2005-05-0 |
| EASA.210.10036797 | 07/10/2011 | Aircraft Pallet Net BUN1 | BUN1() | C90c | BUN1() |
| EASA.210.10036799 | 07/10/2011 | Aircraft Pallet Net BUN2 | BUN2() | C90c | BUN2() |
| EASA.210.10037698 | 16/12/2011 | Aircraft Pallet Net BUN4 | BUN4() | C90c | BUN4() |

DOKASCH GmbH ALUMINIUMVERARBEITUNG AIR CARGO EQUIPMENT + REPAIR - INDUSTRIEGEBIET FEINCHESWIESE 3 56424 STAUDT GERM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|----------------------------------|---------------------|--------------------|----------------|
| EASA.210.10037700 | 16/12/2011 | Aircraft Pallet Net BUN3 | BUN3() | C90c | BUN3() |
| EASA.210.10038153 | 24/01/2012 | Aircraft Pallet Net BUN5 | BUN5() | C90c | BUN5() |
| EASA.210.10038154 | 24/01/2012 | Aircraft Pallet Net BUN6 | BUN6() | C90c | BUN6() |
| EASA.210.10038155 | 24/01/2012 | Aircraft Pallet Net BUN7 | BUN7() | C90c | BUN7() |
| LBA.O.11.400/133 JTSO | 16/03/2000 | Air Freight Pallet, Type PLA | BG()04701 | | |
| LBA.O.11.400/144 JTSO | 20/06/1995 | Air Freight Pallet, Type 55"x96" | BGC01381 | | |
| LBA.O.11.400/176 JTSO | 19/10/2000 | Cargo-Container Type: AMP | AMP-BUD 001 () () | | 0900/2 |
| LBA.O.11.400/177 JTSO | 19/10/2000 | Cargo-Container Type: AAP | AAP-BUD 002 () () | | 0900/1 |
| LBA.O.11.400/180 JTSO | 15/12/2000 | Cargo Container Type: AMK | BUD 003 () () | | 1200/1 |
| LBA.O.11.400/181 JTSO | 12/02/2001 | Cargo Container Type: AMJ | BUD 005 () () | JTSO-C90C Other | 1200/2 |
| LBA.O.11.400/187 JTSO | 16/10/2002 | Cargo ContainerType: AKE | BUD 006 () () | | 2002/3 |
| LBA.O.11.400/188 JTSO | 13/12/2001 | Cargo Container Type: AAK | BUD 007 () () | | 1200/3 |
| LBA.O.11.400/189 JTSO | 28/03/2002 | Cargo Pallet Type: HCU6/E | 2116135(-) | | 2002/01 |
| LBA.O.11.400/197JTSO | 05/07/2003 | PZA Cargo Pallett | BUP 160 () | | EBL-2003/05-01 |
| LBA.O.11.400/198JTSO | 25/07/2003 | PGA Cargo Pallett | BUP 200 () | | EBL-2003/05-02 |
| LBA.O.11.400/23 JTSO | 15/05/1997 | Air Freight Pallet, Type DO-11 | 1350(-) | | |
| LBA O.11.400/6JTSO | 12/11/1998 | Lufftrachtpalette DO 12 | 1340(-) | | EBL/3 |

DRUCK LIMITED - FIR TREE LANE LE6 0FH LEICESTER UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|------------------|---------------|
| CAA.O.00004 | 25/10/2001 | 3000 Series Amplified Output Pressure Sensor | PMP 30XX-XXXX PMP 31XX-XXXX PTX 30XX-XXXX PTX 31XX-XXXX | | |

DUKANE SEACOM, Inc. - 3000 TAFT STREET 33021 HOLLYWOOD USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|-----------------------------|------------------|---------------|
| EASA.IM.210.10052328 | 19/02/2015 | DK120/90 90 day Underwater Acoustic Beacon | DK120/90-(), 266-E5542-() | C121b C142a | DK120/90 |
| EASA.IM.210.10052329 | 19/02/2015 | DK100 Series Battery | 810-2042 | C142a | ULD BATTERY |

DUNLOP AIRCRAFT TYRES LIMITED - 40 FORT PARKWAY B24 9HL BIRMINGHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.015 | 26/05/2004 | 22x6.75-10 12PR (DR25525T) - Aircraft Tyre, Tubeless, Nylon | DR25525T | C62d | AT.DDP.586 |
| EASA.210.016 | 26/05/2004 | H36x12.0-18 18PR (DR32118T) - Aircraft Tyre, Tubeless, Nylon | DR32118T | C62d | AT.DDP.588 |
| EASA.210.164 | 01/10/2004 | 22x6.75-10 8PR - Aircraft Tyre, Tubeless, Nylon | DR25526T | C62d | ATDDP 589 |
| EASA.210.197 | 24/11/2004 | 34 x 11 18PR Aircraft Tyre, Tubeless Nylon | DR11970T | C62d | ATDDP 592 |
| EASA.210.198 | 24/11/2004 | H38x12.0 - 18.425 18PR Aircraft Tyre, Tubeless Nylon | DR32518T | C62d | ATDDP 591 |
| EASA.210.199 | 24/11/2004 | H38x12.0 - 19. 20PR Aircraft Tyre, Tubeless Nylon | DR30820T | C62d | ATDDP 590 |
| EASA.210.235 | 17/01/2005 | H35x11.0-18 20PR Aircraft Tyre - Tubeless Nylon | DR32420T | C62d | AT.DDP.593 |
| EASA.210.236 | 17/01/2005 | H38x13.0-18 18PR Aircraft Tyre - Tubeless Nylon (Retread) | F2A (RETREAD OF DR31018T) | C62d | AT.DDP.574 |
| EASA.210.237 | 17/01/2005 | H35x11.0-18 18PR Aircraft Tyre - Tubeless Nylon | DR32418T | C62d | AT.DDP.594 |
| EASA.210.258 | 15/03/2005 | 16x4.4 8PR - Aircraft Tyre, Tubeless Nylon | DR17026T | C62d | AT.DDP.595 |
| EASA.210.518 | 07/06/2006 | H36x12.0-18 18PR Retread Aircraft Tyre | F2A | C62d | 588 |
| EASA.210.524 | 19/06/2006 | H38x13.0-18 20PR Aircraft Tyre | DR31020T | C62d | DDP599 |
| EASA.210.544 | 31/07/2006 | 20.5x6.75-10 12PR (retread of original P/N DR32212T type cas | F2A | C62d | 587 |
| EASA.210.603 | 12/12/2006 | 18x5.5 10PR Aircraft Tyre | DR9841T | C62d | 600 |
| EASA.210.622 | 13/02/2007 | 43x15.5-17 22PR Aircraft Tyre | DR32622T | C62d | ATDDP 601 |
| EASA.210.623 | 13/02/2007 | 37x14.0-14 22PR Aircraft Tyre | DR20523T | C62d | ATDDP 602 |
| EASA.210.666 | 03/05/2007 | H44.5x16.5-21 28PR Aircraft Tyre | DR29622T | C62d | 603 |
| EASA.210.756 | 21/08/2007 | H43.5x16.0-21 26PR Aircraft Tyre | DR32726T | C62d | AT.DDP.604 |
| EASA.210.899 | 11/03/2008 | H41x16R20 22PR Aircraft Tyre | DZ32922T | C62d | 606 |
| EASA.210.017, REV. A | 06/01/2005 | 20.5x6.75-10 12PR (DR32212T) - Aircraft Tyre, Tubeless, Nylo | DR32212T | C62d | AT.DDP.587 |
| EASA.210.1190 | 14/01/2009 | H41x16.0R20 Radial main aircraft tyre | DZ32923T() | C62d | ATDDP 610 |
| EASA.210.1203 | 27/01/2009 | 450x190-5 Nosewheel aircraft tyre | DR15520T() | C62d | ATDDP 611 |
| EASA.210.1260 | 15/07/2009 | H43.5x16.0-21 F2A retread of DR32726T | F2 (A) RETREAD OF P/N DR32726T | C62d | ATDDP 604 |
| EASA.210.1261 | 07/05/2009 | H36x11.5-19 Mainwheel aircraft tyre | DR33220T() | C62d | ATDDP 614 |
| EASA.210.1270 | 13/07/2009 | H38x13.0-18 F2A retread of DR31020T Retread mainwheel airkra | F2 (A) RETREAD OF P/N DR31020T | C62d | ATDDP 599 |
| EASA.210.1278 | 02/06/2009 | 13.5x4.25-6 Aircraft tyre - Helicopter nosewheel | DR4123T() | C62d | ATDDP 513 |
| EASA.210.1290 | 26/06/2009 | 39x13 Mainwheel aircraft tyre | DR11753T () | C62d | ATDDP 615 |
| EASA.210.513, REV. A | 08/07/2015 | 27X7.75R15 // Nose wheel aircraft tyre | DZ31812T DZ31812T () | C62d | ATDDP598 |
| EASA.210.572, REV. A | 05/09/2008 | H41x16.0-20 22PR Retreaded Aircraft Tyre | F2A RETREAD OF P/N DR31722T F2B RETREAD OF P/N DR31722T | C62d | 585 |
| EASA.210.898, REV. A | 13/01/2010 | 24x7.7R10 16PR Aircraft Tyre | DZ32816T() | C62d | 605 |
| EASA.210.10027846 | 10/11/2009 | 29x11.0-10 Nosewheel aircraft tyre | DR33114T() | C62d | ATDDP 616 |
| EASA.210.10028615 | 28/01/2010 | H34x10.0R16 Main wheel radial aircraft tyre | DZ30720T () | C62d | ATDDP 618 |
| EASA.210.10028616 | 28/01/2010 | 32x8.8R16 Main wheel radial aircraft tyre | DZ33012T () | C62d | ATDDP 617 |
| EASA.210.10028617 | 28/01/2010 | 6.50-10 Nose and Mainwheel aircraft tyre | DR12326T () | C62d | ATDDP 219 |

DUNLOP AIRCRAFT TYRES LIMITED - 40 FORT PARKWAY B24 9HL BIRMINGHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---------------------------------|------------------|---------------|
| EASA.210.10031157 | 29/07/2010 | 5.00-5 Nose aircraft tyre | DR5875T () | C62d | ATDDP 583 |
| EASA.210.10035485 | 27/06/2011 | H30x9.50-16 Retread mainwheel aircraft tyre | F2B RETREAD OF P/N DR31230T () | C62d | ATDDP 579 |
| EASA.210.10036146 | 17/08/2011 | 43x15.5-17 F2A 22PR Retread of DR32622T Mainwheel Tyre | F2A RETREAD OF DR32622T | C62d | ATDDP 601 |
| EASA.210.10036585 | 21/09/2011 | 22x6.50-10 Retreaded of DR19122T nosewheel tyre | F2A RETREAD OF DR19122T | C62d | ATDDP 548 |
| EASA.210.10037794 | 22/12/2011 | 37x14.0-14 Retreaded nosewheel aircraft tyre | F2A RETREAD OF P/N DR20523T() | C62d | ATDDP 602 |
| EASA.210.10038325 | 07/02/2012 | 6.50-10 DR12330T Retreaded Nosewheel Aircraft Tyre | F1A RETREAD OF P/N DR12330T() | C62d | ATDDP 496 |
| EASA.210.10041235 | 31/08/2012 | H34x10.0R16 Main wheel radial aircraft tyre | DZ30730T () | C62e | ATDDP 619 |
| EASA.210.10041425 | 14/09/2012 | 30x8.8R15 Nose wheel radial aircraft tyre | DZ31316T() | C62e | ATDDP 620 |
| EASA.210.10042734 | 17/12/2012 | 33.5x11.25-15 Main wheel aircraft tyre (special application) | DR33520T | C62e | ATDDP 621 |
| EASA.210.10045460 | 26/06/2013 | H38x13.0R18 Main wheel aircraft tyre | DZ33420T() | C62e | ATDDP 624 |
| EASA.210.10046912 | 04/11/2013 | 615x225-10 Main wheel aircraft tyre | DR18428T() | C62e | ATDDP623 |
| EASA.210.10046913 | 04/11/2013 | 18x5.5 Nose wheel aircraft tyre | DR9842T() | C62e | ATDDP622 |
| EASA.210.10047544 | 18/12/2013 | Main wheel aircraft tyre, 36X11.5-19 | DR33222T () | C62e | ATDDP625 |
| EASA.210.10049519 | 16/06/2014 | 18X6 5-8 // Main wheel aircraft tyre | DR19822T() | C62e | ATDDP626 |
| EASA.210.10050382 | 03/09/2014 | H36X12.0-18 // Main wheel aircraft tyre | DR32120T () | C62e | ATDDP 627 |
| EASA.210.10052181 | 06/02/2015 | 615X225-10 // Main wheel aircraft tyre | DR18429T | C62e | ATDDP628 |
| EASA.210.10052859 | 02/04/2015 | 31X9.75-14 // Main wheel aircraft tyre | DR26222T () | C62e | ATDDP 629 |
| EASA.210.10053973 | 08/07/2015 | H41X16.0R20 // Main wheel aircraft tyre | DZ32930T () | C62e | ATDDP630 |

EAE ELECTRONICS GmbH - DEKAN-LAIST-STRASSE 52 55129 MAINZ GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|-----------------------|
| EASA.210.564 | 06/10/2006 | HeliMap.MIDI.P0252 | HELMAP.CONTROLUNIT.P0230(-)(-) HELMAP.DISPLAY.P0236(-)(-) | C113 | DDP.HELMAP.MIDI.P0252 |
| EASA.210.636, REV. A | 19/01/2010 | HeliMap.MIDI Electronic Map | HELMAP.CP.P0230(-)(-)(-) HELMAP.CU.P0230-0(-)(-)(-) HELMAP.DU.P0236(-)(-)(-) HELMAP.EB.P0260(-)(-)(-) HELMAP.SG.P0230-0(-)(-)(-) | C113 | HELMAP.MDI.P0252 |
| EASA.210.10028524 | 19/01/2010 | HeliMap 3 Airborne Multipurpose Electronic Dispay | HELMAP.CU.P0230-1(-)(-)(-) HELMAP.SG.P0230-1(-)(-)(-) | C113 | DDP_EN_HELMAP 3 |
| EASA.210.10037446 | 29/11/2011 | HeliMap-4 Airborne Multipurpose Electronic Display | HELMAP.CP2.P0311(-)(-)(-) HELMAP.EB2.P0313(-)(-)(-) HELMAP.HUB.P0305(-)(-)(-) HELMAP.SG3.P0310(-)(-)(-) | C113 | DDP_EN_HELMAP 4 |

EASTERN AERO MARINE - 5502 NW 37TH AVENUE 33142 MIAMI USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--------------------------------|-------------------|------------------|---------------|
| EASA.IM.210.692 | 19/04/2007 | Life raft model EAM-T46 | R0202A()E | 2C70a | R0202A() |
| EASA.IM.210.950 | 26/02/2008 | UXF-35 Life Preserver | P01202(-) SERIES | C13f | P01202(-) |
| EASA.IM.210.10027540 | 09/10/2009 | IN-V20L8 Infant Life Preserver | P0640(-) | C13f | P0640(-) |
| EASA.IM.210.10027672 | 21/10/2009 | LIFE RAFT MODEL EAM-T10AS | R1300(-) | 2C70a | R1300(-) |
| EASA.IM.210.10050575 | 23/09/2014 | Life Preserver Model AIC-35 | P01400(-) | C13f | P01400 |

EATON Ltd. - SOUTHAMPTON ROAD PO14 9ED TITCHFIELD, FAREHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.104 | 16/06/2004 | AE240/666/667/AE240/666/667 & Firesleeve and AE466/AE866- Me | ELF666-AR(XXXX)(X)(XX)(XX)- | C53a | 2182 |
| EASA.210.105 | 16/06/2004 | AE313/AE413/AE513/AE813 - High Pressure Hose Assemblies for | ELH313-AR(XXXX)(X)(XX)(XX)- | 2C75 | 2194 |
| EASA.210.106 | 18/06/2004 | AE318/AE418/AE518/AE818 High Pressure Hose Assemblies for Hy | ELH318-AR(XXXX)(X)(XX)(XX)- | 2C75 | 2191 |
| EASA.210.103, REV. A | 09/02/2005 | AE246/AE546/AE246+Fire-Sleeve/AE446/AE846 - High Pressure Ho | ELF246-AR(-)(-)(-)(-)(-) | C53a | 2184 |
| EASA.210.107, REV. A | 16/06/2004 | AE591/AE246/AE446/AE546/AE591/AE846 High Pressure Hose Assem | ELH246-AR(-)(-)(-)(-)(-) | 2C75 | 2183 |
| EASA.210.108, REV. A | 09/02/2005 | AE240/666/667/AE466/AE566/AE866 Medium Pressure Hose Assembl | ELH666-AR(XXXX)(X)(XX)(X X)(XXXX)(XXX) | 2C75 | 2181 |
| EASA.210.10032614 | 17/11/2010 | Type IIIA - AE641, AE441, AE841 Hydraulic Hoses Assembly | ELH641-AR(XXXX)(X)(XX)(XX)- | 2C75 | 2189 |
| EASA.210.10044637 | 25/04/2013 | Type IA - 303, 302A Hydraulic Hose Assembly - Rubber | ELH302A-AT2015-(X)(XX)(XX) ELH303-AT2014-(X)(XX)(XX) (XXXX)(XXX) (XXXX)(XXX) | 2C75 | 2271 |
| EASA.210.10044757 | 03/05/2013 | Type IB - 303 Hydraulic Hose Assembly - Rubber | ELH303-AT2014-(X)(XX)(XXXX) -(XXX) ELF302A-AT(XXXX)(XX)(XX) ELF303-AT(XXXX)(XX)(XX)- ELF601-AT(XXXX)(X)(XX)(XX) (XXXX)(XXX) | 2C75 C53a | 2268 2192 |

ELTA SA - 14 PLACE MARCEL DASSAULT 31702 BLAGNAC FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-------------------|------------------|---------------|
| EASA.210.587 | 20/11/2006 | Remote Control Panel model "BASIC RCP" | 04N6812() () | 2C91a 2C126 | 05E69217 |
| EASA.210.624 | 20/01/2007 | Emergency Locator Transmitter model ADT406°AF/AP-H | 01N65901 REV. (X) | 2C91a 2C126 | 07E60279 |

ELTA SA - 14 PLACE MARCEL DASSAULT 31702 BLAGNAC FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|--------------------------|
| EASA.210.626 | 06/02/2007 | AIRBUS Remote Control Panel (RCP) | 97N9023 (X) | 2C91a 2C126 | 05E64447 |
| EASA.210.353, REV. A | 14/09/2007 | ELT Model ADT 406 S | 01N6592(X)(X) 04N62718(X) 04N64250(X) 04N64255(X) 04N64265(X) 07N62351(X) | 2C91a 2C126 | 05E63754 |
| F.O.033 | 15/02/2001 | ELT tri-frequency portable automatic model A06 | 9260013 | | THIS EQUIPMENT INCLUDES: |
| F.O.034 | 15/02/2001 | ELT Three Frequency Survival Model S06 | 94N6097 | | THIS EQUIPMENT INCLUDES: |
| F.O.035 | 15/02/2001 | ELT three frequency portable automatic model A06V1 | 93N6069 | | 96D9005 |
| F.O.036 | 15/02/2001 | ELT three frequency ELT transmetteur Model A06V2r | 95N6088 | | 95D6079 |
| F.O.037 | 15/02/2001 | ELT model A06V2 Programming Box | 95N6089 | | 95D6080 |
| F.O.038 | 15/02/2001 | ELT remote Control Panel | 93N6035 96N9030 97N902(X) | | 97D9002 |
| F.O.089 | 03/10/2002 | tri -frequency automatic fixed ELT | 01N6590(X)(X) | | 02E65151-B |
| F.O.112 | 29/04/2003 | Portable & Survival tri-freq ELT model ADT 406 | 01N6591 (X)(X) 02N60051(X) 02N69004 (X) | | 02E68871 |

EMTEQ EUROPE GmbH - BITZBERGSTRASSE 5 8184 BACHENBUELACH SWITZERLAND

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|---|------------------|---|
| EASA.210.296, REV. C | 02/10/2012 | Position Light Assemblies 9000 and 9200 | 03-9000-(XXXX) 03-9200-(XXXX) EXCL 03-9000-5003,03-9000-5004 EXCL 03-9200-4006 | C30c | DDP 032-03-9000-01 DDP-033-03-9200-01 |
| EASA.210.335, REV. B | 11/10/2010 | Anticollision Light Assembly 9500 | 03-9500-XXXX | C96a | 034-03-9500-00 |
| EASA.210.832, REV. A | 04/10/2010 | Model 9501 Anticollision Light | 03-9501-(XXXX) | C96a | 041-03-9501 |
| EASA.210.10032081 | 07/10/2010 | Model 9800 Combined Wing ACL / Position Light | 03-9800-(XXXX) | C30c C96a | 054-03-9800 |
| EASA.210.10038115 | 20/01/2012 | LED Anti Collision Light 3000-2 | 03-3000-(XXX)2 | C96a | 061-03-3000 |
| EASA.210.10038116 | 20/01/2012 | LED Anti Collision Light 3000-0 | 03-3000-(XXX)0 | C96a | 060-03-3000 |
| EASA.210.10041553 | 02/10/2012 | 9002 & 9202 LED Position Light | 03-9000-5003 03-9000-5004 03-9002-(XXXX) 03-9200-4006 03-9202-(XXXX) | C30c | DDP-058-03-9000 DDP-059-03-9200 |
| EASA.210.10050166 | 08/08/2014 | Combined LED Wingtip Light | 03-0001-0000 03-0001-XXXX EXCLUDING COMBINED LED WINGTIP LIGHT: POWER SUPPLY: 04-5000-XXXX | C30c C96a | DDP-068-03-0001 |
| EASA.210.10028951, REV. A | 04/10/2010 | 9302 Combined Rear ACL / Position Light | 03-9302-() | C30c C96a | 046-03-9302 |
| EASA.210.1113, REV. A | 04/10/2010 | Model 9505 LED Anticollision Light | 03-9505-() | C96a | 045-03-9505 |

ENTWICKLUNGSBETRIEB BRIGITTE BUCHSE - WILHELM-RONTGEN-STR.1 58300 WETTER-VOLMARSTEIN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------|---------------------|-------------------|---------------|
| EASA.210.1172 | 24/03/2015 | RFB TC1 () Emergency Parachute | RFB-TC1(-)(-)(-)(-) | C23d | RFBTC1DDP |
| EASA.210.1225 | 23/04/2009 | Slipack T204 Safety parachute | T204 | TSO C23B Other | 40.010/99 |
| EASA.210.1226 | 23/04/2009 | Thinback T104 Safety parachute | T104 | TSO C23B Other | 40.010/98 |

ENVIROTAIENER ENGINEERING AB - JOHANNESLUNDSVAEGEN 2 194 61 UPPLANDS VAESBY SWEDEN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|---------------|------------------|---------------|
| EASA.210.293 | 03/06/2005 | RKNe1, Thermal insulated LD3 Air Crago Container (ULD) with | 120007R () | C90c | 120007R-01 |
| EASA.210.561 | 29/09/2006 | RAP LD9 Container with dry-ice cooling system | 140007R () | C90c | 140007R |
| EASA.210.562 | 29/09/2006 | RKN LD3 Container with dry-ice cooling system | 120005R () | C90c | 120005R |
| EASA.210.1034 | 25/04/2008 | RAP 140006 Container | 140006-01 | C90c | 140006-01 |
| EASA.210.10030817 | 08/07/2010 | RAP / 140010R | 140010R(-) | C90c | 140010R-10 |

ESSEX INDUSTRIES, Inc. - 4150 CARR LANE COURT 63119 ST. LOUIS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-----------------|---------------|------------------|---------------|
| EASA.IM.210.10052970 | 16/04/2015 | MR - 100 SERIES | MR100() | C99 C116 | DDP-001 |

ESTERLINE BELGIUM - PRESIDENT KENNEDY PARK 35A 8500 KORTRIJK BELGIUM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------|--------------------|-------------|------------------------|------------------|-----------------------------|
| ETSOA.210.10055459 | 13/11/2015 | DU-885AF | P/N K9321063A(XX)-(YY) | C113 | P0903-SDRL- DU-885AF-056 |

EUROAVIONICS GmbH - KARLSRUHER STR. 91 75179 PFORZHEIM GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

EUROAVIONICS GmbH - KARLSRUHER STR. 91 75179 PFORZHEIM GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|--|------------------|----------------|
| EASA.210.804, REV. B | 23/05/2013 | Digital Moving Map and Task Management System: Euronav V CM | 210.002-(XXX) | C113 | DDP210_002_XXX |
| EASA.210.10052607 | 17/03/2015 | EuroNav 7 SW Version 2.X.X, Digital Moving Map and Situation | 215.(XXX)-(XX)3 | C113 C165 | DDP215_XXX_XX3 |
| EASA.210.10037792, REV. B | 23/05/2013 | EuroNav 7, Digital Moving Map and Task Management System | 257.020-025, 257.020-026 CLN14: 257.07-03, 257.07-05 DMG RN7: 257.015-001 WITH HNR-7.0:255.001-001 SW 240.003-005, FDRN7 SYSTEM: 215.(XXX)-(XX)0 | C113 C165 | DDP215_XXX_XX0 |
| EASA.210.10040488, REV. A | 23/05/2013 | EuroNav 7, Digital Moving Map with Software version 1.01 or | 215.(XXX)-(XX)1 | C113 C165 | DDP215_XXX_XX1 |
| EASA.210.10042697, REV. C | 31/07/2014 | EuroNav 7 SW Version 2.X.X, Digital Moving Map and Situation | FDRN7-1.2 (512GB VERSION) FDRN7-2.2 (256GB VERSION) RN7D P/N 257.015-005 RN7 P/N 257.015-001 RN7 P/N 257.015-002 RN7 P/N 257.015-003 RN7 P/N 257.015-004 SYSTEM P/N: 215.(XXX)-(XX)2 UNITS | C113 C165 | DDP215_XXX_XX2 |
| EASA.210.10051882, REV. A | 17/03/2015 | EuroNav 7 CM Digital Moving Map and Situational Awareness Sy | 216.(XXX)-(XX)0 | C165A Other | DDP216_XXX_XX0 |
| EASA.210.1259, REV. B | 23/05/2013 | Digital Moving Map and Task Management System: Euronav V | 210.001-(XXX) | C113 | DDP210_001_XXX |

EXPLISEAT SAS - 60 BOULEVARD SAINT-MICHEL 75006 PARIS FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--------------------------------|--|------------------|----------------|
| EASA.210.10048605 | 25/03/2014 | PHOTON Standard Passenger Seat | PA(10)(1)A() () () PA(10)(2)A() () () PA(10)(3)A() () () PA(10)(4)A() () () PA(10)(5)A() () () PA(10)(6)A() () () PA(10)(7)A() () () PA(10)(8)A() () () | C39c | DDP-PA(10) |
| EASA.210.10054056 | 15/07/2015 | MUON PASSENGER SEAT | PA(10)()B() () () | C127a | DDP-PA(10)()B |
| EASA.210.10054831 | 22/09/2015 | Tachyon Passenger Seat | PT15A-(X)(YYYY) | C39c | DDP-PT15A |

FACTEM - 8 RUE EDOUARD NAUD 92130 ISSY LES MOULINEAUX FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---------------|------------------|---------------|
| EASA.210.10052176 | 06/02/2015 | AVS 46320 / Casque communicant pour pilote d'aéronef | AVS46320XY-BK | C139 | P21-DDP-2350 |

FIREBIRD GmbH & Co. KG - AM TOWER 16 54634 BITBURG GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|-------------------------|--------------------|---------------|
| EASA.210.459, REV. A | 23/04/2012 | V1R1 Personnel Parachute | V1R1-O-01() / R-01 () | C23d | DDP-V1R1 |
| EASA.210.10018466 | 23/04/2012 | Dual Harness Reserve Parachute Type TD400 | TD400 | JTSO C23D Other | 01/DDPTD400 |
| EASA.210.10018467 | 23/04/2012 | Personnel Parachute Omega () / Quick () | OMEGA () / QUICK () | JTSO C23D Other | OMEGA/QUICK |

FLYING SERVICE ENGINEERING & EQUIPMENT Ltd. - FISHPONDS ROAD RG41 2GY WOKINGHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|-----------------|
| EASA.210.102 | 16/06/2004 | F2317 Series - 9G Forward Facing Business Class Passenger Se | F2317-()-()-() | C39b | EU808 |
| EASA.210.168 | 01/10/2004 | F4311 Series Economy/Business Class Quadruple Passenger Seat | F4311-()-()-() | C39b | EU809 |
| EASA.210.301 | 04/07/2005 | 9g Forward Facing Economy Double Passenger Seat, F2311 Serie | F2311 - (X) - (XX) - (XXX) | C39b | 801 |
| EASA.210.495 | 15/05/2006 | F2313 Passenger Seat | F2313-()-()-() | C39b | EU810 |
| EASA.210.496 | 15/05/2006 | F3313 Passenger Seat | F3313-()-()-() | C39b | EU804 |
| EASA.210.582 | 31/10/2006 | Passenger Seat F3313 | F3313-()-()-() | C127a | EU804 |
| EASA.210.583 | 31/10/2006 | Passenger Seat F2313 | F2313-()-()-() | C127a | EU810 |
| EASA.210.166, REV. A | 23/05/2011 | F3311 Series Economy Class Passenger Seat | F3311-()-()-() F4311-()-()-() | C39b | EU800 AND EU809 |

FRC COMPONENT PRODUCTS, Inc. - 1511 SOUTH BENJAMIN AVENUE 50401 MASON CITY USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|----------------------|---------------|---|---------------|
| EASA.IM.210.324 | 12/08/2005 | KA 61 L-Band Antenna | AH-3000-() | 2C66b C74d 2C112a C118 C147 | DDP-AH-300 |

FREEFLIGHT ACQUISITION CORPORATION - 3700 INTERSTATE 35 SOUTH 76706 WACO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|--|------------------|-------------------|----------------|
| EASA.IM.210.866 | 10/12/2007 | 2101 I/O Approach Plus GPS Navigation System | 81440-()-241() | TSO C129 Other | 81440-X-241() |
| EASA.IM.210.1164 | 28/09/2010 | RA-4X00 series Low Range Radio Altimeter | 84560-1X-300X | 2C87 | 84560-1X-300X |

FREEFLIGHT ACQUISITION CORPORATION - 3700 INTERSTATE 35 SOUTH 76706 WACO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-----------------------------|--|------------------|------------------|
| EASA.IM.210.10051533 | 09/12/2014 | GPS-SBAS Sensor Model 1203C | 84327-50-XXXX, WITH SW 200E OR HIGHER AND GPS VERSION 0110 OR HIGHER | C145 | DDP48327-50-XXXX |

F.U.N.K.E. AVIONICS GmbH - HEINZ-STRACHOWITZ-STRASSE 4 86807 BUCHLOE GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|--------------------------------------|---------------------------|
| EASA.210.045 | 26/05/2004 | Mode-S Transponder TRT800 with External Memory EM800 | 800ATC-(-)(-) 800EM -(-)(-) | 2C112a | 03.210.010.04 |
| EASA.210.193 | 26/10/2004 | VHF Transceiver - Model ATR833 | 833-(-)(-) | 2C37e 2C38e | 01.140.010.04 |
| EASA.210.268 | 12/04/2005 | Mode-S Transponder, TRT800A | 800ATC-A-(-)(-) | 2C112a | 03.211.010.04 |
| EASA.210.269 | 11/04/2005 | Mode-S Transponder, TRT800H | 800ATC-H-(-)(-) | 2C112a | 03.212.010.04 |
| EASA.210.270 | 11/04/2005 | VHF COM Transceiver, ATR833A | 833A-(-)(-) | 2C37e 2C38e | 01.141.010.04 |
| EASA.210.1090 | 21/10/2008 | CDTI-2000 Cockpit Display | 5.123.2800001.01-(-) DATA CARD 8.121.2800001.01-(-) DISPLAY | JTSO-C113 JTSO-C147 Other | 6.DDP.2800001.(04) |
| EASA.210.10048027 | 03/06/2014 | FSG 50 VHF Transceiver | FSG 50 | Other RTCA DO-156, RTCA DO-157 | LBA KBL. NR. 10.911/71 |
| EASA.210.10048028 | 03/06/2014 | FSG 60 / FSG 60M | FSG 60, FSG 60M | Other RTCA DO-156, RTCA DO-157 | LBA KBL. NR. 10.911/72 |
| EASA.210.10048029 | 03/06/2014 | FSG 70 /FSG 71M VHF Transceiver | FSG 70, FSG 71M | Other RTCA DO-156, RTCA DO-157 | LBA KBL. 10.911/81 |
| EASA.210.1304, REV. A | 30/08/2013 | VHF Transceiver FSG 2T | F10350(-) | JTSO-2C37E JTSO-2C38E Other | 035.1.00 |
| EASA.210.1305, REV. A | 30/08/2013 | FSG90(X) and FSG90(X)-H1 VHF Communication Transceiver Famil | FSG90(X) FSG90(X)-H1 | JTSO-2C37E JTSO-2C38E Other | 031.00 |
| LBA.O.10.911/106 JTSO | 26/11/2001 | ATR 600 | 600-(XXX)-(XXX) | | 01.130.010.4 |
| LBA.O.10.911/113JTSO | 25/04/2003 | ATR-500 VHF-Transceiver | 500-(-)(-) | | 01.125.010.04 |
| LBA.O.10.911/114JTSO | 29/04/2003 | ATR-600A VHF-Transceiver | 600A(-)(-) | | 01.135.010.04 |
| LBA.O.10.911/115JTSO | 29/04/2003 | ATR Remote Control Unit | 600R01(-)(-) | | 01.131.010.04 |

GABLES ENGINEERING, Inc. - 247 GRECO AVENUE 33146 CORAL GABLES USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|--|---|-------------------------|-------------------|
| EASA.210.154 | 24/08/2004 | Gables ATC/TCAS Control Panel G7534() | G7534() | 2C112a C118 C119b | GD-DDP- G7534 () |
| EASA.IM.210.357 | 12/10/2005 | HF Comm Control Panel G7511 | G7511-01 G7511-02 G7511-101 G7511-102 G7511-201, G7511-201 G7511-202 | C31d C32d | GD-DDP-G7511() |
| EASA.IM.210.1038 | 07/05/2008 | G7514() Series - ATC/TCAS/FID Control Panel | G7514() | 2C112a C118 C119b | GD-DDP-G7514() |

GADRINGER-GURTE GmbH - FLUGHAFEN KASSEL 34379 CALDEN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--------------------|--|--|---------------|
| EASA.210.10039342 | 27/04/2012 | BOGU 1000 series | 11()(), 12()(), 13()(), 14()() | LBA 1973 Other | 1000 |
| EASA.210.10039345 | 27/04/2012 | BAGU 5000 series | 51()(), 52()(), 53()() 54()(), 55()() | LUFTTÜCHTIGKEI TSANFORD FÜR Other | 5000 |
| EASA.210.10039349 | 27/04/2012 | BAGU 6000 series | 61()(), 62()(), 63()() 64()(), 65()(), 66()() | LBA 1973 Other | 6000 |
| EASA.210.10039350 | 27/04/2012 | BAGU 4000 series | 44()(), 45()() | LBA 1973 Other | 4000 |
| EASA.210.10039416 | 03/05/2012 | SCHUGU 2000 series | 21()(), 22()(), 23()() 24()(), 25()(), 26()() 27()(), 28()() | DERUNGEN FÜR ANSCHNALLGUR TE LBA LUFTTÜCHTIGKEI TSANFOR (LFA), AUSGABE JANUAR 1973 Other | 2000 |

GARMIN AT, Inc. - 2345 TURNER ROAD SE 97302 SALEM USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------|------------------|-------------------------|---------------|
| EASA.210.064 | 21/06/2004 | Apollo SL70R Mode C Transponder | 430-06067-1 (XX) | C74d | PD4506 |
| EASA.210.119 | 01/07/2004 | VHF Comm Radio SL40 | 430-6040-2() | 2C37e 2C38e 2C128 | PD1998 |

GARMIN AT, Inc. - 2345 TURNER ROAD SE 97302 SALEM USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|-------------------------------------|--------------------------------|--|---------------|
| EASA.IM.210.489 | 30/03/2006 | GNS 480 GPS/WAAS/Nav/Com | 430-6100-800-002 | 2C34f 2C36f 2C37e 2C38e 2C40c C113 2C128 C146 | PD3157 |
| LBA.N-O.10.916/018 JTSO | 20/02/2003 | GX 50 GPS | 430-6050-40(X) | | PD1400 |
| LBA.N-O.10.930/58JTSO | 17/09/2001 | Apollo SL70 Mode C Transponder | 430-6090-1XX | | 4037 |
| LBA.N-O.10.985/005 JTSO | 12/04/2002 | Apollo SL30 Nav/Comm | 430-6040-3(XX) | | PD3026 |
| LBA.N-O.10.985/012 JTSO | 06/01/2003 | GX 60 GPS/COMM | 430-6050-6(XX) | | PD1491 |
| LBA.N-O.10.985/013 JTSO | 20/02/2003 | GX 65 GPPS/COMM | P/N 430-6050-80(X) WITH SOFTWA | | PD1402 |
| LBA.N-O.10.985/014JTSO | 22/08/2003 | CNX 80 | 430-6100-8XXX-() | | PD 2257 |
| LBA.N-O.10.986/006 JTSO | 13/02/2002 | Apollo MX 20 Multi-Function Display | 430-0270-5(XX) | | PD1469 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|---|---|---------------|
| EASA.210.196 | 10/11/2004 | GNS 430A GPS/VHF COMM/VOR/LOC/GS | 010-00286-() 011-00836-() | 2C34f 2C36f 2C37e 2C38e 2C40c C129a | QAA 806 |
| EASA.210.206 | 24/11/2004 | GMU 44 Magnetometer Model | 010-00296-() 011-00870-() | C6d | 190-00303-12 |
| EASA.210.212 | 15/12/2004 | Audio Panel / Marker Beacon Model GMA 1347 | 006-B0203-() 010-00276-() 011-00809-() | 2C35d C50c | 190-00303-71 |
| EASA.210.214 | 15/12/2004 | GRS 77 | 006-B0223-() 010-00295-() 011-00868-() | C3d C4c C6d | 190-00303-11 |
| EASA.210.216 | 15/12/2004 | GIA 63 | 010-00335-() 011-00781-() | 2C34f 2C36f 2C37e 2C38e 2C40c C129a | 190-00303-08 |
| EASA.210.220 | 05/01/2005 | GDU 1040 Control Display Unit | 006-B0191-() 006-B0319-() 006-B0320-() 010-00337-(), EXCLUDING -00, 011-00972-(), EXCLUDING -00, | C2d C3d C4c C6d C8d C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C55 2C66b C74d C110a 2C112a C113 C129a C147 | 190-00303-17 |
| EASA.210.221 | 05/01/2005 | GTX 33/33D Mode S Transponder | 010-00267-() 010-00294-() 011-00779-() | 2C112a | 190-00421-00 |
| EASA.IM.210.440 | 21/12/2005 | GNS 530A TAWS Multisensorsystem | 010-00292-() 011-00864-() | 2C34f 2C36f 2C37e 2C38e 2C40c C129a C151a | 190-00529-00 |
| EASA.IM.210.444 | 21/12/2005 | GNS 530 TAWS | 010-00325-() 011-00940-() | 2C34f 2C36f 2C37e 2C38e 2C40c C129a C151a | 190-00528-00 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|---------------|
| EASA.IM.210.445 | 21/12/2005 | GPS 500 TAWS | 010-00291-() 011-00863-() | C129a C151a | 190-00527-00 |
| EASA.IM.210.452 | 16/01/2006 | GSM 85 Autopilot Servo Mount | 010-00304-() 011-00894-() | C9c | 190-00568-00 |
| EASA.IM.210.453 | 16/01/2006 | GSA 81 Autopilot Servo Actuator | 010-00303-() 011-00878-() | C9c | 190-00631-00 |
| EASA.IM.210.454 | 16/01/2006 | GMC 710 Controller for Automatic Flight Control System | 010-00347-() 011-01020-() | C9c C52b | 190-00303-69 |
| EASA.IM.210.474 | 03/03/2006 | GA 57 WAAS and FIS Active Antenna | 010-10604-() 011-01032-() | C144 | 190-00661-00 |
| EASA.IM.210.475 | 03/03/2006 | GA 56A WAAS Active Antenna | 010-10599-() 011-01154-() | C144 | 190-00660-00 |
| EASA.IM.210.476 | 03/03/2006 | GTA 82 Trim Adapter | 010-00334-() 011-00960-() | C9c | 190-00303-73 |
| EASA.IM.210.477 | 09/03/2006 | GCU 475 Flight Management System (FMS) Controller | 010-00359-() 011-01054-() | C113 | 190-00599-00 |
| EASA.IM.210.478 | 09/03/2006 | GCU 476 Flight management System (FMS) Controller | 010-00457-() 011-01237-() | C113 | 190-00636-00 |
| EASA.IM.210.479 | 09/03/2006 | GMA 347 Audio Panel | 010-00275-() 011-00807-() | 2C35d C50c | 190-00621-00 |
| EASA.IM.210.541 | 24/07/2006 | GWX 68 Weather Radar | 006-B0266-() 010-00299-() 011-00883-() | 2C63c | 190-00286-06 |
| EASA.IM.210.551 | 30/08/2006 | GA 56W | 010-10561-01 011-01111-00 | C144 | 190-00483-02 |
| EASA.IM.210.615 | 03/01/2007 | GSA 80 Autopilot Servo Actuator | 010-00302-() 011-00877-() | C9c | 190-00725-00 |
| EASA.IM.210.631 | 01/02/2008 | GAD 42 Interface Adapter | 010-00154-() SHIPPING LEVEL 011-00417-() UNIT LEVEL | 2C40c C129a | 190-00159-02 |
| EASA.IM.210.645 | 16/06/2008 | GDU 1045 | 010-00279-() EXCEPT -00 THROU 011-00819-() EXCEPT -00 THROU | C2d C3d C4c C6d C8d C9c C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C52b C55 2C63c 2C66b C74d 2C87 C110a 2C112b C113 C118 C129a C146 C147 C151a | 190-00303-35 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|---------------|
| EASA.IM.210.646 | 16/06/2008 | GDU 1044 | 010-00365-() SHIPPING LEVEL 011-01078-() UNIT LEVEL | C2d C3d C4c C6d C8d C9c C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C52b C55 2C63c 2C66b C74d 2C87 C110a 2C112b C113 C118 C129a C146 C147 C151a | 190-00303-34 |
| EASA.IM.210.647 | 26/02/2007 | GMA 1347D Dual Audio Panel / Marker Beacon | 010-00465-() 011-01257-() | 2C35d C50c | 190-00303-22 |
| EASA.IM.210.650 | 26/02/2007 | GSM 85A Autopilot Servo Mount | 010-00556-() SHIPPING LEVEL 011-01436-() UNIT LEVEL | C9c | 190-00738-00 |
| EASA.IM.210.687 | 31/01/2008 | GIA 63 Integrated Avionics System | 010-00335-() EXCEPT -00 THROU 011-00781-() EXCEPT -00 UNIT | C9c C52b C151a | 190-00303-08 |
| EASA.IM.210.731 | 16/04/2009 | GDU 1240A Display Control | 010-00559-00 THROUGH -5() SHI 011-01440-00 THROUGH -5() UNI | C2d C3d C4c C6d C8d C9c C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C52b C55 2C63c 2C66b C74d 2C87 C110a 2C112b C113 C118 C146 C147 C151a | 190-00303-51 |
| EASA.IM.210.784 | 25/02/2008 | GDC 74B Air Data Computer | 010-00390-0() SHIPPING LEVEL 011-01110-0() UNIT LEVEL | C106 | 190-00303-16 |
| EASA.IM.210.809 | 16/08/2007 | GTX 328 Mode S/A/C Transponder | 010-00634-() SHIPPING LEVEL 011-01684-() WITH SW P/N 006- | 2C112b | 190-00420-06 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|--|------------------|---------------|
| EASA.IM.210.853 | 08/11/2007 | GDU 1043 Control Display | 010-00366-() SHIPPING LEVEL 011-01079-() UNIT LEVEL | C2d | 190-00303-33 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C129a | |
| | | | | C146 | |
| | | | | C147 | |
| | | | | C151a | |
| EASA.IM.210.854 | 08/11/2007 | GDU 1042 Control Display | 010-00367-() SHIPPING LEVEL 011-01080-() UNIT LEVEL | C2d | 190-00303-32 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C129a | |
| | | | | C146 | |
| | | | | C147 | |
| | | | | C151a | |
| EASA.IM.210.910 | 11/08/2011 | GNM-00733 Flight Management System Controller | SHIPPING LEVEL: 010-00733-0() SHIPPING LEVEL: 010-00733-99 UNIT LEV GCU275:011-01983-0() | C113 | 190-00636-05 |
| EASA.IM.210.911 | 18/07/2008 | GMC 705 Automatic Flight Control System Mode Controller | 010-00663-() SHIPPING LEVEL 011-01737-() UNIT LEVEL | C9c | 190-00303-66 |
| | | | | C52b | |
| EASA.IM.210.913 | 30/07/2008 | GCU 477 Flight Management System Controller | 010-00551-0() SHIPPING LEVEL 011-01428-0() UNIT LEVEL | C113 | 190-00636-01 |
| EASA.IM.210.914 | 18/07/2008 | GCU 478 Flight Management System Controller | 010-00669-0() SHIPPING LEVEL 011-01757-0() UNIT LEVEL | C113 | 190-00636-02 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---|--|---------------|
| EASA.IM.210.915 | 23/10/2012 | GMN-00676-A Airborne Weather Radar | 010-00676-0() 011-01768-0() GWX 70 UNIT SHIPPING LEVEL: SUPERSET: 010-00676-99 THROUGH 011-01768-2() THROUGH 10-00676-2() | 2C63c | 190-00829-04 |
| EASA.IM.210.917 | 07/07/2008 | GSD 41 Data Concentrator Unit | 010-00565-0() SHIPPING LEVEL 011-01457-0() UNIT LEVEL | C113 | 190-00303-25 |
| EASA.IM.210.919 | 20/12/2007 | GNS 530W, GNS 530AW GPS WAAS/ VOR/ILS/COM System | GNS 530AW: 010-00418-() SHIPP GNS 530W: 010-00416-() SHIPPI | 2C34f 2C36f 2C37e 2C38e 2C40c C113 C146 | 190-00357-07 |
| EASA.IM.210.920 | 20/12/2007 | GNS 430W, GNS 430AW WAAS GPS/ VOR/ILS/COM System | GNS 430W: 010-00412-() SHIPPI GNS 430AW: 010-00413-() SHIPP | 2C34f 2C36f 2C37e 2C38e 2C40c C113 C146 | 190-00356-07 |
| EASA.IM.210.940 | 17/11/2011 | GMN-00683-A Audio Panel | 010-00683-0() SHIPPING LEV 010-00683-99 SUPERSET 011-01793-0() UNIT LEVEL GMA 36: | 2C35d C139 | 190-00858-00 |
| EASA.IM.210.951 | 18/02/2008 | GNC-420W, GNC-420AW | 010-00410-() SHIPPING LEVEL 010-00411-() SHIPPING LEVEL 011-01058-() UNIT LEVEL 011-01059-() UNIT LEVEL | 2C37e 2C38e C113 C146 | 190-00356-07 |
| EASA.IM.210.952 | 29/02/2008 | GPS 400W | 010-00409-() SHIPPING LEVEL 011-01057-() UNIT LEVEL | C113 C146 | 190-00356-07 |
| EASA.IM.210.953 | 29/02/2008 | GNS 530W TAWS, GNS 530AW TAWS | 010-00417-() SHIPPING LEVEL 010-00419-() SHIPPING LEVEL 011-01065-() UNIT LEVEL 011-01067-() UNIT LEVEL | 2C34f 2C36f 2C37e 2C38e 2C40c C113 C146 C151a | 190-00357-07 |
| EASA.IM.210.954 | 18/02/2008 | GPS 500W | 010-00414-() SHIPPING LEVEL 011-01062-() UNIT LEVEL | C113 C146 | 190-00357-07 |
| EASA.IM.210.955 | 29/02/2008 | GPS 500W TAWS | 010-00415-() SHIPPING LEVEL 011-01063-() UNIT LEVEL | C113 C146 C151a | 190-00357-07 |
| EASA.210.215, REV. A | 15/12/2004 | GDC 74A | 010-00336-() 011-00882-() 011-00978-() | C106 | 190-00303-16 |
| EASA.IM.210.1046 | 01/12/2009 | GA 58 TCAS Antenna | 010-10720-0() SHIPPING LEVEL 010-10720-99 SUPERSET 011-01346-0() UNIT LEVEL | C118 C119b C147 | 190-00587-06 |
| EASA.IM.210.1047 | 13/01/2010 | GPA 65 Power Amplifier/Low Noise Amplifier (PA/LNA) | 010-10721-0() SHIPPING LEVEL 010-10721-99 SUPERSET 011-01347-0() UNIT LEVEL | C118 C147 | 190-00587-07 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|---|---|------------------|---------------|
| EASA.IM.210.1050 | 16/06/2008 | GDU 1044B Control Display | 010-00471-() SHIPPING LEVEL 011-01274-() UNIT LEVEL | C2d | 190-00303-36 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| 2C87 | | | | | |
| C110a | | | | | |
| 2C112b | | | | | |
| C113 | | | | | |
| C118 | | | | | |
| C129a | | | | | |
| C146 | | | | | |
| C147 | | | | | |
| C151a | | | | | |
| EASA.IM.210.1057 | 18/01/2010 | GTS 800 Traffic Advisory System (TAS) Airborne Equipment | 010-00519-0() SHIPPING LEVEL 010-00519-99 SUPERSET 011-01356-0() UNIT LEVEL | C147 C166a | 190-00587-03 |
| EASA.IM.210.1058 | 18/01/2010 | GTS 820 Traffic Advisory System (TAS) Airborne Equipment | 010-00562-0() SHIPPING LEVEL 010-00562-99 SUPERSET 011-01446-0() UNIT LEVEL | C147 C166a | 190-00587-04 |
| EASA.IM.210.1059 | 18/01/2010 | GTS 850 Traffic Alert and Collision Avoidance System (TCAS) | 010-00563-0() SHIPPING LEVEL 010-00563-99 SUPERSET 011-01553-0() UNIT LEVEL | C118 C166a | 190-00587-05 |
| EASA.IM.210.1060 | 23/06/2008 | GDU 1040A Control Display | 010-00320-() SHIPPING LEVEL 011-00916-() UNIT LEVEL | C2d | 190-00303-31 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| 2C87 | | | | | |
| C110a | | | | | |
| 2C112b | | | | | |
| C113 | | | | | |
| C118 | | | | | |
| C129a | | | | | |
| C146 | | | | | |
| C147 | | | | | |
| C151a | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|--|---|--|---------------|
| EASA.IM.210.1062 | 24/06/2008 | GDU 1500 Control Display | 010-00387-() SHIPPING LEVEL 011-01108-() UNIT LEVEL | C2d C3d C4c C6d C8d C9c C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C52b C55 2C63c 2C66b C74d 2C87 C110a 2C112b C113 C118 C129a C146 C147 C151a | 190-00303-18 |
| EASA.IM.210.1117 | 20/04/2009 | GDU 620 PFD/MFD Control Display | 010-00482-0() SHIPPING LEVEL 010-00482-1() SHIPPING LEVEL 011-01264-0() UNIT LEVEL 011-01264-1() UNIT LEVEL | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c 2C41d C52b C113 C118 C147 | 190-01032-00 |
| EASA.IM.210.1148 | 12/12/2011 | GIA 63W Main SW6.(XX)Integrated Avionics System | SHIP LEV: 010-00386-0() SYSTEM SW: 006-B0544-3() THROUGH -1() THROUGH -1 () UNIT LEVEL: 011-01105-0() | C9c 2C34f 2C36f 2C37e 2C38e 2C40c C52b C92c C145 C151b | 190-00303-0A |
| EASA.IM.210.1150 | 12/12/2011 | GIA 63W Main SW 6.(XX)Integrated Avionics System | EXCEPT 006-B0544-30 THRU -34 GIA 63H: 011-01105-3() GIA 63W: 011-01105-2() SHIP LEV: 010-00386-2() SHIP LEV: 010-00386-3() SYSTEM SW: 006-B0544-3() | C9c 2C34f 2C36f 2C37e 2C38e 2C40c C52b C92c C145 C151b | 190-00303-87 |
| EASA.IM.210.1153 | 18/03/2009 | GSM 86 Autopilot Servo Mount | 010-00714-() SHIPPING LEVEL 011-01904-() UNIT LEVEL | C9c | 190-00738-10 |
| EASA.IM.210.1173 | 19/06/2009 | GMN-00641 Iridium Data Link System | 010-00641-0() SHIPPING LEVEL 010-00641-99 (SUPERSET) 011-01706-0() UNIT LEVEL | C50c 2C514 | 190-01049-00 |
| EASA.IM.210.1212 | 21/12/2009 | GMN-00724 Gyro Adapter | 010-00724-0() SHIPPING LEVEL 010-00724-99 SUPERSET 011-01970-0() UNIT LEVEL | C3d C4c C6d C9c | 190-01103-00 |
| EASA.IM.210.1254 | 16/02/2010 | GTX 330 / GTX 330D Mode S Transponder with Extended Squitter | 010-00230-() 010-00293-() SHIPPING LEVEL 011-00455-() UNIT LEVEL | 2C112b C166a | 190-00207-04 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|--|---|---------------|
| EASA.IM.210.1256 | 18/10/2012 | GMN-00832-A VHF Digital Communications Radio | 010-00832-0() SHIP. LEVEL 010-00832-99 SUPERSET UNIT (GDR 66): 011-02303-0() | 2C37e 2C38e 2C128 | 190-00303-23 |
| EASA.IM.210.1273 | 24/02/2012 | GMN-00787-A Air Data Computer | 011-02337-0() SHIP LEV: 010-00787-0() SUPERSET: 010-00787-99 THROUGH -2() THROUGH -2() UNIT LEVEL GDC7400: | C106 | 190-01100-02 |
| EASA.IM.210.1287 | 14/12/2009 | GDU 620 PFD/MFD Control Display | 010-00482-5() SHIPPING LEVEL 010-00482-99 SUPERSET 011-01264-5() UNIT LEVEL WITH SW 006-B1071-1() | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c 2C41d C52b 2C63c C113 C118 C147 | 190-01032-02 |
| EASA.IM.210.1288 | 15/12/2009 | GDU 620 PFD/MFD Control Display with Main SW 006-B0498-1() | 010-00482-0() 010-00482-1() SHIPPING LEVEL 010-00482-99 SUPERSET 011-01264-0() 011-01264-1() UNIT LEVEL WITH SW 006-B0498-1() | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c 2C41d C52b 2C63c C113 C118 C147 C151b | 190-01032-00 |
| EASA.IM.210.222, REV. A | 10/03/2011 | GEA 7x Engine and Airframe Data Acquisition Unit | 010-00282-() (SHIPPING LEVEL) 010-00283-00 TO -04, AND -1() 010-00283-05 TO -09, AND -2() 010-00284-() (SHIPPING LEVEL) 011-00798-() (UNIT LEVEL) 011-00831-() (UNIT LEVEL) SUPERSET 010-00283-99 | C43c C44b C45a C47 C49b C55 | 190-00303-41 |
| EASA.IM.210.621, REV. B | 22/12/2011 | GIA 63W Integrated Avionics System | SHIP LEV: 010-00386-0() SYSTEM SW: 006-B0544-1() THROUGH -1() THROUGH -1() THROUGH -2() UNIT LEVEL: 011-01105-0() | C9c 2C34f 2C36f 2C37e 2C38e 2C40c C52b C145 C151a | 190-00303-13 |
| EASA.IM.210.912, REV. A | 24/11/2011 | GMN 00734-A Automatic Flight Control System Mode Controller | SHIPPING LEVEL: 010-00734-0() SHIPPING LEVEL: 010-00734-2() SHIPPING LEVEL: 010-00734-3() SHIPPING LEVEL: 010-00734-8() SUPERSET: 010-00734-99 UNIT LEVEL: 011-02390-2() UNIT LEVEL: 011-02390-3() UNIT LEVEL: 011-02390-8() UNIT LEV GMC720: 011-02390-0() | C9c C52b | 190-00303-86 |
| EASA.IM.210.10034245 | 22/03/2011 | GDU 620 (G500) SW 5.x PFD/MFD Control Display | 010-00482-6() 011-01264-6() BOOT SW 006-B0191-0() MAIN SW 006-B1071-3() SHIPPING LEVEL 010-00482-5() UNIT LEVEL: 011-01264-5() | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c 2C41d C52b 2C63c 2C87 C113 C118 C147 | 190-01032-05 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--------------------------------|------------------|---------------|
| EASA.IM.21O.10034247 | 21/03/2011 | GDU 620 (G600) SW 5.x PFD/MFD Control Display | 010-00482-1() | C2d | 190-01032-06 |
| | | | 010-00482-2() | C3d | |
| | | | 010-00482-3() | C4c | |
| | | | 011-01264-1() | C6d | |
| | | | 011-01264-2() | C8d | |
| | | | 011-01264-3() | C10b | |
| | | | BOOT SW 006-B0191-0() | 2C34f | |
| | | | MAIN SW 006-B0498-3() | 2C36f | |
| | | | SHIP LEVEL: 010-00482-0() | 2C40c | |
| | | | UNIT LEVEL: 011-01264-0() | 2C41d | |
| | | | | C52b | |
| | | | | 2C63c | |
| | | | | 2C87 | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C147 | |
| | | | | C151a | |
| EASA.IM.21O.10034307 | 24/03/2011 | GDU 1040A with Software 10.x Display Control | SHIPPING LEVEL: 010-00320-00 | C2d | 190-00303-3B |
| | | | SYSTEM SOFTWARE: 006-B0319-8() | C3d | |
| | | | UNIT LEVEL: 011-00916-00 | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | C74d | | | | |
| | 2C87 | | | | |
| | C92c | | | | |
| | C110a | | | | |
| | 2C112b | | | | |
| | C113 | | | | |
| | C118 | | | | |
| | C119c | | | | |
| | C129a | | | | |
| | C146 | | | | |
| | C147 | | | | |
| | C151b | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|------------------|---------------|
| EASA.IM.21O.10034311 | 24/03/2011 | GDU 1040 with Software 10.x Display Control | SHIPPING LEVEL: 010-00337-02 SUPERSET 010-00337-99 SYSTEM SOFTWARE: 006-B0319-8() UNIT LEVEL: 011-00972-02 THROU | C2d | 190-00303-3A |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10034532 | 11/04/2011 | GDU 1042 with Software 10.x Display Control | 011-01080-00 THROUGH -4() SHIP LEVEL: 010-00367-00 THROUGH -4(), UNIT LEVEL: WITH SYSTEM SW 006-B0319-8() | C2d | 190-00303-3C |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------|---------------|
| EASA.IM.21O.10034670 | 19/04/2011 | GDU 1044 with Software 10.x Display Control | 010-00365-00 THROUGH -4() SHIPPING LEVEL, 011-01078-00 THROUGH -4() UNIT LEVEL WITH SYSTEM SW 006-B0319-8() | C2d | 190-00303-3E |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10034676 | 19/04/2011 | GDU 1043 WITH SOFTWARE 10.X DISPLAY CONTROL | 010-00366-00 THROUGH -4() SHIPPING LEVEL, 011-01079-00 THROUGH -4() UNIT LEVEL WITH SYSTEM SW 006-B0319-8() | C2d | 190-00303-3D |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|------------------|---------------|
| EASA.IM.21O.10034687 | 20/04/2011 | GDU 1044B WITH SOFTWARE 10.x DISPLAY CONTROL | 010-00471-00 THROUGH -4() SHIPPING LEVEL, 011-01274-00 THROUGH -4() UNIT LEVEL WITH SYSTEM SW 006-B0319-8() | C2d | 190-00303-3G |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10034689 | 20/04/2011 | GDU 1045 WITH SOFTWARE 10.x DISPLAY CONTROL | 010-00279-02 THROUGH -4() SHIPPING LEVEL, 011-0819-02 THROUGH -4() UNIT LEVEL WITH SYSTEM SW 006-B0319-8() | C2d | 190-00303-3F |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------|---------------|
| EASA.IM.21O.10034693 | 20/04/2011 | GDU 1500 WITH SOFTWARE 10.x DISPLAY CONTROL | 006-B0319-8() 010-00387-00 THROUGH -4() 011-01108-00 THROUGH -4() AND -99 SHIPPING LEVEL, UNIT LEVEL WITH SYSTEM SW | C2d | 190-00303-19 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10034698 | 20/04/2011 | GDU 1240A WITH SOFTWARE 10.x DISPLAY CONTROL | 006-B0319-8() 010-00559-00 THROUGH -5() 011-01440-00 THROUGH -5() AND -99 SHIPPING LEVEL, UNIT LEVEL WITH SYSTEM SW | C2d | 190-00303-52 |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C146 | |
| | | | | C147 | |
| C151b | | | | | |

| GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA | | | | | |
|--|--------------------|--|-----------------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.21O.10035895 | 26/07/2011 | GDU 1040 with Software 11.x Display Control | 006-B0319-9() | C2d | 190-00303-3L |
| | | | 010-00337-02TROU -4()& -99 | C3d | |
| | | | 011-00972-02 THROUGH -4() | C4c | |
| | | | 11.10 OR HIGHER 11.XX : | C6d | |
| | | | SHIPPING LEVEL: | C8d | |
| | | | SYSTEM SOFTWARE | C9c | |
| | | | UNIT GDU1040, GDU1040H: | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| | C147 | | | | |
| | C151b | | | | |
| EASA.IM.21O.10035896 | 26/07/2011 | GDU 1040A with Software 11.x Display Control | 006-B0319-90... | C2d | 190-00303-3M |
| | | | 010-00320-00 | C3d | |
| | | | 011-00916-00... | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| | C147 | | | | |
| | C151b | | | | |

| GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA | | | | | |
|--|--------------------|---|---|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.21O.10035897 | 26/07/2011 | GDU 1042 with Software 11.x Display Control | 006-B0319-90... 010-00367-00... 011-01080-00.. | C2d | 190-00303-3N |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10035898 | 26/07/2011 | GDU 1043 with Software 11.x Display Control | 006-B0319-90... 010-00366-00... 011-01079-00... | C2d | 190-00303-3P |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---|------------------|---------------|
| EASA.IM.21O.10035899 | 26/07/2011 | GDU 1044 with Software 11.x Display Control | 006-B0319-90... 010-00365-00... 011-01078-00.. | C2d | 190-00303-3Q |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |
| EASA.IM.21O.10035901 | 26/07/2011 | GDU 1044B with Software 11.x Display Control | 006-B0319-90... 010-00471-00... 011-01274-00... | C2d | 190-00303-3S |
| | | | | C3d | |
| | | | | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| C147 | | | | | |
| C151b | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|-------------------------------|------------------|---------------|
| EASA.IM.21O.10035903 | 26/07/2011 | GDU 1045 with Software 11.x Display Control | 006-B0319-90... | C2d | 190-00303-3R |
| | | | 010-00279-02... | C3d | |
| | | | 011-00819-02... | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| | C147 | | | | |
| | C151b | | | | |
| EASA.IM.21O.10035905 | 26/07/2011 | GDU 1500 with Software 11.x Display control | 006-B0319-90... | C2d | 190-00303-1A |
| | | | 010-00387-00 THROUGH -4() ... | C3d | |
| | | | 011-01108-00 THROUGH -4() ... | C4c | |
| | | | | C6d | |
| | | | | C8d | |
| | | | | C9c | |
| | | | | C10b | |
| | | | | 2C34f | |
| | | | | 2C35d | |
| | | | | 2C36f | |
| | | | | 2C37e | |
| | | | | 2C38e | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | | | | C43c | |
| | | | | C44b | |
| | | | | C45a | |
| | | | | C47 | |
| | | | | C49b | |
| | | | | C52b | |
| | | | | C55 | |
| | | | | 2C63c | |
| | | | | 2C66b | |
| | | | | C74d | |
| | | | | 2C87 | |
| | | | | C92c | |
| | | | | C110a | |
| | | | | 2C112b | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | C119c | |
| | | | | C129a | |
| | | | | C146 | |
| | C147 | | | | |
| | C151b | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---|--|---------------|
| EASA.IM.210.10035906 | 26/07/2011 | GDU 1240A with Software 11.x Display Control | 006-B0319-90... 010-00559-00 THROUGH -5)... 011-01440-00 THROUGH -5)... | C2d C3d C4c C6d C8d C9c C10b 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C43c C44b C45a C47 C49b C52b C55 2C63c 2C66b C74d 2C87 C92c C110a 2C112b C113 C118 C119c C146 C147 C151b | 190-00303-53 |
| EASA.IM.210.10037005 | 25/10/2011 | GMN-00802-A Garmin Servo Actuator | 010-00802-0() TO 010-00802-2() 010-00802-99 011-02213-0() TO 011-02213-2()) | C9c | 190-01085-00 |
| EASA.IM.210.10037014 | 25/10/2011 | GMN-00803-A Garmin Servo Mount | 010-00803-0() TO 010-00803-3() 010-00803-99 011-02214-0() TO 011-02214-3()) | C9c | 190-01086-00 |
| EASA.IM.210.10037276 | 16/11/2011 | GMN-00831-A Audio Panel | 010-00831-0() SHIPPING 010-00831-99 SUPERSET 011-02299-0 () LEVEL UNIT LEVEL GMA 35: | 2C35d C139 | 190-00858-10 |
| EASA.IM.210.10037615 | 12/12/2011 | GMN-00813-A GPS/WAAS Navigator | SHIPPING LEVEL 010-00811-0() SHIPPING LEVEL 010-00811-5() SUPERSET 010-00811-99() UNIT LEV. GTN625:011-02254-0() WITH APP. SW 006-B1026-0() | C74d C110a 2C112b C113 C118 C146 C147 C151b C165 | 190-01004-06 |
| EASA.IM.210.10037621 | 12/12/2011 | GMN-00820-A GPS/WAAS Navigator | SHIPPING LEVEL 010-00819-0() SHIPPING LEVEL 010-00819-5() SUPERSET 010-00819-99 UNIT LEV. GTN725:011-02281-0() WITH APP. SW 006-B1026-0() | C74d C110a 2C112b C113 C118 C139 C146 C147 C151b C165 | 190-01007-06 |
| EASA.IM.210.10037626 | 12/12/2011 | GMN-00813-B GPS/WAAS/COM Navigator | SHIPPING LEVEL 010-00812-0() SHIPPING LEVEL 010-00812-5() SUPERSET 010-00812-99 UNIT LEV. GTN635:011-02255-0() WITH APP. SW 006-B1026-0() | 2C37e 2C38e C74d C110a 2C112b C113 C118 2C128 C146 C147 C151b C165 | 190-01004-07 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|--|---------------|
| EASA.IM.210.10037627 | 12/12/2011 | GMN-00813-C GPS/WAAS/NAV/COM Navigator | SHIPPING LEVEL: 010-00813-0() SHIPPING LEVEL: 010-00813-5() SHIPPING LEVEL: 010-00889-0() SHIPPING LEVEL: 010-00889-5() SUPERSET: 010-00813-99 UNIT LEV. GTN650:011-02256-0() UNIT LEV. GTN650:011-02256-5() WITH APPL. SW: 006-B1026-0() | 2C34f 2C36f 2C37e 2C38e 2C40c C74d C110a 2C112b C113 C118 2C128 C146 C147 C151b C165 | 190-01004-08 |
| EASA.IM.210.10041516 | 24/09/2012 | GMN-00962-A GTS Processor (TAS, TCAS I, TCAS II) | 010-00962-0() 010-00962-99 SUPERSET 011-02571-0() GTS 825, GTS 855, GTS 8000: SHIPPING LEVEL THROUGH 010-00962-2() THROUGH 011-02571-2() | C118 C119c C147 C166b | 190-00587-53 |
| EASA.IM.210.10041969 | 29/10/2012 | GMN-00736-A Air Traffic Control Radar Beacon System | 010-00736-0() SHIPPING LEVEL 010-00736-99 SUPERSET GTX 3000 UNIT: 011-01997-0() | C112c C166b | 190-00926-04 |
| EASA.IM.210.10042451 | 03/12/2012 | GMN-0971 Automatic Flight Control System Mode Controller | 010-00971-0() 010-00971-3 010-00971-8(), SUPERSET: 010-00971-99, GMC 7200: 011-02584-0() 011-02584-3() 011-02584-9() WITH SHIP. LEVEL. SW 006-B0742-1() | C9c C52b | 190-00303-89 |
| EASA.IM.210.10042463 | 03/12/2012 | GMN-00949 Automatic Flight Control System Mode Controller | 010-00949-8() 011-02544-8() GMC 7250: 011-02544-0() SHIP. LEVEL 010-00949-0() SUPERSET: 010-00949-99 WITH SW 006-B0742-1() | C9c C52b | 190-00303-88 |
| EASA.IM.210.10043491 | 04/02/2013 | GMN-00999-A VHF COM Transceiver | 006-B1061-05 TO -0() 010-01026-5() GTR 225A 011-02807-0() SHIP 010-01026-0() SW 006-B1374-03 TO 0() | 2C128 2C169A | 190-01479-00 |
| EASA.IM.210.10043506 | 04/02/2013 | GMN-00999-C NAV COM | 006-B0082-12 TO -1() 006-B1061-05 TO -0() 010-01025-5() GNC 255A 011-02806-0() SHIP 010-01025-0() SW: 006-B1374-03 TO -0() | 2C34f 2C36f 2C40c 2C128 2C169A | 190-01479-02 |
| EASA.IM.210.10044335 | 05/04/2013 | GMN-00820-A SW 3.0 GPS/WAAS Navigator | 010-00819-0(), 010-00819-5(), APPL. SW 006-B1026-1(), SHIP: GTN 725: 011-02281-0() WITH SUPERSET: 010-00819-99 | 2C35d 2C63c C74d C110a C112c C113 C118 C139 C146c C147 C151b C165 | 190-01007-06 |
| EASA.IM.210.10044462 | 15/04/2013 | GMN-00724-B (GAD 43e) Gyro Adapter | GAD 43E: 011-02349-0() SHIP: 010-00852-0() SUPERSET: 010-00852-99 SW:006-B1176-0(),006-B0876-0() | C3d C4c C6d C9c 2C36f 2C40c | 190-01103-01 |
| EASA.IM.210.10045769 | 17/07/2013 | GMN-00813-B GPS/WAAS/COM Navigator SW v 3.xx | 006-B1026-1() APPLICATION 010-00812-5(), 010-00812-A() SHIPPINGLEVEL:010-00812-0() SUPERSET: 010-00812-99 SW V 3.XX UNIT LEVEL GTN 635: 011-0225 WITH APPL. SW 006-B-1026-1() | C74d C110a C112c C113 C118 2C128 C146c C147 C151b C165 | 190-01004-07 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|--|---------------|
| EASA.IM.210.10045770 | 17/07/2013 | GMN-00813-A GPS/WAAS NAVIGATOR SW v3.xx | 010-00811-5() SHIPPINGLEVEL: 010-00811-0() SUPERSET: 010-00811-99 UNIT LEVEL GTN 625: 011-02254- WITH APP. SW 006-B1026-1() | C74d C110a C112c C113 C118 C146c C147 C151b C165 | 190-01004-06 |
| EASA.IM.210.10045772 | 17/07/2013 | GMN-00813-C GPS/WAAS/NAV/COM Navigator SW v3.xx | 010-00813-5(), 010-00813-A() 010-00889-0(), 010-00889-5() 010-01059-0(), 010-01059-A() 011-002256-5(), 011-002256-A() SHIPPINGLEVEL: 010-00813-0() SUPERSET 010-00813-99 APPL. SW: 006-B1026-1() UNIT LEVEL GTN 650:011-002256 | 2C34f 2C36f 2C40c C74d C110a C112c C113 C118 2C128 C146c C147 C151b C165 | 190-01004-08 |
| EASA.IM.210.10046140 | 21/08/2013 | GMN-00813-C SW 4.xx GPS/WAAS/NAV/COM Navigator (GTN650) | 006-B1026-2() V4.00 010-00813-0(), 010-00813-5() 010-00813-99 SUPERSET 010-00813-A(), 010-00889-0() 010-00889-5(), 010-01059-0() 010-01059-A() SHIPPING LEVEL 011-02256-0(), 011-02256-5() 011-02256-A() UNIT LEVEL APPLICATION SOFTWARE | 2C34f 2C36f 2C40c C74d C110a C112c C113 C118 2C128 C146c C147 C151b C165 2C169A C194 | 190-01004-32 |
| EASA.IM.210.10046151 | 22/08/2013 | GMN-00813-B SW 4.xx GPS/WAAS/COM Navigator (GTN635) | 006-B1026-2() V4.00 010-00812-0(), 010-00812-5() 010-00812-99 SUPERSET 010-00812-A() SHIPPING LEVEL 011-02255-0() UNIT LEVEL APPLICATION SOFTWARE | C74d C110a C112c C113 C118 2C128 C146c C147 C151b C165 2C169A C194 | 190-01004-31 |
| EASA.IM.210.10046152 | 22/08/2013 | GMN-00813-A SW 4.xx GPS/WAAS Navigator (GTN625) | 006-B1026-2() GTN625 010-00811-0(),010-00811-5() 010-00811-99 GTN625 SUPERSET 011-02254-0() GTN625 APPLICATION SOFTWARE V4.00 GTN625 SHIPPING LEVEL UNIT LEVEL | C74d C110a C112c C113 C118 C146c C147 C151b C165 C194 | 190-01004-30 |
| EASA.IM.210.10047478 | 13/12/2013 | GMN-00946-A (GRA 5500) Radar Altimeter | 006-B1447-00 THROUGH 006-B1447-03 APPLICATION 006-B1447-0() EXCEPT 010-00946-0() 010-00946-99 SUPERSET 011-02537-0() SHIPPING LEVEL SOFTWARE THROUGH 010-00946-2() THROUGH 011-02537-2() UNIT LEVEL | 2C87 | 190-01277-03 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---|---|---------------|
| EASA.IM.210.10048915 | 23/04/2014 | GMN-00820-A (GTN 725 v5.xx) Navigator | 006-B1026-3()SOFTWARE (V5.00) 010-00819-0() AND 010-00819-5()SHIPPING LEVEL 010-00819-99 SUPERSET 011-02281-0() UNIT LEVEL | 2C35d 2C63c C74d C110a C112c C113 C118 C139 C146c C147 C151b C165 C194 | 190-01007-33 |
| EASA.IM.210.10049560 | 18/06/2014 | GDU 620 (G600) PFD/MFD Control Display with SW v6.01 | 006-B0498-41 THRU -4() V6.XX 010-00482-0() SHIPPING LEVEL 010-00482-1() SHIPPING LEVEL 010-00482-2() SHIPPING LEVEL 010-00482-3() SHIPPING LEVEL 010-00482-99 SUPERSET 011-01264-0() UNIT LEVEL 011-01264-1() UNIT LEVEL 011-01264-2() UNIT LEVEL 011-01264-3() UNIT LEVEL APPLICATION SOFTWARE | C2d C3d C4c C6e C8e C10b 2C34f 2C36f 2C40c 2C41d C43c C47a C49b C52b 2C63c 2C87 C113 C118 C147 C151b | 190-01032-08 |
| EASA.IM.210.10050444 | 11/09/2014 | GEA 7100 Engine Airframe Unit (GMN-00993-A) | 010-00993-0() SHIPPING LEVEL 010-00993-99 SUPERSET 011-02635-0() UNIT LEVEL | C43c C44c C45b C47a C49b C55 | 190-01360-01 |
| EASA.IM.210.10050649 | 26/09/2014 | GAC 9200 Actuator Controller | 006-B1337-0() 006-B1337-1() 006-B1337-2() 006-B1337-3() 006-B1337-4() 010-00988-0() 010-00988-1() 010-00988-2() 010-00988-99 011-02629-0() 011-02629-1(), 011-02629-2() EXCL.006-B1337-00,006-B1337-01 | C9c | 190-01377-00 |
| EASA.IM.210.10051940 | 19/01/2015 | GMC 715 Mode Controller | 006-B0576-0() EXCEPT (0) 010-00554-0() 010-00554-1() 010-00554-2() 011-01430-0() 011-01430-1() 011-01430-2() GMC 715 SHIPPING LEVEL GMC 715 UNIT LEVEL GMS 715 SYSTEM SOFTWARE | C9c C52b | 190-00303-68 |
| EASA.IM.210.10052504 | 05/03/2015 | GMN-00736 (GTX 3000) //Air Traffic Control Radar Beacon Syst | 006-B0912-1() AND -02 SYSTEM 010-00736-0() SHIPPING LEVEL 010-00736-99 SUPERSET 011-01997-0() UNIT LEVEL SOFTWARE V 3.XX | C112d C166b | 190-00926-05 |
| EASA.IM.210.10052514 | 06/03/2015 | Iridium Data Link System | 006-B1150-1() GSR 56E UNIT 010-00815-01 010-00815-4() 010-00815-5() 010-00815-99 011-02268-01 011-02268-4() 011-02268-5() GSR 56E SHIPPING LEVEL GSR 56E UNIT ONLY SOFTWARE | C159a 2C514 | 190-01849-00 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|---|--|--|---------------|
| EASA.IM.210.10053168 | 04/05/2015 | GDU 1040/1040H with SW v13.xx MFD/ PFD Display | 006-B0319-B() 010-00337-02 THROUGH -1() 010-00337-2() 010-00337-3() THROUGH -4() 010-00337-99 010-00337-99 GDU1040H 011-00972-02 THROUGH -1() 011-00972-2() 011-00972-3() THROUGH 4() GDU 1040/GDU 1040H GDU1040H (UNIT LEVEL) GDU 1040 (SHIPPING LEVEL) GDU 1040 (UNIT LEVEL) (SHIPPING LEVEL) SOFTWARE VERSION 13.XX FOR | C2d C3d C4c C10b 2C34f 2C35d 2C36f 2C40c 2C41d C43c C49b 2C63c 2C66b C92c C110a C113 C118 C119c C146c C147 C151b C194 | 190-00303-3T |
| EASA.IM.210.10055357 | 04/11/2015 | GTX 330 / GTX 330D // Mode S Transponder with Extended Squit | 006-B0172-01(VERSION8.XX)SOFTW 010-00230-() - SHIPPING LEVEL 011-00455-() - UNIT LEVEL GTX 330 GTX 330D SEE APPL.FORM FOR COMPLETENESS | C112d C166b | 190-00421-02 |
| EASA.IM.210.10055433 | 09/11/2015 | GTX 33 / GTX 33D // Mode S Transponder with Extended Squit | 006-B0172-01(VERSION8.XX)SOFTW 010-00267-99 - SUPERSET 010-00267-() - SHIPPING LEVEL 010-00294-() - SHIPPING LEVEL 011-00779-() - UNIT LEVEL GTX 33 GTX 33D SEE APPLICATION FORM FOR COMPL | C112d C166b | 190-00421-03 |
| EASA.IM.210.1002, REV. A | 16/01/2015 | GDU 1400W (GMN-00716) | 006-B1177-0() SOFTWARE 010-00716-0() THROUGH 5() 011-01910-0() THROUGH 5() SHIPPING LEVEL UNIT LEVEL | C113 | 190-00303-90 |
| EASA.IM.210.10037186, REV. A | 16/11/2011 | GMN-00871-A Audio Panel | 010-00871-0() SHIPPING LEVEL 010-00871-1() SHIPPING LEVEL 010-00871-99 SUPERSET GMA350: 011-02385-0() GMA350H: 011-02385-1() | 2C35d C139 | 190-01134-10 |
| EASA.IM.210.10037616, REV. A | 10/04/2013 | GMN-00820-B SW 2.0 GPS/WAAS/NAV/ COM Navigator | APP. SOFTWARE: 006-B1026-0() SHIPPING LEVEL: 010-00820-0() SHIPPING LEVEL: 010-00820-5() SHIPPING LEVEL: 010-00890-0() SHIPPING LEVEL: 010-00890-5() SHIPPING LEVEL: 010-01060-0() SHIPPING LEVEL: 010-01060-A() SUPERSET: 010-00820-99() UNIT LEV. GTN750:011-02282-0() UNIT LEV. GTN750:011-02282-5() UNIT LEV.GTN750:011-02282-A() | 2C34f 2C36f 2C37e 2C38e 2C40c C74d C110a 2C112b C113 C118 C139 C146 C147 C151b C165 | 190-01007-08 |
| EASA.IM.210.10043488, REV. A | 24/09/2014 | GTR 225B | 006-B1374-03 THRU-0() 010-01027-0() 010-01027-2() 010-01027-5() 010-01027-7() 010-01027-99 011-02808-0 () 011-02808-2() NV GTR 225B (UNIT ONLY) NV GTR 225B NIGHT VISION (UNIT SHIPPING LEVEL GTR 225B NIGHT SHIPPING LEVEL GTR 225B N V S SHIPPING LEVEL GTR 225B STAND SHIPPING LEVEL GTR 225B (UNIT SOFTWARE | 2C128 2C169A | 190-01479-01 |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|--------------------------------|------------------|---------------|
| EASA.IM.210.10043490, REV. A | 25/09/2014 | GNC 255B | 006-B1374-03 | 2C34f | 190-01479-03 |
| | | | 010-00999-0() | 2C36f | |
| | | | 010-00999-2() | 2C40c | |
| | | | 010-00999-5() | 2C128 | |
| | | | 010-00999-7() | 2C169A | |
| | | | 011-02719-0() | | |
| EASA.IM.210.10044337, REV. A | 30/04/2013 | GMN-00820-B SW 3.0 GPS/WAAS/NAV/COM Navigators | 010-00820-5(), 010-00890-0() | 2C34f | 190-01007-08 |
| | | | 010-00820-A() | 2C35d | |
| | | | 010-00890-5(), 010-01060-0() | 2C36f | |
| | | | 010-01060-A(), | 2C40c | |
| | | | 011-02282-5(), 011-02282-A() | 2C63c | |
| | | | APPLICATION: SW: 006-B1026-1() | C74d | |
| | | | GTN 750: 011-02282-0() | C110a | |
| | | | SHIP. LEVEL: 010-00820-0() | C112c | |
| | | | SUPERSET: 010-00820-99 | C113 | |
| | | | | C118 | |
| | | | | 2C128 | |
| | | | | C139 | |
| | | | | C146c | |
| | | | | C147 | |
| | C151b | | | | |
| | C165 | | | | |
| EASA.IM.210.10045530, REV. A | 05/08/2013 | GMN-00820-A SW 4.xx GPS/WAAS Navigator | 006-B1026-2() APPLICATION | 2C35d | 190-01007-30 |
| | | | 010-00819-0(),010-00819-5() | 2C63c | |
| | | | 010-00819-99 SUPERSET | C74d | |
| | | | 011-02281-0() UNIT LEVEL | C110a | |
| | | | SHIPPING LEVEL | C112c | |
| | | | SOFTWARE (V4.00) | C113 | |
| | | | | C118 | |
| | | | | C139 | |
| | | | | C146c | |
| | | | | C147 | |
| | | | | C151b | |
| | C165 | | | | |
| | C194 | | | | |
| EASA.IM.210.10046137, REV. A | 20/08/2013 | GMN-00820-B SW 4.xx GPS/WAAS/NAV/COM Navigator | 010-00820-5(), 010-00820-A() | 2C34f | 190-01007-32 |
| | | | 010-00890-0(), 010-00890-5() | 2C35d | |
| | | | 010-01060-0(), 010-01060-A() | 2C36f | |
| | | | 011-02282-5(), 011-02282-A() | 2C40c | |
| | | | GTN 750: 011-02282-0() | 2C63c | |
| | | | SHIP LEVEL: 010-00820-0() | C74d | |
| | | | SUPERSET: 010-00820-99 | C110a | |
| | | | WITH APPL. SW 006-B1026-2() | C112c | |
| | | | | C113 | |
| | | | | C118 | |
| | | | | 2C128 | |
| | | | | C139 | |
| | | | | C146c | |
| | | | | C147 | |
| | C151b | | | | |
| | C165 | | | | |
| | 2C169A | | | | |
| EASA.IM.210.10048536, REV. A | 24/03/2014 | GPS/SBAS/NAV/COM Navigator GTN750 | 006-B1026-3() | 2C34f | 190-01007-35 |
| | | | 010-00820-5() BLACK, STD | 2C35d | |
| | | | 010-00820-A() BLACK, HELI STD | 2C36f | |
| | | | 010-00890-0() GRAY | 2C40c | |
| | | | 010-00890-5() GRAY, STD | 2C63c | |
| | | | 010-01060-A() NV, BLACK, HELI | C74d | |
| | | | 011-02282-5() GRAY | C110a | |
| | | | 011-02282-A() NV | C112c | |
| | | | 10-01060-0() NV, BLACK | C113 | |
| | | | APPLICATION SOFTWARE: | C118 | |
| | | | SETS: 010-00820-0() BLACK | 2C128 | |
| | | | STD | C139 | |
| | | | SUPERSET: 010-00820-99 | C146c | |
| | | | UNIT ONLY: 011-02282-0() BLACK | C147 | |
| | | | | C151b | |
| | | | | C165 | |
| | 2C169A | | | | |
| | C194 | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|--------------------------------|------------------|---------------|
| EASA.IM.210.10048910, REV. A | 05/05/2014 | GPS/SBAS/NAV/COM Navigator GTN 650 | 006-B1026-3() SOFTWARE (V5.XX) | 2C34f | 190-01004-35 |
| | | | 010-00813-0() SHIPPING LEVEL | 2C36f | |
| | | | 010-00813-5() SHIPPING LEVEL | 2C40c | |
| | | | 010-00813-99 SUPERSET | C74d | |
| | | | 010-00813-A() SHIPPING LEVEL | C110a | |
| | | | 010-00889-0() SHIPPING LEVEL | C112c | |
| | | | 010-00889-5() SHIPPING LEVEL | C113 | |
| | | | 010-01059-0() SHIPPING LEVEL | C118 | |
| | | | 010-01059-A() SHIPPING LEVEL | 2C128 | |
| | | | 011-02256-0() UNIT BLACK | C146c | |
| | | | 011-02256-5() UNIT GRAY | C147 | |
| | | | 011-02256-A() UNIT NV | C151b | |
| | | | BLACK | C165 | |
| | | | BLACK, HELI STD | 2C169A | |
| | | | BLACK, STD | C194 | |
| | | | GRAY | Other | |
| | | | EASA.IM.210.10048927, REV. B | 07/05/2014 | |
| 010-00811-0() SHIPPING LEVEL | C110a | | | | |
| 010-00811-5() SHIPPING LEVEL | C112c | | | | |
| 010-00811-99 SUPERSET | C113 | | | | |
| 011-02254-0() UNIT LEVEL | C118 | | | | |
| | 2C128 | | | | |
| | C146c | | | | |
| | C147 | | | | |
| | C151b | | | | |
| | C165 | | | | |
| | C194 | | | | |
| EASA.IM.210.10048928, REV. A | 05/05/2014 | GPS/SBAS/COM Navigator GTN 635 | 006-B1026-3() SOFTWARE (V5.XX) | C74d | 190-01004-34 |
| | | | 010-00812-0() SHIPPING LEVEL | C110a | |
| | | | 010-00812-5() SHIPPING LEVEL | C112c | |
| | | | 010-00812-99 SUPERSET | C113 | |
| | | | 010-00812-A() SHIPPING LEVEL | C118 | |
| | | | 011-02255-0() UNIT LEVEL | 2C128 | |
| | | | | C146c | |
| | | | | C147 | |
| | C151b | | | | |
| | C165 | | | | |
| | 2C169A | | | | |
| | Other | | | | |
| EASA.IM.210.10049559, REV. A | 20/06/2014 | GDU 620 (G500) PFD/MFD Display with SW v6.01 | 006-B1071-41 THRU -4() V6.XX | C2d | 190-01032-07 |
| | | | 010-00482-5() SHIPPING LEVEL | C3d | |
| | | | 010-00482-6() SHIPPING LEVEL | C4c | |
| | | | 010-00482-99 SUPERSET | C6e | |
| | | | 011-01264-5() UNIT EVEL | C8e | |
| | | | 011-01264-6() UNIT LEVEL | C10b | |
| | | | APPLICATION SOFTWARE | 2C34f | |
| | | | | 2C36f | |
| | | | | 2C40c | |
| | | | | 2C41d | |
| | C43c | | | | |
| | C47a | | | | |
| | C49b | | | | |
| | C52b | | | | |
| | 2C63c | | | | |
| | 2C87 | | | | |
| | C113 | | | | |
| | C118 | | | | |
| | C147 | | | | |
| EASA.IM.210.1061, REV. A | 21/07/2008 | GDU 1040 Control Display | 010-00337-() EXCL -00&-01 SL | C9c | 190-00303-30 |
| | | | 011-00972-() EXCL -00&-01 UL | C52b | |
| | | | | 2C63c | |
| | | | | 2C87 | |
| | | | | 2C112b | |
| | | | | C118 | |
| | C146 | | | | |
| | C151a | | | | |
| EASA.IM.210.1120, REV. A | 01/03/2011 | GDL 59 Data Link System | 010-00666-0() | C50c | 190-00912-00 |
| | | | 010-00666-1() | | |
| | | | 010-00666-99 | | |
| | | | 011-01746-0() | | |
| | | | 011-01746-1() | | |
| | | | SHIPPING LEVEL | | |
| | | | SUPERSET | | |
| UNIT LEVEL | | | | | |

GARMIN INTERNATIONAL, Inc. - 1200 EAST 151ST STREET 66062 OLATHE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------------|--------------------|--|---|------------------|------------------------------|
| EASA.IM.210.1184, REV. B | 23/04/2015 | GTC 570 (GMN-00721) 5.7" Touchscreen Controller | 006-B1070-2() APPLICATION 010-00721-1() 010-00721-2() 010-00721-3() 010-00721-4() 010-00721-5() SHIPPING LEVEL 011-01924-1() 011-01924-2() 011-01924-3() 011-01924-4() 011-01924-5() UNIT LEVEL SOFTWARE | C113 C146c | 190-00986-00 |
| EASA.IM.210.1255, REV. B | 02/10/2012 | GTX 33 / GTX 33D Software Vers. 6.00 or later and GMN-01014- | 010-00267-0() TO -3() 010-00267-4() TO -8() 010-00267-99 SUPERSET 010-00294-0() TO -3() 010-00294-4() TO -8() 010-00294-99 SUPERSET 010-01014-0() TO -1() 010-01014-99 SUPERSET GTX 23: GTX 33: GTX 33D: GTX 33DH: GTX 33H: SW 006-B0172-01 SW 006-B1417-0() TO -2() UNIT: 011-00779-() UNIT: 011-02803-0() TO -1() | 2C112b C166a | 190-00421-00 190-00421-01 |
| EASA.IM.210.1300, REV. A | 23/05/2011 | GMN-00641-B Iridium Data Link System | 010-00815-0() GSR 56 SHIP LEV 010-00815-1() GSR 56H SHIP LE 010-00815-99 SUPERSET 011-02268-0() GSR 56 UN LEV 011-02268-1() GSR 56H UN LEV | C50c 2C514 | 190-01121-00 |
| LBA.N-O.10.916/020JTSO | 25/09/2003 | GPS 400 | 010-00171-() 011-00504-() | | 190-00140-67 |
| LBA.N-O.10.916/024JTSO | 12/09/2003 | GPS 500 | 010-00176- () SHIPPING LEVEL | | QAA-801 |
| LBA.N-O.10.930/064 JTSO | 23/01/2003 | GTX 330/330D 2A | 010-00230-() 010-00293-() 011-00455-00, -20 011- 00455-10, -30 | | 190-00207-04 |
| LBA.N-O.10.930/065JTSO | 07/10/2002 | GTX 330 D Transponder | 010-00308-() 011-00455-40, -50 | | 190-00207-04 |
| LBA.N-O.10.930/57 JTSO | 20/06/2000 | GTX 327 SSR Transponder | 010-00188-() 011-00490- () | | 190-00187-07 |
| LBA.N-O.10.930/61 JTSO | 28/05/2001 | GTX 320A SSR ATC Transponder | 010-00247- () 011-00728- () | | 190-00133-10 |
| LBA.N-O.10.985/009JTSO | 02/06/2003 | GNS 530A GPS, VOR/ILS, VHF Comm | 010-00285- () SHIPPING LEVEL | | QAA-807 |

GARRECHT AVIONIK GmbH - AM GRABEN 4 55263 WACKERNHEIM GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|-----------------------|
| EASA.210.705 | 13/04/2007 | VT-02 Mode S Transponder | VT-0201 VT-0202-76 VT-0202-76AC VT-0203 | 2C112b | 02.0200.02 VT02DDP |
| EASA.210.1029 | 19/11/2008 | ATCRBS / Mode S Transponder Antenna Type BD-01 | BD01- () | 2C112b | 342010-BD01 |
| EASA.210.384, REV. A | 26/03/2007 | Mode S Transponder VT-01 | VT-0101- () () () VT-0102- () () ()-070 VT-0102- () () ()-125 VT-0103-1- () () VT-0103-2- () () VT-0104-070 VT-0104-125 | 2C112a | 01.0200.02 VT01DDP |

GE AVIATION SYSTEMS Ltd. - BISHOPS CLEEVE GL52 8SF CHELTENHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---------------------------|---|---------------|
| EASA.210.776 | 26/09/2007 | 345 MFD Electronic Instrumentation Display (EID) | 345MFD(X)-(X) MOD () () | C113 | SC10265 |
| EASA.210.777 | 26/09/2007 | 346 MFD Electronic Instrumentation Display (EID) | 346MFD(X)-(X) MOD () () | C113 | SC10266 |
| EASA.210.135, REV. A | 04/04/2008 | 322MFD Integrated Standby Indicator (ISIS) | 322MFD1-1 MOD() () | C2d C3d C4c C10b C106 C113 | SC10056 |
| CAA.O.00003 | 19/09/2001 | Intergrated Standby Indicator System (ISIS) | 314MFD1-1 | | |

GEMELLI S.p.A. - VIA BERNARDINO LUINI 8 21100 VARESE ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

GEMELLI S.p.A. - VIA BERNARDINO LUINI 8 21100 VARESE ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---------------------|------------------|-------------------------|
| EASA.210.727 | 20/07/2010 | Headset HG-222 | HG-222-()-() | C57a | HG-222-()-() |
| EASA.210.760 | 27/04/2012 | GEM-10-CCCU-()-() | GEM-10-CCCU-()-() | C50c | DDP-GEM-10-CCCU-()-() |
| EASA.210.766 | 28/06/2011 | Internal Communication Distribution Unit | GEM-10-RIB-()-() | C50c | DDP-GEM-10-RIB-()-() |
| EASA.210.10034034 | 02/03/2011 | GEM-05 Cabin Operator Communication Unit | GEM-05-COCU-()-() | C50c | GEM-05-COCU-()-() |
| EASA.210.10034933 | 13/05/2011 | GEM-06-ICDU | GEM-06-ICDU-()-() | C50c | DDP-GEM-06-ICDU-()-() |

GEVEN S.P.A. - ZONA IND. LE NOLA / MARIGLIANO 80035 NOLA ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------|---------------|
| EASA.210.003 | 19/05/2004 | Passenger Double Seat and for Passenger Triple Seat | 13F()-()-00000000 13L()-()-00000000 | C39b | 003/03 |
| EASA.210.026 | 19/05/2004 | Passenger Seats | 14F()-()-00000000 16F()-()-00000000 16G()-()-00000000 | C39b | 001/04 |
| EASA.210.229 | 05/01/2005 | Passenger Seat | 90A009-()-()-()-() 90C009-()-()-()-() | C39b | 003/04 |
| EASA.210.230 | 05/01/2005 | Passenger Seat | 17F113-()-()-()-() | C39b | 002/04 |
| EASA.210.307 | 08/07/2005 | SGL VIP Aircraft Seats | 94A114-()-()-()-() 94A116-()-()-()-() 94C114-()-()-()-() 94C116-()-()-()-() 95A116-()-()-()-() 95C116-()-()-()-() | C39b | 005/05 |
| EASA.210.533 | 11/07/2006 | Infinity Seat Model | A3F136-01-()-() A3G136-01-()-() | C39b | DDP-006/05 |
| EASA.210.537 | 14/07/2006 | Seat Model BREEZE | R0F139-01-()-() | C127a | DDP-003/05 |
| EASA.210.538 | 14/07/2006 | Seat model GEMINI | C0F137-01-()-() C0F137-02-()-() C0F138-01-()-() C0L509-01-()-() C0L509-02-()-() C0L510-01-()-() | C127a | DDP-002/05 |
| EASA.210.710 | 24/05/2007 | DIVA Economy Class Seat | A5F147-01-()-() A5F147-02-()-() A5L516-01-()-() A5L516-02-()-() A5L517-02-()-() | C39b | DDP-07-001 |
| EASA.210.004, REV. A | 06/01/2005 | Passenger DBL LH AFT Facing Seat | 20G108-FS791JC | C127a | 004/03 |
| EASA.210.1010 | 05/08/2008 | Passenger Seat New Diva | C5-01-()-()-()-() C5-02-()-()-()-() | C39b | 08-019 |
| EASA.210.1030 | 20/10/2008 | Observer Seat | G1-02-()-()-()-() | C39b | DDP-08-021 |
| EASA.210.1031 | 18/04/2008 | Infinity Plus | C0F137-03-()-() C0L509-03-()-() C0L509-04-()-() | C127a | 06-001 |
| EASA.210.1042 | 27/10/2008 | Observer Seat | G1-01-()-()-()-() | C127a | 08-022 |
| EASA.210.1116 | 02/12/2008 | Crew Rest Seat | A1-01-()-()-()-() | C39b | 08-018 |
| EASA.210.1151 | 11/12/2008 | Tekna Pilot and Passenger Seat | E5-01-()-()-()-() | C127a | DDP-08-001 |
| EASA.210.1191 | 20/05/2009 | Infinity Premium Passenger Seats | C6-01-()-()-()-() C6-02-()-()-()-() | C127a | 08-026 |
| EASA.210.1223 | 19/10/2009 | MITO Passenger seats | B1-01-()-()-()-() B1-02-()-()-()-() | C39b | 09-002 |
| EASA.210.1227 | 07/08/2009 | Infinity Premium Passenger seats | C6-03-()-()-()-() C6-04-()-()-()-() | C127a | 09-003 |
| EASA.210.1274 | 11/08/2009 | Floatation Cushion "Calipso" | ASP04305)1AA | C72c | 09-010 |
| EASA.210.279, REV. A | 14/02/2008 | Passenger Seat "Gemini" | A0F204-()-()-()-() A0F205-()-()-()-() A0L504-()-()-()-() A0L505-()-()-()-() | C39b | 001/05 |
| EASA.210.549, REV. A | 31/05/2007 | Seat model Globe | A4A013-01-()-() | C127a | DDP-06-005 |
| EASA.210.651, REV. A | 09/07/2010 | Operator & Observer Seats | A4A014-01-()-() A4A014-02-()-() | C39b | 007/05 |
| EASA.210.10035328 | 16/06/2011 | Seat Model Puma | A3-01-()-()-()-() | C39b | 10-025 |
| EASA.210.10035355 | 16/06/2011 | Seat Model NOVA | A2-01-()-()-()-() A2-02-()-()-()-() | C39b | 10-021 |
| EASA.210.10043657 | 15/02/2013 | Passenger Seat "C9" | C9-()-()-()-()-() | C127a | 11-035 |
| EASA.210.10043886 | 04/03/2013 | Passenger Seat Piuma EVO | D2-()-()-()-()-() | C127a | 12-021 |
| EASA.210.10044332 | 08/04/2013 | Flight Attendant Seat "One" | G2-01-000-000 G2-02-000-000 | C127a | 11-037 |
| EASA.210.10044508 | 17/04/2013 | Passenger Seat Privilege | R5-00-000-000 | C127a | 10-026 |
| EASA.210.10044612 | 23/04/2013 | COMODA + Passenger Seat | R7-()-()-()-()-() | C39c | DDP-13-009 |
| EASA.210.10044738 | 02/05/2013 | NOVA Passenger Seat | A2-()-()-()-()-() | C39c | DDP-13-025 |
| EASA.210.10044739 | 02/05/2013 | PUMA Passenger Seat | A3-()-()-()-()-() | C39c | DDP-13-024 |
| EASA.210.10045636 | 10/07/2013 | Comoda Passenger Seat | R7-00-000-000 R7E00-000-000 | C127a | DDP-12-023 |
| EASA.210.10053127 | 29/04/2015 | "VIP" SEAT MODEL // Passenger seats | R4-05-000-000 R4-07-000-000 | C39c | DDP-14-053 |

GEVEN S.P.A. - ZONA IND. LE NOLA / MARIGLIANO 80035 NOLA ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|--|------------------|---------------------------|
| EASA.21O.10030232, REV. B | 17/06/2013 | Seat MISTRAL | B7-01-() () () () B7-02-() () () () B8-01-() () () () | C39b | 10-003 |
| EASA.21O.10033671, REV. C | 08/07/2014 | Lightweight Classic & Prestige | D1-01-() () () () D1-03-() () () () D1-04-() () () () D1-06-() () () () | C127a | DDP-09-011 |
| EASA.21O.10034410, REV. C | 12/06/2012 | Passenger Seat "Piuma" | C7-01-() () () () C7-02-() () () () C7-03-() () () () C7-04-() () () () C7-07-() () () () C7-08-() () () () C7-10-() () () () C7-11-() () () () C7-13-() () () () C7-16-() () () () C7-17-() () () () | C127a | 10-016 |
| EASA.21O.10034654, REV. A | 24/03/2015 | Seat "Lightweight Classic & Prestige" (Aftward Facing) | D1-02-() () () () D1-05-() () () () | C127a | DDP-10-014 |
| EASA.21O.10036977, REV. A | 16/12/2011 | Passenger Seat "Steezy" | C8-01-() () () () C8-03-() () () () C8-04-() () () () C8-05-() () () () | C127a | 11-005 |
| EASA.21O.10044942, REV. A | 28/11/2014 | Floatation Cushion Dafne | DF01-() () () () DP01-() () () () | C72c | DDP-12-020 |
| EASA.21O.1026, REV. B | 15/04/2010 | Breeze Passenger seats Double Forward Facing | R2-05-() () () () R2-06-() () () () | C39b | DDP-08-020 |
| EASA.21O.1069, REV. A | 10/09/2009 | Slim HD Seats | C5-03-() () () () C5-04-() () () () | C39b | DDP-08-025 |
| EASA.21O.1111, REV. B | 12/01/2011 | Flotation Cushion / "Aphrodite" | ASP03115 () 1SP ASP05139 () 1ZA ASP05333 () 2SP | C72c | 08-024 |
| EASA.21O.1128, REV. A | 16/06/2011 | VIP Seat Model | R4-01-() () () () R4-02-() () () () R4-03-() () () () R4-04-() () () () | C39b | 08-017 |
| EASA.21O.1202, REV. A | 09/12/2014 | Breeze Passenger seats B/C, Forward Facing | R2-03-() () () () R2-04-() () () () R2-05-() () () () | C127a | DDP-09_001 |
| EASA.21O.1211, REV. H | 15/10/2015 | FLOATATION CUSHION / BEROE/ Floatation Cushion Non Inflatabl | ASP03115()1JS ASP03891()1AP ASP03891()1LL ASP03891()1PR ASP03891()1SR ASP03891()1TM ASP03891()1TP ASP03891()1TY ASP03891()1VA ASP03891()1WW ASP03891()1ZL ASP03892()1AP ASP03892()1LL ASP03892()1PR ASP03892()1SR ASP03892()1TM ASP03892()1TP ASP03892()1TY ASP03892()1VA ASP03892()1WW ASP03892()1ZL ASP05095()1PV ASP05095()2PV | C72c | DDP-08-002 |
| EASA.21O.1289, REV. A | 01/10/2009 | Slim HD Seats | C5-03-() () () () C5-04-() () () () | C127a | 08-025 |
| ENAC.O.016 | 06/06/2001 | Passenger seats | 10A101-() 10A501-() 10A502-() 11A101-() 11A501-() | | |
| ENAC.O.022 | 06/12/2001 | Passenger seats | AV08-()-() AV09-()-() | | LIGHT SPORT AEROPLANES |
| ENAC.O.030 | 28/05/2002 | Passenger seats | AV10-() () () AV11-() () () | | |
| ENAC.O.031 | 19/12/2002 | Passenger seats | 31A002-() () () () 32A002-() () () () 33A002-() () () () 34A002-() () () () | | 003/02 |

GEVEN S.P.A. - ZONA IND. LE NOLA / MARIGLIANO 80035 NOLA ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-----------------|--|--------------------|---------------|
| ENAC.O.044 | 26/09/2003 | Passenger seats | 20 A 006-FS152JC 20 A 006-FS262JC 20 A 006-FS782JC 20 A 006-FS832JC 20 F 108-FS151JC 20 F 108-FS241JC 20 F 108-FS261JC 20 F 108-FS781JC 20 F 108-FS831JC | JTSO-C39B Other | 002/03 |

GITA AVIATION (CHANGZHOU) CO. LTD. - GUANGHUA ROAD 213014 CHANGZHOU CHINA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|----------------------------------|--|------------------|---------------|
| EASA.21O.241 | 31/01/2005 | 2M2N Cargo Pallet Net Type GA-04 | GA-04-() | C90c | GAL-04DDP |
| EASA.IM.21O.604 | 19/01/2007 | GA-01 Cargo Net | GA-01/108-(GA-01/118-(GA-01/96-(| C90c | GAL-DDP-01 |
| EASA.IM.21O.605 | 19/01/2007 | GA-04 Cargo Net | GA-04/108-(GA-04/118-(GA-04/64-(GA-04/96-(| C90c | GAL-DDP-04 |
| EASA.IM.21O.606 | 19/01/2007 | GA-06 Cargo Net | GA-06/64-(GA-06/88-(| C90c | GAL-DDP-06 |
| EASA.IM.21O.607 | 19/01/2007 | GA-08 Cargo Net | GA-08/64-(GA-08/80-(| C90c | GAL-DDP-08 |
| EASA.IM.21O.10054424 | 13/08/2015 | Cargo Restraint Strap | GA-()1()-(X)(YYY) | C172 | GAL1401DDP |

GKN AEROSPACE SERVICES LIMITED - FERRY ROAD, EAST COWES PO32 6RA ISLE OF WIGHT UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|--------------------|------------------|---------------|
| EASA.21O.10036640 | 26/09/2011 | Crash-resistant flexible fuel tank material FPT/CR1185 | FPT/CR1185-()-() | C80 | TSO/DDP/3690 |
| EASA.21O.10046338 | 10/09/2013 | Crash-Resistant Flexible Fuel Tank Material FPT/CR1321 | FPT/CR1321-()-() | C80 | TSO/DDP/3971 |

GOODRICH CABIN SEATING SYSTEMS - 701 MAPLE STREET 54157 PESHTIGO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

| GOODRICH CABIN SEATING SYSTEMS - 701 MAPLE STREET 54157 PESHTIGO USA | | | | | |
|--|--------------------|--|------------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.461, REV. C | 29/05/2013 | Model 6004 Single Executive Passenger Seat | 603013-() | C127a | 065 |
| | | | 603014-() | | |
| | | | 603018-() | | |
| | | | 603019-() | | |
| | | | 603027-() | | |
| | | | 603048-() | | |
| | | | 603049-() | | |
| | | | 603052-() | | |
| | | | 603054-() | | |
| | | | 603060-() | | |
| | | | 603061-() | | |
| | | | 603062-() | | |
| | | | 603118-() | | |
| | | | 603119-() | | |
| | | | 603121-() | | |
| | | | 603123-() | | |
| | | | 603124-() | | |
| | | | 603127-() | | |
| | | | 603128-() | | |
| | | | 603130-() | | |
| | | | 603133-() | | |
| | | | 603134-() | | |
| | | | 603135-() | | |
| | | | 603137-() | | |
| | | | 603138-() | | |
| | | | 603140-() | | |
| | | | 603141-() | | |
| | | | 603142-() | | |
| | | | 603144-() | | |
| | | | 603149-() | | |
| | | | 603150-() | | |
| | | | 603153-() | | |
| | | | 603157-() | | |
| | | | 603159-() | | |
| | | | 603161-() | | |
| | | | 603162-() | | |
| | | | 603163-() | | |
| | | | 603165-() | | |
| | | | 603166-() | | |
| | | | 603170-() | | |
| | | | 603171-() | | |
| 603177-() | | | | | |
| 603178-() | | | | | |
| 603180-() | | | | | |
| 603187-() | | | | | |
| 603189-() | | | | | |
| 603190-() | | | | | |
| 603193-(), ES202-() | | | | | |
| 603198-() | | | | | |
| 603200-() | | | | | |
| EASA.IM.210.462, REV. C | 29/05/2013 | Model 6005 Double Executive Passenger Seat | 603015-() | C127a | 066 |
| | | | 603016-() | | |
| | | | 603017-() | | |
| | | | 603020-() | | |
| | | | 603024-() | | |
| | | | 603025-() | | |
| | | | 603026-(), 603112-() | | |
| | | | 603117-(), 603084-() | | |
| | | | 603122-() | | |
| | | | 603129-() | | |
| | | | 603131-() | | |
| | | | 603132-() | | |
| | | | 603136-() | | |
| | | | 603139-() | | |
| | | | 603143-() | | |
| | | | 603145-() | | |
| | | | 603154-() | | |
| | | | 603156-() | | |
| | | | 603158-() | | |
| | | | 603160-() | | |
| | | | 603164-() | | |
| | | | 603167-() | | |
| | | | 603168-() | | |
| | | | 603172-() | | |
| | | | 603179-() | | |
| 603182-() | | | | | |
| 603184-() | | | | | |
| 603188-() | | | | | |
| 603191-() | | | | | |
| 603194-(), ES203-() | | | | | |
| 603199-() | | | | | |

| GOODRICH CABIN SEATING SYSTEMS - 701 MAPLE STREET 54157 PESHTIGO USA | | | | | |
|---|--------------------|--|---|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10041949 | 26/10/2012 | 4412 Single Occupant Side Facing Divan | 260095-() | C39c | 161 |
| EASA.IM.210.10041967 | 29/10/2012 | 4026 Single-Occupant FF/RF Divan | 260022-() 260071-() 260083-() 260093-() | C127a | 157 |
| EASA.IM.210.10042066 | 06/11/2012 | 4413 Single-occupant forward and aft facing divan | 260096-() | C127a | 160 |
| EASA.IM.210.10043841 | 28/02/2013 | 4402 Side Facing Divan | 260019-(), 260091-() | C39c | 154 |
| EASA.IM.210.10043918 | 05/03/2013 | 1620 Divan | 960103-() | C39c | 166 |
| EASA.IM.210.10046030 | 07/08/2013 | 80A42S2 Multiple Occupant Divan | 960016-() 960022-() 960029-() 960030-() | C39c | 188 |
| EASA.IM.210.10047836 | 24/01/2014 | Model 6006 Single Occupant Dynamic Executive Seat | 603196-() | C127a | 171 |
| EASA.IM.210.10047837 | 24/01/2014 | Model 6007 Double Occupant Dynamic Executive Seat | 603197-() | C127a | 174 |
| EASA.IM.210.10047839 | 24/01/2014 | Model 5004 Single Occupant Executive Seat | 1000002565-(), 1000002566-() 1000002567-(), 1000002568-() 1000002569-(), 1000002570-() 1000002571-(), ES200-() 503072-(), 503087-() 503091-(), 503096-() 503098-(), 503117-() 503134-(), 503137-() 503142-(), 503143-() 503145-(), 503148-() 503149-(), 503150-() 503152-(), 503155-() 503157-(), 503158-() 503160-(), 503161-() 503163-(), 503164-() | C39c | 158 |
| EASA.IM.210.10047840 | 24/01/2014 | Model 5005 Two Occupant Executive Seat | 503009-(), 503010-() 503013-(), 503014-() 503015-(), 503071-() 503085-(), 503089-() 503092-(), 503097-() 503102-(), 503118-() 503135-(), 503136-() 503140-(), 503153-() 503154-(), 503156-() 503159-(), 503165-() ES201-() | C39c | 159 |
| EASA.IM.210.10050502 | 17/09/2014 | MODEL 3091 Side Facing Single Seat | 303796-() | C39c | 173 |
| EASA.IM.210.10050503 | 17/09/2014 | MODEL 3099 Side Facing Single Seat | 303795-() | C39c | 172 |
| EASA.IM.210.10050504 | 17/09/2014 | MODEL 4415 Aft Facing Double Convertible Divan | 260097-() | C127a | 192 |
| EASA.IM.210.10051938 | 19/01/2015 | Model 4418 // Side Facing Divan Module | 260101-XX | C39c | 203 |
| EASA.IM.210.10052728 | 24/03/2015 | Model 4417 // Aircraft single-occupant forward and aft facin | 260099-() | C127a | 202 |
| EASA.IM.210.10052749 | 25/03/2015 | MODEL 3507 // Side facing divan module | 303585-XX 303714-XX 303737-XX 303748-XX 303762-XX 303792-XX | C39c | 204 |
| EASA.IM.210.10042063, REV. A | 17/09/2014 | MODEL 4411 Single occupant side facing divan | 260070-() 260082-() 260094-() 260102-() | C39c | 162 |

| GOODRICH CORPORATION - 2730 WEST TYVOLA ROAD 28217-4578 CHARLOTTE USA | | | | | |
|--|--------------------|--|----------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10049339 | 02/06/2014 | Model No. 2312 Wall-mounted Single Cabin Attendant Seat | 2312-() | C127a | 14-1 |
| EASA.IM.210.10049340 | 02/06/2014 | Model No. 2313 Track-Mounted Single Cabin Attendant Seat | 2313-() | C127a | 14-1 |
| EASA.IM.210.10049341 | 02/06/2014 | Model No. 2314 Track-Mounted Double Cabin Attendant Seat | 2314-() | C127a | 14-1 |
| EASA.IM.210.10052016 | 27/01/2015 | Model 1425 // Floor-Mounted Flight Observer Seat (FOS) | 1425-1(), 1425-3() | C127a | 14-4 |
| EASA.IM.210.10052505 | 05/03/2015 | 2202 // Wall Mounted High Comfort Cabin Attendant Seat | 2202-() | C127a | 15-2 |
| EASA.IM.210.10052591 | 16/03/2015 | Model 2157 // Floor Mounted Cabin Attendant Seat | 2157-() | C127a | 15-3 |
| EASA.IM.210.10052592 | 16/03/2015 | Model 2158 // Wall Mounted Cabin Attendant Seat | 2158-() | C127a | 15-4 |

| GOODRICH LIGHTING SYSTEMS GmbH - BERTRAMSTRASSE 8 59557 LIPPSTADT GERMANY | | | | | |
|--|--------------------|--|--------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.1074 | 20/05/2011 | 2LA455557 Anticollision Light | 2LA455557-() | C96a | 455557-90 |
| EASA.210.10040840 | 30/07/2012 | GE16386 Anti-Collision/Recognition Light | GE 16386-(XX)-(XX) | C96a | DDP-GE16386 |

| GOODRICH LIGHTING SYSTEMS GmbH - BERTRAMSTRASSE 8 59557 LIPPSTADT GERMANY | | | | | |
|--|--------------------|--------------------|-----------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.10041323 | 07/09/2012 | GE16720 Light Assy | GE16720-()-() | C30c C96a | GE16720 |

| GOODYEAR (THAILAND) PCL - 50/9 PHAHOLYOTHIN ROAD KM. 36 12120 KLONG LUANG, PATUM THANI THAILAND | | | | | |
|--|--------------------|---|---------------|------------------|-----------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.21O.816 | 10/11/2008 | Aircraft tire H40X14.5-19 26 PR 225 MPH | 419K62T2 | C62d | GYTH- DDP-2008-001 |

| G.P.I. - ZA LA BOHALLE 49800 LA BOHALLE FRANCE | | | | | |
|---|--------------------|---|---|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.041 | 19/05/2004 | 2M2N Cargo Net | 2M2N-N2-(XXX)-(XX) | C90c | 2M2N-04-000 |
| EASA.21O.426 | 21/11/2005 | Polyester Cargo Net 2M1N, 96x125x96 | 2M1N-E1-(XXX)-(XX) | C90c | DDP/05/030 |
| EASA.21O.1045 | 16/09/2008 | 2M2N and 2A1N Cargo net | 2M2N-D1-(XXX)-(XX) 2M2N-D3(XXX)-(XX) | C90c | 07/002 |
| EASA.21O.1234 | 19/06/2009 | 1B6N Cargo net 88x108" | 1B6N-N3-(XXX)-(XX) | C90c | DDP-05-002 |
| EASA.21O.225, REV. A | 10/09/2008 | Cargo Net 2M2N / 2A1N | 2M2N-B2-(XXX)-(XX) 2M2N-B3-(XXX)-(XX) | C90c | 2M2N-04-019 |
| EASA.21O.10053888 | 01/07/2015 | TIE DOWN STRAP - 10000 lbs // C172 Ratchet Tie Down Strap - | SHTAALD (XXX)(YY)-(ZZ) SHTUALD (XXX)(YY)-(ZZ) SHTUULD(XXX)(YY)-(ZZ) SHTUYLD (XXX)(YY)-(ZZ) SHTYALD (XXX)(YY)-(ZZ) SHTYYLD (XXX)(YY)-(ZZ) | C172 | DDP/14-001 |
| EASA.21O.10053889 | 01/07/2015 | TIE DOWN STRAP - 1600 lbs // C172 Ratchet Tie Down Strap - 1 | SLTSSLE (XXX)(YY)-(ZZ) SLTVSLE (XXX)(YY)-(ZZ) SLTVVLE(XXX)(YY)-(ZZ) | C172 | DDP/15-006 |
| EASA.21O.10054710 | 10/09/2015 | Tie-Down Strap - 5000 Lbs | STCOA2(XXX)(YY)-(ZZ) STCCA1(XXX)(YY)-(ZZ) STEEA1(XXX)(YY)-(ZZ) STPCA1(XXX)(YY)-(ZZ) STPPA1(XXX)(YY)-(ZZ) | C172 | DDP/13-004 |
| F.O.080 | 08/07/2002 | Cargo Net | 2M2N-118-N1-(XX) | | |
| F.O.085 | 27/08/2002 | Cargo Net | 2K3N-064-B1-(XX) | | 2K3N-02-200 |
| F.O.087 | 29/08/2002 | Cargo Net | 2L3N-064-B1-(XX) | | 2L3N-02-200 |
| F.O.088 | 29/08/2002 | Cargo Net | 2M2N-118-B1-(XX) | | 2M2N-02-200 |
| F.O.094 | 02/12/2002 | Cargo Net | 2G1N-096-R1-(XX) 2G1N-096-R2-(XX) | | 2G1N-02-100 |

| GREINER AEROSPACE GmbH - ERWIN-GREINER STRASSE 5 4690 SCHWANENSTADT AUSTRIA | | | | | |
|--|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.1007, REV. B | 13/10/2008 | Seat Bottom Cushions, Model Number T2SI3021 | EXCL T2SI3021-001-00-()-()-() EXCL T2SI3021-002-00-()-()-() EXCL T2SI3021-003-00-()-()-() T2SI3021-001-()-()-()-() T2SI3021-002-()-()-()-() T2SI3021-003-()-()-()-() | C72c | DDP-T2SI3021 |

| HAMILTON SUNDSTRAND CORPORATION - ONE HAMILTON ROAD 06096 WINDSOR LOCKS USA | | | | | |
|--|--------------------|--------------------|---------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| 6608 | 26/09/1994 | # | | | |
| 6616 | 18/11/1998 | T-20G-10C() | | | |
| LBA.N-O.6601 JTSO | 07/10/1997 | # | | | |
| LBA.N-O.6618 JTSO | 14/09/1999 | APU APS2100 series | | | |
| LBA.N-O.6621 JTSO | 02/04/2003 | APU T-62T-40C11 | 4501966 | | |

| HANSEN PROTECTION A/S - TYKKEMYR 27 1597 MOSS NORWAY | | | | | |
|---|--------------------|---|----------------------------|------------------|--------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.840, REV. A | 02/05/2013 | Helicopter Crew and Passenger Integrated Immersion Suit, Sea | SEAAIR 1 ()-() | 2C502 | HELLY HANSEN SEAAIR 1 |
| EASA.21O.10044737 | 02/05/2013 | HP ETSO Suit | HP ETSO SUIT () () | 2C503 | SD-2-40-003A |
| EASA.21O.10045199 | 06/06/2013 | HP ETSO Lifejacket | HP ETSO LIFEJACKET () () | 2C504 | SD-2-40-000 |
| EASA.21O.10049814 | 10/07/2014 | SeaWind ETSO Suit | SEAWIND ETSO SUIT () () | 2C503 | SD-2-40-006 |

| HEARTSINE TECHNOLOGIES LIMITED - 203 AIRPORT ROAD WEST BT3 9ED BELFAST UNITED KINGDOM | | | | | |
|--|--------------------|--------------------|---------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.10042190 | 14/11/2012 | PAD-PAK-07 Battery | PAD-PAK-07() | C142a | H017-016-204 |

| HEINRICH MERTENS - AM ROTEN BERGE 8 58762 ALTENA GERMANY | | | | | |
|---|--------------------|---------------------------------|---------------------------------|------------------------------------|---------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.659 | 28/02/2007 | 10-34/24 S Emergency Parachute | 10-34/24 S-I 10-34/24 S-II | LBA BRP ISSUE 2.1953 Other | LBA TCDS NO. 40.010/04 |
| EASA.21O.660 | 28/02/2007 | 10-66/24 WF Emergency Parachute | 10-66/24 WF I 10-66/24 WF II | LBA BRE ISSUE MAI 1962 Other | LBA TCDS NO. 40.010/66 |
| LBA.40.010/96 | 19/10/1999 | Emergency Parachute 12-82/23 | 12-82/23 R | | |

| HOFFMANN AIR CARGO EQUIPMENT GMBH - PFINGSWEIDE 27-31 61169 FRIEDBERG GERMANY | | | | | |
|--|--------------------|----------------------------|---------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.281 | 01/07/2005 | Air Cargo Net, Type HTRO 7 | HTRO 7 () | C90c | HTRO 7 |
| EASA.21O.299 | 01/07/2005 | Air Cargo Net, Type HTRO 9 | HTRO 9 () | C90c | HTRO 9 |

HOFFMANN AIR CARGO EQUIPMENT GMBH - PFINGSWEIDE 27-31 61169 FRIEDBERG GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-----------------------------------|---------------|------------------|---------------|
| EASA.210.336 | 09/09/2005 | Air Cargo Net, Type HTR0 8 | HTR0 8 () | C90c | HTR0 8 |
| LBA.O.11.401/24 JTSO | 16/05/2000 | Air Cargo Net, Type HTR0 1 | HTR0 1 () | | HTR0 1 |
| LBA.O.11.401/68 JTSO | 19/05/2000 | Air Cargo Net, Type HTR0 2 | HTR0 2 () | | HTR0 2 |
| LBA.O.11.401/69 JTSO | 26/06/2000 | Cargo Pallet Net Type: HTR0 3 () | HTR0 3 () | | HTR0 3 |
| LBA.O.11.401/70 JTSO | 02/08/2000 | Cargo Pallet Net Type: HTR0 4 () | HTR0 4 () | | HTR0 4 |
| LBA.O.11.401/71 JTSO | 02/08/2000 | Cargo Pallet Net Type: HTR0 5 () | HTR0 5 () | | HTR0 5 |
| LBA.O.11.401/78 JTSO | 12/09/2000 | Air Cargo Net, Type HTR0 6 | HTR0 6 () | | HTR0 6 |

HOLMBERG GmbH & Co. KG - OHLAUER STRASSE 5-11 10999 BERLIN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|---|--|------------------|----------------------------|
| EASA.210.1280 | 20/01/2011 | N40A Handset with Support Bracket | N40-1(XXX)1(XX)-(XX)1 N40-1(XXX)2(XX)-(XX)2 | C57a C58a | HO-P6084- DDP-0000-EASA |
| LBA.O.10.919/018 JTSO | 18/10/2000 | Headphones Series 95-23-XXXXX-13 | 95-23-XXXXX-13 | | 9523-13 |
| LBA.O.10.919/023 JTSO | 04/03/2003 | Handset 89-01-17XXXX with Support Bracket | 89-01-17XXXX 98-01-079XXXX | C57a C58a | 89-01 |
| LBA.O.10.919/025 JTSO | 18/10/2002 | Handset Hörer 89-01-(X)-18 | 89-01-(XXXXX)-18 98-01-(XXXXX)-18 | | 89-01-X-18 |
| LBA.O.10.919/026 | 23/10/2002 | Handset 89-01-(X)-16 support Bracket | 89-01-(XXXXX)-16 98-01-(XXXXX)-17 | | 89-01-16 |
| LBA.O.10.919/10 JTSO | 09/05/2000 | Headset Series 91 | 91-23-XXXXX-07 | | 9123-07 |
| LBA.O.10.919/11 JTSO | 02/08/2000 | Headsets Series 90-06-XXXXX-08 | 90-06-XXXXX-08 | | 9006-08 |
| LBA.O.10.919/13 JTSO | 02/08/2000 | Microphone Series 85-13-XXXXX-01 | 85-13-XXXXX-01 | | 8513-01 |
| LBA.O.10.919/14 JTSO | 02/08/2000 | Microphone Series 85-03-XXXXX-04 | 85-03-XXXXX-04 | | 8503-04 |
| LBA.O.10.919/15 JTSO | 02/08/2000 | Microphone Series 85-13-XXXXX-03 | 85-13-XXXXX-03 | | 8513-03 |
| LBA.O.10.919/16 JTSO | 02/08/2000 | Microphone Series 85-13-XXXXX-02 | 85-13-XXXXX-02 | | 57PT2103F6 |
| LBA.O.10.919/21 JTSO | 20/12/2000 | Headsets Series 91-06-X-19 | 91-06-(X)-19 | | 9106-19 |
| LBA.O.10.919/22 JTSO | 20/12/2000 | Headphone Series 95-06-X-06 | 95-06-(X)-06 | | 9506-06 |
| LBA.O.10.919/4 JTSO | 02/08/2000 | Headsets Series 1046GT2102 | 1046GT2102XX | | 1046-01 |
| LBA.O.10.919/5 JTSO | 02/08/2000 | Telephone Handset Series 89-01-27XX | 89-01-07(XXX) 98-01-079XX) | C57a C58a | 89-01 |
| LBA.O.10.919/6 JTSO | 02/08/2000 | Telephone Handset Series 750T | 750T2112-X 750TXX | | 750-01 |
| LBA.O.10.919/7 JTSO | 02/08/2000 | Microphone Series 85-16-XXXXX-05 | 85-16-XXXXX-05 | | 85-16-08836 |

HONEYWELL INTERNATIONAL, Inc. - 115 TABOR ROAD 07950 MORRIS PLAINS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|-------------------------------|
| EASA.210.005 | 26/05/2004 | DM-855 DME LRM for use in MRC-855A Modular Radio Cabinet | 7510184-855 | 2C66b | DM-855-DDP |
| EASA.210.006 | 26/05/2004 | XS-857A Diversity Mode S Transponder LRM for use in MRC-855A | 7517400-() | 2C112a | XS-857-DDP |
| EASA.210.009 | 26/05/2004 | NV-875A VOR/ILS NAV LRM for use in MRC-855A Modular Radio Ca | 7026202-8XX | 2C34f 2C35d 2C36f 2C40c | NV-875 |
| EASA.210.010 | 26/05/2004 | TR-865A VHF COM Transceiver LRM for use in MRC-855A Modular | 7026201-() | 2C37e 2C38e | TR-865 |
| EASA.210.011 | 26/05/2004 | DF-855 ADF Receiver for use in MRC-855A Modular Radio Cabine | 7510114-855 | 2C41d | DF-855 |
| EASA.210.012 | 26/05/2004 | Primus II RCZ-8XX() - Integrated Communications Unit which | 7510700-() | 2C37e 2C38e 2C112a | RCZ-8XX |
| EASA.210.063 | 21/06/2004 | KT73 Transponder | 050-03451-0000 066-01164-0101 | 2C112a | #230, (DOC 004-02148-6300) |
| EASA.210.151 | 18/08/2004 | HG 2111AB | HG2111AB() | C3d C4c C5e C6d | 26020224 |
| EASA.210.178 | 19/10/2004 | Cockpit Area Microphone | 980-6113-() | C123a | 071-5006 |
| EASA.210.179 | 22/10/2004 | 980-6124-() - DVDR Cockpit Control Panel | 980-6124-002 | C123a | 071-5005 |
| EASA.210.200 | 01/12/2004 | RMA - 55B Multi-Mode Receiver | 066-50029-1201 | 2C34f 2C36f C129a | 998-3390-805 |
| EASA.210.238 | 26/01/2005 | Electronic Radar Display ROD-1 | 80-5214-()-() | 2C63c C110a C113 | E3-881 |
| EASA.210.239 | 26/01/2005 | EGPWS MK V | 965-0976-003-(XXX)-(XXX) 965-0976-020-(XXX)-(XXX) 965-0976-040-(XXX)-(XXX) 965-0976-060-(XXX)-(XXX) 965-1676-(XXX)-(XXX) 965-1690-(XXX)-(XXX) | C92c C117a C129a C151a | SEE P/N DESCRIPTION |
| EASA.210.253 | 04/03/2005 | APU RE100[CS] Category I - Essential | 2119552-3 3800785-1 | JAR-APU CHANGE 2+ORANGE PAPE 1 Other | 31-13095A-03 |
| EASA.210.257 | 15/03/2005 | APU 36-150[IA] Category I - Essential | 2118988-1 2118988-2 3800710-1 | JAR-APU CHANGE 2+ORANGE PAPE 2 Other | 31-4404E-21 |

HONEYWELL INTERNATIONAL, Inc. - 115 TABOR ROAD 07950 MORRIS PLAINS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|-----------------------------|
| EASA.210.274 | 27/04/2005 | TR-865B - VHF COM LRM for use in MRC-855A Modular Radio Cabi | 7026201-() | 2C37e 2C38e | TR-865B-DDP |
| EASA.210.275 | 27/04/2005 | TR-866B - VHF COM Transceiver LRM for use in MRC-855A Modula | 7026201-() | 2C37e 2C38e | TR-866B-DDP |
| EASA.210.277 | 27/04/2005 | KMD 550/850 Multi Function Display System | 066-04035-0101 066-04035-0201 066-04035-0301 066-04035-1101 066-04035-1201 066-04035-1301 071-00158-0211 071-00159-0111 071-00161-0101 071-00161-0102 071-00161-0103 071-00166-0411 071-00168-0311 | 2C63c C110a C113 C151a | 229 |
| EASA.210.310 | 14/07/2005 | MFRD-1 | 80-5204-()-() | 2C63c C110a C113 C118 C119b | E3-733 |
| EASA.210.422 | 11/11/2005 | MK VII Enhanced Ground Proximity Warning System (EGPWS) | 965-1076-001-XXX-XXX 965-1076-020-XXX-XXX 965-1076-030-XXX-XXX 965-1076-040-XXX-XXX | C92c C117a C151a | 071-5017-000 |
| EASA.IM.210.271 | 28/09/2005 | KMH 820 (Traffic Advisory System - TAS), KCM 805 (Traffic Ad | 066-01175-0102 066-01175-2102 071-00112-0200 | C147 C151a | 231 |
| EASA.IM.210.326 | 02/09/2005 | MKXXI EGPWS (GPS) 965-1227 Series | 965-1227-003 965-1227-005 | C151a | 089 |
| EASA.IM.210.327 | 02/09/2005 | MKXXII EGPWS (GPS) 965-1590 Series | 965-1590-006 965-1590-008 965-1590-010 965-1590-011 | C151a | 090 |
| EASA.IM.210.328 | 02/09/2005 | MKXXII EGPWS (GPS) 965-1595 Series | 965-1595-020 965-1595-021 965-1595-022 965-1595-024 | C151a | 097 |
| EASA.IM.210.343 | 14/09/2005 | TPA-100A TCAS | 940-0300-001 | C113 | 071-0074-001 |
| EASA.IM.210.450 | 16/01/2006 | NC-860A NAV/COM LRM | 7026203-() | 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c | NC-860A-DDP |
| EASA.IM.210.457 | 18/01/2006 | TR-866A VHF COM Transceiver LRM for use in MRC-855A Modular | 7026201-XXX | 2C37e 2C38e | TR-866B-DDP |
| EASA.IM.210.639 | 13/04/2007 | Rescu 406S ELT | 1151324-() 1152794-() 1152890-() 1152892-() 1153046-() | TSO C91A TSO C126 Other | 06E0603 APPENDIX B |
| EASA.IM.210.706 | 13/04/2007 | RESCU 406AF ELT | 1152682-() 1152684-() 1152778-() 1152780-() 1153006-() 1153008-() 1153236-() | 2C91a 2C126 | 06E0602 ANNEX B |
| EASA.IM.210.712 | 21/05/2007 | KMG 7010 Magnetometer | 050-03643-0000 050-03643-0001 065-00189-0101 065-00189-1101 | C6d | 004-02307-6300 - DDP#291 |
| EASA.IM.210.719 | 25/06/2007 | VOR/ILS/Datalink with GPS VIDL-G: NV-877A | 7026207-() | 2C34f 2C35d 2C36f 2C40c C129a | NV-877A |
| EASA.IM.210.817 | 26/02/2008 | KXP 2290 Mode S Transponder | 047-12880-0006 (MOUNTING RACK) 050-03683-0000 (INSTALLATION K 066-01198-0101 (TRANSPONDER) | 2C112b | 289 P/N 004-02279-6300 |
| EASA.IM.210.907 | 12/02/2008 | KGS 200 Mercury GNSSU and Installation Kit | 050-03712-0000 INSTALLATION KI 066-01201-0101 GLOBAL NAVIGATI | C129a | 293 (004-01201-6300) |
| EASA.IM.210.956 | 02/04/2008 | GNS-XLS with PCMCIA Worldwide Database Card | 071-00248-0000 DATABASE CARD 17960-01 CONFIGURATION MODUL 17960-0101-() 17960-0102-() 17960-0103-0() 17960-0203-() 17960-0204-0() GNS-XLS | TSO C115B TSO C129 Other | #209 P/N 004-02068-6300 |

HONEYWELL INTERNATIONAL, Inc. - 115 TABOR ROAD 07950 MORRIS PLAINS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|---|---|---------------------------------|
| 6600 | 08/07/2000 | 36-300[] series | | | |
| 6603 | 03/08/1995 | 331-200[] series | | | |
| 6604 | 20/10/1995 | 36-100 [] series | | | |
| 6605 | 23/04/2003 | 36-150 GIV | | | |
| 6606 | 22/07/2003 | 331-350 [] series | | | |
| 6609 | 05/12/1991 | 700-4 [] series | | | |
| 6610 | 02/08/1994 | 331-500 [] series | | | |
| 6611 | 28/05/1998 | 131-9 [] series | | | |
| 6614 | 03/03/1995 | 85-98 [] series | | | |
| 6615 | 26/03/1997 | RE220 [] series | | | |
| EASA.21O.036, REV. A | 26/05/2004 | Multi Function Display System - KMD 250 | 050-03656-0000 066-04036-0101 066-04036-0201 071-00201-0101 071-00201-0102 071-00201-0103 | C113 | 295 |
| EASA.21O.120, REV. A | 18/08/2004 | RTA-4B Weather Radar Transceiver | 066-50008-0409 | 2C63c | 071-5007-000 |
| EASA.21O.165, REV. A | 17/12/2004 | Digital Voice Data Recorder | 980-6025(-) | C123a C124a | 071-5007 |
| EASA.IM.21O.013, REV. B | 02/09/2010 | KRA-405B Radar Altimeter | 066-01153-0101 066-01153-0202 066-01153-2001 066-01153-4001 066-01153-5001 | 2C87 | 215 |
| EASA.IM.21O.1063 | 01/09/2008 | Multi-Mode Digital Radio / KTR 2280 | 050-03721-0000 MMDR INSTALL KI 069-01037-0102 MMDR | 2C34f 2C36f 2C37e 2C38e 2C40c 2C41d 2C128 | #292 DOC. NO. 004-02365-6300 |
| EASA.IM.21O.1118 | 12/11/2008 | Laseref V, Inertial Reference Unit and Mounting Tray | HG2100AC() IRU WG2001AB() MOUNTING TRAY WITH NH2171D() OPERATIONAL PR | C3d C4c C5e C6d C129a | 26022294 |
| EASA.IM.21O.1119 | 12/11/2008 | Super AHRS, Attitude Heading Reference Unit | HG2111AC() WITH SW PART NUMBE | C3d C4c C5e C6d C129a | 26022295 |
| EASA.IM.21O.1147 | 12/01/2009 | RESCU 406SE Emergency Locator Transmitter (ELT) | 1153426(-) 1153472(-) 1153532(-) 1153534(-) 1153536(-) 1153538(-) | 2C91a 2C126 | 08C0575 APPENDIX B |
| EASA.IM.21O.116, REV. B | 31/03/2008 | KHF 1050 High Frequency Radio System | 064-01072-0101 064-01073-0101 064-01073-0102 064-01073-5101 064-01074-0101 | C31d C32d | 235 P/N 004-02071-630 |
| EASA.IM.21O.1235 | 03/08/2009 | Air Data Module (ADM) HG1152DA | HG1152DA() | C106 | C72-3438-115 |
| EASA.IM.21O.150, REV. A | 01/08/2008 | MST-67A Mode S Transponder | 047-09406-0010 MOUNTING RACK 050-02979-0000 INSTAL. KIT 066-01143-2001 SOFTWARE ID 0X 066-01143-2101 SOFTWARE ID 0X | 2C112b | #182 |
| EASA.IM.21O.272, REV. A | 07/03/2013 | NV-875B VOR/ILS NAV LRM | 7026202-802 | 2C34f 2C35d 2C36f 2C40c | NV-875-DDP |
| EASA.IM.21O.352, REV. A | 06/12/2005 | KMH 920 and KCM 805 | 066-01178-0102 066-01178-2102 071-00112-0200 | C118 C151a | #233 |
| EASA.IM.21O.577, REV. A | 28/03/2007 | AR204C COMBI - Lightweight Combination Solid State CVR/FDR | 980-6021-066 980-6021-072 | C123a C124a | 071-5003 |
| EASA.IM.21O.616, REV. B | 13/09/2011 | ALA-52B Radio Altimeter | 066-50007-0() | 2C87 | 698-50046 |
| EASA.IM.21O.713, REV. A | 14/09/2015 | Air Data Heading Altitude Reference System KSG 7200 composed | 050-03652-0000 050-03652-0001 050-03652-0002 INSTALLATION KI 065-00188-0101 065-00188-1101 065-00188-5101 ADAHARS 071-00183-0000 071-00183-0001 RACK ASSEMBLY 071-00188-0101 071-00188-1101 CONFIG. MODULE | C3d C4c C6d C106 | 004-02308-6300 |
| EASA.IM.21O.724, REV. A | 27/04/2009 | RESCU 406AFN Emergency Locator Transmitter (ELT) | 1152682(-) 1153396(-) | 2C91a 2C126 | 07C0276 APPENDIX B |
| EASA.IM.21O.10028290 | 15/12/2009 | XS-858A Diversity Mode S Transponder with Enhanced Surveillance | 7517401(-) | 2C112b C166a | DP7517401 |

HONEYWELL INTERNATIONAL, Inc. - 115 TABOR ROAD 07950 MORRIS PLAINS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|---|--|-----------------------------------|--------------------------|
| EASA.IM.210.10031526 | 23/08/2010 | Attitude Heading Reference Unit (AHRU) | HG2112BB() | C3d C4c C5e C6d | 66000027 |
| EASA.IM.210.10033120 | 20/12/2010 | RVA-36B VHF and VOR/Marker Receiver | 066-50012-1() | 2C35d 2C40c | 071-5032-000 |
| EASA.IM.210.10033125 | 20/12/2010 | ALA-52B 066-50007-1 Low Range Radio Altimeter | 066-50007-1() | 2C87 | 940-2023-571 |
| EASA.IM.210.10034630 | 18/04/2011 | DFA-75B 066-50014-12 Airborne Automatic Direction Finder (AD) | 066-50014-12 () | 2C41d | 071-5030-000 |
| EASA.IM.210.10036251 | 25/08/2011 | DMA-37B 066-50013-12 Distance Measuring Equipment (DME) Rece | 066-50013-12() | 2C66b | 071-5031-000 |
| EASA.IM.210.10037129 | 04/11/2011 | DMA-37B 066-50013-0 Distance Measuring Equipment | 066-50013-0() | TSO-C66C Other | 69001674-001 |
| EASA.IM.210.10039582 | 14/05/2012 | HFR5-V Solid State Cockpit Voice Recorder (SSVCR) | 980-6032-() | C123b C177 | 69000817-001 |
| EASA.IM.210.10039583 | 14/05/2012 | HFR5-D Solid State Flight Data Recorder (SSFDR) | 980-4750-() | C124b | 69000648-001 |
| EASA.IM.210.10040698 | 20/07/2012 | RTA-50D VHF Digital Radio | 965-1696-() | 2C128 2C169A | 071-5057-001 |
| EASA.IM.210.10046345 | 11/09/2013 | Laseref VI Inertial Reference Unit (IRU) (HG2100BC) | HG2100BC() LASEREF IV INERTIAL REFERENCE UNIT (IRU) MAGNETIC VARIATION TABLE NH2217D() FIELD LOADABLE NH2219D() FIELD LOADABLE OPERATIONAL PROGRAM CONSTANTS OPERATIONAL PROGRAM SOFTWARE | C3d C4c C5e C6e C196a | 66020732 |
| EASA.IM.210.10046348 | 11/09/2013 | Super AHRS Attitude Heading Reference Unit (AHRU) | HG2111BC() ATTITUDE HEADING MAGNETIC VARIATION TABLE NH2217D() FIELD LOADABLE NH2219D() FIELD LOADABLE OPERATIONAL PROGRAM CONSTANTS OPERATIONAL PROGRAM SOFTWARE REFERENCE UNIT (AHRU) | C3d C4c C5e C6e C196a | 66020733 |
| EASA.IM.210.10047809 | 23/01/2014 | KXP 2290A Transponder | 066-01198-0102 | C112d C166b | 296 PN 004-02279-6301 |
| EASA.IM.210.10050107 | 04/08/2014 | HGT1700[] AND HGT1700[A] Auxiliary Power Unit | 70720975-00 AND 70720041-00 | CS-APU Other | HON. 0518:071814:ETSO |
| EASA.IM.210.10050750 | 08/10/2014 | TPU-67B TCAS II, Change 7.1 | 066-01146-2121 066-01146-2221 | C119c | 004-02414-6300 |
| EASA.IM.210.10050887 | 22/10/2014 | RVA-36C VOR/Marker Beacon Receiver | 69001410-() | 2C35d 2C40c | DDP69001410-001 |
| EASA.IM.210.10051780 | 23/12/2014 | Laseref VI Inertial Reference Unit (IRU) (HG2100BB) | 02, 03 HG2100BB() EXCLUDING 00, 01 | C3d C4c C5e C6d C196a | 66020904 |
| EASA.IM.210.10051975 | 23/01/2015 | VDR RTA-44D | 064-50000-2000 064-50000-2051 064-50000-2052 | 2C37e 2C38e | 998-2858-805 |
| EASA.IM.210.10052390 | 23/02/2015 | RDR-4000 Weather Radar System | (3 MCU) RP-1() ANTENNA DRIVE DA-1() FLAT PLATE ANTENNA ARRAY FP()-1 MOUNTING TRAY (FOR RADAR P/N: 930-1[XXX-XXX] P/N: 930-2[XXX-XXX] P/N: 930-3[XXX-XXX] P/N: 930-4[XXX-XXX] P/N: 930-7[XXX-XXX] PROCESSOR) MT-() RADAR PROCESSOR UNIT TRANSMITTER-RECEIVER UNIT TR-1() | 2C63c | 993-4020-801 |
| EASA.IM.210.01080 | 22/02/1973 | 660-4 [] series | | | |
| EASA.IM.210.01082 | 19/10/1972 | 700-5 [] series | | | |
| EASA.IM.210.01084 | 22/06/1966 | 30-92 series | | | |
| EASA.IM.210.01085 | 27/04/1971 | 36-4 series | | | |
| EASA.IM.210.01086 | 26/03/1971 | 36-6 series | | | |
| EASA.IM.210.01088 | 03/09/2008 | 85-37 [] series | | | |
| EASA.IM.210.01094 | 03/12/1963 | 85-115 [] series | | | |
| EASA.IM.210.01095 | 07/06/1984 | 85-129[] series | | | |
| EASA.IM.210.01096 | | 85-185[] series | | | |
| EASA.IM.210.01097 | | 36-280[] series | | | |
| EASA.IM.210.01100 | 31/01/1984 | 331-250[] series | | | |
| EASA.IM.210.10031524, REV. A | 11/09/2014 | HG2100BB Laseref VI Inertial Reference Unit (IRU) | HG2100BB02 HG2100BB03 | C3d C4c C5e C6d C129a | 66000026 |

| HONEYWELL INTERNATIONAL, Inc. - 115 TABOR ROAD 07950 MORRIS PLAINS USA | | | | | |
|---|--------------------|--|--|---|-----------------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10033117, REV. B | 27/08/2012 | KGS 200 WAAS Mercury GNSSU | 066-01201-0102 066-01201-0103 066-01201-0104 066-01201-0105 | C145 C146 | 294 (004-02377-6300) |
| EASA.IM.210.10033126, REV. A | 22/09/2014 | DFA-75B 066-50014-11 & DFA-75B 066-50014-13 Airborne Automat | 066-50014-11 () 066-50014-13 () | 2C41d | 940-2024-571 |
| EASA.IM.210.10033128, REV. A | 17/01/2014 | INR Integrated Navigation Receiver | 940-2001-() | 2C34f 2C35d 2C36f 2C40c C129a C161 | DDP69000613 |
| EASA.IM.210.10033216, REV. A | 22/09/2014 | DMA-37B 066-50013-11 & DMA-37B 066-50013-13 Distance Measuri | 066-50013-11() 066-50013-13() | 2C66b | 940-2022-571 |
| EASA.IM.210.10036227, REV. A | 22/10/2014 | TPA-100B Traffic Alert and Collision Avoidance System (TCAS) | 940-0331-() 940-0351-() 940-0431-() 940-0451-() 940-1431-() | C119c | 994-6043-200 |
| EASA.IM.210.10039659, REV. A | 23/05/2012 | AH-1000 Attitude Heading Reference Unit (AHRU) | HG2205AB() AHRU WG2005AB() TRAY | C3d C4c C5e C6e | 66020312 |
| EASA.IM.210.10041599, REV. A | 06/12/2012 | XS-858B Mode S Transponder | 7517402-() | C112c C166b | DP7517402 |
| F.N-O.077 | 27/03/2002 | 331-600[A] | 3800610-1 3888394-240401 | | 31-15857-01A |
| LBA.6617 JTSO | 14/04/2000 | RE100[] | | | |
| LBA.6619 JTSO | 21/07/2000 | 331-400[] series | | | |
| LBA.N-O.10.480/011 JTSO | 26/09/2002 | HG2100 | HG2100AB() WG2001AA() | | 26019747 |
| LBA.N-O.10.911/105 JTSO | 13/02/2001 | VHF Data Radio RTA-44D | 064-5000-0505 | | 2072799 |
| LBA.N-O.10.911/116JTSO | 21/05/2003 | RTA-44D | 064-50000-2000, -2051 | | 998-2858-805 FOR -2000,998-288 |
| LBA.N-O.10.916/23 JTSO | 24/11/2000 | GPS Navigations System KLN 94 | 050-3321-0000 069-01034-() 071-00163-() | | 227 |
| LBA.N-O.10.930/070JTSO | 04/07/2003 | TRA-67A | 066-01127-1402 066-01127-1502 066-01127-1602 | | 176 |
| LBA.N-O.10.940/009 JTSO | 26/09/2002 | KTA910 | 066-01177-0101 | | #233 |
| LBA.N-O.10.985/010 JTSO | 20/09/2002 | KMH920 Multi-Hazard Awareness Processor | 066-01178-0101 066-01178-2101 071-00167-0101, -0102, -0103 | | #233 |
| LBA.N-O.10.985/015JTSO | 19/05/2003 | KI-825 | 80-5205-()-() | | E3-754 |
| LBA.N-O.10.985/02 JTSO | 02/08/2000 | COM/NAV Transceiver KX165A | 069-01033-0101() 069-01033-0201() | | 288 |

| HONEYWELL UK LTD (SKYFORCE) - ARLINGTON BUSINESS PARK RG12 1EB BRACKNELL UNITED KINGDOM | | | | | |
|--|--------------------|--------------------------------|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.161 | 20/09/2004 | KMD 150 Multi Function Display | 050-03318-0000 CM2013 CM3000-001 CM3000-002 CM3001-002 CM3002-001 CM3003-001 CM3003-002 CM3100 CM3XXX | C113 | TRSY066_02 |
| EASA.210.423 | 15/11/2005 | Observer Mk III | OB1108-005 OB1302-003 OB1303-001 OB1303-002 OB1303-003 OB1305-001 OB2101-003 OB2106-001 OB2106-002 OB2109-002 OB2111-XXX OB2222-XXX OB2312-001 | C113 | 11302-11847 |

| HONEYWELL UK LTD (SKYFORCE) - ARLINGTON BUSINESS PARK RG12 1EB BRACKNELL UNITED KINGDOM | | | | | |
|--|--------------------|--|--|------------------|------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.937 | 17/01/2008 | OB3000 Sky Sentinel Integrated electronic moving map & missi | OB3001-001 OB3001-002 OB3001-003 OB3001-004 OB3001-009 OB3100-001 OB3100-002 OB3111-(XXX) OB3222-(XXX) | C113 | 11302-12280 |
| EASA.210.203, REV. A | 09/11/2005 | Skymap IIIC (SM4000) | CM2XXX SC2XXX SM2100 SM2105 SM2106 SM2200 SM 2202 SM2204 SM2207 SM4001 | C113 | TR/SKY/068 |
| EASA.210.10032506 | 12/11/2010 | OB3000 SENTINEL with OB3300 display (Integrated electronic m | OB3001-011 OB3100-003 OB3301-XXX OB3302-XXX | C113 | 11302-12280 |
| EASA.210.10040090, REV. A | 14/04/2014 | Observer / OB2000 | OB1108-005, OB1302-003 OB1303-001, OB1303-002 OB1303-003, OB1305-001 OB1305-002, OB2101-003 OB2101-004, OB2106-001 OB2106-002, OB2106-003 OB2109-002, OB2109-004 OB2112-007, OB2111-[] OB2211-[], OB2312-001 OB2320-[], OB2222-[] OB2400-[], OB2500-[] OB2501-001, OB2600-[] OB2700-[] | C113 | 11302-11847, 14A |

| HOOVER INDUSTRIES, Inc. - 7260 N.W. 68TH STREET 33166-2014 MIAMI USA | | | | | |
|---|--------------------|-----------------------|----------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.663 | 11/05/2007 | Flotation vest FV-35F | 3505-() () () () | C13f | DDP-FV-35F |

| HR SMITH (TECHNICAL DEVELOPMENTS) L - KINGSLAND HR6 9QA LEOMINSTER UNITED KINGDOM | | | | | |
|--|--------------------|--|---|-----------------------------------|--------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.790 | 24/07/2007 | 10-264-35 Series GPS Antenna | 10-264-35 | C144 | 10-264-35 |
| EASA.210.1160 | 12/11/2008 | ELT 500/503 Series | 500-1 500-12 500-12Y 500-16 500-16Y 500-2-1 500-2-2 500-22 500-2-3 500-4 503-1 503-17 503-19-() 503-20-() 503-25-() 503-35-() 503-36-() 503-39() 503-4 503-7 | JTSO-2C91A JTSO-2C126 Other | DDP 500/503 SERIES |
| EASA.210.1198 | 26/10/2009 | 10-118-28 Series Multi Band ELT Antenna | 10-118-28() | 2C91a 2C126 | DDP 10-118-28() |
| CAA.O.00005 | 10/12/2002 | Crash Position Indicator System - 15-503-134 | 15-503-134-1 SERIES 15-503-134 SERIES | JTSO-2C91A JTSO-2C126 Other | 15-503-134 |
| CAA.O.00008 | 27/09/2003 | 500-27 () | 500-27() | | 500-27 |

| IACOBUCCI HF AEROSPACE S.p.A. - STRADA SC ASI 1/S NN 16-18 03013 FERENTINO ITALY | | | | | |
|---|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10045669 | 11/07/2013 | Single VIP Seat Type - HFST02 (Fwd) and HFST03 (Aft) | HFST02() () () () () HFST03() () () () () | C127a | 016-2012 |
| EASA.210.10048744 | 04/04/2014 | Single/Double BBJ VIP Seat - HFST11 | HFST08() () () () () | C127a | DDP022-2013 |
| EASA.210.10049335 | 02/06/2014 | Double BBJ VIP Seat - HFST09 (Aft) | HFST09() () () () () | C127a | DDP023-2013 |
| EASA.210.10049336 | 02/06/2014 | Single/Double BBJ VIP Seat - HFST11 | HFST11() () () () () | C127a | DDP024-2013 |
| EASA.210.10050421 | 09/09/2014 | Full Size Meal Cart - MKTF01 | MKTF01() () () () () | C175 | 011-2011 |
| EASA.210.10050422 | 09/09/2014 | Half Size Meal Cart - MKTH02 | MKTH02() () () () () | C175 | DDP012-2011 |

| IACOBUCCI HF AEROSPACE S.p.A. - STRADA SC ASI 1/S NN 16-18 03013 FERENTINO ITALY | | | | | |
|---|--------------------|--|--|--------------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10051660 | 16/12/2014 | Single FWD VIP Seat CS23 - HFST12 | HFST12(0)(0)-(0)(0)(0) | C39c | DDP004-2014 |
| EASA.210.10051661 | 16/12/2014 | Single Rearward VIP Seat C23 - HFST13 | HFST13() () () () () () | C39c | DDP005-2014 |
| EASA.210.10051662 | 16/12/2014 | SNG/DBL Sideward VIP Seat CS23 - HFST 14 | HFST14() () () () () () | C39c | DDP006-2014 |
| EASA.210.10052175 | 06/02/2015 | Business Class FWD FC VIP Seat - HFST10 | HFST10(0)(0)-(0)(0)(0) | C39c | DDP008-2014 |
| EASA.210.10052820 | 31/03/2015 | Full Size Atlas Meal Trolley - MKTF06 | MKTF06() () () () () () | C175 | DDP009-2014 |
| INDUSTRIAL NEOTEX S.A. - C/ FORJADORES S/N, PARC.17/11 28660 BOADILLA DEL MONTE (MADRID) SPAIN | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10049725 | 02/07/2014 | NT04AXX-SERIES Atlas half-size trolley | NT04A(CC)-(XX)(FF)-(ZZ) | C175 | DDP-0501 |
| EASA.210.10041948, REV. A | 31/10/2012 | NT01AXX-Series Trolley | NT01A(CC)-(XX)(FF)-(ZZ) | C175 | 0401 |
| INNOVINT AIRCRAFT INTERIOR GMBH - HOLZMUEHLENSTRASSE 84-86 22041 HAMBURG GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| TS 30.130/3TS | 06/05/1998 | Baby Bassinet | 7250(-) 7253(-) ATTACH PARTS 1600(-) | Other TS 30.130/3TS | |
| TS 30.130/4 NTS | 26/02/2003 | Child Restraint System | 2500(-) | Other TS 30.130/4 NTS | 25059-02 |
| TS 30.130/5TS | 10/12/1998 | VIP Seats and Divan Upholstery | 8010(-) 8020(-) 8030(-) 8040(-) | Other TS 30.130/5 TS | |
| TS 30.132/2TS | 12/04/1999 | Folding Table | 1251(-) | Other TS 30.132/2 TS | |
| TS 40.400/1TS | 02/04/1998 | On-board wheelchair | 2218(-) 2218-N(-) | Other TS 40.400/1 TS | |
| TS 40.400/2TS | 01/04/1998 | Medical Kit | 6240(-) 6240-(1)-(-) 6240-(2)-(-) 6240-(3)-(-) | Other TS 40.400/2 TS | |
| TS 40.400/4NTS | 31/07/2002 | Doghouse | 5240(-) | Other TS 40.400/4 NTS | |
| IPECO HOLDINGS Ltd. - AVIATION WAY SS2 6UN SOUTHEND ON SEA UNITED KINGDOM | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.204 | 24/11/2004 | 3B711-XXXX-XX - LH/RH Double Passenger Seat | 3B711-0501-XX 3B711-0502-XX 3B711-0503-XX 3B711-0504-XX | C127a | 156 |
| EASA.210.232 | 10/01/2005 | Pilot & Co-Pilot Crew Seat 0A318-0001 ()-0002() | 3A318-0007-()-() 3A318-0008-()-() | C127a | 150 |
| EASA.210.302 | 04/07/2005 | Model 3B710 - **** - LH/RH Double Passenger Seat & LH/RH Tri | 3B710-0503-(X) 3B710-0504-(X) 3B710-0505-(X) 3B710-0506-(X) 3B710-0509-(X) 3B710-0510-(X) 3B710-0511-(X) 3B710-0512-(X) 3B710-0513-(X) 3B710-0514-(X) 3B710-0515-(X) 3B710-0516-(X) 3B710-0517-(X) 3B710-0518-(X) 3B710-0519-(X) 3B710-0520-(X) 3B710-0521-(X) 3B710-0522-(X) 3B710-0523-(X) 3B710-0524-(X) | C39b | 155 |
| EASA.210.451 | 16/01/2006 | 0A254-0073-0074 Crew Seat | 3A254-0071-()-() 3A254-0072-()-() | C127a | 167 |
| EASA.210.542 | 31/07/2006 | 0B770-0501()/0B770-0502() LH&RH Forward Facing Single Attend | 3B770-0507-()-() 3B770-0508-()-() | C39b | 169 |
| EASA.210.630 | 29/10/2008 | 0B729-0501() STANCHION MOUNTED SEAT | 3B729-0507-()-() | C39b | 178 |
| EASA.210.637 | 21/03/2007 | 0A394-0001-0002 Executive Passenger Seat | 3A394-0007-()-() 3A394-0008-()-() 3A394-0009-()-() 3A394-0010-()-() | C39b | 173 |
| EASA.210.638 | 21/03/2007 | 0A407-0001-0002 Executive Passenger Seat | 3A407-0007-()-() 3A407-0008-()-() 3A407-0009-()-() 3A407-0010-()-() | C39b | 174 |

IPECO HOLDINGS Ltd. - AVIATION WAY SS2 6UN SOUTHEND ON SEA UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|---|--|------------------|---------------|
| EASA.210.714 | 21/06/2007 | 0A403-0001-0002 Executive Passenger seat | 3A403-0007-()-() 3A403-0008-()-() 3A403-0009-()-() 3A403-0010-()-() 3A403-0077-()-() 3A403-0078-()-() | C127a | 179 |
| EASA.210.813 | 27/09/2007 | 400-0001-0002 Side Facing Divan | 3A400-0061-()-() LH DIVAN - 3A400-0062-()-() RH DIVAN - 3A400-0063-()-() LH DIVAN - 3A400-0064-()-() RH DIVAN - 3A400-0065-()-() LH DIVAN - 3A400-0066-()-() RH DIVAN - | C39b | 180 |
| EASA.210.908 | 12/02/2008 | 409-0001 Jump Seat | 3A409-0007-()-() | C127a | 172 |
| EASA.210.941 | 07/07/2009 | 380-0001-0002 Pilot/Co-pilot seat | 3A-380-0007-()-2 3A-380-0008-()-2 | C127a | DDP 161 |
| EASA.210.095, REV. A | 09/02/2005 | Pilot and Co-Pilot Crew Seat | 3A254-0051-()-() 3A254-0052-()-() | C39b | 151 |
| EASA.210.1093 | 09/10/2008 | 185-0011-0012 Crew Seat | 3A185-0015-(XX)-(X) 3A185-0016-(XX)-(X) | C127a | 125 |
| EASA.210.1177 | 11/12/2008 | 0A258-0043/44 Pilot and Co-Pilot Crew Seats | 3A258-0041-()-() 3A258-0042-()-() | C127a | 133 |
| EASA.210.1187 | 21/04/2009 | 398-0001 Cabin Attendant Seat | 3A398-0007-(XX)-(X) | C127a | 168 |
| EASA.210.10029188 | 10/03/2010 | 382-0001 Observer Seat | 3A382-0007-()-() | C127a | 166 |
| EASA.210.10029189 | 10/03/2010 | 386-0001-0002 Crew Seat | 3A386-0007-()-() 3A386-0008-()-() | C127a | 165 |
| EASA.210.10032791 | 02/12/2010 | 424-0001-0002 Pilot Co-Pilot Seat | 3A424-0007-()-() 3A424-0008-()-() | C127a | 182 |
| EASA.210.10033923 | 21/02/2011 | 256-0001-0002 Pilot Co-Pilot Seat | 3A256-0007-()-() 3A256-0008-()-() | C39c | 126 |
| EASA.210.10036038 | 08/08/2011 | 413-0001 Operator and Observer Seat | 3A413-0007-()-() | C39c | 190 |
| EASA.210.10040594 | 12/07/2012 | 444-0001 First Observer Seat | 3A444-0007-()-() | C127a | 192 |
| EASA.210.10041198 | 29/08/2012 | 441-0001 Second Observer Seat | 3A441-0007-()-() | C127a | 191 |
| EASA.210.10046386 | 13/09/2013 | 449-0001-0002 Pilot / Co-Pilot Seat | 3A449-0007-()-() 3A449-0008-()-() | C127a | 195 |
| EASA.210.10046839 | 29/10/2013 | 453-0001/2/71/72 Executive Passenger Seat | 3A453-0007-()-() 3A453-0008-()-() 3A453-0009-()-() 3A453-0010-()-() 3A453-0045-()-() 3A453-0046-()-() 3A453-0047-()-() 3A453-0048-()-() 3A453-0049-()-() 3A453-0050-()-() 3A453-0055-()-() 3A453-0056-()-() 3A453-0059-()-() 3A453-0060-()-() 3A453-0061-()-() 3A453-0062-()-() 3A453-0063-()-() 3A453-0064-()-() 3A453-0065-()-() 3A453-0066-()-() 3A453-0067-()-() 3A453-0068-()-() 3A453-0077-()-() 3A453-0078-()-() | C127a | 193 |
| EASA.210.10048013 | 05/02/2014 | 188-0051-0052 / Pilot/ Co-Pilot Seat | 3A188-0047-()-() 3A188-0048-()-() | C39c | 203 |
| EASA.210.10048780 | 09/04/2014 | 458-0001 Operator Seat | 3A458-0007-()-() | C127a | 197 |
| EASA.210.1100, REV. A | 18/05/2011 | 275-0001 Observer Seat | 3A275-0007-(XX)-2 3A275-0007-(XX)-3 | C127a | 183 |
| EASA.210.1133, REV. A | 08/07/2009 | 383-0001 1st Observer Seat | 3A383-0007-()-() | C127a | 163 |
| EASA.210.1134, REV. A | 08/07/2009 | 384-0001 2nd Observer Seat | 3A384-0007-()-() | C127a | 164 |

ISOTH'AIR PRODUCTION - ZI LES AIGUILLONS - CHEMIN DU BERGE 30230 BOUILLARGUES FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|--|------------------|---------------------|
| EASA.210.113 | 16/06/2004 | Isotherm Container Type RKE, RKN, RKG, RMP, RAP | RAP OA-() RKE OA-() RKG OA-() RKN OA-() RMP OA-() | C90c | SEE P/N DESCRIPTION |

KELLY MANUFACTURING COMPANY - 555 S TOPEKA 67214 WICHITA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|----------------------|------------------|-----------------|
| EASA.IM.210.10040839 | 31/07/2012 | RCA 2600 Series Digital Electronic Attitude Indicator | 102-02(XX)-(XX)-(XX) | C4c C113 | 12-KMC-ETSO2600 |

KID-SYSTEME GmbH - LUENEBURGER SCHANZE 30 21614 BUXTEHUDE GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

KID-SYSTEME GmbH - LUENEBURGER SCHANZE 30 21614 BUXTEHUDE GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---------------------------------------|------------------|---------------|
| EASA.21O.10055498 | 13/11/2015 | On Board Control Equipment Worldwide (OBCE-WW) | Z476H0010111 AMDT B Z476H(XXXXXXX) | 2C514 | DDPZ476H0010B |

KONINKLIJKE FABRIEK INVENTUM B.V. - GALVANIBAAN 5 3439 MG NIEUWEGEIN NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|--|------------------|--------------------------|
| EASA.21O.10048819 | 11/04/2014 | DF1575 LH(>&<)>RH Oven | 4315750-00-0000 4315751-00-0000 | C184 | 43157-DDP-3-01 |
| EASA.21O.10048931 | 25/04/2014 | Galley Insert, Convection Oven, DF1500 Atlas LH(>&<)>RH | 4315000-00-0000 4315001-00-0000 | C184 | 43150-DDP-3-01 |
| EASA.21O.10048932 | 25/04/2014 | Galley Insert, Convection Oven, DF1500 ARINC LH(>&<)>RH | 4315000-90-0000 4315001-90-0000 | C184 | 43150-DDP-3-02 |
| EASA.21O.10051359 | 26/11/2014 | DS3500 STEAM OVEN (ARINC) | 4323500-00-6600 4323500-02-6600 4323500-12-6600 4323501-00-6600 4323501-02-6600 4323501-12-6600 | C184 | 43235-DP-04, -05, -06 |
| EASA.21O.10051370 | 26/11/2014 | DF3500 Convection oven (ARINC) | 4313500-00-6600 4313500-02-6600 4313501-00-6600 4313501-02-6600 | C184 | 43135-DP-03 |
| EASA.21O.10051630 | 12/12/2014 | DF3500 CONVECTION OVEN (ATLAS) | 4313510-00-6600 4313510-02-6600 4313511-00-6600 4313511-02-6600 | C184 | 43135-DP-05, 43135-DP-06 |
| EASA.21O.10051631 | 12/12/2014 | DS3500 STEAM OVEN (ATLAS) | 4323510-00-6622 4323510-02-6622 4323511-00-6622 4323511-02-6622 | C184 | 43235-DP-07 |

KORRY ELECTRONICS COMPANY - 11910 BEVERLY PARK ROAD 98204 EVERETT USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--------------------------------|---------------|------------------|---------------|
| EASA.IM.21O.10052855 | 02/04/2015 | CP-2B Weather Radar Controller | 1146000-() | 2C63c | 1146019-090 |

L-3 COMMUNICATIONS - 600 THIRD AVENUE 10016 NEW YORK USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|---|---|---------------|
| EASA.21O.218 | 04/01/2005 | TAWS 8000 | 805-18000-() 805-18200-() | C151a | 016-18047-001 |
| EASA.IM.21O.1107 | 24/11/2009 | MAG-3100 Magnetometer | 9200-21200-() | C6d | 0030-21213-01 |
| EASA.IM.21O.10028950 | 22/02/2010 | GH-3100 Electronic Standby Instrument | 501-1860-()() 501-1870-() | C2d C4c C6d C8d C10b 2C34f 2C36f 2C40c C46a 2C66b C106 C113 C115b | 0030-10021-01 |
| EASA.IM.21O.10030856 | 09/07/2010 | Electronic Standby Instrument ESI-1000 with Software 2.x | 9200-32100-(XX)(Y)(Z) | C2d C3d C4c C6d C10b C46a C113 | 0030-32047-01 |
| EASA.IM.21O.10033092 | 21/12/2010 | ESI-2000 Electronic Standby Instrument with Lithium Ion Batt | 9200-32500-(XX)(Y)(Z) 9230-32501-() | C2d C3d C4c C6d C10b C46a C113 | 0030-32548-01 |
| EASA.IM.21O.10042301 | 22/11/2012 | SKY899A TCAS I | EXCLUDING 805-11900-001 TCR899: 805-11900-() | JTSO-C118 Other | 016-11945-002 |

L-3 COMMUNICATIONS - 600 THIRD AVENUE 10016 NEW YORK USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|----------------------------------|---|---|---------------|
| EASA.IM.210.10049647 | 26/06/2014 | GH-3900 Standby instrument | 8010-34001-() () 9200-34X00-() () 9230-34004-() 9230-34029-() () SEE APPL. FORM FOR DETAILS | C2d C3d C4c C6e C8e C10b 2C34f 2C35d 2C36f 2C40c C46a 2C66b C95a C106 C113 | 0030-34062-01 |
| EASA.IM.210.10051663 | 16/12/2014 | MCDU-R MC-860 | A50A000-00() | C113 | 12591-2A932 |
| EASA.IM.210.10052219 | 10/02/2015 | Magnetometer MAG-3000 | 501-1826-(XX) | C6e | 508-2420 |
| EASA.IM.210.10044366, REV. B | 14/09/2015 | GH-3900.2 Standby Instrument | 8010-34400-() () FOR THE 9200-34400-() () 9200-34410-() () FOR THE 9200-34500-() () 9200-34600-() () 9200-34700-() () 9230-34012-() FOR THE DCM GH-3900.2 STANDBY INSTRUMENT SYSTEM SOFTWARE | C2d C3d C4c C6e C8e C10b 2C34f 2C35d 2C36f 2C40c C46a 2C66b C95a C106 C113 C115b | 0030-34462-01 |
| EASA.IM.210.10051312, REV. A | 02/12/2014 | AIR DATA COMPUTER ADC-4000 | ADC-4000 9200-30000-0(XX) ADC-4000 9200-30000-2(XX) | C106 A1 | 0030-30038-01 |
| EASA.IM.210.1037, REV. B | 04/10/2013 | Avionics Digital Radio, ADR-7050 | 9200-21453-() | 2C34f 2C36f 2C37e 2C38e 2C40c 2C128 | 0030-21486-01 |
| LBA.N-O.10.540/07 JTSO | 09/01/2001 | WX500 Stormscope | 805-11500-() 805-11930-() | | 016-11528-001 |
| LBA.N-O.10.986/008 JTSO | 03/05/2002 | WX-1000/SKY497 | 78-8060-5900-8 78-8060-5900-9 | | 016-11945-001 |
| LBA.N-O.10.986/009 JTSO | 21/03/2002 | RGC250 Radar Graphics Computer | 805-11400-() | | 016-11465-001 |
| LBA.O.10.540/010JTSO | 12/08/2002 | WX-950 | 805-10930-() 805-10950-() | | |
| LBA.O.10.540/8 | 28/04/1999 | WX-900 | 78-8060-5980-0 | TSO C110A Other | |
| LBA.O.10.941/002NTSO | 05/02/2002 | TRC 899 | 805-11900-() | TSO C118 TSO C147 Other | |
| LBA.O.10.941/1NTSO | 11/08/1999 | SKY 497 | 805-10800-001 | TSO C147 Other | |

L-3 COMMUNICATIONS AVIATION RECORDERS - 100 CATTLEMEN ROAD 34232 SARASOTA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|--|------------------|----------------------------|
| EASA.IM.210.814, REV. B | 02/11/2010 | FA2100 Cockpit Voice Recorder | 2100-102X-XX | C123a | 2100-102X-XX, ISSUE 1 & |
| EASA.IM.210.10046139 | 21/08/2013 | LDR 1000 Lightweight Data Recorder | 1000-1() | 2C197 | 905-E5855-42 |
| EASA.IM.210.10049650 | 27/06/2014 | FA2100FDR | 2100-2() 2100-4() ACCELEROMETER P/N: 17A() ALSO COVERING THREE AXIS | C124b | 905-E6097-42 |
| EASA.IM.210.10049718 | 03/07/2014 | S161 Control Unit | S161-() | C123b | 905-E6114-42 |
| EASA.IM.210.10049851 | 14/07/2014 | S058 //Cockpit Area Microphone | S058-() | C123b | 905-E6092-42 |
| EASA.IM.210.10049882 | 16/07/2014 | FA2100CVR / Cockpit Voice Recorder | 2100-1025-02 AND 2100-1026-02 2100-1() EXCLUDING | C123b C177 | 905-E6153-42 |
| EASA.IM.210.10054175 | 26/06/2015 | FA2100FDR | 17A() 2100-2() 2100-4() | C124b | 905-E6097-42 |
| EASA.IM.210.10041496, REV. A | 30/04/2014 | Cockpit Voice and Flight Data Recorder | 5() | C123b C124b | 905-E5748-42 |

(L-3) ELECTRODYNAMICS, Inc. - 1200 HICKS ROAD 60008 ROLLING MEADOWS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------------|---------------|
| EASA.IM.210.10034229 | 17/03/2011 | SRVIVR Cockpit Voice and Flight Data Recorder (CVFDR) | 1493100-10XX 1493100-20XX 1493100-30XX | C123b C124b C177 | 6081145 |

(L-3) ELECTRODYNAMICS, Inc. - 1200 HICKS ROAD 60008 ROLLING MEADOWS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------------|---------------|
| EASA.IM.210.10037709 | 16/12/2011 | SRVIVR Cockpit Voice and Flight Data Recorder (CVFDR) | 1493100-11ZZ 1493100-21ZZ 1493100-31ZZ | C123b C124b C177 | 6081170 |

L'HOTELLIER - 4 RUE HENRI POINCARE 92167 ANTONY CEDEX FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|----------------------------------|--------------------|------------------|--|
| EASA.210.1135 | 15/12/2008 | Smoke Detector | 12192-00 | C1c | 12192-00 |
| EASA.210.1136 | 10/12/2008 | Smoke Detector | 12821-00 | C1c | 12821-00 |
| EASA.210.389, REV. A | 23/05/2012 | Smoke Detector 10056-01 10056-02 | 10056-01, 10056-02 | C1c | 10056-01 AND DDP 10056-02 DDP10056-01 REV. 0 FOR P/N ISSUE C FOR P/N 10056-02 |

LIFEPOR, Inc. - 1610 HERITAGE STREET 98674 WOODLAND USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---------------------------------|---------------|------------------|---------------|
| EASA.IM.210.10044103 | 19/03/2013 | Dynamic Divan Model 17-0011 | 17-0011() | C127a | DDP-17-0011 |
| EASA.IM.210.10044651 | 26/04/2013 | Side Facing Divan Model 17-0010 | 17-0010() | C39c | DDP-17-010 |

MANUFACTURE FRANCAISE DES PNEUMATIQUES MICHELIN - PLACE DES CARMES DECHAUX 63040 CLERMONT-FERRAND CEDEX 9 FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-------------------------------------|------------------|---------------|
| EASA.210.260 | 22/03/2005 | Falcon F7X NLG Tyre, 16x6.0 R6/12PR | M17201 | C62d | MICH 12/04 |
| EASA.210.262 | 29/03/2005 | Gulfstream G IV & V MLG Tyre, Model H34X9.25R18/18PR/225MPH | M17901 | C62d | MICH 34/04 |
| EASA.210.263 | 29/03/2005 | Gulfstream G IV & V NLG Tyre, Model H21X7.25R10/12PR/225MPH | M18001 | C62d | MICH 33/04 |
| EASA.210.292 | 03/06/2005 | Embraer 190 MLG Tyre, H41x16.0R0/22PR/225MPH | M18601 | C62d | MICH 14/05 |
| EASA.210.329 | 29/08/2005 | A380 NLG Tyre | M17402 | C62d | MICH 25/05 |
| EASA.210.331 | 29/08/2005 | Embraer ERJ170 MLG Tyre | M15801 | C62d | MICH 20/05 |
| EASA.210.332 | 29/08/2005 | Fairchild FH-227 NLG Tyre and Mitsubishi MU-2 MLG Tyre | 025-350-0 | C62d | MICH 45/05 |
| EASA.210.333 | 29/08/2005 | Boeing 737 NLG Tyre | M15501 | C62d | MICH 19/05 |
| EASA.210.334 | 29/08/2005 | Boeing 777/767-400ER MLG Tyre | M12301 IND02 | C62d | MICH 41/05 |
| EASA.210.340 | 12/09/2005 | Airbus A330/A340 MLG Tyre | M05102 IND02 | C62d | MICH 43/05 |
| EASA.210.351 | 28/09/2005 | A380 NLG Tire 1270X455R22/32PR/235MPH | M17401 | C62d | MICH 13/05 |
| EASA.210.421 | 11/11/2005 | Embraer ERJ 190 MLG Tire - H41x16.0R20/22PR/225MPH | M18602 | C62d | MICH 47/05 |
| EASA.210.511 | 22/05/2006 | Airbus A318, A319, A320, A321 NLG Tire 30x8.8R15 / 16PR / 22 | M08201 | C62d | MICH 15/06 |
| EASA.210.512 | 22/05/2006 | Falcon F7X MLG Tire H32x10.5R16.5 / 16PR / 225MPH | M18901 | C62d | MICH 07/06 |
| EASA.210.514 | 01/06/2006 | Boeing 777 / 767-400ER MLG Tyre - Model 50x20.0R22/32PR - 23 | M12301 IND02 RETREADED WITH TR | C62d | MICH 21/06 |
| EASA.210.558 | 21/09/2006 | Boeing B777-200LR/-300ER NLG Tyre - Model 43x17.5R17/32PR/23 | M17701 | C62d | MICH 38/06 |
| EASA.210.559 | 21/09/2006 | Boeing 787 Nose Landing Gear Tyre - Model 40x16.0R16/26PR/23 | M18501 | C62d | MICH 35/06 |
| EASA.210.664 | 29/06/2007 | A300/310/318/319/320 Main Landing Gear Tyre Model 46x17.0R20 | M01103-02 RETREADED WITH TREAD | C62d | MICH 04/07 |
| EASA.210.723 | 29/06/2007 | Boeing 737 Nose Landing Gear Tyre | M12801IND02 | C62d | MICH 06/07 |
| EASA.210.778 | 15/08/2007 | A330/A340 Main Landing Gear Tyre | M05102 IND 02 RETREAD CODE T07 | C62d | MICH 22/07 |
| EASA.210.785 | 02/08/2007 | Boeing 737 Main Landing Gear Tyre H44.5x16.5R21 - 30PR - 235 | M19001 | C62d | MICH 23/07 |
| EASA.210.845 | 14/11/2007 | Airbus A321 Main Landing Gear Tyre 1270x455R22 - 225 mph | M13901 IND 01 | C62d | MICH 27/07 |
| EASA.210.847 | 30/05/2008 | MLG Tyre 11.00-12 / 8PR / 160 mph; MLG Tyre 11.00-12 / 10PR | 021-354-2 021-355-0 | C62d | MICH 34/07 |
| EASA.210.848 | 30/05/2008 | Nose Landing Gear Tyre 16x4.4 / 6PR / 160 mph | 061-605 | C62d | MICH 35/07 |
| EASA.210.849 | 16/11/2007 | MLG & NLG Tyre 15x6.0-6 / 6PR / 120 mph, MLG & NLG Tyre 15x6 | 061-501-0 070-449-0 072-449-0 | C62d | MICH 36/07 |
| EASA.210.861 | 30/05/2008 | 17.5x6.25-6 / 8PR / 160 mph Nose Landing Gear Tyre | 021-327-0 | C62d | MICH 40/07 |
| EASA.210.862 | 30/05/2008 | 18x4.4 / 6PR / 160 mph Nose Landing Gear Tyre | 021-611-0 | C62d | MICH 43/07 |
| EASA.210.863 | 17/12/2007 | 18x4.4 / 6PR / 190 mph Nose Landing Gear Tyre | 019-611-0 | C62d | MICH 44/07 |
| EASA.210.867 | 30/05/2008 | Nose Landing Gear Tyre 17.5x6.25-6 / 10PR / 120 mph | 061-326-0 | C62d | MICH 39/07 |
| EASA.210.868 | 06/06/2008 | Main Landing Gear Tyre 24x7.7 / 16PR / 225 mph | 039-677-2 | C62d | MICH 72/07 |
| EASA.210.869 | 06/06/2008 | Main Landing Gear Tyre 24x7.7 / 14PR / 210 mph | 038-675-2 | C62d | MICH 71/07 |
| EASA.210.870 | 17/12/2007 | Main Landing Gear Tyre 24x7.7 / 14PR / 190 mph | 026-675-0 | C62d | MICH 69/07 |
| EASA.210.871 | 06/06/2008 | Main Landing Gear Tyre 24x7.7 / 14PR / 190 mph | 028-675-3 | C62d | MICH 70/07 |
| EASA.210.872 | 17/12/2007 | Main Landing Gear Tyre 19.5x6.75-8 / 10PR / 190 mph | 028-335-3 | C62d | MICH 55/07 |
| EASA.210.873 | 06/06/2008 | Nose Landing Gear Tyre 5.00-5 / 8PR / 160 mph | 021-310-0 | C62d | MICH 85/07 |

MANUFACTURE FRANCAISE DES PNEUMATIQUES MICHELIN - PLACE DES CARMES DECHAUX 63040 CLERMONT-FERRAND CEDEX 9 FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-------------------------------------|------------------|---------------|
| EASA.210.874 | 17/12/2007 | Main Landing Gear Tyre 24x7.25-12 / 12PR / 190mph | 026-609-0 | C62d | MICH 68/07 |
| EASA.210.875 | 17/12/2007 | Main Landing Gear Tyre 30x9.5-14 / 16PR / 210 mph | 027-215-0 | C62d | MICH 78/07 |
| EASA.210.876 | 06/06/2008 | Nose Landing Gear Tyre 26x6.6 / 12PR / 225 mph | 029-658-0 | C62d | MICH 74/07 |
| EASA.210.878 | 30/05/2008 | Main & Nose Landing Gear Tyre 22x6.75-10 / 8PR / 160 mph | 021-523-0 | C62d | MICH 60/07 |
| EASA.210.879 | 07/01/2008 | Main Landing Gear Tyre 22x5.75-12 / 10PR / 190 mph | 026-520-0 | C62d | MICH 59/07 |
| EASA.210.880 | 07/01/2008 | Main & Nose Landing Gear Tyre 380x150-5 / 6PR / 120 mph | 070-544-0 | C62d | MICH 79/07 |
| EASA.210.881 | 07/01/2008 | Main Landing Gear Tyre 22x7.75-10 / 12PR / 190 mph | 026-528-0 | C62d | MICH 63/07 |
| EASA.210.882 | 06/06/2008 | Main Landing Gear Tyre 22x7.75-10 / 10PR / 160 mph | 021-527-0 | C62d | MICH 62/07 |
| EASA.210.883 | 30/05/2008 | MLG & NLG Tyre 19.5x6.75-8 / 10PR / 160 mph | 021-335-1 061-335-1 | C62d | MICH 53/07 |
| EASA.210.884 | 30/05/2008 | Main & Nose Landing Gear Tyre 18x5.5 / 10PR / 210 mph | 033-631-0 | C62d | MICH 52/07 |
| EASA.210.885 | 30/05/2008 | Nose Landing Gear Tyre 18x4.4 / 10PR / 210 mph | 031-613-8 | C62d | MICH 47/07 |
| EASA.210.886 | 30/05/2008 | Nose Landing Gear Tyre 18x4.4 / 10PR / 210 mph | 031-613-4 | C62d | MICH 46/07 |
| EASA.210.887 | 07/01/2008 | Main & Nose Landing Gear Tyre 18x5.5 / 8PR / 190 mph | 028-630-0 | C62d | MICH 50/07 |
| EASA.210.888 | 30/05/2008 | Nose Landing Gear Tyre 18x4.4 / 12PR / 210 mph | 031-614-0 | C62d | MICH 49/07 |
| EASA.210.889 | 07/01/2008 | Nose Landing Gear Tyre 18x4.4 / 12PR / 210 mph | 027-614-0 | C62d | MICH 48/07 |
| EASA.210.890 | 30/05/2008 | Main Landing Gear Tyre 20x4.4 / 8PR / 160 mph | 028-619 | C62d | MICH 57/07 |
| EASA.210.891 | 07/01/2008 | Nose Landing Gear Tyre 19.5x6.75-8 / 10PR / 190 mph | 026-335-1 | C62d | MICH 54/07 |
| EASA.210.892 | 17/12/2007 | NLG Tyre 5.00-5 / 6PR / 120 mph | 070-312-0 071-312-0 072-312-0 | C62d | MICH 83/07 |
| EASA.210.893 | 17/12/2007 | Main & Nose Landing Gear Tyre 5.00-5 / 4PR / 120 mph | 070-308-0 | C62d | MICH 81/07 |
| EASA.210.894 | 17/12/2007 | Nose Landing Gear Tyre 450x190-5 / 10PR / 190 mph | 026-545-0 | C62d | MICH 80/07 |
| EASA.210.895 | 17/12/2007 | Nose Landing Gear Tyre 19.5x6.75-8 / 8PR / 210 mph | 027-382-0 | C62d | MICH 56/07 |
| EASA.210.934 | 06/02/2008 | Main Landing Gear Tyre 17.5x5.75R9 - 12 R9 - 190 mph | M19401 | C62d | MICH 122/07 |
| EASA.210.942 | 06/02/2008 | MLG & NLG Tyre 5.00-5 / 4PR / 120 mph; NLG Tyre 5.00-5 / 4PR | 071-308-0 072-308-0 | C62d | MICH 82/07 |
| EASA.210.943 | 06/02/2008 | NLG Tyre 5.00-5 / 10PR / 120 mph; NLG Tyre 5.00-5 / 10PR / 1 | 071-311-0 072-311-0 | C62d | MICH 84/07 |
| EASA.210.944 | 06/02/2008 | MLG & NLG Tyre 6.00-6 / 4PR / 120 mph; MLG & NLG Tyre 6.00-6 | 070-315-0 071-315-0 072-315-0 | C62d | MICH87/07 |
| EASA.210.945 | 06/02/2008 | MLG & NLG Tyre 6.00-6 / 6PR / 120 mph | 070-314-0 071-314-0 072-314-0 | C62d | MICH 88/07 |
| EASA.210.946 | 06/02/2008 | MLG & NLG Tyre 6.00-6 / 8PR / 120 mph | 070-317-0 071-317-0 072-317-0 | C62d | MICH 89/07 |
| EASA.210.947 | 30/05/2008 | Main & Nose Landing Gear Tyre 6.00-6 / 6PR / 160 mph | 061-316-1 | C62d | MICH 90/07 |
| EASA.210.948 | 06/02/2008 | Nose Landing Gear Tyre 5.00-5 / 8PR / 160 mph | 070-310-0 | C62d | MICH 86/07 |
| EASA.210.961 | 30/05/2008 | Nose Landing Gear Tyre 18x4.25-10 / 6PR / 210 mph | 031-595-0 | C62d | MICH 42/07 |
| EASA.210.962 | 25/02/2008 | Main & Nose Landing Gear Tyre 22x6.75-10 / 10PR / 190 mph | 026-524-0 | C62d | MICH 61/07 |
| EASA.210.963 | 30/05/2008 | Nose Landing Gear Tyre 17.5x6.25-6 / 8PR / 190 mph | 028-327-0 | C62d | MICH 41/07 |
| EASA.210.964 | 25/02/2008 | Nose Landing Gear Tyre 18x4.4 / 6PR / 190 mph | 030-611-0 | C62d | MICH 45/07 |
| EASA.210.965 | 25/02/2008 | NLG Tyre 18x4.4 / 10 PR / 190 mph; 18x4.4 / 10 PR / 210 mph | 031-613-2 031-613-5 | C62d | MICH 38/07 |
| EASA.210.966 | 25/02/2008 | Nose Landing Gear Tyre 18-5.5 / 8PR / 210 mph | 027-630-0 | C62d | MICH 51/07 |
| EASA.210.967 | 30/05/2008 | Nose Landing Gear Tyre 21x7.25-10 / 10PR / 225 mph | 031-506-1 | C62d | MICH 58/07 |
| EASA.210.968 | 06/06/2008 | Main Landing Gear Tyre 22x8.0-10 / 10 PR / 190 mph | 028-699-1 | C62d | MICH 66/07 |
| EASA.210.969 | 06/06/2008 | Main Landing Gear Tyre 22x8.0-10 / 12PR / 190 mph | 028-700-0 | C62d | MICH 67/07 |
| EASA.210.970 | 06/06/2008 | Nose Landing Gear Tyre 26x6.6 / 10PR / 225 mph | 035-657-1 | C62d | MICH 73/07 |
| EASA.210.972 | 25/02/2008 | Nose Landing Gear Tyre 27x7.75-15 / 12PR / 225 mph | 029-616-0 | C62d | MICH 75/07 |

MANUFACTURE FRANCAISE DES PNEUMATIQUES MICHELIN - PLACE DES CARMES DECHAUX 63040 CLERMONT-FERRAND CEDEX 9 FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-------------------------------------|------------------|------------------------------------|
| EASA.210.974 | 25/02/2008 | MLG Tyre 6.50-10 / 8PR / 120 mph | 076-345-0 077-345-0 078-345-0 | C62d | MICH 94/07 |
| EASA.210.975 | 25/02/2008 | Main & Nose Landing Gear Tyre 6.00-6 / 8PR / 160 mph | 070-317-1 | C62d | MICH 92/07 |
| EASA.210.976 | 25/02/2008 | MLG & NLG Tyre 6.50-10 / 6PR / 120 mph, NLG Tyre 6.50-10 / 6 | 076-367-0 077-367-0 078-367-0 | C62d | MICH 93/07 |
| EASA.210.977 | 25/02/2008 | MLG Tyre 29x11.00-10 / 10PR / 160 mph | 076-446-1 077-446-1 078-446-1 | C62d | MICH 77/07 |
| EASA.210.978 | 25/02/2008 | MLG & NLG Tyre 6.00-6 / 8PR / 160 mph, NLG Tyre 6.00-6 / 8PR | 021-317-1 021-317-2 061-317-1 | C62d | MICH 91/07 |
| EASA.210.980 | 10/03/2008 | MLG Tyre 6.50-10 / 10PR / 120 mph | 076-356-0 077-356-0 078-356-0 | C62d | MICH 95/07 |
| EASA.210.981 | 10/03/2008 | MLG & NLG Tyre 6.50-10 / 10PR / 160 mph | 021-356-1 076-356-1 | C62d | MICH 96/07 |
| EASA.210.982 | 17/03/2008 | Main & Nose Landing Gear Tyre 6.50-10 / 12PR / 160 mph | 021-357-1 | C62d | MICH 97/07 |
| EASA.210.983 | 06/06/2008 | Main Landing Gear Tyre 6.50-10 / 12PR / 190 mph | 028-357-0 | C62d | MICH 98/07 |
| EASA.210.984 | 17/03/2008 | MLG Tyre 6.50-8 / 6PR / 120 mph, MLG & NLG Tyre 6.50-8 / 8PR | 072-363-0 072-364-0 | C62d | MICH 99/07 |
| EASA.210.985 | 17/03/2008 | Main & Nose Landing Gear Tyre 6.50-8 / 6PR / 160 mph | 025-337-0 | C62d | MICH 100/07 |
| EASA.210.986 | 20/03/2008 | Main & Nose Landing Gear Tyre 6.50 -8 / 8PR / 160 mph | 025-338-0 | C62d | MICH 101/07 |
| EASA.210.987 | 20/03/2008 | Main Landing Gear Tyre 6.50-8 / 8PR / 160 mph | 061-338-2 | C62d | MICH 102/07 |
| EASA.210.988 | 20/03/2008 | Main Landing Gear Tyre 670x210-12 / 10PR / 160 mph | 028-667-2 | C62d | MICH 103/07 |
| EASA.210.989 | 20/03/2008 | MLG Tyre 7.00-6 / 6PR / 120 mph, MLG & NLG Tyre Tyre 7.00-6 | 070-313-0 071-313-0 072-313-0 | C62d | MICH 104/07 |
| EASA.210.990 | 20/03/2008 | MLG Tyre 7.00-6 / 8 PR / 120 mph | 070-306-0 071-306-0 072-306-0 | C62d | MICH 105/07 |
| EASA.210.991 | 30/05/2008 | Nose Landing Gear Tyre 7.50-14 / 8PR / 160 mph | 021-360-0 | C62d | MICH 106/07 |
| EASA.210.992 | 06/06/2008 | Nose Landing Gear Tyre 7.50-14 / 12PR / 160 mph | 028-362-1 | C62d | MICH 107/07 |
| EASA.210.993 | 10/03/2008 | Nose Landing Gear Tyre 16x4.4R8 - 10PR - 190 mph | M19301 | C62d | MICH 30/07 |
| EASA.210.994 | 20/03/2008 | Main Landing Gear Tyre H29x9.0-15 / 16PR / 210 mph | 027-438-0 | C62d | MICH 119/07 |
| EASA.210.995 | 20/03/2008 | Main Landing Gear Tyre H27x8.5-14 / 16PR / 210 mph | 027-697-0 | C62d | MICH 114/07 |
| EASA.210.996 | 20/03/2008 | Main Landing Gear Tyre H30x9.5-16 / 16PR / 225 mph | 036-210-0 | C62d | MICH 120/07 |
| EASA.210.1017 | 04/04/2008 | MLG Tyre 8.00-6 / 6PR / 120 mph, MLG Tyre 8.00-6 / 6 PR / 12 | 071-371-0 072-371-0 072-374-0 | C62d | MICH 108/07 |
| EASA.210.1018 | 04/04/2008 | MLG & NLG Tyre 8.50-10 / 8PR / 120 mph, MLG Tyre 8.50-10 / 1 | 072-376-0 072-379-0 | C62d | MICH 109/07 |
| EASA.210.1019 | 06/06/2008 | MLG & NLG Tyre 8.50-10 / 8PR / 160 mph, MLG Tyre 8.50-10 / 1 | 021-349-0 021-350-0 | C62d | MICH 111/07 |
| EASA.210.1020 | 04/04/2008 | Main & Nose Landing Gear Tyre 8.50-10 / 8PR / 160 mph | 025-349-0 | C62d | MICH 110/07 |
| EASA.210.1021 | 04/04/2008 | Main Landing Gear Tyre 8.50-6 / 6PR / 120 mph | 076-325-0 | C62d | MICH 112/07 |
| EASA.210.1052 | 08/07/2008 | Main Landing Gear Tyre 52x21.0R22 / 36PR / 235MPH | M13104 | C62d | MICH 25/08 |
| EASA.210.1053 | 08/07/2008 | Main Landing Gear Tyre 29x7.7R15 / 225MPH | M06201 IND 04 | C62d | MICH 20/08 |
| EASA.210.1055 | 09/07/2008 | Main Landing Gear Tyre H38x13.0R18 - 20PR - 225 mph | M19601 | C62d | MICH 16/08 |
| EASA.210.1082 | 06/08/2008 | Main Landing Gear Tyre 26x6.6R14 - 14PR - 225 mph | M08401 | C62d | MICH 91/08 |
| EASA.210.1125 | 09/10/2008 | Nose & Landing Gear Tyre 50x20.0R22 / 34PR / 235MPH | M42204 | C62d | MICH 94/08 |
| EASA.210.1174 | 14/01/2009 | Nose Landing Gear Tyre 16x4.4 / 8 PR / 190 MPH | 026-606-0 | C62d | MICH 103/08 |
| EASA.210.1215 | 13/02/2009 | Main Landing Gear Tyre 54x21.0R23 / 38PR / 235MPH | M19501 | C62d | MICH 04/09 |
| EASA.210.1229 | 13/03/2009 | Main Landing Gear Tyre 26x6.6R14 / 14PR / 210MPH | M15702 | C62d | MICH 06/09 |
| EASA.210.1258 | 07/07/2009 | Main Landing Gear Tyre H44.5x16.5-21/28 PR/225 MPH; Retread | 029-894-0 | C62d | RTD EASA H44.5 X16.5-21-28RT-225 7 |
| EASA.210.1268 | 27/05/2009 | Nose Landing Gear Tyre 18x4.4 / 10PR / 210 MPH | 027-613-0 | C62d | EASA 18X4.4-10TRT-2109 |
| EASA.210.1269 | 27/05/2009 | Main Landing Gear Tyre 6.00-6 / 8PR / 160 MPH | 025-317-0 | C62d | EASA 6.00-6-8TL-1606 |

MANUFACTURE FRANCAISE DES PNEUMATIQUES MICHELIN - PLACE DES CARMES DECHAUX 63040 CLERMONT-FERRAND CEDEX 9 FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|-------------------------------------|--------------------|--------------------------------|
| EASA.21O.1279 | 03/06/2009 | General Aviation Tyre 15x6.0 / 6PR / 160 MPH | 025-501-0 | C62d | EASA-15.0X6.0-6-6 TL-1603 |
| EASA.21O.1282 | 10/06/2009 | Nose Landing Gear Tyre 17.5x5.75R8 / 225MPH | M13301 IND 02 | C62d | MICH 22/09 |
| EASA.21O.1303 | 10/11/2009 | General Aviation Tyre 23x7.0-12 / 12PR / 210MPH | 027-504-0 | C62d | EASA-23X70-12-12 TRT-2103 |
| EASA.21O.1309 | 11/08/2009 | Main Landing Gear Tyre H49x19.0-22 / 32PR / 235MPH; Retread | 040-805-0 TREAD CODE 690 | C62d | RTD EASA H49X19-22-32RT-23 510 |
| EASA.21O.1311 | 23/09/2009 | Main Landing Gear Tyre 1270 x 455R22 / 225mph Retread. | M13901 IND 01 TREAD CODE T089 | C62d | MICH R09/13 |
| EASA.21O.1312 | 11/08/2009 | General Aviation Tyre 5.00-5 / 6PR / 160MPH | 025-309-0 | C62d | EASA 5.00-5 6TL-1601 |
| EASA.21O.243, REV. A | 22/03/2005 | Falcon F7X MLG Tyre, H32x10.5 R6.5/16PR | M17001 | C62d | MICH 03/04 |
| EASA.21O.330, REV. A | 24/02/2010 | Nose Landing Gear Tyre 24x7.7R10 - 16 PR - 225 mph | M18201 | C62d | MICH 16/05 |
| EASA.21O.850, REV. A | 10/12/2007 | NLG Tyre 16x4.4 / 8PR / 160 mph | 021-606 079-606-0 | C62d | MICH 37/07 |
| EASA.21O.973, REV. A | 05/12/2008 | Main Landing Gear Tyre 28x9.00-12 / 12 PR / 160 mph | 028-728 | C62d | MICH 76/07 |
| EASA.21O.10018228 | 05/03/2015 | Main Landing Gear Tyre 46x17.0R20 / 30 PR/ 225 mph | M01103-02 AMDT B | JTSO C62D Other | MICH 16/00 |
| EASA.21O.10027901 | 16/11/2009 | Main Landing Gear Tyre H41x16.0R20 / 22PR / 225mph Retread | M18602 TREAD CODE T087 | C62d | MICH R09/18 |
| EASA.21O.10029128 | 08/03/2010 | General Aviation Tyre 17.5x5.75-8 - 12PR - 120 mph | 021-627-1 | C62d | 17.5X5.75-8-12TL-1 202 |
| EASA.21O.10029883 | 29/04/2010 | Nose Landing Gear Tyre 1050x395R16 / 28PR / 235mph | M07603 | C62d | MICH 03/10 |
| EASA.21O.10030619 | 28/06/2010 | Main Landing Gear Tyre 1270x455R22/32PR/225MPH; Retread | M20101-01, TREAD CODE T082 | C62d | MICH 10/04 |
| EASA.21O.10031957 | 27/09/2010 | Main Landing Gear Tyre 1400 x 530R23 - 42PR - 235mph | M18801 | C62d | MICH 05/10 |
| EASA.21O.10032703 | 26/11/2010 | Nose Landing Gear Tyre 14.5X5.5R6 - 225 mph | M15201-01 | JTSO-C62D Other | MICH 08/01 ISSUE 1 |
| EASA.21O.10032733 | 26/11/2010 | Main Landing Gear Tyre 26x6.6R14 / 14PR / 225 mph | M15102 | C62d | MICH 30/10 |
| EASA.21O.10032734 | 26/11/2010 | Main Landing Gear Tyre 46x17.0R20 / 30PR / 225 mph | M01106 | C62d | MICH 29/10 |
| EASA.21O.10038329 | 07/02/2012 | 27x8.5R12 / 16 PR / 225 mph Nose Landing Gear Tyre | M20001 | C62d | MICH 43/11 |
| EASA.21O.10039100 | 10/04/2012 | H42x15.0R21 / 26PR / 225 mph Main Landing Gear Tyre | M20201 | C62d | MICH 44/11 |
| EASA.21O.10039101 | 10/04/2012 | Main Landing Gear Tyre 52x21.0R22 / 36 PR / 245 mph | M20501 | C62d | MICH 06/12 |
| EASA.21O.10040490 | 05/07/2012 | Nose Landing Gear Tyre 14.5x5.5R6 - 225 mph | M08301 IND 03 | C62d | MICH 22/12 |
| EASA.21O.10040862 | 31/07/2012 | Main Landing Gear Tyre H32x10.5R16.5 / 16PR / 225mph | M18902 | C62e | MICH 33/12 |
| EASA.21O.10042058 | 06/11/2012 | Main Landing Gear Tyre 50x20.0R22 / 34PR / 235 mph | M42202 | C62e | MICH39/12 |
| EASA.21O.10042061 | 06/11/2012 | Main Landing Gear Tyre 50x20.0R22 / 32 PR / 235 mph | M12302 | C62e | MICH 38/12 |
| EASA.21O.10044914 | 17/05/2013 | Main Landing Gear Tyre H33X10,5R17 / 18 PR / 225 mph | M20701 | C62e | MICH 004/13 |
| EASA.21O.10044941 | 21/05/2013 | Main Landing Gear Tyre H32x10.5R16.5 - 18 PR - 235 mph | M20801 | C62e | MICH 018/13 |
| EASA.21O.10045645 | 09/07/2013 | Nose Landing Gear Tyre 16x6.0R6 / 12 / 225 mph | M17203 | C62e | 013/13 |
| EASA.21O.10046098 | 15/08/2013 | Main Landing Gear Tyre 50 x 20.0R22 - 34 PR - 245 mph | M42203 | C62e | MICH 009/13 |
| EASA.21O.10046099 | 15/08/2013 | Nose Landing Gear Tyre 1050x395R16 - 28 PR - 245 mph | M20301 | C62e | MICH 029/13 |
| EASA.21O.10047545 | 18/12/2013 | Nose Landing Gear Tyre 450x190-5 - 8PR - 190 MPH | 019-545-0 | C62e | EASA 450X190-5-8TL-190 1 |
| EASA.21O.10047605 | 23/12/2013 | NOSE LANDING GEAR TYRE / 43x17.5R17 / 32PR / 235 MPH | M17701 RETREAD TREAD CODE T092 | C62e | MICH R13/07 |
| EASA.21O.10048175 | 18/02/2014 | NOSE LANDING GEAR TYRE / 20.5x6.75-10 - 12PR - 225 MPH | 036-897-0 | C62e | EASA 20.5X6.75-10-12TL-2252 |
| EASA.21O.10050369 | 03/09/2014 | MAIN LANDING GEAR TYRE// H42x16.0R20 - 24PR - 225 mph | M21101 | C62e | MICH 027/14 |
| EASA.21O.10051626 | 12/12/2014 | NOSE LANDING GEAR TYRE // 30x8.8R15/16 / 225 mph | M08203 | C62e | MICH 060/14 |
| EASA.21O.10051627 | 12/12/2014 | MAIN LANDING GEAR TYRE // 46x17.0R20/30PR / 225 mph | M01110 | C62e | MICH 057/14 |
| EASA.21O.10052438 | 27/02/2015 | MAIN LANDING GEAR TIRE / 26x6.6R14/ 14PR / 225 mph | M15103 | C62e | MICH 070/14 |
| EASA.21O.10035481, REV. A | 08/09/2011 | Main Landing Gear Tyre 52x21.0R22 / 36PR / 235mph | M13104 RETREAD TREAD CODE T090 | C62d | MICH R11/10 |
| EASA.21O.10052168, REV. A | 24/07/2015 | MAIN LANDING GEAR TIRE // 52x21.0R22 / 36PR / 245 mph | M13105 | C62e | MICH 068/14 |
| EASA.21O.1005, REV. B | 31/03/2015 | Main Landing Gear Tyre 1400x530R23 / 40PR / 235MPH | M16004 () M16004, M16004 AMDT A | C62d | MICH 19/02 |
| EASA.21O.1022, REV. A | 05/12/2008 | Nose Landing Gear Tyre 8.90-12.50 / 6PR / 160mph | 021-436 | C62d | MICH 113/07 |
| F.O.012 | 22/06/2000 | Aircraft Tire | M015101-01 | C62d | MICH 25/00 |

MANUFACTURE FRANCAISE DES PNEUMATIQUES MICHELIN - PLACE DES CARMES DECHAUX 63040 CLERMONT-FERRAND CEDEX 9 FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|---------------|------------------|----------------------------------|
| F.O.013 | 22/06/2000 | Aircraft Tire | M12601-01 | | |
| F.O.024 | 29/08/2000 | 1270x455R22 / 32PR Aircraft Tire | M20101-01 | | MICH 29/00 |
| F.O.031 | 08/02/2001 | Tyre for Facon 900 MLG | M15001-01 | | TYRE 29X7.7 R15/16PR |
| F.O.039 | 06/03/2001 | Tire | M 16001-04 | | MICH 05/01 |
| F.O.040 | 06/03/2001 | Tire | M 14001-01 | | MICH 03/01 |
| F.O.050 | 15/06/2001 | Tire for Concorde A/C | M16801 | | |
| F.O.053 | 12/11/2001 | MLG Tire for Hawker Horizon | M15701 | | 26X6.6R14 AIR X/ 14PR /210MPH |
| F.O.055 | 12/11/2001 | Tire for Boeing 747 | M42201 | | |
| F.O.056 | 03/12/2001 | Tire for MLG Cessna Citation X & Sovereign | M14401 | | 26X6.6R14 / 12PR / 210 MPH |
| F.O.069 | 11/02/2002 | Aircraft Tire | M15601 | | QTR MICH 45/01 |
| F.O.070 | 11/02/2002 | Aircraft Tire | M08202 | | QTR MICH 48/01 |
| F.O.090 | 05/10/2002 | PILATUS PC 21 NLG tire | M16201 | | MICH 56/01 |
| F.O.106 | 13/02/2003 | Boeing 777 NLG Tire | M17702 | | MICH 26/02 |
| F.O.107 | 13/02/2003 | Boeing 777 MLG Tire | M13102 | | MICH 34/02 |
| F.O.110 | 26/03/2003 | Eclipse 500 MLG Tire | M16901 | | 42/02 |
| F.O.115 | 20/05/2003 | Cessna 560XL MLG tire | M13702 | | MICH 31/03 |

MARS A.S. - OKRUZNI II 239 569 43 JEVICKO CZECH REPUBLIC

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.1015 | 02/07/2008 | PTCH-P40, PTCH-P50 Emergency parachute | 02361-() FOR PTCH-P50 02537-() FOR PTCH-P40 02543-() FOR PTCH-P50 | C23d | 002-08 |
| EASA.210.1011, REV. A | 14/05/2008 | Emergency parachute ATL-88-1, ATL-88/90-1, ATL-88/92-S-1, AT | 02574-() 02575-() 02576-() 02577-() 02578-() 02579-() 02580-() 02581-() 02582-() 02583-() | C23d | 001-08 |
| LBA 40.010/94 | 03/09/2003 | Rettungsfallschirm, Type ATL-88, ATL-88/90 | ATL-88 ATL-88/90 | | |

MARTIN-BAKER AIRCRAFT COMPANY Ltd. - LOWER ROAD UB9 5AJ HIGHER DENHAM, NEAR UXBRIDGE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--------------------------------------|------------------|--------------------------------|
| EASA.210.552 | 05/09/2006 | S-92 Passenger Seat | MBCS9950 () | C127a | MBAS92PS |
| EASA.210.553 | 05/09/2006 | MBCS12410 Utility Seat | MBCS12410 () | C39b | MBA-GEN-UTIL |
| EASA.210.921 | 20/05/2008 | TSO MFOS Operators seat | MBCS15250() | C39b | MBA-DDP-MFOS-RSL |
| EASA.210.101, REV. A | 31/08/2004 | MBCS12200 Utility Seat | MBCS12200 | C127a | MBAS920B |
| EASA.210.1139 | 17/12/2008 | Console Operator Seat | MBCS12900() | C39b | MBA-DDP-TSO-COS |
| EASA.210.1307 | 14/12/2009 | S-92 Passenger Seat - Reclined | MBCS15950() | C127a | MBAS92PS-3DEG |
| EASA.210.473, REV. A | 20/11/2012 | S-92 Series High Comfort Crew Seat | MBCS6380-1() MBCS6380(XX)(XXX) | C127a | MBAS92HCCS |
| EASA.210.567, REV. A | 20/11/2012 | S-92 Crew Seat | MBCS6100-1(XX)(XXX) MBCS6100-3() | C127a | MBAS92CS-1 |
| EASA.210.824, REV. A | 20/11/2012 | Multi-Platform Armored Crew Seat | MBCS15500() MBCS15500-1() | C127a | MBA-DDP-MPACS-CIV |
| EASA.210.10030429 | 15/06/2010 | MBCS9600 Passenger Seat forward/aft facing | MBCS9600() MBCS9600-1() | C127a | MBA/BK117C2/PS ISSUE 4 |
| EASA.210.10034349 | 28/03/2011 | Rotating Operator's Seat & Pallet Assembly | MBCS12925() | C39b | MBA-DDP-ROTATING MFOS & PALLET |
| EASA.210.10039036 | 02/04/2012 | Multi Functional Operator's Seat | MBCS12650() | C39c | MBA-DDP-TSO MFOS-MBCS12650 |
| EASA.210.10051544 | 08/01/2015 | Rotating Seat Forward and Aft Facing | MBCS6930() | | |
| EASA.210.10051545 | 08/01/2015 | GE/ge/02/26/0052:98 | MBCS3310-1() | | |

MEGGITT AEROSPACE LIMITED - BOURNEMOUTH INTERNATIONAL AIRPORT BH23 6EW CHRISTCHURCH UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|--|
| EASA.210.354, REV. A | 24/06/2008 | Nose Wheel Airbus A340-500/600 | DAP00076-01 (XX) DAP00077-01 (XX) | C135 | 1326 + 1327 |
| EASA.210.543, REV. A | 31/07/2006 | AH55055 Nose Wheel for Gulfstream V | AH55055 (XX) | C135 | DDP1133 |
| EASA.210.707, REV. A | 24/06/2008 | GULFSTREAM V - Main Wheel Landing Gear | AHA2114 | C135 | 1135 |
| EASA.210.928, REV. C | 02/04/2015 | Embraer 505 Phenom 300. Brake | DAP00097-01 DAP00097-02 DAP00097-03 DAP00097-04 | C26c | 1365 FOR DAP00097-01 1402 FOR DAP00097-02 1443 FOR DAP00097-03 1479 FOR DAP00097-04 |
| EASA.210.929, REV. A | 07/08/2009 | Embraer 505 Phenom 300 Mainwheel | DAP-00098-01 DAP-00098-02 | C26c | 1364&1372 (MINOR CHANGE EXPL.) |
| EASA.210.930, REV. A | 03/08/2011 | Embraer 505 Phenom 300 Nosewheel | DAP00099-01 DAP00099-02 | C26c | 1366 + 1421 |

| MEGGITT AEROSPACE LIMITED - BOURNEMOUTH INTERNATIONAL AIRPORT BH23 6EW CHRISTCHURCH UNITED KINGDOM | | | | | |
|--|--------------------|------------------|---|-------------------|-----------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10044555 | 22/04/2013 | ATR-72 Brake | AHA-1653-10 AHA-1653, AHA-1653-9 | TSO-C26C Other | 980 |
| EASA.210.10045144 | 04/06/2013 | AW189 Nose Wheel | DAP00214-01 | C26c | 1437 NOSE WHEEL |
| EASA.210.10045145, REV. A | 09/07/2015 | AW189 // Brake | DAP00212-02 DAP00212-03 DAP00213-01 | C26c | 1482 |

| MEGGITT (UK) LIMITED - BOURNEMOUTH INTERNATIONAL AIRPORT BH23 6EW CHRISTCHURCH UNITED KINGDOM | | | | | |
|---|--------------------|---|--|-------------------------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.049 | 19/05/2004 | MA342S - Secondary Flight Display Repeater | 34201(-)(-) | C113 | DC 1397 |
| EASA.210.261 | 29/03/2005 | MA271A - Air Data Unit | 271(-)(-)(-) | C106 | DC1441 |
| EASA.210.265 | 11/04/2005 | MA277A - Static Pressure Transducer Unit Plus (STPU+) | 277(-)(-)(-) | C106 | DC1426 |
| EASA.210.266 | 11/04/2005 | MA276A - High Integration Air Data Computer Plus (HIDAC+) | 276(-)(-)(-) | C106 | DC 1427 |
| EASA.210.276 | 27/04/2005 | MA341S - Secondary Flight Display Repeater | 341(-)(-)(-) | C113 | DC1417 |
| EASA.210.669 | 15/03/2007 | MA50-1A Air Data Computer | 50-1(-)(-) | TSO C106 Other | DC1489 |
| EASA.210.050, REV. A | 14/01/2005 | MA392S - Secondary Flight Display Mark 2 | 392(-)(-)(-) | C3d C4c C6d C106 C113 | DC 1395 |
| EASA.210.1081 | 12/07/2012 | MA342S-A Secondary Flight Display Repeater | 34206(-)(-) | C113 | DC1520 |
| EASA.210.309, REV. A | 29/01/2007 | 19004 Series Magnetometer Heading Sensor | 19004(-)(-) | C7d | DC1433 |
| EASA.210.472, REV. A | 13/03/2006 | MA273A Air Data Unit | 273(-)(-)(-) | C106 | DC 1465 |
| EASA.210.10034780 | 29/04/2011 | MA19010S Tri Axis Magnetic Sensor (TAM) | 19010(-)(-) | C6d | DC1558 |
| EASA.210.10051646 | 15/12/2014 | MA400S2 // Integrated Secondary Flight Display | 400(XX)-(XX)-(XX) EXCLUDING | C3d C4c C6e C113 C106A1 | DDPMA400S2 |
| EASA.210.10052236 | 11/02/2015 | MA344S1 //Secondary Flight Display Repeater (SFDR) | 344(XX)-(XX)-(XX) EXCLUDING 34400-01-(XX) | C113 | DDPMA344S1 |
| EASA.210.10032456, REV. A | 11/02/2015 | MA344S //Secondary Flight Display Repeater (SFDR) | 34400-01-(XX) | C113 | DDPDC1583 |
| EASA.210.10039935, REV. B | 15/12/2014 | MA400S1 Integrated Secondary Flight Display (ISFD) | 4000-00-(XX), 4001-00-(XX) | C3d C4c C6e C106 C113 | DDP40000 |
| EASA.210.10054819, REV. A | 30/09/2015 | MA278A High Integration Air Data Computer Plus | 278(XX)-(XX)-(XX) | C106A1 | DDPMA278A |
| EASA.210.10054821, REV. A | 30/09/2015 | MA279A Static Pressure Transducer Unit Plus | 279(XX)-(XX)-(XX) | C106A1 | DDPMA279A |
| EASA.210.1230, REV. A | 15/12/2014 | MA400S Integrated Secondary Flight Display (ISDF) | 4000-00-(XX), 4001-00-(XX) | C3d C4c C6d C106 C113 | DDP40000 |
| ETSOA.210.10052688 | 20/03/2015 | MA341S1//Secondary Flight Display Repeater (SFDR)P/N: 341(xx) | | C113 | MA341S1 |

| MEL AVIATION LTD - 32 ADDISON ROAD CO10 2YW SUDBURY UNITED KINGDOM | | | | | |
|--|--------------------|------------------------------------|----------------------------------|------------------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10027473 | 05/10/2009 | Portable Oxygen Unit MO3048 Series | MO3048 MO3048-01 MO3048-02 | Other UK CAA BCAR A4-8 | MO3048-02DDP |

| MESSIER-BUGATTI-DOWTY - 7 RUE GENERAL VALERIE ANDRE 78140 VELIZY-VILLACOUBLAY FRANCE | | | | | |
|--|--------------------|---|---------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.007 | 19/05/2004 | Falcon 2000 MLG Wheel | C20384(XXX) | C26c | C20384200 |
| EASA.210.008 | 19/05/2004 | A300/A310 NLG Wheel | 286351(XXX) | C26c | 286351005 |
| EASA.210.248 | 09/03/2005 | ATR 42/72 NLG Wheel | C20 589 (XXX) | C135 | C20 589 000 |
| EASA.210.250 | 09/03/2005 | ATR 42/72 MLG Wheel | C20 586 (XXX) | C135 | C20 586 000 |
| EASA.210.252 | 09/03/2005 | ATR 42/72 Brakes | C20 585 (XXX) | C135 | C20 585 000 |
| EASA.210.554 | 06/09/2006 | Main and Centerline Wheel Assembly 3-1639() | 3-1639() | C135 | 3-1639 |
| EASA.210.555 | 06/09/2006 | Main and Centerline Carbon Brake Assembly 2-1705() | 2-1705() | C135 | 2-1705 |
| EASA.210.673 | 29/09/2008 | C20621 Main wheel | C20621() | C135 | C20621000 |
| EASA.210.674 | 29/09/2008 | C20623 Carbon brake | C20623() | C135 | C20623100 |
| EASA.210.690 | 24/05/2007 | C20594() Carbon brake | C20594000 | C135 | C20594000 |
| EASA.210.1248 | 23/09/2009 | C20645 CARBON BRAKE | C20645() | C135 | C20645000 |
| EASA.210.593, REV. A | 16/05/2008 | C20598 Nose Wheel | C20598() | C135 | C20598000 |
| EASA.210.688, REV. A | 16/05/2008 | C20596 Nose Wheel | C20596() | C135 | C20596000 |
| EASA.210.689, REV. A | 24/05/2007 | C20595 Main Wheel | C20595() | C135 | C20595000 |
| EASA.210.746, REV. A | 16/05/2008 | C20600 Main Wheel | C20600() | C135 | C20600000 |

MESSIER-BUGATTI-DOWTY - 7 RUE GENERAL VALERIE ANDRE 78140 VELIZY-VILLACOUBLAY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|--|-----------------------|--|
| EASA.21O.825, REV. A | 29/10/2007 | C20633 Carbon Brake | C20633() | C135 | C20633000 |
| EASA.21O.826, REV. A | 16/05/2008 | C20626 Main Wheel | C20626() | C135 | C20626000 |
| EASA.21O.10042257 | 19/11/2012 | C20692 Brake | C20692000 C20692() STARTING FROM | C135a | DDPC20692000 |
| EASA.21O.10042258 | 19/11/2012 | C20703 Main Wheel Assembly | C20703000 C20703() STARTING FROM | C135a | DDPC20703000 |
| EASA.21O.10042455 | 03/12/2012 | C20659 Nose Wheel Assembly | C20659() STARTING FROM C20659000 | C135a | DDPC20659000 |
| EASA.21O.10042456 | 03/12/2012 | C20657 Brake | C20657() STARTING FROM C20657000 | C135a | DDPC20657000 |
| EASA.21O.10042457 | 03/12/2012 | C20658 Main Wheel Assembly | C20658() STARTING FROM C20658000 | C135a | DDPC20658000 |
| EASA.21O.10043919 | 05/03/2013 | C20648 Carbon Brake | C20648000 C20648() STARTING FROM | C135a | DDPC20648000 |
| EASA.21O.10043921 | 05/03/2013 | C20649 Main Wheel Assembly | C20649000 C20649() STARTING FROM | C135a | DDPC20649000 |
| EASA.21O.10044477 | 15/04/2013 | C20672 Nose Wheel Assembly | C20672() STARTING FROM C20672100 | C135a | ETSO/TSO C20672100 |
| EASA.21O.10045603 | 05/07/2013 | C20674 Main Wheel Assembly | C20674() STARTING C20674101 | C135a | ETSO/TSO C20674101 |
| EASA.21O.10045606 | 05/07/2013 | C20677 Brake | C20677() STARTING C20677100 | C135a | ETSO/TSO C20677100 |
| EASA.21O.10031594, REV. A | 27/09/2010 | Carbon Brake 2-1542-(), 2-1545-(), 2-1577-(), 2-1578-() | 2-1542-10 2-1542-11 2-1542-4 2-1542-9 2-1545-4 2-1545-7 2-1545-8 2-1545-9 2-1577-1 2-1577-7 2-1577-8 2-1577-9 2-1578-1 2-1578-5 2-1578-6 2-1578-7 | FAA TSO C26C Other | 2-1542-4/-9/-10/-11 2-1545-4/-7/-8/-9 2-1577-1/-7/-8/-9 2-1578-1/-5/-6/-7 |
| EASA.21O.1009, REV. A | 16/05/2008 | C20637 Nose Wheel | C20637() | C135 | C20637000 |
| F.O.020 | 12/07/2000 | Aircraft Brake | C20524(XXX) | | C20524000 |
| QAC 141 N°036 | 04/01/2001 | 3-1591 Main Wheel | 3-1591 | FAA TSO C26C Other | 3-1591 |
| QAC 141 N°037 | 04/01/2001 | 2-1663() Carbone brake | 2-1663 | FAA TSO C26C Other | 2-1663-3 |
| QAC 141 N°038 | 04/01/2001 | 3-1596 Nose Wheel | 3-1596 | FAA TSO C26C Other | 3-1596 NOSE WHEEL |
| QAC 141 N°096 | 14/02/2002 | C20545() Main Wheel | C20545000 | FAA TSO C26C Other | C20545000 |
| QAC 141 N°097 | 14/02/2002 | C20546() Nose Wheel | C20546000 | FAA TSO C26C Other | C20546000 |
| QAC 141 N°098 | 14/02/2002 | C20544() Carbon brake | C20544000 | FAA TSO C26C Other | C20544000 |
| QAC 141 N°109 | 04/10/2002 | 3-1628 Main Wheel | 3-1628 | FAA TSO C26C Other | 3-1628 MAIN WHEEL |
| QAC 141 N°2000/05726 | 26/09/2000 | C20534() Carbon brake | C20534000 | FAA TSO C26C Other | C20534000 |
| QAC 141 N°53386 | 11/04/1988 | C20180100<(>, <)> C20180120<(>, <)> C20182000 Main Wheel | C20181100, C20180120, C20182000 | FAA TSO C26C Other | |
| QAC 141 N°53603 | 12/12/1997 | C20194() Carbon brake | C20194500 | FAA TSO C26C Other | C2014500 |
| QAC 141 N°940054 | 07/06/1994 | 3-1510-1 Nose Wheel | 3-1510-1 | FAA TSO C26C Other | 3-1510-1 |
| QAC 141 N°951610 | 07/04/1995 | C20449000 Carbon Brake C20452000 Main Wheel | C20449000 C20452000 | FAA TSO C26C Other | C20449000 C20452000 |
| QAC 141 N°952717 | 24/07/1995 | 3-1547 Nose Wheel | 3-1547 | FAA TSO C26C Other | 3-1547 |
| QAC 141 N°955061 | 08/12/1995 | 3-1546 MLG Wheel | 3-1546 | FAA TSO C26C Other | 3-1546 |
| QAC 141 N°965633 | 29/11/1996 | C20195() Main Wheel | C20195() | FAA TSO C26C Other | C20195160 |
| QAC 141 N°965634 | 29/11/1996 | C20225() Carbon brake | C20225() | FAA TSO C26C Other | C20225300/301 |
| QAC 141 N°975053 | 10/10/1997 | C20210() Carbon brake | C20210() | FAA TSO C26C Other | C20210500 |
| QAC 141 N°976070 | 08/12/1997 | C20211() Main Wheel | C20211() | FAA TSO C26C Other | C20211160 |
| QAC 141 N°982318 | 28/04/1998 | C20383() Nose Wheel | C20383() | FAA TSO C26C Other | C20383000 |
| QAC 141 N°983406 | 22/06/1998 | C20500() Main Wheel | C20500000 | FAA TSO C26C Other | C20500000 |

MESSIER-BUGATTI-DOWTY - 7 RUE GENERAL VALERIE ANDRE 78140 VELIZY-VILLACOUBLAY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|---------------|-----------------------|---------------|
| QAC 141 N°984329 | 05/08/1998 | C20382() Carbon brake | C20382() | FAA TSO C26C Other | C20382100 |
| QAC 141 N° 986511 | 18/11/1998 | Aircraft Brake C20497() for Sikorsky S-92 | C20497(XXX) | | C20497000 |
| QAC 141 N° 986515 | 18/11/1998 | Aircraft Wheel C20498() for Sikorsky S-92 | C20498(XXX) | | C20498100 |
| QAC 141 N°990851 | 02/02/1999 | C20509() Main Wheel | C20509000 | FAA TSO C26C Other | C20509000 |
| QAC 141 N°990852 | 02/02/1999 | C20508() Carbon brake | C20508000 | FAA TSO C26C Other | C20508000 |
| QAC 193 N°108R1 | 10/09/2003 | C20562() Nose Wheel | C20562000 | FAA TSO C135 Other | C20562000 |
| QAC 193 N°112R1 | 10/09/2003 | C20559() Main Wheel | C20559000 | FAA TSO C135 Other | C20559000 |
| QAC 193 N°113R1 | 10/09/2003 | C20558() Carbon brake | C20558000 | FAA TSO C135 Other | C20558000 |

MICROTURBO S.A.S. - 8 CHEMIN DU PONT DE RUPE 31200 TOULOUSE FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|---------------|------------------|-------------------------------|
| EASA.210.10045083, REV. A | 07/06/2013 | e-APU60 model 342 Auxiliary Power Unit / Category 1 | 342-11 | CS-APU | MICROTURBO REPORT 0342/13/089 |
| LETTER 3507 DGAC/SFACT | 22/01/1990 | Saphier 4 series | | | |
| LETTER 4188 DTA/M | 19/07/1971 | Saphire 2 series | | | |
| QAC 150 | 14/12/1993 | Saphir 20 series | | | |

MID-CONTINENT INSTRUMENT Co., Inc. - 9400 E. 34TH STREET NORTH 67226 WICHITA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------|--------------------|--|---------------|--|---------------|
| EASA.IM.210.10041601 | 04/10/2012 | MD835 Emergency Power Supply | MD835(-) | C179a | DDP-MD835 |
| EASA.IM.210.10044581 | 22/04/2013 | MD302 Standby Attitude Module | 6420302(-) | C2d C3d C4c C10b C106 C113 C179a | DDP-MD302 |
| EASA.IM.210.10047096 | 18/11/2013 | TA102 Dual USB Charging Port | 6430102(-) | C71 | TA-102 |
| EASA.IM.210.10048085 | 11/02/2014 | TB17 / 17 Amp Hour Lithium-Ion Battery | 6430017(-) | C179a | DDP-TB17 |
| EASA.IM.210.10050184 | 12/08/2014 | TB44 Advanced Lithium-Ion Battery | 6430044(-) | C179a Other | DDP-TB44 |
| EASA.IM.210.10050269 | 22/08/2014 | TI-250 DC-to-AC 250VA Static Electrical Power Inverter | 6430250(-) | C73 | DDP-TI250 |
| EASA.IM.210.10052582 | 13/03/2015 | Static Inverter TI120(X) | 6431200(-) | C73 | DDP-TI1200 |
| EASA.IM.210.10052586 | 13/03/2015 | MD93 | 6420093(-) | C71 | DDP-MD93 |
| LBA.N-O.10.929/14 JTSO | 09/02/2000 | Course Deviation Indicator MD200 | MD200(-) | | MD200-JTSO |

MIKROTECHNA PRAHA A.S. - BARRANOVA 409 143 00 PRAHA 4 - MODRANY CZECH REPUBLIC

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|----------------|------------------|---------------|
| EASA.210.023, REV. A | 09/02/2005 | LUN 1120 Counter Drum Pointer Altimeter | LUN 1120.XXXXX | C10b | 22/10/03/1120 |

MILLENNIUM CONCEPTS, INC. - 9050 W. MONROE CIRCLE 67209 WICHITA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|----------------------------------|------------------|---------------|
| EASA.IM.210.10030346, REV. A | 17/06/2010 | Model 2023 Crew and cabin dynamic seating system | 2023-2511{}-{} 2023-2521{}-{} | C127a | 2023-DDP001 |

MITAS A.S. - SVEHLOVA 1900/3 106 00 PRAHA 10 - ZABEHVICE CZECH REPUBLIC

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------|--------------------|--|---------------|------------------|-----------------------|
| EASA.210.748 | 20/03/2008 | 6.00-6 M1 TL Aircraft Tyre | 81200101 | C62d | TPF-MIT 014-04 |
| EASA.210.749 | 20/03/2008 | 6.50-10 M1 TL Aircraft Tyre | 81210101 | C62d | TPF-MIT 015-04 |
| EASA.210.1051 | 06/08/2008 | 5.00 5 M 1 TL Aircraft Tyre | 81220101 | C62d | TPF - MIT 016 - 07 EN |
| EASA.210.10055168 | 16/10/2015 | 550 x 225 Model 5 Turbeless. Aircraft Tyre | 81621101 | C62e | DDP-15/02 |
| ETSOA.210.10052398 | 24/02/2015 | 720 x 310 Model 5 Tubeless. | 81666101 | C62e | DDP-15/01 |

MOOG Inc. - SENECA & JAMISON ROAD 14052 EAST AURORA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--------------------------------|--|--|---------------|
| EASA.IM.210.10028353 | 21/12/2009 | CRM500GA Remote Magnetometer | 8350-0140(-) | C6d | 6960-0104-01 |
| EASA.IM.210.10030683 | 01/07/2010 | KFD 840 Primary Flight Display | 8350-0840(-) WITH (-) = -06 OR GREATER | C2d C3d C4c C6d C8d C10b 2C34f 2C36f 2C40c C52b C106 C113 | 6960-0103-01 |

NATIONAL PARACHUTE INDUSTRIES, INC. - 78 WHITE RD EXT 12463 PALENVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

NATIONAL PARACHUTE INDUSTRIES, INC. - 78 WHITE RD EXT 12463 PALENVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|-------------------------|---|-------------------|---------------|
| EASA.IM.210.1263 | 24/06/2009 | National FLAT Parachute | 81002-(XX) CANOPY 81101-(XX) HARNESS/CONTAINER | TSO C23B Other | 623091 |

NORDISK AVIATION PRODUCTS A.S. - WEIDEMANNSGATE 8 3080 HOLMESTRAND NORWAY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|-----------------------------------|---------------|------------------|---------------|
| EASA.210.568 | 17/10/2006 | AMP Container | 13280-1(XX) | C90c | #164 |
| EASA.210.578 | 25/10/2006 | PGA Pallet 11600-A | 11600-A() | C90c | #156 |
| EASA.210.579 | 25/10/2006 | PMC Pallet 11600-M | 11600-M() | C90c | #157 |
| EASA.210.580 | 25/10/2006 | AKE Container 11560 | 11560-1() | C90c | #154 |
| EASA.210.581 | 25/10/2006 | AKE Container 11560-2 | 11560-2() | C90c | #155 |
| EASA.210.691 | 02/04/2007 | Air Cargo Container type LBY | 13522-1() | C90c | 165 |
| EASA.210.774 | 15/10/2007 | LAJ Air Cargo Container | 13536-1() | C90c | 166 |
| EASA.210.922 | 23/05/2008 | ABY Air Cargo Container | 16194-1() | C90c | 170 |
| EASA.210.1218 | 08/05/2009 | AKE UltraLite Air Cargo Container | 17000-1() | C90c | 172 |
| EASA.210.1301 | 21/06/2010 | AMJ 10850-1 Air Cargo Container | 10850-1() | C90c | 151 |
| EASA.210.10030854 | 09/07/2010 | AMX Air Cargo Container | 17240-1() | C90c | 171 |
| EASA.210.10030859 | 09/07/2010 | AKN Air Cargo Container | 20200-1() | C90c | 174 |
| EASA.210.10031937 | 23/09/2010 | AMF 10890-1 Air Cargo Container | 10890-1() | C90c | 142 |
| EASA.210.10032338 | 28/10/2010 | AMV Air Cargo Container | 18450-1() | C90c | 173 |
| EASA.210.10035554 | 29/06/2011 | PBF Air Cargo Pallet | 17751-1() | C90c | 177 |
| EASA.210.10036283 | 26/08/2011 | AKH Alulite Air Cargo Container | 22390-1() | C90c | 178 |
| EASA.210.10037560 | 06/12/2011 | AKH Air Cargo Container | 126540-3() | C90c | 150 |
| EASA.210.10039853 | 30/05/2012 | AKE Air Cargo Container | 21000-1() | C90c | 180 |
| EASA.210.10039958 | 05/06/2012 | PLA Air Cargo Pallet | 127830() | C90c | 145 |
| EASA.210.10039959 | 05/06/2012 | AKE Air Cargo Container | 11870-1() | C90c | 158 |
| EASA.210.10040174 | 15/06/2012 | ALF Air Cargo Container | 12160-1() | C90c | 161 |
| EASA.210.10041045 | 17/08/2012 | AAV Air Cargo Container | 24400-1() | C90c | 182 |
| EASA.210.10041272 | 03/09/2012 | AML Air Cargo Container | 17930-1() | C90c | 181 |
| EASA.210.10042276 | 20/11/2012 | AMU Air Cargo Container | 10476-1() | C90c | 139 |
| EASA.210.10042299 | 22/11/2012 | AMF Air Cargo Container | 10890-2() | C90c | 143 |
| EASA.210.10042465 | 03/12/2012 | AMD Air Cargo Container | 11240-1() | C90c | 149 |
| EASA.210.10042515 | 06/12/2012 | AMA Air Cargo Container | 510333-4() | C90c | 141 |
| EASA.210.10042552 | 11/12/2012 | AAU Air Cargo Container | 10650-1() | C90c | 140 |
| EASA.210.10042736 | 17/12/2012 | AAF Air Cargo Container | 11010-1() | C90c | 147 |
| EASA.210.10042738 | 17/12/2012 | AAK Air Cargo Container | 10660-1() | C90c | 144 |
| EASA.210.10042847 | 20/12/2012 | AAF Air Cargo Container | 11010-2() | C90c | 148 |
| EASA.210.10043228 | 14/01/2013 | AAP Air Cargo Container | 510150-2() | C90c | 136 |
| EASA.210.10043443 | 30/01/2013 | ABB Air Cargo Container | 11450-1() | C90c | 153 |
| EASA.210.10043920 | 05/03/2013 | AAP Air Cargo Container | 510150-4() | C90c | 137 |
| EASA.210.10045839 | 23/07/2013 | PNA Air Cargo Pallet | 11600-N() | C90d | 183 |

NORTHROP GRUMMAN LITEF GmbH - LOERRACHER STR. 18 79115 FREIBURG GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|--|-------------------|
| EASA.210.1108 | 12/09/2008 | LCR-93 Altitude and Heading Reference System (AHRU) | 142185-(XXXX)-(XXX) | JTSO-C3D JTSO-C4C JTSO-C5E JTSO-C6D Other | 142185-0010-100 |
| EASA.210.1109 | 12/09/2008 | LCR-92 Altitude and Heading Reference Unit | 124210-(XXXX)-(XXX) 141450-(XXXX)-(XXX) 141852-(XXXX)-(XXX) 142300-(XXXX)-(XXX) | TSO C4C TSO C5E TSO C6D Other | 10.480/07-5 TS |
| EASA.210.1110 | 12/09/2008 | Compass Controller Unit (CCU) | 140855(XXXX)-(XXX) | TSO C6C Other | 10.480/6TS |
| EASA.210.1192 | 15/01/2009 | LTR-97 and LCR-98 Vertical Gyro/ Directional Gyro replacement | 142830-(XXXX)-(YYY) LTR-97 143250-(XXXX)-(YYY) LCR-98 | JTSO-C4C JTSO-C5E JTSO-C6D Other | 142830-0010-100 |
| EASA.210.1193 | 15/01/2009 | LCR-88 A Attitude and Heading Reference System (AHRU) | 121319-(XXXX)-(YYY) | TSO C4C TSO C5E TSO C6D Other TECH. SPEZ. 10.480/4TS AUSG. 4 | LBA TS 10.480/4TS |
| EASA.210.855, REV. A | 08/09/2008 | LCR-100 Attitude Heading Reference System | 145130-(XXXX)-(XXX) | C3d C4c C5e C6d | 145130-0010-100 |

NSE - LES SEIGNES 03250 NIZEROLLES FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|-------------|-------------------------|------------------|---------------|
| EASA.210.10037281, REV. B | 29/04/2013 | GIC-NSD | GIC-411884X-00 AMDT (X) | C113 | DDP-Z4080 |

OPTIMARES S.p.A. - STRADA STATALE 156 DEI MONTI KM 44 04018 SEZZE SCALO ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|--|------------------|---------------|
| EASA.210.10039569 | 11/05/2012 | Model "ZEST", Type Number 01 - Business Class Seat | -() () () 01-() () () () () | C39c | Always accept |
| EASA.210.10046200 | 28/08/2013 | Model: ZEST+ Type number 02 B/C Seat | 02-(0)(0)(0)(0)-(0)(0)(0)(0) | C39c | DDP-02 |
| EASA.210.10046847 | 29/10/2013 | 03 E/C Seat | 03-(0)(0)(0)(0)-(0)(0)(0)(0) | C39c | DDP-03 |

OPTIMARES S.p.A. - STRADA STATALE 156 DEI MONTI KM 44 04018 SEZZE SCALO ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|--------------------|------------------|-----------------------------|
| EASA.210.10050647 | 26/09/2014 | Model "ZEST Suite". Type Number 04 - F/C Seat | 04-(000000)-000000 | C39c | Intermed. Reg. Prereg. Sub. |
| EASA.210.10054880 | 25/09/2015 | 09 // Model Maxima Plus F/C Seat | 09-(000000)-000000 | C127a | DDP-09 |

OROLIA S.A.S. - Z.I. DES CINQ CHEMINS 56520 GUIDEL FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.1095 | 27/08/2008 | KANNAD 121 AF-H ELT | S18 26 502-02() | 2C91a | DOC 03 032 A |
| EASA.210.1096 | 27/08/2008 | KANNAD 121 AF Two Freq. ELT | S18 24 502-XX.(X).(XX) | 2C91a | 00/89 |
| EASA.210.818, REV. B | 19/07/2013 | Emergency Locator Transmitter KANNAD 406 COMPACT | S1840501-XX.(X).(XX) S1840502-XX.(X).(XX) | 2C91a 2C126 | DOC05268 |
| EASA.210.1097, REV. B | 19/07/2013 | KANNAD 406 ELT Interface | S1825501-XX.(X).(XX) | 2C91a 2C126 | DOC 02368 |
| EASA.210.1098, REV. A | 19/07/2013 | KANNAD 406 Three frequ.ELT | S18 18 502-XX.(X).(XX) ELT S18 19 502-XX.(X).(XX) ELT S18 19 506-XX.(X).(XX) BATTERY S18 19 524-XX.(X).(XX) BRACKET S18 20 502-XX.(X).(XX) ELT S18 20 506-XX.(X).(XX) BATTERY S18 20 511-XX.(X).(XX) BRACKET S18 20 513-XX.(X).(XX) RCP S18 20 514-XX.(X).(XX) DONGLES S18 21 502-XX.(X).(XX) ELT S18 22 502-XX.(X).(XX) ELT S18 23 502-XX.(X).(XX) ELT | 2C91a 2C126 | 00/88 |
| EASA.210.1265, REV. D | 09/02/2015 | INTEGRA FAMILY | 0141823 AMDT F OR HIGHER FOR B S1850501-XX.(X).(XX) FOR AP S1850551-02 FOR BRACKET UNIVER S1850581-01.(X).(XX) FOR INTEG S1851501-XX.(X).(XX) FOR AF S1852501-XX.(X).(XX) FOR AF-H S1854501-XX.(X).(XX) FOR AP-H | C126a C142a | DOC09080 |

PAC SEATING SYSTEMS Inc. - 3370 SW 42ND AVENUE 34990 PALM CITY USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--------------------------|------------------|---------------|
| EASA.210.10047044 | 13/11/2013 | Forward/Aft facing single seat | (F)S1407-() | C39c | DDP-FS1407 |
| EASA.210.10047059 | 14/11/2013 | Forward/Aft facing double seat | (F)S2401-() | C39c | DDP-FS2401 |
| EASA.IM.210.10029747 | 19/04/2010 | Single Seat | (F)S1206-() | C39b | FS1206 |
| EASA.IM.210.10029748 | 19/04/2010 | Double Seat | (F)S2206-() | C39b | FS2206 |
| EASA.IM.210.10031256 | 05/08/2010 | Single Seat | (F)S1306-() | C39b | FS1306 |
| EASA.IM.210.10032256 | 20/10/2010 | Single Seat FS1307 | (F)S1307-() | C39b | FS1307 |
| EASA.IM.210.10040941 | 06/08/2012 | (F)S1400-() Single Seat | (F)S1400-() | C127a | FS-1400 |
| EASA.IM.210.10040942 | 06/08/2012 | (F)S1404-() Single Seat | (F)S1404-() SINGEL SEAT | C127a | FS1404 |
| EASA.IM.210.10041596 | 02/10/2012 | 2-Place Divan AB300K | AB300K-() | C39c | AB300K |
| EASA.IM.210.10041891 | 22/10/2012 | 1-PL Divan AB300C | AB300C-() | C39c | AB300C |
| EASA.IM.210.10046500 | 25/09/2013 | One Place Forward or Side Facing Divan | BO740F-() | C39c | DDP-BO740F |
| EASA.IM.210.10046501 | 25/09/2013 | One Place Aft Facing Divan | BO741A-() | C39c | DDP-BO741A |
| EASA.IM.210.10048418 | 10/03/2014 | Forward/Aft Facing Single Seat | FS1403-() | C39c | DDP-FS1403 |
| EASA.IM.210.10048535 | 19/03/2014 | Three Place Side Facing Divan | FD3105-() | C39c | DDP-FD3105 |
| EASA.IM.210.10052469 | 03/03/2015 | TYPE A, DOUBLE SEAT // Forward facing double seat | FS2502-() | C127a | DDP-FS2502 |
| EASA.IM.210.10054050 | 15/07/2015 | TYPE A, DOUBLE SEAT // FORWARD/ AFT FACING DOUBLE SEAT | (F)S2409-() | C39c | FS2409 |
| EASA.IM.210.10054051 | 15/07/2015 | TYPE A, 2 PL DIVAN // 2-PL FORWARD FACING DIVAN | (F)D2211-() | C39c | FD2211 |
| EASA.IM.210.10054052 | 15/07/2015 | TYPE A, 2 PL DIVAN // 2-PL AFT FACING DIVAN | (F)D2212-() | C39c | FD2212 |

PALNET GmbH AIR CARGO PRODUCTS - VULKANSTRASSE 10 54578 WIESBAUM GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|---------------|------------------|-----------------|
| EASA.210.018 | 26/05/2004 | Cargo Pallet Type: 25 R 02 | 25 R 02-() | C90c | 25 R 02 |
| EASA.210.058 | 16/06/2004 | Cargo Pallet Type: 25 G 01 | 25 G 01-() | C90c | 25 G 01 |
| EASA.210.545 | 01/08/2006 | AKH-1 | 8136 1000 () | | DDP AKH-1 () |
| EASA.210.546 | 01/08/2006 | LD3 Container Type LOC-1-(), | 8136 0000 () | | DDP LOC-1 () |
| EASA.210.823 | 25/09/2007 | Triple Horse Box | 27 M THB-() | C90c | 27 M THB |
| EASA.210.997 | 20/03/2008 | 25 M 03 - HDP() Heavy Duty Air Cargo Pallet 96 x 125" | 25M03-HDP() | C90c | 25 M 03-HDP() |
| EASA.210.998 | 14/03/2008 | 25 L 10 Air Cargo Pallet 60.4 x 125" | 25 L 10-() | C90c | 25 L 10 |
| EASA.210.10032294 | 25/10/2010 | Horse Box Collapsible | 27 M HBC-() | C90c | 27 M HBC |
| EASA.210.10036777 | 06/10/2011 | Light Weight Air Cargo Pallet 60.4 x 125" | 25L18() | C90c | 25 L 18 |
| EASA.210.10037470 | 29/11/2011 | Heavy Duty Air Cargo Pallet 60.4 x 125" | 25L10-()/HDP | C90c | 25 L 10-() HDP |
| EASA.210.10044650 | 26/04/2013 | 25M31, Pallet 96 x 125" | 25M31 | C90d | 25 M 31 |
| EASA.210.10044652 | 26/04/2013 | Air Cargo Pallet 88 x 125" | 25A41 | C90d | 25 A 41 |
| LBA.O.11.400/182 JTSO | 12/07/2001 | Air Cargo Pallet Type: 25 M 03-() | 25 M 03-() | | 25M03 |
| LBA.O.11.400/183 JTSO | 13/07/2001 | Air Cargo Pallet 25 A 04-() | 25 A 04-() | | 25A04 |
| LBA.O.11.400/184 JTSO | 19/07/2001 | Air Cargo Pallet 25 B 05 - () | 25 B 05 - () | | 25B05 |
| LBA.O.11.400/185 JTSO | 03/09/2001 | Air Cargo Pallet 25 E 06 - () | 25 E 06 - () | | 25E06 |
| LBA.O.11.400/186 JTSO | 30/08/2001 | Air Cargo Pallet 25 K 07 - () | 25 K 07 - () | | 25K07 |

PARATEC GMBH - FLUGPLATZ SAARLOUIS-DUEREN 66798 WALLERFANGEN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|----------------|------------------|---------------|
| LBA.O.40.014/06 JTSO | 17/12/2001 | Personnel Parachute Type: Next (/)Speed 2000 () | 301()/2010() | C23d | 20/30-EBL |

PARATEC GMBH - FLUGPLATZ SAARLOUIS-DUEREN 66798 WALLERFANGEN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

PARKER HANNIFIN CORPORATION - 6035 PARKLAND BLVD 44124-4141 CLEVELAND USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|----------------|------------------|---------------|
| EASA.IM.210.10035977 | 03/08/2011 | Main Wheel and Brake Assembly | 40-466, 30-278 | C26c | AA29-002 |
| EASA.IM.210.10035980 | 03/08/2011 | Nose Wheel | 40-474 | C26c | AA29-001 |
| EASA.IM.210.10046028 | 07/08/2013 | Nose wheel | 40-432 | C26c | AA88-001 |
| EASA.IM.210.10050428 | 10/09/2014 | Aircraft Wheels and Wheel and Brake Assemblies // Nose Wheel | 40-479() | C26c | DDPAA63-002 |

PENNY & GILES AEROSPACE Ltd. - 1 AIRFIELD ROAD BH23 3TH CHRISTCHURCH UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|------------------|---------------|
| EASA.210.1242 | 20/04/2009 | D51615-202 Data Acquisition Flight Recorder | D51615-202-(XXX) | C123a C124a | 3050 |
| EASA.210.464, REV. B | 28/04/2008 | D51610 Enhanced Software Configurable Air Data Unit (E-SCADU) | D51610-0102 D51610-0202 D51610-0502 D51610-0602 D51610-0702 D51610-0802 D51610-0903 D51610-1002 D51610-1102 D51610-1202 D51610-2302 D51610-2602 D51610-(XXX) EXCLUDING P/N | C106 | 3018 |
| EASA.210.10028714 | 04/02/2010 | Multi-Purpose Flight Recorder (Dual Power Input) | D51615-142 | C123a C124a | 3053 |
| EASA.210.10033130 | 20/12/2010 | D51615-3411-250 Flight Recorder | D51615-3411-250 | C123a C124a | 3057 |
| EASA.210.10046693 | 11/10/2013 | D51615-203 Dual Input Data Acquisition Flight Recorder | D51615-203-() | C123b C124b | 3064 |
| CAA.O.00002 | 05/04/2002 | Multi-Purpose Flt Rec D51615 & CCU D51616 | D51615-1() D51616-10() D51616-20() | | |

PPG INDUSTRIES, Inc. - ONE PPG PLACE 15272 PITTSBURGH USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|-------------------------------------|---------------|------------------|---------------|
| ETSOA.IM.210.10054279 | 03/08/2015 | PPG Intelligent Window Model: IW() | NP-2027() | C178 | NP-2027 |

PRATT & WHITNEY CANADA CORP. - 1000 MARIE-VICTORIN BLVD E J4G 1A1 LONGUEUIL CANADA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|---|--|------------------|
| EASA.IM.210.1291 | 30/03/2010 | AUXILIARY POWER UNIT PW901A P/N 3900001-() and ECB 390002-(XX) | 3900001-() 3902712-() ECB 390002-(XX) | JAR-APU CHANGE 2+ORANGE PAPE 2 Other | 3856 P/N 3900287 |
| EASA.IM.210.586, REV. A | 29/08/2007 | PW980A APU | EAPL 3900941-() ECB 3900942-() | JAR-APU CHANGE 2+ORANGE PAPE 1 Other | ER5324 |
| EASA.IM.210.01110 | | ST6L-73 series | | | |

PRATT & WHITNEY RZESZOW S.A. - UL. HETMANSKA 120 35-078 RZESZOW POLAND

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|-------------------------------------|---------------|---------------------------------|------------------------------------|
| EASA.210.10017339, REV. A | 11/09/2015 | APS2000 series Auxiliary Power Unit | 4505000 | JAR-APU AMENDMENT 3 Other | |
| EASA.210.10035886, REV. A | 11/09/2015 | APS5000 series Auxiliary Power Unit | 7000000 | CS-APU | MODEL SPECIFICATION ESR1819 |
| EASA.210.10036804, REV. A | 14/09/2015 | APS3000 series Auxiliary Power Unit | 4507289 | CS-APU | MODEL SPECIFICATION ESR 1581 |

PRONAL - Z.I. DE ROUBAIX EST 59115 LEERS FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|-----------------|------------------|---------------|
| F.O.011 | 17/10/2000 | Wall of bladders for flexible fuel tank | RAHE(XXXXX)-(X) | | AA-0110/A |

PRVNI BRNENSKA STROJIRNA VELKA BITES, A.S. - VLKOVSKA 279 595 12 VELKA BITES CZECH REPUBLIC

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|------------------------------------|---------------|-------------------|------------------------|
| EASA.210.1023 | 09/04/2008 | Safir 5K/G MIS APU | 488 000.03 | TSO C77B Other | PEJ/MIS/002/07/ OLZ |
| EASA.210.10049520 | 17/06/2014 | Safir 5K/G-Z8 Auxiliary Power Unit | 488 100.10 | CS-APU | PEJ/Z8/001/09/OLZ |

PS ENGINEERING INC. - 9800 MARTEL ROAD 37772 LENOIR CITY USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|----------------|------------------|---------------|
| EASA.IM.210.385 | 18/10/2005 | PMA8000 Audio Control Panel/Marker Beacon System | 050-890-0(XXX) | 2C35d C50c | 002-890-0900 |

PS ENGINEERING INC. - 9800 MARTEL ROAD 37772 LENOIR CITY USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|--|--|-------------------------------|---------------|
| EASA.IM.210.536, REV. A | 26/03/2007 | KMA 29 Audio Panel | 050-290-(XXXX) 066-01181-(XXXX) | 2C35d C50c | 002-290-0900 |
| EASA.IM.210.10028565 | 22/01/2010 | PMA6000() Audio Control Panel / Marker Beacon Receiver | 050-604-(XXXX) AFTER JUNE 2009 6000() BEFORE JUNE 2009 | TSO-C35D TSO-C50C Other | 002-600-0900 |
| EASA.IM.210.10053809 | 24/06/2015 | Audio and VHF Com Control panel/Model name PAR200, Audio Con | 050-228-(XXXX) | C139 2C169A | 002-228-0900 |
| LBA.N-O.10.510/003 JTSO | 16/07/2002 | PAC24 Audio Control Panel | 050-240-(XXXX) | | 002-240-1000 |
| LBA.N-O.10.923/32 JTSO | 03/12/1999 | Audio Selector Panel PMA 7000M-S() | PMA 7000S() | | 002-799-0599 |

RDDS AVIONICS LIMITED - STAR LANE CT9 4ED MARGATE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---------------------|------------------------|------------------|---------------|
| EASA.210.10049318, REV. A | 12/06/2014 | Radar Control Panel | IU200-240-(3)-(1).(05) | C113 | 153.358 |

RECARO AIRCRAFT SEATING AMERICA Inc - ALLIANCE AIRPORT 76177 FORT WORTH USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|----------------------|------------------|---------------|
| EASA.IM.210.10054671 | 08/09/2015 | 3510A // TYPE "A" TRANSPORT AEROPLANE FORWARD FACING SEAT | 3510A() () () () | C127a | DDP003/2015 |

RECARO AIRCRAFT SEATING GmbH & Co. - DAIMLERSTRASSE 21 74523 SCHWAEBISCH HALL GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|---------------------|---------------|
| EASA.210.153 | 24/08/2004 | Passenger Seat Type: 3510B | 3510B()-2()Z() 3510B()-3()Z() 3510B()-4()Z() | C127a | 002/2004 |
| EASA.210.195 | 05/11/2004 | Passenger Seat Type: FF6510 | FF6510-1-() FF6510-2-() FF6510-3-() | C39b | 003/2004 |
| EASA.210.935 | 22/01/2008 | 3510G / 3510G-2 & 3510G-4 Seat Assembly | 3510G()-2()Z() 3510G()-4()Z() | C39b | 004/2007 |
| EASA.210.960 | 15/02/2008 | 3510E / 3510E-2 & 3510E-3 Seat Assembly | 3510E()-2()Z() 3510E()-3()Z() | C127a | 001/2008 |
| EASA.210.1122 | 06/10/2008 | 4420C Seat Assembly | 4420C()-2()Z() | C127a | 002/2008 |
| EASA.210.1213 | 26/02/2009 | 6510D Seat Assembly Forward Facing | 6510D()-2()Z() | C127a | 002/2009 |
| EASA.210.1220 | 26/03/2009 | 4420D Passenger Seat Assembly | 4420D()-2()Z() | C39b | 003/2009 |
| EASA.210.172, REV. A | 02/05/2005 | Passenger Seat 3510A | 3510A()-2()Z() 3510A()-3()Z() | C127a | 004/2004 |
| EASA.210.249, REV. A | 22/01/2008 | Passenger Seat Type 3510D | 3510D()-1()Z() 3510D()-2()Z() 3510D()-3()Z() 3510D()-4()Z() | C39b | 001/2004 |
| EASA.210.306, REV. A | 20/09/2005 | Passenger Seat Type 3510C | 3510C() - 2 () Z () 3510C() - 3 () Z () 3510C() - 4 () Z () | C127a | 001 |
| EASA.210.635, REV. A | 27/07/2007 | 3610A Forward Facing Passenger Seat | 3610A()-2()Z() 3610A()-3()Z() 3610A()-4()Z() 3610A()A2()Z() 3610A()A3()Z() 3610A()A4()Z() | C127a | 001/2006 |
| EASA.210.10028208 | 09/12/2009 | 3510H / 3510H-2 <(>&<> 3510H-3 Seat Assembly | 3510H()-2()Z() 3510H()-3()Z() | C127a | 008/2009 |
| EASA.210.10029206 | 12/03/2010 | 3520A / 3520A-2, 3520A-3, 3520A-4 Seat Assembly | 3520A()-2()Z() 3520A()-3()Z() 3520A()-4()Z() | C39b | 007/2009 |
| EASA.210.10032366 | 29/10/2010 | 3520E / 3520E()-3 Passenger Seat | 3520E()-3()Z() | C127a | 005/2010 |
| EASA.210.10032367 | 29/10/2010 | 3520D / 3520D()-2, 3520D()-3 Passenger Seat | 3520D()-2()Z() 3520D()-3()Z() | C127a | 004/2010 |
| EASA.210.10032421 | 04/11/2010 | Passenger Seat Premium Traveller Type PT4400 / PT4400-2-() | 412-2()Z()-() PT4400-1-() PT4400-2-() PT4400-3-() PT4400-4-() | JTSO-C127A Other | 001/2002 |
| EASA.210.10032562 | 17/11/2010 | Passenger Seat 4420G / 4420G-2 | 4420G()-2()Z() | C127a | 008/2010 |
| EASA.210.10033453 | 24/01/2011 | 6510E / 6510E-2, 6510E-3 Seat Assembly | 6510E()-2()Z() 6510E()-3()Z() | C127a | 009/2010 |
| EASA.210.10034750 | 28/04/2011 | 3520B Passenger Seat Assembly | 3520B()-2()Z() 3520B()-3()Z() 3520B()-4()Z() | C127a | 002/2010 |
| EASA.210.10034752 | 28/04/2011 | 3520C Passenger Seat Assembly | 3520C()-2()Z() 3520C()-3()Z() 3520C()-4()Z() | C127a | 003/2010 |
| EASA.210.10035256 | 09/06/2011 | 3620B Passenger Seat Assembly | 3620B()-2()Z() 3620B()-3()Z() 3620B()-4()Z() | C39c | 001/2011 |
| EASA.210.10037562 | 06/12/2011 | 3620C / 3620C-2, 3620C-3 Economy Class Passenger Seat | 3620C()-2()Z() 3620C()-3()Z() | C127a | 003/2011 |
| EASA.210.10039314 | 25/04/2012 | 5510A / 5510A-2, 5510A-3 Seat | 5510A()-2()Z() 5510A()-3()Z() | C127a | DDP004/2011 |
| EASA.210.10042703 | 13/12/2012 | 3510Q / 3510Q-2 & 3510Q-3 Passenger Seat | 3510Q()-2()Z() 3510Q()-3()Z() | C127a | DDP003/2012 |
| EASA.210.10043298 | 18/01/2013 | 5510B / 5510B-2 Seat Assembly | 5510B()-2()Z() | C39c | DDP004/2012 |

RECARO AIRCRAFT SEATING GmbH & Co. - DAIMLERSTRASSE 21 74523 SCHWAEBISCH HALL GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|---|------------------|-----------------------------------|
| EASA.210.10044118 | 19/03/2013 | 3520G / 3520G-2, 3520G-3 Seat Assembly | 3520G(-)2()Z() 3520G(-)3()Z() | C39c | DDP001/2013 |
| EASA.210.10047477 | 13/12/2013 | 3620D Economy Class Seat Assembly | 3620D()0()0()Z()0()0() | C127a | 002/2013 |
| EASA.210.10048202 | 20/02/2014 | 3001A Floatation Cushion Assembly | 3001A()0()0()0()0()0() | C72c | 005/2013 |
| EASA.210.10027728, REV. A | 30/04/2014 | 4420E Seat Assembly | 4420E()0()0()Z()0()0() | C127a | 006/2009 |
| EASA.210.10027761, REV. A | 29/11/2011 | 3620A / 3620A-2, 3620A-3 & 3620A-4 Seat Assembly | 3620A(-)2()Z() 3620A(-)3()Z() 3620A(-)4()Z() | C127a | 005/2009 |
| EASA.210.10028868, REV. A | 18/07/2012 | 3510K / 3510K-2, 3510K-3, 3510K-4 Passenger Seat Assembly | 3510K(-)2()Z() 3510K(-)3()Z() 3510K(-)4()Z() | C127a | 001/2010 |
| EASA.210.10039986, REV. A | 21/06/2012 | 4400B / 4400B-2 Seat Assembly | 4400B(-)2()Z() | C127a | 001/2012 |
| EASA.210.10041656, REV. A | 23/10/2012 | 3510N / 3510N-2 / 3510N-3 Seat Assembly | 3510N(-)2()Z(), 3510N(-)3()Z() | C127a | DDP002/2012 |
| EASA.210.10047274, REV. A | 16/12/2013 | 3520F Economy Class Seat Assembly | 3520F()0()0()Z()0()0() | C127a | 004/2013 |
| EASA.210.10049819, REV. A | 12/08/2014 | 3710A Economy Class Seat Assembly | 3710A()0()0()Z()0()0() | C127a | 003/2013 |
| EASA.210.10054881, REV. A | 06/11/2015 | 3530A // Economy Class Passenger Seat Assembly, Forward Faci | 3530A()0()0()Z()0()0() | C127a | DDP001/2015 |
| EASA.210.1048, REV. A | 24/11/2008 | BC4420B / BC4420B-2 Seat Assembly | 821(-)Z()(-) 834(-)Z()(-) | C39b | 003/2008 |
| EASA.210.1152, REV. C | 07/10/2009 | 6510 Seat Assembly Forward Facing | 659-2()Z()(-) 662-2()Z()(-) 663-2()Z()(-) 674-2()Z()(-) 674-3()Z()(-) | C127a | 004/2008 |
| EASA.210.1302, REV. A | 23/09/2009 | 3510J Front row seats | 3510J(-)2(-)Z(-) 3510J(-)3(-)Z(-) 3510J(-)4(-)Z(-) | C127a | DDP004/2009 |
| LBA 30.131/26 | 19/07/1999 | Passenger seat model 3410 Forward Facing Type A | 318-XXZXX() 3410-2(-) 3410-3(-) | C127a | Minor Change |
| LBA NO. 30.131/104 | 27/01/2015 | 3410 Economy Class Seat Assembly | 3410-1-1, 3410-2-1, 3410-3-1 3430-4-1 | C39b | DDP001/2009 |
| LBA NO. 30.131/129 | 27/01/2015 | 7410 Economy Class Seat Assembly | CVS(-) | C39b | GERÄTE- KENNBLATT 30.131/29 |
| LBA NO. 30.131/99 | 27/01/2015 | 3230 Economy Class Seat Assembly | 3230-1-1, 3230-2-1, 3230-3-1 3230-4-1 | C39b | DDP006/2010 |
| LBA.O.11.1111/1 JTSO | 03/07/2002 | Passenger Seat Type: BC 4420 | MODEL 4420-2(-) | | 002/2002 |
| LBA.O.11.111/3JTSO | 13/08/2003 | Passenger Seat Type BC4420B | MODEL BC4420B-2(-) MODEL BC4420B-3(-) | | 002/2003 |
| LBA.O.30.131/118 JTSO | 17/05/2000 | Passenger Seat Premium Traveller Type: 4400 | 4400-1(-) 4400-2(-) 4400-3(-) 4400-4(-) | C39b | 001/2000 |
| LBA.O.30.131/21JTSO | 26/04/2002 | Passenger Seat Type: 4420 | MODEL 4420-1(-) MODEL 4420-2(-) MODEL 4420-3(-) | | 001/2001 |

REGENT AEROSPACE CORPORATION - 28110 W. HARRISON PARKWAY 91355 VALENCIA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--------------------------------------|---------------|------------------|---------------|
| EASA.IM.210.757 | 07/08/2007 | Life Preserver / Single Cell | RSS-301(XX) | C13f | RSS301-01 |
| EASA.IM.210.1250 | 19/06/2009 | RSS-303 Life Preserver / Single Cell | RSS-303(XX) | C13f | RSS303 |
| EASA.IM.210.10027589 | 12/10/2009 | Life Preserver / Twin Cell | RSS-302(XX) | C13f | RSS303 |

ROCKWELL COLLINS FRANCE - P.O. BOX 20008 31701 BLAGNAC CEDEX FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|--|------------------|
| EASA.210.417 | 09/11/2005 | Display Control Panel Type DCP-255F | 597-2211-XXX | C10b C113 | CPN 222-2341-447 |
| EASA.210.1267 | 10/09/2010 | CTL-40xx Control Tune UnitP/N: 597-2359-0XX for CTL-4032 (CO | 597-2359-0XX FOR CTL-4032 597-2360-0XX FOR CTL-4062 597-2361-0XX FOR CTL-4092 597-2369-0XX FOR CTL-4000 | 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d 2C66b C74d 2C112b C113 | CPN 222-3038-241 |

ROCKWELL COLLINS, Inc. - 400 COLLINS ROAD N.E. 52498 CEDAR RAPIDS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---|---------------|----------------------------------|-----------------|
| EASA.210.042 | 26/05/2004 | ADF-4000 | 822-1470(-) | 2C41d | 523-0790046 |
| EASA.210.046 | 26/05/2004 | VIR-4000 | 822-1467(-) | 2C34f 2C35d 2C36f 2C40c | 523-0790046 |
| EASA.210.295 | 08/06/2005 | CTL 92E Series Transponder Control Head | 822-1807(-) | C74d 2C112a C119b | CPN 523-0806076 |

ROCKWELL COLLINS, Inc. - 400 COLLINS ROAD N.E. 52498 CEDAR RAPIDS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|---|---|---|---|
| EASA.IM.210.465 | 07/02/2006 | HFS-900D | 822-0990-() EXCL 822-0990-001, -002 & -003 | C31d C32d | 523-0805866 |
| EASA.IM.210.483 | 13/03/2006 | VHF-2100 | 822-1287-XXX | 2C37e 2C38e 2C128 | CPN 523-0807412 |
| EASA.IM.210.484 | 13/03/2006 | VHF-4000 | 822-1468-2XX 822-1468-3XX | 2C37e 2C38e 2C128 | 02-2A |
| EASA.IM.210.492 | 03/05/2006 | VHF-4000E | 822-1872-0XX 822-1872-1XX 822-1872-2XX 822-1872-3XX | 2C37e 2C38e 2C128 | CPN 523-0808027 |
| EASA.IM.210.530 | 04/07/2006 | ALT-1000 Radio Altimeter | 822-1939-XXX | 2C87 | 523-0808066 |
| EASA.IM.210.550 | 24/08/2006 | VHF-2100E | 822-2168-() | 2C37e 2C38e 2C128 | CPN 523-0808349 |
| EASA.IM.210.560 | 29/09/2006 | CTL-23D/23-G COMM/NAV Control unit | 822-2177-0XX 822-2178-0XX | 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C66b | CPN 523-0808013 |
| EASA.IM.210.718 | 29/05/2007 | Radio - Altimeter ALT - 4000 | 822-0615-XXX | TSO C87 Other | CPN 523-0801631 |
| EASA.IM.210.734 | 11/06/2007 | Nav Control CTL-32G | 822-2179-() | 2C34f 2C35d 2C36f 2C40c 2C66b | CPN 523-0807919 |
| EASA.IM.210.735 | 06/06/2007 | COM Control CTL-22D/CTL-22G | 822-2175-() 822-2176-() | 2C37e 2C38e | CPN 523-0807919 |
| EASA.IM.210.736 | 06/09/2007 | Global Positioning System GPS-4000S | 822-2189-(XXX) | C145 | CPN 523-0808933 |
| EASA.IM.210.737 | 31/05/2007 | CTL-93T TCAS Control | 822-2182-XXX | 2C112b C119b | CPN 523-0807972 |
| EASA.IM.210.754 | 11/06/2007 | ADF Control CTL-62G | 822-2180-() | 2C41d | CPN 523-0807919 |
| EASA.IM.210.755 | 11/06/2007 | ATC Control CTL-92G | 822-2181-() | C74d 2C112b | CPN 523-0807919 |
| EASA.IM.210.782 | 10/09/2007 | CPL-920D HF Antenna Coupler | 822-0987-(XXX) | C31d C32d | 523-0801643 |
| EASA.IM.210.932 | 11/02/2008 | DBU-5000 Data Base Unit | 822-2215-XXX | C113 | 523-0810199 |
| EASA.IM.210.933 | 26/05/2008 | DME-900 Distance Measuring Equipment | 822-0329-XXX | TSO C66A Other | 523-0807111 |
| EASA.210.280, REV. C | 11/05/2005 | TDR-94/-94D Mode-S Transponder | 622-9210-0XX 622-9210-1XX 622-9210-2XX 622-9210-3XX 622-9210-4XX FOR THE TDR-94D 622-9352-0XX 622-9352-1XX 622-9352-2XX 622-9352-3XX 622-9352-4XX FOR THE TDR-94 | 2C112b | 523-0805847 TDR-94, X8 TDR-94D |
| EASA.IM.210.1075 | 10/07/2008 | Global Landing Unit GLU-920 | 822-1152-XXX | 2C34f 2C36f C129a | CPN 523-0810307 |
| EASA.IM.210.493, REV. A | 22/04/2008 | GLU-925 | 822-1821-0XX 822-1821-1XX 822-1821-3XX 822-1821-4XX | 2C34f 2C36f C129a | 523-0807506 |
| EASA.IM.210.10036148 | 16/08/2011 | ADF-900 | 822-0299-021 | TSO C41D | ISSUE 10: 523-0805872 ISSUE 1: 523-0808717 |
| EASA.IM.210.10036153 | 16/08/2011 | VOR-900 | 822-0297-021 | FAA TSO C35D, C40C Other | 1: 523-0808716 8: 523-0807113 |
| EASA.IM.210.10036228 | 23/08/2011 | WRT-701X and WRT-701X FLW | EXCEPT 622-5132-6XX FOR WRT-70 FOR WRT-701X FOR WRT-701X FLW TSO C63B FOR P/N 622-5132-XXX TSO C63C FOR P/N 622-5132-6XX | FAA TSO C63B/C Other | 523-0790171 |
| EASA.IM.210.10036358 | 02/09/2011 | TTR-4000 Traffic Collision Avoidance Subsystem (TCAS) | 822-1294-X0X (JTSO C119B) 822-1294-X3X (ETSO C119C) | C119c JTSO C119B Other | 523-0790097 |
| EASA.IM.210.10036359 | 02/09/2011 | TTR-921 TCAS II Traffic Collision Avoidance Subsystem | 822-1293-X0X (JTSO C119B) 822-1293-X2X (JTSO C119B) 822-1293-X3X (ETSO C119C) | C119c JTSO C119B Other | 523-0790097 |
| EASA.IM.210.10036943 | 18/10/2011 | DME-2100 Radio Distance Measuring Equipment | 822-2325-XXX | 2C66b | 945-1556-001 |

| ROCKWELL COLLINS, Inc. - 400 COLLINS ROAD N.E. 52498 CEDAR RAPIDS USA | | | | | |
|--|--------------------|---|--|---------------------------------|-----------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.10038798 | 15/03/2012 | VHF-4000E/VHF Communications Transceiver | 822-1872-XXX EXCLUDING 822-1872-001 EXCLUDING 822-1872-101 EXCLUDING 822-1872-201 EXCLUDING 822-1872-301 | 2C128 2C169A | 523-0808027 |
| EASA.IM.210.10038802 | 15/03/2012 | VHF-4000F/VHF Communications Transceiver | 822-2993-XXX | 2C128 2C169A | 523-0819159 |
| EASA.IM.210.10038832 | 19/03/2012 | VHF-4000/VHF Communications Transceiver | 822-1468-XXX EXCLUDING 822-1468-001 EXCLUDING 822-1468-002 EXCLUDING 822-1468-101 EXCLUDING 822-1468-102 EXCLUDING 822-1468-201 EXCLUDING 822-1468-202 EXCLUDING 822-1468-301 EXCLUDING 822-1468-302 | 2C128 2C169A Other | 523-0790045 |
| EASA.IM.210.10046458 | 20/09/2013 | TTR-2100 Traffic Collision Avoidance System (TCAS) | 822-2911-XXX | C119c | 945-2056-001 |
| EASA.IM.210.10047790 | 24/01/2014 | LRA-900 Radio Altimeter<(>,<)> Low Range | 822-0334-52X | 2C87 | 945-6946-003 |
| EASA.IM.210.10048347 | 05/03/2014 | DFA-901 - ADF Antenna | 822-5404-003) 822-5404-XXX (EXCLUDING 822-5404-001 AND | 2C41d | 523-0805872 |
| EASA.IM.210.10049297 | 27/05/2014 | TTR-4100 TCAS Transmitter-Receiver | 822-3075-XXX | C119c | 946-4024-001 |
| EASA.IM.210.10050524 | 17/09/2014 | LRA-2100 Radio Altimeter | 822-2365-XXX | C87a | 945-6946-010 |
| EASA.IM.210.10051817 | 07/01/2015 | HFS-2200 High Frequency Receiver- TransmitterHFSS-2200 High F | 822-2764-XXX RCU410001000004 RCUY0001000XXX EXCLUDING | C158 C170 | 945-3546-02 |
| EASA.IM.210.10052593 | 16/03/2015 | TDR-94/94D ATC/Mode S Transponder | 622-9210-5XX (FOR TDR-94D) 622-9352-5XX (FOR TDR-94) | C112d C166b | TDR-94: RCPN 523-0805847 |
| EASA.IM.210.10036194, REV. A | 14/10/2013 | LRA-900 Radio Altimeter and RAA-700 Radio Altimeter Antenna | 622-8701-002 FOR RAA-700 822-0334-52X FOR LRA-900 822-0334-XXX EXCLUDING | FAA TSO C87 Other | 523-0806511 |
| EASA.IM.210.10040261, REV. A | 10/11/2015 | TSS-4100 and TSSA-4100 Traffic Surveillance Processing Unit | -002/-003 STATUS) 810-0052-XXX (EXCEPT -001/ 822-2132-XXX FOR TSS-4100 FOR TSSA-4100 | 2C112b C119c C166a | 523-0818273 |
| EASA.IM.210.10044649, REV.A | 13/02/2015 | RTA-4112 / RTA-4114 / RTA-4118 Weather Radar | 822-2254-(XXX) 822-2255-(XXX) 822-2256-(XXX) | 2C63c | 523-0818368 |
| LBA.N-O.10.911/108 JTSO | 05/12/2001 | VHF-920 Communications Transceiver | 822-1250-XXX | | 02-01A |
| LBA.N-O.10.911/112 JTSO | 18/10/2002 | VHF-4000 Transceiver | 822-1468-0(-),-1(-) | | 2-02A |
| LBA.N-O.10.916/025 JTSO | 21/01/2003 | GPS-4000A | 822-1377-(-) | | 01-00 |
| LBA.N-O.10.922/095 JTSO | 31/01/2003 | NAV-4500 | 822-1579-(-) | | 02-05A |
| LBA.N-O.10.925/034 JTSO | 18/10/2002 | DME-4000 | 822-1466-(-) | | 02-04A |
| LBA.N-O.10.930/067 JTSO | 04/12/2002 | TDR-94, TDR-94D Mode-S Transponder | 622-9210-007 622-9352-007 | | 06-90 ISSUE 9, 12-90 |
| LBA.N-O.10.930/071JTSO | 11/03/2003 | CTL-92E | 822-1807-001, -002, -003, -004 | | 1-03 |
| LBA.N-O.10.930/075JTSO | 13/06/2003 | TPR-901 | 822-1338-(-) | | |
| LBA.N-O.10.930/59 JTSO | 31/07/2000 | TPR-901 Mode S Transponder | 822-1338-001 822-1338-002 822-1338-020 | | 11-99A |
| LBA.N-O.10.952/072JTSO | 30/06/2003 | WXR-2100 | 622-5135-8() 622-5136-8() 822-1710() | | 03-8A |
| LBA.N-O.10.985/011 JTSO | 20/02/2003 | NAV-4000 | 822-1465-(-) | | 02-05A |
| ROEDER PRAEZISION GMBH - AM FLUGPLATZ 63329 EGELSBACH GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.999 | 17/02/2009 | RP08 Ballast Converter | 3320331-3717-(XX) | C141 | BC2DP332033 |
| ROHDE & SCHWARZ MESSGERAETEBAU GmbH - MUEHLDOERFSTRASSE 15 81671 MUENCHEN GERMANY | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| LBA.O.10.914/24 JTSO | 12/11/2002 | XK516D | 964-0452-(-) 964-0453-(-) 964-0459-(-) | JTSO-C31D JTSO-C32D Other | 6030.1203 I |
| SAFRAN POWER UK Ltd. - WESTFIELD ROAD LU7 9GT PITSTONE GREEN UNITED KINGDOM | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.053, REV. B | 27/01/2006 | 23080 Starter Generator Series | 23080-(-) | C56a | 1649 |
| EASA.210.054, REV. A | 28/07/2004 | 30V Brushless DC Generator | 30086-011 | C56a | 1627 |
| EASA.210.127, REV. A | 28/07/2004 | 30V DC Starter Generator | 23091-004 | C56a | 1633 |
| EASA.210.128, REV. B | 17/02/2006 | 23081-(XXX) 30V DC Starter Generator | 23081-(-) | C56a | 1650 |
| SAGEM DEFENSE SECURITE - 18-20 QUAI DU PONT DU JOUR 92100 BOULOGNE BILLANCOURT FRANCE | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.109 | 16/06/2004 | Parallel Servo Actuator 6256 | 6256-176-(-) | C9c | 8086-C07-DDP |
| EASA.210.233 | 14/01/2005 | Parallel Servo Actuator Model 6264 | 2-6264-151-(-) 4-6264-151-(-) 6264-162-(-) 6264-164-(-) | C9c | SEE P/N DESCRIPTION |

SAGEM DEFENSE SECURITE - 18-20 QUAI DU PONT DU JOUR 92100 BOULOGNE BILLANCOURT FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|--------------------------|-----------------------|
| EASA.21O.1049 | 16/06/2008 | Integrity Monitor Module (IMM2010) | 260522328-XXXX | C113 | 3300100571 |
| EASA.21O.629, REV. A | 21/04/2008 | Smart Electro Mechanical Actuator (SEMA) | 418-00876-(XXX) | C9c | 3300160726 |
| EASA.21O.10032535 | 12/11/2010 | Flux Valve (Magnetic Sensor Unit) | 261310206-01XX | C6d | 3300348393 R10 000 |
| EASA.21O.10035020 | 19/05/2011 | Aircraft Piloting Inertial Reference Sensor (APIRS) F207 | 261500123-050X 420-01867-2XX | C4c C5e C6e | 3300392323 |
| EASA.21O.10035484 | 27/06/2011 | Aircraft Piloting Inertial Reference Sensor (APIRS) F201 | 261500123-04XX 420-00339-0XX 420-01867-3XX | C4c C5e C6e | 3300378204 |
| EASA.21O.10053420 | 26/05/2015 | Aircraft Piloting Inertial Reference Sensor (APIRS) F207 | 261500123-250X 420-01867-2XX ATTITUDE HEADING REFERENCE REMOVABLE MEMORY MODULE (RMM) UNIT (AHRU) | C4c C5e C6e | 3300604038 |
| EASA.21O.10054452 | 17/09/2015 | Aircraft Piloting Inertial Reference Sensor (APIRS) F227 | 261500123-07XX (AHRU) 420-00346-0XX (AHCP) 420-01867-4XX (RMM) | C3d C4c C5e C6e | 3300611673 |
| ETSOA.21O.10052675 | 20/03/2015 | Aircraft Piloting Inertial Reference Sensor APIRS F201Magnet | | C4c C5e C6e | 3300590571 |
| F.O.009 | 04/02/2000 | APIRS | 420-00332-7(XX) 420-00346-0(XX) 420-01867-4(XX) | | |
| F.O.121 | 08/07/2003 | Linear and Parallel Servo Actuator | 1-8486-() 2-8486-() 3-8486-() 6256-150-()-() 6256-151-()-() 6256-161-()-() 6256-162-()-() 6256-163-()-() 6256-164-()-() 6256-166-()-() 6256-171-()-() 6256-173-()-() 8486-() | | (SEE REM) |

SANDEL AVIONICS, Inc. - 2401 DOGWOOD WAY 92081 VISTA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------|--------------------|---|-----------------|---|---------------|
| EASA.IM.21O.441 | 21/12/2005 | ST3400 TAWS/RMI | ST3400-XXX | C113 C151a | 82006-1126 |
| EASA.IM.21O.442 | 21/12/2005 | SN3500 EHSI | SN3500-XXX | C113 | 82005-1126 |
| EASA.IM.21O.644 | 07/05/2007 | SN4500 Primary Navigation Display | SN4500-XXX | C6d 2C34f 2C35d 2C36f 2C40c 2C41d C113 C118 C119b | 82009-1126 |
| EASA.IM.21O.788 | 21/01/2008 | SA4550 Primary Attitude Display | SA4550-(XXX) | C3d C4c 2C34f 2C36f C52b C113 | 82010-1126 |
| EASA.IM.21O.1275 | 15/09/2009 | SG102 Attitude Heading Reference System. | SG102-(XXX) | C4c C6d | 82011-1126 |
| EASA.IM.21O.1276 | 23/07/2009 | MT102 Attitude Heading Reference System | MT102-(XXX) | C6d | 82012-1126 |
| EASA.IM.21O.10050343 | 05/09/2014 | ST3400H Helicopter Terrain Awareness and Warning System | ST3400H-() | 2C87 C113 C118 C194 | 82046-1126 |
| LBA.N-O.10.986/01 JTSO | 25/01/2000 | SN3308 Navigation Display | SN3308()-XX-XX | | 82001-1126 |

SANDIA AEROSPACE CORPORATION - 3700 OSUNA ROAD NE, SUITE 711 87109 ALBUQUERQUE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|----------------------------|---|------------------|---------------|
| EASA.IM.21O.10028259 | 15/12/2009 | STP78 Oat Probe | 305561-() | C106 | 305950 |
| EASA.IM.21O.10028260 | 15/12/2009 | ST26 Tach-Gen Adapter | 305662-() | C49b | 305948 |
| EASA.IM.21O.10028261 | 14/12/2009 | SAE5-35 Altitude Encoder | 305154-00 | C88a | 305949 |
| EASA.IM.21O.10038142 | 23/01/2012 | ST 32 Interface Adapter | 305952-(XX) 306031-(XX) 306057-(XX) | C47a C49b | 306075 |
| EASA.IM.21O.10028262, REV. B | 22/05/2014 | SAC 7-35 Air Data Computer | 305548-XX WITH SW P/N 901001 VERSION 10 OR LATER | C88a C106 | 305951 |

SATCO, Inc. - 1601 EAST EL SEGUNDO BLVD. 90245 EL SEGUNDO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

SATCO, Inc. - 1601 EAST EL SEGUNDO BLVD. 90245 EL SEGUNDO USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|------------------------|------------------|---------------|
| EASA.IM.210.1251 | 08/06/2009 | Container Assembly - M1, Wide Door | 35200-511 35200-517 | C90c | 35200 |
| EASA.IM.210.10030738 | 05/07/2010 | Container Assembly - LD3, Standard | 34124-() | C90c | 34124 |
| EASA.IM.210.10031696 | 06/09/2010 | Container Assembly - M1, High Cube | 35444-() | C90c | 35444 |
| EASA.IM.210.10031754 | 09/09/2010 | Container Assembly - M1, High Cube | 36000 - () | C90c | 36000 |
| EASA.IM.210.10031895 | 20/09/2010 | Container Assembly - LD3, Inboard | 33675 - () | C90c | 33675 |
| EASA.IM.210.10033300 | 12/01/2011 | Container Assembly 37010 Series | 37010-(SERIES) | C90c | 37010 |
| EASA.IM.210.10038803 | 15/03/2012 | 35115-(Series) Container Assembly | 35115-(SERIES) | C90c | 35115 |
| EASA.IM.210.10038933 | 23/03/2012 | 35220-(SERIES) CONTAINER ASSEMBLY - LD9 | 35220-(SERIES) | C90c | DDP35220 |

SCHROTH SAFETY PRODUCTS GmbH - IM OHL 14 59757 ARNSBERG GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|--|--------------------|---------------|
| EASA.210.585 | 15/11/2006 | Model 3 High Mobility Restraint System | 3-()-() | C114 | 3/DDP |
| EASA.210.1214 | 10/02/2009 | 2-Point Lap Belt System 12-()-() | 12-()-() E/12-()-() | JT50-C22G Other | 12/DDP |
| EASA.210.1217 | 14/07/2009 | Model 26 Restraint Harness | 26-()-() | C114 | 26/DDP |
| EASA.210.10045727 | 15/07/2013 | Model 27-()-() Harness Restraint System | 27-()-() | C114 | 27/DDP |
| EASA.210.10051964 | 21/01/2015 | Model 5-()-(), Extension Belt ES5, EB5 // 3-point Restraint | EB5-02-() EXTENSION BELT P/N: ES5-02-() RESTRAINT SYSTEM P/N 5-()-() | C114 | 5/DDP |
| EASA.210.10053398 | 29/05/2015 | MODEL 29-()-() // Inflatable 3-point diagonal automatic rest | 29-()-() | C114 A1 | 29/DDP |
| EASA.210.10029419, REV. B | 23/04/2012 | Model 19 - 2 Point Lap, Extension and Y Belt | 19-()-(), E/19-()-() Y/19-()-() | C22g | 19/DDP |
| EASA.210.10047902, REV. A | 12/06/2015 | Restraint Model 28 and Extension belt Model E28 // Restraint | 28-()-() E28-()-() | C22g | 28-DDP |
| EASA.210.1101, REV. A | 23/04/2012 | Model 6 Safety Belt<(>,<)> Extension and Y Belt | 6-()-(), E/6-()-() Y/6-()-() | C22g | 6/DDP |
| I 531-40.073/10JT50 | 02/11/1993 | Flight Attendant Restraint System 1-()-() | 1-01-() 1-02-() 1-05-() 1-06-() 1-07-() 1-08-() 1-09-() 1-10-() 1-11-() 1-12-() | | |
| I 531-40.073/11JT50 | 16/05/1995 | 4 point Static Restraint System 4-()-() | 4-01-() 4-02-() 4-03-() 4-04-() | | |
| I 531-40.073/12JT50 | 19/05/1995 | 3 point Belt with Diagonal Shoulder Belt 5-()-() | 5-01-() 5-02-() | | |
| LBA.O.40.073/16 JT50 | 10/04/2001 | 3-Point-Diagonal-Belt Type: 7-()-() | 7-()-() | | 7/DDP |
| LBA.O.40.073/17 JT50 | 11/06/2001 | 4-Point Static Harness Restraint System 8-()-() | 8-()-() | | 8/DDP |
| LBA.O.40.073/18 JT50 | 04/07/2001 | 4-Point Harness Restraint System Type: 9-()-() | 9-()-() | | 9/DDP |
| LBA.O.40.073/19 JT50 | 26/07/2001 | 3-Point-Diagonal-Belt System Type: 10-()-() | 10-()-() | | 10/DDP |
| LBA.O.40.073/20 JT50 | 03/05/2002 | 4/5-Point-Harness-Restraint-System Type: 11-()-() | 11-()-() | | 11/DDP |
| LBA.O.40.073/21 JT50 | 20/11/2001 | 2-Point Lap Belt System Type: 14-()-() | 14-()-() | | 14/DDP |
| LBA.O.40.073/22 JT50 | 21/11/2001 | 4/5-Point Harness Restraint System Type: 15-()-() | 15-()-() | | 15/DDP |
| LBA.O.40.073/23JT50 | 26/03/2003 | 4/5-Point-Harness-Restraint-System Type: 23-()-() | 23-()-() | | 23/DDP |
| LBA.O.40.073/24JT50 | 26/03/2003 | 4/5-Point-Harness-Restraint-System Type: 22-()-() | 22-()-() | | 22/DDP |
| LBA.O.40.073/25JT50 | 26/03/2003 | 4/5-Point-Harness-Restraint-System Type: 21-()-() | 21-()-() | | 21/DDP |
| LBA.O.40.073/26JT50 | 26/03/2003 | 4/5-Point-Harness-Restraint-System Type 20-()-() | 20-()-() | | 20/DDP |
| LBA.O.40.073/29 JT50 | 31/01/2002 | 4-Point-Harness-Restraint-System Type: 18-()-() | 18-()-() | | 18/DDP |
| LBA.O.40.073/30JT50 | 09/01/2003 | 3-Point-Diagonal-Static-Belt-System Type: 24-()-() | 24-()-() | | 24/DDP |
| LBA.O.40.073/31JT50 | 09/01/2003 | 3-Point-Diagonal-Belt-System Type: 25-()-() | 25-()-() | | 25/DDP |

SELEX ES S.p.A. - PIAZZA MONTE GRAPPA 4 00195 ROMA (RM) ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---------------------------|--|------------------|---------------|
| EASA.210.342, REV. A | 10/11/2006 | Transceiver SRT 651/N-GDF | CP 9000-GDF: E3959.1100 MT-1138 : 3-91864.0000//A RT-651:E6826.0000, RAC-0737/01 | 2C37e 2C38e | 5048 |

SELL GmbH - DR.-SIEGFRIED-STRASSE 35745 HERBORN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|--|------------------|---------------------|
| EASA.210.10053245 | 07/05/2015 | 940 series Water Boiler and 960 series Rail | 940()-()-()-0000-()-() 960()-()-()-0000-()-() | C184 | DDP-940X-XX-0000-XX |
| EASA.210.10053934 | 06/07/2015 | Steam/Convection Oven | 830()-()-()-0000-()-() | C184 | DDP-830X-XX-0000-XX |

SELL GmbH - DR.-SIEGFRIED-STRASSE 35745 HERBORN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|--|------------------|---------------------|
| EASA.210.10054436 | 14/08/2015 | 900 series Coffee Maker and 920 series Beverage Maker | 900(-)(-)-0000-(-) 920(-)(-)-0000-(-) | C184 | DDP-9X0X-XX-0000-XX |
| EASA.210.10055276 | 28/10/2015 | Bun Warmer | 893(-)(-)-0000-(-) | C184 | DDP-893X-XX-0000-XX |

SENNHEISER ELECTRONIC GmbH & Co. KG - AM LABOR 1 30900 WEDEMARK GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|---------------|
| EASA.210.516 | 02/06/2006 | Headphones HDC 55-26-LHBC with active noise compensation | HDC055- () | C57a | 0155 |
| EASA.210.594 | 27/11/2006 | HME 46 Headset | 046-55- () 999- () | C57a C58a | 0146 |
| EASA.210.595 | 27/11/2006 | HD 46 Headphone | 046-69- () -999- () | C57a | 0246 |
| EASA.210.694 | 04/04/2007 | HMEC 46 Headsets and Headphones | 046-35- () HEADSETS AND HEADPH -999- () CABLE FOR HEADSETS AN | C57a C58a | 0346 |
| EASA.210.1035 | 16/03/2009 | HMEC 26 Headsets | 026-35- () | C57a C58a | 0226 |
| EASA.210.1036 | 19/12/2008 | HME 26 Headsets | 026-55- () | C57a C58a | 0126 |
| EASA.210.1281 | 07/07/2009 | HMEC 26-T Headsets | 026-C5- () | C57a C58a | 0326 |
| EASA.210.10042453 | 03/12/2012 | HMEC 26-2 Aviation Headset | 026- ()-2- () | C139 | 0226 |
| EASA.210.10050481 | 15/09/2014 | HME 26-2 Aviation Headset | 026-55-2- () | C139 | 0526 |
| LBA.O.10.919/17 JTSO | 08/12/1999 | Microphone MKE 45 and MKE 45-1 | 045-305-(XXX) | | 1245 |
| LBA.O.10.919/19 JTSO | 15/12/2000 | Headsets Series 100 | 100-251- () | | 0110 |
| LBA.O.10.919/20 JTSO | 16/01/2001 | Headsets Series 300 | 300-231- () | | 0130 |
| LBA.O.10.919/8 JTSO | 06/01/2000 | Headset Serie 25 | 025-230-(XXX) | | 1025 |
| LBA.O.10.919/9 JTSO | 15/06/1999 | Head Sets and Speakers, Microphones Serie 45 | 045-250-025 | | XX45 |

SENSOR SYSTEMS, Inc. - 8929 FULLBRIGHT AVENUE 91311 CHATSWORTH USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-----------------------------------|----------------|------------------|--------------------|
| EASA.IM.210.1168 | 16/02/2009 | Low Range Radio Altimeter Antenna | S67-2002-[18] | 2C87 | SSIDDP-S67-2002-18 |
| EASA.IM.210.1169 | 25/05/2009 | ELT Antenna | S65-8282-406 | 2C91a 2C126 | 8282-406 |
| EASA.IM.210.1170 | 16/02/2009 | Marker Beacon Antenna | S35-1000-(XXX) | 2C35d | SSIDDP-S35-1000 |
| EASA.IM.210.1181 | 25/08/2009 | Dual Glide Slope Antenna | 41422-(XXX) | 2C34f | SSIDDP-41422 |
| EASA.IM.210.1182 | 01/12/2009 | Dual Localizer Antenna | S65-147-(X) | 2C36f | SSIDDP-S65-147-7 |
| EASA.IM.210.1183 | 27/05/2009 | ADF Receiving Antenna | S72-1712-(XX) | 2C41d | SSIDDP72-1712 |
| EASA.IM.210.10046410 | 19/09/2013 | Low Range Radio Altimeter Antenna | S67-2002-28 | C87a | SSIDDP-S67-2002-28 |

SHADIN, L.P. D/B/A SHADIN AVIONICS - 100 SOUTH 5TH STREET 1075 55402 MINNEAPOLIS USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|-------------|--|------------------|---------------|
| EASA.IM.210.10054663 | 04/09/2015 | AIS-360 | 833615- () // ARINC AND DISCRET I/O ADAPTER | C55a | SD-150043 |

SIEMENS SAS - 40 AVENUE DES FRUITIERS 93527 SAINT DENIS FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------|--------------------|--|---|------------------|--------------------------------|
| EASA.210.294 | 02/06/2005 | Optical Smoke Detector | PPC11()-() PPC12()-() | C1c | PPC1100-00TSO AND PPC1200-00-T |
| EASA.210.437 | 21/12/2005 | Optical Smoke Detector - Ambient smoke detector | PMC11()-() | C1c | PMC110101 |
| EASA.210.438 | 20/12/2005 | Optical smoke detector - Duct smoke detector | GMC11()-() | C1c | GMC110101 |
| ETSOA.210.10054627 | 03/09/2015 | Ambient Smoke DetectorDDP PMC3101-01_rev4, dated 07 July 201 | PMC31()-() | C1c | PMC3101-01_REV4 |
| F.O.014 | 03/07/2000 | Photoelectrical Smoke Detector | CGAB20 (XX)-(XX) CGDU20 (XX)-(XX) CGDU22(XX)-(XX) | | |
| F.O.091 | 16/10/2002 | Optical smoke detector | CGFT21(XX)-(XX) | | CGFT 2100-00 |
| F.O.104 | 06/02/2003 | Optical smoke detector | CGFT23(XX)-(XX) | | CGFT2300-00 |

SIGMA TEK, Inc. - 1001 INDUSTRIAL ROAD 67010 AUGUSTA USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------|--------------------|--|----------------|--|---------------|
| EASA.210.145, REV. A | 06/01/2005 | VHF COMM/NAV/ADF Radio Control Panel 1U661 | 1U661- ()-() | 2C34f 2C37e 2C38e 2C40c 2C41d 2C66b | 87R042 |
| LBA.N-O.10.929/15 JTSO | 08/03/2000 | Radio Control Panel 1U619-001 | 1U619-001 | | 87R036 |

SIRIO PANEL S.p.A. - LOCALITA' LEVANELLA BECORPI 52025 MONTEVARCHI ITALY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|------------------------------|---------------|------------------|----------------|
| EASA.210.10041196 | 29/08/2012 | 727-1208 Anticollision Light | 727-1208(XX) | C96a | 6WD-NE000857-E |
| EASA.210.10041197 | 29/08/2012 | 727-1209 Position Lights | 727-1209(XX) | C30c | 6WD-NE001009-E |

SIRS NAVIGATION Ltd. - WROTHAM ROAD DA13 0QB MEOPHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

SIRS NAVIGATION Ltd. - WROTHAM ROAD DA13 0QB MEOPHAM UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|---------------------------------|------------------|-----------------------------------|
| EASA.210.539 | 17/07/2006 | PG2CL-28V, Direct Reading Magnetic Compass | PG2CL-28V | C7d | PG2-003-DDP |
| EASA.210.1121 | 02/12/2008 | PGA Magnetic Standby Compass | PGA () | C7d | PG2-001-DDP ISSUE 5, PG2-004-D |
| EASA.210.1008, REV. A | 06/09/2011 | KCA Magnetic Standby Compass | KCA (), 1007KCA1 WL1001KCA1 | C7d | KHI-5002-DDP |

SMS TRADING AS COBHAM AVIONICS - 174-178 QUAI DE JEMMAPES 75010 PARIS FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|-----------------------------------|-----------------------------|--|---------------|
| EASA.210.10038109 | 03/02/2012 | Radio Altimeter Indicator IND 201 | 102-2100 102-2100-(X)(X) | 2C87 FOR P/N 102-2100-(X)(X) & JTSO2C87 FOR P/ N 102-2100 Other | 805-0034 |
| F.O.002 | 11/06/1999 | Stand-by Control Panel | 10(X)-1(X)90 | JTSO-2C37E JTSO-2C38E Other | |

SPEKON SAECHSISCHE SPEZIALKONFEKTION GmbH - NORDSTRASSE 40 02782 SEIFHENNERSDORF GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|------------------------------------|------------------------------|------------------|-------------------------|
| EASA.210.668 | 14/03/2007 | SE-5 L Emergency Parachute | 50-769/01-() | C23d | 50-769/01 |
| LBA.11.400/2 TS, REV. 2 | 16/07/1999 | Seat Container | 50-616/01:00 50-616/02:00 | | |
| LBA.O.40.010/89 JTSO | 02/01/2001 | Emergency Parachute Type:RE-5L-() | RE-5-L-() | | LBA.O. 40.010/89JTSO |

STELIA AEROSPACE - ZONE INDUSTRIELLE DE L'ANCIEN ARSEN 17300 ROCHEFORT FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|------------------|------------------------|
| EASA.210.255 | 10/03/2005 | Model FFCL4 Double Passenger Seat | FFCL4-(XXXXXX)-(XX) | C127a | 466 |
| EASA.210.256 | 10/03/2005 | Model FFCL5 Single Passenger Seat | FFCL5-(XXXXXX)-(XX) | C127a | 465 |
| EASA.210.284 | 31/05/2005 | Type A Passenger Seat, Model FJBP5 | FJBP5-(XXXX2X)-(XX) | C127a | 458 |
| EASA.210.320 | 22/07/2005 | Model FFCL4 Double Passenger Seat | FFCL4-(XXXXXX)-(XX) | C39b | 502 |
| EASA.210.321 | 22/07/2005 | Model FFCL5 Single Passenger Seat | FFCL5-(XXXXXX)-(XX) | C39b | 501 |
| EASA.210.323 | 11/08/2005 | Pearl Seat FJPL | FJPL1-(XXXXXX)-(XX) | C127a | 464 |
| EASA.210.387 | 27/10/2005 | A380 Type A Double Passenger Seat Model FFCL6 | FFCL6-(XXXXXX)-(XX) | C127a | 509 |
| EASA.210.388 | 27/10/2005 | A380 Type A Single Passenger Seat Model FFCL7 | FFCL7-(XXXXXX)-(XX) | C127a | 510 |
| EASA.210.418 | 10/11/2005 | Passenger Seat Model FJBP6 | FJBP6-(XXXX2X)-(XX) | C127a | 511 |
| EASA.210.897 | 02/08/2011 | Left/Right Pilot and 3rd Crewmember Seats, Type I | TAAI7-(XXXXXX)-(XX) | C39b | 632 |
| EASA.210.926 | 08/09/2008 | Business Class, Double Passenger Seat EVOLYS II | FJEV3-(XXXX2X)-(XX) FJEV3-(XXXX3X)-(XX) | C127a | 579 |
| EASA.210.959 | 04/10/2012 | Fourth Occupant Seat A400M | NPAI1-(XXXXXX)-(XX) | C39b | 636 |
| EASA.210.1039 | 17/11/2010 | FJEV1 Double Passenger Seat EVOLYS II | FJEV1-(XXXX2X)-(XX) FJEV1-(XXXX3X)-(XX) | C39b | 595 |
| EASA.210.1040 | 17/11/2010 | FJEV2 Triple Passenger Seat EVOLYS II | FJEV2-(XXXX2X)-(XX) | C39b | 596 |
| EASA.210.1129 | 13/03/2009 | First Class, Single Passenger Seat Class 180 | FFCL8-(XXXXXX)-(XX) | C39b | 601 |
| EASA.210.1253 | 11/01/2010 | Business Class, Single Passenger Seat SOLSTYS | FJSL1-(XXX5XX)-(XX) FJSL1-(XXX6XX)-(XX) FJSL1-(XXX7XX)-(XX) FJSL1-(XXX8XX)-(XX) | C127a | 599 |
| EASA.210.205, REV. A | 15/03/2005 | Airbus A380 Crew Seat Model TAAI4 | TAAI4-00IM () - () TAAI4-04PE () - () | C127a | SEE P/N DESCRIPTION |
| EASA.210.526, REV. A | 26/02/2007 | FJEV1 Double Passenger Seat EVOLYS | FJEV1-(XXXX2X)-(XX) FJEV1-(XXXX3X)-(XX) | C127a | 533 |
| EASA.210.527, REV. A | 26/02/2007 | FJEV2 Triple Passenger Seat EVOLYS | FJEV2-(XXXX2X)-(XX) | C127a | 529 |
| EASA.210.10029218 | 12/03/2010 | Single Passenger Seat SOLSTYS | FJSL3-(XXX5XX)-(XX) FJSL3-(XXX6XX)-(XX) FJSL3-(XXX7XX)-(XX) FJSL3-(XXX8XX)-(XX) | C127a | 616 |
| EASA.210.10034701 | 20/04/2011 | Business Class Single Passenger Seat Solstys | FJSL5-(XXX5XX)-(XX) FJSL5-(XXX6XX)-(XX) FJSL5-(XXX7XX)-(XX) FJSL5-(XXX8XX)-(XX) | C127a | 630 |
| EASA.210.10035982 | 03/08/2011 | First Class Single Passenger Seat Ultimate 17 | FFUL1-(XXXXXX)-(XX) | C127a | 609 |
| EASA.210.10039086 | 04/04/2012 | First Class Single Passenger Seat Ultimate 17 | FFUL2-(XXXXXX)-(XX) | C127a | 648 |
| EASA.210.10041708 | 10/10/2012 | Business Class Single Passenger Seat Solstys | FJSL2-(XXX5XX)-(XX) FJSL2-(XXX6XX)-(XX) FJSL2-(XXX7XX)-(XX) FJSL2-(XXX8XX)-(XX) | C127a | 607 |
| EASA.210.10045840 | 23/07/2013 | Single Passenger Seat SOLSTYS | FJSL7-(XXX5XX)-(XX) FJSL7-(XXX6XX)-(XX) FJSL7-(XXX7XX)-(XX) FJSL7-(XXX8XX)-(XX) | C127a | 679 |

STELIA AEROSPACE - ZONE INDUSTRIELLE DE L'ANCIEN ARSEN 17300 ROCHEFORT FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------|--------------------|--|--|------------------|---------------|
| EASA.210.10047726 | 15/01/2014 | B/C Single Passenger Seat SOLSTYS | FJSL4-(XXX5XX)-(XX) FJSL4-(XXX6XX)-(XX) FJSL4-(XXX7XX)-(XX) FJSL4-(XXX8XX)-(XX) | C127a | 625 |
| EASA.210.10049317 | 28/05/2014 | Business Class Double Passenger Seat EQUINOX 3D | FJEQ3-(XXX5XX)-(XX) FJEQ3-(XXX6XX)-(XX) FJEQ3-(XXX7XX)-(XX) | C127a | 673 |
| EASA.210.10049717 | 02/07/2014 | Business Class, Double Passenger Seat EQUINOX@ 3D, Type A / | FJEQ4-(XXXXXX)-(XX) | C127a | 704 |
| EASA.210.10050015 | 25/07/2014 | Business Class Double Passenger Seat EQUINOX 2D | FJEQ1-(XXX5XX)-(XX) FJEQ1-(XXX6XX)-(XX) FJEQ1-(XXX7XX)-(XX) | C127a | 664 |
| EASA.210.10050068 | 30/07/2014 | Business Class Triple Passenger Seat EQUINOX 2D | FJEQ2-(XXX7XX)-(XX) | C127a | 665 |
| EASA.210.10050188 | 11/08/2014 | TAAI8 Crew Seating System | TAAI8-(XXXXXX)-(XX) | C127a | 600 |
| EASA.210.10050679 | 30/09/2014 | Business Class, Double Passenger Seat Equinox@ 2D, Type A / | FJEQ6-(XXXXXX)-(XX) | C39c | 708 |
| EASA.210.10051056 | 05/11/2014 | Business Class, Double Passenger Seat DOVETAIL@ Forward and | FJDT2-(XXX5XX)-(XX) FJDT2-(XXX6XX)-(XX) FJDT2-(XXX7XX)-(XX) FJDT2-(XXX8XX)-(XX) | C127a | 643 |
| EASA.210.10052234 | 11/02/2015 | Business Class, Single Passenger Seat DOVETAIL@ Forward faci | FJDT1-(XXX5XX)-(XX) FJDT1-(XXX6XX)-(XX) FJDT1-(XXX7XX)-(XX) FJDT1-(XXX8XX)-(XX) | C127a | 642 |
| EASA.210.10052235 | 11/02/2015 | Business Class, Single Passenger Seat DOVETAIL@ Aft facing T | FJDT3-(XXX5XX)-(XX) FJDT3-(XXX6XX)-(XX) FJDT3-(XXX7XX)-(XX) FJDT3-(XXX8XX)-(XX) | C127a | 644 |
| ETSOA.210.10054295 | 04/08/2015 | FJEQ7 // B/C seat Equinox@ 2D double passenger seat | FJEQ7-(XXX5XX)-(XX) FJEQ7-(XXX6XX)-(XX) FJEQ7-(XXX7XX)-(XX) | C127a | 709 |
| ETSOA.210.10055164 | 16/10/2015 | EQUINOX B/C SeatsP/N | FJEQ10(XXX5XX)-(XX) FJEQ10(XXX6XX)-(XX) FJEQ10(XXX7XX)-(XX) | C127a | 712 |
| F.O.048 | 31/05/2001 | Bi-place passenger seat | FJBP2-(XXXXXX)-(XX) | | |

SURVITEC GROUP Ltd. - 1-5 BEAUFORT ROAD CH41 1HQ BIRKENHEAD, MERSEYSIDE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|---------------------------------|--|--|---------------|
| EASA.210.609 | 15/12/2006 | 10R MK1 Liferaft | 00051001 00051003 00051004 00051017 00051018 00051019 00051020 00051024 00051026 00051040 00051041 00051061 00051062 00051072 00051073 00051213 00051214 00051288 | | 126 AND 142 |
| EASA.210.799 | 07/08/2007 | Lifejacket Type 102 Mk3 and Mk4 | 00002291 00002292 00002333 000024() () 000025() () | C13f | 154 |
| EASA.210.1176 | 25/02/2009 | Life Raft Aerolite-4F(MK*) | 43425(XXX) W PACKING ASSEMBLY 00033(XXX) | TSO C70A CAA UK SPEC 2 Other | 148 |
| EASA.210.1219 | 25/02/2009 | Heliraft F14R (MK*) | 42572(XXX) W PACKING ASSEMBLY 00051(XXX) | TSO C70A CAA UK SPEC 2 Other | 143 |
| EASA.210.1238 | 23/06/2009 | 90211 Immersion Suit | 90211 91311 91711 | CAA UK SPEC 19 CAA UK SPEC 5 Other | SS/DDP003/93 |
| EASA.210.1239 | 25/06/2009 | 90304 Lifejacket Mk. 1 | 90304 | CAA UK SPEC 5 Other | SS/DDP002/91 |
| EASA.210.1240 | 25/06/2009 | 96202 Lifejacket | 91009A 91009M 96202() | CAA UK SPEC 5 Other | SS/DDP008/02 |

SURVITEC GROUP Ltd. - 1-5 BEAUFORT ROAD CH41 1HQ BIRKENHEAD, MERSEYSIDE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|--|--|---|-----------------------------------|
| EASA.210.1241 | 25/06/2009 | 93204 Helicopter Passenger Suit | 91003 91007/2A 91007/2M 93204 93205 96301 B28 B48 SURV0638 | CAA UK SPEC 19 Other | 006/99 009/02 SS/DDP 004/95 |
| EASA.210.610, REV. B | 02/02/2009 | Liferaft Model: F10R(MK*), F9R(MK*), F8R (MK*) | LIFERAFT F10R(MK*) P/N:42571() LIFERAFT F8R(MK*) P/N 42909() LIFERAFT F9R(MK*) P/N:42910() PACKING ASSEMBLY P/N:00051() | TSO C70A CAA UK SPEC 2 Other | 142 |
| EASA.210.10031407 | 16/08/2010 | Life Raft Model: F10R MK3 | 00098(XXX) 45457(XXX) | 2C505 | 160 |
| EASA.210.10038243 | 31/01/2012 | Aerolite 10 Life Raft | 00026(XXX) LIFE RAFT 02009(XXX) LIFE RAFT WITH 45484(XXX) LIFE RAFT WITH FURLABLE CANOPY STANDARD CANOPY STOWAGE PACK | TSO C70A CAA UK SPECIFICATIONS NO. 2 Other | 73 |
| EASA.210.10038805 | 15/03/2012 | Heliraft F11R | 00051(XXX) STOWAGE PACK 45495(XXX) LIFE RAFT | TSO C70A Other | 158 |
| EASA.210.10040264 | 21/06/2012 | Heliraft 18R(MK*) | 00051(XXX) PACKING ASSEMBLY 39997(XXX) LIFE RAFT 18R(MK1) 41971(XXX) LIFE RAFT 18R(MK3) | CAA UK SPEC. 2 Other | 127 |
| EASA.210.10040894 | 02/08/2012 | Life Raft Type F12R Mk(*) | LIFE RAFT 50516(XXX) PACKING ASSEMBLY 00098(XXX) | 2C70a 2C505 | 161 |
| EASA.210.10042577 | 16/06/2014 | Life Raft Type: Aerolite 46 (46RA MK.1) | 00033048, 00033050, 00033052 00033054, 00033056, 00033057 00033061, 00033062, 00033063 00033088, 00033089 | ISSUE 2 AND FAA TSO C70A CAA UK SPECIFICATION NO. 2 Other | 138 |
| EASA.210.10045605 | 05/07/2013 | Life Raft Type F14R MK(***) | LIFE RAFT P/N 45428(XXX) PACKING ASSEMBLY P/N 00098(XXX) | 2C70a 2C505 | 162 |
| EASA.210.10046662 | 09/10/2013 | Reversible Liferaft Model F7R - Heliraft (also designed as F | 00051(XXX) PACKED ASSEMBLY 42570(XXX) LIFERAFT F7R 42907(XXX) LIFERAFT F5R 42908(XXX) LIFERAFT F6R | 2C70a | 141 |
| EASA.210.10049787 | 08/07/2014 | Mk50 Single and Double Chamber Helicopter Passenger Flight j | A393200A(**) A393300A(**) | C13f 2C504 | 188 |
| EASA.210.10054520 | 27/08/2015 | AEROLITE 33F // 33 Person Inflatable LiferaftP/N 43223(xxx) | | FAA-TSO-C70A CAA UK SPEC. NO.2 AND Other | 147 |
| E11638 | 23/07/2004 | Adult & Child Lifejacket Mk 20 | A312300A(XX) A312300A(XX) RFD A312305A(XX) RFD A312306A(XX) RFD | | 172 |
| E12230 | 19/05/2004 | Infant Inflatable Lifejacket Mk22 | A316100A(XX) A316100A(XX)RFD A316101A(XX)RFD A316102A(XX)RFD | | |
| E15841 | 06/06/2002 | Lifejacket Type 105 Mk1 | 000026(XX) 2293 | TSO C13F Other 2C70b 2C505 | 155 163 |
| EASA.210.1237, REV. A | 16/07/2014 | 93204 Helicopter Passenger Suit | 430-AP, 430-APP, 459-AP 459-APP, 93204() | CAA UK SPEC 19 Other | SS/DDP009/02 |

SURVIVAL ONE LTD - SURVITEC HOUSE, KIRKTON DRIVE AB21 0BG DYCE, ABERDEEN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|---|-----------------------|---|---------------|
| EASA.210.10042581 | 02/07/2014 | Type 500 Immersion Suit | 50(X)(XX)(XXX) | CAA UK SPECIFICATION NO. 19 Other | Never accept |
| EASA.210.1072, REV. B | 01/07/2015 | 1000-Series Immersion Suit // Helicopter Occupant Immersion | 100(X) (XXX) (XX) (X) | 2C503 | 1000 |

SWITLIK PARACHUTE COMPANY Inc. - 1325 EAST STATE STREET 08609 TRENTON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--------------------------------|----------------------------|-------------------------|-----------------|
| EASA.IM.210.10048026 | 31/03/2014 | Life preserver/AV-100, H Style | S-411XX-() | CAA/UK SPEC. 5 Other | DDP-AV-100(H) |
| EASA.IM.210.10049965 | 22/07/2014 | LIFE JACKET / HV-35E | S-9430-() | 2C504 | DDP-HV-35E |
| EASA.IM.210.10055230 | 23/10/2015 | Life Jacket, Model HV-35C | S-7200-54() S-7200-55() | 2C504 | DDP-HV-35C-ETSO |

TAIWAN FYLIN INDUSTRIAL Co., Ltd. - CENTRAL TAIWAN SCIENCE PARK 40763 TAICHUNG TAIWAN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|----------------------|---------------|------------------|---------------|
| EASA.IM.210.10052550 | 10/03/2015 | 01S // AKE Container | 01S0000-() | C90d | 01S0000-() |
| EASA.IM.210.10054741 | 14/09/2015 | 27A // PGA Pallet | 27A0000-() | C90d | 27A0000-() |

TAIWAN FYLIN INDUSTRIAL Co., Ltd. - CENTRAL TAIWAN SCIENCE PARK 40763 TAICHUNG TAIWAN

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|-------------------|---------------|------------------|---------------|
| EASA.IM.210.10052017, REV. A | 25/03/2015 | 26A // PRA Pallet | 26A0000-() | C90d | 26A0000-() |

TBONE AVIATION A/S - YDERLANDSVEJ 23 2300 COPENHAGEN DENMARK

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--------------------------------|---|------------------|---------------|
| EASA.210.1071 | 19/02/2009 | tbone aviation headset / Basic | 258260-[] TBONE AVIATION HEAD 258261-[] EARPIECE ASSY 258265-[] AMPLIFIER 258269-[] INTERCOM CABLE | C57a C58a | 301787-DN |

TEAM t/a COBHAM AVIONICS - SILIC - BP 20191 94563 RUNGIS CEDEX FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|---|------------------------------------|--|-----------------|
| EASA.210.019 | 19/05/2004 | Audio & Radio Control Display Unit Model CDU 4057 | CDU4057(XX)(XX) | C31d 2C34f 2C35d 2C36f 2C37e 2C38e 2C40c 2C41d C50c 2C66b C74d 2C112a C113 | 67.0425.12.99 |
| EASA.210.020 | 19/05/2004 | Audio Management Unit Model AMU 4056 | AMU 4056 (XX) (XX) | C50c | 67.0585.11.00 |
| EASA.210.1195 | 03/12/2009 | ACP Audio Control Panel | ACP3000(XX)(YY) | C50c | 67.3041.10.09 A |
| EASA.210.1196 | 09/12/2009 | AMU Audio Management Unit | AMU4242(XX)(XX) | C50c | 67.3056.10.09 |
| 53351 SFACT/N | 06/04/1993 | # | CP1600(XX)(XX) | QAC 51 Other | |
| 53569 SFACT/TC | 10/06/1985 | CP2426 AUDIO CONTROL PANEL | CP2426(XX) | QAC 51 Other | |
| 53570 SFACT/TC | 10/06/1985 | CP2425 AUDIO CONTROL PANEL | CP2425(XX) | QAC 51 Other | |
| 54092 SFACT/N | 08/10/1993 | SC2253 SELECTIVE CALLING UNIT | SC2253AD(XX) SC2253(XX) | QAC 12 Other | |
| 940055 SFACT/N | 05/01/1994 | ACP2531, PA2532 AUDIO CONTROL PANEL | ACP2531(XX)(XX) PA2532(XX)(XX) | QAC 51 Other | |
| 940073 SFACT/N | 07/01/1994 | CAU2533, CAU2583 AUDIO MANAGEMENT UNIT | CAU2533(XX)(XX) CAU2583(XX)(XX) | QAC 51 Other | |
| 953130 SFACT/N | 02/06/1997 | AP71(xx)1(xxx) SSCVR | AP71(XX)1(XXX) | QAC 58 Other | |
| 973200 SFACT/N | 02/06/1997 | AP71(xx)3(xxx) SSCVR | AP71(XX)3(XXX) | QAC 58 Other | |
| 973201 SFACT/N | 02/06/1997 | AP71(xx)2(xxx) SSCVR | AP71(XX)2(XXX) | QAC 58 Other | |
| 990447 SFACT/N | 20/01/1999 | SL3924(xx)(xx) Selective Calling Unit | SL3924(XX)(XX) | QAC 12 Other | |
| 990451 SFACT/N | 20/01/1999 | PA4028(xx)(xx) Passenger Address Amplifier | PA4028(XX)(XX) | QAC 51 Other | |
| EASA.210.1085, REV. A | 13/06/2012 | ARCDU Audio and Radio Control Display Unit | CDU2500(XX)(XX) CDU3000(XX)(XX) | C113 | 67.3030.09.09 |

TECHNIFY MOTORS GmbH - PLATANENSTRASSE 14 09356 ST. EGIDIEN GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---------------------|----------------------|-----------------------------|---------------|
| EASA.210.059, REV. B | 20/08/2013 | TAE-AED-125 | 02-7730-5503-()-() | C43c C44b C55 C113 | DDP-02-01 |
| EASA.210.060, REV. B | 20/08/2013 | TAE-AED-125-SR1 | 02-7730-5504-()-() | C43c C44b C113 | DDP-02-01 |
| EASA.210.061, REV. A | 20/08/2013 | TAE-AED-125-SR2 | 30-7730-5503-()-() | C43c C44b C113 | DDP-02-01 |
| EASA.210.10046132 | 20/08/2013 | Display TAE-CED-125 | 02-7730-5501-()-() | JT50 C113 Other | 01-01 |

TELEPHONICS CORPORATION - 815 BROAD HOLLOW ROAD 11735 FARMINGDALE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|---------------|------------------|---------------|
| EASA.210.138 | 20/07/2004 | Weather Radar RT-1601 Receiver Transmitter | 379-2011-001 | 2C63c C102 | 379-DDP-001 |

TENENCIA Ltd. - 70 PRIORY ROAD CV8 1LQ KENILWORTH UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|---|----------------------------|------------------|----------------------|
| EASA.210.10045442 | 25/06/2013 | QCC1200 - Double Seat & QCC1300 - Triple Seat | QCC 1()()-(XXX)-(XXX)-C39C | C39c | DF/ENG/070-QCC 1000 |
| EASA.210.10049463 | 10/06/2014 | QCC1200 & QCC1300 Aircraft Double & Triple Seat | QCC1()()-(XXX)-(XXX) | C127a | DF/ENG/070-QCC1000/1 |

THALES AVIONICS ELECTRICAL SYSTEMS - 41 BLD DE LA REPUBLIQUE 78400 CHATOU FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

THALES AVIONICS ELECTRICAL SYSTEMS - 41 BLD DE LA REPUBLIQUE 78400 CHATOU FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|----------------------|---------------|------------------|------------------------|
| EASA.210.672 | 21/03/2007 | DC Starter Generator | G3666-() | C56a | Y42-227 |
| F.O.032 | 08/02/2001 | DC Starter Generator | G3570-(XXX) | | Y42-167 OF 18/10/00 |

THALES AVIONICS S.A.S - 19-21 AV MORANE SAULNIER 78140 VELIZY VILLACOUBLAY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|---|---------------|
| EASA.210.923 | 15/10/2009 | TOPSTAR 200NG GPS | C17149(A-)(-) C17149(B-)(-) C17149(C-)(-) C17149(D-)(-) C17149(E-)(-) C17149(F-)(-) C17149(G-)(-) | C129a | J61288-AA |
| EASA.210.1154 | 05/11/2008 | ADU 3200 | C17133()() | C106 | J41865AA |
| EASA.210.157, REV. A | 11/03/2013 | FMC2 NAVM Flight Management Computer Navigation Module - FMS | C13084A(-)(-) | C115b C129a | J68864AA |
| EASA.210.741, REV. B | 07/12/2012 | ADC RRJ | AIRCRAFT TABLE C17152AA00 WITH G6249AAD02 OR G6249AAD04 APPLICATION SOFTWARE & G6250AAD(XX) | C106 | J61900AA |
| EASA.210.789, REV. A | 15/03/2012 | Integrated Electronic Stand-by Instrument V2 | C16786AA01 C16786EA01 C16786ZA01 | C2d C4c C10b C95 C113 | J62273AB |
| EASA.210.971, REV. B | 17/03/2011 | ADU 3008 Air Data Computer | C17053 (A-)(-) C17053 (J-)(-) C17053 (L-)(-) C17053(M-)(-) | C106 | J61367AA |
| EASA.210.10033812 | 10/02/2011 | ESI V2 Electronic Standby Instrument | C16790AAXX | C2d C4c C10b C95 C113 | J49863AA |
| EASA.210.10034220 | 17/03/2011 | Serial Actuator | C18419A(-) | C9c | J14985AA |
| EASA.210.10039534 | 10/05/2012 | IESI V1 Family 5. | C16221AJ(-)(-) C16221J(-)(-) C16221R(-)(-) C16221U(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74024-AA |
| EASA.210.10039543 | 10/05/2012 | IESI V1 Family 6 | C16221K(-)(-) C16221L(-)(-) C16221M(-)(-) C16221Q(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74025-AA |
| EASA.210.10039553 | 10/05/2012 | IESI V1 Family 1 | C16221D(-)(-) C16221S(-)(-) C16221W(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74027-AA |
| EASA.210.10039555 | 10/05/2012 | IESI V1 Family 2 | C16221AN(-)(-) C16221AP(-)(-) C16221AT(-)(-) C16221V(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74026-AA |
| EASA.210.10039557 | 10/05/2012 | IESI V1 Family 3 | C16221A(-)(-) C16221C(-)(-) C16221F(-)(-) C16221H(-)(-) C16221T(-)(-) C16221Z(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74028-AA |
| EASA.210.10039558 | 10/05/2012 | IESI V1 Family 4 | C16221G(-)(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74030-AA |
| EASA.210.10047210 | 25/11/2013 | GPS/SBAS receiver Topstar 200 LPV | C17149H(-)(-), C17149J(-)(-) C17149K(-)(-), C17149L(-)(-) C17149M(-)(-), C17149N(-)(-) C17149P(-)(-), C17149Q(-)(-) | C145c C146c | J69138AA |
| EASA.210.10047407 | 10/12/2013 | Integrated Electronic Standby Instrument IESI V2 Family 5 | C16786Y(-)(-) | C2d C4c C10b C95 C113 | J74119AA |

THALES AVIONICS S.A.S - 19-21 AV MORANE SAULNIER 78140 VELIZY VILLACOUBLAY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|---|---|---------------|
| EASA.21O.10037355, REV. B | 04/02/2013 | Flight Control Module (FCM) | C13172A(-)(-) EXCEPT C13172AB02 & C13172AC02 | C9c | J7402AA |
| EASA.21O.10038806, REV. F | 14/08/2015 | Integrated Electronic Standby Instrument (IESI V2) - Family | C16786AE[X](XX) C16786C[X](XX) C16786D[X](XX) C16786J[X](XX) C16786K[X](XX) C16786L[X](XX) C16786M[X](XX) C16786N[X](XX) C16786P[X](XX) C16786U[X](XX) C16786V[X](XX) | C2d C4c C10b C95 C113 | J62273AB |
| EASA.21O.10038825, REV. A | 15/06/2012 | ESI V2 Electronic Standby Instrument | C16790B(-)(-) | C2d C4c C10b C95 C113 | J49862AB |
| EASA.21O.10038962, REV. F | 14/08/2015 | Integrated Electronic Standby Instrument (IESI V2) - Family | C16786AA[X](XX) C16786AD[X](XX) C16786F[X](XX) C16786G[X](XX) C16786H[X](XX) C16786W(Y)[X](XX) EXCLUDING P/N C16786AA01 | C2d C4c C10b C95 C113 | J62273AB |
| EASA.21O.10039545, REV. A | 10/05/2012 | IESI V1 Family 7 | C16221AKA(-) C16221ALA(-) C16221AZA(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74010-AA |
| EASA.21O.10039550, REV. A | 10/05/2012 | IESI V1 Family 8 | C16221AQA(-) | JTSO-C2D JTSO-C4C JTSO-C10B JTSO-C95 JTSO-C113 Other | J74029-AA |
| EASA.21O.10040093, REV. B | 03/07/2013 | IAD 68 (v301.1) | C19685CB03, C19685CB04 | C113 C115b C129a | J55749 |
| EASA.21O.10041905, REV. C | 06/11/2014 | IESI V2 FAMILY 4: Integrated Electronic Standby Instrument | C16786BA01 C16786BA02 C16786BAA01 | C2d C4c C10b C95 C113 | J74012AA |
| EASA.21O.10043999, REV. A | 20/06/2013 | FMC2 NAVM Flight Management Computer Navigation Module - FMS | C13084C(-)(-) | C115b C129a | J68790AA |
| EASA.21O.10049471, REV. B | 09/09/2014 | IAD 68-1 / Integrated Avionics Display Unit including a Flig | C19685CB05 C19685CB06 | C113 C115b C129a | J55749 |
| F.O.005 | 17/09/1999 | Integrated Electronic Standby Instrument | C16221(XX)(XX) | | J33957AA |
| F.O.122 | 13/08/2003 | Electronic Standby Instrument (ESI) | C16393() | | |
| QAC 104 N°53291 | 26/03/1985 | # | H341(*) (*) M (*) FAMILY | TSO C4C Other | DNI/IM N°3294 |

THALES COMMUNICATIONS & SECURITY S.A.S - 4 AVENUE DES LOUVRESSES 92230 GENNEVILLIERS FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|----------------------------|--------------------|------------------|---------------|
| EASA.21O.021 | 19/05/2004 | Radio Altimeter ERT540 | 9599-607-195() | 2C87 | 61002239AA580 |
| EASA.21O.208 | 01/12/2004 | Enhanced VHF Radio, EVR750 | EVR750-04-() | 2C37e 2C38e | 4689708A556-F |
| EASA.21O.1286, REV. C | 13/10/2010 | AHV1600 Radar Altimeter | AHV1600-01-XX XX X | 2C87 | 62390481-580 |
| F.O.004 | 02/07/1999 | VHF-Transceiver | EVR 750-03-XXXXX | | |
| F.O.025 | 04/09/2000 | VHF Tranceiver | EVR716-11-(XXXXX) | | 489709A556/A1 |
| F.O.029 | 27/10/2000 | VHF Data Radio | EVR716-01-(XXXXX) | | |
| F.O.074 | 26/02/2002 | Multi Mode Receiver (MMR) | TLS2020-F51A(XXX) | | 56150894AA580 |

THALES UK Ltd. - 2 DASHWOOD LANG ROAD KT15 2NX ADDLESTONE WEYBRIDGE UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|-----------------------|------------------|---------------|
| CAA.O.00006 | 24/12/2002 | Control Display Navigation Unit (CDNU) - 81850 | 81850A03(X) 17 01(XX) | | 769 |

THERMOCOAX SAS - USINE DE PLANQIVON 61438 ATHIS-DE-L'ORNE FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-----------------|---|------------------|---------------|
| F.O.079 | 25/04/2002 | Overheat Sensor | NGC1-120-10A06 NGC1-120-20A06 NGR1-124A3-1(XXX) NGR1-124A3-2(XXX) NGR1-124A3-3(XXX) | | NG340R058 R3 |
| F.O.105 | 12/02/2003 | Overheat Sensor | NGR1-215A4-31 | | NG340R088 R2 |

THOMMEN AIRCRAFT EQUIPMENT AG - HAUPTSTRASSE 85 4437 WALDENBURG SWITZERLAND

| THOMMEN AIRCRAFT EQUIPMENT AG - HAUPTSTRASSE 85 4437 WALDENBURG SWITZERLAND | | | | | |
|--|--------------------|--|--------------------------------|---|-------------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.565 | 09/10/2006 | AD20 Standby Altimeter | AD20.() | C10b | AD-DDP-900 |
| EASA.210.715 | 24/07/2007 | 3A67.22.20F.05.1.PM, 3 Inch Encoding Altimeter | 3A67.22.20F.05.1.PM | C10b C88a | 232-3A-06 |
| EASA.210.762 | 24/08/2007 | AD42 Air Data Display, SD31 Airspeed Indicator (Repeater) | AD42.() SD31.() | C2d C10b C88a C106 | AD-DDP-400 SD-DDP-600 |
| EASA.210.927 | 03/03/2008 | 3H63.() Altimeter with Barosetting-Output | 3H63.() WITH MOD 05 OR HIGHER | C10b | 280-3H-07 |
| EASA.210.1086 | 17/09/2008 | 5A58 2-Inch Airspeed Indicator | 5A58.() | C2d | 285-5A-08 |
| EASA.210.1126 | 15/12/2008 | 3-Inch Airspeed Indicator Type 5A16 | 5A16.() | C2d | 286-5A-08 |
| EASA.210.1142 | 07/04/2009 | 3-Inch Vertical Speed Indicator Type 4A16 | 4A16.() | C8d | 287-4A-08 |
| EASA.210.1209 | 07/04/2009 | 2-Inch Maximum Allowable Airspeed Indicator Type 5C56 | 5C56.() | C46a | 292-5C-09 |
| EASA.210.716, REV. A | 07/08/2007 | 3A65.22.20F.05.1.RB Encoding Altimeter | 3A65.22.20F.05.1.RB | C10b C88a | 244-3A-06 |
| EASA.210.765, REV. A | 02/06/2009 | Altimeter (Repeater) AD21, Airspeed Indicator (Repeater) SD2 | AD21.() SD21.() | C2d C10b | AD-DDP-700 SD-DDP-800 SD21 |
| EASA.210.1186, REV. A | 28/01/2009 | MD21 Standby MACH speed indicator | MD21.(XX.XXX.XX.XX) | C2d C46a C95 | MD-DDP-900 |
| FOCA Z34-16-01 | 11/07/2005 | AD32 Air Data Display | AD3X.() | TSO C10B TSO C88A TSO C106 Other | AD-DDP-400 |
| FOCA Z34-17-01 | 17/02/2005 | AC32 Digital Air Data Computer | AC32.() | TSO C88A TSO C106 Other | AC-DDP-500 |

| THOMPSON AERO SEATING LIMITED - 20-24 MILL STREET BT63 6NH GILFORD, CRAIGAVON UNITED KINGDOM | | | | | |
|---|--------------------|---|--------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10037480 | 29/11/2011 | VT02 Series Vantage Passenger Seat | VT02-00-(XXX)-(XX) | C127a | 0001 |
| EASA.210.10037956 | 09/01/2012 | VT03 Series Vantage Passenger Seat System | VT03-00-(XXX)-(XX) | C127a | 0003 |
| EASA.210.10040976 | 10/08/2012 | VT04 Series Vantage Passenger Seat | VT04-00-(XXX)-(XX) | C39c | 0005 |
| EASA.210.10041012 | 15/08/2012 | VT04 Series Vantage Passenger Seat | VT04-00-(XXX)-(XX) | C127a | 0004 |
| EASA.210.10046047 | 08/08/2013 | VT07 Series Vantage Passenger Seat System | VT07-00-(XXX)-(XX) | C39c | VT07 |
| EASA.210.10047361 | 05/12/2013 | VT06 Series Vantage Passenger Seat System | VT06-00-(XXX)-(XX) | C127a | VT06 |
| EASA.210.10047690 | 13/01/2014 | VT08 Series Vantage Passenger Seat System | VT08-00-(XXX)-(XX) | C39c | VT08 |
| EASA.210.10048087 | 12/02/2014 | VT09 Series Vantage Passenger Seat System | VT09-00-(XXX)-(XX) | C127a | VT09 |
| EASA.210.10051075 | 06/11/2014 | VT10 Series Vantage Passenger Seat | VT10-00-(XXX)-(XX) | C127a | VT01 |
| EASA.210.10051489 | 05/12/2014 | VT15 Series Vantage | VT15-00-(XXX)-(XX) | C127a | VT15 |
| EASA.210.10051596 | 11/12/2014 | VT11 SERIES VANTAGE | VT11-00-(XXX)-(XX) | C127a | VT11 |
| EASA.210.10053784 | 23/06/2015 | VT14 SERIES VANTAGE XL | VT14-00-(XXX)-(XX) | C127a | VT14 |
| EASA.210.10054093 | 17/07/2015 | VT12 SERIES VANTAGE | VT12-00-(XXX)-(XX) | C127a | VT12 |
| EASA.210.10043255, REV. A | 12/02/2013 | VT05 Series Vantage Passenger Seat | VT05-00-(XXX)-(XX) | C127a | VT05 |

| TL ELEKTRONIC a.s. - AIRPORT BUILDING 125 503 41 HRADEC KRALOVE CZECH REPUBLIC | | | | | |
|---|--------------------|-----------------------------------|----------------|------------------|------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.563 | 30/10/2006 | TL-2824C RPM & Engine Hours Meter | TL-2824C_AA(X) | C49b | TLD-2824C-CB-001 |

| TOST GmbH FLUGZEUGGERAETEBAU MUENCHEN - THALKIRCHNER STRASSE 62 80337 MUENCHEN GERMANY | | | | | |
|---|--------------------|--|----------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10054822 | 21/09/2015 | TOST AIRCRAFT WHEEL NG // Disk brake wheel for sailplanes; p | 010-5XX-XXX-XX | C26c | 010 |

| TRANS-CAL INDUSTRIES, INC - 16141 COHASSET ST. 91406 VAN NUYS USA | | | | | |
|--|--------------------|---------------------------------|-------------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.IM.210.1044 | 04/07/2008 | Altitude Digitizer Model SSD120 | SSD120-(XX)(X)(X) | C88a | 2008-3 |

| TRIAGNOSYS GmbH - ARGELSRIEDER FELD 22 // TE3 82234 WESSLING, OT OBERPFAFFENHOFEN GERMANY | | | | | |
|--|--------------------|--|--|------------------|------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10040524 | 09/07/2012 | GSMConneX (AeroBTS+, NCU) GSM Picocell | 21T810-(XX)-(XX)-(XX) 21T820-(XX)-(XX)-(XX) | 2C514 | 2011-21T810-1027 |
| EASA.210.10048393, REV. A | 02/09/2014 | WSU | 00-5802-XX OR 21T840-XX-XX-XX | 2C514 | 2013-21T840-1454 |

| TRIG AVIONICS Ltd. - HERIOT WATT RESEARCH PARK EH14 4AP RICcartON, EDINBURGH UNITED KINGDOM | | | | | |
|--|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.1277 | 25/08/2009 | TT22 Remote Mount Transponder | 00745-00-(XX) UNIT LEVEL 00746-00-(XX) SHIPPING LEVEL | 2C112b C166a | DEV/TT22/008 |
| EASA.210.643, REV. B | 24/02/2011 | TT31 Mode S Transponder | 00220-00(-) UNIT LEVEL 00225-00(-) SHIPPING LEVEL | 2C112b | DEV/TT31/199 |
| EASA.210.906, REV. A | 10/02/2011 | TT31 Mode S Elementary Surveillance (ELS) Transponder | 00220-00(-) UNIT LEVEL 00225-00(-) SHIPPING LEVEL WITH SW REV 2.() OR 3.() | C166a | DEV/TT31/199 |
| EASA.210.10034899 | 11/05/2011 | TT22 Remote Mount Mode S Transponder with Software 2.x | 00745-00-(XX) UNIT LEVEL 00746-00-(XX) SHIPPING LEVEL | C112c C166a | DEV/TT22/007 |

| TRIG AVIONICS Ltd. - HERIOT WATT RESEARCH PARK EH14 4AP RICcartON, EDINBURGH UNITED KINGDOM | | | | | |
|---|--------------------|--|--|-------------------------|----------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10034900 | 11/05/2011 | TT21 SW 2.(xx) Remote Mount Mode S Transponder | 00565-00-(XX) SHIPPING LEVEL 00675-00-(XX) UNIT LEVEL | C112c C166a | DEV/TT21/007 |
| EASA.210.10037782 | 22/12/2011 | TC978 Front Panel Controller | 00808-00-(XX) | C88a | DEV.TC978.005 |
| EASA.210.10042343 | 26/11/2012 | TC90 Panel Mount Controller for VHF Transceiver | 00857-00-(XX) | 2C169A | DEV/TC90/008 |
| EASA.210.10046272 | 04/09/2013 | GenTXP Mode S Transponder | 00970-00-(XX) WITH SOFTWARE 00971-00-(XX) WITH SOFTWARE TRANSPONDER SHIPPING LEVEL) TRANSPONDER UNIT LEVEL) VERSION V3.(XX) (GENTXP VERSION V3.(XX) (GENTXP | C112d C166b Other | DEV.GENTXP.199 |
| EASA.210.10046583 | 04/10/2013 | KT74 Mode S Transponder | 01157-00-(XX) WITH SOFTWARE 01158-00-(XX) WITH SOFTWARE TRANSPONDER - SHIPPING LEVEL) TRANSPONDER - UNIT LEVEL) VERSION V3.(XX) (KT74 VERSION V3.(XX) (KT74 | C112d C166b | DEV.KT74.199 |
| EASA.210.10046993 | 08/11/2013 | AXP340 Mode S Transponder | SHIPPING LEVEL: 01156-00-(XX) UNIT LEVEL: 01155-00-(XX) WITH SOFTWARE VERSION V3.(XX) WITH SOFTWARE VERSION V3.(XX) | C112d C166b | DEV.AXP340.199 |
| EASA.210.10042695, REV. B | 11/12/2013 | TY9x Series of VHF Transceiver | 00879-00-(XX) TY92 00881-00-(XX) TY92 00882-00-(XX) TY91 00883-00-(XX) TY91 01192-00-(XX) TY91L 01193-00-(XX) TY91L 01195-00-(XX) TY92L 01196-00-(XX) TY92L | 2C128 2C169A | DEV/TY92/006 |
| EASA.210.1056, REV. A | 18/08/2009 | TT21 Remote Mount Mode S Elementary Surveillance Transponder | 00565-00-(XX) SHIPPING LEVEL 00675-00-(XX) TRANSPONDER | 2C112b C166a | DEV/TT21/008 |
| EASA.210.1112, REV. B | 22/12/2011 | TC20 Front Panel Controller | 00649-00-(XX) | C88a 2C112b | DEV/TC20/005 |
| TYPHOON INTERNATIONAL LIMITED - 10 SLINGSBY PLACE, ST. MARTIN'S COU WC2E 9AB LONDON UNITED KINGDOM | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10039825 | 29/05/2012 | Immersion Suit model OWP and TOFS | 130500-(XX) | Other UK CAA SPEC 19 | 130500 |
| EASA.210.10046494 | 25/09/2013 | Constant wear 275N Lifejacket Model 400500 | 400500-(XX) P/N 130501 | 2C504 2C503 | 400500 130501 |
| UKU(TSI)-UCAK KOLTUK URETIMI SANAYI TICARET A.S. (TURKISH SEAT INDUSTRY - ASIM KIBAR OSB VATAN CAD. AL NO:1/2 41310 IZMIT KO | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.10047473 | 13/12/2013 | Economy and Convertible Class Seat / E01 and C01 | C01-(XXXXX)-(XXX) E01-(XXXXX)-(XXX) | C39c C127a | TSI-01 |
| UNIMOR RADIOCOM SP.Z.O.O. - UL.BUDOWLANYCH 46C 80-298 GDANSK POLAND | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| CAA PL Z-FC-23/02 | 13/11/2002 | RS 6112 VHF Comm Transceiver | RS 6112 RS 6112B | 2C37e 2C38e | |
| UNIVERSAL AVIONICS SYSTEMS CORPORATION - 3260 E. UNIVERSAL WAY 85756 TUCSON USA | | | | | |
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.097 | 16/06/2004 | UNS-1E - Flight Management System | 10171 2017-() | C115b C129a | 20511 |
| EASA.210.098 | 16/06/2004 | UNS-1Esp - Flight Management System | 10191 2019-() | C115b C129a | 20512 |
| EASA.210.099 | 16/06/2004 | UNS-1F - Flight Management System | 1018-() 11921 2192-() | C115b C129a | 20513, 20524 |
| EASA.210.123 | 05/07/2004 | UNS-1C+ - Flight Management System | 10171 10172-() 1406-() | C109 C115b C129a | 20515 |
| EASA.210.124 | 05/07/2004 | UNS-1Csp+ - Flight Management System | 10191 10192-() 1406-() | C109 C115b C129a | 20516 |
| EASA.210.125 | 05/07/2004 | UNS-1D+ - Flight Management System | 1018-() 11921-() 11922-() 1406-() | C109 C115b C129a | 20517 |
| EASA.210.126 | 05/07/2004 | UNS-1K - Flight Management System | 11162-() 1117-() 11921 1406-() | C109 C115b C129a | 20518 |
| EASA.210.170 | 08/10/2004 | Terrain Awareness and Warning System TAWS | 3010-00-() SCN 11.() 30101 | C92c C151a | 10099 |

| UNIVERSAL AVIONICS SYSTEMS CORPORATION - 3260 E. UNIVERSAL WAY 85756 TUCSON USA | | | | | |
|---|--------------------|--|--|---|----------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.264 | 30/03/2005 | MFD-640 Flat Panel Multi-Function Display | 50011 6402-10001-() 6402-10011-() 6402-11001-() 6402-11011-() 6402-12001-() | C105 C113 C119b | 20521 |
| EASA.IM.21O.344 | 21/09/2005 | EFI-890R Primary Flight / Navigation Display Unit | 8904-23533-() | C2d C3d C4c C5e C6d C8d C10b C52b C92c C95 C105 C113 C115b C118 C119b C129a C151a | RPRT-2005-1002 |
| EASA.IM.21O.349 | 27/09/2005 | EFI-890R Controls + DCU | 43001 4300-10000-() 50011 5021-() 5022-() 5023-() 5024-() 5025-() 5026-() 5027-() | C113 | RPRT-2005-1003 |
| EASA.IM.21O.515 | 02/06/2006 | GLS-1250 GPS Landing System | 1086-() 10861 | C129a | RPRT-2006-1013 |
| EASA.IM.21O.662 | 05/03/2007 | UCD 3040 Universal Cockpit Display System | 30401 3040-() SCN 31.X 3055-() SCN 30.X | C113 | 2006-1011 |
| EASA.IM.21O.671 | 21/03/2007 | Vision 1 Synthetic Vision System | 30111-() VIDEO INTERFACE UNIT 30151 CONFIGURATION MODULE (CM) 3015-() REMOTE COMPUTER UNIT | C113 | 2006-1010 |
| EASA.IM.21O.696 | 25/06/2007 | UNS-1E SCN 803/903 Flight Management System | 2017-() SCN 803.X/903.X | C115b C129a | DDP-2007-1001 |
| EASA.IM.21O.697 | 25/06/2007 | UNS-1Esp SCN 803/903 Flight Management System | 2019-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1002 |
| EASA.IM.21O.698 | 25/06/2007 | UNS-1L SCN 803/903 Flight Management System | 2116-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1004 |
| EASA.IM.21O.699 | 25/06/2007 | UNS-1F SCN 803/903 Flight Management System | 2192-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1003 |
| EASA.IM.21O.700 | 25/06/2007 | UNS-1C+ SCN 803/903 Flight Management System | 10172-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1005 |
| EASA.IM.21O.701 | 25/06/2007 | UNS-1Csp+ SCN 803/903 Flight Management System | 10192-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1006 |
| EASA.IM.21O.702 | 25/06/2007 | UNS-1K+ SCN 803/903 Flight Management System | 11162-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1008 |
| EASA.IM.21O.703 | 25/06/2007 | UNS-1D+ SCN 803/903 Flight Management System | 11922-() WITH SCN 803.X/903.X | C115b C129a | DDP-2007-1007 |
| EASA.IM.21O.708 | 15/09/2008 | ASU SCN 32 and CCP, Application Server Unit and Cursor Contr | 3040-06-1() WITH SCN 32.X APP 3065-() CURSOR CONTROL PANEL | C113 | DDP-2007-1010 |
| EASA.IM.21O.709 | 16/03/2009 | Universal Cockpit Display Terminal: UCDDT-III SCN 40 | 3056-00-(), SCN 40.X | C113 | DDP-2007-1011 |
| EASA.IM.21O.726 | 25/10/2007 | Radio Control Unit RCU SCN 1016 | 4120-() SCN 1016.0.X CONFIGURATION MODULE 41201 | C113 | 2007-1013 |
| EASA.IM.21O.877 | 19/11/2007 | ADU SCN 11 Accessible Data Unit | 3060-01-() WITH SCN 11.X | C109 | 2007-1009 |
| EASA.IM.21O.905 | 06/12/2007 | MFD-640 SCN 1011 Multi-Function-Display | 6402-33011-() SCN 1011.5.X 6402-43011-() SCN 1011.5.X 6402-44011-() SCN 1011.5.X | C105 C113 C119b | 2007-1012 |
| EASA.IM.21O.100, REV. A | 11/04/2008 | UNS-1L Flight Management System | 1117-() FLAT PANEL CDU 11921 CONFIGURATION MODULE 2116-() NAVIGATION COMPUTER | C115b C129a | 20514 |
| EASA.IM.21O.1025 | 10/07/2008 | UL-701 SCN 22 Communications Management Unit (CMU) | 10651 1068-() SCN 22.X | 2C37e 2C38e | DDP-2008-1002 |
| EASA.IM.21O.1033 | 22/06/2009 | EIU-440 SCN 1019.0 Engine Interface Unit | 44001 CONFIGURATION MODULE 4400-() WITH SCN 1019.0.2 OR | C43c C44b C47 C49b C113 | 2008-1001 |

UNIVERSAL AVIONICS SYSTEMS CORPORATION - 3260 E. UNIVERSAL WAY 85756 TUCSON USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|--------------------------|--------------------|--|---|---|---------------|
| EASA.IM.210.1088 | 03/09/2008 | EFI-890R Accessories | 50011 CONFIGURATION MODULE 5029-() ALTITUDE CONTROL PANE 5030-() MFD DISPLAY CONTROL P 5031-() PFD CONTROL PANEL 5032-() PFD CONTROL PANEL 5033-() RADAR CONTROL PANEL 890119-() INCLINOMETER | C113 | 2008-1007 |
| EASA.IM.210.1143 | 18/12/2008 | SDDTU SCN 10.X Solid State Data Transfer Unit | 1408-() SCN 10.X | C109 | 2008-1008 |
| EASA.IM.210.1157 | 19/09/2012 | CVFDR Cockpit Voice and Flight Data Recorder SCN 2000.0.X an | CCU: 1640-(), 1641-() CCU: 1642-(), 1643-() CVFDR: 1605-(), CVR: 1606-() FDR: 1607-(), MIC: 16301-() INSTALL KIT K12083-1, K12084-1 WITH SW SCN 2004.0.() | C123b C124b C155 C177 | DDP-2012-1002 |
| EASA.IM.210.10040796 | 26/07/2012 | Data Concentrator Unit DCU 4300-2XX00 SCN 1018.0.X | 1021.0.X 4300-20000-() SCN 1018.0.X 4300-20100-() 4300-21000-() 4300-21100-() SCN 1018.0.X, 1020.0.X SCN 1018.0.X, 1021.0.X | C113 | 2012-1003 |
| EASA.IM.210.10041174 | 28/08/2012 | Terrain Awareness and Warning System TAWS SCN 12.X | 3010-00-() CLASS A 3010-01-() CLASS B 30101 CONFIGURATION MODULE | C92c C151b | 2010-1001 |
| EASA.IM.210.1076, REV. A | 26/06/2012 | EFI-890() SCN 1017.1 Electronic Flight Instrument PFD/ND/MF | 8904-35533-() WITH SCN 1017.1.X | C2d C3d C4c C5e C6d C8d C10b 2C34f 2C35d 2C36f 2C40c 2C41d C43c C44b C46a C47 C49b C52b 2C63c 2C66b 2C87 C92c C95 C105 C113 C115b C119b C129a C151b | 2007-1014 |
| LBA.N-O.10.911/101 JTSO | 28/09/1999 | UL-601 Datalink Management System | 10651 1066-() | | 20292 |

URSUK OY - TEIJONKATU 3 20750 TURKU FINLAND

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--------------------------------|--------------------------|------------------|---------------|
| EASA.210.10050925 | 30/10/2014 | URSUIT RDS ETSO Immersion suit | 5106ETSO-()-()-()-() | 2C503 | RDSETSO |

UUDS - 12 RUE DU MEUNIER 95700 ROISSY FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------------|------------------|---------------|
| F.O.103 | 29/01/2003 | Stretcher | TMC99-001-(XX)-(XX) | | 01-12-02 |

VAN RIEMSDIJK ROTTERDAM B.V. VRR / VRR AVIATION - STOLWIJKSTRAAT 57 3079 DN ROTTERDAM NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-----------------------------|-------------------|------------------|---------------|
| EASA.210.519 | 12/06/2006 | Container RKN-2006-01 | 735.001-000(-XX) | C90c | DDP060112 |
| EASA.210.532 | 06/07/2006 | RAP-2006-01 Cargo Container | 735.050-000 (-XX) | C90c | DDP060422 |
| EASA.210.548 | 18/08/2006 | PGA-0401 Cargo Pallet | 441.710(-XXX) | C90c | DDP040910 |
| EASA.210.557 | 15/09/2006 | PGA-0601 20 FT pallet | 441.810 (-XXX) | C90c | DDP060708 |
| EASA.210.584 | 08/11/2006 | PAB-SP01, PAB Seat Pallet | 390.050 (-XXX) | C90c | DDP060707 |
| EASA.210.588 | 20/11/2006 | PRA pallet / PRA-0601 | 441.805 (-XXX) | C90c | DDP060710 |
| EASA.210.589 | 20/11/2006 | RAP-2006-02 Cargo Container | 735.085(-XXX) | C90c | 060824 |
| EASA.210.592 | 20/11/2006 | PRA-0401 Pallet | 441.705 (-XXX) | C90c | 041010 |
| EASA.210.617 | 04/01/2007 | RLF-2006-01 Container | 131.001-000(-XX) | C90c | 060825 |
| EASA.210.682 | 29/06/2007 | AAN Container / AAN-7210 | RR1.721.0XX | C90c | DDP050316 |
| EASA.210.744 | 31/05/2007 | HMA Container / HMA-0702 | 441.820(-XXX) | C90c | 070201 |
| EASA.210.770 | 29/06/2007 | ABY Container / ABY-8810 | RR1.881.0XX | C90c | DDP050488 |
| EASA.210.773 | 31/07/2007 | AEP Container / AEP-5510 | RR1.551.0() | C90c | 050255 |
| EASA.210.779 | 31/07/2007 | ALP Container / ALP-6510 | RR1.651.0() | C90c | 050265 |

| VAN RIEMSDIJK ROTTERDAM B.V. VRR / VRR AVIATION - STOLWIJKSTRAAT 57 3079 DN ROTTERDAM NETHERLANDS | | | | | |
|--|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.791 | 06/08/2007 | AKH Container / AKH-0701 | 224.001 (-XXX) | C90c | 070717 |
| EASA.210.792 | 06/08/2007 | HML Container / HML-0701, HMR Container / HMR-0701 | 250.040(-XXX) 250.080(-XXX) | C90c | 070148 |
| EASA.210.794 | 10/09/2007 | AKP-7380 Cargo Container | 738.001-XXX | C90c | 070738 |
| EASA.210.795 | 21/09/2007 | AAN Container / AAN-7219 | RR1.721.9(XX) | C90c | 070709 |
| EASA.210.833 | 23/10/2007 | ABN Container / ABN-8210 | RR1.821.0(XX) | C90c | 050482 |
| EASA.210.841 | 09/11/2007 | HMA Container / HMA-FA2P | 500.001(-XXX) | C90c | 070501 |
| EASA.210.1013 | 01/10/2008 | AAM Container / AAM-0485 | 682.020(-XXX) | C90c | DDP082020 |
| EASA.210.1064 | 01/07/2008 | RAP Container / RAP-0801 | 735.150(-XXX) | C90c | 083515 |
| EASA.210.1078 | 01/09/2008 | PLH Pallet / PLH-0497 | 685.010(-XXX) | C90c | DDP084970 |
| EASA.210.1079 | 16/09/2008 | PKH Pallet / PKH-0496 | 685.001(-XXX) | C90c | 084960 |
| EASA.210.591, REV. A | 16/01/2014 | PLB-0510 Pallet | 1566-10-0(XXX) 441.305-1(XX) | C90c | DDP050510 |
| EASA.210.619, REV. A | 17/01/2014 | PMH Pallet / PMH-2006-01, 125" x 96" heavy duty pallet | 1593-10-0(XXX) 520.155(-XXX) | C90c | DDP061211 |
| EASA.210.667, REV. A | 21/11/2014 | AAP-7510 Container | 1275-10-1(XXX) RR1.751.01(XX) | C90c | DDP050210 |
| EASA.210.683, REV. A | 17/09/2013 | AAA Container / AAA-7710 | RR1.771.0XX, 1276-10-0(XXX) | C90c | DDP050317 |
| EASA.210.751, REV. B | 16/01/2014 | HMJ Container / HMJ-0703 | 1193-10-1(XXX) 120.090(-XXX) 250.060(-XXX) | C90c | DDP070325 |
| EASA.210.949, REV. A | 16/01/2014 | RAP Container / RAP-0701 | 1375-10-0(XXX) 735.100(-XXX) | C90c | DDP073510 |
| EASA.210.10028265 | 14/12/2009 | PRA Pallet / PRA-0504 | 441.905(-XXX) | C90c | 090504 |
| EASA.210.10028324 | 17/12/2009 | PGA Pallet / PGA-0505 | 441.910(-XXX) | C90c | 090505 |
| EASA.210.10028408 | 05/01/2010 | PAJ Pallet / PAJ-0509 | 739.001(-XXX) | C90c | 090509 |
| EASA.210.10034825 | 05/05/2011 | PBJ Pallet / PBJ-0531 | 1582-10-01(XX) | C90c | 110531 |
| EASA.210.10034932 | 13/05/2011 | PGA PALLET / PGA-0532 | 1514-10-01(XX) | C90c | 110532 |
| EASA.210.10040508 | 06/07/2012 | PBE Seat Pallet / PBE-0518 | 780.180(-XXX) | C90c | 100518 |
| EASA.210.10040640 | 16/07/2012 | PEE Seat Pallet / PEE-0519 | 780.185(-XXX) | C90c | 100519 |
| EASA.210.10041236 | 31/08/2012 | HMJ Horse Container / HMJ-0538 | 1193-10-0XXX | C90c | 120538 |
| EASA.210.10042735 | 17/12/2012 | HMX Horse Container / HMX-0542 | 1199-10-0XXX | C90c | 120542 |
| EASA.210.10044219 | 26/03/2013 | ABY Container / ABY-0549 | 1488-10-0(XXX) | C90c | 120549 |
| EASA.210.10045604 | 05/07/2013 | AMF Cargo Container / AMF-0564 | 1691-10-0(XXX) | C90d | 120564 |
| EASA.210.10046372 | 12/09/2013 | HMA Horse Container / HMA-0543 | 1197-10-0(XXX) | C90d | 120543 |
| EASA.210.10046404 | 17/09/2013 | PRA Pallet / PRA-0540 | 1515-10-0(XXX) | C90d | DDP120540 |
| EASA.210.10046616 | 04/10/2013 | ALP Container / ALP-0565 | 1265-10-0(XXX) | C90d | DDP120564 |
| EASA.210.10048779 | 09/04/2014 | PMC Pallet / PMC-0578 | 1591-10-0(XXX) | C90d | DDP130578 |
| EASA.210.10048860 | 17/04/2014 | AMD CONTAINER/ AMD-0599 / Cargo Container | 1294-10-0(XXX) | C90d | DDP140599 |
| EASA.210.10048872 | 17/04/2014 | AMP-0422 // Cargo Container | 1295-10-1(XXX) 228.001(-XXX) RR1.951.(XXX) | C90d | DDP130422 |
| EASA.210.10049785 | 08/07/2014 | AKN Container / AKN-0571.Cargo Container | 1232-10-0(XXX) | C90d | DDP130571 |
| EASA.210.10049786 | 08/07/2014 | AMX CONTAINER / AMX-0583 // Cargo Container | 1299-10-0(XXX) | C90d | DDP140583 |
| EASA.210.10051386 | 27/11/2014 | Type PMX Pallet, Model PMX-0584 // Heavy Duty Cargo Pallet | 1593-10-1(XXX) | C90d | DDP140584 |
| EASA.210.10051442 | 02/12/2014 | ALF Container/ALF-0577 // Cargo Container | 1261-10-0(XXX) | C90d | DDP130577 |
| EASA.210.10055071 | 09/10/2015 | AMV CONTAINER / AMV-0593 // Cargo Container | 1296-10-0(XXX) | C90d | DDP150593 |
| EASA.210.10055072 | 09/10/2015 | AAY CONTAINER / AAY-0585 // Cargo Container | 1278-10-0(XXX) | C90d | DDP150585 |
| EASA.210.10028426, REV. A | 17/09/2013 | AAX Container / AAX-7910 | 1279-10-0(XXX) RR1.791.0XX | C90c | DDP090508 |
| EASA.210.10035100, REV. A | 09/04/2013 | PBF Pallet / PBF-0527 | 1483-10-0(XXX), 197.012(-XXX) | C90c | 110527 |
| EASA.210.10042230, REV. A | 16/01/2014 | AMJ Container / AMJ-0523F | 1293-10-0(XXX) RR1.931.0XX | C90c | DDP100523 |
| EASA.210.1188, REV. A | 16/01/2013 | Cool Container RKN-0491 | 1332-10-0(XXX) 735.130(-XXX) | C90c | 083513 |
| EASA.210.1189, REV. A | 04/06/2014 | AMA Container / AMA-0498 / Main Deck Cargo Container | 1297-10-0(XXX) 238.080(-XXX) | C90c | DDP083808 |
| EASA.210.1262, REV. A | 15/06/2012 | HAY Horse Container / HAY-0503 | 1178-10-0(XXX), 780.170(-XXX) | C90c | 090503 |

VIKING LIFE-SAVING EQUIPMENT A/S - SAEDDING RINGVEJ 13 6710 ESBJERG V DENMARK

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---|--|------------------|---------------|
| EASA.210.10031380 | 12/08/2010 | Helicopter Pilot Lifejacket PV9355 | PV9355 () () () () () () | 2C504 | DDP/PV9355 |
| EASA.210.10040596 | 12/07/2012 | Viking Helicopter Pilot Life Jacket PV9365 | PV9365 () () () () () () | 2C504 | PV9365 |
| EASA.210.10043884 | 04/03/2013 | Viking Pilot immersion suit PS4044 | PS4044(0)(0)(0)(0)(0)(0) | 2C503 | PS4044 |
| EASA.210.10044071 | 18/03/2013 | Viking Pilot immersion suit PS4045 | PS4045 0(0)(0)(0)(0)(0)(0) | 2C503 | PS4045 |
| EASA.210.10055419 | 06/11/2015 | PS5040 VIKING HELICOPTER TRANSPORTATION SUIT | PS5040() () () () () () | 2C502 | DDP/PS5040 |
| EASA.210.10029099, REV. B | 07/05/2014 | PS4002 / PS4003 Helicopter transportation suit. | PS4002(0)(0)(0)(0)(0)(0) PS4003(0)(0)(0)(0)(0)(0) | C2C503 Other | DDP/PS4003 |
| EASA.210.10031468, REV. A | 21/02/2011 | Helicopter Pilot Suit PS4043 | PS4043(0)(0)(0)(0)(0)(0) | 2C503 | PS4043 |
| EASA.210.1016, REV. A | 26/01/2011 | Helicopter Life Jacket Type PV9302 | PV9302 () () () () () () | 2C504 | PV9302/DDP |

WERTHENBACH-HYDRAULIK- ANTRIEBSTECHNIK GmbH - GRAFENHEIDERSTR. 101 33729 BIELEFELD GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

WERTHENBACH-HYDRAULIK- ANTRIEBSTECHNIK GmbH - GRAFENHEIDERSTR. 101 33729 BIELEFELD GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------|--------------------|--------------------|---|------------------|---------------|
| LBA.O.31.252/1 JTSO | 21/07/2000 | Hose Assemblies WH | WH 466- () WH 566- () WH 666- () WH 666- ()F () | | WHJTSO53/2C75 |

WHELEN ENGINEERING COMPANY Inc. - 51 WINTHROP ROAD 06412 CHESTER USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|----------------|------------------|---------------|
| EASA.IM.210.10044117 | 19/03/2013 | 71554() Tail Position Light | 01-0771554-() | C30c | 05860 |
| EASA.IM.210.10045878 | 25/07/2013 | OR600() Wingtip Position / Anti-Collision Light | 01-0771733-() | C30c C96a | 05923 |
| EASA.IM.210.10049880 | 16/07/2014 | OR650() | 01-0790725-() | C30c C96a | 06016 |
| EASA.IM.210.10049881 | 16/07/2014 | OR650()E | 01-0790701-() | C30c C96a | 06018 |
| EASA.IM.210.10049949 | 21/07/2014 | OR500() // Tail Position/Anti-Collision Light | 01-0771774-() | C30c C96a | 06019 |

WINSLOW MARINE PRODUCTS CORPORATION D/B/A WINSLOW LifeRaft Company - 11700 WINSLOW DRIVE 34269 LAKE SUZY USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|----------------------|--------------------|------------------|---------------|
| EASA.IM.210.10028015 | 25/11/2009 | Life Raft / FA-AV() | XXXXFAXX-XXX-X-XXX | 2C70a | ENG-009 |

ZIM FLUGSITZ GmbH - ROENTGENSTRASSE 4+7 88677 MARKDORF GERMANY

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|---------------------------|--|------------------|----------------|
| EASA.210.1222 | 30/09/2009 | Economy Class Seat ECO-01 | EC1() () 2C() EC1() () 2L() EC1() () 2R() EC1() () 3C() EC1() () 3L() EC1() () 3R() EC1() () 4C() | C127a | 500801_DDP_001 |
| EASA.210.10027474 | 05/10/2009 | Economy Class Seat ECO-01 | EC1() () 2C() EC1() () 2L() EC1() () 2R() EC1() () 3C() EC1() () 3L() EC1() () 3R() EC1() () 4C() | C39b | 500801-DDP-002 |
| EASA.210.10038954, REV. B | 12/08/2014 | Business Class Seat BC1 | BC1() () 2C() BC1() () 2L() BC1() () 2R() BC1() () 3C() BC1() () 3L() BC1() () 3R() | C127a | 501001-DDP-001 |
| EASA.210.10038955, REV. B | 12/08/2014 | Business Class Seat BC1 | BC1() () 2C() BC1() () 2L() BC1() () 2R() BC1() () 3C() BC1() () 3L() BC1() () 3R() | C39c | 501001-DDP-002 |

ZLIN AIRCRAFT A.S. - LETISTE 1887 765 02 OTROKOVICE CZECH REPUBLIC

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|-----------------|------------------|---------------|
| EASA.210.10050734 | 07/10/2014 | K62 Aircraft main wheel for CS23 aircraft | K62-1100.00.() | C26c | DDPK6201132 |
| EASA.210.10050874 | 21/10/2014 | K63 - Aircraft Nose wheel for CS23 aircraft | K63-1100.00.() | C26c | DDPK6301132 |
| EASA.210.10050873, REV. A | 29/10/2014 | B62 - Aircraft main wheel brake for CS 23 aircraft | B62-1200.00.() | C26c | DDPB6201132 |

ZODIAC AEROSAFETY SYSTEMS - 61 RUE PIERRE CURIE 78370 PLAISIR FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|--|------------------|-------------------|
| EASA.210.254 | 09/03/2005 | Tank Wall Model 106S | 106S060-2 | C80 | 121S071 |
| EASA.210.439 | 21/12/2005 | Crashworthy Tank Wall | 106S055-3 106S056-3 | C80 | 121S077 & 121S076 |
| EASA.210.525 | 20/07/2006 | Life Raft Model SR8 | 2459(X)(X) - (X) | 2C505 | 05-349 |
| EASA.210.540 | 20/07/2006 | Life Raft Model SR12 | 2457(X)(X)-(X) | 2C505 | 05-292 |
| EASA.210.613 | 20/12/2006 | 38 persons life raft | 21990(X)-(X) | 2C70a | 06-387 |
| EASA.210.652 | 26/02/2007 | SR16 Life raft | 2458(X)(X)-(X) | 2C505 | 05-354 |
| EASA.210.1099 | 28/08/2008 | Flexible tank wall | 106S108 | C80 | 121S079 |
| EASA.210.10050193 | 12/08/2014 | INFANT-SMALL CHILD LIFE PRESERVER | 21620()-() | C13f | 01-089 |
| EASA.210.10050482 | 16/09/2014 | 12-Person Reversible Life-Raft | 246200-() TO 246249-() | 2C70b 2C505 | 246200-0 |
| EASA.210.10050724 | 06/10/2014 | 9-PERSON REVERSIBLE LIFE-RAFT / 246300 | 246300-() TO 246349-() | 2C70b 2C505 | 246300-0 |
| EASA.210.10041318, REV. B | 22/10/2012 | 725 Life Raft | 2460(X)(X)-(X) | 2C70a | 246000-0 |
| EASA.210.10041821, REV. A | 22/10/2012 | 731 Life Raft | 2461(X)(X)-(X) | 2C70a | 246100-0 |
| F.O.052 | 10/10/2001 | Crashworthy Tank Wall | 106S055-1 106S055-2 106S056-1 106S076 | | |

ZODIAC AEROTECHNICS S.A.S. - 61 RUE PIERRE CURIE 78370 PLAISIR FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|---------------|------------------|---------------|
|-----------------|--------------------|-------------|---------------|------------------|---------------|

| ZODIAC AEROTECHNICS S.A.S. - 61 RUE PIERRE CURIE 78370 PLAISIR FRANCE | | | | | |
|--|--------------------|--|--|---|------------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.067 | 16/06/2004 | Smoke Goggle | MXGR20-() | C99 | 4DDP0329A |
| EASA.21O.068 | 16/06/2004 | Quick Set Oxygen Mask Regulator | MLC20-() | C78 C89 | 4DDP0338A |
| EASA.21O.10018220 | 05/07/2011 | Full Face Mask Regulator | MF20-() () () | JTSO-C78 JTSO-C89 JTSO-C99 Other | 4DDP0298A |
| EASA.21O.10018226 | 15/03/2011 | Quick Donning Mask Regulator MC20 | MC20-() () () | JTSO-C78 JTSO-C89 Other | 4DDP0302A |
| EASA.21O.10028785 | 09/02/2010 | Active Switch Microphone (SmartMike™) | ASM2-XXX | C58a | 4DDP0489A |
| EASA.21O.10033672 | 03/02/2011 | Quick donning mask MC10 | MC-10-() () () | QAC 151 AND QAC 159 Other (TSO-C78 AND TSO-C89) | 4DDP0281 |
| EASA.21O.10033821 | 10/02/2011 | Crew oxygen mask regulator | MC40-XXX(-Y) | 2C78 C89 | 4DDP0607A |
| EASA.21O.10035927 | 27/07/2011 | Crew Oxygen Mask Regulator MD40 | MD40-XX-YYY[V][Z] | 2C78 C89 | 4DDP687A |
| EASA.21O.10036517 | 21/09/2011 | Oxygen mask regulator / with detachable goggles | MLD40-XX-YYY(-Z) | 2C78 C89 C99 | 4DDP0727A |
| EASA.21O.10036842 | 12/10/2011 | Full Face Quick Donning Mask Regulator MF40 | MF40-XX-YYY(-Z) | 2C78 C89 C99 | 4DDP0737A |
| EASA.21O.10053839 | 26/06/2015 | SmartMike Universal | ASM3-XXX | C139 | 4DDP0908A |
| EASA.21O.10018222, REV. A | 02/10/2015 | SMOKE GOGGLES // Protective Breathing Equipment Smoke Goggle | MXG(X)(X)(XX)(X)(X) | JTSO-C99 Other | 4DDP0299A |
| EASA.21O.10033674, REV. B | 11/12/2012 | Full Face Quick Donning Mask MLD20 | MLD20-() () () | JTSO-C78, JTSO-C89, JTSO-C99 Other | 4DDP0304A, 4DDP0304 |
| EASA.21O.1014, REV. A | 12/10/2011 | Fluid Quantity Measurement System (G250 FQMS) | 722861-(X)-0 722872-(X)-0 738721-(X)-(Y) 738776-(X)-0 742397-(X)-(Y) 765923-(X)-0 765924-(X)-0 765925-(X)-0 765926-(X)-0 765927-(X)-0 765928-(X)-0 765929-(X)-0 765930-(X)-0 765931-(X)-0 765932-(X)-0 765933-(X)-0 765934-(X)-0 765935-(X)-0 765936-(X)-0 765937-(X)-0 765938-(X)-0 765939-(X)-0 | C55 | 1034 |
| F.O.007 | 27/10/1999 | Mask Regulator MRA | MRA(X)(X)(X)-(X) | | |
| F.O.073 | 21/02/2002 | Oxygen Mask MLD20 | MLD20(X)(X)(X)-(X) | | |

| ZODIAC AIRCARGO EQUIPMENT B.V. - TOERMALIJNSTRAAT 16 1812 RL ALKMAAR NETHERLANDS | | | | | |
|---|--------------------|--|---------------|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.21O.140 | 27/07/2004 | Unit Load Device, AKE/LD3 Container, Model AKE002003 | AKE002003 | C90c | 5325 |
| EASA.21O.141 | 27/07/2004 | Unit Load Device, AKE/LD3 Container, Model AKE001003 | AKE001003 | C90c | 5324 |
| EASA.21O.163 | 27/09/2004 | Unit Load Device, PAG Pallet, Model PAG001002 | PAG001002 | C90c | DDP5355 |
| EASA.21O.194 | 04/10/2004 | Unit Load Device, AKE Container, Model AKE001004 | AKE001004 | C90c | 5531 |
| EASA.21O.209 | 15/12/2004 | Unit Load Device, AKE/LD3 Container, Model AKE004003 | AKE004003 | C90c | 5464 |
| EASA.21O.210 | 15/12/2004 | Unit Load Device, AKE Container, Model AKE002004 | AKE002004 | C90c | 5454 |
| EASA.21O.211 | 15/12/2004 | Unit Load Device, AKE Container, Model AKE004002 | AKE004002 | C90c | 5458 |
| EASA.21O.217 | 15/12/2004 | Unit Load Device, AKE Container, Model AKE004001 | AKE004001 | C90c | 5456 |
| EASA.21O.219 | 04/01/2005 | Unit Load Device, AAP/LD9 Container, Model AAP001001 | AAP001001 | C90c | 5353 |
| EASA.21O.287 | 07/05/2004 | Unit Load Device, AKE Cargo Container, Model AKE002002 | AKE002002 | C90c | 5303 |
| EASA.21O.288 | 07/05/2004 | Unit Load Device, AKE Cargo Container, Model AKE002001 | AKE002001 | C90c | 5276 |
| EASA.21O.289 | 07/05/2004 | Unit Load Device, AKE Cargo Container, Model AKE001002 | AKE001002 | C90c | 5302 I |

ZODIAC AIRCARGO EQUIPMENT B.V. - TOERMALIJNSTRAAT 16 1812 RL ALKMAAR NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|--|--|---------------------------------|------------------------|
| EASA.210.290 | 07/05/2004 | Unit Load Device, AKE Cargo Container, Model AKE001001 | AKE001001 | C90c | 5260 |
| EASA.210.291 | 03/06/2005 | Unit Load Device, AKE/LD3 Container, Model AKE001009 | AKE001009 | C90c | 5661 |
| EASA.210.318 | 14/07/2005 | Airfreight Pallet Type L3 | L3-P(-) | JTSO-C90b Other | L3/E |
| EASA.210.358 | 14/10/2005 | Airfreight pallet Type A65 | A65-P(-) | JTSO-C90C Other | A65/E |
| EASA.210.359 | 14/10/2005 | Airfreight pallet Type A6 | A6-P(-) | JTSO-C90b | A6/E |
| EASA.210.360 | 14/10/2005 | Airfreight pallet Type K3 | K3-P(-) | JTSO-C90b | K3/E |
| EASA.210.361 | 14/10/2005 | Airfreight Pallet Type M3 | M3-P(-) | JTSO-C90b | M3/E |
| EASA.210.362 | 14/10/2005 | Airfreight pallet Type PA6 | PA6(-) PA6 - X - () | JTSO-C90A Other | 11.400/112 |
| EASA.210.363 | 14/10/2005 | Airfreight PalletType PB6 | PB6(-) | JTSO-C90A Other | LBA TCDS 11.400/117 |
| EASA.210.364 | 14/10/2005 | Airfreight Pallet series PK327, PK330, PK334, PK338 and PK34 | PK3 | JTSO-C90b | 11.400/148 |
| EASA.210.365 | 14/10/2005 | Airfreight pallet Type PL3 | PL3(-) | JTSO-C90b | 11.400/149 |
| EASA.210.366 | 14/10/2005 | Airfreight pallet Type PL3S | PL3S(-) | JTSO-C90b | 11.400/126 |
| EASA.210.367 | 14/10/2005 | Airfreight pallet Type PM3 | PM3(-) | JTSO-C90A Other | 11.400/113 |
| EASA.210.368 | 14/10/2005 | Airfreight container Type AA | AA-F(-) | JTSO-C90b | AAF/E |
| EASA.210.369 | 14/10/2005 | Airfreight container Type 5H, A320LD | 5H112 5H212 | JTSO-C90b | 11.400/138 |
| EASA.210.370 | 14/10/2005 | Airfreight container Type H1, A320 LD | H1(-) | JTSO-C90b | 11.400/153 |
| EASA.210.371 | 14/10/2005 | Airfreight container Type AAPN | AAPN(-) | JTSO-C90b | 11.400/154 |
| EASA.210.372 | 14/10/2005 | Airfreight container Type ALPN | ALPN(-) | JTSO-C90b | 11.400/155 |
| EASA.210.373 | 14/10/2005 | Airfreight container Type 3 | 3-B(-) | JTSO-C90b | 3/E |
| EASA.210.374 | 14/10/2005 | Airfreight container Type 3 | 3-D(-) | JTSO-C90b | 3D/E |
| EASA.210.375 | 14/10/2005 | Airfreight container Type 1 | 1B(-) | JTSO-C90b | 1/E |
| EASA.210.376 | 14/10/2005 | Airfreight container Type 3 | 3-V(-) | JTSO-C90b | 3V/E |
| EASA.210.377 | 14/10/2005 | Airfreight container Type AMP | AMP(-) | JTSO-C90b | AMP/E |
| EASA.210.378 | 14/10/2005 | Airfreight container Type 3 | 3-K(-) | JTSO-C90C Other | 3K/E |
| EASA.210.379 | 14/10/2005 | Airfreight container Type 3AV | 3-AV(-) | JTSO-C90C Other | 3AV/E |
| EASA.210.380 | 14/10/2005 | Airfreight container Type 3AB | 3-AB(-) | JTSO-C90C Other | 3AB/E |
| EASA.210.382 | 14/10/2005 | Airfreight pallet Type B3 | B3-P(-) | JTSO-C90b | B3/E |
| EASA.210.383 | 14/10/2005 | Airfreight container Type 3AD | 3-AD(-) | JTSO-C90C Other | 3AD/E |
| EASA.210.395 | 04/11/2005 | Airfreight container Type 2M1C | 1-1 1-2 1-2R 1-2RJ 1-4 1-4A | JTSO-C90A JTSO-C90b Other | 11.400/44 |
| EASA.210.396 | 04/11/2005 | Airfreight container Type LD-3 | 2-1 2-11 2-12 2-13 2-14 2-15 2-16 2-2 2-3 2-4 2-5 2-6 | JTSO-C90A Other | 11.400/48 |
| EASA.210.397 | 04/11/2005 | Main Deck Baggage Container | 4-1 4-1R | Other | 11.400/61 |
| EASA.210.398 | 04/11/2005 | Airfreight container Type LD-9 | 5-12(-) 5-2(-) | JTSO-C90A Other | 11.400/69 |
| EASA.210.399 | 04/11/2005 | Airfreight pallet Type 2A4P | 6-5 | JTSO-C90 Other | 11.400/70 |
| EASA.210.400 | 04/11/2005 | Airfreight pallet Type 2M1P | 6-1 | JTSO-C90 Other | 11.400/75 |
| EASA.210.401 | 04/11/2005 | Airfreight container Type 2L2C | 006112 3-2 | JTSO-C90A Other | 11.400/87 |
| EASA.210.402 | 04/11/2005 | Airfreight container Type 3N | 3N-B(-) | JTSO-C90b Other | CB3N/E |
| EASA.210.403 | 04/11/2005 | Airfreight container Type LD-3 | 003111 003112 003211 003212 003214 003216 003311 003312 | JTSO-C90A Other | 11.400/94 |
| EASA.210.404 | 04/11/2005 | Airfreight container Type 3 (LD3) | 3-F(-) | JTSO-C90A Other | 3F/E |

ZODIAC AIRCARGO EQUIPMENT B.V. - TOERMALIJNSTRAAT 16 1812 RL ALKMAAR NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|--|--------------------|-----------------|
| EASA.210.405 | 04/11/2005 | Airfreight container Type LD-3 | 4M3111 4M3112 4M3121 4M3122 4M31S1 4M3211 4M3212 4M3221 4M3222 4M3311 4M3312 4M3321 4M3322 | JTSO-C90A Other | 11.400/109 |
| EASA.210.406 | 04/11/2005 | Airfreight container Type LD-1 | 001111 001112 001211 001212 001214 001216 001311 001312 | JTSO-C90A Other | 11.400/115 |
| EASA.210.407 | 04/11/2005 | Airfreight container Type LD-3 Cooltainer | C-3226 | JTSO-C90A | 11.400/124 |
| EASA.210.408 | 04/11/2005 | Airfreight container Type LD-3 | CL3111 CL3112 CL3211 CL3212 CL3214 CL3216 CL3218 CL3219 CL3311 CL3312 | JTSO-C90b Other | 11.400/132 |
| EASA.210.409 | 04/11/2005 | Airfreight container Type LD-3 (CB3) | CB3111 CB3111S CB3112 CB3112S CB3211 CB3211S CB3212 CB3212S CB3214 CB3216 CB3218 CB3219 CB3311 CB3311S CB3312 CB3312S | JTSO-C90b Other | 11.400/134 |
| EASA.210.410 | 04/11/2005 | Airfreight container Type LD-1 | CL1111 CL1112 CL1211 CL1212 CL1311 CL1312 | JTSO-C90A Other | 11.400/135 |
| EASA.210.411 | 04/11/2005 | Airfreight container Type LD-1 | CM1111 CM1112 CM1211 CM1212 CM1311 CM1312 | JTSO-C90A Other | 11.400/136 |
| EASA.210.412 | 04/11/2005 | Airfreight container Type LD-3 (CL3N) | CL3N22 | JTSO-C90b Other | 11.400/145 |
| EASA.210.413 | 04/11/2005 | Airfreight container Type LD-1 (CB1) | CB1-() | JTSO-C90b Other | 11.400/147 |
| EASA.210.414 | 04/11/2005 | Airfreight container Type LD-3 (CV) | CV-3-() | JTSO-C90C Other | CV/E |
| EASA.210.415 | 04/11/2005 | Airfreight container Type H1 | H1-V-() | JTSO-C90C Other | H1V/E |
| EASA.210.425 | 21/11/2005 | PAG 2A4 Cargo Pallet | PAG001001 | C90c | 5724 |
| EASA.210.429 | 12/12/2005 | PBJ Pallet | PBJ001001 | C90c | 5407 |
| EASA.210.430 | 08/12/2005 | PMC/2M3 Pallet | PMC001004 | C90c | 5561 |
| EASA.210.431 | 08/12/2005 | AKE/LD3 Container - Cover Door | AKE001005 | C90c | 5519 |
| EASA.210.432 | 08/12/2005 | AKE / LD3 Container - Cover Door | AKE001006 | C90c | 5521 |
| EASA.210.433 | 08/12/2005 | AKH/LD3-45 Container | AKH004001 | C90c | 5556 |
| EASA.210.434 | 08/12/2005 | AKE/LD3 Container | AKE001008 | C90c | 5610 |
| EASA.210.435 | 08/12/2005 | AKE/LD3 Container - Cover door | AKE001010 | C90c | 5663 |
| EASA.210.436 | 08/12/2005 | AKE/LD3 Container Bi-fold door | AKE002005 | C90c | 5665 |
| EASA.210.632 | 30/01/2007 | AKH001 / LD3-45 Cargo Container | AKH001() | C90c | 5531 |
| EASA.210.1130 | 02/10/2008 | AMF/LD36 Cargo container | AM-F-() | C90c | REPORT NO. 5958 |
| EASA.210.139, REV.A | 07/01/2011 | Unit Load Device, PMC/2M3 Cargo Pallet | PMC001() | C90c | 5328 |
| EASA.210.169, REV. 1 | 14/10/2005 | Airfreight container Type AL-F | AL-F-() | C90c | ALF/E |

ZODIAC AIRCARGO EQUIPMENT B.V. - TOERMALIJNSTRAAT 16 1812 RL ALKMAAR NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|---------------|------------------|----------------|
| EASA.210.223, REV. 1 | 14/10/2005 | Airfreight container Type AAX1 | AAX1-) | C90c | AAX1/E |
| EASA.210.10044221, REV. A | 25/02/2014 | ALF / LD6 CARGO CONTAINER / Lightweight cargo container type | 6-B-) | C90d | EPF-41-000086 |
| EASA.IM.210.10047852, REV. A | 04/02/2014 | AKE / LD3 Cargo Container | 3S-V-) | C90d | EPFC-41-000002 |
| ETSOA.210.10053046 | 22/04/2015 | AKH Cargo Container Type H1S // AKH Cargo Container H1S seri | H1S-V-) | C90d | EPFC-41-000006 |
| ETSOA.210.10054251 | 30/07/2015 | AKH Cargo Container Type H2S | H2S-V-) | C90d | EPFC-41-000007 |

ZODIAC AIRCATERING EQUIPMENT EUROPE - TOERMALIJNSTRAAT 16 1812 RL ALKMAAR NETHERLANDS

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------|--------------------|--|----------------------------|------------------|-----------------------|
| EASA.210.10036556 | 19/09/2011 | Cabin Service Trolley TE501 | TE501(XXX) | C175 | EPF-41-000033 |
| EASA.210.10036628 | 26/09/2011 | Cabin Service Trolley TH059 | TH059(XXX) | C175 | EPF-41-000022 |
| EASA.210.10036629 | 26/09/2011 | Cabin Service Trolley TG077 | TG077(XXX) | C175 | EPF-41-000023 |
| EASA.210.10036631 | 26/09/2011 | Cabin Service Trolley TK503 | TK503(XXX) | C175 | EPF-41-000003 |
| EASA.210.10036634 | 26/09/2011 | Cabin Service Trolley TL501 | TL501(XXX) | C175 | EPF-41-000025 |
| EASA.210.10036944 | 18/10/2011 | Cabin Service Container | BC001(XXX) DLH306-(XXX) | C175 | EPF-41-000032 |
| EASA.210.10037071 | 31/10/2011 | TK600-series Trolley | TK600(XXX) | C175 | EPF-41-000001 |
| EASA.210.10037271 | 16/11/2011 | TL600-series Trolley | TL600(XXX) | C175 | EPF-41-000002 |
| EASA.210.10037455 | 29/11/2011 | TK601 Series Trolley | TK601(XXX) | C175 | EPF-41-000012 |
| EASA.210.10037463 | 29/11/2011 | TK607 Series Trolley | TK607(XXX) | C175 | EPF-41-000018 |
| EASA.210.10037469 | 29/11/2011 | TL604 Series Trolley | TL604(XXX) | C175 | EPF-41-000020 |
| EASA.210.10037589 | 08/12/2011 | TK605-series Trolley | TK605(XXX) | C175 | EPF-41-000016 |
| EASA.210.10037642 | 13/12/2011 | TK606-series Trolley | TK606(XXX) | C175 | EPF-41-000017 |
| EASA.210.10037688 | 15/12/2011 | TL606-series Trolley | TL606(XXX) | C175 | EPF-41-000021 |
| EASA.210.10037695 | 16/12/2011 | TL601-series Trolley | TL601(XXX) | C175 | EPF-41-000019 |
| EASA.210.10037743 | 20/12/2011 | TK604-series Trolley | TK604(XXX) | C175 | EPF-41-000015 |
| EASA.210.10037795 | 22/12/2011 | TK602-series Trolley | TK602(XXX) | C175 | EPF-41-000013 |
| EASA.210.10037797 | 22/12/2011 | TK603-series Trolley | TK603(XXX) | C175 | EPF-41-000014 |
| EASA.210.10038327 | 07/02/2012 | TK723-series Trolley | TK723(XXX) | C175 | EPF-41-000035 |
| EASA.210.10039280 | 23/04/2012 | TY604-series Trolley | TY604(XXX) | C175 | EPF-41-000108 |
| EASA.210.10039281 | 23/04/2012 | TX604-series Trolley | TX604(XXX) | C175 | EPF-41-000107 |
| EASA.210.10040978 | 10/08/2012 | TG603-Series Trolley | TG603(XXX) | C175 | EPF-41-000059 |
| EASA.210.10040980 | 10/08/2012 | TG600-Series Trolley | TG600(XXX) | C175 | EPF-41-000050 |
| EASA.210.10040996 | 13/08/2012 | TG602-Series Trolley | TG602(XXX) | C175 | EPF-41-000058 |
| EASA.210.10040997 | 13/08/2012 | TG601-Series Trolley | TG601(XXX) | C175 | EPF-41-000057 |
| EASA.210.10040998 | 13/08/2012 | TG604-Series Trolley | TG604(XXX) | C175 | EPF-41-000060 |
| EASA.210.10041013 | 15/08/2012 | TG605-Series Trolley | TG605(XXX) | C175 | EPF-41-000061 |
| EASA.210.10041027 | 16/08/2012 | TH601-Series Trolley | TH601(XXX) | C175 | EPF-41-000063 |
| EASA.210.10041029 | 16/08/2012 | TH600-Series Trolley | TH600(XXX) | C175 | EPF-41-000062 |
| EASA.210.10041042 | 17/08/2012 | TH602-Series Trolley | TH602(XXX) | C175 | EPF-41-000064 |
| EASA.210.10041043 | 17/08/2012 | TH603-Series Trolley | TH603(XXX) | C175 | EPF-41-000065 |
| EASA.210.10041046 | 17/08/2012 | TH604-Series Trolley | TH604(XXX) | C175 | EPF-41-000066 |
| EASA.210.10041047 | 17/08/2012 | TH605-Series Trolley | TH605(XXX) | C175 | EPF-41-000067 |
| EASA.210.10041290 | 04/09/2012 | TG721-series trolley - waste trolley full size | TG721(XXX) | C175 | EPF-41-000088 |
| EASA.210.10041793 | 16/10/2012 | TL602-series trolley - Atlas trolley half size | TL602(XXX) | C175 | EPF-41-000119 |
| EASA.210.10041888 | 22/10/2012 | TH525 waste trolley half size | TH525(XXX) | C175 | EPF-41-000129 |
| EASA.210.10041965 | 29/10/2012 | TL551 Bar Trolley Half Size | TL551(XXX) | C175 | EPF-41-000103 |
| EASA.210.10042050 | 06/11/2012 | TG516-series trolley Waste trolley full size | TG516(XXX) | C175 | EPF-41-000074 |
| EASA.210.10042052 | 06/11/2012 | TL519-series trolley - Atlas Trolley half size | TL519(XXX) | C175 | EPF-41-000082 |
| EASA.210.10042169 | 13/11/2012 | TL612-Series Trolley | TL612(XXX) | C175 | EPF-41-000172 |
| EASA.210.10042274 | 20/11/2012 | BB60-Series Container | BB60(X)(XXX) | C175 | EPF-41-000011 |
| EASA.210.10042296 | 22/11/2012 | TK613-Series Trolley | TK613(XXX) | C175 | EPF-41-000159 |
| EASA.210.10043885 | 04/03/2013 | TK535 Series Trolley | TK535(XXX) | C175 | EPF-41-000133 |
| EASA.210.10044064 | 18/03/2013 | TL583-Series Trolley | TL583(XXX) | C175 | EPF-41-000145 |
| EASA.210.10044104 | 19/03/2013 | TL-544-Series Trolley | TL544(XXX) | C175 | EPF-41-000144 |
| EASA.210.10044182 | 25/03/2013 | TK581-Series Trolley | TK581(XXX) | C175 | EPF-41-000146 |
| EASA.210.10044367 | 09/04/2013 | TG527-series Trolley | TG527(XXX) | C175 | EPF-41-000143 |
| EASA.210.10044443 | 12/04/2013 | TK547-Series Trolley | TK547(XXX) | C175 | EPF-41-000142 |
| EASA.210.10044554 | 19/04/2013 | TL508-Series Trolley | TL508(XXX) | C175 | EPF-41-000208 |
| EASA.210.10049947 | 21/07/2014 | TK584-SERIES TROLLEY / Atlas Trolley Full size | TK584(XXX) | C175 | EPF-41-000379 |
| EASA.210.10049948 | 21/07/2014 | TL589-SERIES TROLLEY / Atlas Trolley Half size | TL589(XXX) | C175 | EPF-41-000378 |
| EASA.210.10050023 | 25/07/2014 | TL605-SERIES TROLLEY //Atlas Trolley Half size | TL605(XXX) | C175 | EPF-41-000346 |
| EASA.210.10050024 | 25/07/2014 | TL607-SERIES TROLLEY //Atlas Trolley Half size | TL607(XXX) | C175 | EPF-41-000358 |
| EASA.210.10050025 | 25/07/2014 | TL603-SERIES TROLLEY // Atlas Trolley Half size | TL603(XXX) | C175 | EPF-41-000357 |
| EASA.210.10054268 | 31/07/2015 | ZK101-SERIES TROLLEY // Hybrite S Trolley Full Size | ZK101(XXX) | C175 | EPF-41-000481 |
| EASA.210.10055049 | 08/10/2015 | ZK102-SERIES TROLLEY // Hybrite S Trolley Full Size | ZK102(XXX) | C175 | EPF-41-000483 |
| EASA.210.10055050 | 08/10/2015 | TK809-SERIES TROLLEY // Beverage Trolley Full Size Hybrite | TK809(XXX) | C175 | EPF-41-000538 |
| EASA.210.10055404 | 06/11/2015 | BG081 SERIES // Container | BG081(XXX) | C175 | DDP EPF-41-000559 |
| EASA.210.10055405 | 06/11/2015 | TK615-SERIES TROLLEY // Hybrite Trolley Full Size | TK615(XXX) | C175 | DDP EPF-241-000002 |
| EASA.210.10055461 | 11/11/2015 | TL614-SERIES TROLLEY // Hybrite Trolley Half Size | TL614(XXX) | C175 | EPF-241-000005 |

ZODIAC SEATS FRANCE - RUE ROBERT MARECHAL SENIOR 36100 ISSOUDUN FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|---|---|------------------|----------------|
| EASA.210.002 | 19/05/2004 | Passenger seats type 177 | 177(X)2-() () | C127a | 03-21-T177 |
| EASA.210.025 | 19/05/2004 | Model 23 Passenger Seat | 23182()-() 23183()-() | C127a | 04-06-2318 |
| EASA.210.040 | 19/05/2004 | Model 179 Passenger Seat | 179 1 () 179 2 () | C39b | 04-02-T179 |
| EASA.210.047 | 19/05/2004 | Passenger Seat Model 5836 | 58362() | C127a | 04-11-5836 |
| EASA.210.048 | 19/05/2004 | Passenger Seat Model 9553 | 95532()-() 95533()-() | C127a | 03-22-9553 |
| EASA.210.069 | 16/06/2004 | Double and triple Passenger Seat Model: 2326 | 23262 ()-() 23263()-() | C127a | 03-19-2326 |
| EASA.210.070 | 16/06/2004 | Type A double and triple Passenger Seat Model: 2327 | 2362 ()-() 2363()-() | C127a | 03-19-2326 |
| EASA.210.094 | 16/06/2004 | Passenger Seats Model 9404 | 9404(X)1(X)-(X)1 9404(X)1(X)-(X)3 9404(X)1(X)-(X)7 9404(X)()-(X)-(X)2 9404(X)()-(X)-(X)4 9404(X)()-(X)-(X)8 | C127a | 03-04.9404 O |
| EASA.210.096 | 16/06/2004 | Type A Biplance, Triplace and Quadriplace Passenger Seats | 23172() 23173() 23174() | C127a | 03-20-2317 |
| EASA.210.117 | 01/07/2004 | Passenger Seats Type A Model 2319 | 23192 ()-() 23193 ()-() 23194 ()-() | C127a | 04-20-2319 |
| EASA.210.121 | 01/07/2004 | Passenger Seat | 10032()-() 10033()-() | C127a | 04-18-1003 |
| EASA.210.133 | 05/07/2004 | Double and Triple Passenger Seats | 14012()-() 14013()-() | C127a | 04-17-1401 |
| EASA.210.136 | 08/07/2004 | Passenger Seat Model 9582 | 95822 ()-() 95823 ()-() 95824 ()-() | C127a | 04-07-9582 |
| EASA.210.174 | 12/10/2004 | Backward facing double passenger seat | 95537()-() | C127a | 04-01-9553 |
| EASA.210.190 | 26/10/2004 | Double and Triple Passenger Seat - Model 30 | 30()2()-() 30()3()-() | C39b | 04-22-3000 |
| EASA.210.192 | 26/10/2004 | Double and Triple Passenger Seat - Model 30 | 30()2()-() 30()3()-() | C127a | 04-25-3000 |
| EASA.210.240 | 26/01/2005 | Model 58 Passenger Seat | 58282(X) (X)-(X) (XX) | C127a | 04-27-5828 |
| EASA.210.244 | 14/02/2005 | Model 5838 Passenger Seat | 58382 (X) (X)-0-(XX) | C127a | 04-30-5838 |
| EASA.210.251 | 09/03/2005 | Seats Model 95, Double and Triple Passenger Seat | 95(XX)2(X)(X)-0(XX) 95(XX)3(X)(X)-0(XX) | C127a | 05-01-9572 |
| EASA.210.285 | 31/05/2005 | Seats Model 192 Type B, forward and backward facing | 192(XX) - (XX) - (XX) | C127a | 05-02-T192 |
| EASA.210.311 | 14/07/2005 | Model 50 Passenger Seat | 50B22 () 50B23 () | C127a | 04-15-50B2 |
| EASA.210.312 | 14/07/2005 | Model 185 Pilot/Copilot Seat | 185()1-() () 185()2-() () | C127a | 04-16-T185 |
| EASA.210.313 | 14/07/2005 | Model 9F Passenger Seat Series | 9F()1()-() 9F()2()-() 9F()3()-() 9F()4()-() | C127a | 04-09-9F01 |
| EASA.210.314 | 14/07/2005 | Model 2320 Passenger Seat Series | 23202()-() 23203()-() 23204()-() | C127a | 04-12-2320 |
| EASA.210.315 | 14/07/2005 | Model 170 Passenger Seat | 17021()-() | C127a | 04-14-1702 |
| EASA.210.419 | 11/11/2005 | Model 16 Passenger Seat | 16(XX)2(X)(X)-0(XX) 16(XX)3(X)(X)-0(XX) | C39b | DDP-05-16-1601 |
| EASA.210.466 | 22/02/2006 | Model 35 Passenger Seat | 35(XX)2(X)(X)-0(XX) 35(XX)3(X)(X)-0(XX) 35(XX)4(X)(X)-0(XX) | C39b | DDP-05-12-3502 |
| EASA.210.481 | 15/03/2006 | Model 58 Passenger Seat | 58(XX)2(X)(X)-0(XX) | C127a | DDP-06-01-5842 |
| EASA.210.482 | 09/03/2006 | Model 35 Passenger Seat | 35(XX)2(X)(X)-0(XX) 35(XX)3(X)(X)-0(XX) 35(XX)4(X)(X)-0(XX) | C127a | DDP-06-03-3502 |
| EASA.210.488 | 30/03/2006 | Model 18 Type A Passenger Seat | 18(XX)1(X)(X)-0(XX) | C39b | DDP-05-18-1801 |
| EASA.210.507 | 24/05/2006 | Model 18 Type A Passenger Seat | 18(XX)1(X)(X)-0(XX) | C127a | DDP-05-19-1801 |
| EASA.210.528 | 28/06/2006 | Model 23 Type A passenger seat | 23(XX)2(X)(X)-0(XX) 23(XX)3(X)(X)-0(XX) 23(XX)4(X)(X)-0(XX) | C127a | DDP-06-02-2329 |
| EASA.210.529 | 28/06/2006 | Model 65 Type A passenger seat | 65(XX)2(X)(X)-0(XX) | C127a | DDP-06-04-65E9 |
| EASA.210.924 | 25/06/2009 | Model 1E Passenger Seat | P/N 1E(XX)(X)(X)-0(XX) | C39b C127a | DDP-07-06-1EXX |
| EASA.210.925 | 17/02/2010 | Model 36 Passenger Seat | 36(XX)2(X)(X)-0(XX) 36(XX)3(X)(X)-0(XX) 36(XX)4(X)(X)-0(XX) | C127a | 07-05-36XX |
| EASA.210.118, REV. A | 01/09/2004 | Passenger Double Type IV Seat | 23192 ()-() | C39b | 04-19-T190 |
| EASA.210.1197 | 21/01/2009 | Model 193 Observer Seat | 193(X)(X)-(XX)-(XX) | C127a | DDP-08-06-T193 |
| EASA.210.1216 | 10/02/2009 | Model 191 | 191(X)(X)-(XX)-(XX) | C127a | 08-07-T191 |
| EASA.210.1247 | 06/04/2009 | Model 181 | 181(X)(X)-(XX)-(XX) | C127a | DDP-03-09-T181 |
| EASA.210.1252 | 08/04/2009 | Model 182 | 182(X)(X)-(XX)-(XX) | C127a | DDP-03-16-T182 |
| EASA.210.1284 | 02/10/2009 | MODEL 21 B/C PASSENGER SEAT | 21()-() () | C39b C127a | 09-03-21XX |

ZODIAC SEATS FRANCE - RUE ROBERT MARECHAL SENIOR 36100 ISSOUDUN FRANCE

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|--|------------------|----------------------------------|
| EASA.210.224, REV. B | 23/07/2007 | Type A Double Passenger Seat Model 15 | 15()2()-()-() | C127a | 04-28-1502 |
| EASA.210.247, REV. A | 13/09/2005 | Triple Passenger Seat Model 9B | 9B(XX)3(X)(X)-(X)(XX) | C127a | 05-03-9B09 |
| EASA.210.316, REV. A | 23/12/2005 | Model 14 Passenger Seat Series | 14()2()-() 14()3()-() | C39b | DDP-04-17-1401 |
| EASA.210.317, REV. A | 29/06/2006 | Model 65 Passenger Seat | 65(XX)2(X)(X)-0(XX) | C39b | 04-08-65C0 |
| EASA.210.420, REV. A | 30/08/2007 | Type A Passenger Seat Model 16 | 16(XX)2(X)(X)-0(XX) 16(XX)3(X)(X)-0(XX) 19(XX)1(X)(X)-0(XX) | C127a | DDP-05-17-1601 |
| EASA.210.958, REV. A | 05/11/2008 | Model 196 Mono passenger seat | 196()-()-() 196()-()-()-() 196()-()-()-()-() 196()-()-()-()-()-() 196()-()-()-()-()-()-() 196()-()-()-()-()-()-()-() | C127a | DDP-08-01-T196 |
| EASA.210.10033100 | 17/12/2010 | Model 22 Passenger Seat | 22(XX)1(X)(X)-0(XX) 22(XX)2(X)(X)-0(XX) | C39b C127a | FD9950118 |
| EASA.210.10036018 | 05/08/2011 | Model 436 Cabin Attendant Seat | 436(X)(X)-(XX)-(XXX) | C39c | DDP-11-01-T436 |
| EASA.210.10036020 | 05/08/2011 | Model 437 Cabin Attendant Seat | 437(X)(X)-(XX)-(XXX) | C39c | DDP-11-02-T437 |
| EASA.210.10036519 | 19/09/2011 | Model 5751 Passenger Seat | Z1(XX)2(X)(X)(X)0(XX) Z1(XX)3(X)(X)(X)0(XX) Z1(XX)4(X)(X)(X)0(XX) | C39c | FD9018797 |
| EASA.210.10036578 | 21/09/2011 | Model 536 Cabin Attendant Seat | 536(X)(X)-(XX)-(XXX) | C127a | 11-05-T536 |
| EASA.210.10036580 | 21/09/2011 | Model 537 Cabin Attendant Seat | 537(X)(X)-(XX)-(XXX) | C127a | 11-06-T537 |
| EASA.210.10036637 | 26/09/2011 | Passenger Seat Model 13 | 13(XX)2(X)(X)(X)0(XX) | C39b C127a | FD9018781 |
| EASA.210.10040215 | 19/06/2012 | Model 198 Anti-Crash Crew Seat | 198(X)(X)-(XX)-(XX) | C127a | FD9036095 |
| EASA.210.10041359 | 12/09/2012 | Model 284 Crew Seat. | 284(X)(X)-(XX)-(XX) | C127a | T284_DDP_FD9040265 |
| EASA.210.10041552 | 12/10/2012 | Model 1S Passenger Seat | 1S(XX)(X)(X)(X)(X)0(XX) | C127a | FD9034930 |
| EASA.210.10041718 | 12/10/2012 | Seat Model 189 | 1891(X)-(XX)-(XX) | C127a | DDP-05-14-T189 |
| EASA.210.10043656 | 15/02/2013 | Pilot Seat Model 445 | 445(X)(X)-(XX)-(XX) | C127a | T445_FD9049506 |
| EASA.210.10048861 | 17/04/2014 | MODEL 189 // Type IV Pilot / Co-pilot seat (Crew Seat Forwar | 18910-50-50 | C39c | T189DDP FD9077657 |
| EASA.210.10049038 | 05/05/2014 | Model Z300 Passenger Seat | Z3(XX)2(X)(X)(X)0(X)(X) Z3(XX)3(X)(X)(X)0(X)(X) Z3(XX)4(X)(X)(X)0(X)(X) | C39c C127a | Z300_DDP_FD72738 |
| EASA.210.10049813 | 10/07/2014 | Model 444 Pilot Seat | 444(X)(X)-(XX)-(XX) | C127a | T444_DDP_FD9082785 |
| EASA.210.10050888 | 22/10/2014 | Model 538 // Type A ISIS Cabin Attendant Seat | 538(X)(X)(X)(X)(X)(X)(XX)-(XXX) | C39c | T538_DDP_FD9094480 |
| EASA.210.10051681 | 17/12/2014 | MODEL 538 / Type A ISIS Cabin Attendant Seat | 538(X)(X)(X)(X)(X)(X)(XX)-(XXX) | C127a | T538_DDP_FD9094480 |
| EASA.210.10052621 | 17/03/2015 | Type A Rotating Cabin Attendant Seat / MODEL 183P/N 183(X)X | | C39c C127a | T183_DDP_FD9034466 |
| EASA.210.10055277 | 28/10/2015 | Model 443 Third Occupant Seat | 443(X)(X)-(XX)-(XX) | C127a | T443_DDP_FD9110663 |
| EASA.210.10033394, REV. A | 03/02/2011 | Model 5751 Passenger Seat | Z1(XX)2(X)(X)(X)0(XX)(X) Z1(XX)3(X)(X)(X)0(XX)(X) Z1(XX)4(X)(X)(X)0(XX)(X) | C127a | FD9005655 |
| EASA.210.10039088, REV. C | 21/01/2014 | MODEL 31 PASSENGER SEAT | 31(XX)2(X)(X)(X)0(X)(X) 31(XX)3(X)(X)(X)0(X)(X) 31(XX)4(X)(X)(X)0(X)(X) | C39c C127a | FD9028317 |
| EASA.210.1073, REV. A | 13/09/2012 | Model 38 Passenger Seat | 38(XX)(X)(X)(X)(X)0(XX) | C39c C127a | 38_DDP_FD9040236 |
| EASA.210.1141, REV. A | 22/09/2010 | Operator Seat Model 187 | 187(X)(X)-(XX)-(XX) | C39b | DDP-05-26-T187 |
| EASA.210.1210, REV. C | 23/07/2015 | MODEL CIRRUS 1C & 2C // Type A passenger seat | 1C(XX)1(XX)(X)0(XX) 2C(XX)1(XX)(X)0(XX) P/N 455(X)(X)-(XX)-(XX) | C39b C127a | 08-08-1C00 T455_DDP_FD9110855 |
| F.O.028 | 25/10/2000 | Type 1 Passenger Seat | 58(XX)2(X)(X)-(XX) | | |
| F.O.057 | 30/01/2002 | Type A passenger seat | 9E(XX)2(X)(X)-(X)(XX) | | |
| F.O.075 | 20/03/2002 | Passenger seat type 10 | 10(XX)2(X)(X)-(X)(XX) 10(XX)3(X)(X)-(X)(XX) | | #02-05-1002 |
| F.O.076 | 20/03/2002 | Passenger seat | 58(XX)1(X)(X)-(X)(XX) | | |
| F.O.081 | 27/08/2002 | Single Passenger Seat | 17(XX)1(X)(X)-(XX) | | DDP-02-17-1701 |
| F.O.082 | 27/08/2002 | Type A Passenger Seat | 50902(X)(X)-(X)(XX) | | DDP-02-14-5090 |
| F.O.083 | 27/08/2002 | Type A Passenger Seat | 95573(X)(X)-(X)(XX) | | DDP-02-12-9557 |
| F.O.084 | 27/08/2002 | Passenger Seat | 10012(X)(X)-(X)(XX) | | DDP-02-13-1001 |
| F.O.086 | 27/08/2002 | Passenger Seat | 95583(X)(X)-(XX) | | DDP-02-16-9558 |
| F.O.092 | 28/10/2002 | Type A Passenger Seat | 58102(X)(X)-(X)(XX) | | 02-15-5810 |
| F.O.093 | 28/10/2002 | Type A Passenger Seat | 10022(X)(X)-(X)(XX) 10023(X)(X)-(X)(XX) | | 02-10-1002 |
| F.O.097 | 15/01/2003 | Type A Passenger Seat | 23012(X)(X)-(XX) 23013(X)(X)-(XX) 23014(X)(X)-(XX) | | 02-19-2301 |
| F.O.098 | 06/01/2003 | Type A Passenger Seat | 99292(X)(X)-(X)(XX) 99293(X)(X)-(X)(XX) | | 02-11-9929 |
| F.O.099 | 15/01/2003 | Type A Passenger Seat | 58072(X)(X)-(XX) | | 02-22-5807 |
| F.O.101 | 20/01/2003 | Type I Passenger Seat | 12(XX)2(X)(X)-(XX) | | DDP-02-21-1201 |
| F.O.102 | 20/01/2003 | Type A Passenger Seat | 95482(X)(X)-(XX) 95483(X)(X)-(XX) | | DDP-02-23-9548 |

| ZODIAC SEATS FRANCE - RUE ROBERT MARECHAL SENIOR 36100 ISSOUDUN FRANCE | | | | | |
|---|--------------------|-----------------------|--|------------------|-------------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| F.O.108 | 03/03/2003 | Type 1 Passenger Seat | 98(XX)2(X)(X)-(X)(XX) 98(XX)3(X)(X)-(X)(XX) 98(XX)4(X)(X)-(X)(XX) | | DDP-02-24-9806`R1 |
| F.O.109 | 03/03/2003 | Passenger Seat | 9A(XX)2(X)(X)-(X)(XX) 9A(XX)3(X)(X)-(X)(XX) | | DDP-03-03-9A14 |
| F.O.113 | 07/05/2003 | Passenger Seat | 9A152 ()-() 9A153 ()-() 9A154 ()-() | | 03-08-9A15 |
| F.O.114 | 14/05/2003 | ERJ 170 Pilot Seat | 180(X)1-(XX)-(XX) 180(X)2--(XX)-(XX) | | 02-25-T180 |
| F.O.116 | 06/06/2003 | Passenger Seat | 58302(X)(X)-(X)(XX) 58303(X)(X)-(X)(XX) | | 02-05-5830 |
| F.O.117 | 06/06/2003 | Passenger Seat | 23072(X)(X)-(X)(XX) 23073(X)(X)-(X)(XX) 23074(X)(X)-(X)(XX) 23092(X)(X)-(X)(XX) 23093(X)(X)-(X)(XX) 23094(X)(X)-(X)(XX) | | 03-02-2309 |
| F.O.119 | 07/07/2003 | Passenger Seat | 95753 ()-() | | 03-11-9575 |
| F.O.120 | 07/07/2003 | Passenger Seat | 58312 ()-() | | 03-10-5831 |
| F.O.126 | 25/09/2003 | Passenger Seat | 15(XX)2(XX)-(XX) | | 03-18-1501 |
| F.O.127 | 25/09/2003 | Passenger Seat | 65D92 ()-() | | 03-17-65D9 |
| F.O.128 | 25/09/2003 | Passenger Seat | 95793(X)(X)-(XX) | | 03-12-9579 |

| ZODIAC SEATS UK LIMITED - LLANTARNAM INDUSTRIAL PARK NP44 3HQ CWMBRAN UNITED KINGDOM | | | | | |
|---|--------------------|--|--|------------------|---------------|
| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
| EASA.210.167 | 01/10/2004 | F11300 Series - Upper Class Passenger Sleeper System | F11306-001-011 F11306-001-12 F11307-001-011 F11307-001-12 F11308-001-011 F11308-001-012 F11309-001-011 F11309-001-12 F11310-001-011 F11310-001-012 F11311-001-011 F11311-001-0122 F11312-001-011 F11312-001-012 | C39b | R582 |
| EASA.210.173 | 12/10/2004 | F11200 Series - Upper Class Single Sleeper Seat System | F11202-001-011 F11202-001-012 F11202-001-013 F11202-001-014 F11202-001-015 F11202-001-016 F11202-001-017 F11202-001-018 F11203-001-011 F11203-001-012 F11221-001-011 F11221-001-012 F11221-001-013 F11221-001-014 F11221-001-015 F11221-001-016 | C127a | R571 |
| EASA.210.245 | 17/02/2005 | F11400 Series - Premium VIP Class Cabin Seats | F11426-001-001 F11426-001-002 F11426-001-003 F11426-001-004 F11426-001-005 F11426-001-006 F11426-001-007 F11426-001-008 F11426-001-009 F11426-001-010 | C39b | R574 |
| EASA.210.286 | 01/06/2005 | F11700 Series - Side Facing Single Passenger Seat & Plinth S | F11701-001-(XXX) F11702-001-(XXX) F11703-001-(XXX) F11704-001-(XXX) F11705-001-(XXX) F11706-001-(XXX) F11707-001-(XXX) F11708-001-(XXX) F11709-001-(XXX) | C39b | R 586 |
| EASA.210.297 | 29/06/2005 | S20212-001 Series - Business Class Double Seats | S20212-001-(XXX) | C39b | R587 |
| EASA.210.305 | 08/07/2005 | Upper Class Passenger Single Sleeper Seat System - F11200-0 | F11204-001-(XXX) F11205-001-(XXX) F11223-001-(XXX) F11224-001-(XXX) | C127a | R589 |

ZODIAC SEATS UK LIMITED - LLANTARNAM INDUSTRIAL PARK NP44 3HQ CWMBRAN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|----------------------|--------------------|--|--|------------------|--------------------|
| EASA.210.308 | 20/07/2005 | P10807-(xxx)-(xxx) - First Class Passenger Single Seat Cabin | P10807-(XXX)-(XXX) | C39b | R557 |
| EASA.210.390 | 27/10/2005 | First Class Cabin Seats Model P10426-001 Series | P10426-001-(XXX) | C127a | R542 |
| EASA.210.391 | 27/10/2005 | Premium Economy Seats Model 0985-02 Series | 0985-02-(XXX) | C39b | R562 |
| EASA.210.392 | 27/10/2005 | First Class Cabin Seats Model P10200-001 Series | P10227-001-098/198 P10227-001-099/199 P10228-001-098/198 P10228-001-099/199 P10229-001-098/198 P10229-001-099/199 P10230-001-098/198 P10230-001-099/199 P10231-001-098/198 P10231-001-099/199 P10232-001-098/198 P10232-001-099/199 P10288-001-098/099 P10288-001-198/199 P10296-001-198/199 P10297-001-198/199 | C127a | R535 |
| EASA.210.394 | 27/10/2005 | Premium Economy Seats Model 0985-03 Series | 0985-03-(XXX) | C39b | R563 |
| EASA.210.427 | 09/12/2005 | Premium Economy Class Seats Model 0995-02 series | 0995-02-(XXX) | C39b C127a | R581 |
| EASA.210.428 | 09/12/2005 | Premium Economy Class Seats Model 0995-03 series | 0995-03-(XXX) | C39b C127a | R581 |
| EASA.210.456 | 27/01/2006 | S20214-001 Series Double Business Class Seats | S20214-001-(XXX) | C39b | R597 |
| EASA.210.497 | 17/05/2006 | M20203-001 Series Business Class Double Seats | M20203-001-(XXX) | C39b | R555 |
| EASA.210.498 | 17/05/2006 | M20302-001 Series Business Class Triple Seats | M20302-001-(XXX) | C39b | R556 |
| EASA.210.499 | 17/05/2006 | S20211-001 Series Business Class Double Seats | S20211-001-(XXX) | C39b | R573 |
| EASA.210.500 | 17/05/2006 | S20210-001 Business Class Double Seats | S20210-001-(XXX) | C39b | R570 |
| EASA.210.501 | 17/05/2006 | M20206-001 Business Class Double Seats | M20206-001-(XXX) | C39b | R561 |
| EASA.210.502 | 17/05/2006 | M20205-001 Business Class Double Seats | M20205-001-(XXX) | C127a | R559 |
| EASA.210.503 | 18/05/2006 | M20201-001 Series Business Class Seats | M20201-001-(XXX) | C39b | R552 |
| EASA.210.504 | 18/05/2006 | M20202-001 series Business Class Seats | M20202-001-(XXX) | C39b | R553 |
| EASA.210.505 | 18/05/2006 | M20301-001 series Business Class Seats | M20301-001-(XXX) | C39b | R554 |
| EASA.210.506 | 18/05/2006 | M20204-001 series Business Class | M20204-001-(XXX) | C39b | R560 |
| EASA.210.517 | 06/06/2006 | F12000 Series Executive Class Single Cabin Seat - Solar Ecl | F12010-001-(XXX) | C39b | R594 |
| EASA.210.556 | 14/09/2006 | F11210 Series "Malcolm" Upper Class Suites | F11210-001-(XXX) | C127a | R571 |
| EASA.210.597 | 29/11/2006 | Upper Class Single Cabin Suites F11220-001 Series | F11220-001-(XXX) | C127a | R589 |
| EASA.210.598 | 29/11/2006 | Upper Class Single Cabin Suites F11129-001 Series, F11130-00 | F11129-001-(XXX) F11130-001-(XXX) | C39b | R584 |
| EASA.210.599 | 29/11/2006 | Upper Class Single Cabin Suites F11330-001 Series | F11330-001-(XXX) | C39b | R582 |
| EASA.210.600 | 29/11/2006 | Upper Class Single Cabin Suites F11710-001 Series | F11710-001-(XXX) | C39b | R586 |
| EASA.210.618 | 09/01/2007 | S20214-001 Series Double Business Class Seats | S20214-001-(XXX) | C127a | R597 |
| EASA.210.620 | 15/01/2007 | Solar F12000 Series | F12710-001-(XXX) | C39b | R602 APPENDIX 2 |
| EASA.210.640 | 06/02/2007 | F12110 Series Seat/Plinth Assembly | F12110-001-(XXX) | C39b | 592 AND APPENDIX 1 |
| EASA.210.680 | 26/03/2007 | S32005-001 Series "Envoy" Business Class Seat | S32005-001-(XXX) | C39b | R607 |
| EASA.210.739 | 21/05/2007 | F12157-001 Series | F12157-001-(XXX) | C127a | R601 |
| EASA.210.761 | 25/06/2007 | RX1 First Class Cabins | P10200-017-() P10900-017-() | C39b | R546 |
| EASA.210.798 | 14/02/2008 | F12920 First Class Single Seat/ Adapter Assembly | F12920-001-(XXX) F12920-002-(XXX) | C127a | R617 |
| EASA.210.834 | 15/07/2008 | S33008-002 Business Class Double Seats Series | S33(X)08-002-(XXX) | C127a | R620 |
| EASA.210.856 | 26/01/2009 | F12810-001 Series First Class Single Seats | F12800-010-(XXX) | C127a | R598 |
| EASA.210.858 | 13/01/2009 | F16(X)08-010 Series First Class Single Seats for B787 Instal | F16()08-010-()() | C127a | R619 |
| EASA.210.860 | 25/02/2008 | F17(X)07-010 Series First Class Single Seats | F17(X)07-010-(XXX) | C127a | R618 |
| EASA.210.902 | 15/05/2008 | F20005-010 "Lauren" Business Class Single Sleeper Seats | F20005-010-(XXX) | C39b | R622 |
| EASA.210.032, REV. B | 12/12/2005 | S20304-001 Series - Business Class Triple Seats | S20304-001-(XXX) | C39b | R578 |
| EASA.210.033, REV. B | 12/12/2005 | S20209-001 Series - Business Class Seats | S20209-001-(XXX) | C39b | R577 |
| EASA.210.034, REV. B | 12/12/2005 | S20101-001 series Business Class Single Seats | S20101-001-(XXX) | C39b | R567 |
| EASA.210.055, REV. A | 22/11/2007 | Single Passenger Sleeper Seat and Plinth System F11100 Serie | F11101-001-031 F11101-001-032 F11101-001-033 | C39b | R584 |

ZODIAC SEATS UK LIMITED - LLANTARNAM INDUSTRIAL PARK NP44 3HQ CWMBRAN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------|--------------------|-------------|----------------|------------------|---------------|
| | | | F11101-001-034 | | |
| | | | F11102-001-031 | | |
| | | | F11102-001-032 | | |
| | | | F11102-001-033 | | |
| | | | F11102-001-034 | | |
| | | | F11103-001-031 | | |
| | | | F11103-001-032 | | |
| | | | F11103-001-033 | | |
| | | | F11103-001-034 | | |
| | | | F11104-001-031 | | |
| | | | F11104-001-032 | | |
| | | | F11104-001-033 | | |
| | | | F11104-001-034 | | |
| | | | F11105-001-031 | | |
| | | | F11105-001-032 | | |
| | | | F11105-001-033 | | |
| | | | F11105-001-034 | | |
| | | | F11106-001-031 | | |
| | | | F11106-001-032 | | |
| | | | F11106-001-033 | | |
| | | | F11106-001-034 | | |
| | | | F11107-001-031 | | |
| | | | F11107-001-032 | | |
| | | | F11107-001-033 | | |
| | | | F11107-001-034 | | |
| | | | F11108-001-031 | | |
| | | | F11108-001-032 | | |
| | | | F11108-001-033 | | |
| | | | F11108-001-034 | | |
| | | | F11109-001-031 | | |
| | | | F11109-001-032 | | |
| | | | F11109-001-033 | | |
| | | | F11109-001-034 | | |
| | | | F11110-001-031 | | |
| | | | F11110-001-032 | | |
| | | | F11110-001-033 | | |
| | | | F11110-001-034 | | |
| | | | F11111-001-031 | | |
| | | | F11111-001-032 | | |
| | | | F11111-001-033 | | |
| | | | F11111-001-034 | | |
| | | | F11112-001-031 | | |
| | | | F11112-001-032 | | |
| | | | F11112-001-033 | | |
| | | | F11112-001-034 | | |
| | | | F11115-001-031 | | |
| | | | F11115-001-032 | | |
| | | | F11115-001-033 | | |
| | | | F11115-001-034 | | |
| | | | F11116-001-031 | | |
| | | | F11116-001-032 | | |
| | | | F11116-001-033 | | |
| | | | F11116-001-034 | | |
| | | | F11117-001-031 | | |
| | | | F11117-001-032 | | |
| | | | F11117-001-033 | | |
| | | | F11117-001-034 | | |
| | | | F11118-001-031 | | |
| | | | F11118-001-032 | | |
| | | | F11118-001-033 | | |
| | | | F11118-001-034 | | |
| | | | F11119-001-031 | | |
| | | | F11119-001-032 | | |
| | | | F11119-001-033 | | |
| | | | F11119-001-034 | | |
| | | | F11120-001-031 | | |
| | | | F11120-001-032 | | |
| | | | F11120-001-033 | | |
| | | | F11120-001-034 | | |
| | | | F11125-001-031 | | |
| | | | F11125-001-034 | | |
| | | | F11125-001-035 | | |
| | | | F11125-001-038 | | |
| | | | F11126-001-031 | | |
| | | | F11126-001-034 | | |
| | | | F11126-001-035 | | |
| | | | F11126-001-038 | | |
| | | | F11127-001-031 | | |
| | | | F11127-001-034 | | |
| | | | F11127-001-035 | | |
| | | | F11127-001-038 | | |

ZODIAC SEATS UK LIMITED - LLANTARNAM INDUSTRIAL PARK NP44 3HQ CWMBRAN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|---------------------------|--------------------|--|---|--------------------|--------------------------------|
| | | | F11128-001-031 F11128-001-034 F11128-001-035 F11128-001-038 | | |
| EASA.210.087, REV. A | 08/12/2005 | S20207-001 series - Business class double seats | S20207-001-(XXX) | C39b C127a | R565 |
| EASA.210.088, REV. A | 10/06/2005 | S20208-001 Series - Business Class Seat (Double) | S20208-001-(XXX) | C127a | R566 |
| EASA.210.089, REV. A | 10/06/2005 | S20303-001 Series - Business Class Seat (Triple) | S20303-001-(XXX) | C127a | R576 |
| EASA.210.091, REV. B | 10/06/2005 | F11000-001 Series - First Class Passenger Seat | F11006-001-(XXX) | C127a | R564 |
| EASA.210.1065 | 18/12/2008 | S34006 series [Vantage] Business Class seats | S34(X)06-002-(XXX) | C127a | R623 |
| EASA.210.1066 | 14/01/2009 | S34013 series [Vantage] Business Class seats | S34()13-002-() () | C127a | R625 |
| EASA.210.1092 | 18/11/2008 | F19(X)07-010 Series First Class Single Seats | F19()07-010-() () | C127a | R621 |
| EASA.210.1205 | 13/10/2009 | Aura S37X13 Series Business Class Seats | S37(X)13-002-(XXX) | C127a | R630 |
| EASA.210.1206 | 21/10/2009 | Nimbus F13X15 Series First Class Seats | F13(X)15-010-(XXX) | C127a | R629 |
| EASA.210.1208 | 09/09/2010 | Vega F19X15 Series First Class Seat | F19(X)15-010-(XXX) | C127a | R628 |
| EASA.210.122, REV. C | 29/09/2011 | F10900-006 Series Mohawk/Dusk Business Class Sleeper Seats | F10900-006-(XXX) | C39b C127a | R579 |
| EASA.210.162, REV. A | 19/04/2005 | 0985-02 W Series - Premium Economy Class Double Seats | 0985-02-(XXX) | C39b | R580 |
| EASA.210.590, REV. A | 11/10/2007 | Solar F12000 Series Side Facing Seat | F12510-001-(XXX) F15()07-010-() () | C39b | R602 |
| EASA.210.614, REV. C | 09/07/2014 | Upper Class Single Cabin Suites | F11818-001-(XXX) F23(X)07-010-(XXX) F23(X)08-010-(XXX) | C39b | R588 |
| EASA.210.641, REV. A | 22/11/2007 | Solar F12000 Series Business Class Single Cabin Suites | F12410-001-(XXX) F12610-001-(XXX) | C39b | R606 |
| EASA.210.681, REV. A | 26/10/2009 | Apollo F16020-010 Series First Class Single Cabin Suites | F16020-010-() () | C127a | R608 |
| EASA.210.10027380 | 25/09/2009 | M7000 Series Passenger Seats | M7(XXX) - (XXX) | Other TSO-C39B* | R462 ISSUE 11, R494 ISSUE 4 |
| EASA.210.10029966 | 07/05/2010 | S37X07 Series Business Class Seats | S37(X)07-002-(XXX) | C127a | R638 |
| EASA.210.10031616 | 31/08/2010 | S38007 Series Premium Economy Class Seats | S38(X)07-002-(XXX) | C39b | R636 |
| EASA.210.10037163 | 07/11/2011 | S41(X)07 Series Business Class Seats DaVinci | S41(X)07-002-(XXX) | C127a | R640 |
| EASA.210.10037188 | 09/11/2011 | F21(X)15 Series First Class Seats | F21(X)15-010-(XXX) | C127a | R634 |
| EASA.210.10038446 | 17/02/2012 | S37(X)06 Series Business Class Seats | S37(X)06-002-(XXX) | C127a | R643 |
| EASA.210.10039224 | 18/04/2012 | S37(X)08 Series Business Class Seats | S37(X)08-002-(XXX) | C127a | R642 |
| EASA.210.10039404 | 03/05/2012 | S41(X)08 Series Business Class Seats | S41(X)08-002-(XXX) | C127a | R641 |
| EASA.210.10040671 | 18/07/2012 | 13(X)30 Flagship II First Class Seats | F13(X)30-010-(XXX) | C127a | R646 |
| EASA.210.10041554 | 02/10/2012 | S42(X)13 Series Business Class Seat | S42(X)13-002-(XXX) | C127a | R645 |
| EASA.210.10042662 | 13/12/2012 | S41(X)03 Series DaVinci Premium Economy Seat | S41(X)03-002-(XXX) | C127a | R647 |
| EASA.210.10043434 | 28/01/2013 | S41(X)06 Series DaVinci Premium Economy Class Seat | S41(X)06-002-(XXX) | C39c | R648 |
| EASA.210.10045726 | 15/07/2013 | S42(X)06 Series Business Class Seats | S42(X)06-002-(XXX) | C39c | R649 |
| EASA.210.10049171 | 16/05/2014 | Reverb II Passenger Seat | AG50-() ()-() () | C127a | R652 |
| EASA.210.10049238 | 22/05/2014 | F26(X)08 Series Dovetail Business Class Seat | F26(X)08-010-(XXX) | C127a | R650 |
| EASA.210.10050744 | 07/10/2014 | Aura Enhanced S45(x)13 series | S45(X)13-002-(XXX) | C127a | R653 |
| EASA.210.10050860 | 20/10/2014 | Aura Enhanced S45(x)07 series | S45(X)07-002-(XXX) | C127a | R654 |
| EASA.210.10033941, REV. A | 25/10/2013 | Mercury F21(X)07 Series First Class Seats | F21(X)04-010-(XXX) F21(X)07-010-(XXX) | C127a | R639 |
| EASA.210.10038458, REV. A | 10/07/2013 | Yuri / Business Class Seat | BF-TSO-051-()()() BF-TSO-071-()()() | C39b | RA-DOA-07-2011-2 |
| EASA.210.1080, REV. A | 10/07/2013 | Reverb Seat | AE-00-002-() () AE-00-003-() () AE-00-004-() () AE-00-005-() () AE-00-006-() () AE-00-007-() () AE-00-008-() () AE-00-009-() () AE-00-010-() () AE-00-011-() () AE-00-012-() () | C127a | RA-DOA-07-2009-2 |

ZODIAC SEATS UK LIMITED - LLANTARNAM INDUSTRIAL PARK NP44 3HQ CWMBRAN UNITED KINGDOM

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-----------------------|--------------------|-------------|--|------------------|------------------|
| EASA.21O.1091, REV. A | 10/07/2013 | Reverb Seat | AE-00-013-() AE-00-014-() AE-00-015-() AE-00-016-() AE-00-017-() AE-00-018-() AE-00-019-() AE-00-020-() AE-00-021-() AE-00-022-() AE-00-023-() AE-00-024-() | C39b | RA-DOA-07-2009-1 |

ZODIAC SEATS US L.L.C. - 2000 WEBER DRIVE 76240-9699 GAINESVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------|--------------------|--------------------------------------|--|------------------|-------------------------------|
| EASA.21O.039 | 26/05/2004 | Model AI-1000I - () Passenger Seats | 119265-() 119266-() | C39b | G-112 |
| EASA.IM.21O.348 | 05/04/2007 | Model AI-1000-() - Passenger Seats | 855205 - () 858397 - () | C127a | G-154 |
| EASA.IM.21O.642 | 07/02/2007 | Model 5600 Passenger Seat (B767-300) | 857824-() 857825-() 857826-() 857827-() 857828-() 857829-() 857830-() 857831-() 857832-() 857833-() 857834-() 857835-() 857836-() 857837-() 857838-() 857839-() 857840-() 857841-() 857842-() 857843-() 857844-() 857845-() 857846-() 857847-() 857890-() 857892-() 857893-() 858384-() | C39b | G-144 |
| EASA.IM.21O.733 | 15/05/2007 | Passenger Seats Model AI-1000I-CAA | 117582-() 117583-() 117584-() 117585-() | C127a | G176 |
| EASA.IM.21O.740 | 21/05/2007 | Model 7800 Passenger Seats | 856641-() 856642-() 856643-() 856644-() | C39b | G-177 (LOT), G-174 (AEROFLOT) |
| EASA.IM.21O.1001 | 03/03/2008 | Model 8001 Passenger Seats | 849978-() 850586-() | C39b | G-54 |
| EASA.IM.21O.1271 | 25/05/2009 | Model 7070 Passenger Seats | 860016-() | C39b | G-189 |

ZODIAC SEATS US L.L.C. - 2000 WEBER DRIVE 76240-9699 GAINESVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|-------------------------|--------------------|------------------------------------|------------------------|------------------|----------------|
| EASA.IM.210.325, REV. B | 22/03/2011 | Model 5600 Passenger Seats | 855056-() | C127a | G-153 ISSUE 1 |
| | | | 855059-() | | G-162 ISSUE 3 |
| | | | 855060-() | | G-201 ISSUE 1 |
| | | | 855061-() | | G-285 ISSUE 3 |
| | | | 855062-() | | |
| | | | 855063-() | | |
| | | | 855064-() | | |
| | | | 855065-() | | |
| | | | 855066-() | | |
| | | | 855067-() | | |
| | | | 855068-() | | |
| | | | 855104-() | | |
| | | | 855105-() | | |
| | | | 855107-() | | |
| | | | 855108-() | | |
| | | | 858219-() | | |
| | | | 858220-() | | |
| | | | 858221-() | | |
| | | | 858222-() | | |
| | | | 858223-() | | |
| | | | 858224-() | | |
| | | | 858225-() | | |
| | | | 858226-() | | |
| | | | 858227-() | | |
| | | | 858306-() | | |
| | | | 859083-() | | |
| | | | 865369-405, 865369-406 | | |
| | | | 865370-405, 865370-406 | | |
| | | | 865371-405, 865371-406 | | |
| | | | 865372-405, 865372-406 | | |
| | | | 865373-405, 865373-406 | | |
| | | | 865374-405, 865374-406 | | |
| | | | 865375-405, 865375-406 | | |
| EASA.IM.210.347, REV. A | 03/03/2015 | MODEL 7070 // Business Class Seats | 850765-(), 876637-() | C127a | G-150 |
| EASA.IM.210.467, REV. B | 21/07/2010 | Model 5750 Passenger Seats | 858070-() | C127a | G-163, ISSUE 4 |
| | | | 858071-() | | G-179, ISSUE 2 |
| | | | 858072-() | | G-291, ISSUE 1 |
| | | | 858073-() | | |
| | | | 858074-() | | |
| | | | 858076-() | | |
| | | | 858077-() | | |
| | | | 858078-() | | |
| | | | 858079-() | | |
| | | | 858080-() | | |
| | | | 858399-() | | |
| | | | 858400-() | | |
| | | | 858401-() | | |
| | | | 858402-() | | |
| | | | 858403-() | | |
| | | | 858404-() | | |
| | | | 858405-() | | |
| | | | 858406-() | | |
| | | | 858407-() | | |
| | | | 858408-() | | |
| | | | 858409-() | | |
| | | | 858410-() | | |
| | | | 858411-() | | |
| | | | 858412-() | | |
| | | | 858413-() | | |
| | | | 858748-() | | |
| | | | 858749-() | | |
| | | | 858750-() | | |
| | | | 858751-() | | |
| | | | 858752-() | | |
| | | | 858753-() | | |
| | | | 859732-() | | |
| | | | 859742-() | | |
| 859744-() | | | | | |
| 864654-() | | | | | |
| 864655-() | | | | | |
| 864656-() | | | | | |
| 864657-() | | | | | |
| EASA.IM.210.10040952 | 07/08/2012 | Model 7811 B/C Passenger Seat | 862221-() | C127a | G-297 |
| EASA.IM.210.10040953 | 07/08/2012 | Model C100 Passenger Seat | 855151-() | C127a | G-332 |

ZODIAC SEATS US L.L.C. - 2000 WEBER DRIVE 76240-9699 GAINESVILLE USA

| Approval Number | Date of last issue | Description | Partnumber(s) | ETSO Standard(s) | DDP Reference |
|------------------------------|--------------------|--|------------------------|------------------|---------------|
| EASA.IM.21O.10034772, REV. G | 23/11/2015 | MODEL 5751 // T/C Passenger Seat | 864146-(00) | C127a | 392 |
| | | | 864147-(00) | | |
| | | | 864149-(00) | | |
| | | | 864150-(00) | | |
| | | | 864151-(00) | | |
| | | | 864152-(00) | | |
| | | | 864153-(00) | | |
| | | | 864154-(00) | | |
| | | | 864155-(00) | | |
| | | | 864156-(00) | | |
| | | | 864157-(00) | | |
| | | | 864158-(00) | | |
| | | | 864159-(00) | | |
| | | | 864204-(00) | | |
| | | | 865609-(00) | | |
| | | | 865620-(00) | | |
| | | | 866492-(00) | | |
| | | | 866604-(00) | | |
| | | | 866730-(00) | | |
| | | | 867099-(00) | | |
| | | | 869633-(00) | | |
| | | | 869986-(00) | | |
| | | | 873588-(00) | | |
| 874191-(00) | | | | | |
| EASA.IM.21O.10039255, REV. B | 28/03/2014 | Model 5751 Passenger Seats | 867367-(00) | C39c | G-385 |
| | | | 867368-(00) | | |
| | | | 867369-(00) | | |
| | | | 867370-(00) | | |
| | | | 867371-(00) | | |
| | | | 867372-(00) | | |
| | | | 867373-(00) | | |
| | | | 868380-(00) | | |
| 874117-(00) | | | | | |
| EASA.IM.21O.10045319, REV. D | 30/06/2015 | MODEL 5810 // Premium Economy Class Passenger Seat | 861901-4(0) | C127a | G-397 |
| | | | 874759-4(0) | | |
| | | | 874971-4(0) | | |
| 876429-4(0) | | | | | |
| EASA.IM.21O.10051961, REV. A | 26/02/2015 | MODEL 6810 // Crewrest Seat | 874973-402, 874753-402 | C127a | G-380, G-379 |