

EASA Certification Information

No.: 2017-05

Issued: 22 March 2017

Subject: Revocation of various ETSOA certificates due to the revocation of the APDOA No.

EASA.AP123.

Authorisation No: EASA.210.102, EASA.210.168, EASA.210.301, EASA.210.495, EASA.210.496,

EASA.210.582, EASA.210.583, EASA.210.166, REV. A

| ETSOA No. | Description | P/N | Date of last issue |
|-------------------------|--|----------------------------------|--------------------|
| EASA.210.102 | F2317 Series - 9G Forward Facing | F2317-()-()-() | 16/06/2004 |
| | Business Class Passenger Seat | | |
| EASA.210.168 | F4311 Series Economy/Business Class Quadruple Passenger Seat | F4311-()-()-() | 01/10/2004 |
| EASA.210.301 | 9g Forward Facing Economy Double Passenger Seat, F2311 Serie | F2311 - (X) - (XX) - (XXX) | 04/07/2005 |
| EASA.210.495 | F2313 Passenger Seat | F2313-()-()-() | 15/05/2006 |
| EASA.210.496 | F3313 Passenger Seat | F3313-()-()-() | 15/05/2006 |
| EASA.210.582 | Passenger Seat F3313 | F3313-()-()-() | 31/10/2006 |
| EASA.210.583 | Passenger Seat F2313 | F2313-()-()-() | 31/10/2006 |
| EASA.210.166, REV. A | F3311 Series Economy Class Passenger | F3311-()-()-() F4311-()-()-() | 23/05/2011 |
| | Seat | | |

Issued by: EASA

Holder of the Certificate: Flying Service Engineering & Equipment, Ltd.

Springfield Road HP5 1PP Chesham United Kingdom Background:

With the revocation of EASA.AP123 on 16/03/2017 the capability for design is no longer provided and as a consequence EASA has decided to revoke all ETSO authorizations granted to Flying Service Engineering & Equipment, Ltd.

In accordance with the applicable EASA administrative procedures¹, EASA decided to revoke the aforementioned authorisations. EASA has submitted the decision to revoke EASA.210.102, EASA.210.168, EASA.210.301, EASA.210.495, EASA.210.496, EASA.210.582, EASA.210.583, EASA.210.466, EASA.210.466, EASA.210.582, EASA.210.583, EASA.210.466, EASA.210.466, EASA.210.582, EASA.210.583, EASA.210.466, EASA.210.466, EASA.210.466, E

EASA.210.166, REV. A on 21 March 2017.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency Parts & Appliances Section Postfach 10 12 53 D – 50452 Köln

E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (http://easa.europa.eu/certification/internal-working-procedures.php)