

## **EASA Certification Information**

No.: 2020-06 Issued: 12 May 2020

Subject: Decision to accept TENENCIA, Ltd. request to surrender the following ETSO

authorisation:

ETSOA No.	Description	P/N	Date of last	DDP ref.
			issue	
EASA.210.10065245	PF3000 // PF3200 and PF3300	PF3-2-01-165-xxx,	17/04/2018	DF/ENG/070-PF3001
	Aircraft Double and Triple Seat	PF3-2-01-166-xxx,		
		PF3-2-01-169-xxx,		
		PF3-2-01-170-xxx		
		PF3-2-01-173-xxx,		
		PF3-2-01-174-xxx,		
		PF3-3-01-121-xxx,		
		PF3-3-01-122-xxx		
		PF3-3-01-123-xxx,		
		PF3-3-01-124-xxx,		
		PF3-3-01-125-xxx,		
		PF3-3-01-126-xxx		
		PF3-3-01-127-xxx,		
		PF3-3-01-128-xxx,		
		PF3-3-01-129-xxx,		
		PF3-3-01-130-xxx		
		PF3-3-01-139-xxx,		
		PF3-3-01-140-xxx,		
		PF3-3-01-143-xxx,		
		PF3-3-01-144-xxx		
		PF3-3-01-151-xxx,		
		PF3-3-01-152-xxx,		
		PF3-3-01-189-xxx,		
		PF3-3-01-190-xxx		
		PF3-3-01-191-xxx,		
		PF3-3-01-192-xxx,		
		PF3-3-01-193-xxx,		
		PF3-3-01-194-xxx		

Holder of the Certificate: TENENCIA, Ltd.

Dakota House

Coventry Airport CV8 3AZ

Coventry

**United Kingdom** 



## **Background:**

On the date mentioned in the table above EASA issued the specified authorisation to TENENCIA, Ltd.

TENENCIA, Ltd. has confirmed that there have been three shipsets manufactured in accordance with this ETSOA and they are installed to the following aircraft operated by Israir Airlines in Israel:

Airbus A320-232 MSN 4354 Registration 4X-ABF Airbus A320-232 MSN 4413 Registration 4X-ABG Airbus A320-232 MSN 7110 Registration 4X-ABI

On the 31st of May 2019, TENENCIA, Ltd and INTER-TEC SERVICES LIMITED (holder of EASA Part 21 Subpart J DOA EASA.21J.495) signed a joint statement for the change of ownership of the design data covered by the ETSO Authorisation in object.

On the 4th of May 2020, TENENCIA, Ltd confirmed the intention to surrender the ETSO Authorization in object.

On the 12<sup>th</sup> May 2020, INTER-TEC SERVICES LIMITED has received the ETSO Authorization EASA.21O.10073229 for the seat P/N's mentioned in the table above and will ensure the continuity of the management of the continuing airworthiness of the shipsets currently in service

## Contact:

Any request, query or comment shall be sent to:

European Aviation Safety Agency European Technical Standard Orders Section Postfach 10 12 53 D – 50452 Köln

E-Mail: etsoa@easa.europa.eu